REPORT ON
ASTM PHASE I ENVIRONMENTAL SITE ASSESSMENT
AND LIMITED SUBSURFACE SAMPLING
AKRIDGE PARCEL AT BUZZARD POINT,
SQUARE 0607, LOT 0013
WASHINGTON, DC

by

Haley & Aldrich, Inc. Boston, Massachusetts

for

McKissack & McKissack Washington, DC

File No. 40223-002 8 January 2014

Haley & Aldrich, Inc. 7926 Jones Branch Dr. Suite 870 McLean, VA 22102

> Tel: 703.336.6200 Fax: 703.356.4699 HaleyAldrich.com



8 January 2014 File No. 40223-002

McKissack & McKissack 1401 New York Avenue, NW Suite 900 Washington, DC 20005

Attention: James Beall

Senior Project Manager

Subject: ASTM Phase I Environmental Site Assessment and Limited Subsurface Sampling

Akridge Parcel at Buzzard Point, Square 0607, Lot 0013

Washington, DC

Ladies and Gentlemen:

The enclosed report presents the results of a Phase I environmental site assessment (Phase I assessment) conducted at the above-referenced property, Square 0607, Lot 0013, in Washington, DC (herein referred to as the "subject site"). A Phase I assessment was conducted by Haley & Aldrich, Inc. (Haley & Aldrich) for seven parcels at Buzzard Point proposed for redevelopment as a professional soccer stadium, in accordance with our proposal to McKissack & McKissack dated 28 June 2013 ("Agreement"). This report was prepared in response to a request from Mr. James Beall of McKissack & McKissack to provide a separate stand-alone Phase I assessment for the subject site. The results of limited Phase II subsurface sampling, performed to evaluate the potential impact of "recognized environmental conditions" (RECs), are also included in this report.

Our conclusions regarding the presence and potential impact of RECs on the subject site are intended to help the user evaluate the "business environmental risk" associated with the subject site, as defined in the ASTM E 1527-05 Standard and discussed in Section 1.1 of this report.

Thank you for the opportunity to perform these services for you. Please do not hesitate to contact us if you have any questions or comments.

Sincerely yours,

HALEY & ALDRICH, INC.

Karin S. Holland Senior Technical Specialist Gregory B. Grose, PG Senior Project Manager

Enclosures



REPORT ON

ASTM PHASE I ENVIRONMENTAL SITE ASSESSMENT AND LIMITED SUBSURFACE SAMPLING

AKRIDGE PARCEL AT BUZZARD POINT, SQUARE 0607, LOT 0013 WASHINGTON, DC

by

Haley & Aldrich, Inc. Boston, Massachusetts

The undersigned declare the following:

We declare that, to the best of our professional knowledge and belief, we meet the definition of Environmental Professional as defined in 40 CFR Part 312, §312.10.

We have the specific qualifications based on education, training, and experience to assess the nature, history, and setting of the subject site and "develop opinions and conclusions regarding conditions indicative of releases or threatened releases." We have developed and performed the "all appropriate inquiries" (AAI) in conformance with the standards and practices set forth in 40 CFR Part 312.

Gregory B. Grose, PG Senior Project Manager Karin S. Holland Senior Technical Specialist

for

McKissack & McKissack, Inc. Washington, DC

File No. 40223-002

EXECUTIVE SUMMARY

Haley & Aldrich, Inc. (Haley & Aldrich) performed a Phase I environmental site assessment (Phase I assessment) of the "Akridge" parcel at Buzzard Point, Square 0607, Lot 0013 (herein referred to as the "subject site") in Washington, DC. The scope of work is described and conditioned by our proposal dated 28 June 2013. As indicated in our proposal, this Phase I assessment was performed in conformance with the scope and limitations of the American Society for Testing and Materials (ASTM) E 1527-05 Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process (ASTM E 1527-05 Standard) as referenced in 40 Code of Federal Regulations (CFR) Part 312 [the All Appropriate Inquiries (AAI) Rule]. Deviations from this Standard, and/or data gaps and their significance are described in Section 1.5 of this report. Limited Phase II subsurface sampling was also conducted to evaluate issues identified during the Phase I portion of the assessment. Our conclusions are intended to help the user evaluate the "business environmental risk" associated with the subject site, as defined in the ASTM E 1527-05 Standard and discussed in Section 1.1 of this report.

The subject site is bound by 1^{st} , 2^{nd} , S, and T Streets SW, and comprises a parking lot and a single-level storage building. The building is utilized to store end-of-life passenger vehicles and a motorcycle.

The objective of a Phase I assessment is to identify known and suspect "recognized environmental conditions" (RECs), historical RECs (HRECs), and *de minimis* conditions associated with the subject site, as defined in the ASTM E 1527-05 Standard and in Section 1.1 of this report. The objective of the limited Phase II subsurface sampling is to provide a preliminary evaluation of RECs identified during the Phase I portion of the assessment, including order of magnitude cost and schedule impacts on the proposed development.

The ASTM E 1527-05 Standard requires an environmental professional's opinion of the potential impacts of RECs, HRECs, and *de minimis* conditions identified on a site during a Phase I assessment. Our opinion is rendered with respect to an REC's potential (high, medium, or low) to require remedial response based on prevailing agency requirements and our understanding that the subject site is one of seven parcels being evaluated for potential redevelopment as a professional soccer stadium. Our opinion regarding a REC's potential impact on the subject site (high, medium, low, or unknown) is based on the scope of our work, the information obtained during the course of our work, the conditions prevailing at the time our work was performed, the applicable regulatory requirements in effect at the time our work was performed, and/or our experience evaluating similar sites, and our understanding of the client's intended use for the subject site.

Data gaps were not identified for this report.

RECOGNIZED ENVIRONMENTAL CONDITIONS

The ASTM E 1527-05 Standard defines a REC as "the presence or likely presence of any hazardous substances or petroleum products on a property under conditions that indicate an existing release, a past release, or a material threat of a release of any hazardous substances or petroleum products into structures on the property or into the ground, ground water, or surface water of the property." A material threat is defined by the ASTM E 1527-05 Standard as "a physically observable or obvious threat which is reasonably likely to lead to a release that, in the opinion of the environmental professional, is threatening and might result in impact to public health or the environment."



This Phase I assessment identified 13 RECs. Details regarding the nature of these RECs and our opinion regarding potential impacts are provided below.

KNOWN RECOGNIZED ENVIRONMENTAL CONDITIONS

Consistent with ASTM E 1527-05 Section 12.5 (Report Format), and for the purposes of this assessment, those RECs identified as being present with respect to the subject site are referred to as Known Recognized Environmental Conditions (KRECs). Two KRECs have been identified on the subject site from the limited Phase II subsurface sampling results.

KREC #1: Potential Impact: Explanation: Shallow subsurface petroleum impact from surface staining or urban fill

Low

Apparent hydrocarbon stains were observed on the asphalt-paved portion of the subject site utilized as a parking lot. A crack was observed in the asphalt under one of these stains and a soil sample (GSS-607-13-1, see Figure 3) collected by Haley & Aldrich from beneath the asphalt revealed a total petroleum hydrocarbons – diesel range organics (TPH-DRO) concentration of 184 milligrams per kilogram (mg/kg). This TPH-DRO detection confirms the presence of minor petroleum contamination in shallow soil, exceeding the D.C. Municipal Regulations (DCMR) Tier 0 Soil Standard for TPH of 100 mg/kg. The vertical extent of impact is currently not known, although based on the relatively low concentration immediately beneath the staining, the degree of impact appears to be minor. The TPH-DRO detection may also be related to urban fill encountered in this boring.

Analytical results for a soil sample collected along S Street (GTW-607-13-2, see Figure 3) from a depth of 5 to 10 feet below grade indicated minor petroleum impact (TPH-DRO at 119 mg/kg). This TPH-DRO detection confirms the presence of minor petroleum contamination in shallow soil, exceeding the DCMR Tier 0 Soil Standard for TPH of 100 mg/kg. Benzo(a)pyrene was also detected at 8.67 mg/kg, slightly exceeding the DC Risk-Based Corrective Action (DCRBCA) Screening Levels (SL) for construction worker exposure of 5.92 mg/kg. Other polycyclic aromatic hydrocarbons (PAHs) and metals (arsenic at 4.8 mg/kg and chromium at 10.3 mg/kg) were detected at concentrations exceeding the EPA Region III Risk-Based Screening Level (RSLs) for residential soil. The source and extent of impact is not known, although urban fill was encountered in this boring, which commonly yields similar results.

KREC #2: Potential Impact: Explanation: Minor groundwater contamination associated with chlorinated solvents

Advantage Environmental Consultants, LLC (AEC) detected chlorinated solvents (tetrachloroethylene, trichloroethylene [TCE], 1,2 dichloroethane, and vinyl chloride[VC]) in a groundwater sample collected near the southeast corner of the subject site during a Phase II assessment conducted in 2005. The source of the chlorinated solvents is not known; however, Geomatrix, Inc. indicated an "asphalt pit" in this area of the subject site on Figure 3 of their Phase II assessment report completed in 1990. Chlorinated solvents detected in groundwater may also be due to migration from some unknown source



upgradient from the subject site. A groundwater sample collected by Haley & Aldrich in this area of the subject site (GTW-13-1A on the attached figure) confirmed the presence of minor contamination associated with chlorinated solvents, including relatively low concentrations of TCE and VC (43.9 and 38 micrograms per liter [μ g/L], respectively). The VC concentration exceeds the EPA Region III Risk-Based Screening Level (SL) for residential exposure via ingestion, which may not be applicable to the subject site. The extent of impact is not known, although volatile organic compounds were reportedly not detected in groundwater samples collected by AEC at several other locations in 2005, suggesting the extent may be limited to the southeast corner of the subject site.

SUSPECT RECOGNIZED ENVIRONMENTAL CONDITIONS

Consistent with ASTM E 1527-05 Section 12.5 (Report Format), and for the purposes of this assessment, those RECs that have been identified as being likely present with respect to the subject site are referred to as Suspect Recognized Environmental Conditions (SRECs). The Phase I assessment identified seven SRECs.

The following SREC was identified during our December 2013 subject site visit inside the on-site

storage building.

SREC #1: Heavy staining near floor drains in the on-site storage building

Potential Impact: Medium

Explanation: Heavy staining of the concrete floor appearing to be caused by hydrocarbons

was observed immediately surrounding two floor drains, one in the northwestern portion and a second in the southeastern portion of the building. Although no cracks were apparent in the concrete in the areas where staining was observed, it is unknown whether the source of the stains has also migrated into these floor drains or where the floor drains discharge. In addition, the source of the staining could have penetrated the concrete floor. A potential therefore exists for apparent hydrocarbon spills or leaks to have migrated to the

subsurface.

The following SRECs were observed on the adjacent property north of the subject site during a site visit by Haley & Aldrich for the comprehensive Phase I assessment of Buzzard Point in August 2013.

SREC #2: Potentially unlined/unpaved sump at Super Salvage Inc., 1711 1st Street SW

Potential Impact: Low
Explanation: On-site stormwater and spil

On-site stormwater and spills are captured and pumped to a sump in the southwestern portion of the lot before being disposed off-site by a licensed contractor. During a site visit to this property, the sump contained large quantities of oily liquid and it was not possible to ascertain whether the sump was lined and/or confirm the integrity of the lining. The site representative could not confirm the status of the sump lining. A potential therefore exists for hydrocarbons to migrate from the sump to the subsurface.



Heavy staining of concrete at Super Salvage Inc., 1711 1st Street SW **SREC #3:**

Potential Impact:

Low

Explanation: During the site visit to this property, heavy concrete staining was observed at

many locations. The concrete was in moderate to good condition where visible. In other areas, for example the area surrounding the sump's pump, the staining was too thick to confirm the integrity of the concrete. A potential therefore

exists for hydrocarbons to migrate to underlying soil and groundwater.

SREC #4: Oil layer in secondary containment under aboveground storage tanks (ASTs) at

Super Salvage Inc., 1711 1st Street SW

Potential Impact: Low

Explanation: A thick layer of oil was observed at the bottom of the AST tanks in the eastern

portion of this property. It is understood that the flooring of the containment is paved with concrete. However, the integrity of the concrete could not be A potential therefore exists for hydrocarbons to migrate to

underlying soil and groundwater.

SREC #5:

Concrete staining in area of an AST at Super Salvage Inc., 1711 1st Street SW

Potential Impact:

Explanation:

Concrete staining on paving next to an AST was observed in the northern portion of this property. The concrete paving was in relatively good condition. However a large quantity of waste had been dumped immediately adjacent to the AST preventing Haley & Aldrich representatives from confirming the

condition of the concrete beneath this waste. A potential exists for oil to migrate through the concrete to underlying soil and groundwater.

The following SRECs were identified on the adjacent properties east and south of the subject site.

SREC #6: Substation operations at Potomac Electric Power Company (PEPCO) Square

663. Lot 0024

Potential Impact: Medium

Explanation: Due to the age of the substation and the nature of activities taking place, there

is a potential for leaks, spills or polychlorinated biphenyl-containing materials

to be present at this lot.

SREC #7: Potentially leaking AST and underground pipeline at Potomac Electric Power

Company (PEPCO) Square 609, Lot 0804

Potential Impact: Low

Explanation: A #6 fuel oil AST was installed in the late 1960s at the property at Square

> 0609, Lot 0804; and Square 0611, Lots 19 and 10. An underground pipeline was used to connect the AST to the nearby Generating Station. The AST was decommissioned and the underground pipeline filled in 1981. No information regarding releases from the AST or pipeline is known. The site was also employed for bulk fuel storage and vehicle and equipment maintenance and storage. Two independent sampling programs conducted in 2005 indicated that soil and groundwater was affected by petroleum hydrocarbon releases. It is unknown whether more recent studies have been performed and whether soil

and groundwater are still impacted.



HISTORICAL RECs

The ASTM E 1527-05 Standard defines an HREC as an environmental condition "which in the past would have been considered a recognized environmental condition, but which may or may not be considered a recognized environmental condition currently." This Phase I assessment identified the following four HRECs.

HREC #1: Leaking Underground Storage Tank (LUST) case # 93094 for an on-site 20,000 gallon gasoline underground storage tank (UST) historically impacted soil and groundwater under the subject site and was reported in August 1993. The LUST case received regulatory closure in May 1994. Based on its status, impacts from the LUST do not present a threat to human health or the environment under current conditions and it is unlikely that the LUST will require additional regulatory action.

HREC #2: LUST case # 92076 on an adjacent parcel north of the subject site owned by Rollingwood Real Estate LLC at 1714 2nd St SW is associated with a gasoline LUST that historically impacted soil and groundwater. The status of the LUST release is listed as closed. Based on its status, impacts from the LUST do not present a threat to human health or the environment under current conditions and it is unlikely that the LUST will require additional regulatory action.

HREC #3: LUST case # 96030 on an adjacent parcel north of the subject site at 1711 1st Street SW, owned by Super Salvage, Inc., and related to a tank containing gasoline was reported to be impacting soil and was granted regulatory closure. Based on its status and impacts being limited to soil, impacts from the LUST do not present a threat to human health or the environment under current site conditions and it is unlikely that the LUST will require additional regulatory action.

HREC #4: LUST case # 93051 on an adjacent parcel east of the subject site in Square 663, Lot 0024, PEPCO Generating Station. In 1993, significant gasoline and diesel contamination was discovered in soil and groundwater on the northern portion of Square 665, Lot 0024. PEPCO performed monitoring and remediation activities during the 1990s, removing more than 1,000 gallons of liquid-phase hydrocarbons. However, the latest groundwater sampling data reviewed in a 2005 Phase I indicated that total petroleum hydrocarbons and benzene, toluene, ethylbenzene and xylenes were above applicable regulatory standards in certain monitoring wells. Based on its status, impacts from the LUST do not present a threat to human health or the environment under current site conditions and it is unlikely that the LUST will require additional regulatory action.

DE MINIMIS CONDITIONS

The ASTM E 1527-05 Standard defines *de minimis* conditions as those conditions which "do not present a threat to human health or the environment and that generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies." The ASTM E 1527-05 Standard notes that "conditions determined to be *de minimis* are not recognized environmental conditions."

This Phase I assessment revealed the following *de minimis* condition: during the subject site visit performed in August 2013, minor stains were observed on loose gravel west of the building in the northwestern portion of the lot maintained by the United States Park Police. On a subsequent subject site visit in December 2013, the staining was no longer visible. No odors or stressed vegetation were encountered during either visit, suggesting that the staining was superficial in nature and unlikely to have migrated to the subsurface.



SUMMARY AND RECOMMENDATIONS

In summary, several RECs were identified during the comprehensive Buzzard Point Phase I assessment in August 2013 and subsequent Phase II sampling. An additional REC was identified during the December 2013 subject site visit of the storage building (staining around floor drains), which could impact the proposed development. We recommend that the outfall location for the drains be determined and that additional soil and groundwater sampling be performed to assess the potential subsurface impact from staining observed around floor drains inside the storage building.

Limited Phase II subsurface sampling described in this report did not delineate the extent of petroleum impacts detected in soil or groundwater at the subject site, but based on the relatively low concentrations detected, it is our opinion that additional regulatory action is unlikely under current subject site conditions. However, if excavation and construction dewatering are necessary for subject site development, then proper handling of soil and groundwater may be required:

- Groundwater contaminated by gasoline and chlorinated solvents detected near the southeast corner of the site (in the vicinity of the former gasoline UST and "asphalt pit") may require treatment prior to discharge or off-site disposal. If a deep structure (i.e. subsurface parking garage) is constructed in this area of the subject site that requires long-term dewatering, then a treatment system may be required, along with appropriate maintenance, permitting, and monitoring.
- Minor petroleum-impacted soil associated with surface staining in the parking lot is not appropriate for unrestricted use as fill.
- Urban fill encountered at the north end of the subject site along S Street with minor petroleum impact and metals concentrations may not be appropriate for unrestricted use as fill.

We recommend developing a site-specific health and safety plan and a soil management plan to address proper handling of excavated soil. If groundwater will be encountered during the proposed development, then the soil management plan should include proper handling procedures for construction dewatering. Excavated soil may require characterization and treatment/off-site disposal. The District Department of the Environment (DDOE) may require submission of a Work Plan to document how the developer will comply with applicable standards.

Schedule impacts on the proposed development associated with the recommended tasks range from 3 to 6 months, depending upon DDOE review and approval. Potential order of magnitude cost impacts from the identified RECs on the proposed development range from \$60,000 to \$370,000 (see Table 3 for assumptions regarding these order of magnitude costs). Note that these cost ranges assume a nominal volume of soil (200 cubic yards) and groundwater (4,000 gallons) will require removal for the proposed development. We have assumed deep foundation designs that produce minimal soil and groundwater spoils. If shallow foundations or a subsurface structure is constructed on the site, requiring the removal of a greater volume of soil and groundwater than we have assumed, then we request the opportunity to revise our order of magnitude cost and schedule impacts accordingly.

The remainder of this report contains additional information regarding the Phase I assessment, the resulting findings summarized above, and limitations affecting this report.



TABLE OF CONTENTS

			rage			
		E SUMMARY	ii			
	COF TA		ix			
LIST	r of fi	GURES	ix			
1.	INTI	RODUCTION	1			
	1.1	Objective	1			
	1.2	Site Identification	2			
	1.3	Scope of Services	2			
	1.4	Non-Scope Considerations	2 2 3			
	1.5	Exceptions and Deviations	3			
2.	SITE	SITE DESCRIPTION				
	2.1	Site Ownership and Location	5 5			
	2.2	Site and Vicinity Description	5 5			
	2.3	Physical Setting	5			
3.	PRE	VIOUS REPORTS	7			
4.	SITE	CHISTORY	10			
5.	ENV	IRONMENTAL RECORDS REVIEW	12			
	5.1	Standard Environmental Records Review	12			
	5.2	Additional Environmental Records Review	15			
	5.3	User Responsibilities	16			
6.	SITE	RECONNAISSANCE AND KEY PERSONNEL INTERVIEW(S)	17			
	6.1	Subject Site Observations	17			
	6.2	Adjoining Property Observations	20			
7.	SUB	SUBSURFACE EXPLORATION				
	7.1	Geoprobe Sampling and Monitoring Well Installations 5 and 6 December 2012	21			
	7.2	Subsurface Findings	22			
8.	FINI	DINGS AND CONCLUSIONS	24			
9.		DENTIALS	30			
REF	ERENC	ES	31			
TAB	BLES					
	URES					
		A – Haley & Aldrich Proposal dated 28 June 2013				
		B – Historical Research DocumentationC – Site History				
		D – Regulatory Records Documentation				
		E - Site Photographs				
		F – Geoprobe Reports & Observation Well Installation Reports				
		G - Groundwater Sampling Records				

APPENDIX H – Laboratory Analytical Reports

LIST OF TABLES

Table No.	Title
1	Summary of Soil Quality Data
2	Summary of Groundwater Quality Data
3	Order of Magnitude Cost and Schedule Impacts from Identified RECs

LIST OF FIGURES				
Figure No.	Title			
1	Project Locus			
2	Site Plan			
3	Sampling Locations			



1. INTRODUCTION

This report presents the results of a Phase I environmental site assessment (Phase I assessment) and limited Phase II subsurface sampling conducted at the Akridge parcel at Buzzard Point, Square 0607, Lot 0013 in Washington, DC (herein referred to as the "subject site"). A Phase I assessment was conducted by Haley & Aldrich, Inc. (Haley & Aldrich) for seven parcels at Buzzard Point proposed for redevelopment as a professional soccer stadium, in accordance with our proposal to McKissack & McKissack dated 28 June 2013 ("Agreement", Appendix A). This report was prepared in response to a request from Mr. James Beall of McKissack & McKissack to provide a separate stand-alone Phase I assessment for the subject site. Limited Phase II subsurface sampling was also conducted on the subject site in accordance with our proposal dated 24 September 2013 ("Agreement", Exhibit 1) and subsequent modifications documented in a letter dated 18 December 2013 to McKissack & McKissack. This Phase I assessment was performed in conformance with the scope and limitations of the American Society of Testing and Materials (ASTM) E 1527-05 Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process (ASTM E 1527-05 Standard) to comply with 40 Code of Federal Regulations (CFR) Part 312 (the All Appropriate Inquiries [AAI] Rule).

1.1 Objective

The objective of a Phase I assessment is to identify known and suspect "recognized environmental conditions" (RECs), historical RECs (HRECs), and *de minimis* conditions associated with the subject site by evaluating subject site history, existing observable conditions, current subject site use, and current and former uses of adjoining properties as well as potential releases at surrounding properties that may impact the subject site. RECs are defined in the ASTM E 1527-05 Standard as "the presence or likely presence of any hazardous substances or petroleum products on a property under conditions that indicate an existing release, a past release, or a material threat of a release of any hazardous substances or petroleum products into structures on the property or into the ground, groundwater, or surface water at the property. The term includes hazardous substances or petroleum products even under conditions in compliance with laws. The term is not intended to include *de minimis* conditions that generally do not present a threat to human health or the environment and that generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies." A material threat is defined by the ASTM E 1527-05 Standard as "a physically observable or obvious threat which is reasonably likely to lead to a release that, in the opinion of the environmental professional, is threatening and might result in impact to public health or the environment."

Consistent with ASTM E 1527-05 Section 12.5 (Report Format), and for the purposes of this assessment, those RECs identified as being present with respect to the subject site are referred to as Known Recognized Environmental Conditions (KRECs), and those RECs identified as being likely present with respect to the subject site are referred to as Suspect Recognized Environmental Conditions (SRECs). The ASTM E 1527-05 Standard defines HRECs as environmental conditions "which in the past would have been considered a recognized environmental condition, but which may or may not be considered a recognized environmental condition currently."

The objective of the limited Phase II subsurface sampling was to provide a preliminary evaluation of RECs identified during the Phase I portion of the assessment, including order of magnitude cost and schedule implications on the proposed development. Our conclusions are intended to help the user evaluate the "business environmental risk" associated with the subject site, defined in the ASTM E 1527-05 Standard as "a risk which can have a material environmental or environmentally-



driven impact on the business associated with the current or planned use of a parcel of commercial real estate, not necessarily limited to those environmental issues required to be investigated in this practice. Consideration of business environmental risk issues may involve addressing one or more non-scope considerations..."

The completion of this Phase I assessment is only one component of the process required to satisfy the AAI Rule. In addition, the user must adhere to a set of user responsibilities as defined by the ASTM E 1527-05 Standard and the AAI Rule. User responsibilities are discussed in section 5.3 of this report. A user seeking protection from Comprehensive Environmental Response, Compensation and Liability Act (CERCLA) liability as an innocent landowner, bona fide prospective purchaser, or contiguous property owner must complete all components of the AAI process in addition to meeting ongoing obligations. AAI components, CERCLA liability relief, and ongoing obligations are discussed in the AAI Rule and in Appendix XI of the ASTM E 1527-05 Standard.

1.2 Site Identification

The subject site is owned by The John Akridge Companies, Inc. (Akridge) and comprises a parking lot and a building utilized for storing end-of-life passenger vehicles and a motorcycle. The subject site is surrounded by S Street SW to the north, T Street SW to the south, 1st Street SW to the east and 2nd Street SW to the west.

1.3 Scope of Services

Haley & Aldrich performed the following scopes of service to complete this Phase I assessment. These services were performed either by, or under the direct supervision of, an environmental professional as defined by the AAI Rule.

- 1. Conducted visual observations of site conditions, and of abutting property use, to evaluate the nature and type of activities that have been or are being conducted at and adjoining to the subject site, in terms of the potential for release or threat of release of hazardous substances or petroleum products.
- 2. Reviewed federal, state, tribal, and local environmental database information within the ASTM-specified distance from the subject site using a database service to access records. Used 7.5-minute topographic maps to evaluate the subject site's physical setting.
- 3. Reviewed District environmental files pertaining to the subject site and nearby sites with the potential to impact the subject site.
- 4. Reviewed previous reports prepared for the subject site.
- 5. Reviewed the following sources of historical use information: Sanborn maps, aerial photographs and topographic maps.
- 6. Contacted District agencies regarding the subject site and surrounding properties and structures.
- 7. Interviewed the key site manager and property tenant representatives.
- 8. Performed limited Phase II subsurface sampling and analysis.



9. Interpreted the information and data assembled as a result of the above work tasks, and formulated conclusions regarding the potential presence and impact of RECs, including HRECs.

1.4 Non-Scope Considerations

The ASTM E 1527-05 Standard includes the following list of "additional issues" that are non scope considerations outside of the scope of the ASTM Phase I assessment practice: asbestos-containing materials, radon, lead-based paint, lead in drinking water, wetlands, regulatory compliance, cultural and historic resources, industrial hygiene, health and safety, ecological resources, endangered species, indoor air quality, bio-agents, and mold. These items were not included in this Phase I assessment of the subject site.

A limited assessment of the presence of polychlorinated biphenyls (PCBs) is included in the ASTM work scope. Accordingly, our assessment of the presence of PCBs is limited to those potential sources specified in the ASTM E 1527-05 Standard as "electrical or hydraulic equipment known or likely to contain PCBs...to the extent visually and or physically observed or identified from the interview or records review."

1.5 Exceptions and Deviations

1.5.1 Deviations

Haley & Aldrich completed this Phase I assessment in substantial conformance with the ASTM E 1527-05 Standard. In our opinion, no additions were made to or deviations and deletions made from the ASTM work scope in completing this Phase I assessment.

1.5.2 Data Gaps

No data gaps were identified for this report. Thus, it is our opinion that sufficient information was obtained to identify subject site conditions indicative of releases or threatened releases of hazardous substances and petroleum hydrocarbons. Our opinion is limited by the conditions prevailing at the time our work was performed and the applicable regulatory requirements in effect.

1.5.3 Limitations

Our work for this project was performed in accordance with the standards and practices set forth in 40 CFR Part 312 and is consistent with the ASTM E 1527-05 Standard for Phase I Environmental Site Assessments. Several organizations other than ASTM, such as professional associations ASFE and AGWSE, have also developed guidelines or standards for environmental site assessments. The Phase I assessment presented in this report may vary from the specific guidelines or standards required by other organizations.

This Phase I assessment was prepared pursuant to an Agreement dated 9 July 2013 between McKissack & McKissack and Haley & Aldrich, which Agreement is attached hereto and is made a part of this report. The limited Phase II subsurface sampling was performed pursuant to an Agreement dated 30 October 2013 and a subsequent letter dated 18 December 2013 between McKissack & McKissack and Haley & Aldrich. All uses of this report are subject to, and



deemed accepting of, the conditions and restrictions contained in these Agreements. The observations and conclusions described in this report are based solely on the Scope of Services provided pursuant to these Agreements. Haley & Aldrich has not performed any additional observations, investigations, studies, or other testing not specified in these Agreements. Haley & Aldrich shall not be liable for the existence of any condition the discovery of which would have required the performance of services not authorized under these Agreements.

This report is prepared for the exclusive use of McKissack & McKissack and their prime contract holder, the District of Columbia Department of General Services (DGS) in connection with the proposed development of the subject site. A copy of this report will be provided to SW Landholder, LLC (Owner) in accordance with an Access Agreement between the Owner and Haley & Aldrich, dated 12 November 2013. There are no intended beneficiaries other than McKissack & McKissack. Haley & Aldrich shall owe no duty whatsoever to any other person or entity on account of the Agreements or the report. Use of this report by any person or entity other than McKissack & McKissack or the DGS for any purpose whatsoever is expressly forbidden unless such other person or entity obtains written authorization from McKissack & McKissack and from Haley & Aldrich. Use of this report by such other person or entity without the written authorization of McKissack & McKissack and Haley & Aldrich shall be at such other person's or entity's sole risk, and shall be without legal exposure or liability to Haley & Aldrich.

Use of this report by any person or entity, including by McKissack & McKissack, for a purpose other than for with the proposed development of the subject site is expressly prohibited unless such person or entity obtains written authorization from Haley & Aldrich indicating that the report is adequate for such other use. Use of this report by any person or entity for such other purpose without written authorization by Haley & Aldrich shall be at such person's or entity's sole risk and shall be without legal exposure or liability to Haley & Aldrich.

This report reflects subject site conditions observed and described by records available to Haley & Aldrich as of the date of report preparation. The passage of time may result in significant changes in subject site conditions, technology, or economic conditions, which could alter the findings and/or recommendations of the report. Accordingly, McKissack & McKissack and any other party to whom the report is provided recognize and agree that Haley & Aldrich shall bear no liability for deviations from observed conditions or available records after the time of report preparation.

Use of this report by any person or entity in violation of the restrictions expressed in this report shall be deemed and accepted by the user as conclusive evidence that such use and the reliance placed on this report, or any portions thereof, is unreasonable, and that the user accepts full and exclusive responsibility and liability for any losses, damages, or other liability which may result.



2. SITE DESCRIPTION

2.1 Site Ownership and Location

2.1.1 Name of Site Owners

SW Landholder, LLC owns the subject site.

2.1.2 Name of Site Operator

Akridge is the operator of the subject site.

2.1.3 Project Locus Map

The United States Geologic Survey (USGS) topographic map for the subject site is the Washington West, District of Columbia Quadrangle, dated 1983 (see Figure 1). The USGS topographic map was used as the source for subject site setting information.

2.2 Site and Vicinity Description

Figure 2 is a Site Plan of the subject site and shows relevant features of the subject site and immediately adjoining properties, as described below. The subject site comprises a parking lot and a small building in the northwestern portion utilized for end-of-life vehicle storage.

The area in the vicinity of the subject site is generally characterized as urban industrial and commercial.

- North: Rollingwood Real Estate and Super Salvage, Inc. Rollingwood Real Estate reportedly used to store and refurbish bicycles for the Washington DC Capital Bike Share Program. Super Salvage, Inc. operates a salvage yard for diverse metal structures.
- South: Marc/Park parking (a parking lot)
- West: National defense unit
- **East:** Potomac Electric Power Company (PEPCO) owns and operates an electrical substation.

2.3 Physical Setting

The subject site geology and hydrology were evaluated based on the results of the limited Phase II sampling (see Section 6 of this report) performed by Haley & Aldrich subsequent to the Phase I assessment, available public information or references, and upon our experience and understanding of subsurface conditions in the subject site area.

2.3.1 Topography

Topographically, the subject site and its vicinity are relatively flat with a gradual downward slope to the south. The subject site is at an elevation of approximately 21 feet above sea level (based on the Environmental Resources Data report).



2.3.2 Geology

Three borings were advanced under the subject site as part of the limited Phase II sampling in December 2013. Shallow soil under the site (to a depth of five feet below ground surface [bgs]) generally comprises sand and silt with some gravel and clay. Construction-related materials, including brick, glass, concrete fragments and possible asphalt or ash fill were encountered in shallow soil. Clay was generally observed to a depth of 29 feet bgs. Deeper soils to a depth of 40 feet bgs were comprised of clay, sand and/or gravel. According to information obtained from the Environmental Data Resources (EDR), Inc., report, bedrock beneath the subject site consists of a stratified sequence of Cretaceous–aged sedimentary rock.

Soils details in the subject site vicinity were not available, however, due to the proximity of the Anacostia River, alluvial sediments likely exists above the sedimentary rock. The subject site and vicinity are located in area comprised of urban land characterized by disturbed surface soils covered with structures and other impervious materials (pavement and concrete).

2.3.3 Hydrology

Based on surface topography, surface water from the subject site appears to flow in a southerly direction.

Also based on topography and the location of nearest water bodies (the Anacostia River, located approximately 0.15 miles east and 0.2 miles south and the Potomac River located approximately 0.3 miles west of the subject site), regional groundwater flow is anticipated to be tidally influenced. Hydrogeologic investigations were not performed at the subject site during this Phase I assessment and limited Phase II sampling; therefore, it is unknown to what extent localized variations in groundwater depth and flow occur on the subject site.

According to the Flood Insurance Rate Map supplied by EDR, the subject site is located within a floodplain. Potable water is supplied to the subject site by the District of Columbia Water and Sewer Authority. There is no known monitoring or pumping wells located on the property.



3. PREVIOUS REPORTS

The following reports previously prepared for the subject site and surrounding properties were reviewed for this Phase I assessment. Information contained in these reports is included herein and summarized below. Copies of pertinent sections of these reports are included in Appendix B.

- *Assessment of the Buzzard Point Properties," prepared by Geomatrix, Inc., for Potomac Electric Power Company, dated March 1990. *Note: This report included a multi-lot properties currently and formerly owned by PEPCO (including the subject site) located south of Potomac Avenue, North of V Street, east of 2nd Street, and west of Half Street. Only findings that may impact the condition of the subject site are discussed herein.*
- "Limited Phase II Environmental Investigation, Buzzard Point, 2nd Street SW / V Street SW, Washington, D.C.," prepared by URS Corporation, Inc. (URS), for Potomac Electric Power Company, dated 22 March 2005. *Note: This report included a multi-lot area, south of T Street, North of V Street, east of 2nd Street, and west of 1st Street. Only findings that may impact the condition of the subject site are discussed herein.*
- "Phase I Environmental Site Assessment, Buzzard Point, Squares 609 & 611, 2nd Street and V Street, SW, Washington, DC," prepared by URS for PEPCO Holdings Inc., dated 4 April 2005. Note: This report included a multi-lot area, south of T Street, North of V Street, east of 2nd Street, and west of 1st Street. Only findings that may impact the condition of the subject site are discussed herein.
- "Phase I Environmental Site Assessment, Buzzard Point, 2nd Street and V Street, SW, Washington, DC," prepared by Advantage Environmental Consultants, LLC (AEC), for The John Akridge Companies, Inc., dated 10 June 2005. *Note: This report included a multi-lot area located south of S Street, North of V Street, east of 2nd Street, and west of 1st Street. Only findings that may impact the condition of the subject site are discussed herein.*
- "Phase II Environmental Site Assessment, Buzzard Point, 2nd Street and V Street, SW, Washington, DC," prepared by AEC for The John Akridge Companies, Inc., dated 10 June 2005. Note: This report included a multi-lot area located south of S Street, North of V Street, east of 2nd Street, and west of 1st Street. Only findings that may impact the condition of the subject site are discussed herein.

Subject site: In 1990, Geomatrix collected soil samples for total petroleum hydrocarbon (TPH), benzene, toluene, ethylbenzene and xylenes (BTEX), PCBs, and toxicity metals. The subject site was identified as "Site 2" in the report and was being used as a gasoline filling station for PEPCO vehicles at the time of the investigation. Soil samples were collected from 0 to 2 feet bgs. Of the thirteen samples collected, ten showed TPH concentrations ranging from 100 ppm to 360 parts per million (ppm). Geomatrix concluded that TPH concentrations were fairly well distributed throughout the site.

At the time of the AEC 2005 Phase I, the subject site was used as a fenced parking lot with a prefabricated metal storage building and trailers. The subject site was used for vehicle fueling and storage by PEPCO from the late 1960s until 1993. Three Underground Storage Tanks (USTs) were located on-site:



- 6,000 gallon gasoline UST removed in 1988;
- 6,000 gallon diesel UST removed in 1988; and
- 20,000 gallon gasoline UST removed in 1993 and assigned Leaking Underground Storage Tank (LUST) case 93094 due to the discovery of petroleum impact to groundwater at the subject site during removal of the UST. Confirmatory soil samples were not significantly contaminated; however, groundwater samples were above regulatory limits. One monitoring well (MW-13) was later installed in this area. Petroleum concentrations in soil were below action limits at the time, although BTEX (1.77 milligrams per liter [mg/L]) and total petroleum hydrocarbons ([TPH]; 3.0 mg/L) were above action limits for groundwater. The LUST case received regulatory closure in May 1994.

In May 2005, AEC advanced borings (B-1 through B-9, B-27, B-29, and B-30) using Geoprobe rigs, screened soils with a photoionization detector, collected soil samples for total TPH diesel range organics (TPH DRO), TPH gasoline range organics (TPH GRO), Volatile Organic Compounds (VOCs), and priority pollutant metals, PCBs, metals, and ignitability, installed groundwater monitoring wells, and collected groundwater samples for TPH DRO, VOCs, and lead. Soil results indicated:

- TPH-DRO/GRO were below detection limits in soil except for DRO detected on the southwest corner of Lot 0013 at 11 ppm and DRO detected on the southeast corner of the subject site near the former USTs at 45 ppm.
- VOCs and PCBs were below detection limits.
- Lead was detected across Lot 0013 at concentrations below 170 ppm.

Groundwater samples indicated:

- TPH DRO and lead were below detection limits.
- VOCs detected on the southeast corner of the subject site near the former USTs included benzene and solvents.

PEPCO Generating Station, located immediately east of the subject site at Square 0665, Lot 0024 and Square 0661, Lot 0804: The AEC 2005 Phase I identified four LUST cases. In the early 1970s, a release was reported from a four-inch diameter underground pipeline that connected the Generating Station (Lot 0024) to the two, 0.411-million gallon #2 fuel oil aboveground storage tanks ([ASTs]; Lot 0804) under S Street. In 1993, significant gasoline and diesel contamination was discovered in soil and groundwater on the northern portion of Lot 0024.

Monitoring wells installed in both lots identified TPH GRO, TPH DRO, and BTEX in soil and monitoring wells as well as liquid-phase hydrocarbons (LPH). The groundwater flow direction was documented to be west and southwest.

In January 1996, PEPCO installed a soil vapor extraction system that operated through November 1999 that removed approximately 6,925 gallons of petroleum. From May 2001 to April 2002, a portable high vacuum pump and treat system was used to recover LPH from two of the most contaminated wells (MW-5 and MW-11), removing 1.5 gallons of groundwater and 1,350 gallons of petroleum. The site had been monitored monthly since 1993 with semi-annual sampling events. Results were reported to DC Department of Health (now DC Department of the Environment [DCDE]) in quarterly reports.



The AEC 2005 Phase I reviewed the March 2004 groundwater sampling data. TPH GRO, TPH DRO, and BTEX were above applicable regulatory standards except in three downgradient wells. Only passive remediation with absorbent booms and monitoring was ongoing.

Super Salvage, Inc. located immediately north of the subject site: These lots operated as a metal scrap yard since the 1960s. The URS and AEC 2005 Phase Is identified these lots on the RCRA Small Quantity Generator, LUST, and UST databases. One 2,000 gallon UST was permanently out of use. The LUST case was granted regulatory closure. No additional details were provided.

Square 0609, Lot 0804; Square 0611, Lots 19 & 10, located immediately southeast of the subject site: At the time of the URS and AEC 2005 Phase Is, these lots were used as a fenced parking lot with an unused 1.9-million gallon bulk #6 fuel oil AST installed in the late 1960s, an associated firefighting foam house, and a small storage shed. These lots were used as a coal storage yard from the late 1920s until the Generating Station began using fuel oil to power the station in 1968. From 1968 until the Generating Station was decommissioned in 1981, the lots were used by PEPCO for bulk fuel storage and leased to W.A. Chester for use as a vehicle and equipment maintenance and storage lot. An underground pipeline installed beneath 1st Street was used to connect the 1.9-million gallon AST to the Generating Station. The AST was decommissioned and the underground pipeline was filled in 1981. No information regarding releases from the AST or pipeline is known.

A URS sampling program conducted in 2005 indicated that soil and groundwater were affected by releases of petroleum hydrocarbons. No visual or olfactory evidence of contamination was observed, but laboratory analysis identified various levels of metals and TPH-DRO/GRO in soil and groundwater samples collected. An AEC sampling program conducted in 2005 also indicated that soil and groundwater were impacted by releases of petroleum hydrocarbons with low levels of TPH-DRO and lead detected.



4. SITE HISTORY

Past usage of the site and/or adjoining properties was assessed through a review of Sanborn maps dated 1928, 1959, 1977, 1984, 1988, 1990, 1991, 1992, 1994, and 1998; a review of aerial photographs dated 1944, 1949, 1951, 1957, 1963, 1968, 1970, 1977, 1983, 1988, 1994, 1998, 2000, 2005, 2007, 2008, 2009, 2011 and 2012; and topographic maps dated 1885, 1894, 1947, 1951, 1956, 1965, 1971, 1972, 1983 and 1994 prepared for the subject site (Appendix C).

By the late 1940s, the subject site was developed with residential properties. Grading of these properties took place between the late 1950s and the late 1960s. The subject site was observed to be vacant until 1970, at which time PEPCO operated a garage in the northwestern portion of the site. The remainder of the subject site was used for parking. By 2005, a small structure is shown in the northeastern corner of the subject site. This structure is no longer present in 2011.

The table below provides a detailed summary of pertinent information from the historical sources reviewed:

Dates	Description of Subject Site	Description of Adjoining Properties	Sources
The subject site was developed with residential properties. The dwellings on the subject site appear to have been graded by 1957.		North: residential dwellings and light commercial/industrial structures South: grading East: residential dwellings West: a commercial/industrial property	1949 and 1951 aerial photos
		North, east and west: the residential dwellings have been graded. Light commercial/industrial structures are still observed. By 1957, a substation is located southeast of the subject site. By 1968, two ASTs were observed on the property northeast of the subject site. These are later identified as fuel oil tanks on the 1984 Sanborn map. A truck parking lot was also observed in the east of the subject site.	1957, 1963 and 1968 aerial photos and 1984 Sanborn map



Dates	Description of Subject Site	Description of Adjoining Properties	Sources
		North: A parking garage and an associated office and a scrap metal yard reportedly owned by Onec are located adjacent to the subject site. South: an AST is located in the southern portion of the property immediately adjacent to the subject site. This AST is no	1970, 1977, 1983, 1988, 1994, 1998, 2000, 2005, 2007. 2008, 2009, 2011 and 2012 aerial photos and 1984, 1988, 1990, 1991, 1992, 1994 and 1998 Sanborn maps
1970-2012	PEPCO operates a garage in the northwestern portion of the subject site. The remainder of the subject site is used for parking.	longer present in 2007. East: According to the Sanborn map dated 1984, PEPCO is located east of the subject site. A transfer yard was observed south of the storage tanks on the PEPCO property. A conveyor yard is located southeast of the subject site. West: By 1983, the northern portion of the commercial/industrial property is no longer present and the footprint of this structure has	
		been graded. By 1988, the entire commercial/industrial structure adjacent to the subject site is no longer present. By 1998, a parking lot is located southwest of the subject site. This parking lot is no longer present in 2005. By 2007, a large commercial/industrial building was observed adjacent to the west of the subject site.	

Notes:

1. Unless otherwise noted above, per the ASTM standard, sources were reviewed dating back to 1940 or first developed use, whichever is earlier, and at five-year intervals if the use of the property has changed within that time period.

Copies of historical references reviewed are included in Appendix B.



5. ENVIRONMENTAL RECORDS REVIEW

5.1 Standard Environmental Records Review

Haley & Aldrich used the electronic database service Environmental Date Resources to complete the environmental records review. The database search was used to identify properties that may be listed in the referenced agency records, located within the ASTM-specified approximate minimum search distances as shown in the table below. Section 5.1.1 presents a description of each database searched.

Database Searched	Approximate Minimum Search Distance	Subject Site Listed?	Number of Sites within Search Distance
NPL Sites	1 mile	No	1
Delisted NPL Sites	0.5 mile	No	0
CERCLIS Sites	0.5 mile	No	1
CERCLIS-NFRAP Sites	0.5 mile	No	3
Federal ERNS	Site only	No	0
RCRA non-CORRACTS TSD Facilities	0.5 mile	No	0
RCRA CORRACTS TSD Facilities	1 mile	No	1
RCRA Generators	Site & Adjoining	Yes	4
Federal Institutional Controls/Engineering Controls	Site Only	No	0
State and Tribal Equivalent NPL Sites	1 mile	No	0
State and Tribal Equivalent CERCLIS Sites	0.5 mile	No	0
State and Tribal Registered Storage Tanks	Site & Adjoining	No	5
State and Tribal Landfills and Solid Waste Disposal Sites	0.5 mile	No	0
State and Tribal Leaking Storage Tanks	0.5 mile	Yes	33
State and Tribal Institutional Controls/Engineering Controls	Site Only	No	0
State and Tribal Voluntary Cleanup Sites	0.5 mile	No	1
State and Tribal Brownfield Sites	0.5 mile	Yes	13
DC Historical USTs	0.25 mile	Yes	7

The Environmental Data Resources (EDR) report also contains search results of other State environmental databases that are relevant to the subject site.

Haley & Aldrich also searched the Orphan Site List provided in the EDR report for the subject site and sites adjoining the subject site. Orphan sites are those that, due to incorrect or incomplete addresses,



could not be mapped. Neither the subject site not the adjoining properties were identified on the Orphan Site List. The complete environmental database report is provided in Appendix D.

5.1.1 Descriptions of Databases Searched

Numerous regulatory databases were searched during this Phase I assessment. Each database reviewed is described in the EDR report presented in Appendix D. Those databases required by the ASTM E 1527-05 Standard are identified below.

- 1. **NPL Sites:** The National Priorities List (NPL) is a list of contaminated sites that are considered the highest priority for cleanup by the U.S. Environmental Protection Agency (USEPA).
- 2. **Delisted NPL Sites:** The Delisted National Priorities List (NPL) is a list of formal NPL sites formerly considered the highest priority for cleanup by the USEPA that met the criteria of the National Oil and Hazardous Substances Pollution Contingency Plan (NCP) for deletion from the NPL because a no further response was appropriate.
- 3. **CERCLIS Sites:** The Comprehensive Environmental Response, Compensation, and Liability Act Information System (CERCLIS) list identifies sites which are suspected to have contamination and require additional investigation to assess whether they should be considered for inclusion on the NPL.
- 4. **CERCLIS-NFRAP Sites:** CERCLIS-NFRAP status indicates that a site was once on the CERCLIS List but has No Further Response Actions Planned (NFRAP). Sites on the CERCLIS-NFRAP List were removed from the CERCLIS List in February 1995 because, after an initial investigation was performed, no contamination was found, contamination was removed quickly, or the contamination was not significant enough to warrant NPL status.
- 5. **Federal ERNS:** The Federal Emergency Response Notification System (ERNS) list tracks information on reported releases of oil and hazardous materials.
- 6. **RCRA non-CORRACTS TSD facilities:** The Resource Conservation and Recovery Act (RCRA) non-CORRACTS TSD Facilities List tracks facilities which treat, store, or dispose of hazardous waste and are not associated with corrective action activity.
- 7. **RCRA CORRACTS TSD facilities:** The RCRA CORRACTS TSD Facilities list catalogues facilities that treat, store, or dispose of hazardous waste and have been associated with corrective action activity.
- 8. **RCRA Generators:** The RCRA Generator list is maintained by the USEPA to track facilities that generate hazardous waste.
- 9. **Federal Institutional Controls/Engineering Controls:** The Federal Institutional Control list and Engineering Control list are maintained by the USEPA. Some Institutional Control and Engineering Control information may not be made publicly available and therefore will not be included on this registry.



- 10. **State and Tribal Equivalent NPL/CERCLIS Sites:** The (ASTM E 1527-05 Standard) requires searching "State and Tribal Equivalent NPL Sites." A state equivalent to the Federal NPL list is not maintained in District of Columbia. The subject site is not within tribal jurisdiction.
- 11. **State and Tribal Equivalent CERCLIS Sites:** The (ASTM E 1527-05 Standard) requires searching "State and Tribal Equivalent CERCLIS Sites." A state equivalent to the Federal CERCLIS list is not maintained in District of Columbia. The subject site is not within tribal jurisdiction.
- 12. **State and Tribal Registered Storage Tanks:** The District of Columbia Department of the Environment maintains a list of aboveground and underground storage tanks. The subject site is not within tribal jurisdiction.
- 13. **State and Tribal Landfills and Solid Waste Disposal Sites:** The District of Columbia Solid Waste Disposal Division is responsible for waste disposal at facilities located in Virginia. The subject site is not within tribal jurisdiction.
- 14. **State and Tribal Leaking Storage Tanks:** The District of Columbia Department of the Environment maintains an inventory of reported leaking underground storage tank incidents. The subject site is not within tribal jurisdiction.
- 15. **State and Tribal Voluntary Cleanup Sites:** The District of Columbia Department of Health maintains a list of Voluntary Cleanup sites. The subject site is not within tribal jurisdiction.
- 16. **State and Tribal Brownfield Sites:** The District of Columbia Department of the Environment maintains a list of Brownfield sites which includes properties where redevelopment or re-use may be compromised by the presence or presumed presence of hazardous materials or petroleum. The subject site is not within tribal jurisdiction.
- 17. Other Databases Searched (Historical Cleaners and Auto Stations): EDR Proprietary Records include Historical Cleaners, a database that consists of potential dry cleaner sites; and Historical Auto Stations, available listings of potential gas station/filling station/service station sites.

5.1.2 Detailed Description of Relevant Subject Site Listings

The EDR report identified the following database listings in searched databases (including more databases than listed above) at the subject site.

100 S Street, SW (Square 0607, Lot 0013, Map ID # 1) is listed on the Brownfields database.

PEPCO Buzzard - Tank #1 located at 180 S Street, SW (Square 0607, Lot 0013, Map ID # A2) is listed on the LUST (case number 93094) and Brownfields databases. The site owned and operated a gasoline or diesel UST. A release from the UST was reported in August 1993 and reportedly impacted soil. The status of the release is listed as closed. Based on its status, impacts from the LUST do not present a threat to human health or the environment under current conditions and it is unlikely that the LUST will require additional regulatory action.



Buzzard Point Facility, also located at 180 S Street, SW (Square 0607, Lots 0013, Map ID # I36) is listed on the UST database. Three tanks storing gasoline are listed as Permanently Out of Use.

5.1.3 Detailed Descriptions of Relevant Nearby Site Listings

The EDR report identified database listings in searched databases (including more databases than listed above) within the prescribed search radii. The majority of the database listings were USTs and LUST sites. Based on the urban area of the site, characterized by subsurface building levels, subway tunnels, and utilities that create barriers to groundwater flow, and based on the assumption that the groundwater under the subject site is tidally influenced, only those sites in the immediate vicinity of the subject site would be anticipated to have the potential to affect the subject site. These sites are listed below.

PEPCO, located at 1st and T Street, SW (Map ID # 7), immediately east of the subject site and crossgradient of the subject site, is listed on the UST database. Two entries are included in this database for tanks of capacity 6,000 gallons and containing diesel. These entries are listed as Permanently Out of Use.

Super Salvage, Inc. located at 1711 1st Street, SW (Map ID # C9, C10 and C11), adjacent to the north and upgradient of the subject site, is listed on the LUST (case # 96030), UST and RCRA-CESQC databases. A tank containing gasoline was reported to be leaking in October 1995 and reportedly impacted soil. The status of this release is listed as Closed. A 2,000-gallon gasoline located at the site is listed as Permanently Out of Use. Additionally, this entity is listed as a Conditionally Exempt Small Quantity Generator for storing ignitable hazardous wastes, as well as waste cadmium, lead, benzene, methyl ethyl ketone, tetrachloroethylene (PCE), and trichloroethylene (TCE). No violations have been reported associated with this listing. Based on its status and impacts being limited to soil, impacts from the LUST do not present a threat to human health or the environment under current site conditions and it is unlikely that the LUST will require additional regulatory action

Attis located at 1714 2nd Street, SW (Square 0605, Lots 0007, Map ID # A3) and adjacent to the north and upgradient of the subject site, is listed on the UST database. The 3,500-gallon tank contained gasoline. The entry is listed as Permanently Out of Use. AT&T is also located at 1714 2nd Street, SW (Square 0605, Lots 0007, Map ID # A4) and is listed on the LUST (case # 92076) and Brownfield databases. The site owned and operated a 3,500 gallon gasoline UST. A release from the UST was reported in July 1992 and impacted soil and groundwater. The status of the release is listed as Closed. Based on its status, impacts from the LUST do not present a threat to human health or the environment under current conditions and it is unlikely that the LUST will require additional regulatory action.

An entry located at 1700 1st Street, SW (Map ID # C10), located approximately 300 feet northeast and crossgradient of the subject site, is listed on the Brownfield database. No additional details are provided.

5.2 Additional Environmental Records Review

To supplement the (ASTM E 1527-05 Standard) environmental record sources, we contacted the following state and local government agencies, and/or reviewed the following additional sources:



5.2.1 D.C. Department of the Environment

Additional environmental records were requested for this assessment through a Freedom of Information Act (FOIA) request to the DDOE. To date, no response has been received from the FOIA request. Due to the information obtained through interviews with key subject site personnel, and other records reviews, it does not appear that responses to the FOIA requests should affect our conclusions regarding the site. However, if a response is received that affects our conclusions regarding the subject site, we will provide an addendum to this report.

5.2.2 Fire and EMS Department

Additional environmental records were requested for this assessment through a FOIA request to the DC Fire and EMS Department. This department responded to our request on 27 December 2013. According to the files held by this department, operations taking place at the subject site and adjoining properties are unlikely to be impacting the subject site. A copy of the response from the DC Fire and EMS Department is included in Appendix D.

5.3 User Responsibilities

The AAI Rule requires that the user of the report consider the following:

- Whether the user has specialized knowledge about previous ownership or uses of the subject site that may be material to identifying RECs;
- Whether the user has determined that the subject site's Title contains environmental liens or other information related to the environmental condition of the property, including engineering and institutional controls and Activity and Use Limitations, as defined by ASTM;
- Whether the user is aware of commonly known or reasonably ascertainable information about the subject site including whether or not the presence of contamination is likely on the subject site and to what degree it can be detected; and
- Whether the user has prior knowledge that the price of the subject site has been reduced for environmentally related reasons.

We requested such information for inclusion in this report. Though neither the AAI Rule nor the ASTM E 1527-05 Standard requires that this information be provided to the environmental professional(s), failure on the part of the user to obtain such information for their own records, should it be reasonably ascertainable, may invalidate the user's compliance with the AAI Rule for CERCLA liability protection in the future.



6. SITE RECONNAISSANCE AND KEY PERSONNEL INTERVIEW(S)

A subject site visit to observe site conditions was conducted by Karin Holland and Christian-Noel Tschibelu of Haley & Aldrich on 28 August 2013. Access to the building located in the northwestern portion of the subject site was provided to Karin Holland on 23 December 2013. Access to the subject site was provided by Terrance Jones of Akridge and by Lieutenant Mike Wilson of the US Capitol Police. Haley & Aldrich personnel observed accessible interior areas of the subject site building(s), including common areas, basement areas, mechanical spaces, and tenant spaces. Haley & Aldrich also observed the exterior portions of the subject site, including the property boundaries, and observed adjoining property conditions from the subject site boundaries and/or public thoroughfares. No weather-related conditions or other conditions that would limit our ability to observe the subject site or adjoining properties occurred during our subject site visit.

Terrance Jones and Mike Wilson were interviewed during the subject site visits. The findings of the subject site visit and interviews are discussed below. Site photographs are included in Appendix E.

ASTM E 1527-05 Standard Section 10.8 requires that, prior to the subject site visit, the current subject site owner or key site manager and user, if different from the current owner or key site manager, be asked if there are any helpful documents that can be made available for review. These consist of environmental site assessment reports, audits, permits, tank registrations, Material Safety Data Sheets, Community Right-to-Know plans, safety plans, hydrogeologic or geotechnical reports, or hazardous waste generator reports. We made such a request but were not provided with any documents.

6.1 Subject Site Observations

6.1.1 Current Use of the Property and General Description of Structures

The subject site is operated by Akridge and comprises an asphalt parking lot and a building that stores end-of-life vehicles, including passenger vehicles and a motorcycle. Three metal containers are located in the northern portion of the subject site. The Akridge site representative believed that the subject site has been used for current activities for at least ten years.

6.1.2 Potable Water Supply and Sewage Disposal System or Septic Systems

The subject site is not connected to a potable water supply and a sewage disposal system.

6.1.3 Use and Storage of Petroleum Products and Hazardous Materials

Bulk petroleum products and/or hazardous materials were not observed or reported to be currently used, stored, and/or disposed of at the subject site. However, petroleum and hazardous materials were previously used and stored at the subject site, as described below:



Tank #	AST/ UST	Contents/ Capacity	Location ¹	Use	Closure Status	Observations/ Evidence of release	
9	LUST (case # 93094)	Gasoline, 20,000 gallon	Unknown	Unknown	Out of use, listed as Closed	A loose gravel and vegetated area was observed in the	
10	UST	Gasoline, 6,000 gallon	Unknown	Unknown	Removed in 1988	western portion of the subject site and	
11	UST	Diesel, 6,000 gallon	Unknown	Unknown	Removed in 1988	could be the potential location of one of the former USTs.	

Notes:

Three small, empty cylinders were observed in the building. The former contents of these containers are unknown.

6.1.4 Disposal of Petroleum Products and Hazardous Materials

Petroleum products and hazardous materials were not observed at the subject site.

6.1.5 Odors

No odors were detected at the subject site during the subject site visits in August and December 2013. However, a hydrocarbon-like odor was encountered during the limited Phase II sampling at depths of approximately seven to eleven feet bgs in a borehole (GTW-607-13-2, see Section 6) advanced in the northeastern portion of the subject site.

6.1.6 PCBs Associated with Electrical or Hydraulic Equipment

Due to the nature of activities, PCB-containing materials are unlikely to be present at the subject site.

6.1.7 Unidentified Substance Containers

Three small, empty jerry cans were observed in the building. The former contents of these containers are unknown.

6.1.8 Heating and Cooling System

The subject site is not equipped with a heating or cooling system.

6.1.9 Stains or Corrosion on Floors, Walls, or Ceilings

Staining believed to be associated with hydrocarbon spills was observed on the concrete floor inside the building. The concrete was observed to be in good condition.



^{1.} Approximate tank locations are shown on Figure 2.

6.1.10 Floor Drains and Sumps

Two floor drains were observed in the building, one in the northwestern portion and a second in the southeastern portion of the building. Heavy staining appearing to be caused by hydrocarbons was observed on concrete surrounding the floor drains. Although no cracks were apparent in the concrete in the areas where staining was observed, it is unknown whether the source of the stains has also migrated into these floor drains or where the floor drains discharge. In addition, the source of the staining could have penetrated the concrete floor.

At least three drains were also observed in the southern portion of the parking lot.

6.1.11 Hydraulic Elevators

No hydraulic elevators were observed or reported at the subject site.

6.1.12 Vehicle Maintenance Lifts

No hydraulic vehicle maintenance lifts were observed or reported at the subject site.

6.1.13 Emergency Generators and Sprinkler System Pumps

No emergency generators and sprinkler system pumps were observed or reported at the subject site.

6.1.14 Catch Basins

No catch basins were observed or reported at the subject site.

6.1.15 Dry Wells

Dry wells were not observed or reported at the subject site.

6.1.16 Pits, Ponds, Lagoons, and Pools of Liquid

Pits, Ponds, Lagoons, and Pools of Liquid were not observed or reported at the subject site.

6.1.17 Stained Soil or Pavement

Minor stains appearing to be caused by hydrocarbons were observed on asphalt in the northern and central portions of the subject site. During the site visit in August 2013, minor stains were observed on loose gravel west of the building in the northwestern portion of the lot. On the subsequent subject site visit in December 2013, the staining was no longer visible. No odors or stressed vegetation was encountered during either visit, suggesting that the staining was superficial in nature and is unlikely to have migrated to the subsurface.

6.1.18 Stressed Vegetation

Grasses, shrubs and small trees were observed in the northwest portion of the subject site to the building. Evidence of stressed vegetation was not observed.



6.1.19 Solid Waste and Evidence of Waste Filling

Evidence of solid waste and waste filling was not observed. Storage of waste cloths and packaging was observed in the western portion of the building.

6.1.20 Wastewater and Stormwater Discharge

The subject site does not generate wastewater.

6.1.21 Monitoring, Water Supply, or Irrigation Wells

Monitoring, water supply, and irrigation wells were not observed or reported at the subject site.

6.1.22 Sanitary Sewer and Septic Systems

Septic systems were not observed or reported at the subject site.

6.2 Adjoining Property Observations

Properties adjoining the subject site were generally observed to be light industrial or commercial in nature.



7. SUBSURFACE EXPLORATION

In order to evaluate subsurface conditions of the subject site and assess whether current and former operation at and adjacent to the subject site are impacting the subject site, Haley & Aldrich conducted a limited Phase II subsurface assessment at the subject site. The approximate locations of explorations are shown on Figure 3.

7.1 Geoprobe Sampling and Monitoring Well Installations 5 and 6 December 2012

On 5 and 6 December 2012, Haley & Aldrich oversaw the advancement of temporary groundwater monitoring wells at two locations (see Figure 3) at the subject site by Vironex Drilling, Inc. Two wells were initially advanced to approximate depths of 23.5 and 15 feet bgs (GTW-607-13-1 and GTW-607-13-2, respectively); however, the clay formation encountered within the screened interval of these wells did not provide adequate yield of groundwater for collection of the proposed analyses. Adjacent, deeper wells (GTW-607-13-1A and GTW-607-13-2A) were therefore advanced to approximate depths of 36 and 34.7 feet bgs. GTW-607-13-1 is located in the vicinity of the on-site 20,000 gallon gasoline LUST (case # 93094) in the southeastern portion of the subject site and GTW-607-13-2 is located along S Street at the north end of the site (topographically down-gradient from the Super Salvage property). An additional Geoprobe (GSS-607-13-3) was advanced in the central portion of the subject site in the vicinity of observed staining of asphalt.

Geoprobe reports and observation well installation reports are included in Appendix F.

7.1.1 Soil Sampling 5 December 2013

Soil samples collected during the advancement of the temporary groundwater monitoring wells (GTW-607-13-1 and GTW-607-13-2) and the Geoprobe (GSS-607-13-3) were screened for VOCs by exposing a photoionization detector (PID) to vapors accumulated in the headspace of jar samples. The soil sample corresponding to the highest PID reading from each boring was submitted for laboratory analysis. Samples collected for TPH-GRO and VOCs were field preserved using VOC sampling kits. The soil samples were placed on ice in the field prior to being shipped via overnight courier to Pace Analytical Services, Inc. (Pace) in Huntersville, North Carolina. Priority pollutant metals analyses were performed at the Pace laboratory in Asheville, North Carolina, while TPH, VOCs and semi-volatile organic compounds (SVOCs) analyses were performed at the Pace laboratory in Charlotte, North Carolina.

7.1.2 Groundwater Sampling 12 and 13 December 2012

Monitoring well GTW-607-13-1A was sampled using low-flow sampling techniques on 12 December 2012. The following groundwater quality parameters were monitored and recorded prior to sampling: pH, temperature, conductivity, dissolved oxygen, oxidation-reduction potential, and turbidity. Wells GTW-607-13-1, GTW-70-13-2 and GTW-607-13-2A did not provide sufficient yield for low-flow sampling; these wells were therefore purged and allowed to recover for sampling within 24 hours. No evidence of free product or sheens were observed in groundwater from the sampled monitoring wells or detected using an electronic oilwater interface probe. Groundwater sampling records are included in Appendix G. Groundwater samples were collected and placed in laboratory prepared containers and stored on



ice in the field prior to being submitted for TPH and VOCs analyses at the Pace laboratory in Charlotte, North Carolina.

7.2 Subsurface Findings

Subsurface investigations described in this report did not define the lateral extent of petroleum impacts to soil or groundwater at the subject site. The objective was to explore SRECs and KRECs to evaluate current conditions to assess the general magnitude of potential impacts.

7.2.1 Soil Results

Soil analytical results are summarized in Table 1, along with regulatory screening levels for comparison. Laboratory analytical reports are included in Appendix H.

Analytical results for a soil sample collected near the southeastern corner of the subject site (GTW-607-13-1-3) from a depth of 10 to 15 feet bgs in the area of the former 20,000-gallon gasoline UST were less than the laboratory reporting limits for VOCs, SVOCs, TPH-GRO, and TPH-DRO. Arsenic (7.1 mg/kg) and chromium (18.2 mg/kg) were detected at concentrations exceeding the EPA Region III Risk-Based Screening Levels for residential soil.

Analytical results for a soil sample collected at the north end of the subject site (GTW-607-13-2-2, located along S Street) from a depth of 5 to 10 feet bgs indicated minor petroleum impact (TPH-DRO and PAHs). The TPH-DRO concentration detected (119 mg/kg) slightly exceeds the DC Tier 0 Soil Standard for TPH of 100 mg/kg. Benzo(a)pyrene was detected at 8.67 mg/kg, slightly exceeding the DC Risk-Based Corrective Action (DCRBCA) Screening Levels for construction worker exposure of 5.92 mg/kg. Other PAHs, along with arsenic (4.8 mg/kg) and chromium (10.3 mg/kg) were detected at concentrations exceeding the EPA Region III Risk-Based Screening Levels for residential soil. The source and extent of impact is currently not known, although brick, concrete fragments, glass, wood and apparent ash or asphalt (typical of urban fill) was encountered in this boring, which commonly yields similar results.

Analytical results for a soil sample collected from beneath the asphalt in an area of staining on the parking lot in the central portion of the subject site (GSS-607-13-3-1) indicated minor petroleum impact. The TPH-DRO concentration detected in GTW-607-13-3-1 (184 mg/kg) exceeds the DC Tier 0 Soil Standard for TPH of 100 mg/kg. The extent of vertical impact is currently not known, although based on the relatively low concentration immediately beneath the staining, the degree of impact appears to be minor. Brick and apparent asphalt debris, typical of urban fill were also observed in this sample.

7.2.2 Groundwater Results

Groundwater analytical results are summarized in Table 2, along with regulatory screening levels for comparison. Laboratory analytical reports are included as Appendix H.

Analytical results for groundwater collected from GTW-607-13-1A, located in the southeastern portion of the subject site, were generally consistent with findings from the 2005 AEC Phase II assessment, with gasoline-related constituents (TPH-GRO at 2.1 mg/L, benzene at 10.2 micrograms per liter [μ g/L] and methyl tertiary butyl ether [MTBE] at 38 μ g/L) and relatively low concentrations of chlorinated solvents (TCE at 43.9 μ g/L and vinyl chloride (VC)



at 38 μ g/L). MTBE (54 μ g/L) and acetone (115 μ g/L) were also detected in groundwater collected from GTW-607-13-1, the shallow well adjacent to GTW-607-13-1A. The gasoline-related constituents are likely associated with the former 20,000-gallon gasoline UST in this area of the site. The source for the chlorinated solvents is not known, but may be related to a former "asphalt pit" identified on a site figure in a 1990 Geomatrix report or may have migrated from some other unknown off-site source. The extent of impact is was not delineated during our sampling, however volatile organic compounds were reportedly not detected in several other groundwater samples collected by AEC at the subject site in 2005, suggesting that the extent may be limited to the southeast corner.

The groundwater analytical results for GTW-607-2 and GTW-607-2A, located at the north end of the site along S Street, were less than the laboratory reporting limits for TPH-DRO, TPH-GRO, and VOCs, with the exception of acetone, which was detected at concentrations of 79 and 625 μ g/L, respectively.



8. FINDINGS AND CONCLUSIONS

Haley & Aldrich performed a Phase I environmental site assessment (Phase I assessment) of the Akridge parcel at Buzzard Point, Square 0607, Lot 0013 in Washington, DC. The scope of work is described and conditioned by our proposal dated 28 June 2013. As indicated in our proposal, this Phase I assessment was performed in conformance with the scope and limitations of the American Society for Testing and Materials (ASTM) E 1527-05 Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process (ASTM E 1527-05 Standard) as referenced in 40 Code of Federal Regulations (CFR) Part 312 [the All Appropriate Inquiries (AAI) Rule]. Deviations from this Standard, and/or data gaps and their significance are described in Section 1.5 of this report. Limited Phase II subsurface sampling was also conducted to evaluate issues identified during the Phase I portion of the assessment. Our conclusions are intended to help the user evaluate the "business environmental risk" associated with the subject site, as defined in the ASTM E 1527-05 Standard and discussed in Section 1.1 of this report.

The subject site is bound by 1^{st} , 2^{nd} , S, and T Streets SW, and comprises a parking lot and a single-level storage building. The building is utilized to store end-of-life passenger vehicles and a motorcycle.

The objective of a Phase I assessment is to identify known and suspect "recognized environmental conditions" (RECs), historical RECs (HRECs), and *de minimis* conditions associated with the subject site, as defined in the ASTM E 1527-05 Standard and in Section 1.1 of this report. The objective of the limited Phase II subsurface sampling is to provide a preliminary evaluation of RECs identified during the Phase I portion of the assessment, including order of magnitude cost and schedule impacts on the proposed development.

The ASTM E 1527-05 Standard requires an environmental professional's opinion of the potential impacts of RECs, HRECs, and *de minimis* conditions identified on a site during a Phase I assessment. Our opinion is rendered with respect to an REC's potential (high, medium, or low) to require remedial response based on prevailing agency requirements and our understanding that the subject site is one of seven parcels being evaluated for potential redevelopment as a professional soccer stadium. Our opinion regarding a REC's potential impact on the subject site (high, medium, low, or unknown) is based on the scope of our work, the information obtained during the course of our work, the conditions prevailing at the time our work was performed, the applicable regulatory requirements in effect at the time our work was performed, and/or our experience evaluating similar sites, and our understanding of the client's intended use for the subject site.

Data gaps were not identified for this report.

RECOGNIZED ENVIRONMENTAL CONDITIONS

The ASTM E 1527-05 Standard defines a REC as "the presence or likely presence of any hazardous substances or petroleum products on a property under conditions that indicate an existing release, a past release, or a material threat of a release of any hazardous substances or petroleum products into structures on the property or into the ground, ground water, or surface water of the property." A material threat is defined by the ASTM E 1527-05 Standard as "a physically observable or obvious threat which is reasonably likely to lead to a release that, in the opinion of the environmental professional, is threatening and might result in impact to public health or the environment."



This Phase I assessment identified 13 RECs. Details regarding the nature of these RECs and our opinion regarding potential impacts are provided below.

KNOWN RECOGNIZED ENVIRONMENTAL CONDITIONS

Consistent with ASTM E 1527-05 Section 12.5 (Report Format), and for the purposes of this assessment, those RECs identified as being present with respect to the subject site are referred to as Known Recognized Environmental Conditions (KRECs). Two KRECs have been identified on the subject site from the limited Phase II subsurface sampling results.

KREC #1: Potential Impact: Explanation: Shallow subsurface petroleum impact from surface staining or urban fill

Low

Apparent hydrocarbon stains were observed on the asphalt-paved portion of the subject site utilized as a parking lot. A crack was observed in the asphalt under one of these stains and a soil sample (GSS-607-13-1, see Figure 3) collected by Haley & Aldrich from beneath the asphalt revealed a total petroleum hydrocarbons – diesel range organics (TPH-DRO) concentration of 184 milligrams per kilogram (mg/kg). This TPH-DRO detection confirms the presence of minor petroleum contamination in shallow soil, exceeding the D.C. Municipal Regulations (DCMR) Tier 0 Soil Standard for TPH of 100 mg/kg. The vertical extent of impact is not known, although based on the relatively low concentration immediately beneath the staining, the degree of impact appears to be minor. The TPH-DRO detection may also be related to urban fill encountered in this boring.

Analytical results for a soil sample collected along S Street (GTW-607-13-2, see Figure 3) from a depth of 5 to 10 feet below grade indicated minor petroleum impact (TPH-DRO at 119 mg/kg). This TPH-DRO detection confirms the presence of minor petroleum contamination in shallow soil, exceeding the DCMR Tier 0 Soil Standard for TPH of 100 mg/kg. Benzo(a)pyrene was also detected at 8.67 mg/kg, slightly exceeding the DC Risk-Based Corrective Action (DCRBCA) Screening Levels (SL) for construction worker exposure of 5.92 mg/kg. Other PAHs and metals (arsenic at 4.8 mg/kg and chromium at 10.3 mg/kg) were detected at concentrations exceeding the EPA Region III Risk-Based Screening Level (RSLs) for residential soil. The source and extent of impact is not known, although urban fill was encountered in this boring, which commonly yields similar results.

KREC #2: Potential Impact: Explanation:

Minor groundwater contamination associated with chlorinated solvents

Low

AEC detected chlorinated solvents (PCE, TCE, 1,2-dichloroethane, and VC) in a groundwater sample collected near the southeast corner of the subject site during a Phase II assessment conducted in 2005. The source of the chlorinated solvents is not known; however, Geomatrix, Inc. indicated an "asphalt pit" in this area of the subject site on Figure 3 of their Phase II assessment report completed in 1990. Chlorinated solvents detected in groundwater may also be due to migration from some unknown source upgradient from the subject site. A groundwater sample collected by Haley & Aldrich in this area of the subject site (GTW-13-1A on the attached figure) confirmed the presence of minor



contamination associated with chlorinated solvents, including relatively low concentrations of TCE and VC (43.9 and 38 μ g/L, respectively). The VC concentration exceeds the EPA Region III Risk-Based Screening Level for residential exposure via ingestion, which may not be applicable to the subject site. The extent of impact is currently not known, although volatile organic compounds were reportedly not detected in groundwater samples collected by AEC at several other locations in 2005, suggesting the extent may be limited to the southeast corner of the subject site.

SUSPECT RECOGNIZED ENVIRONMENTAL CONDITIONS

Consistent with ASTM E 1527-05 Section 12.5 (Report Format), and for the purposes of this assessment, those RECs that have been identified as being likely present with respect to the subject site are referred to as Suspect Recognized Environmental Conditions (SRECs). The Phase I assessment identified seven SRECs.

The following SREC was identified during our December 2013 subject site visit inside the on-site

storage building.

SREC #1: Heavy staining near floor drains in the on-site storage building

Potential Impact: Medium

Explanation: Heavy staining of the concrete floor appearing to be caused by hydrocarbons

was observed immediately surrounding two floor drains, one in the northwestern portion and a second in the southeastern portion of the building. Although no cracks were apparent in the concrete in the areas where staining was observed, it is unknown whether the source of the stains has also migrated into these floor drains or where the floor drains discharge. In addition, the source of the staining could have penetrated the concrete floor. A potential therefore exists for apparent hydrocarbon spills or leaks to have migrated to the

subsurface.

The following SRECs were observed on the adjacent property north of the subject site during a site visit by Haley & Aldrich for the comprehensive Phase I assessment of Buzzard Point in August 2013.

SREC #2: Potentially unlined/unpaved sump at Super Salvage Inc., 1711 1st Street SW

Potential Impact: Lo

Explanation: On-site stormwater and spills are captured and pumped to a sump in the

southwestern portion of the lot before being disposed off-site by a licensed contractor. During a site visit to this property, the sump contained large quantities of oily liquid and it was not possible to ascertain whether the sump was lined and/or confirm the integrity of the lining. The site representative could not confirm the status of the sump lining. A potential therefore exists for

hydrocarbons to migrate from the sump to the subsurface.

SREC #3: Heavy staining of concrete at Super Salvage Inc., 1711 1st Street SW

Potential Impact: Low

Explanation: During the site visit to this property, heavy concrete staining was observed at

many locations. The concrete was in moderate to good condition where visible. In other areas, for example the area surrounding the sump's pump, the staining



was too thick to confirm the integrity of the concrete. A potential therefore exists for hydrocarbons to migrate to underlying soil and groundwater.

SREC #4: Oil layer in secondary containment under ASTs at Super Salvage Inc., 1711 1st

Street SW

Potential Impact: Low

Explanation: A thick layer of oil was observed at the bottom of the AST tanks in the eastern

portion of this property. It is understood that the flooring of the containment is paved with concrete. However, the integrity of the concrete could not be confirmed. A potential therefore exists for hydrocarbons to migrate to

underlying soil and groundwater.

SREC #5:

Concrete staining in area of an AST at Super Salvage Inc., 1711 1st Street SW

Potential Impact:

Low

Explanation: Concrete staining on paving next to an AST was observed in the northern

portion of this property. The concrete paving was in relatively good condition. However a large quantity of waste had been dumped immediately adjacent to the AST preventing Haley & Aldrich representatives from confirming the condition of the concrete beneath this waste. A potential exists for oil to

migrate through the concrete to underlying soil and groundwater.

The following SRECs were identified on the adjacent properties east and south of the subject site.

SREC #6: Substation operations at Potomac Electric Power Company (PEPCO) Square

663, Lot 0024

Potential Impact:

Medium

Explanation:

Due to the age of the substation and the nature of activities taking place, there is a potential for leaks, spills or PCB-containing materials to be present at this

lot.

SREC #7: Potentially leaking AST and underground pipeline at Potomac Electric Power

Company (PEPCO) Square 609, Lot 0804

Potential Impact:

Explanation:

Low

A #6 fuel oil AST was installed in the late 1960s at the property at Square 0609, Lot 0804; and Square 0611, Lots 19 and 10. An underground pipeline was used to connect the AST to the nearby Generating Station. The AST was decommissioned and the underground pipeline filled in 1981. No information regarding releases from the AST or pipeline is known. The site was also employed for bulk fuel storage and vehicle and equipment maintenance and storage. Two independent sampling programs conducted in 2005 indicated that soil and groundwater was affected by petroleum hydrocarbon releases. It is unknown whether more recent studies have been performed and whether soil

and groundwater are still impacted.

HISTORICAL RECs

The ASTM E 1527-05 Standard defines an HREC as an environmental condition "which in the past would have been considered a recognized environmental condition, but which may or may not be



considered a recognized environmental condition currently." This Phase I assessment identified the following four HRECs.

HREC #1: LUST case # 93094 for an on-site 20,000 gallon gasoline UST historically impacted soil and groundwater under the subject site and was reported in August 1993. The LUST case received regulatory closure in May 1994. Based on its status, impacts from the LUST do not present a threat to human health or the environment under current conditions and it is unlikely that the LUST will require additional regulatory action.

HREC #2: LUST case # 92076 on an adjacent parcel north of the subject site owned by Rollingwood Real Estate LLC at 1714 2nd St SW is associated with a gasoline LUST that historically impacted soil and groundwater. The status of the LUST release is listed as closed. Based on its status, impacts from the LUST do not present a threat to human health or the environment under current conditions and it is unlikely that the LUST will require additional regulatory action.

HREC #3: LUST case # 96030 on an adjacent parcel north of the subject site at 1711 1st Street SW, owned by Super Salvage, Inc., and related to a tank containing gasoline was reported to be impacting soil and was granted regulatory closure. Based on its status and impacts being limited to soil, impacts from the LUST do not present a threat to human health or the environment under current site conditions and it is unlikely that the LUST will require additional regulatory action.

HREC #4: LUST case # 93051 on an adjacent parcel east of the subject site in Square 663, Lot 0024, PEPCO Generating Station. In 1993, significant gasoline and diesel contamination was discovered in soil and groundwater on the northern portion of Square 665, Lot 0024. PEPCO performed monitoring and remediation activities during the 1990s, removing more than 1,000 gallons of LPH. However, the latest groundwater sampling data reviewed in a 2005 Phase I indicated that total petroleum hydrocarbons and benzene, toluene, ethylbenzene and xylenes were above applicable regulatory standards in certain monitoring wells. Based on its status, impacts from the LUST do not present a threat to human health or the environment under current site conditions and it is unlikely that the LUST will require additional regulatory action.

DE MINIMIS CONDITIONS

The ASTM E 1527-05 Standard defines *de minimis* conditions as those conditions which "do not present a threat to human health or the environment and that generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies." The ASTM E 1527-05 Standard notes that "conditions determined to be *de minimis* are not recognized environmental conditions."

This Phase I assessment identified the following *de minimis* condition: during the subject site visit performed in August 2013, minor stains were observed on loose gravel west of the building in the northwestern portion of the lot maintained by the United States Park Police. On a subsequent site visit in December 2013, the staining was no longer visible. No odors or stressed vegetation were encountered during either visit, suggesting that the staining was superficial in nature and unlikely to have migrated to the subsurface.



SUMMARY AND RECOMMENDATIONS

In summary, several RECs were identified during the comprehensive Buzzard Point Phase I assessment in August 2013 and subsequent Phase II sampling. An additional REC was identified during the December 2013 subject site visit of the storage building (staining around floor drains), which could impact the proposed development. We recommend that the outfall location for the drains be determined and additional soil and groundwater sampling be performed to assess the potential subsurface impact from staining observed around floor drains inside the storage building.

Limited Phase II subsurface sampling described in this report did not delineate the extent of petroleum impacts detected in soil or groundwater at the subject site, but based on the relatively low concentrations detected, it is our opinion that additional regulatory action is unlikely under current subject site conditions. However, if excavation and construction dewatering are necessary for subject site development, then proper handling of soil and groundwater may be required:

- Groundwater contaminated by gasoline and chlorinated solvents detected near the southeast corner of the site (in the vicinity of the former gasoline UST and "asphalt pit") may require treatment prior to discharge or off-site disposal. If a deep structure (i.e. subsurface parking garage) is constructed in this area of the subject site that requires long-term dewatering, then a treatment system may be required, along with appropriate maintenance, permitting, and monitoring.
- Minor petroleum impacted soil associated with surface staining in the parking lot is not appropriate for unrestricted use as fill.
- Urban fill encountered at the north end of the subject site along S Street with minor petroleum impact and metals concentrations may not be appropriate for unrestricted use as fill.

We recommend developing a site-specific health and safety plan and a soil management plan to address proper handling of excavated soil. If groundwater will be encountered during the proposed development, then the soil management plan should include proper handling procedures for construction dewatering. Excavated soil may require characterization and treatment/off-site disposal. The District Department of the Environment (DDOE) may require submission of a Work Plan to document how the developer will comply with applicable standards.

Schedule impacts on the proposed development associated with the recommended tasks range from 3 to 6 months, depending upon DDOE review and approval. Potential order of magnitude cost impacts from the identified RECs on the proposed development range from \$60,000 to \$370,000 (see Table 3 for assumptions regarding these order of magnitude costs). Note that these cost ranges assume a nominal volume of soil (200 cubic yards) and groundwater (4,000 gallons) will require removal for the proposed development. We have assumed deep foundation designs that produce minimal soil and groundwater spoils. If shallow foundations or a subsurface structure is constructed on the site, requiring the removal of a greater volume of soil and groundwater than we have assumed, then we request the opportunity to revise our order of magnitude cost and schedule impacts accordingly.



9. CREDENTIALS

This Phase I assessment report was prepared by Karin Holland under the direct supervision of Gregory Grose, who served as the Project Manager of this project. Qualification information for the project personnel is provided below.

KARIN HOLLAND

Senior Specialist

Ms. Holland received a Bachelor of Arts degree in Natural Sciences from the University of Cambridge, United Kingdom in 2002 and a Master of Science degree in Law and Environmental Science from the University of Nottingham, United Kingdom in 2003. Ms. Holland is involved in a variety of projects, including environmental site assessments, soil management, and field sampling events. Her responsibilities with Phase I Environmental Site Assessments include site history research, interaction with clients and state regulatory agencies, interpretation and evaluation of environmental conditions, and development of recommendations for future investigations.

GREGORY GROSE

Senior Project Manager

Mr. Grose has 21 years of experience in the engineering and environmental consulting industry. He has a diverse background, having served as environmental group leader for 10 years with responsibility for personnel performing due diligence, hazardous building materials assessment and abatement, permitting and compliance, assessment and remediation. Mr. Grose has performed regulatory compliance and assessment monitoring, site characterization and remediation at over 100 LUST sites and numerous operable units at RCRA solid waste facilities and CERCLA sites. He has also provided due diligence and brownfield support, including various state voluntary cleanup programs in the Mid-Atlantic Region.

\\WAS\common\Projects\40223 - M&M Potomac Ave SW\002\Reports\Akridge\2014 0108 HAI PotomacAve PI Akridge F.docx

REFERENCES

- 1. Topographic Map, Washington West, District of Columbia Quadrangle, United States Geological Survey 7.5 minute series, dated 1983.
- 2. Haley & Aldrich, Inc., site visit conducted by Karin Holland and Christian-Noel Tschibelu on 28 August 2013.
- 3. Tat-Lin Angus of PEPCO, Terrance Jones of Akridge and John Keller of Super Salvage, Inc. interviews with Haley & Aldrich, Inc., on 28 August 2013.
- 4. Environmental Date Resources, Database Report, dated July 2013.
- 5. "Assessment of the Buzzard Point Properties," prepared by Geomatrix, Inc., prepared for Potomac Electric Power Company, dated March 1990.
- 6. "Limited Phase II Environmental Investigation, Buzzard Point, 2nd Street SW / V Street SW, Washington, D.C.," prepared by URS Corporation, Inc. (URS), prepared for Potomac Electric Power Company, dated 22 March 2005.
- 7. "Phase I Environmental Site Assessment, Buzzard Point, Squares 609 & 611, 2nd Street and V Street, SW, Washington, DC," prepared by URS, prepared for PEPCO Holdings Inc., dated 4 April 2005.
- 8. "Phase I Environmental Site Assessment, Buzzard Point, 2nd Street and V Street, SW, Washington, DC," prepared by Advantage Environmental Consultants, LLC (AEC), prepared for The John Akridge Companies, Inc., dated 10 June 2005.
- 9. "Phase II Environmental Site Assessment, Buzzard Point, 2nd Street and V Street, SW, Washington, DC," prepared by AEC, prepared for The John Akridge Companies, Inc., dated 10 June 2005.

TABLE 1 - SUMMARY OF SOIL QUALITY
AKRIDGE PARCEL AT BUZZARD POINT, SQUARE 607, LOT 0013
WASHINGTON, DC

FILE NO.: 40223-002

	DCRBSLs for a	Commercial Wo	rker	DCRBSLs for a Construction Worker			Table 1 - Detected Constituents in Soil				
	Surficial Soil (mg/kg)	Sub-surface	Soil (mg/kg)	Soil to Depth of Construction (mg/kg)	DC Tier 0 Soil	EPA Region III	Location:	Lot	607, Square 13		
Constuent of Concern	Ingestion, Inhalation				Standards	Screening Level	Sample ID:	GSS-607-13-1-3	GTW-607-13-2-2	GSS-607-13-3-1	
Constuent of Concern	(Vapor Emissions &	Indoor	Outdoor	Ingestion, Inhalation (Vapor Emissions and		(RSL) for Residential	Depth (ft):	10-15 Lab	5-10 Lab	0-2 Lab	
	Particulate), & Dermal	Inhalation**	Inhalation	Particulates) & Dermal Contact	(mg/kg)	Soil (mg/kg)	Date:	12/5/2013 Qualifier	12/5/2013 Qual	12/5/2013 Qual	
	Contact						Units:	mg/kg	mg/kg	mg/kg	
Benzene	4.83E+01	3.36E-02	2.10E+01	6.91E+02	1.00E+00	1.10E+00 c		<4.3	<6.1	<4.6 1g	
Toluene	8.11E+04 *	6.91E+02	4.49E+05 *	6.46E+04 *	1.00E+01	5.00E+03 nc		<4.3	<6.1	<4.6	
Ethylbenzene	2.32E+02	2.70E-01	1.81E+02	3.18E+03 *	1.00E+01	5.40E+00 c		<4.3	<6.1	<4.6	
Xylenes (total)	9.82E+04 *	2.67E+01	1.70E+04 *	2.39E+04 *	1.00E+01	6.30E+02 nc		<8.6	<12.3	<9.2	
Ethylene dibromide (EDB)	1.23E+00	2.02E-03	1.45E+00	1.78E+01	NA	3.40E-02 c		<4.3	<6.1	NA	
Ethylene dichloride (EDC (1,2-DCA))	2.72E+01	1.58E-02	9.98E+00	3.04E+02	NA	4.30E-01 c		<4.3	<6.1	NA	
Methyl tertiary butyl ether (MTBE)	1.47E+03	1.55E+00	1.00E+03	8.49E+03	NA	4.30E+01 c		<4.3	<6.1	NA	
Acenaphthene	3.30E+04 *	NA	NA	3.71E+04 *	NA	3.40E+03 nc		<0.398	<4.18	NA	
Anthracene	1.65E+05 *	NA	NA	1.86E+05 *	NA	1.70E+04 nc		<0.398	4.72	NA	
Benzo(a)anthracene	2.11E+00	6.85E+02 *	3.00E+05 *	5.92E+01 *	NA	1.50E-01 c		<0.398	8.62	NA	
Benzo(a)pyrene	2.11E-01	3.01E+03 *	1.26E+05 *	5.92E+00	NA	1.50E-02 c		<0.398	8.67	NA	
Benzo(b)fluoranthene	2.11E+00	2.30E+04 *	2.08E+06 *	5.92E+01 *	NA	1.50E-01 c		<0.398	7.66	NA	
Benzo(g,h,i)perylene	1.75E+04 *	NA	NA	2.02E+04 *	NA	NA		<0.398	5.03	NA	
Benzo(k)fluoranthene	2.10E+01 *	2.50E+04 *	2.04E+06 *	5.80E+02 *	NA	1.50E+00 c		<0.398	6.21	NA	
Chrysene	2.10E+02 *	1.41E+04 *	5.23E+06 *	5.78E+03 *	NA	1.50E+01 c		<0.398	9.86	NA	
Fluoranthene	2.20E+04 *	NA	NA	2.48E+04 *	NA	2.30E+03 nc		<0.398	21	NA	
Fluorene	2.20E+04 *	NA	NA	2.48E+04 *	NA	2.30E+03 nc		<0.398	<4.18	NA	
Indeno(1,2,3-cd)pyrene	NA	NA		NA	NA	1.50E-01 c		<0.398	4.61	NA	
Naphthalene	3.22E+02	1.25E+00	8.48E+02 *	4.16E+03 *	NA	3.60E+00 c		<0.398	<4.18	NA	
Phenanthrene	1.75E+04 *	NA	NA	2.02E+04 *	NA	NA		<0.398	18.6	NA	
Pyrene	1.65E+04 *	NA	NA	1.86E+04 *	NA	1.70E+03 nc		<0.398	17.6	NA	

Notes:

- *: Calculated RBSL exceeded saturated soil concentration and calculated value is shown
- #: Calculated RBSL exceeded pure component water solubility and calculated value is shown
- +: Calculated RBSL exceeded saturated soil vapor concentration and calculated value is shown.

Soil concentrations are presented on a dry weight basis.

- **: These values may change when the Division develops the vapor intrusion pathway.
- c: Carcinogenic Screening Level (SL) with Target Risk (TR) = 1E-06
- nc: Non-carcinogenic Screening Level (SL) with Hazard Index (HI) = 1

NA: Not available due to lack of an input parameter.

1g: The internal standard response was below criteria, but there were no detectioins associated with this consituent and the results are unaffectied by this high bias.

BOLD Values	Exceed the District of Columbia Risk-Based Screening Levels for Ingestion, Inhalation (Vapor Emissions & Particulate), & Dermal Contact with Surficial Soil for Commercial Workers
BOXED Values	Exceed the District of Columbia Risk-Based Screening Levels for Ingestion, Inhalation (Vapor Emissions and Particulates) & Dermal Contact with Soil for Construction Workers
SHADED Values	Exceed the EPA Region III Risk-Based Screening Levels for Ingestion, Inhalation and Dermal Contact with Residential Soil
THICK BOXED Values	Exceed the District of Columbia Petroleum Program Tier 0 Standards for Soil

Source:

District of Columbia Risk-Based Corrective Action (DCRBCA) Section 5.0 (June 2011)

United States Environmental Protection Agency (EPA) Region III Screening Level (RSL) Tables (November 2013)

Haley Aldrich, Inc.

Soil and Groundwater Results Summary with Screening Levels.xls

TABLE 1 - SUMMARY OF SOIL QUALITY
AKRIDGE PARCEL AT BUZZARD POINT, SQUARE 607, LOT 0013
WASHINGTON, DC

FILE NO.: 40223-002

	DCRBSLs for a	Commercial Wo	rker	DCRBSLs for a Construction Worker				Table 1 - Detected Constituents in Soil						
	Surficial Soil (mg/kg)	Sub-surface	Soil (mg/kg)	Soil to Depth of Construction (mg/kg)		EPA Region III		Lot 607, Square 13						
Construent of Consern	Ingestion, Inhalation				DC Tier 0 Soil	Screening Level	Sample ID:	GSS-607	-13-1-3	GTW-607-13-2-2	GSS-607-1	3-3-1		
Constuent of Concern	(Vapor Emissions &	Indoor	Outdoor	Ingestion, Inhalation (Vapor Emissions and	Standards	(RSL) for Residential	Depth (ft):	10-15	Lab	5-10 Lab	0-2	Lab		
	Particulate), & Dermal	Inhalation**	Inhalation	Particulates) & Dermal Contact	(mg/kg)	Soil (mg/kg)	Date:	12/5/2013	Qualifier	12/5/2013 Qual	12/5/2013	Qual		
	Contact						Units:	mg/	kg	mg/kg	mg/kg	5		
TPH-GRO	5.56E+06 *	3.76E+02	2.29E+05 *	1.04E+09 *	1.00E+02	1.10E+01 c		<5.6		<7.7	<4.7			
TPH-DRO	2.02E+06 *	1.46E+04 *	8.89E+06 *	1.27E+08 *	1.00E+02	6.10E-01 c		<6.0		119	184			
										-				
Antimony	NA	NA	NA	NA	NA	3.10E+01 nc		< 0.49	M1, R1	<0.54	NA			
Arsenic	NA	NA	NA	NA	NA	6.10E-01 c		7.1		4.8	NA			
Beryllium	NA	NA	NA	NA	NA	1.40E+03 c		0.78	R1	0.50	NA			
Cadmium	NA	NA	NA	NA	NA	1.80E+03 c		0.39		<0.11	NA			
Chromium	NA	NA	NA	NA	NA	2.90E-01 c		18.2		10.3	NA			
Copper	NA	NA	NA	NA	NA	3.10E+03 nc		18.9		37.9	NA			
Lead	NA	NA	NA	NA	NA	4.00E+02 nc		9.4		170	NA			
Nickel	NA	NA	NA	NA	NA	1.30E+04 c		11		6.9	NA			
Selenium	NA	NA	NA	NA	NA	3.90E+02 nc		< 0.99	R1	<1.1	NA			
Silver	NA	NA	NA	NA	NA	3.90E+02 nc		< 0.49	R1	<0.54	NA			
Thallium	NA	NA	NA	NA	NA	7.80E-01 nc		< 0.99	R1	<1.1	NA			
Zinc	NA	NA	NA	NA	NA	2.30E+04 nc		31.7		78.5	NA			
Mercury	NA	NA	NA	NA	NA	1.00E+01 nc		0.03	R1	4.0	NA			

Notes:

- *: Calculated RBSL exceeded saturated soil concentration and calculated value is shown
- #: Calculated RBSL exceeded pure component water solubility and calculated value is shown
- +: Calculated RBSL exceeded saturated soil vapor concentration and calculated value is shown.

Soil concentrations are presented on a dry weight basis.

- **: These values may change when the Division develops the vapor intrusion pathway.
- c: Carcinogenic Screening Level (SL) with Target Risk (TR) = 1E-06
- nc: Non-carcinogenic Screening Level (SL) with Hazard Index (HI) = 1

NA: Not available due to lack of an input parameter.

M1: Maxtrix spike recovery exceeded quality control limits. Batch accepted based on laboratory contorl smaple recovery.

R1: Relative Percent Difference value was outside the control limits.

BOLD Values

Exceed the District of Columbia Risk-Based Screening Levels for Ingestion, Inhalation (Vapor Emissions & Particulate), & Dermal Contact with Surficial Soil for Commercial Workers

Exceed the District of Columbia Risk-Based Screening Levels for Ingestion, Inhalation (Vapor Emissions and Particulates) & Dermal Contact with Soil for Construction Workers

Exceed the EPA Region III Risk-Based Screening Levels for Ingestion, Inhalation and Dermal Contact with Residential Soil

Exceed the District of Columbia Petroleum Program Tier 0 Standards for Soil

Source:

District of Columbia Risk-Based Corrective Action (DCRBCA) Section 5.0 (June 2011)

United States Environmental Protection Agency (EPA) Region III Screening Level (RSL) Tables (November 2013)

TABLE 2 - SUMMARY OF GROUNDWATER
AKRIDGE PARCEL AT BUZZARD POINT, SQUARE 607, LOT 0013
WASHINGTON, DC
FILE NO.: 40223-002

Groundwater and Surface Water S Point of Exposure (POE)				DCRBSLs for a	a Con	struction Work	er			OCRBSLs for a	Comm	nercial Wo	rker				Region ning Le			Table 2 - Dete	ected Constituents in	n Groundwater		
	Groundwater	Groundwater Surface Water (mg/L)		Grour	ndwat	ter (mg/L)				Ground	lwater	r (mg/L)			DC Tier 1	Grou	ındwate	er	Location:		Lot 607,	Square 13		
Constuent of Concern	(mg/L)															Groundwater	(1	mg/L)		Sample ID:	GTW-607-13-1A-1	GTW-607-13-1-1	GTW-607-13-2A-1	GTW-607-13-2-1
			Class C	Class D	Outdoor Inhal	ation	Incidental		Vapor		Indoor		Outdoor	ıtdoor Incidental		Standards (mg/L)				Depth (ft bgs):	33	21	32	14
			CCC		Outdoor Illiai	ation	Dermal Conta	act	Intrusion		Inhalation **		Inhalation		Dermal Contact					Sample Date:	12/12/2013	12/13/2013	12/13/2013	12/13/2013
			4-day Avg	30-day Avg															Units:	mg/L	mg/L	mg/L	mg/L	
Acetone	NA		NA	NA	NA		NA		NA		NA		NA		NA	DCRBSL	1.20E	+04	NC	•	<0.025	1.15E-01	7.90E-02	6.25E-01
Benzene	5.00E-03	М	1000	51	1.38E+04	#	4.71E+00		3.06E+03		4.48E-01	1.	.99E+02		6.78E-02	DCRBSL	3.90E	-01	С		1.02E-02	< 0.001	<0.001	<0.001
Toluene	1.00E+00	М	600	15000	7.67E+06	#	1.32E+02		4.92E+07	+	6.22E+03 #	2.	.76E+06	#	4.75E+01	DCRBSL	8.60E	+02	NC		<0.001	< 0.001	<0.001	<0.001
Ethylbenzene	7.00E-01	M	40	2100	4.22E+04	#	6.20E+00		1.26E+04		1.37E+00	6.	.08E+02	#	8.93E-02	DCRBSL	1.30E	+00	С		< 0.001	<0.001	<0.001	<0.001
Xylenes (total)	1.00E+01	M			1.75E+05	#	1.81E+02	#	9.02E+05	+	1.42E+02 #	6.	.28E+04	#	6.50E+01	DCRBSL	1.90E	+02	NC		<0.002	<0.002	<0.002	<0.002
Ethylene dibromide (EDB)	1.18E-05				2.06E+03		3.58E-01		7.70E+01		6.56E-02	2.	.96E+01		5.15E-03	DCRBSL	6.50E	-03	С		<0.001	< 0.001	<0.001	<0.001
Ethylene dichloride (EDC (1,2-DCA))	5.00E-03	M			1.57E+04	#	8.97E+00		9.40E+02		5.06E-01	2.	.26E+02		1.29E-01	DCRBSL	1.50E	-01	С		< 0.001	<0.001	<0.001	<0.001
Methyl tertiary butyl ether (MTBE)	2.20E-02				3.31E+06	#	1.16E+02		1.06E+05		1.06E+02	4.	.77E+04		6.51E+00	DCRBSL	1.20E	+01	С		3.90E-03	5.40E-02	<0.001	<0.001
cis-1,2-Dichloromethane	NA		NA	NA	NA		NA		NA		NA		NA		NA	NA	NA	١.			7.02E-02	< 0.001	<0.001	<0.001
trans-1,2-Dichloromethane	NA		NA	NA	NA		NA		NA		NA		NA		NA	NA	NA	١.			1.00E-03	< 0.001	<0.001	<0.001
Trichloroethene	NA		NA	NA	NA		NA		NA		NA		NA		NA	NA	4.40E	-01	С		4.39E-02	< 0.001	< 0.001	<0.001
Vinyl chloride	NA		NA	NA	NA		NA		NA		NA		NA		NA	NA	1.50E	-02	С		3.80E-02	<0.001	<0.001	<0.001
TPH-GRO	3.45E+01				NA		NA	#	1.51E+08	+	2.71E+02 #	1.	.20E+05	#	NA	1.00E+00	2.60E	+01	С		2.10E+00	NA	<0.080	NA
TPH-DRO	3.45E+01				NA		NA	#	1.84E+07	+	1.71E+03 #	7.	.60E+05	#	NA	1.00E+00	1.10E	+00	С	•	<0.50	NA	<0.50	NA

Notes

- *: Calculated RBSL exceeded saturated soil concentration and calculated value is shown.
- #: Calculated RBSL exceeded pure component water solubility and calculated value is shown.
- +: Calculated RBSL exceeded saturated soil vapor concentration and calculated value is shown.
- Soil concentrations are presented on a dry weight basis.
- $\ensuremath{^{**}}\xspace$ These values may change when the Division develops the vapor intrusion pathway.
- c: Carcinogenic Screening Level (SL) with Target Risk (TR) = 1E-06
- nc: Non-carcinogenic Screening Level (SL) with Hazard Index (HI) = 1

NA: Not available due to lack of an input parameter.

BOLD Values	Exceed the District of Columbia Groundwater Standard at the Point of Exposure (POE) Well
BOXED Values	Exceed the District of Columbia Risk-Based Screening Levels for Ingestion, Inhalation (Vapor Emissions and Particulates) or Dermal Contact with Soil for Commercial Workers
SHADED Values	Exceed the EPA Region III Risk-Based Screening Levels for Ingestion, Inhalation and Dermal Contact with Groundwater (Un-restricted)
THICK BOXED Values	Exceed the District of Columbia Petroleum Program Tier 1 Standards for Groundwater


Sources:


District of Columbia Risk-Based Corrective Action (DCRBCA) Section 5.0 (June 2011)
United States Environmental Protection Agency (EPA) Region III Screening Level (RSL) Tables (November 2013)


R	ecognized Environmental Conditions	Previous Findings	Limited Phase II Findings	Potential Impact on Proposed	Potential Remedies	Order of Magnitude Opi	de Opinion of Cost (Range)		tion Schedule
	- Conditions	Frevious Findings	Limited Fliase II Findings	Development	rotential nemeties	Low Assumptions	High Assumptions	(we	eks)*
	Surface staining (on asphalt of the on-site paved parking lot south-southeast of the storage building)	1990 Geomatrix Soil Results: TPH 48 to 360 mg/kg @0-2'	TPH-DRO 119 @ 5-10' & 184 mg/kg @ 0 2'	Soil excavated during construction with TPH >100 mg/kg DC Tier 0 Screening Level is not appropriate for unrestricted use as fill (may require appropriate treatment/disposal)	Develop a Site-Specific Health & Safety Plan and a Soil Management Plan to guide construction activities and proper management of impacted soil encountered during construction	Impacted soil has been contaminated with exempt \$ 10,000 petroleum fuel(s) only and can be treated at a petroleum contaminate soil recycling facility	DDOE requires a comprehensive assessment (up to 6 additional temporary wells, soil & groundwater sampling along with additional waste characterization sampling to confirm non-hazardous waste for disposal).	4	8
KREC #1:				If chromium VI >0.029 mg/kg, then soil may not appropriate for unrestricted use as fill.	Evaluate chromium VI content in shallow soil	\$ - Not Required	\$ 10,000 Geoprobe sampling to collect 8 soil samples from 0 - 5 feet bgs for chromium valence state analyses.	4	8
	Urban fill encountered in two borings at depths to approximately 6 feet bgs	2005 AEC Soil Results: Lead 10.9 ppm @ 2', 170 & 75.1 ppm @ 4', 130 & 83.4 ppm @ 5', 140 & 10.2 ppm @ 6', 28 ppm @8'	Arsenic 4.8 mg/kg and chromium 10.3 mg/kg @ 5-10'. Arsenic may be consistent with background and chromium may be present as insoluble salts (chromium III).	If off-site disposal of excavated soil is required: 1) soils contaminated by exempt petroleum fuels may be suitable for recycling 2) soils contaminated by other sources may require disposal at a permitted landfill.	Off-site disposal of impacted soil excavated during construction	Off-site transportation & disposal of up to 200 cuyds (2 east-west transects 400' x 5' x 1.3' ea) of petroleum-contaminated soil (property owner will sign a waste profile to indicate contamination associated with virgin petroleum fuels only to be acceptable for soil recycling)	Off-site transportation & disposal of up to 200 cuyds of non-hazardous waste soil at a \$ 30,000 Range could be higher if greater volumes of soi are excavated for disposal.	2	8
			2013 H&A Groundwater Results:	Vapor Intrusion (VI) potential may exist for construction of occupied structures due to PAHs detected in soil and VOCs	Install an impermeable barrier to prevent VI	\$ - Not Required	\$ 20,000 Install a geomembrane vapor barrier (up to 10k sqft occupied structure). Does not include cost for granular bedding material beneath slab, which is required.	0	2
KDE C #2	Former asphalt pit identified on Figure 3 of a 1990 Geomatrix, Inc. assessment report; located near the southeast corner of the site	2005 AEC Groundwater Results: vinyl chloride 160 ppb, trans-1,2-dichloroethene 10 ppb, cis-	VOCs: vinyl chloride 38 ppb, trans-1,2-	detected in groundwater.	Install sub-slab ventilation	\$ - Not Required	\$ 40,000 Air permit, design and installation for up to 10k sqft occupied structure over areas with VI potential	0	6
KREC #2:		1,2-dichloroethene 1,300 ppb, benzene 11 ppb, trichloroethene 4,100 ppb & tetrachloroethene 5.6 ppb	dichloromethene 1 ppb, cis-1,2- dichloromethene 70.2 ppb, benzene 10.2 ppb & trichloroethene 43.9 ppb	Management of contaminated groundwater may be required if encountered during construction or long	Containment & off-site disposal or on-site treatment & monitoring prior to discharge may be required for construction dewatering.	Limited to 4,000 gallons pumped to an on-site tank \$ 5,000 with vac truck removal and disposal as petroleum- contaminated water	\$ 10,000 Limited to 4,000 gallons pumped to an on-site tank with vac truck removal and disposal as non-hazardous waste water at a permitted disposal facility. Range could be higher if greater volumes of water are removed for	0	2
			TPH-GRO: 2.1 mg/L	term dewatering is required for subsurface structures.	Installation of an on-site treatment system, long-term monitoring & maintenance may be required for dewatering of subsurface structures.	\$ - Not Required	\$ 85,000 Subsurface structures.	0	12
SREC #1:	Heavy staining on the concrete floor around floor drains in the on-site storage building.	N/A	N/A	The outfall for these drains has not been determined. Potential subsurface impacts associated the stains has not been evaluated.	Review construction drawings for the storage building to determine the location of floor drain discharge piping or conduct a dye tracer study. Collect sub-slab soil samples around the floor drains.	\$ 20,000 Geoprobe sampling to collect up to 3 sub slab soil samples, up to 2 storm drain sediment samples & up to 2 additional temporary wells, soil & groundwater sampling.	Impact from the site is confirmed in the storm	8	12
HREC #1:	HREC: a 20,000 gallon gasoline LUST (case # 93094) impacted soil and groundwater under the subject site and was reported in August 1993. The LUST case received regulatory closure in May 1994.	2005 AEC Soil Results: TPH 45 ppm @4' and 11 ppm @ 6' along southern property boundary	PAHs: benzo(a)anthracene 8.62 mg/kg, benzo(a)pyrene 8.67 mg/kg & benzo(b)fluoranthene 7.66 mg/kg @ 5- 10'	Selected PAHs in soil exceed DCRBSLs for Commercial Workers & Construction Workers	HASP & Soil Management Plan for KREC #1 to include potential petroleum impacted soil.	DDOE accepts the Soil Management Plan without requiring entry into the Voluntary Cleanup Program (VCP). Disposal contractor accepts waste characterization sample results from the Limited Phase II.	VCP or Site Response & Remediation Program support to enter the site into an applicable regulatory program.	0	10
				Associated environmental management	Work Plan development.	\$ 5,000 DDOE accepts a modified Soil Management Plan.	On-site environmental monitoring during excavation/dewatering activities (up to 3 months), confirmation soil sampling/analysis (up to 13 soil samples for TPH/BTEX/metals), confirmation groundwater sampling/analysis (up to 4 water samples for TPH/BTEX/metals), PID monitoring and reporting.	1	10
					Order of Magnitude Cost Range for Impacts on Proposed Development from Identified RECs:		\$ 370,000 Order of Magnitude Schedule Impacts or Proposed Development from Identified RECs		26

Note

^{*} Assumes most activities can be performed concurrently and that DDOT/DCRA reviews will be completed within 4 to 6 weeks.







APPENDIX A

Haley & Aldrich proposal dated 28 June 2013

Haley & Aldrich, Inc. 7926 Jones Branch Dr. Suite 870 McLean, VA 22102

Tel: 703.336.6200 Fax: 703.356.4699 HaleyAldrich.com



28 June 2013 File No. 40223-970

McKissack & McKissack 1401 New York Avenue, NW Suite 900 Washington, DC 20005

Attention: William J. Carlson

Senior Project Manager

Subject: Proposal for Phase I Environmental Site Assessment

Potomac Avenue & 1st Street SW

Washington, DC

Ladies and Gentlemen:

Haley & Aldrich, Inc., is pleased to submit this proposal to provide environmental consulting services. This proposal presents our scope of work to perform a Phase I environmental site assessment (Phase I ESA) at the above-referenced site (subject site), using methods consistent with the ASTM E 1527-05 Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process (ASTM E 1527-05 Standard) as referenced in 40 CFR Part 312 (the All Appropriate Inquiries [AAI] Rule).

The completion of this Phase I ESA is only one component of the process required to satisfy the AAI Rule. In addition, the user must adhere to a set of user responsibilities as defined by the ASTM E 1527-05 Standard and the AAI Rule. User responsibilities are discussed below. A user seeking protection from Comprehensive Environmental Response, Compensation and Liability Act (CERCLA) liability as an innocent landowner, bona fide prospective purchaser, or contiguous property owner must complete all components of the AAI process in addition to meeting ongoing obligations. AAI components, CERCLA liability relief, and ongoing obligations are discussed in the AAI Rule and in Appendix XI of the ASTM E 1527-05 Standard.

PROJECT UNDERSTANDING AND BACKGROUND

It is our understanding that McKissack & McKissack is in the process of preparing a Feasibility Study for proposed development of the subject site, and in connection with the Feasibility Study, desires a Phase I ESA of the subject site consistent with the ASTM E 1527-05 Standard practices.

Haley & Aldrich understands the subject site consists of the following parcels bounded by Potomac Avenue, SW, 2nd Street, SW, T Street, SW and Half Street, SW:

■ Square 0605, Lots 0007 & 0802 (1711 & 1714 1st Street, SW)

McKissack & McKissack 28 June 2013 Page 2

- Square 0607, Lot 0013
- Square 0661, Lots 0800, 0805 and 0804
- Square 0665, Lot 0024 (1930 1st Street, NW)

PROJECT OBJECTIVES

The objective of a Phase I assessment is to identify known and suspect "recognized environmental conditions" (RECs), historical RECs (HRECs), and *de minimis* conditions associated with the subject site by evaluating site history, existing observable conditions, current site use, and current and former uses of adjoining properties as well as potential releases at surrounding properties that may impact the subject site. RECs are defined in the ASTM E 1527-05 Standard as "the presence or likely presence of any hazardous substances or petroleum products on a property under conditions that indicate an existing release, a past release, or a material threat of a release of any hazardous substances or petroleum products into structures on the property or into the ground, groundwater, or surface water at the property. The term includes hazardous substances or petroleum products even under conditions in compliance with laws. The term is not intended to include *de minimis* conditions that generally do not present a threat to human health or the environment and that generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies." A material threat is defined by the ASTM E 1527-05 Standard as "a physically observable or obvious threat which is reasonably likely to lead to a release that, in the opinion of the environmental professional, is threatening and might result in impact to public health or the environment."

Consistent with ASTM E 1527-05 Section 12.5 (Report Format), and for the purposes of this assessment, those RECs that have been identified as being present with respect to the subject site are referred to as Known Recognized Environmental Conditions (KRECs), and those RECs that have been identified as being likely present with respect to the subject site are referred to as Suspect Recognized Environmental Conditions (SRECs). The ASTM E 1527-05 Standard defines HRECs as environmental conditions "which in the past would have been considered a recognized environmental condition, but which may or may not be considered a recognized environmental condition currently."

The ASTM E 1527-05 Standard requires an environmental professional's opinion of the potential impacts of RECs, HRECs, and *de minimis* conditions identified on a site during a Phase I assessment. Our conclusions regarding the potential impact of RECs, HRECs, and *de minimis* on the subject site are intended to help the user evaluate the "business environmental risk" associated with the subject site, defined in the ASTM E 1527-05 Standard as "a risk which can have a material environmental or environmentally-driven impact on the business associated with the current or planned use of a parcel of commercial real estate, not necessarily limited to those environmental issues required to be investigated in this practice. Consideration of business environmental risk issues may involve addressing one or more non-scope considerations..." The non-scope considerations listed in the ASTM E 1527-05 Standard are discussed below in the Authorization section of this proposal.

The Phase I assessment work scope has been developed to be consistent with the ASTM E 1527-05 Standard, based on our current understanding of the subject site. The Phase I assessment consists of four components: Records Review, Site Reconnaissance, Interviews, and Report Preparation.



SCOPE OF WORK

1. <u>Records Review</u> - Haley & Aldrich will assemble and review readily available information on site history and usage as it relates to the presence of hazardous substances and petroleum products that would constitute RECs on the subject site. The ASTM E 1527-05 Standard lists standard and additional records for review.

We will review information from the mandatory databases within the ASTM-specified approximate minimum search distances. The mandatory databases include: NPL; Delisted NPL; CERCLIS; CERCLIS NFRAP; ERNS; RCRA non-CORRACTS TSD; RCRA CORRACTS TSD; RCRA Generators; Federal Institutional and Engineering Controls; State and Tribal Landfills and Solid Waste Disposal Sites; State and Tribal equivalent NPL and CERCLIS Sites; State and Tribal Registered Storage Tanks; State and Tribal Leaking Storage Tanks; State and Tribal Institutional and Engineering Controls; State and Tribal Voluntary Clean-up Sites; and State and Tribal Brownfields Sites. We intend to use an electronic database service to provide a report summarizing information from the required records, and will rely on the database service to conform to ASTM requirements for currency of the information. Should the database search report identify listed sites with the potential to impact the subject site, Haley & Aldrich may review the federal or state files pertaining to the listed sites, as reasonably ascertainable and practically reviewable. The budget presented below does not include costs for review of files at more than one agency's office.

As required by ASTM, a current 7.5-minute USGS topographic map or equivalent will be used to evaluate the physical setting in the subject site area, and will be supplemented by discretionary review of readily available information concerning surface topography, surface water, soil, bedrock, and groundwater conditions on and in the vicinity of the subject site.

To complete the ASTM records review, Haley & Aldrich may contact one or more of the following agencies concerning the subject site: Health Department, Fire Department, Water Department, Zoning Board, and Engineering Department. We will contact the agencies for information concerning records related to storage, use, or release of hazardous substances or petroleum products that may constitute RECs on the subject site, and will document our contacts in writing.

ASTM requires that "obvious uses" of the subject site be identified from the present back to the first developed use or back to 1940, whichever is earlier. In order to complete that task, Haley & Aldrich will review one or more of the following ASTM-listed standard historical sources: aerial photographs, fire insurance maps, property tax files, recorded land title records, USGS topographic maps, local street directories, building department records, and zoning/land use records. Haley & Aldrich may also review ASTM-listed "other historical sources" including newspaper archives, internet sites, and local libraries and historical societies.

Haley & Aldrich will review reports previously prepared for the subject site, if provided.



Pursuant to the ASTM E 1527-05 Standard, records identified by ASTM as "Additional" or "Other" will be reviewed when, in Haley & Aldrich's judgment, they are (1) reasonably ascertainable; (2) sufficiently useful, accurate, and complete; and (3) generally obtained pursuant to local good commercial or customary practice.

2. <u>Site Reconnaissance</u> - Haley & Aldrich will visit the subject site and view interior and exterior conditions to assess the nature and type of activities that have been conducted with respect to the potential for RECs to be present. Haley & Aldrich will observe and document visible evidence of current and past usage of the subject site, particularly related to potential filling, previous structures, sewage disposal systems, hazardous substances, petroleum products, storage tanks, and evidence of spills or releases of hazardous substances or petroleum products. Conditions of adjoining properties will also be observed from the subject site boundaries and/or public thoroughfares.

We understand that you will make all areas of the subject site accessible to our representative(s) for the site visit. For budgeting purposes, we have assumed that all areas of the subject site will be made accessible and that the site reconnaissance will be conducted in one site visit.

Our observations and conclusions related to the site reconnaissance may be limited by prevailing weather conditions or other conditions at the time of our site visit. Our report will include a discussion of factors limiting our site reconnaissance, if applicable.

- 3. Interviews with Owners and Occupants - The ASTM E 1527-05 Standard requires that interviews be performed with a "key site manager" (the owner or occupant of the subject site) and with representatives of building occupants. In accordance with ASTM, an interview will be conducted with a representative of each occupant if the building has five or fewer occupants. If the building contains more than five occupants, an interview will be conducted with those major occupants, as defined by ASTM, and those occupants whose operations could indicate RECs in connection with the subject site. We request that the current owner(s) or representative(s) be notified of our visit and asked to participate in an interview regarding subject site usage and history. If the subject site is abandoned, ASTM requires interviews with one or more owners or occupants of neighboring or nearby properties. Further, as required by the ASTM E 1527-05 Standard, we ask that you request the current site owner to assemble and make available to Haley & Aldrich copies of previous environmental investigation reports and audits of the property, and other information related to storage, use, or release of hazardous substances or petroleum products at the site, such as environmental permits, registrations for tanks, material safety data sheets, or waste disposal records.
- 4. <u>Interview with State and/or Local Government Officials</u> Haley & Aldrich may interview one or more state and/or local government officials in conjunction with the state and local government records review with the intention to obtain information indicating RECs in connection with the subject site.
- 5. <u>Evaluation and Report</u> Haley & Aldrich will interpret the information and data assembled from work scope items No. 1 through No. 4 above, and will formulate conclusions regarding



evidence of RECs at the subject site and their potential impact on the subject site. We will prepare three copies of a report summarizing the results of our assessment and discussing our conclusions regarding the potential presence and impact of RECs in connection with the subject site, based on the work scope described above.

The report will be prepared in accordance with the standards and practices set forth in 40 CFR Part 312 (the AAI Rule), and consistent with the ASTM E 1527-05 Standard. Documentation supporting the conclusions presented will be appended to the report. As required by ASTM, our final report will include declarations that the Phase I assessment was conducted consistent with the scope and limitations of the ASTM E 1527-05 Standard, and the persons who signed the report meet the definition of environmental professional. In addition, the Phase I assessment report will indicate whether RECs were or were not identified in connection with the subject site, and whether there were data gaps. If data gaps were identified, Haley & Aldrich will indicate whether they are considered significant (i.e., affect our ability to identify conditions indicative of RECs).

USER RESPONSIBILITIES

The AAI Rule requires that the user of the report consider the following:

- Whether the user has specialized knowledge about previous ownership or uses of the subject site that may be material to identifying RECs;
- whether the user has determined that the subject site's Title contains environmental liens or other information related to the environmental condition of the property, including engineering and institutional controls and Activity and Use Limitations (AULs), as defined by ASTM;
- whether the user is aware of commonly known or reasonably ascertainable information about the subject site including whether or not the presence of contamination is likely on the subject site and to what degree it can be detected; and
- whether the user has prior knowledge that the price of the subject site has been reduced for environmentally related reasons.

We request that you provide this information to us for inclusion in our report. Though it is not required by the AAI Rule or the ASTM E 1527-05 Standard that this information be provided to Haley & Aldrich, failure on the part of the user to obtain such information for their own records, should it be reasonably ascertainable, may invalidate the user's compliance with the AAI Rule for CERCLA liability protection in the future.

COSTS

Services associated with completing work scope items Nos. 1 through 5 will be conducted for a lump sum of \$10,000. That lump sum fee does not include costs related to meetings or lengthy conference calls. Meetings, lengthy conference calls, and other additional services, if required, will be billed separately in accordance with our attached Standard Rate Schedule.



SCHEDULE

We will provide a draft summary of our findings, to include a description of RECs identified, as well as any data failures that may affect our assessment, if applicable, within two weeks following receipt of written authorization to proceed. We will provide a Final copy of our Phase I ESA report for your review within three to four weeks of our receipt of a signed copy of this proposal.

The majority of the information from the Phase I assessment should be available within 2 to 3 weeks of authorization to proceed. Please note, however, that responses to agency records requests may not be received within that time frame. At your discretion, we can either wait for the response to the requests prior to preparing our Final Phase I ESA report, or we can supplement the report with the responses if they are received and contain information that would alter our conclusions.

AUTHORIZATION

Our work scope for this project will be performed in accordance with the standards and practices set forth in 40 CFR Part 312, and consistent with the ASTM E 1527-05 Standard for Phase I ESAs. Organizations other than ASTM have also developed "guidelines" or "standards" for environmental site assessments and the scope of work herein may vary from the specific guidelines or standards issued by other organizations. If this project requires conformance with a guideline or standard other than ASTM, we will be pleased to review our proposal considering the specific requirements, and revise and resubmit this proposal, if necessary.

Our report will be prepared for your exclusive use, solely for the purposes stated in this proposal. The report may not be used or relied upon by any other party, without the prior written permission of Haley & Aldrich. We agree, however, that the report may be conveyed to the District of Columbia Department of General Services, if applicable, subject to their acceptance of the terms of this proposal. Any other use of this report without written authorization of Haley & Aldrich shall be at such other person's or entity's sole risk, and shall be without legal exposure or liability to Haley & Aldrich.

No subsurface explorations or chemical analysis of environmental media (e.g., soils or groundwater) will be performed during this assessment. Therefore, our conclusions regarding the evidence of RECs will be based on observations of existing visible conditions, and on our interpretation of subject site history and site usage information. Further, our conclusions regarding the presence of hazardous substances and petroleum products may not be applicable to areas beneath existing structures, unless specific subsurface exploration, sampling, and/or analytical information is available and reviewed by us for such areas.

The ASTM E 1527-05 Standard includes the following list of "additional issues" that are non-scope considerations outside of the scope of the ASTM Phase I practice: asbestos-containing materials, radon, lead-based paint, lead in drinking water, wetlands, regulatory compliance, cultural and historic resources, industrial hygiene, health and safety, ecological resources, endangered species, indoor air quality, bio-agents, and mold. Assessment of these items is not included in our proposed work scope. A limited assessment of the presence of PCBs is included in the ASTM work scope. Accordingly, our



McKissack & McKissack 28 June 2013 Page 7

assessment of the presence of PCBs is limited to those potential sources specified in the ASTM E 1527-05 Standard as "electrical or hydraulic equipment known or likely to contain PCBs, to the extent visually and or physically observed or identified from the interview or records review."

Consulting services will be provided in accordance with our "Standard Terms and Conditions, 2003", which is integral to this proposal.

If the above arrangements are satisfactory to you, please indicate your approval by signing and returning one copy of this proposal. When accepted by you, this proposal together with the attached Terms and Conditions will constitute our Agreement.

CLOSING

Thank you for inviting Haley & Aldrich to submit this proposal. We look forward to our association with you on the project. Should you have any questions regarding the proposal, please do not hesitate to contact us.

Sincerely yours, HALEY & ALDRICH, INC.	This proposal, and the attached "Standard Terms and Conditions, 2003" are understood and accepted:
John State	MCKISSACK & MCKISSACK
Gregory B. Grose, PG	Ву
Senior Project Manager	(authorized signature)
David A. Schoenwolf, PE Senior Vice President	By (print or type name) Title Date

Attachments:

Standard Terms and Conditions, 2003 Standard Rate Schedule

C:\Users\ggrose\Documents\McKissack & McKissack\M&M Potomac Ave SW DC Phase I Proposal.docx





1. General

These Standard Terms and Conditions, together with the attached proposal and Standard Fee Schedule, constitute the Agreement between Haley & Aldrich and the entity or person to whom the proposal is addressed ("Client") to perform basic or additional services. The Standard Fee Schedule may be omitted for lump sum type Agreements.

2. Performance of Services

Haley & Aldrich's services will be performed in accordance with generally accepted practices of engineers and/or scientists providing similar services at the same time, in the same locale, and under like circumstances. Client agrees that Haley & Aldrich has been engaged to provide professional services only, and that Haley & Aldrich does not owe a fiduciary responsibility to Client. No other warranty, expressed or implied, is included or intended by this Agreement.

3. Environmental Professional Services

Haley & Aldrich employees may serve as Environmental Professionals under state or federal programs, which may include rendering opinions regarding site assessments and remediation. In carrying out such functions, the Environmental Professional will select such explorations, data collections, remediation actions or other services which, in the Environmental Professional's opinion, are appropriate, under the statutes and regulations, to establish a basis for such opinion. Client acknowledges that a federal, state or local agency may review, comment and/or audit Haley & Aldrich's services and may require additional site activities, even though Haley & Aldrich and such Environmental Professionals have each performed such services in accordance with the standard of care set forth herein. Client agrees to compensate Haley & Aldrich for services performed in response to such an audit at Haley & Aldrich's billing rates then in effect.

4. Payment

Invoices will generally be submitted monthly. Payment will be due within thirty (30) days of invoice date. Interest will be added to accounts in arrears at the rate of one and one-half (1.5) percent per month on the outstanding balance. In the event Haley & Aldrich must engage counsel to enforce overdue payments, Client will reimburse Haley & Aldrich for all reasonable attorney's fees and court costs.

5. Insurance

Haley & Aldrich will maintain: workers' compensation insurance as required under the laws of the state in which the services will be performed; commercial general liability insurance with a combined single limit of \$1,000,000 per occurrence and \$2,000,000 in the aggregate for bodily injury, including death and property damage; automobile liability insurance with a combined single limit of \$1,000,000 per occurrence; professional

liability insurance in the amount of \$1,000,000 per claim and in the aggregate; and contractor's pollution liability insurance in the amount of \$1,000,000 per occurrence and in the aggregate. Haley & Aldrich will furnish Client with a certificate of insurance evidencing the coverages listed above and providing thirty (30) days prior written notice in the event of cancellation or material change in coverage.

6. Confidentiality

Haley & Aldrich will hold confidential all business and technical information obtained or generated in performing of services under this Agreement. Haley & Aldrich will not disclose such information without Client's consent except to the extent required for: (1) performance of services under this Agreement; (2) compliance with professional standards of conduct for preservation of the public safety, health, and welfare; (3) compliance with any court order, statute, law, or governmental directive; and/or (4) protection of Haley & Aldrich against claims or liabilities arising from the performance of services under this Agreement. Haley & Aldrich's obligations hereunder shall not apply to information in the public domain or lawfully obtained on a non-confidential basis from others.

7. Ownership of Documents and Processes

All documents (including drawings, specifications, estimates, field notes, and other data) and all processes (including scientific, technological, software, and other concepts, whether or not patentable) created, prepared, or furnished under this Agreement by Haley & Aldrich, or Haley & Aldrich's independent contractors and consultants pursuant to this Agreement, are instruments of service and shall remain the property of Haley & Aldrich whether or not the Project is completed. Haley & Aldrich shall retain ownership of all documents and processes, and any copyright or right to patent thereto. Client may make and retain copies thereof as is necessary for completion, occupancy or operation of the project by Client or others; however, such documents are not intended or represented to be suitable for additions or alterations to the project, use on any other project or completion of the project without Haley & Aldrich's professional involvement. Any reuse or modification without written verification or adaptation by Haley & Aldrich for the specific purpose intended is at Client's sole risk and without liability or legal exposure to Haley & Aldrich or its independent contractors or consultants. Client shall indemnify. defend, and hold harmless Haley & Aldrich and its independent contractors, and consultants from all claims. damages, losses, and expenses, including attorney's fees, arising out of or resulting therefrom. Any such verification or adaptation will entitle Haley & Aldrich to further compensation.

8. Electronic Media

Client recognizes that data, plans, specifications, reports, documents, or other information recorded on or transmitted as electronic media are subject to undetectable alteration, either intentional or unintentional. Accordingly, documents provided to Client in electronic media are for informational purposes only and are not an end product. Client agrees to defend, indemnify, and hold Haley & Aldrich harmless from any claims, liabilities, losses or damages arising out of the reuse of alteration of electronic media. Haley & Aldrich makes no warranties, either expressed or implied, regarding the fitness or suitability of the electronic media.

9. Suspension of Work and Termination

Client may, at any time, suspend further work by Haley & Aldrich or terminate this Agreement. Suspension or termination shall be by written notice effective seven (7) days after receipt by Haley & Aldrich. Client agrees to compensate Haley & Aldrich for all services performed and commitments made prior to the effective date of the suspension or termination, together with reimbursable expenses including those of subcontractors, subconsultants, and vendors.

If Client fails to make payment when due for services and reimbursable expenses, Haley & Aldrich may, upon seven (7) days' written notice to Client, suspend performance of services under this Agreement. Unless payment in full is received by Haley & Aldrich within seven (7) days of the date of the notice, the suspension shall take effect without further notice. In the event of a suspension of services, Haley & Aldrich shall have no liability to Client for delay or damage to Client or others because of such suspension of services.

10. Force Majeure

Except for Client's obligation to pay for services rendered, no liability will attach to either party from delay in performance or nonperformance caused by circumstances or events beyond the reasonable control of the party affected, including, but not limited to, acts of God, fire, flood, unanticipated site or subsurface conditions, explosion, war, request or intervention of a governmental authority (foreign or domestic), court order (whether at law or in equity), labor relations, accidents, delays or inability to obtain materials, equipment, fuel or transportation.

Delays within the scope of this article that cumulatively exceed thirty (30) calendar days shall, at the option of either party, make this Agreement subject to termination or renegotiation. Should the Client require that Haley & Aldrich maintain its personnel and equipment available during the delay period, Client agrees to compensate Haley & Aldrich for the additional labor, equipment, and any and all other direct costs associated with Haley & Aldrich in maintaining its personnel on Site during the delay period.

11. Mold/Biological Pollutants

Client agrees that Haley & Aldrich shall have no liability for any claim, direct or indirect, for bodily injury or property damage, including loss of use, arising from, alleged to arise from, or caused by the presence of, or exposure to, any Mold or other Biological Pollutants in or around any structure. In addition, Client shall defend, indemnify, and hold harmless Haley & Aldrich from third-party claims for damages arising from, or alleged to arise from, or caused by the presence of or exposure to, any Mold or other Biological Pollutant in or around any structure, except for damages arising from or caused by Haley & Aldrich's sole negligence.

The term "Mold or other Biological Pollutants" includes, but is not limited to, molds, fungi, spores, bacteria, and viruses, and the by-products of biological organisms.

12. Subsurface Risks

Client recognizes that special risks occur whenever engineering or related disciplines are applied to identify subsurface conditions. Even a comprehensive sampling and testing program, implemented with appropriate equipment and experienced personnel under the direction of a trained professional who functions in accordance with a professional standard of practice, may fail to detect certain hidden conditions. Environmental, geological, and geotechnical conditions that Haley & Aldrich may infer to exist between sampling points may differ significantly from those that actually exist. The passage of time also must be considered, and Client recognizes that due to natural occurrences or direct or indirect human intervention at or near the site, actual conditions may quickly change. Client realizes that these risks cannot be eliminated altogether, but certain techniques can be applied to reduce them to a level that may be tolerable. The services included in this Agreement are those which Client agreed to, or selected, consistent with Client's risk preferences and other considerations.

13. Disclosure of Hazards (Right-to-Know)

Haley & Aldrich will take reasonable precautions for the health and safety of Haley & Aldrich's employees while at the site. Client will obtain from Site Owner, and furnish to Haley & Aldrich, at the time of Client's authorization to proceed, all available information concerning oil, hazardous, toxic, radioactive or asbestos material in, on or near the site. If a hazardous material or condition is discovered that had not been disclosed to Haley & Aldrich, then, upon notification, Client and Haley & Aldrich shall seek to determine an equitable adjustment to be made to this Agreement. In addition, Client agrees to assume all liability and shall hold Haley & Aldrich harmless from any claims, losses, liabilities or damages arising out of personal injury or death resulting from such hazardous material or condition.

14. Public Responsibility

Client acknowledges that Client or the site owner, as the case may be, is now and shall remain in control of the site

for all purposes at all times. Except as required by law or regulation, Haley & Aldrich will not report to any federal, state, county, or local public agencies having jurisdiction over the subject matter, any conditions existing at the site that may present a danger to public health, safety, or the environment. Client agrees to notify each federal, state, county, and local public agency, as they each may require, of the existence of any condition at the site that may present a potential danger to public health, safety, or the environment.

Notwithstanding the provisions of the foregoing, Haley & Aldrich will comply with subpoenas; judicial orders or government directives; federal, state, county, and local laws, regulations, and ordinances; and codes regarding the reporting to the appropriate public agencies of findings with respect to potential dangers to public health, safety, or the environment. Haley & Aldrich shall have no liability to Client or to any other person or entity for reports or disclosures made in accordance with such requirements. Client shall defend, indemnify, and hold Halev & Aldrich harmless from and against any and all claims, demands, liabilities, and expense, including reasonable attorneys' fees incurred by Haley & Aldrich and arising directly or indirectly out of reporting such information under a bona fide belief or upon advice of counsel that such reporting or disclosure is required by

15. Site and Subsurface Investigations

Client agrees to furnish right of entry and permission for Haley & Aldrich to perform surveys, borings, and other investigations, including subsurface explorations, pursuant to the scope of services. Haley & Aldrich will take reasonable precautions to minimize damage to the property and exercise reasonable care when locating underground structures in the vicinity of proposed subsurface explorations. If Haley & Aldrich is required to restore the property or subsurface conditions or structures to its former condition, the cost plus fifteen (15) percent will be added to the fee. Client shall indemnify, defend, and hold harmless Haley & Aldrich and its independent contractors and consultants from any and all claims, damages, losses, and expenses (including attorneys' fees), arising out of or resulting from any such damage, except to the extent caused by Haley & Aldrich's negligence.

16. Samples

Samples of soil, water, waste, rock, or other materials collected from the site will be disposed of 14 days after submission of Haley & Aldrich's report or other deliverables unless Client advises otherwise in writing or unless applicable law requires their retention. We will dispose of such samples by contract with a qualified waste disposal contractor. Client agrees to pay all costs associated with the storage, transport, and disposal of samples, and to indemnify Haley & Aldrich for any liability arising therefrom. If samples must be stored by Haley & Aldrich for a period in excess of 14 days after completion of Haley & Aldrich's report, or other

deliverables, Client agrees to pay an additional fee for storage as determined by Haley & Aldrich. Client recognizes and agrees that Haley & Aldrich is a bailee and assumes no title to said waste or samples nor any responsibility as generator of said waste or samples.

17. Services During Construction

If Haley & Aldrich provides services including the performance of services during the construction phase of the project, it is understood that the purpose of such services, including visits to the Site, will be to enable Haley & Aldrich to better perform the duties and responsibilities assigned to and undertaken by it as a design professional, and to determine, in general, if construction is proceeding in a manner indicating that the completed work of Contractors will conform generally to the Contract Documents.

Haley & Aldrich shall not, during such visits or as a result of observations of construction, supervise, direct, or have control over Contractors' work nor shall Haley & Aldrich have authority over, or responsibility for, the means, methods, sequences or procedures of construction selected by the Contractors or safety precautions and programs incident to the work of Contractors or for any failure of Contractors to comply with laws, rules, regulations, ordinances, codes or orders applicable to Contractors furnishing and performing their work. Haley & Aldrich does not guarantee the performance of the construction contract by the Contractors, and does not assume responsibility for Contractors' failure to furnish and perform their work in accordance with the Contract Documents.

If Haley & Aldrich's services during construction include shop drawing review, Haley & Aldrich will review (or take other appropriate action with respect to) shop drawings, samples, and other data which Contractors are required to submit, but only for conformance with the design concept of the project and compliance with the information given in the Contract Documents. Such review or other actions shall not extend to means. methods, techniques, sequences, or procedures of manufacture (including the design of manufactured products) or construction, or to safety precautions and programs incident thereto. Haley & Aldrich's review or other actions shall not constitute approval of an assembly or product of which an item is a component, nor shall it relieve the Contractors of (a) their obligations regarding review and approval of any such submittals, and (b) their exclusive responsibility for the means, methods, sequences, and procedures of construction, including safety of construction.

18. Reliance

Any opinions rendered pursuant to this Agreement are for the sole and exclusive use of Client, and are not intended for the use of, or reliance upon, by any third parties without the prior written approval of Haley & Aldrich. Client agrees to indemnify, hold harmless, and defend Haley & Aldrich to the fullest extent permitted by law for any claims, losses, or damages allegedly suffered by third parties due to the unauthorized reliance on any opinion provided hereunder.

19. Waiver of Consequential Damages

Neither party, nor their parent, affiliated or subsidiary companies, nor the officers, directors, agents, employees, or contractors of any of the foregoing, shall be liable to the other in any action or claim for incidental, indirect, special, collateral, consequential, exemplary or punitive damages arising out of or related to the Services, whether the action in which recovery of damages is sought is based upon contract, tort (including, to the greatest extent permitted by law, the sole, concurrent or other negligence, whether active or passive, and strict liability of any protected individual or entity), statute or otherwise.

20. Hazardous Substance Claims

By authorizing Haley & Aldrich to proceed with the services, Client confirms that Haley & Aldrich has not created nor contributed to the presence of any hazardous substances or conditions at or near the Site. Client recognizes that there is an inherent risk in drilling borings, pushing or driving probes, excavating trenches, or implementing other methods of exploration at or near a site contaminated by hazardous materials. Further, Client recognizes that these are inherent risks even through the exercise of the Standard of Care. Client accepts this risk and agrees to indemnify and hold Haley & Aldrich, and each of Haley & Aldrich's subcontractors, consultants, officers, directors, and employees harmless against any and all claims for damages, costs, or expenses direct or consequential, in connection with a release of hazardous substances, except to the extent that such claims, damages, or losses are adjudicated to have resulted from Haley & Aldrich's gross negligence or willful misconduct in the performance of the services.

21. Limitation of Remedies

To the fullest extent permitted by law, the total liability of Haley & Aldrich, its officers, directors, and employees to Client, and anyone claiming by, through, or under Client, for any and all injuries, claims, losses, expenses, or damages whatsoever arising out of or in any way related to Haley & Aldrich's services, from any cause or causes whatsoever, including, but not limited to, negligence, errors, omissions, strict liability or contract, shall be limited to an amount of \$50,000 or Haley & Aldrich's fee, whichever is greater.

If Client prefers not to limit Haley & Aldrich's liability to this sum, Haley & Aldrich may increase this limitation upon Client's written request. If Haley & Aldrich approves the request, Haley & Aldrich will agree to increase the limitation to \$100,000, provided that Client agrees to pay \$1,000 for this change. The additional fee is for the additional risk assumed by Haley & Aldrich and is not a charge for additional liability insurance.

22. Dispute Resolution

If a dispute arises out of or relates to this Agreement or the breach thereof, the parties will attempt in good faith to resolve the dispute through negotiation. If the dispute is not resolved by these negotiations, the matter will be submitted to non-binding mediation with a mutually agreed upon mediator. The parties agree that they will participate in the mediation in good faith, that they will share equally in its costs, and that neither party will commence a civil action with respect to the matters submitted to mediation until after the completion of the initial mediation session.

23. Legal Action

All legal actions by either party against the other for any cause or causes, including, but not limited to, breach of this Agreement, negligence, misrepresentations, breach of warranty or failure to perform in accordance with the standard of care, however denominated, shall be barred two (2) years from the day after completion of Haley & Aldrich's Services. In the event that Client institutes a suit against Haley & Aldrich, and if such suit is not successfully prosecuted, or if it is dismissed, or if a verdict is rendered for Haley & Aldrich, Client agrees to pay Haley & Aldrich any and all costs of defense. including attorneys' fees, expert witnesses' fees, and court costs and any and all other expenses of defense which may be reasonably necessary, immediately following dismissal of the case or immediately upon judgment being rendered in favor of Haley & Aldrich.

24. Precedence

These Terms and Conditions shall take precedence over any inconsistent or contradictory provisions contained in any proposal, contract, purchase order, requisition, notice to proceed, or like document.

25. Severability

If any of these Terms and Conditions are finally determined to be invalid or unenforceable in whole or part, the remaining provisions shall remain in full force and effect, and be binding upon the parties. The parties agree to reform these Terms and Conditions to replace any such invalid or unenforceable provision with a valid and enforceable provision that comes as close as possible to the intention of the stricken provision.

26. Survival

These conditions shall survive the completion of Haley & Aldrich's services on this project and the termination of services for any cause.

27. Governing Law

This Agreement shall be governed and construed in accordance with the laws of the state of the contracting office of Haley & Aldrich.

End of Standard Terms and Conditions

APPENDIX B

Historical Research Documentation

Government of the District of Columbia

District Department of the Environment

Underground Storage Tank Branch



Toxic Substances Division

No Further Action Letter

April 1, 2010

Ms. Fariba Mahvi Pepco Holdings, Inc 701 Ninth Street, NW Washington, DC 20068

RE:

FACILITY NAME:

Pepco (Buzzard Generating Station)

FACILITY ADDRESS:

33 V Street, SE

FACILITY ID:

2-000609

LUST ID:

93051

Dear Ms. Mahvi:

The District Department of the Environment ("DDOE"), Underground Storage Tank Branch ("UST Branch"), hereby issues this No Further Action Letter ("NFA") in reference to the property/facility located at 33 V Street, SE (the "site"), and currently owned by **PEPCO HOLDINGS, INC** (the "Owner"), pursuant to the Underground Storage Tank Management Act of 1990 (D.C. Code § 8-113.01, *et seq.*), and the District of Columbia Underground Storage Tank Regulations, as set forth at Title 20 of the District of Columbia Municipal Regulations, Chapters 55-70 (20 DCMR 55-70).

This office has reviewed the Risk-Based Corrective Action (RBCA) report, dated March 24, 2010, prepared by Mactec Engineering and Consulting, Inc for the above referenced property and all other information submitted to date by the Owner pertaining to the release and clean-up of a regulated substance from the underground storage tank system at the above-referenced Facility. Based on the information reviewed, it is the judgment of the UST Branch that presently, the residual contamination left in place at this site does not pose a threat to human health and/or the environment. The site was evaluated under the current and future commercial land use scenario as spelled in the Risk Based Corrective Action Technical Guidance document. Accordingly, the UST Branch finds that no further remedial action is necessary at the site, unless the residually contaminated soil is removed, disturbed, or excavated.

The owner shall be responsible for removing all equipment and ensure that wells are closed down, removed, grouted and sealed properly in accordance with 20 DCMR § 6207.16.

In the event that additional work is performed at this site, which will require any additional removal, disturbance or excavation of the residually contaminated soil, Owner must report to this office for further direction and guidance, prior to commencement of work, as required by 20 DCMR § 6202. Failure to do so may result in an enforcement action against any responsible party, current or future Owners, pursuant to the Act and the regulations promulgated pursuant to that Act.

While **PEPCO HOLDINGS**, **INC** has complied with the current Leaking Underground Storage Tank case closure requirements of this Program, District of Columbia's Underground Storage Tank Management Act, and the regulations promulgated pursuant to that Act, this NFA shall not absolve the Owner, operator, or a responsible party from previously incurred or potential future liability due to any residual contamination left in place.

Please note that DDOE is required to publish success stories in brochures, fact sheets and on our website of sites cleanup in the District and returned to productive use. As such, this site may be chosen for this purpose. Please inform our office in writing if you have any objections or concerns with us using this site.

Should you have any question or concerns about this NFA, please call Dr. Bob Emwanta at 202.535.1944 or send an email to Bob.Emwanta@dc.gov.

Sincerely,

Fianna Phill, Chief

Underground Storage Tank Branch

Cc: Dr. Neven A. Kresic, Mactec Engineering

Advantage Environmental Consultants, LLC

PHASE I ENVIRONMENTAL SITE ASSESSMENT

Buzzard Point 2nd Street and V Street, SW Washington, DC 20024

AEC Project No. 05-099 June 10, 2005

Prepared for.

The John Akridge Companies, Inc. 601 13th Street, NW Suite 300 North Washington, DC 20005

Prepared by:

Advantage Environmental Consultants, LLC 8610 Washington Boulevard, Suite 217 Jessup, Maryland 20794
TEL (301) 776-0500 • FAX (301) 776-1123

TABLE OF CONTENTS

1.0	EXECUTIVE SUMMARY	1
1.1 1.2	SUMMARY AND FINDINGS	1 4
2.0	INTRODUCTION	5
2.1 2.2 2.3 2.4	PURPOSE SCOPE OF SERVICES LIMITATIONS AND EXCEPTIONS USER RELIANCE	5 6
3.0	SITE DESCRIPTION	8
3.1 3.2 3.3 3.4 3.5 3.6	LOCATION AND LEGAL DESCRIPTION. ZONING INFORMATION. CHARACTERISTICS OF THE SITE AND SURROUNDING PROPERTIES. CURRENT USE OF THE SITE. DESCRIPTION OF IMPROVEMENTS. CURRENT USES OF ADJOINING PROPERTIES.	8 9
4.0	USER PROVIDED INFORMATION	13
4.1 4.2 4.3 4.4 4.5 4.6	REASON FOR PERFORMING PHASE I ESA SPECIALIZED KNOWLEDGE VALUATION REDUCTION FOR ENVIRONMENTAL ISSUES. TITLE RECORDS. ENVIRONMENTAL LIENS OR ACTIVITY AND USE LIMITATIONS. OWNER, PROPERTY MANAGER, AND OCCUPANT INFORMATION	13 13 13
5.0	RECORDS REVIEW	14
5. 5. 5. 5. 5. 5. 5. 5. 5. 5. 5. 5. 5. 5	FEDERAL DATABASE REVIEWS. STATE DATABASE REVIEWS. LOCAL REGULATORY AGENCY RESEARCH. 3.1 County/Local Health Department. 3.2 County/Local Fire Department. 3.3 Department of Planning and Zoning. PHYSICAL SETTING SOURCES. 4.1 Topography and Hydrology. 4.2 Soils. 4.3 Geology. 4.4 Hydrogeology. HISTORICAL USE INFORMATION. 5.1 Aerial Photographs. 5.2 Fire Insurance Maps. 5.3 City Directories. 5.4 Property Tax Files. 5.5 Interview Information. 5.6 Previous Environmental Reports.	161818181819202022222424
5 6.0	5.7 Historical Use Summary	26 27

8.0	REFERENCES	31
7.0	FINDINGS AND CONCLUSIONS	30
6.8	OTHER CONDITIONS OF POTENTIAL CONCERN	29
6.7	INDICATIONS OF SOLID WASTE DISPOSAL	29
6.6	POLYCHLORINATED BIPHENYLS (PCBs)	20
6.5	STORAGE TANKS	28
6.4	Waste Generation, Storage and Disposal	27
6.3	HAZARDOUS SUBSTANCES IN CONNECTION WITH IDENTIFIED USES	27
6.2	Interviews	27
6.1	METHODOLOGY AND LIMITING CONDITIONS	27

APPENDICES

Appendix A - Site Vicinity Map

Appendix B - Site Plan

Appendix C - Site Photographs

Appendix D - Historical Research Documentation/Maps

Appendix E - Aerial Photographs

Appendix F - Records of Communication

Appendix G - Regulatory Records Documentation

Appendix H - Prior Environmental Reports

Appendix I – Qualifications of Environmental Professionals

1.0 Executive Summary

1.1 Summary and Findings

Advantage Environmental Consultants, LLC (AEC) has conducted a Phase I Environmental Site Assessment (ESA), in conformance with the scope and limitations of ASTM Practice E 1527-00, of the property referred to as Buzzard Point in southwest Washington, DC (hereinafter referred to as the "Site"). Any exceptions to, or deletions from, this practice are described in Section 2.3 of this report.

The Site consists of an approximately 384,051 square foot area that is bound by S Street, SW to the north, 1st Street, SW to the east, V Street, SW to the south, and 2nd Street, SW to the west in Washington, DC. T Street, SW transects the Site, and divides it into a small northern lot and a larger southern lot. The real estate designation for the northern Site lot is Square 607, Lot 13, and the designation for the southern Site lot is Square 609, Lot 804, and Square 611, Lots 19 and 810. Currently, the Site is used as two fenced parking lots; however, the Site has been owned by the Potomac Electric Power Company (PEPCO) since 1929, and was formerly used as a coal storage yard, a vehicle fueling area, a bulk #6 fuel oil storage facility, and an equipment storage area for the eastern adjacent decommissioned PEPCO Buzzard Point Generating Station (herein referred to as the "Generating Station").

Improvements to the Site include a prefabricated metal building and storage trailers at the northern Site lot and an unused bulk #6 fuel oil above-ground storage tank (AST), the associated fire fighting foam house, and a small storage shed at the southern Site lot. Guard stands are located at the entrances to both parking lots, and additional improvements at the Site include parking medians, light poles, and landscaping. The Site is leased from PEPCO to the US government for vehicle storage. This Phase I ESA was performed for financing purposes, to document any known contaminants, and discover the existence of any unknown contaminants at the Site.

The following summarizes the independent conclusions representing AEC's best professional judgment based on available information.

Historical Use Information

The review of historical resources indicated that the southern Site lot was used as a coal storage yard from the late 1920s until the Generating Station began using fuel oil to power the station in 1968. From 1968 until the Generating Station was decommissioned in 1981, the southern Site lot was used by PEPCO for bulk fuel storage and leased to W.A. Chester, Inc. for use as a vehicle and equipment maintenance and storage lot. An underground pipeline installed beneath 1st Street, SW was used to connect the 1.9-million gallon AST at the Site to the Generating Station.

The northern Site lot appeared to have been used for vehicle fueling and storage by PEPCO from the late 1960s until 1993. On-site Underground Storage Tanks (USTs) (one 6,000-gallon gasoline, one 6,000-gallon diesel fuel and one 20,000-gallon gasoline) were removed in 1988 and 1993.

Adjoining Properties

The Site is situated in a medium-density, mixed commercial, industrial, and government-use area of southwest Washington DC that is referred to as Buzzard Point. The area consists of several properties owned by the Potomac Electric Power Company, including the Site, the decommissioned Generating Station and active gas-fired combustion turbine yard (CT Yard), and a former PEPCO #2 fuel oil storage facility. Additional adjacent properties include a scrap metal yard, a US military fort, a US Coast Guard headquarters building, and two marinas. Potential environmental concerns were identified at four of the surrounding properties.

PEPCO Buzzard Point Generating Station

The Generating Station, located approximately 35 feet east across 1st Street from the Site, was identified in four separate Leaking Underground Storage Tank (LUST) cases, one of which remains open (LUST Case No. 93-051). In the early 1970s, a release was reported from a four-inch diameter underground pipeline that connected the CT Yard of the Generating Station to the two, 0.411-million gallon #2 fuel oil ASTs located north across S Street from the CT Yard. The release was repaired, and one 15" diameter monitoring well was subsequently installed in the vicinity of the pipeline leak. Significant petroleum (gasoline and diesel) contamination was discovered in soil and groundwater at the CT Yard portion of the Generating Station property in 1993. A total of 21 monitoring wells (MWs) were installed in the vicinity of the CT Yard and the #2 fuel oil ASTs. Two monitoring wells were also installed at the Site in the area of the former vehicle fueling station. Both soil and groundwater samples revealed the presence of Total Petroleum Hydrocarbon (TPH) Gasoline-Range Organics (GRO), Diesel Range Organics (DRO), and Benzene, Toluene, Ethyl benzene and Xylene (BTEX). In addition, the majority of the MWs located in the CT Yard and north adjacent bulk fuel storage area have historically contained liquid-phase hydrocarbon (LPH). Groundwater flow direction has been documented at this property to be west and southwest, towards the Site.

PEPCO installed a soil vapor extraction (SVE) system in the CT Yard and at the southern portion of the north adjacent bulk fuel storage area in January 1996, and operated the system through November 1999. From May 2001 to April 2002, a portable high vacuum pump and treat system was used to recover LPH at this property. The wells and groundwater vacuum monitoring points (GVPs) appear to have been monitored monthly from January 2003 through July 2004, with semi-annual sampling events. Groundwater sampling data for this property that was dated March 8, 2004 indicated that groundwater contaminants in the three downgradient wells were below Maximum Contaminant Levels and/or DC Water Quality Standards for BTEX and TPH GRO and DRO, while levels of these constituents remained above the applicable regulatory standards in remaining MWs

and GVPs. Currently, only passive remediation with absorbent booms and monitoring is ongoing at the Generating Station property.

The Generating Station was also identified on the Resource Recovery and Conservation Small Quantity Generator (RCRA SQG) database twice, and on the UST database.

Super Salvage, Inc.

The Super Salvage, Inc. property, located approximately 35 feet north of the Site, was listed on the RCRA SQG, LUST and UST databases. In addition, AEC observed operations at the facility to include the storage of metal scraps and debris on property soils, and historical research indicated that the Super Salvage, Inc. facility has been located adjacent to the Site since the 1960s. Violations were not reported on the RCRA SQG listing, and the LUST case has been granted closure. The UST listing stated that one 2,000-gallon UST was permanently out of use.

US Army Fort McNair

Fort McNair is a large US Army fort that is located west of the Site. This facility was listed on the Comprehensive Environmental Response, Compensation and Liability System (CERCLIS) database in association with the address 350 P Street, SW. The listed address is located approximately 2,000 feet northwest of the Site and appears to be downgradient. The listing indicated that the site status has been categorized as "low," and the facility has been listed on the CERCLIS database since 1980. The listing also indicated that lead cleanup is ongoing. Based on distance, gradient, site status and ongoing cleanup activities, the CERCLIS listing does not appear to represent a concern.

Fort McNair was also listed on the LUST database three times; however, based on distance and the documented west and southwest groundwater flow direction in the vicinity of the Site, AEC does not consider the LUST listings associated with Fort McNair to be a concern.

James Creek Marina

The James Creek Marina, located approximately 50 feet southwest and downgradient, was listed on the LUST and the UST databases. The LUST listing indicated that the case has been granted closure. The UST listing stated that one 10,000-gallon gasoline UST and one 10,000-gallon diesel fuel UST were currently in use, and one 2,000-gallon gasoline UST was permanently out of use. Based on the status of the LUST case and the downgradient location of this facility, it does not appear that the James Creek Marina is a concern to the Site.

Hazardous Substances

AEC did not observe any hazardous substances in connection with identified uses at the Site.

Waste Generation, Storage, and Disposal

No indications of waste generation, storage, or disposal were noted on the Site as it is used as two parking lots.

Storage Tanks

One 1.9-million gallon bulk fuel AST is located at the southern portion of the Site. Historically, the AST and an associated underground pipeline were used to provide #6 fuel oil from the AST to the adjacent Generating Station from the late 1960s until the Generating Station was decommissioned in 1981. No information regarding releases from the AST or pipeline is known.

In addition, a fueling station was historically located at the northern portion of the Site. Two 6,000-gallon and one 20,000-gallon USTs were installed at the Site for the storage of gasoline and diesel fuel from the late 1960s until 1993. A LUST Case was associated with the 20,000-gallon UST due to the discovery of petroleum impact to groundwater at the Site during removal of the UST. The LUST Case was granted regulatory closure in May of 1994; however, further soil and groundwater investigation of this area was included as an addendum to a *Comprehensive Site Assessment* report that was being prepared for the adjacent Generating Station. Groundwater contamination was

AEC considers the historic use of the bulk fuel AST, pipeline, and former USTs at the Site to be recognized environmental conditions.

Polychlorinated Biphenyls (PCBs)

AEC observed fluorescent light fixtures on poles installed throughout both Site lots. In 1979, the USEPA banned the manufacture and sale of PCBs. Based on the reported date of construction of the parking lot (after 1988), ballasts associated with the fluorescent light fixtures are unlikely to contain PCBs.

AEC did not identify additional equipment that would be suspected to contain PCBs at the Site.

Regulatory Review

UST and LUST listings associated with the Site were discussed in the Storage Tanks Section of this Executive Summary. Other than those listings discussed in the Adjacent Properties section of this Executive Summary, no regulatory database-listed properties were identified as potential concerns to the Site.

1.2 Recommendations

AEC has conducted a Phase II subsurface investigation of the Site concurrently with this Phase I assessment to determine the current condition of on-site soils and groundwater. The results of the Phase II investigation will be provided to the Client under separate cover. As such, AEC has no further recommendations.

2.0 Introduction

2.1 Purpose

The purpose of this Phase I Environmental Site Assessment (ESA) is to provide a professional opinion on the presence of recognized environmental conditions and other potential environmental conditions in connection with the Site, as they existed on the date of the site inspection, and to recommend whether further investigation is required. The American Society for Testing and Materials (ASTM) Standard Practice E 1527-00, Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process, defines good commercial and customary practice for conducting an environmental site assessment of a parcel of commercial real estate with respect to the range of contaminants pertinent to the scope of the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA), as well as petroleum products. As such, this ESA is intended to satisfy one of the requirements that permit the user to qualify for the innocent landowner defense to CERCLA liability. In other words, this ESA represents one of the practices that constitute "all appropriate inquiry into the previous ownership and uses of the property consistent with good commercial or customary practice" as defined in 42 USC Section 9601(35)(B).

The goal of the process is to identify recognized environmental conditions, which are defined by the Practice as "the presence or likely presence of any hazardous substances or petroleum products on a property under conditions that indicate an existing release, a past release, or a material threat of release of any hazardous substances or petroleum products into the structures on the property or into the ground, groundwater or surface water of the property". The term *recognized environmental condition* includes hazardous substances or petroleum products even under conditions in compliance with laws. The term is not intended to include de minimis conditions that generally do not present a material risk of harm to public health or the environment and that generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies.

2.2 Scope of Services

This assessment was conducted in accordance with generally accepted Phase I industry standards using ASTM Standard Practice E 1527-00 and AEC Proposal Number 05-102. The following services were provided for this assessment:

- An evaluation of information contained within Federal and State environmental databases, and other local environmental records, within specific search distances.
- An evaluation of past Site uses through a review of reasonably ascertainable standard historical sources such as chain-of-title information, historical maps, city directories, aerial photographs, prior environmental reports, and interviews with knowledgeable persons.

- A qualitative evaluation of the physical characteristics of the Site through a review of published topographic, geologic, hydrogeologic, wetland, and flood plain maps; published groundwater data; and area observations to characterize surface water flow in the Site area.
- An evaluation of current Site conditions including, but not limited to, a search for the following items including: underground storage tanks (above or below ground); potential PCB-containing electrical equipment; hazardous materials and petroleum products generation; treatment, storage, or disposal of hazardous, regulated, or medical wastes.
- The preparation of a Phase I ESA report, which represents the findings from the studies of the items described above and provides conclusions and recommendations based on the information gathered above and provided by the Client.

2.3 Limitations and Exceptions

This Phase I ESA was conducted in accordance with ASTM guidelines for the performance of Phase I Environmental Site Assessments. No other warranties, either express or implied, are made by AEC. AEC's evaluations, analyses, and opinions should not be taken as representations regarding subsurface conditions or the actual value of the Site. Subsurface conditions may differ from the conditions implied by the surficial observations, and can only be reliably evaluated through intrusive techniques.

Documentation and data provided by the Client, designated representatives of the Client, or other interested third parties, or from the public domain, and referred to in the preparation of this assessment, are assumed to be complete and correct and have been used and referenced with the understanding that AEC assumes no responsibility or liability for their accuracy. AEC's conclusions are based upon such information and documentation and on our observations of Site conditions, as they existed on the date of the site inspection. Since Site conditions may change significantly over a short period of time and additional data may become available, data reported and conclusions drawn in this report are limited to current conditions and may not be relied upon on a significantly later date.

Reasonable efforts have been made during this assessment to uncover evidence of USTs, ASTs, and ancillary equipment associated with these tanks. "Reasonable efforts" are limited to information gained from visual observation of unobstructed areas, recorded database information held in public record, and available information gathered from interviews. Such methods may not identify subsurface equipment that may have been hidden from view due to snow cover, paving, dense vegetation, construction or debris pile storage, or incorrect information from sources.

This investigation was not an environmental compliance audit. While some observations and discussion in this report may address conditions and/or operations that may be

regulated, the regulatory compliance of those conditions and/or operations is outside the scope of this investigation.

Nothing in this report constitutes a legal opinion or legal advice. For information regarding specific individual or organizational liability, AEC recommends consultation with independent legal counsel.

2.4 User Reliance

This report is intended exclusively for the use and benefit of the Client identified on the first page of this report.

This report is not for the use or benefit of, nor may it be relied upon by, any other person or entity for any purpose without the advance written consent of AEC. AEC makes no representation to any third party except that it has used the degree of care and skill ordinarily exercised by a reasonable prudent environmental professional in the same community and in the same time frame given the same or similar facts and circumstances. No other warranties are made to any third party, either express or implied.

3.0 Site Description

3.1 Location and Legal Description

The Site is bound by S Street, SW, 1st Street, SW, V Street, SW and 2nd Street, SW in Washington, DC. According to the Fares 2004 DC Assessment Directory, the Site is described as Square 607, Lot 13; Square 609, Lot 804; and Square 611, Lots 19 and 810. The Site comprises a total of 384,051 square feet of area. A Site Vicinity Map is included as Appendix A.

3.2 Zoning Information

Zoning information was obtained from the District of Columbia Office of Zoning's website http://www.dcoz.dcgov.org/info/map.shtm. According to the on-line zoning map, dated July 29, 2003, the Site is Zoned M (General Industry). The M zoning "permits general industrial uses to a maximum FAR of 6.0, and a maximum height of ninety (90) feet with standards of external effects and new residential prohibited."

AEC notes that a real estate offering document prepared by Cassidy & Pinkard and dated March 2005 indicated that the Site is zoned CG/CR. According to the document, the Zoning Commission for DC adopted the Map Amendment and Overlay District at Buzzard Point-Capital Gateway (GC), which created new zoning throughout much of the Site vicinity.

3.3 Characteristics of the Site and Surrounding Properties

The Site is situated in a medium-density, mixed industrial, commercial, and government-use area of southwest Washington DC that is referred to as Buzzard Point. The area consists of several properties owned by the Potomac Electric Power Company, including the Site, the decommissioned Generating Station and active gas-fired combustion turbine yard (CT Yard), and a former bulk #2 fuel oil storage facility. Remaining adjacent properties include a scrap metal yard, a US military fort, a US military headquarters building, and two marinas. Additional industrial and commercial business are located further north and east of the Site and the Anacostia River is present approximately 330 feet southeast and south of the Site. Detail regarding the immediately surrounding properties is provided in Section 3.6.

The Site is currently developed as two fenced, asphalt-paved parking lots that are separated by T Street, SW. The smaller northern Site lot is developed with a prefabricated metal building and a few storage trailers. The larger southern Site lot is developed with a bulk fuel AST, an associated fire fighting foam shed and a small storage shed. Guard stands are located at the parking lot entrances. Additional Site developments include parking medians, light poles, and landscaping. A copy of the Site Map is included as Appendix B.

3.4 Current Use of the Site

The Site consists of two, fenced, asphalt-paved parking lots that are both leased by PEPCO to the US Government for vehicle storage. The prefabricated building that exists at the northwestern portion of the northern lot is also leased and used by the US Government. AEC was not provided with access to this building for security reasons and the interviewed PEPCO employees did not know details regarding the specific use of this building by the government. The on-site trailers appeared to be used for storage. A 1.9-million gallon #6 fuel-oil AST and an associated fire fighting foam house that were previously used by PEPCO were present at the southern portion of the southern Site lot. The AST and an underground pipeline connecting the AST to the Generating Station have not been used by PEPCO since 1981. The fire fighting foam house was reportedly still operable as of 1995. A small storage shed that is used to store parking lot maintenance equipment (i.e., brooms, landscaping equipment, salt, etc.) was located at the northeastern portion of the southern parking lot.

3.5 Description of Improvements

The Site is improved with a prefabricated building, the bulk fuel storage AST and associated fire fighting foam house, a storage shed and trailers, and asphalt-paved parking areas.

• Source of Potable Water

Potable water in the vicinity of the Site is provided by the District of Columbia Water and Sewer Authority (WASA). According to a representative of the Army Corps of Engineers, who supplies the public drinking water supply for WASA, all water supplied to the District meets or exceeds local, state, and federal Environmental Protection Agency (EPA) drinking water quality standards.

Sewage Disposal

Public sanitary sewer service is provided in the vicinity of the Site by the Washington Area Sewer Authority (WASA). The Site does not use a private septic system.

Site Plan

A Site Plan is included as Appendix B.

3.6 Current Uses of Adjoining Properties

The area surrounding the Site consists of a mix of industrial, commercial and US government properties. The following table identifies the adjacent property uses.

Direction	Adjoining Property Use			
North	The Site is bordered to the north by S Street, SW, followed by the Super Salvage, Inc. metal scrap yard. A former PEPCO #2 fuel oil storage facility with two 0.411-million gallon bulk fuel storage ASTs are located northeast of the Site.			
East	The Site is bordered to the east by 1 st Street, SW, followed by the decommissioned Generating Station and active CT Yard.			
South	The Site is bordered to the south by V Street, SW, followed by the US Coast Guard headquarters building. The James Creek Marina and the Buzzard Point Marina are located southwest and southeast of the Site, respectively, along the bank of the Anacostia River.			
West	The Site is bordered to the west by US Army Fort McNair. A portion of US Army Fort McNair was under construction during the Site reconnaissance.			

Potential environmental concerns were identified at the following surrounding properties. Specific information was obtained for these properties from listings in the regulatory database report reviewed for this assessment (Sections 5.0), as well as prior reports and interviews. Potential concerns are discussed as follows:

PEPCO Buzzard Point Generating Station

The Generating Station, located approximately 35 feet east across 1st Street from the Site. was identified in four separate LUST cases, one of which remains open (LUST Case No. 93-051). A file review at the DC DOH revealed that In the early 1970s, a release was reported from a four-inch diameter underground pipeline that connected the CT Yard of the Generating Station to the two, 0.411-million gallon #2 fuel oil ASTs located north across S Street from the CT Yard. The release was repaired, and one 15" diameter monitoring well was subsequently installed in the vicinity of the pipeline leak. Significant petroleum (gasoline and diesel) contamination was discovered in soil and groundwater at the CT Yard portion of the Generating Station property in 1993. Initial assessments of the contamination revealed TPH concentrations ranging from 881 milligrams per kilogram (mg/kg) to 30,700 mg/kg. A total of 21 monitoring wells (MWs) were installed in the vicinity of the CT Yard and the north adjacent bulk fuel ASTs, and two monitoring wells were also installed at the Site in the area of the former vehicle fueling station. The MWs were installed between May 1993 and January 1995. Both soil and groundwater samples revealed the presence of TPH GRO, DRO, and BTEX. In addition, the majority of the MWs located in the CT Yard and north adjacent bulk fuel storage area have historically contained LPH. Groundwater flow direction has been documented at this property to be west and southwest, towards the Site.

PEPCO installed a SVE system in the CT Yard and at the southern portion of the bulk fuel storage area in January 1996, and the system was in operation through November 1999. The SVE system reportedly removed approximately 6,925 gallons of petroleum. From May 2001 to April 2002, a portable high vacuum pump and treat system was used to recover LPH from two of the most contaminated wells (MW-5 and MW-11). The pump and treat system removed an estimated 1.5 gallons of groundwater and 1,350 gallons of petroleum from these wells. The wells and/or groundwater vacuum monitoring points (GVPs) have been monitored monthly since 1993, with semi-annual sampling events. Results have been reported to the DC DOH in quarterly reports.

Groundwater sampling data for the Generating Station property that was dated March 8, 2004 indicated that groundwater contaminants in the three downgradient wells were below Maximum Contaminant Levels and/or DC Water Quality Standards.for TPH GRO, TPH DRO and BTEX, while levels of these constituents remained over the applicable regulatory standards in remaining MWs and GVPs. Currently, only passive remediation with absorbent booms and monitoring is ongoing at the Generating Station property.

The Generating Station was also identified on the RCRA SQG database twice, and on the UST database. The RCRA SQG database listings were associated with the generation of waste cadmium, lead and mercury, and did not include reported violations. The UST listing indicated that two 4,000-gallon used oil USTs were reported to be currently in use, and the following USTs were listed as permanently out of use: two 10,000-gallon heating oil USTs, four 2,000-gallon used oil USTs, one 2,000-gallon gasoline UST, and one 500-gallon hazardous substance UST.

Based on the historic presence of significant quantities of LPH in soil and groundwater at the adjacent Generating Station and the documented groundwater flow direction, this property is considered to be a concern to the Site.

Referenced prior environmental reports obtained through the DC DOH file review regarding LUST Case No. 93-051 included the following reports:

- Comprehensive Site Assessment, PEPCO Buzzard Point Station (CSA), prepared by TPH Technology, Inc. (TPH Inc.), dated August 11, 1993 (Executive Summary only)
- Corrective Action Plan, Remedial Specifications and Implementation Details, Buzzard Point Generating Station (CAP), prepared by TPH Inc., dated March 10, 1995
- Progress Report, LUST Case #93-051 Buzzard Point Station, prepared by PEPCO, dated June 7, 2002
- Progress Report, LUST Case #93-051 Buzzard Point Station, prepared by PEPCO, dated August 19, 2004

Super Salvage, Inc.

The Super Salvage, Inc. property, located approximately 35 feet north of the Site, was listed on the RCRA SQG, LUST and UST databases. In addition, AEC observed operations at the facility to include the storage of metal scraps and debris on property soils, and historical research indicated that the Super Salvage, Inc. facility has been located adjacent to the Site since the 1960s. Violations were not reported on the RCRA SQG listing. The LUST case has been granted regulatory closure. The UST listing stated that one 2,000-gallon UST was permanently out of use at this property. While regulatory listings do not indicate an obvious environmental concern, the long term use of this property as a scrap yard has the potential to create a recognized environmental condition.

US Army Fort McNair

Fort McNair is a large US Army fort that is located west of the Site. This facility was listed on the Comprehensive Environmental Response, Compensation and Liability System (CERCLIS) database in association with the address 350 P Street, SW. The listed address is located approximately 2,000 feet northwest of the Site and appears to be in a downgradient location from the Site. The CERCLIS listing indicated that the site status has been categorized as "low," and the facility has been listed on the CERCLIS database since discovery in 1980. The listing also indicated that lead cleanup is ongoing at this facility. Based on distance, gradient, site status and ongoing cleanup activities, the CERCLIS listing does not appear to represent a concern.

Fort McNair was also listed on the LUST database three times. Two of the LUST cases were listed as open cases while the third case has been granted regulatory closure. The two open LUST listings specify the location of the LUSTs as the Fort McNair parking lot, at 103 3rd Street, SW. This location is approximately 700 feet northwest of the Site. There is no indication of the capacity or contents of the LUSTs, and Fort McNair was not listed on the UST database. However, based on distance and the documented west and southwest groundwater flow direction in the vicinity of the Site, AEC does not consider any of the LUST listings associated with Fort McNair to be a concern.

James Creek Marina

The James Creek Marina, located approximately 50 feet southwest and downgradient of the Site, was listed on the LUST and the UST databases. The LUST listing indicated that the case has been granted regulatory closure. The UST listing stated that one 10,000-gallon gasoline UST and one 10,000-gallon diesel fuel UST were currently in use at this property, and one 2,000-gallon gasoline UST was permanently out of use. Based on the regulatory status of the LUST case and the downgradient location of this facility, it does not appear that the James Creek Marina is a concern to the Site.

Specific concerns were not noted for the remaining surrounding properties.

4.0 User Provided Information

4.1 Reason for Performing Phase I ESA

According to Mr. Dodd Walker, of the John Akridge Companies, Inc., the Client retained AEC to conduct this Phase I ESA for financing purposes, to document any known contaminants, and discover the existence of any unknown contaminants at the Site.

4.2 Specialized Knowledge

Mr. Walker provided two previous environmental reports to AEC that documented on-site soil and groundwater contamination.

4.3 Valuation Reduction for Environmental Issues

Mr. Walker had no knowledge of value reduction of the Site for environmental issues.

4.4 Title Records

Title records were not provided to AEC; however, interview information indicated that PEPCO has owned the Site since the late 1920s.

4.5 Environmental Liens or Activity and Use Limitations

Mr. Walker was not aware of any environmental liens or activity or use limitations that are related to environmental issues at the Site.

4.6 Owner, Property Manager, and Occupant Information

The current owner of the Site is PEPCO. The Site is leased and occupied by the US Government.

5.0 Records Review

AEC reviewed Federal and State environmental databases provided by Environmental Data Resources, Inc. (EDR) of Milford, Connecticut, for information pertaining to documented and/or suspected releases of regulated hazardous substances and/or petroleum products within specified search distances.

AEC also reviewed the unmappable sites listed in the environmental database report by cross-referencing addresses and site names. Unmappable ("orphan") sites are sites that cannot be plotted with confidence, but can be located by zip code or city name. In general, a site cannot be mapped because of inaccurate or missing location information in the record provided by the regulatory agency. Any unmappable sites that AEC identified within the specified search radii are included and discussed in the corresponding database sections.

5.1 Federal Database Reviews

National Priorities List (NPL)

The National Priorities List (Superfund) is the EPA's database of uncontrolled or abandoned hazardous waste sites identified for priority remedial actions under the Superfund Program. This database was last updated April 28, 2005.

 Neither the Site nor any properties within one mile of the Site are listed on the Federal NPL.

Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS)

The CERCLIS List is a compilation of known and suspected uncontrolled or abandoned hazardous waste sites which are, or were, under investigation by the EPA but have not been elevated to the status of a Superfund (NPL) site. This database was last updated February 15, 2005.

- The Site was not listed on the CERCLIS database.
- US Army Fort McNair was listed on the CERCLIS database. This facility was previously discussed in Section 3.6 of this report.

Resource Conservation and Recovery Information System (RCRIS)

The USEPA's Resource Conservation and Recovery Act (RCRA) Program identifies and tracks hazardous waste from the point of generation to the point of disposal.

RCRIS Treatment, Storage, and Disposal (TSD) Facilities

The RCRIS-TSD database is a compilation by the USEPA of reporting facilities that transport, treat, store, or dispose of hazardous waste. This database was last updated on March 13, 2005.

 Neither the Site nor any properties within one-half mile of the Site were identified on the RCRIS-TSD database.

RCRIS CORRACTS

The RCRIS CORRACTS database identifies TSD facilities that have conducted, or are currently conducting, corrective actions as regulated under RCRA. This database was last updated on March 29, 2005.

- The Site was not listed on the RCRIS CORRACTS database.
- The Southeast Federal Center at 2nd and M Street, SW, was listed on the CORRACTS database. This facility is located over 3,000 feet from the Site. The listing indicated that this facility required corrective actions from 1997 through 2004; however, based on distance, the CORRACTS listing does not appear to represent a concern to the Site.

RCRIS Generators

The RCRIS Generator database tracks large and small quantity generators (SQG) of hazardous waste. This database was last updated on March 13, 2005.

- The Site was not listed on the RCRIS database of hazardous waste generators.
- A total of three RCRIS SQGs were identified within one-quarter mile of the Site. Listings associated with the adjacent PEPCO Buzzard Point Generating Station and Super Salvage, Inc. facilities were previously discussed in Section 3.6.
- The Steuart Petroleum Company South Capital Terminal, located at 1721 South Capital Street was also identified on the RCRIS SQG and LUST databases. In addition, Steuart Investment Company was identified on the LUST database at 1724 South Capital, SE. It is not clear whether these addresses refer to portions of the same Steuart facility; however, previous reports have indicated that a Steuart fuel terminal was formerly located east of the northeast adjacent PEPCO bulk fuel storage facility, approximately 800 feet northeast of the Site. One of the Steuart LUST listings has been granted regulatory closure, while the remaining LUST case

appears to have been open since 1987. The RCRIS SQG listing indicated that the facility had two reported violations; however both list compliance dates. The prior CSA report that was reviewed during the DC DOH file review identified the Steuart facility as a possible source for contamination at the PEPCO CT Yard; however, based on distance and the intervening groundwater remediation activities that have been conducted at the Generating Station, AEC does not consider the former Steuart facility to be an immediate concern to the Site.

RCRIS Administrative Action Tracking System (RAATS)

The RAATS database maintains records of enforcement actions issued under RCRA for major violators. This database was last updated on April 17, 1995.

The Site was not listed in the RAATS database.

Emergency Response Notification System (ERNS) Database

The ERNS is a national database used to collect information on reported releases of oil or hazardous substances. ERNS is now part of the National Response Center (NRC) database. This database was last updated December 31, 2004.

The Site is not listed in the ERNS database.

5.2 State Database Reviews

State Hazardous Waste Sites (SHWS):

The District of Columbia does not maintain a SHWS database. Such cases are maintained on the CERCLIS database, which was previously discussed.

Solid Waste Facilities/Landfill Sites (SWF/LF)

The District of Columbia does not maintain a SWF/LF database as the District does not have landfills.

Leaking Underground Storage Tanks (LUST)

The District of Columbia's LUST database is a list of petroleum release cases monitored by the DC DOH. This database was last updated January 6, 2005.

- The Site was listed in the LUST and the UST databases. These listings are discussed in the following Section 6.5 of this report.
- A total of 13 additional LUST listings were associated with facilities within one-half mile of the Site. Four of these listings were associated with adjacent properties, and

were previously discussed in Section 3.6 of this report. The two LUST listings associated with Steuart Petroleum and Steuart Investment Company were previously discussed in the RCRIS SQG subsection of this report.

- The Home Moving and Storage facility at 1812 Half Street, SW, approximately 500 feet northeast of the Site, was included on the LUST database. Groundwater flow in this specific area has not been documented; however, due to this facility's proximity to the Anacostia River, it is likely that groundwater flow would be towards the southeast. As such, AEC does not consider this facility to be a concern.
- The remaining six LUST cases are not considered likely to impact the Site based on topographic relationship, distance, and/or regulatory status (i.e., closed case).

Underground Storage Tanks (USTs)

This database lists registered USTs that are regulated under Subtitle I of the RCRA and must be registered with the State department responsible for administering the UST Program. This database was last updated January 6, 2005.

- The Site was listed twice on the UST database in association with the former use of the northern Site lot as a vehicle fueling area. These listings are discussed in the following Section 6.5 of this report.
- Three UST listings were associated with adjacent properties and were discussed in Section 3.6 of this report.
- None of the remaining UST listings were considered to be a concern to the Site based on the lack of reported releases or the closed status of an associated LUST case, and/or the indication that the USTs have been permanently removed.

Voluntary Cleanup Program (VCP) Sites

The VCP database oversees owner or developer initiated voluntary remediation of contaminated lands and buildings that return actual or potentially contaminated properties to productive uses. This database was last updated March 1, 2004.

 Neither the Site nor any properties within one-half mile of the Site were identified on the VCP database.

5.3 Local Regulatory Agency Research

The following local regulatory agency review was conducted to obtain any environmentally significant information concerning the Site that may be readily available.

5.3.1 County/Local Health Department

A file review was conducted at the DC DOH under the FOIA. A copy of AEC's request letter is included in Appendix F. Information gained from the file review is included in Sections 3.6 of this report.

5.3.2 County/Local Fire Department

As required by the agency, AEC has submitted a written request under the Freedom of Information Act (FOIA) to the D.C. Fire & EMS Department in order to obtain any environmentally significant information concerning the Site. At the time of completion of this report, a response from this agency remained outstanding. Upon receipt and review, AEC will forward any pertinent information to the Client. A copy of AEC's request letter is included in Appendix F.

5.3.3 Department of Planning and Zoning

As previously noted, according to the on-line zoning map, the Site is zoned M (General Industry); however, a real estate offering document prepared by Cassidy & Pinkard, dated March 2005, indicated that the Site is zoned CG/CR. According to the referenced document, the Zoning Commission for DC adopted the Map Amendment and Overlay District at Buzzard Point-Capital Gateway (GC), which created new zoning throughout much of the Site vicinity.

5.4 Physical Setting Sources

The following physical setting sources were reviewed to provide information about the topographic, hydrologic, geologic and/or hydrogeologic characteristics of the Site.

5.4.1 Topography and Hydrology

USGS Topographic Quadrangle

AEC reviewed a copy of the United States Geological Survey (USGS) 7.5 Minute Series, Alexandria, Virginia Topographic Quadrangle map dated 1994. According to the map, the elevation of the Site is approximately 14 feet above mean sea level (msl). The area on and around the Site is relatively level, with the natural topographic gradient across the Site being south-southwest. The Site was illustrated with the prefabricated building at the northern Site boundary, an apparent access road from T Street, SW onto the northern Site lot, and the bulk fuel storage AST at the southern portion of the southern Site lot. No surface bodies of water were illustrated on the Site.

A copy of the topographic map is included as Appendix A.

Hydrology/Storm Water Management

Surface drainage at the Site flows into the stormwater drains located at the edges of the parking lots, which discharge to the municipal storm sewer. AEC did not observe evidence of vegetative stress or other evidence of environmental impairment on the Site.

No evidence of surface impoundments, ponds, lagoons, drywells, irrigation wells, injection wells, water supply wells, or storm water management systems was observed on the Site on the date of the site inspection. Two pits are located adjacent to the bulk fuel storage AST, at the southeastern portion of the Site. The function or purpose of the pits could not be ascertained during the Site inspection, and Mr. Shahid Anis indicated that he had no knowledge of the previous function or purpose associated with the pits. The pits were inspected on the date of the site reconnaissance and were found to contain water. No evidence of a petroleum sheen or odor was noted. In addition, water samples that were collected from the pits during the course of the previous URS *Limited Subsurface Investigation*, dated March 22, 2005, were non-detect for both TPH GRO and TPH DRO. Based on AEC's observations of the water in the pits and the previous non-detect laboratory results, it does not appear that they have contributed to recognized environmental conditions at the Site at this time.

Wetlands

According to wetlands data obtained from National Wetlands Inventory (NWI) maps presented in the regulatory database report reviewed for this assessment, no wetlands were illustrated on the Site, and very little wetlands were associated with the bank of the Anacostia River, located south and southeast of the Site.

Flood Zone

According to the EDR database report which contains Federal Emergency Management Agency (FEMA) Flood Insurance Rate Map (FIRM) information, 100-year flood zones are located south and southwest of the Site, and 500-year flood zones appear to extend along the southeastern portion of the eastern Site boundary, and north from the Anacostia River through the west adjacent Fort McNair property. A copy of the database report is provided in Appendix G.

5.4.2 Soils

According to the Soil Survey of District of Columbia prepared by the United States Department of Agriculture Soil Conservation Service as obtained from the website http://www.sawgal.umd.edu/nrcsweb/DC/DistrictOfColumbia/dmap/10/indexW.html, soil at the Site is classified as Urban Land (Ub). Urban Land soils are classified as areas where more than 80 percent of the surface is covered by asphalt, concrete, buildings, or other impervious surfaces. Urban land soils are not a hydric soil, and permeability of the soil is considered highly variable due to cutting and filling activities.

5.4.3 Geology

According to the Maryland Geologic Survey Geologic Map of Maryland dated 1968 obtained from the website http://www.mgs.md.gov/esic/geo/lgcp.html#ql (which includes the District of Columbia), the Site is located in the Atlantic Coastal Plain physiographic province, which is situated east of the fall line that separates the unconsolidated sediments of the Atlantic Coastal Plain province from the metamorphic units of the Piedmont. Specifically, the Site is underlain by the Mesozoic Era, Cretaceous System, and Lower Cretaceous Series stratigraphic unit.

5.4.4 Hydrogeology

According to the USGS Ground Water Atlas of the United States (1997), the principal aquifer underlying the Site is the Potomac aquifer of the Northern Atlantic Coastal Plain aquifer system. The Northern Atlantic Coastal Plain aquifer system consists mostly of semi consolidated sand aquifers separated by clay confining units.

Based on the review of the soil, geologic, and hydrogeologic information as well as prior subsurface investigation reports, AEC concludes that the potential of site soils for contaminant or leachate migration is low to moderate. Prior environmental investigations have shown that the depth to the unconfined aquifer at the Site exists at a depth of approximately 15 to 20 feet below ground surface (bgs). Groundwater flow direction has been shown to be to the west-southwest, towards the convergence of the Potomac and Anacostia Rivers and the Washington Channel.

5.5 Historical Use Information

AEC reviewed the following historical sources to develop a history of the previous uses of the Site and surrounding area, in order to help identify the likelihood of past uses having led to recognized environmental conditions in connection with the Site.

5.5.1 Aerial Photographs

AEC reviewed an aerial photographs dated 1957, 1963, 1970, 1980 and 1988 that were obtained from EDR and an aerial photograph dated January 2004 that was obtained from GlobeXplorer.com. The results of the aerial photograph reviews are summarized as follows:

	Aerial Photograph Review
Year	Observations
1957	SITE: The northern Site lot appeared to be used as an unpaved vehicle or electrical equipment storage area. The southern lot appeared to be used as a storage lot for stockpiled coal. A conveyor system and a small building appeared to be located at the east-central portion of the southern Site lot. A railroad siding also appeared to be located along the northern and eastern portion of the Site lot SURROUNDING AREA: Surrounding areas appeared to consist of former Ft. McNair buildings to the west and northwest, a few small structures and trees to the north, a partially cleared lot followed by the former Steuart fuel storage terminal to the northeast, a small cleared lot, the Generating Station and additional coal storage to the east, and two marinas and an undeveloped lot to the south.
1963	SITE: Site conditions were similar to those in the 1957 photograph, with the exception that additional vehicles or equipment were stored on the northern Site lot, and at the northeastern corner of the southern Site lot. SURROUNDING AREA: Surrounding areas were similar to those on the 1957 photograph, with the exceptions that two small structures appeared to have been constructed at the previously undeveloped lot south of the Site, and areas of the marina southwest of the Site had been cleared.
1970	SITE: The prefabricated building had been installed at the northern Site lot, and it appeared that this area was being used for vehicle fueling and storage. The bulk fuel storage AST had been constructed at the southern portion of the southern Site lot, while the remaining portions of the lot were still being used for coal storage. SURROUNDING AREA: Areas north, west and south of the Site appeared similar to those on the 1963 photograph. The combustion turbines appeared to have been installed in the former coal storage area at the eastern adjacent Generating Station property. In addition, two bulk storage ASTs had been installed northeast of the Site.
1980	SITE: The Site appeared similar to the 1970 photograph, with the exception that it did not appear that the southern Site lot was being used for coal storage any longer. SURROUNDING AREA: Surrounding areas appeared similar to those on the 1970 photograph, with the exception that the US Coast Guard headquarters building had been constructed south of the Site and the northernmost Ft. McNair building, which had been located northwest of the Site, had been demolished.
1988	SITE: The Site appeared similar to the 1980 photograph; however, it appeared that the Site lots were becoming overgrown. SURROUNDING AREA: Surrounding areas appeared similar to the 1980 photograph, with the exception that the remaining two Fort McNair buildings that were located west of the Site had been demolished.

	Aerial Photograph Review
Year	Observations
2004	SITE: The Site appeared similar as it did on the date of the Site reconnaissance. Both Site lots were developed as asphalt-paved parking lots. The prefabricated building and bulk fuel storage AST were present at the north and south portions of the Site. SURROUNDING AREA: Areas surrounding the Site appeared similar as they did on the date of the Site reconnaissance. Surrounding areas consisted of the scrap yard to the north, the PEPCO bulk fuel storage facility to the northeast, the Generating Station to the east, the Buzzard Point Marina to the southeast, the Coast Guard headquarters building to the south, the Fort McNair Yacht Club marina to the southwest, and Ft. McNair to the west.

Copies of the reviewed aerial photographs are included in Appendix E.

5.5.2 Fire Insurance Maps

Sanborn Maps dated 1984, 1988, 1990, 1991, 1992 and 1994 were reviewed for this assessment. The following are descriptions and interpretations from the historical map review: Copies of the fire insurance maps are provided in Appendix D.

	Historical Map Review			
Years	Observations			
1984 through 1994	SITE: The Site appeared as a PEPCO vehicle storage lot and garage building on the northern Site lot and a PEPCO property storage yard and bulk fuel storage facility on the southern Site lot on all of the reviewed fire insurance maps. SURROUNDING AREA: Areas surrounding the Site appeared similar on all of the reviewed Sanborn maps, with the exception that buildings associated with Fort McNair to the west of the Site were demolished between 1984 and 1988, and one new building was constructed in approximately 1990. Surrounding areas on all of the reviewed maps generally consisted of a parking lot and scrap metal yard to the north, the PEPCO bulk fuel storage facility followed by the Steuart Petroleum bulk fuel terminal and a Hess Oil & Chemical Corporation fuel plant to the northeast, the PEPCO transfer yard and Generating Station to the east, and the Buzzards Point Marina, US Government Office Building (Coast Guard headquarters), and the Fort McNair Yacht Club to the south.			

5.5.3 City Directories

AEC reviewed historic city directories dated 1948, 1956, 1965, 1970, 1975, 1980, 1990 and 2000 at the Martin Luther King, Jr. Library, Washingtonian Room. The following is a summary of information from the city directory review.

	City Directory Review
Years	Observations
1948	SITE: Addresses related to the Site were not listed. SURROUNDING AREA: Listings for surrounding areas included residences, Morauer & Hartzell excavating contractors, Webb Aircraft Sales, Conserco Concrete, Howat Concrete Company, Stephens Clifford dairy, Highland Farms Milk Company, WashTrailor Company and Keyston Alloys Company.
1956	SITE: Addresses related to the Site were not listed SURROUNDING AREA: Listings for surrounding areas included residences, High's Dairy, John S. Reece auto wrecker, D&M Wrecking Company, John S. Reece auto storage lot, US Army Department of Engineers, Corinthian Yacht Club, Howat Concrete Company, and Am Moving Service, Inc.
1965	SITE: cor Buzzard Point Yard SURROUNDING AREA: Listings for the surrounding area included Shulman's Liquor Morauer & Hartzell, Merchant's Transfer & Storage, Austin Nichols & Company, Inc., Super Salvage, Inc., Hall's Restaurant, Blue Spade Wall Covering, Corinthian Yacht Club Steward House, Corinthian Yacht Club club house, Howat Concrete, and Long Marine Service (repairs).
1970	SITE: Cor PEPCO (Equip Yard), PEPCO (garage) SURROUNDING AREA: Listings for the surrounding area included residences, High's Dairy Products, Inc., Shulman's SW Liquors, Austin Nichols & Co., Merchant's Transfer & Storage, Super Salvage, Inc., Buzzard Point Boat Yard & Sail Boat Rentals, PEPCO (Buzzard Point Generating Station), Hall's Restaurant, US Army HQ, Jacob's Transfer, Corinthian Yacht Club, Littleford Michl Marine Service (repairs), Gov't Services, Inc., Fort McNair Yacht Basin, and Howat Concrete Company.
1975	SITE: Addresses related to the Site were not listed. SURROUNDING AREA: Listings for the surrounding area included Buzzard Point Marina, Shulman's SW Liquor, Fairchild Adjustment, Merchant Transfer & Storing, United Van Lines Agency, Super Salvage, Inc., residences, American Battle Monument, Finance & Act of USA, Morauer & Hartzell, Valet Shop, McLachlen Nat'l Bank, Office Cleaning, Inc., US Railway Association, USCG Documentation and Westwood Management.
1980	SITE: Addresses related to the Site were not listed. SURROUNDING AREA: Listings for the surrounding area included Shulman's Liquor, Super Salvage, Inc., PEPCO, Buzzard Point Boat, Buzzard Point Marina, residences, Custom Food Mng Sys, McLachln Bk Wtrfrnt, Office Cleaning, Inc., United St. Railway, US Gov't Nat'l Admin, US Railway Association, Westwood Management and Ft. McNair Yacht.

	City Directory Review				
Years	Observations				
1990	SITE: Addresses related to the Site were not listed. SURROUNDING AREA: Listings for the surrounding area included Chang's Carry Out, Shulman's Liquor, Super Salvage, Inc., Buzzard Point Boat, residences, Carlson Food Systems, Gelco Travel, Liberty Building, Tamsco, US Trans CG Aux HQ, Boat Repairs, Chief Warrant Officers, Fort McNair Yacht and Goose Bay Aggregate.				
2000	SITE: Addresses related to the Site were not listed. SURROUNDING AREA: Listings for the surrounding area included Super Salvage, Inc., Buzzard Point Boat, Building Service Management, Nat'l War College Alumni Assn, US DOT, US Trans CG HQ Support Command, US Trans CG Info, Personnel, apartments and the James Creek Marina.				

5.5.4 Property Tax Files

AEC reviewed available tax file information for the Site from the District of Columbia Chief Financial Officer's website (http://www.taxpayerservicecenter.com). The tax file indicates that the Site is owned by PEPCO. No additional pertinent information was available from this source. Property detail reports of the Site parcels are included in Appendix D.

5.5.5 Interview Information

AEC interviewed Mr. Shahid Anis of PEPCO for information regarding the Site. Information obtained from Mr. Anis is included in pertinent sections of this report. A copy of the questionnaire that answered by Mr. Anis is included in Appendix F.

5.5.6 Previous Environmental Reports

PEPCO provided the following previous environmental reports in association with the Site to the Client:

- Phase I Environmental Assessment report, prepared by URS Corporation, Inc. (URA), dated April 4, 2005
- Limited Phase II Environmental Investigation report, prepared by URS, dated March 22, 2005

AEC reviewed the previous reports as a part of this assessment. The findings and conclusions of the reviewed reports are summarized below.

URS prepared a Phase I ESA of the Buzzard Point Property in April 2005. AEC notes that this assessment did not include the northern Site lot (Square 607). The URS assessment included interviews with Mr. Shahid Anis and Mr. Fariba Mahui of PEPCO, and referenced previous environmental reports in association with the Site and adjacent Generating Station. In addition, an environmental assessment questionnaire that was answered by Mr.

S.H. Taylor and Mr. L.B. Spencer of W.A. Chester, Inc. was included in the report. The questionnaire indicated that the southern Site lot was leased to W.A. Chester, Inc. beginning in 1972 for use as a vehicle and equipment storage and maintenance area.

Based on their assessment, URS identified the historic use of the southern Site lot for coal storage and fuel storage as concerns. In particular, potential leaks from the underground pipeline and the pits near the bulk fuel storage AST were thought to have the potential to create a recognized environmental condition at the southern Site lot. The former fueling station that was located at the northern Site lot was also identified as a recognized environmental condition. Off-site recognized environmental conditions included the inactive Generating Station, the former PEPCO storage yard, and the Super Salvage scrap yard.

URS conducted a Limited Phase II Environmental Investigation in January 2005 that included 12 soil borings completed to depths ranging from 10 feet to 32 feet bgs. This report did not include boring logs. In addition to the boring exploration, water from the two concrete pits located adjacent to the AST was also sampled and analyzed. The URS investigation did not include any sampling of surficial soils at the site; all sampling was at a depth of at least 10 feet below ground surface. This study did not include an investigation of the northern Site lot (Square 607).

Groundwater, pit water, and soils were sampled and analyzed for various chemical parameters including TPH GRO and DRO, VOCs, Semi-Volatile Organic Compounds (SVOCs), priority pollutant metals, and PCBs.

The result of the analyses indicated that some soils at the site are impacted with petroleum hydrocarbons and groundwater is impacted with petroleum hydrocarbons and lead. The lead impact to groundwater was identified at both locations where analyses were performed. The lead concentrations in groundwater were elevated and were not likely to be the result of naturally occurring conditions. These lead concentrations ranged from 1,900 to 8,800 micrograms per liter (ug/l). URS concluded that there is evidence that soil and groundwater has been affected by releases of petroleum hydrocarbons, and the presence of combustion products and metals.

Geomatrix conducted an assessment of the Buzzard Point Properties, including the northern Site lot. The date of this assessment is unknown (a review of the document failed to provide a date at which the field work was performed or report was prepared). Due to the sampling methodology (composite) and the fact that laboratory analytical reports were not attached to the document received from PEPCO, this material was deemed unreliable.

Previous environmental reports concerning the adjacent Generating Station were obtained by AEC at the DC DOH. Information from these reports was discussed in Section 3.6 of this report.

Copies of the reviewed prior reports have been provided in Appendix H. Due to the volume of these reports, information that has been deemed superfluous has been omitted from the copies attached herein.

5.5.7 Historical Use Summary

The past use of the Site, as determined by a review of reasonably ascertainable historical information, is summarized in the following table:

Historical Use of the Site				
Years	Site Use			
Late 1920s to 1968	The Site was used as a coal storage yard and a vehicle or equipment storage lot.			
1968 to 1981	The northern Site lot was used as a vehicle fueling and storage lot. The southern Site lot was used for coal storage and bulk fuel storage, until the remaining coal was removed or used in approximately 1972. After 1972, the southern Site lot was used for bulk fuel storage by PEPCO, and as a vehicle and equipment storage and maintenance area by W.A. Chester, Inc.			
1981 to 1990s	The Generating Station was decommissioned in 1981, and the Site appeared to be unused from 1981 until it was developed into two asphalt-paved parking lots, sometime after 1988.			
1990s to present	Two asphalt-paved parking lots that are owned by PEPCO and leased to the US Government.			

The review of the above-referenced historical sources indicated that the southern Site lot was used as a coal storage yard from the late 1920s until the Generating Station began using fuel oil to power the plant in 1968. From this point until the Generating Station was decommissioned in 1981, the southern Site lot was used for bulk fuel storage. An underground pipeline was used to connect the 1.9-million gallon AST to the Generating Station. The northern Site lot appeared to have been used for vehicle fueling and storage from the late 1960s until the USTs (one 6,000-gallon gasoline, one 6,000-gallon diesel fuel and one 20,000-gallon gasoline) were removed in 1988 and 1993. In conclusion, the historical use of the Site as a coal storage yard, a bulk fuel storage facility and a vehicle fueling station are recognized environmental conditions.

6.0 Site Reconnaissance

The objective of the site reconnaissance was to obtain information indicating the likelihood of any recognized environmental conditions in connection with the Site. This reconnaissance was conducted on Tuesday, June 7, 2005 by Ms. Leslie Kopchinski, Project Manager of AEC. Ms. Kopchinski was not provided with access to the Site during the site reconnaissance; however, the majority of on-site improvements could be observed through the security fences. Mr. Jeff Stein and Mr. John Merletti of AEC were provided with Site access during the concurrent Phase II Subsurface Investigation. The weather conditions at the time of both Site inspections were sunny, with temperatures in the 75-degree Fahrenheit range.

6.1 Methodology and Limiting Conditions

The site reconnaissance consisted of walking the public sidewalks around the perimeter of the Site and the public access roads in the surrounding area of the Site. As previously noted, AEC had very limited access to the Site for the purpose of the Phase I Site Assessment; however, Mr. Jeff Stein and Mr. John Merletti of AEC were provided with access to the Site during the concurrent Phase II Subsurface Investigation. Photographs of the Site were taken during the Phase II investigation to document existing site conditions and are included and described in Appendix C.

6.2 Interviews

AEC interviewed Mr. Shahid Anis and Mr. Vernon Gibson, both of PEPCO, regarding the Site. Information obtained from this interview is included in pertinent sections of this report.

6.3 Hazardous Substances in Connection with Identified Uses

AEC did not observe any hazardous substances in connection with identified uses at the Site. Reportedly, parking lot maintenance supplies such as a broom, salt and landscaping equipment are stored in the shed located on the southern Site lot. AEC was not provided with access to this shed during either Site visit; however, Mr. Anis stated that the same parking lot maintenance supplies are currently stored in this area, and AEC does not consider these supplies to be a concern to the Site. Additionally, AEC was not provided with access to the prefabricated building at the northern Site lot due to security concerns. Mr. Vernon Gibson of PEPCO indicated that the building is used by the US Government, and he had no additional knowledge regarding the use of this building by the government.

6.4 Waste Generation, Storage and Disposal

No indications of waste generation, storage, or disposal were noted on the Site as it is used as two parking lots.

6.5 Storage Tanks

One 1.9-million gallon bulk fuel storage AST is located at the southern portion of the southern Site lot. The AST is surrounded by an approximate six foot concrete containment dike. The exact installation date of this AST is unknown; however, historical research has revealed that it was installed when the adjacent PEPCO Generating Station was converted from being fueled by coal to using #6 fuel oil in the late 1960s. Mr. Shahid Anis of PEPCO stated that he did not know whether releases from the bulk fuel storage AST had occurred. Reportedly, an underground pipeline connected the AST to the Generating Station. Mr. Anis did not provide any information regarding the pipeline or any related releases. Previous environmental reports have indicated that both the AST and the underground pipeline were taken out of service in 1981 when the Generating Station was decommissioned. The previous URS Phase I ESA report indicated that the AST has remained empty since 1981 and the pipeline was filled in place.

Additionally, the northern Site lot was previously used by PEPCO as a vehicle fueling station and storage lot from 1970 until 1993. One 20,000-gallon gasoline UST, one 6,000-gallon gasoline UST, and one 6,000-gallon diesel fuel UST were previously located at the southeastern portion of the northern Site lot, identified as 180 S Street, SW and as the Buzzard Point gas station. Both of the 6,000-gallon USTs were removed from the Site in November 1988. Regulatory review revealed two separate UST listings that reference four 6,000-gallon gasoline and diesel USTs at the Site; however, all other referenced previous reports and correspondence state that two 6,000-gallon USTs were present. LUST Cases were not identified in association with the removal of the two 6,000-gallon USTs. Correspondence from PEPCO dated March 30, 1988 that was included in the previous URS Phase I ESA suggested that the USTs were to be removed by Chevron USA, Inc. so that they would not have to be upgraded when federal UST upgrade legislation took effect.

The Site was identified in LUST Case 93-094 in relation to the 20,000-gallon UST, which was removed in September 1993. According to the file at the DC DOH, confirmation soil samples that were collected during the removal of the UST were not significantly contaminated; however, groundwater samples were above regulatory limits for some constituents. As a CSA was already being prepared for the adjacent Generating Station at this time, the DC DOH required PEPCO to prepare a CSA Addendum report to include the former 20,000-gallon UST site. A copy of the CSA Addendum report was not available for review; however, the LUST Case 93-094 file indicated that one monitoring well (MW-13) was installed in this area. Petroleum concentrations in soil during the installation of the well were below DC DOH action limits, while BTEX and TPH constituents were above action limits in groundwater. The BTEX concentration was 1.77 mg/L and the TPH concentration was 3.0 mg/L. Additional information was not provided in the LUST Case file; however, the case was granted regulatory closure on May 9, 1994.

The Site was used for the storage of significant quantities of #6 fuel oil, gasoline, and diesel fuel in ASTs and USTs from the late 1960s until 1993. In addition, an underground pipeline was trenched between the 1.9-million gallon bulk fuel storage AST and the adjacent Generating Station, and no information regarding releases from the AST or pipeline is

known. AEC considers the historic use of the AST, pipeline, and USTs at the Site to be recognized environmental conditions.

6.6 Polychlorinated Biphenyls (PCBs)

The Site was investigated for the presence of equipment that could contain polychlorinated biphenyls (PCBs). PCBs are toxic coolants or lubricating oils that can be found in oil-filled equipment such as electrical transformers, capacitors, hydraulic elevators, hydraulic service bay lifts, and fluorescent light ballasts. No equipment that could potentially contain PCBs was identified at the Site.

Fluorescent light ballasts

AEC observed fluorescent light fixtures on poles installed throughout both Site lots. In 1979, the USEPA banned the manufacture and sale of PCBs. Based on the reported date of construction of the parking lot (after 1988), ballasts associated with the fluorescent light fixtures are unlikely to contain PCBs. However, any ballasts that are not labeled "non-PCB" should be disposed of in accordance with applicable local, state, and federal regulations.

AEC did not identify additional equipment that would be suspected to contain PCBs at the Site.

6.7 Indications of Solid Waste Disposal

AEC did not note indications of solid waste disposal at the time of the site visit. No waste receptacles were observed at Site, and Mr. Shahid Anis stated that waste is not generated at the Site.

6.8 Other Conditions of Potential Concern

AEC also examined the Site for evidence of the following potential environmental conditions:

Conditions	Not Observed	Observed	Potential Concern?
Chemical/Petroleum Odors	X		No
Pools of Liquid	X		No
Floor Drains/Sumps/Wells	X		No
Stains or Corrosion	X		No
Unidentified Containers	Х		No
Stained Soil or Pavement	X		No
Stressed Vegetation	X		No

AEC did not observe any of the above-mentioned conditions of potential concerns at the Site.

7.0 Findings and Conclusions

Advantage Environmental Consultants, LLC has performed a Phase I Environmental Site Assessment, in conformance with the scope and limitations of ASTM Practice E 1527-00, of the property known as Buzzard Point in Washington, DC. This assessment has revealed the following recognized environmental conditions in connection with the Site.

The historical use of the Site as a coal storage yard, a bulk fuel storage facility and a vehicle fueling station are recognized environmental conditions.

In addition, this assessment has revealed the following recognized environmental conditions in connection with off-site properties:

- The adjacent Generating Station and former PEPCO bulk fuel storage facility, in association with LUST Case #93-051, which has documented the presence of significant soil and groundwater contamination at these properties and groundwater flow towards the Site
- The adjacent Super Salvage, Inc., facility, which has operated a metal scrap yard at this location since the 1960s

8.0 References

ASTM, "Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process," ASTM Designation E 1527-00, Published July 2000;

Buzzard Point, prepared by Cassidy & Pinkard, dated March 2005;

Buzzard Point Station progress report, prepared by Potomac Electric Power Company (PEPCO), dated August 19, 2004;

Buzzard Point Station progress report, prepared by PEPCO, dated August 19, 2004;

Comprehensive Site Assessment, PEPCO, Buzzard Point Station (Executive Summary), prepared by TPH Technology, Inc., dated August 11, 1993;

Corrective Action Plan, Remedial Specifications and Implementation Details, Buzzard Point Generating Station, prepared by TPH Technology, Inc., dated March 10, 1995;

District of Columbia Chief Financial Officer's Real Property Tax Assessment database website www.taxpayerservicecenter.com;

Environmental Data Resources, Inc. (EDR), The EDR Aerial Photo Decade Package, Inquiry Number 1428986.4, dated May 25, 2005;

EDR, Radius Map with GeoCheck, Inquiry Number 1428986.2s, dated May 26, 2005;

EDR, Sanborn Fire Insurance Map Report, Inquiry Number 1428986.3s, dated May 26, 2005;

Globexplorer aerial photograph, www.globexplorer.com, dated 2004;

Haines Criss Cross City Directories, Washington, DC, dated 1970, 1975, 1980, 1990 and 2000;

Limited Phase II Environmental Investigation, prepared by URS Corporation, Inc., dated March 22, 2005;

Maryland Geologic Survey Geologic Map of Maryland dated 1968 obtained from the website http://www.mgs.md.gov/esic/geo/;

R.L. Polk & Company, Washington, DC City Directories, dated 1948, 1956 and 1965;

United States Department of Agriculture, Soil Survey of the District of Columbia, dated 1975;

United States Geological Survey (USGS) 7.5 Minute Series, Alexandria, VA Topographic Map, www.topozone.com, dated 1994;

United States Geological Survey, Ground Water Atlas of the United States, 1997;

APPENDICES

Appendix A - Site Vicinity Map (1)

Appendix B - Site Plan (1)

Appendix C - Site Photographs (5)

Appendix D - Historical Research Documentation/Maps (12)


Appendix E - Aerial Photographs (6)

Appendix F - Records of Communication (7)


Appendix G - Regulatory Records Documentation (56)

Appendix H - Prior Environmental Reports (89)

Appendix I – Qualifications of Environmental Professionals (6)



APPENDIX A SITE VICINITY MAP



Advantage

CONSULTANTS, LLC.

8610 Baltimore Washington Boulevard, Suite 217 Jessup, MD 20794

Phone: 301-776-0500 Fax 301-776-1123

Site Map Buzzard Point 2nd Street and S Street, SW Washington, DC 20024

AEC Project No.: 05-099


Report Date: 6/10/05

Drawn By:

LAK



APPENDIX B SITE PLAN



18

KEY

- 1 = On-site Prefabricated Building
- 2 = On-site Bulk Fuel Storage AST
- 3 = On-site Pits

- 4 = PEPCO Bulk Fuel Storage ASTs
- 5 = PEPCO Combustion Turbine Yard
- 6 = Buzzard Point Marina
- 7 = US Coast Guard Headquarters Building
- 8 = James Creek Marina

Advantage

CONSULTANTS, LLC.

8610 Baltimore Washington Boulevard, Suite 217 Jessup, MD 20794

Phone: 301-776-0500 Fax 301-776-1123

Site Plan
Buzzard Point
2nd Street and S Street, SW
Washington, DC 20024


AEC Project No.: 05-099

Report Date:


6/10/05

Drawn By:

LAK



APPENDIX C SITE PHOTOGRAPHS




Photograph 1: View of the northern Site lot and prefabricated building.




Photograph 2: Additional view of the northern Site lot, facing north.




Photograph 3: View of the bulk fuel storage AST at the southern Site lot.




Photograph 4: View of the parking areas at the southern Site lot, facing north.



Photograph 5: View of a guard stand and storage trailer at the northern Site lot.




Photograph 6: View towards the eastern adjacent combustion turbine yard and the decommissioned Buzzard Point Generating Station.



Photograph 7: View towards the southern adjacent US Coast Guard headquarters building.



Photograph 8: View towards the north adjacent Super Salvage, Inc. facility.



Photograph 9: View towards the west adjacent Fort McNair building.

Advantage Environmental Consultants, LLC

PHASE II ENVIRONMENTAL SITE ASSESSMENT

Buzzard Point 2nd Street and V Street, SW Washington, DC 20024

AEC Project No. 05-093 June 10, 2005

Prepared for.

The John Akridge Companies, Inc. 601 13th Street, NW Suite 300 North Washington, DC 20005

Prepared by:

Advantage Environmental Consultants, LLC 8610 Washington Boulevard, Suite 217 Jessup, Maryland 20794 TEL (301) 776-0500 • FAX (301) 776-1123

TABLE OF CONTENTS

EXEC	UTIVE S	SUMMARY	i
4.0	Wirns	DUCTION	4
1.0		DUCTION	
	1.1	Project Introduction and Purpose	
	1.2	Site Location and Description	
	1.3	Site Topography and Hydrology	
	1.4	Site History	2
	1.5	Summary of Potential Sources of Contamination	
		1.5.1 Onsite Concerns	
		1.5.2 Offsite Concerns	
	1.6	Previous Investigations	5
2.0	SUBSURFACE INVESTIGATION ACTIVITIES7		
	2.1	Introduction	
	2.2	Geoprobe Boring Advancement	8
	2.3	Soil Sampling Methodology	
	2.4	Groundwater Sampling Methodology	
	2.5	Sample Handling and Analysis	
3.0	INVESTIGATION ACTIVITY RESULTS10		
J.U	3.1	Soil Sample Analytical Results	
	3.1	Groundwater Sample Analytical Results	
	3.3	Local Geology and Hydrogeology	12
	3.3	Local Geology and Hydrogeology	. 1 2.
4.0	SUMN	IARY AND EVALUATION OF RESULTS	.13
	4.1	TPH in Soil Results Evaluation	
	4.2	VOCs in Soil Results Evaluation	.13
	4.3	Metals in Soil Results Evaluation	
	4.4	PCBs in Soil Results Evaluation	.14
	4.5	Soil Disposal Characteristics Results Evaluation	
	4.6	TPH DRO in Groundwater Results Evaluation	
	4.7	VOCs in Groundwater Results Evaluation	
	4.8	Lead in Groundwater Results Evaluation	
	4.9	Conclusions	
APPE	NDICES		
VDDE	NDIX A	FIGURES	
	NDIX A	PRIOR REPORTS AND SUPPORTING DOCUMENTATION	
	NDIX C		
	NDIX D	· · · · · · · · · · · · · · · · · · ·	
	NDIX E		
, ti I 1		WINDOWN TO THE OTHER	

FIGURES

FIGURE 1: SITE VICINITY MAP

FIGURE 2: SITE MAP WITH BORING LOCATIONS

FIGURE 3: SOIL QUALITY MAP - TPH GRO/DRO - SHALLOW (0-8')

FIGURE 4: SOIL QUALITY MAP - TPH GRO/DRO - DEEP (>8')

FIGURE 5: SOIL QUALITY MAP - VOCS

FIGURE 6: SOIL QUALITY MAP - LEAD

FIGURE 7: SOIL QUALITY MAP - PCBS

FIGURE 8: SOIL QUALITY MAP - TCLP METALS

FIGURE 9: GROUNDWATER QUALITY MAP - TPH DRO

FIGURE 10: GROUNDWATER QUALITY MAP - VOCS

FIGURE 11: GROUNDWATER QUALITY MAP - DISSOLVED LEAD

LABORATORY ANALYTICAL SUMMARY TABLES

TABLE 1: TPH GRO AND DRO

TABLE 2: VOLATILE ORGANIC COMPOUNDS

TABLE 3: LEAD

TABLE 4: PRIORITY POLLUTANT METALS

TABLE 5: TCLP/RCRA-8 METALS

TABLE 6: VOLATILE ORGANIC COMPOUNDS

EXECUTIVE SUMMARY

This Phase II Site Assessment Report has been developed for The John Akridge Companies, Inc. for the Buzzard Point property (the "Site") by Advantage Environmental Consultants, LLC (AEC). Based on information provided by The John Akridge Companies, Inc., the development plan includes construction of mixed use buildings with basement parking garage(s). As part of this development, it is planned to excavate the majority, if not all, of the subsurface materials to depths between 30-50 feet below ground surface (bgs). This work was done in support of the calculation of contaminated soil volume estimates and to identify other environmental issues related to the construction of subsurface structures during the proposed development of the Site.

The Site is bound by V Street, SW, 2nd Street, SW, S Street, SW and 1st Street, SW. The real estate designation is Square 607 Lot 13, Square 609 Lot 804, and Square 611 Lots 19 and 810. The total site area is 384,052 square feet.

Thirty soil borings were advanced on the Site in a general grid pattern. Some select areas were focused on during this investigation. These areas are known potential contaminant sources, and included: the former fleet fueling station (Underground Storage Tank (UST) system) in the northern area of the Site (at the corner of 1st Street, SW and T Street, SW); and, the retired 1.9-million gallon above-ground storage tank (AST) and associated underground petroleum transfer lines and oil-water separation or valve pits in the southern area of the Site. The borings were advanced using two Geoprobe rigs. The drilling activities occurred on May 21 and 22, 2005.

Field Methodology Summary

In general, soil samples were collected at the Site from three depth intervals: surface soil (0.5 to 2 foot bgs (below the pavement and sub-base)); shallow soil (2 to 3 feet bgs); and, deep soil (from zones exhibiting elevated photoionization detector (PID) readings or directly above the water table). Grab soil samples were collected from all of the borings from varying intervals, including shallow and deeper zones. Groundwater samples were also collected from multiple locations at the Site using temporary PVC wells.

The soil samples were analyzed for the following: Total Petroleum Hydrocarbon (TPH) Gasoline Range Organics (GRO) and Diesel Range Organics (DRO) via Environmental Protection

Agency (EPA) Method 8015M, Volatile Organic Compounds (VOCs) via EPA Method 8260, priority pollutant metals via EPA Methods 200.7 and 245.4, lead via EPA SM3113B, Polychlorinated Biphenyls (PCBs) via EPA Method 8082, Toxicity Characteristic Leachate Procedure (TCLP) metals via EPA Methods 1311/200.7 and 1311/245.1, and ignitability via EPA Method 40 CFR 261.21. The groundwater samples were analyzed for the following: TPH DRO via EPA Method 8015M, VOCs via EPA Method 8260, and dissolved lead via EPA SM3113B. The dissolved lead samples were field filtered prior to containerization using new, pre-cleaned 0.45 micron disposal filters

Soil Analytical Results Summary

The results of the TPH GRO and DRO in soils analyses identified TPH DRO concentrations in six of the 24 soil samples collected by AEC from the Site. None of the soil samples indicated TPH GRO concentrations. All six soil samples which were above the laboratory detection limit were collected from within the fill material. None of the deeper samples collected from the native material indicated TPH DRO concentrations above detection limits. The TPH DRO concentrations above the laboratory detection limit in the soil samples ranged from 11 milligrams per kilograms (mg/kg) in sample B-7 (6') to 77 mg/kg in sample B-10 (11-12'). These samples were also screened with a PID during drilling operations, but none of the samples responded significantly above background levels. Results of the soil sampling indicate that the TPH DRO contamination is widely distributed across the Site, and is therefore thought to be associated with either limited size petroleum surface spills, or coal dust and fragments mixed into the fill material. None of the TPH GRO or DRO sample analysis results exceed the DC Department of Health (DCDOH) Leaking Underground Storage Tank (LUST) standards.

The results of the VOC in soils analyses identified VOC concentrations in one of the nine soil samples collected by AEC from the Site. This sample, B-11 (2-3'), was collected from within the fill material at a relatively shallow depth. It should be noted that all of the soil samples which were non-detect for VOCs were also collected from within or directly below the fill material. The majority of the VOCs detected in B-11 are associated with petroleum hydrocarbons. URS Corporation (URS) conducted a Limited Phase II Environmental Investigation in January 2005 and advanced one of their 12 borings in the immediate vicinity of B-11. The soil sample collected from this boring (URS B-2 19 feet bgs) was non-detect for TPH GRO and DRO; however, a groundwater sample from this boring indicated a TPH GRO concentration of 110 micrograms per liter (ug/l). These samples were also screened with a PID

during drilling operations, but none of the samples responded significantly above background levels. Results for sampling of the VOCs indicate that the VOC contamination is not widely distributed across the Site and is therefore thought to be associated with a limited size petroleum surface spill. None of the VOC sample analysis results exceed the DCDOH Residential Soil - Generic Soil Quality Standards.

The results of the lead in soils analyses identified lead concentrations in 26 of the 28 soil samples collected by AEC from the Site. All of the 26 soil samples with lead concentrations above the laboratory detection limit were collected from within or directly above the fill material. The lead concentrations in soil samples B-13 (2-3'), and B-16 (2.5') were below the laboratory detection limit. The remainder of the lead concentrations in soil samples ranged from 1.8 mg/kg in sample B-21 (7') to 1,000 mg/kg in sample B-24 (7-8'). Results for sampling of the metals indicate that the lead contamination is widely distributed across the site. None of the lead sample analysis results exceed the DCDOH Residential Soil - Generic Soil Quality Standards, with the exception of B-10 (11-12') and B-24 (7-8').

The other priority pollutant metal of potential concern related to past Site use is arsenic. The results of the arsenic in soils analyses identified arsenic concentrations in eight of the ten soil samples collected by AEC from the Site. All of the eight soil samples with arsenic concentrations above the laboratory detection limit were collected from within the fill material. The arsenic concentrations range from below the laboratory detection limit in samples B-21 (7') and B-9 (4') to 8.2 mg/kg in sample B-24 (7-8'). All of the arsenic sample analysis results exceed the DCDOH Residential Soil - Generic Soil Quality Standards. The range of arsenic concentrations in the eastern United States presented in Elements in North American Soils (Dragun and Chiasson, 1991) is <1.0 mg/kg to 73 mg/kg with a mean of 7.4 mg/kg. Therefore, arsenic in Site soils appears to be naturally occurring. Furthermore, AEC understands that the proposed arsenic cleanup level at the Spring Valley World War I era chemical weapons testing range cleanup site in DC is 20 mg/kg. This means that any concentration lower than 20 mg/kg can be left in place in this residential neighborhood. This cleanup level was recommended by the Spring Valley Scientific Advisory Panel as proposed by the EPA. The Spring Valley cleanup level is significantly higher than any concentration detected at the Site.

The PCB concentrations in all eleven of the soil samples collected by AEC from the Site were below the laboratory detection limit. The PCB concentrations in all nine of the soil and all four

of the groundwater samples collected by URS from the Site were also below the laboratory detection limit.

Soil samples were collected from multiple locations and varying depths across the Site. The purpose of these samples was to characterize the soil material that will be disturbed and may require special disposal in connection with the proposed construction of the subsurface structures at the Site. The soil samples were analyzed for common waste characterization analytes including: TCLP metals; ignitability; TPH GRO and DRO; VOCs; and PCBs. In conclusion, the results of all of the analysis discussed above did not identify any compounds or characteristics which would preclude the disposal of any of the designated soil at a commercial petroleum contaminated soil-disposal facility.

As a general note, during construction excavation operations, hydrocarbon odor in soil is as important a driver as the laboratory derived hydrocarbon concentration for determining if the soil is clean or hydrocarbon contaminated. The assumption is that "contamination" is defined as soils with TPH or other VOC concentrations greater than the laboratory detection limit, or for PID-screened soils, the background concentration (usually less then 5 parts per million (ppm). Because all of the soil (both contaminated and uncontaminated) is to be removed during construction activities, and any level of contamination makes soil unsuitable for clean fill or construction debris, the commonly used 100 mg/kg TPH DCDOH LUST standard is not appropriate for this project. The 100 mg/kg TPH DCDOH LUST standard is typically used as a guideline for determining which contaminated soil can be left in place.

Groundwater Analytical Results Summary

The TPH DRO concentrations in all five of the groundwater samples collected by AEC from the Site were below the laboratory detection limit. The TPH DRO concentrations in six of the seven groundwater samples collected by URS from the Site were also below the laboratory detection limit. The groundwater sample from URS boring B-11 indicated a TPH DRO concentration of 550 ug/l. This boring is located at the southern end of the Site, down gradient of the AST.

The results of the VOC in groundwater analyses identified VOC concentrations in one of the ten groundwater samples collected by AEC from the Site. This groundwater sample, B-9, was collected from the vicinity of the former vehicle fueling station in the southeastern portion of the northern Site lot. The majority of the VOCs detected in B-9 are associated with chlorinated

hydrocarbons. Results for sampling of the VOCs indicate that the VOC contamination is not widely distributed across the Site. None of the VOC sample analysis results exceed the DCDOH Residential Groundwater - Risk Based Screening Levels, with the exception of vinyl chloride and trichloroethene. It should be noted that groundwater is not used as a potable water source in the Site vicinity.

The results of the analysis did not identify the presence of dissolved lead above the laboratory detection limits in all 12 of the groundwater samples collected by AEC from the Site.

Site Condition Summary

Low levels of TPH and VOCs in soil and groundwater have been detected throughout the Site. In general, the TPH and VOCs in soil are found primarily in the upper 12 feet in the artificial fill material. Generally low levels of lead in soil (with two exceptions) and low levels of arsenic in soil have also been detected in the artificial fill material. These contaminants are thought to be associated with either limited size petroleum surface spills, or coal dust and fragments mixed into the fill material. In the case of the chlorinated hydrocarbon groundwater contamination near the former vehicle fueling station (southeastern portion of the northern Site lot), the low levels and limited extent of impact makes this issue less significant. In addition, the possible lead in groundwater and PCB in soil contamination issues have been ruled out as issues of concern.

Based on the historic presence of significant quantities of Liquid Phase Hydrocarbon (LPH) in soil and groundwater at the adjacent Buzzard Point Generating Station, the ongoing groundwater remediation project, and the groundwater flow direction, this property could be considered to be a long term concern to the Site. This concern increases based on the selection of the foundation for the proposed development. If the proposed subsurface structures are constructed to require continuous dewatering then the risk of hydrocarbon contaminated groundwater from offsite entering the dewatering system is elevated. If the foundation is constructed so that dewatering is not necessary, this risk is minimized.

1.0 INTRODUCTION

1.1 Project Introduction and Purpose

This Phase II Site Assessment Report has been developed for The John Akridge Companies, Inc. for the Buzzard Point property (the "Site") by Advantage Environmental Consultants, LLC (AEC). Based on information provided by The John Akridge Companies, Inc., the development plan includes construction of mixed use buildings with basement parking garage(s). As part of this development, it is planned to excavate the majority, if not all, of the subsurface materials to depths between 30-50 feet below ground surface (bgs). This work was done in support of the calculation of contaminated soil volume estimates and to identify other environmental issues related to the construction of subsurface structures during the proposed development of the Site.

1.2 Site Location and Description

The Site is situated in a medium-density, mixed commercial, industrial, and government-use area of southwest Washington DC that is referred to as Buzzard Point. The area consists of several properties owned by the Potomac Electric Power Company (PEPCO), including the Site, the decommissioned Buzzard Point Generating Station and active combustion turbine yard (CT Yard), and a former bulk fuel storage facility. Additional adjacent properties include a scrap metal yard, a US military fort, a US military (Coast Guard) headquarters building, and two marinas. Additional industrial and commercial business are located further north and east of the Site and the Anacostia River is present approximately 330 feet southeast and south of the Site. A Site Vicinity Map showing the approximate site location is included as Figure 1 in Appendix A.

The Site consists of four individual lots in three adjacent squares (Square 607, Lot 13; Square 609, Lot 804; and Square 611, Lots 19 and 810) which comprise approximately 384,051 square feet. The Site is bound by S Street, SW to the north, 1st Street, SW to the east, V Street, SW to the south, and 2nd Street, SW to the west. T Street, SW transects the Site, and divides it into a small northern lot and a larger southern lot.

Currently, the Site is used as two fenced parking lots; however, the Site has been owned by PEPCO since 1929, and was formerly used as a coal storage yard, a vehicle fueling area with

Underground Storage Tanks (USTs), a bulk #6 fuel oil above-ground storage tank (AST), and a laydown area (equipment storage) for the eastern adjacent decommissioned PEPCO generating station.

Improvements at the Site include a prefabricated metal building and storage trailers at the northern Site boundary, an unused bulk #6 fuel oil AST and an associated fire fighting foam house at the southern portion of the Site, and guard stands at the entrances to the parking lots. Other improvements include parking medians, light poles and landscaping. The parking lots are leased from PEPCO by the US government. This Phase II Site Assessment was performed for financing purposes, to document any known contaminants, and discover the existence of any unknown contaminants at the Site. A site plan is included as Figure 2 in Appendix A.

1.3 Site Topography and Hydrology

AEC reviewed a copy of the United States Geological Survey (USGS) 7.5 Minute Series, Alexandria, Virginia Topographic Quadrangle map dated 1994. According to the map, the elevation of the Site is approximately 14 feet above mean sea level (msl). The area on and around the Site is relatively level, with the natural topographic gradient across the Site being south-southwest. The Site area was illustrated with the prefabricated building at the northern Site boundary, an apparent access road from T Street, SW onto the northern Site lot, and the bulk fuel storage AST at the southern portion of the southern Site lot. No surface bodies of water were illustrated on the Site.

1.4 Site History

The review of the historical resources (as discussed in the Phase I Environmental Site Assessment (ESA) commissioned for the property) indicated that the southern Site lot was used for a coal storage yard with an associated railroad siding from the late 1920s until the PEPCO Generating Station began using fuel oil to power the plant in the mid 1970s. From this point until the Generating Station was decommissioned in 1981, the southern Site lot was used for bulk fuel storage. The northern Site lot appeared to have been used for vehicle fueling and storage from the late 1960s until the USTs were removed in 1988 and 1993.

1.5 Summary of Potential Sources of Contamination

1.5.1 Onsite Concerns

The northern Site lot was previously used by PEPCO as a vehicle fueling station and storage

lot. One 20,000-gallon gasoline UST, one 6,000-gallon gasoline UST, and one 6,000-gallon diesel fuel UST were previously located at the southeastern portion of the northern Site lot, identified as 180 S Street, SW and as the Buzzard Point gas station. Both of the 6,000-gallon USTs were removed from the Site in November, 1988. Regulatory review revealed two separate UST listings that reference two 6,000-gallon gasoline USTs and two 6,000-gallon diesel fuel USTs at the Site; however, it appears that these listings are incorrect. Leaking Underground Storage Tank (LUST) Cases were not identified in association with the removal of the two 6,000-gallon USTs.

The Site was identified in LUST Case 93-094 in relation to the 20,000-gallon UST, which was removed in September 1993. According to the regulatory file at the DC Department of Health (DCDOH), confirmation soil samples that were collected during the removal of the UST were not significantly contaminated; however, groundwater samples were above regulatory limits for some constituents. As a Comprehensive Site Assessment (CSA) was already being prepared for the adjacent PEPCO Generating Station at this time, the DCDOH required PEPCO to prepare a CSA Addendum report to include the former 20,000-gallon UST site. A copy of the CSA Addendum report was not available for review; however, the LUST Case 93-094 file indicated that one monitoring well (MW-13) was installed in this area. Petroleum concentrations in soil during the installation of the monitoring well were below DCDOH action limits, while Benzene, Toluene, Ethyl benzene and Xylenes (BTEX) and Total Petroleum Hydrocarbon (TPH) constituents were above action limits in the initial groundwater sample. The BTEX concentration was 1.77 mg/l and the TPH concentration was 3.0 milligrams per liter (mg/l). Additional information was not provided in the LUST Case file; however, the LUST Case was granted regulatory closure on May 9, 1994.

A 1.9 million gallon capacity bulk fuel storage AST is located at the southern portion of the Site. The AST is surrounded by an approximate six foot high concrete containment dike. The exact installation date of this AST is unknown; however, historical research has revealed that it was installed when the adjacent PEPCO Generating Station was converted from being fueled by coal to using #6 fuel oil in the late 1960s. Mr. Shahid Anis of PEPCO stated in a previous report that he did not know whether releases from the bulk fuel storage AST had occurred. Reportedly, an underground pipeline connected the AST to the Generating Station. Mr. Anis did not provide any information regarding the pipeline or any related releases. Both the AST and the underground pipeline were taken out of service in 1981 when the Generating Station

was decommissioned. Reportedly, the AST has remained empty since that time and the pipeline was filled in place.

The review of the above-referenced historical sources indicated that the southern Site lot was used as a coal storage yard from the late 1920s until the PEPCO Generating Station began using fuel oil to power the plant in 1968. A railroad siding associated with this coal storage yard was aligned along the northern and eastern side of the southern Site lot. Contaminants of concern typically associated with a railroad siding are petroleum compounds (TPH DRO and GRO), Volatile Organic Compounds (VOCs), Polychlorinated Biphenyls (PCBs) and the metals arsenic and lead.

1.5.2 Offsite Concerns

The Buzzard Point Generating Station, located approximately 35 feet east across 1st Street from the Site, was identified in four separate LUST cases, one of which remains open (LUST Case No. 93-051). A file review at the DC DOH revealed that In the early 1970s, a release was reported from a four-inch diameter underground pipeline that connected the CT Yard of the Generating Station to the two, 0.411-million gallon #2 fuel oil ASTs located north across S Street from the CT Yard. The release was repaired, and one 15" diameter monitoring well was subsequently installed in the vicinity of the pipeline leak. Significant petroleum (gasoline and diesel) contamination was discovered in soil and groundwater at the CT Yard portion of the Generating Station property in 1993.

Initial assessments of the contamination revealed TPH concentrations ranging from 881 milligrams per kilogram (mg/kg) to 30,700 mg/kg. A total of 23 monitoring wells (MWs) were installed at this property in the vicinity of the CT Yard and the north adjacent bulk fuel storage ASTs, as well as at the southeast corner of the northern Site lot (due to its former use as a vehicle fueling area identified as 180 S Street, SW), between May 1993 and January 1995. The majority of the MWs installed at the CT Yard and north adjacent bulk fuel storage area have historically contained Liquid Phase Hydrocarbon (LPH). Groundwater flow direction has been documented at this property to be west and southwest, towards the Site.

PEPCO installed a soil vapor extraction (SVE) system in the CT Yard and at the southern portion of the bulk fuel storage area in January 1996, and operated the system through November 1999. The SVE system reportedly removed approximately 6,925 gallons of

petroleum. From May 2001 to April 2002, a portable high vacuum pump and treat system was used to recover LPH from two of the most contaminated wells (MW-5 and MW-11). The pump and treat system removed an estimated 1,350 gallons of LPH from these wells.

The wells and groundwater vacuum monitoring points (GVPs) appear to have been monitored monthly from January 2003 through July 2004, with semi-annual sampling events. Groundwater sampling data for this property that was dated March 8, 2004 indicated that groundwater contaminants in the three most down gradient wells were below Maximum Contaminant Levels and/or DC Water Quality Standards for BTEX and TPH Gasoline-Range Organics (GRO) and Diesel Range Organics (DRO), while levels of these constituents remained over the applicable regulatory standards in remaining MWs and GVPs. Currently, only passive remediation with absorbent booms and monitoring is ongoing at the Generating Station property.

Based on the historic presence of significant quantities of LPH in soil and groundwater at the adjacent Buzzard Point Generating Station, the ongoing groundwater remediation project, and the groundwater flow direction, this property could be considered to be a long term concern to the Site. This concern increases based on the selection of the foundation for the proposed development. If the proposed subsurface structures are constructed to require continuous dewatering then the risk of hydrocarbon contaminated groundwater from offsite entering the dewatering system is elevated. If the foundation is constructed so that dewatering is not necessary, this risk is minimized.

1.6 Previous Investigations

A number of items including tables and figures from the reports discussed below have been excerpted and placed in Appendix B to aid in the discussion.

Geomatrix conducted an assessment of the Buzzard Point Properties. The date of this assessment is unknown (a review of the document failed to provide a date at which the field work was performed or report was prepared). Due to the sampling methodology (composite) and the lack of an attached laboratory analytical report to the document received from PEPCO, this material was deemed only partially reliable.

URS Corporation (URS) conducted a Limited Phase II Environmental Investigation in January 2005 that included 12 soil borings completed to depths ranging from 10 feet to 32 feet bgs. This report did not include boring logs. In addition to the boring exploration, water from the two concrete pits located adjacent to the AST was also sampled and analyzed. The URS investigation did not include any sampling of surficial soils at the site; all sampling was at a depth of at least 10 feet below ground surface. This study did not include an investigation of Square 607.

Groundwater, pit water, and soils were sampled and analyzed for various chemical parameters including TPH GRO and DRO, VOCs, Semi-Volatile Organic Compounds (SVOCs), priority pollutant metals, and PCBs.

The result of the analyses indicated that some soils at the Site are impacted with petroleum hydrocarbons and groundwater is impacted with petroleum hydrocarbons and lead. The lead impact to groundwater was identified at both locations where analyses were performed. The lead concentrations in groundwater were elevated and were not likely to be the result of naturally occurring conditions. These lead concentrations ranged from 1,900 to 8,800 micrograms per liter (ug/l). URS concluded that there is evidence that soil and groundwater has been affected by releases of petroleum hydrocarbons, and the presence of combustion products and metals. The term "combustion product" is not defined but it may refer to the potential atmospheric fallout of emissions particulate from the adjacent generating station or perhaps the presence of coal in the fill material.

2.0 SUBSURFACE INVESTIGATION ACTIVITIES

2.1 Introduction

Thirty soil borings were advanced on the Site in a general grid pattern. Some select areas were focused on during this investigation. These areas are known potential contaminant sources, and included: the former fleet fueling station (UST system) in the northern area of the Site (at the corner of 1st Street, SW and T Street, SW); and, the retired 1.9-million gallon above-ground storage tank (AST) and associated underground petroleum transfer lines and oil-water separation or valve pits in the southern area of the Site. The borings were advanced using two Geoprobe rigs. The drilling activities occurred on May 21 and 22, 2005.

In general, soil samples were collected at the Site from three depth intervals: surface soil (0.5 to 2 foot bgs (below the pavement and sub-base)); shallow soil (2 to 3 feet bgs); and, deep soil (from zones exhibiting elevated photoionization detector (PID) readings or directly above the water table). Grab soil samples were collected from all of the borings from varying intervals, including shallow and deeper zones. Groundwater samples were also collected from multiple locations at the Site using temporary PVC wells. The TPH and VOC soil samples were generally collected from zones exhibiting elevated PID responses or other signs of contamination. The PCBs, priority pollutant metals, and lead soil samples were generally collected from the shallow soil intervals. The TCLP metals soil samples were generally collected from the interior of the Site near the existing lead in soil exceedances. The lead and VOCs in water samples were collected from locations distributed across the Site.

The soil samples were analyzed for the following: TPH GRO and DRO via EPA Method 8015M, VOCs via EPA Method 8260, priority pollutant metals via EPA Methods 200.7 and 245.4, Lead via EPA Standard Methods (SM) 3113B, PCBs via EPA Method 8082, Toxicity Characteristic Leachate Procedure (TCLP) metals via EPA Methods 1311/200.7 and 1311/245.1, and ignitability via EPA Method 40 Code of Federal Regulations (CFR) 261.21. The groundwater samples were analyzed for the following: TPH DRO via EPA Method 8015M, VOCs via EPA Method 8260, and dissolved lead via EPA SM3113B. The dissolved lead samples were field filtered prior to containerization using new, pre-cleaned 0.45 micron disposal filters.

2.2 Geoprobe Boring Advancement

Sample cores were collected continuously using 1.5-inch, inside-diameter, stainless steel macro-core samplers with new acetate liners. Cores were collected in four feet intervals by using a truck-mounted hydraulic press to drive the sampler through the stratum. All sampling equipment was decontaminated in the field using non-phosphate liquinox and distilled water prior to use. AEC contracted Bassett Environmental Associates, Inc. of Harrisburg, Pennsylvania and Hugo Drilling, Inc. of Knoxville, Maryland to perform the drilling activities.

Soil sample collection for laboratory analysis is discussed in Section 2.3. Groundwater sample collection for laboratory analysis is discussed in Section 2.4. Following completion of soil and groundwater sample collection, the temporary PVC wells were removed (if used at the location), the bore holes filled with the geoprobe cuttings, then topped with bentonite and capped with an asphalt patch (or top soil as appropriate). Boring locations are illustrated on Figure 2 in Appendix A, and copies of the boring logs for this investigation are included in Appendix C.

2.3 Soil Sampling Methodology

Upon retrieval, each soil sample was screened in the field using a handheld PID to screen for VOCs. For the most part no significant PID readings were detected in any of the borings. Following the screening, grab soil samples were collected from all of the borings from varying depth intervals. Some borings had multiple intervals sampled. All samples were placed in appropriate pre-cleaned, laboratory-supplied, four-ounce glassware. Once collected, the samples were placed on ice in a cooler to await shipment to the laboratory.

2.4 Groundwater Sampling Methodology

Groundwater samples from the temporary PVC wells were collected using a pre-cleaned disposable weighted bailer or a peristaltic pump with new PVC tubing for each location. Specifically, the sample from each well was placed in 40 milliliter glass jars with teflon-lined septa and preserved with hydrochloric acid, amber glass liter bottles preserved with hydrochloric acid, and 500 milliliter polyethylene bottles preserved with nitric acid. The samples designated to be analyzed for dissolved lead were field filtered using new pre-cleaned disposable pressure filters sized for metals analysis (0.45 microns). Once collected, the samples were placed on ice in a cooler to await shipment to the laboratory.

2.5 Sample Handling and Analysis

Samples were packaged for shipping using strict chain-of-custody procedures. The coolers were packed with individually wrapped sample containers and ice and sealed with laboratory provided custody seals and shipping tape. Samples were shipped to Anabell Environmental, Inc. in Gaithersburg, Maryland. The soil samples were analyzed for the following: TPH GRO and DRO via EPA Method 8015M, VOCs via EPA Method 8260, priority pollutant metals via EPA Methods 200.7 and 245.4, Lead via EPA SM3113B, PCBs via EPA Method 8082, TCLP Metals via EPA Methods 1311/200.7 and 1311/245.1, and ignitability via EPA Method 40 CFR 261.21. The groundwater samples were analyzed for the following: TPH DRO via EPA Method 8015M, VOCs via EPA Method 8260, and dissolved lead via EPA SM3113B.

3.0 INVESTIGATION ACTIVITY RESULTS

3.1 Soil Sample Analytical Results

Figure 3 in Appendix A and Table 1 in Appendix D summarize the results of the shallow soil samples analyzed for TPH GRO and DRO. Figure 4 in Appendix A and Table 1 in Appendix D summarize the results of the deep soil samples analyzed for TPH GRO and DRO. Figure 5 in Appendix A and Table 2 in Appendix D summarize the results of the soil samples analyzed for VOCs. Figure 6 in Appendix A and Tables 3 (lead only) and 4 (Priority Pollutant Metals) in Appendix D summarize the results of the soil samples analyzed for lead. Figure 7 in Appendix A summarize the results of the soil samples analyzed for PCBs. Figure 8 in Appendix A and Table 5 in Appendix D summarize the results of the soil samples analyzed for TCLP metals. Only lead concentrations (as opposed to all of the priority pollutant metals) are included in Figure 6 in Appendix A. Only those compounds with concentrations above the laboratory detection limits are included in the tables in Appendix D. Copies of the completed laboratory analytical reports and chain-of-custody forms for the samples are provided in Appendix E.

All TPH GRO concentrations in both the shallow and deep soil samples were below the laboratory detection limit. The TPH DRO concentrations in shallow soil samples B-1 (2'), B-3 (4'), B-5 (8'), B-6 (5'), B-8 (5'), B-9 (4'), B-16 (3.5-4'), B-20 (4'), B-22 (6'), B-23 (1'), B-24 (7-8'), B-26 (7-8'), and B-27 (6') were below the laboratory detection limit. The remainder of the TPH DRO concentrations in shallow soil samples ranged from 11 mg/kg in sample B-7 (6') to 50 mg/kg in sample B-21 (7'). The TPH DRO concentrations in deep soil samples B-11 (19'), B-12 (10'), B-19 (11-12'), B-25 (11'), and B-28 (9-10') were below the laboratory detection limit. The remainder of the TPH DRO concentrations in deep soil samples ranged from 20 mg/kg in sample B-14 (9') to 77 mg/kg in sample B-10 (11-12').

The results of the VOC analysis of the soil samples indicated all compounds below detection limits with the exception of various compounds detected in the sample from B-11 (2-3'). These compounds included Ethylbenzene (12 micrograms per kilograms (ug/kg)), total xylenes (100 ug/kg), Isopropylbenzene (37 ug/kg), 1,1,2,2-tetrachloroethane (14 ug/kg), N-propylbenzene (190 ug/kg), 1,3,5-Trimethylbenzene (230 ug/kg), Tert-butylbenzene (120 ug/kg), 1,2,4-Trimethylbenzene (120 ug/kg), Sec-butylbenzene (110 ug/kg), 4-Isopropyltoluene (81 ug/kg), and naphthalene (880 ug/kg). Acetone was detected in a limited number of soil samples.

Acetone is a common laboratory cross contaminant and is not thought to be a compound of concern at the site. Acetone concentrations are not shown on either the tables or figures.

The lead concentrations in soil samples B-13 (2-3'), and B-16 (2.5') were below the laboratory detection limit. The remainder of the lead concentrations in soil samples ranged from 1.8 mg/kg in sample B-21 (7') to 1,000 mg/kg in sample B-24 (7-8'). The other priority pollutant metal of potential concern related to past site use is arsenic. The arsenic concentrations range from below the laboratory detection limit in samples B-21 (7') and B-9 (4') to 8.2 mg/kg in sample B-24 (7-8').

The PCB concentrations in all eleven of the soil samples collected from the site were below the laboratory detection limit.

All of the metals concentrations in the soil samples were below the TCLP metals regulatory limits (pass as opposed to fail). The sample analyzed for ignitability (B-14 (5')) was also below the regulatory criteria (i.e., did not flash below designated temperature). This sample was representative of the coal dust material.

3.2 Groundwater Sample Analytical Results

Figure 9 in Appendix A summarizes the results of the groundwater samples analyzed for TPH DRO. Figure 10 in Appendix A and Table 6 in Appendix D summarize the results of the groundwater samples analyzed for VOCs. Figure 11 in Appendix A summarizes the results of the groundwater samples analyzed for dissolved lead. Only those compounds with concentrations above the laboratory detection limits are included in the tables in Appendix D. Copies of the completed laboratory analytical reports and chain-of-custody forms for the samples are provided in Appendix E.

The results of the analysis did not identify the presence of any TPH DRO above the laboratory detection limits in the groundwater samples collected from the site.

The results of the VOC analysis of the groundwater samples indicated all compounds below detection limits with the exception of various compounds detected in the sample from B-9. These compounds included vinyl chloride (160 ug/l), trans-1,2-dichloroethene (10 ug/l), cis-1,2-dichloroethene (1,300 ug/l), benzene (11 ug/l), trichloroethene (4,100 ug/l), and

tetrachloroethene (5.6 ug/l). Acetone was detected in a limited number of groundwater samples (B-9, B-17 and B-20). Acetone is a common laboratory cross contaminant and is not a compound of concern at the site. Acetone levels are not shown on either the tables or figures.

The results of the analysis did not identify the presence of any dissolved lead above the laboratory detection limits in the groundwater samples collected from the Site.

3.3 Local Geology and Hydrogeology

The Site is within the Atlantic Coastal Plain Physiographic Province. The Coastal Plain consists of a series of Cretaceous, Tertiary and recent-aged fluvial and marine deposits overlying crystalline basement rocks. The depth to the basement rocks is estimated to be about 150 feet in the vicinity of the site. The soils in the general vicinity of the Site are primarily interbedded clays, silts, sands and gravels belonging to the Pamlico Formation.

The soils beneath the Site consist of fill materials and interbedded clay, silt, sand and gravel deposits that are consistent with the Pamlico Formation. The fill materials range in depth from two feet to over 12 feet and consist of a mixture of sand, clay, silt, coal dust and fragments and construction debris. The average thickness of the fill is between seven and eight feet and increases to as much as 12 feet in the southern end of the Site. One feature of the fill is the existence of coal dust (silt to sand size particles) in a number of areas of the Site. This coal dust is found in borings B-7 (1.5-3.5 feet bgs), B-8 (1.5-2 feet bgs), B-11 (2.5-3.5 feet bgs), B-13 (1.5-3.5 feet bgs), B-14 (3.5-5.5 feet bgs), B-16 (1.5-3 feet bgs), B-19 (1.5-3 feet bgs), B-20 (1-2 feet bgs), and B-26 (6-7 feet bgs). In general, this material is fairly shallow and exists mainly in the western portion of the site. The underlying deposits consist of interbedded clays, sandy silts, and silty fine sands with occasional gravel.

The water table aquifer lies within the fill and underlying Pamlico deposits. The depth to groundwater within the water table aquifer ranges from about 6 to 12 feet across the site. A 24 hour water level was taken from one of the temporary well points from the central portion of the site and indicated a depth to water of approximately 9.7 feet bgs. According to information reviewed as part of this analysis, groundwater flow in the water table aquifer is from northeast to southwest.

4.0 SUMMARY AND EVALUATION OF RESULTS

4.1 TPH in Soil Results Evaluation

The results of the TPH GRO and DRO in soils analyses identified TPH DRO concentrations in six of the 24 soil samples collected by AEC from the Site. None of the soil samples indicated TPH GRO concentrations. All six soil samples which were above the laboratory detection limit were collected from within the fill material. None of the deeper samples collected from the native material indicated TPH DRO concentrations above detection limits. The TPH DRO concentrations above the laboratory detection limit in the soil samples ranged from 11 mg/kg in sample B-7 (6') to 77 mg/kg in sample B-10 (11-12'). These samples were also screened with a PID during drilling operations, but none of the samples responded significantly above background levels. Results of the soil sampling indicate that the TPH DRO contamination is widely distributed across the Site, and is therefore thought to be associated with either limited size petroleum surface spills, or coal dust and fragments mixed into the fill material. None of the TPH GRO or DRO sample analysis results exceed the DCDOH LUST standards.

4.2 VOCs in Soil Results Evaluation

The results of the VOC in soils analyses identified VOC concentrations in one of the nine soil samples collected by AEC from the Site. This sample, B-11 (2-3'), was collected from within the fill material at a relatively shallow depth. It should be noted that all of the soil samples which were non-detect for VOCs were also collected from within or directly below the fill material. The majority of the VOCs detected in B-11 are associated with petroleum hydrocarbons. URS advanced one of their 12 borings in the immediate vicinity of B-11. The soil sample collected from this boring (URS B-2 19 feet bgs) was non-detect for TPH GRO and DRO; however, a groundwater sample from this boring indicated a TPH GRO concentration of 110 ug/l. These samples were also screened with a PID during drilling operations, but none of the samples responded significantly above background levels. Results for sampling of the VOCs indicate that the VOC contamination is not widely distributed across the Site and is therefore thought to be associated with a limited size petroleum surface spill. None of the VOC sample analysis results exceed the DCDOH Residential Soil - Generic Soil Quality Standards.

4.3 Metals in Soil Results Evaluation

The results of the lead in soils analyses identified lead concentrations in 26 of the 28 soil samples collected by AEC from the Site. All of the 26 soil samples with lead concentrations

above the laboratory detection limit were collected from within or directly above the fill material. The lead concentrations in soil samples B-13 (2-3'), and B-16 (2.5') were below the laboratory detection limit. The remainder of the lead concentrations in soil samples ranged from 1.8 mg/kg in sample B-21 (7') to 1,000 mg/kg in sample B-24 (7-8'). The lead contamination is widely distributed across the Site. None of the lead sample analysis results exceed the DCDOH Residential Soil - Generic Soil Quality Standards, with the exception of B-10 (11-12') and B-24 (7-8').

The other priority pollutant metal of potential concern related to past Site use is arsenic. The results of the arsenic in soils analyses identified arsenic concentrations in eight of the ten soil samples collected by AEC from the Site. All of the eight soil samples with arsenic concentrations above the laboratory detection limit were collected from within the fill material. The arsenic concentrations range from below the laboratory detection limit in samples B-21 (7') and B-9 (4') to 8.2 mg/kg in sample B-24 (7-8'). All of the arsenic sample analysis results exceed the DCDOH Residential Soil - Generic Soil Quality Standards. The range of arsenic concentrations in the eastern United States presented in Elements in North American Soils (Dragun and Chiasson, 1991) is <1.0 mg/kg to 73 mg/kg with a mean of 7.4 mg/kg. Therefore, arsenic in Site soils appears to be naturally occurring. Furthermore, AEC understands that the proposed arsenic cleanup level at the Spring Valley World War I era chemical weapons testing range cleanup site in DC is 20 mg/kg. This means that any concentration lower than 20 mg/kg can be left in place in this residential neighborhood. This cleanup level was recommended by the Spring Valley Scientific Advisory Panel as proposed by the EPA. The Spring Valley cleanup level is significantly higher than any concentration detected at the Site.

4.4 PCBs in Soil Results Evaluation

The PCB concentrations in all eleven of the soil samples collected by AEC from the Site were below the laboratory detection limit. The PCB concentrations in all nine of the soil and all four of the groundwater samples collected by URS from the site were also below the laboratory detection limit.

4.5 Soil Disposal Characteristics Results Evaluation

Soil samples were collected from multiple locations and varying depths across the Site. The purpose of these samples was to characterize the soil material that will be disturbed and may require special disposal in connection with the proposed construction of the subsurface

structures at the Site. The soil samples were analyzed for common waste characterization analytes including: TCLP metals; ignitability; TPH GRO and DRO; VOCs; and PCBs. In conclusion, the results of all of the analysis discussed above did not identify any compounds or characteristics which would preclude the disposal of any of the designated soil at a commercial petroleum contaminated soil-disposal facility.

As a general note, during construction excavation operations, hydrocarbon odor in soil is as important a driver as the laboratory derived hydrocarbon concentration for determining if the soil is clean or hydrocarbon contaminated. The assumption is that "contamination" is defined as soils with TPH or other VOC concentrations greater than the laboratory detection limit, or for PID-screened soils, the background concentration (usually less then 5 parts per million (ppm). Because all of the soil (both contaminated and uncontaminated) is to be removed during construction activities, and any level of contamination makes soil unsuitable for clean fill or construction debris, the commonly used 100 mg/kg TPH DCDOH LUST standard is not appropriate for this project. The 100 mg/kg TPH DCDOH LUST standard is typically used as a guideline for determining which contaminated soil can be left in place.

4.6 TPH DRO in Groundwater Results Evaluation

The TPH DRO concentrations in all five of the groundwater samples collected by AEC from the Site were below the laboratory detection limit. The TPH DRO concentrations in six of the seven groundwater samples collected by URS from the Site were also below the laboratory detection limit. The groundwater sample from URS boring B-11 indicated a TPH DRO concentration of 550 ug/l. This boring is located at the southern end of the Site, down gradient of the AST.

4.7 VOCs in Groundwater Results Evaluation

The results of the VOC in groundwater analyses identified VOC concentrations in one of the ten groundwater samples collected by AEC from the Site. This groundwater sample, B-9, was collected from the vicinity of the former vehicle fueling station in the southeastern portion of the northern Site lot. The majority of the VOCs detected in B-9 are associated with chlorinated hydrocarbons. Results for sampling of the VOCs indicate that the VOC contamination is not widely distributed across the Site. None of the VOC sample analysis results exceed the DCDOH Residential Groundwater - Risk Based Screening Levels, with the exception of vinyl chloride and trichloroethene. It should be noted that groundwater is not used as a potable water source in the Site vicinity.


4.8 Lead in Groundwater Results Evaluation

The results of the analysis did not identify the presence of dissolved lead above the laboratory detection limits in the groundwater samples collected by AEC from the Site. Based on the results of AEC's field effort, it is suspected that URS had their priority pollutant metals (of which lead is a component) in water samples analyzed for total metals as opposed to dissolved metals. There is no mention in the URS report concerning field filtration of these samples so this assumption is probably correct. Based on the condition of the water during AEC's field effort, (i.e., very high turbidity in the geoprobe collected water samples), the metals in water results are probably not indicative of subsurface conditions and may have resulted in a "false positive" outcome for at least the significantly elevated lead in groundwater issue. This assumption is supported by AEC's dissolved lead in groundwater data which was non-detect in all of the 12 samples which were analyzed.

4.9 Conclusions


Low levels of TPH and VOCs in soil and groundwater have been detected throughout the Site. In general, the TPH and VOCs in soil are found primarily in the upper 12 feet in the artificial fill material. Generally low levels of lead in soil (with two exceptions) and low levels of arsenic in soil have also been detected in the artificial fill material. These contaminants are thought to be associated with either limited size petroleum surface spills, or coal dust and fragments mixed into the fill material. In the case of the chlorinated hydrocarbon groundwater contamination near the former vehicle fueling station (southeastern portion of the northern Site lot), the low levels and limited extent of impact makes this issue less significant. In addition, the possible lead in groundwater and PCB in soil contamination issues have been ruled out as issues of concern.


Based on the historic presence of significant quantities of LPH in soil and groundwater at the adjacent Buzzard Point Generating Station, the ongoing groundwater remediation project, and the groundwater flow direction, this property could be considered to be a long term concern to the Site. This concern increases based on the selection of the foundation for the proposed development. If the proposed subsurface structures are constructed to require continuous dewatering then the risk of hydrocarbon contaminated groundwater from offsite entering the dewatering system is elevated. If the foundation is constructed so that dewatering is not necessary, this risk is minimized.





APPENDIX A


FIGURES





























PHASE I ENVIRONMENTAL SITE ASSESSMENT BUZZARD POINT PROPERTY (SQUARES 609 & 611) 2ND ST SW / V ST SW WASHINGTON DC

Prepared for PEPCo Holdings Inc. 701 Ninth Street NW Washington DC 20001

April 4, 2005

URS

URS Corporation, Inc. 200 Orchard Ridge Drive, Suite 101 Gaithersburg, Maryland 20878 URS Project No. 15296734

TABLE OF CONTENTS

Executive Summary		ES-1	
Section 1	Intro	duction	1-
	1.1	Objective	1-1
	1.2	Scope of Work	
	1.3	Limiting Conditions	1-2
	1.4	Limitations of the Assessment	1-2
Section 2	Site	Description	2- 1
	2.1	Physical Location and Description of Property	
	2.2	Environmental Setting	
		2.2.1 Topography and Surface Water Characteristics	
		2.2.2 Local Geology, Soils and Groundwater	2-1
Section 3	Histo	oric Site and Surrounding Property Conditions	3-1
	3.1	Current and Prior Ownership	3-1
	3.2	Site History	3-1
	3.3	Interviews	3-1
	3.4	Previous Reports	3-2
	3.5	Aerial Photographs and Topographic Maps	3-4
	3.6	Other Documents	3-4
	3.7	Historical Summary	3-7
Section 4	Site !	Inspection	4-1
	4.1	Current Uses of the Property	4-1
	4.2	Site Observations	4-1
		4.2.1 Easements and Utilities	4-1
		4.2.2 Stormwater	
		4.2.3 Hazardous Substances and Wastes	4-1
		4.2.4 Underground/Aboveground Storage Tanks	4-2
		4.2.5 PCB-Containing Equipment	
		4.2.6 Solid Waste	
		4.2.7 Wastewater	4-2
		4.2.8 Wells	4-2
		4.2.9 Sumps, Pits, Ponds, and Lagoons	
		4.2.10 Other Physical Evidence of Contamination	
	4.3	Current Uses of Adjoining Properties	
	4.4	Surrounding Properties of Potential Environmental Concern	
Section 5	Regu	latory Agency Review	5-1
	5.1	Environmental Database Review	
	5.2	Regulatory Agency Contact	5-4
URS			

TABLE OF CONTENTS

Section 6	Conclusions		
	6.1 6.2	Onsite Recognized Environmental Conditions	
Section 7	Refer	ences	7-1

URS

List of Tables, Figures and Appendices

Tables		Page
Table 1	Summary of Historical Information.	3-2
Table 2	Environmental Database Summary	5-1
Figures		
Figure 1	Site Location Map	
Figure 2	Site Plan	
Appendices		
Appendix A	Previous Reports	
Appendix B	Historical Documents	
Appendix C	UST Documents	
Appendix D	Resumes of URS Personnel	
Appendix E	Site Photographs	
Appendix F	EDR Database Search	
Appendix G	Regulatory Agency Contacts	

PEPCo Holdings Inc. (PHI) retained URS Corporation (URS) to conduct a Phase I Environmental Site Assessment (ESA) of the Buzzard Point site located between T and V Streets SW and 1st and 2nd Streets SW (Squares 609 and 611) in Southwest Washington DC (the Property or the subject property). PHI is planning to sell the Property. The purpose of URS' Phase I ESA was to evaluate whether current or historical activities on or near the subject property may have resulted in significant contamination by hazardous substances or wastes, also known as a Recognized Environmental Condition (REC). This ESA was performed in accordance with ASTM Practice E 1527-00 standards, URS' proposal dated August 6, 2004 and PEPCo's Purchase Order 4500003335 dated August 31, 2004.

The subject property is situated on a 1.593-acre (69,375 square foot) parcel of land in a predominantly industrial area of Washington DC known as Buzzard Point, and is currently used as an asphalt-paved parking lot leased to the National Geospatial Intelligence Agency (NGIA). The Property is one of five PEPCo properties located at Buzzard Point.

According to the information provided by site personnel, historical documents, and previous reports, the subject property once functioned as a coal storage yard. The PEPCo generating station, located on the adjacent property to the east, was activated in 1928 and was initially fueled by coal. Therefore, it is reasonable to assume that coal piles were located on the subject property as early as 1928. However, at some point in the late 1960's or early 1970's, the generating station switched from being coal-fired to fuel-fired. During this time period, the current 1.9-million gallon steel aboveground storage tank (AST) was constructed on the southern portion of the subject property. The AST contained fuel oil that fired the generating station's oil-fired steam generators through an underground pipeline that ran beneath 1st Street SW. The remaining coal piles were removed from the subject property by 1980. The AST was retired and the underground pipeline was filled in shortly after the generating station was decommissioned in 1981.

URS conducted a site reconnaissance of the Property on September 16, 2004 to identify current site uses and potential sources of hazardous substances both on the Property, and in the Property vicinity. The site reconnaissance consisted of visual inspection, interviews, and a pedestrian survey. No intrusive activities, such as soil and water sampling, were conducted as part of this ESA.

The Property is completely enclosed by a fence with two access points (one along 1st Street SW and one along 2nd Street SW). Each access point is guarded by a security located inside the parking lot. On the outside of the fence, the property is surrounded by a small grassy area followed by a public sidewalk. One small shed is located on the northeast corner of the property. The shed contains maintenance equipment such as brooms, salt, landscaping equipment, etc. that is used by the NGIA to maintain the parking lot. A second structure is located on the southern portion of the subject property next to the retired AST. The shed, which contains a fire pump, is within the dike and fenced area that encloses the AST. URS was unable enter the dike/fenced area containing the AST and the small fire pump shed. Pole-mounted lights, as well as small vegetated areas were observed throughout the parking lot.

No underground storage tanks were observed or reported on the subject property. There are two identical pits/subgrade structures located near the AST on the southeastern portion of the subject property. Site representatives did not know the function or purpose of the pits. No

environmental concerns related to hazardous materials, solid wastes, wastewater, or PCB-containing equipment were observed.

Soil sampling was conducted in 1990 on three of five PEPCo-owned Buzzard Point properties. The subject property, identified as Site 3 in the report, was included in the scope of the assessment; however, soil samples were not collected on the subject property because it was actively being used as a storage yard, parking lot, and maintenance area for vehicles. Sampling results from two of the three sites revealed soil contamination. Soil samples collected revealed the presence of total petroleum hydrocarbons (TPH) and ethylbenzene at Site 1, north of the Property, and the presence of TPH at the adjacent former PEPCo/Chevron gasoline station.

The District of Columbia, Department of Consumer and Regulatory Affairs, Underground Storage Tank Management Branch (DCRA) issued a directive requiring a Corrective Action Plan to be submitted regarding suspected groundwater contamination at the adjacent generating plant, and identified the case as LUST Case # 93-051. The DCRA Directive also identified the former PEPCo/Chevron gasoline station located at 180 S Street SW and the active PEPCo aboveground tank farm that provided fuel for the combustion turbine yard (CT Yard) as requiring additional assessment. Since 1993, PEPCo has conducted monthly monitoring and provided the results in quarterly reports to DCRA.

The most recent (August 2004) progress report of the groundwater remediation project at the adjacent generating plant states that since May 2003, samples have been taken quarterly at the three downgradient wells and results have been consistently below regulatory standards.

Environmental Data Resources, Inc. (EDR) was contracted to review state and federal records. Pertinent results of the EDR search are discussed in Section Five. Federal and State records researched by EDR indicate that no environmental records (such as those involving operating procedures, permits, spill and release incidents, air emissions, non-compliance events, tank removals, tank closures, waste storage and disposal, and polychlorinated biphenyls) exist for the Property.

Based on a review of available information, it is apparent that the subject property has a long history of industrial use. As a result, past activities conducted on the property (i.e. coal storage and fuel supply for the adjacent generating station) are of concern. In particular, potential leaks from the underground pipeline while it was still in use, as well as the pits that may have been oil water separators or were associated with the former underground pipeline in some way, have the potential to create a Recognized Environmental Condition on the subject property.

Based on the review of available information, the following offsite properties were identified that are likely to create a Recognized Environmental Conditions on the subject property:

- the inactive PEPCo generating station (adjacent to the east and crossgradient) which is currently undergoing groundwater remediation,
- the former gas station (adjacent to the north and upgradient) which was identified as having TPH contamination in soil,
- and the former PEPCo storage yard (located at Q and 2nd Streets SW, three blocks north and upgradient) which was also identified has having TPH contaminants in soil, and

 the Super Salvage scrap yard (located at R and 1st Streets SW, two blocks north and upgradient of the subject property) where large scale waste debris and scrap metal operations were observed being conducted over site soils.

Releases from these nearby sites have the potential to create a Recognized Environmental Condition on the subject property.

Further investigation is recommended.

This Executive Summary is not intended to be a "stand-alone" document, but a summary of our findings as described in the following report. It is intended to be used in conjunction with the scope of services and limitations described therein.

PEPCo Holdings Inc. (Client), retained URS Corporation (URS) to conduct a Phase I Environmental Site Assessment (ESA) of the Buzzard Point site located between T and V Streets SW and 1st and 2nd Streets S.W. (Squares 609 and 611) in Washington, D.C. (subject property or Property). This Phase I Environmental Site Assessment was conducted in conformance with the methods and procedures described in the American Society for Testing and Materials (ASTM) "Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process" (Standard Designation E 1527-00). The Phase I ESA was also conducted in accordance with URS' proposal dated August 6, 2004 with reference to PEPCo's Purchase Order 4500003335 dated August 31, 2004. The Phase I ESA objectives, scope, and limitations are presented in the following sections.

1.1 OBJECTIVE

The objective of URS' Phase I Environmental Site Assessment was to evaluate whether current or historical activities on or adjacent to the subject property may have resulted in a "Recognized Environmental Condition." A Recognized Environmental Condition is defined by ASTM as:

"The presence or likely presence of any hazardous substances or petroleum products on a property under conditions that indicate an existing release, a past release, or a material threat of a release of any hazardous substances or petroleum products into structures on the property or into the ground, groundwater or surface water of the property. The term includes hazardous substances or petroleum products even under conditions in compliance with laws. The term is not intended to include de minimis conditions that generally do not present a material risk of harm to public health or the environment and that generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies. Conditions determined to be de minimis are not recognized environmental conditions."

A Historical Recognized Environmental Condition is defined separately as:

"[An] environmental condition which in the past would have been considered a recognized environmental condition, but which may or may not be considered a recognized environmental condition currently. The final decision will be influenced by the current impact of the historical recognized environmental condition on the property."

1.2 SCOPE OF WORK

URS' Scope of Work for the Phase I Environmental Site Assessment consisted of an inspection of the subject property and nearby area, a review of historical information on activities on the subject property, review of readily available regulatory information concerning the subject property and nearby properties of environmental concern, review of previous reports concerning nearby properties and preparation of a report detailing URS' results, conclusions, and recommendations.

1.3 LIMITING CONDITIONS

URS' site inspection included a walking inspection of areas of the subject property that were accessible by foot, and a drive-by inspection of surrounding and adjacent properties, including those properties identified in the environmental database search. The following conditions limited URS' ability to inspect all areas of the subject property:

- An inactive aboveground storage tank (AST) located on the southern portion of the subject property is enclosed by a 6-foot concrete dike and fence. As a result, URS was unable to closely inspect the immediate surroundings of the tank.
- A small shed located beside the AST that reportedly contains a fire pump could not be accessed during the site inspection.

No other conditions that would limit URS' ability to complete the scope of work were encountered during the performance of the Environmental Site Assessment.

1.4 LIMITATIONS OF THE ASSESSMENT

The Phase I Environmental Site Assessment was prepared in accordance with URS' proposal dated August 6, 2004. The work conducted by URS is limited to these services with and no other services beyond those explicitly stated should be inferred or are implied.

The conclusions presented in this report are professional opinions based solely upon URS' visual observations of the Property and adjacent properties, and upon URS' interpretations of the readily available historical information, conversations with personnel knowledgeable about the Property, and other readily available information, as referenced in the report. These conclusions are intended exclusively for the purpose stated herein, at the Property indicated, and for the project indicated.

URS has performed the scope of work set forth in the proposal related to this project, in specific reliance on the understandings and agreements reached between URS and PEPCo Holdings Inc. (Client). Without limiting the generality of the foregoing, and to insure that there are no misunderstandings regarding the scope of URS' activities, be advised that the Scope of Work did not include structural, electrical or mechanical issues, or other activities not expressly described in the proposals or in URS' report. Upon written request, URS will issue a proposal to expand the Scope of Work to include these or additional matters within our expertise.

The report(s) and any other information which URS prepared and submitted to Client in connection with this project (collectively, the "Reports") are for the sole use and benefit of Client for the property described in the report and may not be used or relied upon by any other person or entity without the prior written consent of Client and URS. Any such consent given by URS shall be deemed to be and shall be subject to the terms and conditions of the Proposals and the Agreement, including without limitation, the warranty, liability and indemnity terms thereof, and any person given such consent (Grantee) shall be deemed to have agreed to such terms and conditions by its use and reliance on the Reports. Such Grantee must also agree not to reveal the contents of the Reports to any other person or entity without the prior written consent of both Client and URS.

Client recognizes and agrees that:

- (1) The information in the Reports relates only to the properties specifically described in the Proposals and Reports and was presented in accordance with and subject to the scope of work described in the Proposals which were specifically agreed to by Client;
- (2) The information and conclusions provided in the Reports apply only to the subject properties as they existed at the time of URS' site examination. Should site use or conditions change or should there be changes in applicable laws, standards or technology, the information and conclusions in the Reports may no longer apply;
- (3) URS makes no representations regarding the value or marketability of these properties or their suitability for any particular use, and none should be inferred based on the Reports;
- (4) The Reports are intended to be used in their entirety and no excerpts may be taken to be representative of the findings of this investigation;
- (5) URS' services in the development of this report were conducted in a manner consistent with that level of care and skill ordinarily exercised by members of the same professions currently practicing in the same locality under similar conditions and no other guaranty, warranty, or representation, either express or implied, is included or intended herein.

The scope of services proposed are limited to visual observations of site conditions on the day inspected; review of readily available and relevant data; and, statements made and information provided by the Client, his agents, outside parties, and regulatory agencies. URS will exercise due and customary care in the conduct of its assessment but will not independently verify information provided by others. Therefore, URS will assume no liability for any loss resulting from errors or omissions arising from the use of inaccurate/incomplete information or misrepresentations made by others.

Information concerning the subject property was obtained from a site inspection conducted by Ms. Lynne McMullen of URS on September 16, 2004, interviews with representatives of the subject property owner, and review of the documents referenced in Section 7.0 of this report. Adjacent properties were inspected by Mr. Roger Naylor and Ms. Lynne McMullen both of URS on September 2, 2004. URS was escorted during both site visits by Mr. Shahid Anis, Environmental Consultant with PEPCo.

2.1 PHYSICAL LOCATION AND DESCRIPTION OF PROPERTY

The subject property is one city block that is bordered by T and V Streets S.W. and 1st and 2nd Streets S.W. (identified as Square 609, Lot 804 and Square 611, Lots 810 and 19 on a city tax map). The Property is rectangular-shaped, situated on a 1.593-acre (69,375 square foot) parcel of land in a predominantly industrial area known as Buzzard Point in Washington D.C. The Property is currently used as an asphalt-paved parking lot that is leased to the National Geospatial Intelligence Agency.

Utilities available to the Property include electricity, natural gas, public water and sewer. A Site Location Map is presented as Figure 1, and a Site Plan is presented as Figure 2.

2.2 ENVIRONMENTAL SETTING

Environmental characteristics including topography, geology, and hydrogeology were evaluated based on site observations, published literature, and maps.

2.2.1 Topography and Surface Water Characteristics

According to the United States Geological Survey topographic map of the Alexandria, Virginia Quadrangle, 1965 (photorevised, 1983), the elevation of the subject property is approximately 14 feet above mean sea level (msl). The subject property is generally level, with the natural topographic gradient across the subject property being south-southeast.

Stormwater runoff on the subject property flows into the stormwater drains located on the edges of the parking lot, which discharge to the municipal storm sewer. The nearest surface bodies of water are the Anacostia River, the Potomac River, and Washington Channel. The Anacostia River is located approximately 330 feet southeast of the subject property; the Potomac River is approximately 3,630 feet southwest; and the Washington Channel is approximately 1,485 feet to the west. All three waterways converge at a point approximately 3/4 mile southwest of the Property and flow to the south. No surface impoundments were observed on the subject property.

2.2.2 Local Geology, Soils and Groundwater

A review of selected information from public sources concerning the geology and hydrology of the Property and surrounding area indicate the following classification and characteristics.

Geology

The subject property is geologically located in the Atlantic Coastal Plain physiographic province, which consists of marine and fluvial sediments. The overburden at the Property generally

consists of deep deposits of alluvial soils. It is underlain by the Mesozoic Era, Cretaceous System, and Lower Cretaceous Series stratigraphic unit.

Soils

According to the United States Department of Agriculture (USDA) Soil Survey of District of Columbia (1976), the soils mapped at the subject property consist of the "Urban Land". The Urban Land soil unit consists of areas where more than 80% of the surface is covered by asphalt, concrete, buildings, or other impervious surfaces. These areas include large areas where miscellaneous artificial fill was placed over swamps or streams.

Depth to bedrock was estimated at more than 5 feet below ground surface (bgs). The dominant soil composition in the vicinity is silt loam, which is moderately well drained. Subsurface soils consist mostly of quaternary aged sands, gravels and silts of the Wicomico Formation. Aquifer materials have very low permeability.

Soils collected during a previous investigation conducted by TPH Technology indicated that the subject property is located on the Pamlico Formation and Recent Alluvium which consists of gravel, sand and silt, and clayey fill.

Groundwater

Groundwater in the area of the subject property is typically encountered approximately 15 to 20 feet bgs and flows west-southwest towards the convergence of the three waterways. General groundwater flow throughout D.C. is generally to the south towards the Potomac River. Areas located to the north are topographically, and assumed to be hydrogeologically, upgradient of the subject property. The groundwater in Washington DC is known to be impacted by various sources and is not used for a source of public drinking water supply.

Wetland and Flood Zone

According to the USGS Alexandria, Virginia Quadrangle topographic map, the subject property was not identified as being located within a wetland area. There are no wetland areas within 1 mile of the subject property. According to the Federal Emergency Management Agency Flood Insurance Rate Map (community panel: 110001 0025B, effective November 15, 1985), the subject property is not located within a 100-year or 500-year flood zone.



The history of land use on and near the subject property was determined from interviews, review of historic aerial photographs, city directories, and the other documents referenced in Section 7.

3.1 CURRENT AND PRIOR OWNERSHIP

PEPCo currently owns the subject property. A chain of title search was not included in the scope of work for this Phase I ESA.

3.2 SITE HISTORY

According to the information provided by site personnel, historical documents, and previous reports, the subject property once functioned as a coal storage yard. The PEPCo generating station, located on the adjacent property to the east, was activated in 1928 and was initially fueled by coal. Therefore, it is reasonable to assume that coal piles were located on the subject property as early as 1928. However, at some point in the late 1960's or early 1970's, the generating station switched from being coal-fired to fuel-fired. It is during this time period that the current 1.9-million gallon steel aboveground storage tank (AST) was constructed on the southern portion of the subject property. The AST contained fuel oil that fired the generating station's oil-fired steam generators through an underground pipeline that ran beneath 1st Street SW. The remaining coal piles were removed from the subject property by 1980. The AST was retired and the underground pipeline was filled in shortly after the generating station was decommissioned in 1981.

During the 1980's and early 1990's, the subject property was leased out to W.A. Chester, Inc. and used as a storage yard, parking lot, and vehicle maintenance area. Currently, the subject property is being leased out to the National Geospatial Intelligence Agency who uses the Property as a secured employee automobile parking lot.

3.3 INTERVIEWS

URS interviewed Shahid Anis, an engineer for PEPCo for the past 28 years. He was not aware of any incidents, unusual odors, stains or other conditions on the actual subject property that would indicate a potential environmental concern. However, Mr. Anis did report that there have been incidents that have occurred on adjacent PEPCo properties (specifically, the PEPCo generating station site adjacent to the east and the former gas station site adjacent to the north) that may present environmental concerns on the subject property. The two adjacent properties are discussed in further detail in section 3.4.

URS also interviewed Fariba Mahui, the PEPCo tank coordinator, regarding the decommissioning of the AST on the subject property in the early 1980's. Ms. Mahui reported that a hole was cut out of the tank to enable its cleaning and that the underground pipeline that fed the fuel in the tank to the generating station's steamers was filled in. Further documentation detailing the decommissioning of the tank and underground pipeline was not available.



3.4 PREVIOUS REPORTS

URS reviewed previous environmental reports provided by PEPCo concerning the subject property and the adjacent PEPCo properties. Copies of the previous reports are presented in Appendix A and are summarized below:

Geomatrix, Inc., Assessment of the Buzzard Point Properties, 1990

In 1990, Geomatrix Inc. conducted soil sampling on five PEPCo-owned Buzzard Point properties located in Southwest Washington D.C. The subject property, identified as Site 3 in the report, was included in the scope of the assessment. However, Geomatrix was unable to take soil samples on the subject property because it was actively being used as a storage yard, parking lot, and maintenance area for vehicles. The report states that the objective of the investigation was to determine if the sites were "environmentally clean". Geomatrix collected soil samples that were analyzed for total petroleum hydrocarbons (TPH), benzene, toluene, ethylbenzene, xylene (BTEX), polychlorinated biphenyls (PCBs), and EP toxicity metals. PEPCo's generating station (identified as Site 5) was not evaluated because it was actively being used as a substation.

Soil samples collected from the three other PEPCo sites revealed the following:

- Site 1 (Square 603, located at Q and 1st Streets SW, three blocks north and upgradient of the subject property) was being used as an office area and parking lot at the time of the investigation. The site contained active USTs and has a history of UST removal. Two of the soil samples were taken from a depth of 3 to 5 feet; two were taken from a depth of 8 to 10 feet. Of the four samples collected, one sample had a TPH concentration of 32 parts per million (ppm), TPH of 1440 ppm, and ethylbenzene of 1 ppm. None of the parameters analyzed were detected in the other two soil samples.
- Site 2 (Square 607, located between 2nd and T Streets SW, adjacent to the north and upgradient to the subject property) was being used as a filling station for PEPCO vehicles at the time of the investigation. All samples were collected from a depth of 0 to 2 feet. Of the thirteen samples collected, ten of the samples showed TPH concentrations ranging from 100 ppm to 360 ppm.
- Site 4 (Square 661, located at R and 1st Streets SW, approximately 330 feet northeast and upgradient to the subject property) was a vacant lot at the time of the investigation and was being used for storage of excavated soils. Soil samples were collected from a depth of 0 to 2 feet. None of the four samples collected revealed the presence of TPH, BTEX, or PCBs.

Geomatrix reported that the extent of TPH contamination at Site 1 was unknown. Concentrations of TPH at Site 2 were fairly well distributed throughout the site. It was concluded that the presence of TPH at Site 1 and 2 most likely resulted from prior and current activities at those two sites. Releases from these upgradient sites have the potential to create a REC on the subject property.

TPH Technology, Incorporated, Corrective Action Plan, Remedial Specifications and Implementation Details, Buzzard Point Generating Station, Half & S Streets SW, Washington, DC, DC LUST Case # 93-051, March 10, 1995

According to the report, in 1968, an underground oil pipeline was installed at the combustion turbine yard (CT Yard), located on the northern portion of the generating station site (approximately 50 feet northeast and upgradient of the subject property), to transfer fuel oil from the AST farm located on the adjacent property to the north to the generating station. In the early 1970's, a leak was detected in the fuel oil pipeline and was repaired. However, in 1993, PEPCo personnel discovered the presence of petroleum in an onsite monitoring well. As a result, the District of Columbia, Department of Consumer and Regulatory Affairs, Underground Storage Tank Management Branch (DCRA) issued a directive requiring a Corrective Action Plan to be submitted for the suspected on-site groundwater contamination at the generating plant. The release was assigned LUST Case # 93-051. Under this plan, PEPCo was also required to continue monitoring all wells, remove free phase product, and submit monthly recovery reports until the case was deemed closed by DCRA. The DCRA Directive also identified the former PEPCo/Chevron gasoline station located at 180 S Street SW (the block adjacent to the north of the subject property and identified as Site 2 in the Geomatrix report) and the active PEPCo aboveground tank farm that provided fuel for the CT Yard (located approximately 500 feet northeast of the subject property) as requiring additional assessment. A Comprehensive Site Assessment (CSA) Report was written in August 1993 for the two properties, but was not available at the time this report was prepared.

Beginning in May 1993 and ending in January 1995, PEPCo installed a total of 23 monitoring wells throughout the generating station and CT Yard, as well as on the AST tank farm and former gas station site (as required by DCRA's directive). Both the soil and the groundwater samples revealed the presence of TPH and BTEX. The closest monitoring well to the subject property, MW-13, is located approximately 105 feet to the north on the adjacent former gas station. The soil cutting from MW-13 was found to have a TPH concentration of less than 29.8 mg/kg and a BTEX concentration of .02392 mg/kg. PEPCo's proposed remedial method was "to remove free-phase and adsorbed-phase product from the soil and groundwater beneath the CT Yard, and then allow natural processes to reduce soluble hydrocarbon concentrations once the free-phase and adsorbed-phase products were removed." Since 1993, PEPCo has conducted monthly monitoring and provided the results in quarterly reports to DCRA.

PEPCo, Buzzard Point Station - LUST Case # 93-051, Progress Report, August 19, 2004

In August of 2004, PEPCo submitted a progress report of the groundwater remediation project at the adjacent generating plant to the DCRA Underground Storage Tank Division. The report provided a summary of the site activities and analytical results of groundwater samples for three downgradient wells (located approximately 200 feet upgradient to the east and northeast of the subject property) for the period of April through July 2004. At the three wells (which are considered immediately downgradient of the CT Yard and Tank Farm), the results from the August 2004 sampling were fairly similar to the results of the March 2004 sampling. BTEX levels remained below Maximum Contaminants Levels (MCLs) for drinking water. Furthermore, TPH levels remained below the District of Columbia Water Quality Standards. The report states that since May 2003, samples have been taken quarterly at the three downgradient wells and results have been consistently below regulatory standards. According to the report, the "results

indicate that the contamination is confined to the site and due to a flat gradient, groundwater has no flow movement to leach the contamination outside the site boundary."

URS obtained documents from the PEPCo office providing information on USTs that were historically and currently located on adjacent PEPCo properties. Copies of these documents are provided in Appendix C.

- At one time, the adjacent property to the north (the former PEPCo/Chevron filling station) had two 6,000-gallon USTs which were owned by Chevron. One UST contained leaded gasoline and the other contained diesel fuel. These two tanks were removed in November 1988. There was also a 20,000-gallon gasoline UST, owned by PEPCo, which was removed in August 1993. According to PEPCo personnel, there are no longer any USTs located at the former filling station site.
- There have been several USTs removed from the adjacent property to the east (the PEPCo generating station and CT yard). According to documentation, four 2,000-gallon USTs (installed in 1968) containing waste oil were removed from the ground from 1991 until 1993. In addition, two 10,000-gallon USTs containing # 2 fuel oil, one 2,000-gallon UST containing fuel additive, and one 500-gallon UST containing varsol (installation dates unknown) were filled in with inert material in June 1984.
- According to site personnel and documentation, only two USTs remain. Two 4,000-gallon USTs are located at the adjacent generating plant and CT yard and contain waste oil. These tanks were installed in September 1993.

3.5 AERIAL PHOTOGRAPHS AND TOPOGRAPHIC MAPS

URS reviewed historical aerial photographs and topographical maps that covered the area of the subject property. The USGS Alexandria Quadrangle topographic maps, 1956, 1965 (photorevised 1971, 1972, 1979), and 1994 were reviewed. Aerial photographs were available from 1948, 1957, 1963, 1970, 1980, 1988 and 2002. The following table summarizes this information. Photocopies of the historical aerial photographs and topographical maps are provided in Appendix B.

Table 1 Summary of Historical Information Buzzard Point 1st Street SW/V Street SW Washington DC

Date	Location	Observation	Source
1948	Subject	Coal piles and what appears to be a conveyor are present	Aerial Photo
	Property		
	Adjacent	North: Many small square structures, most likely residences	
		East: PEPCo generating station	
		South: Mostly wooded land with a few small structures	
		West: Several large buildings, most likely Ft. McNair housing	

SECTIONTHREE

Historic Site and Surrounding Property Conditions

Date	Location	Observation /	Source
1956	Subject	A rail spur and a small building are shown	Topographic
	Property		Map
	Adjacent	North: Vacant	
		East: PEPCo generating station	
		South: A few small square structures Wort: Soveral lorge buildings, most likely Et. McNair housing	
1957	Subject	West: Several large buildings, most likely Ft. McNair housing Coal piles are present. A small building and conveyor belts are	Aerial Photo
1951	Property	shown.	Aenai Photo
	Adjacent	North: Several clumps of trees with only a few small structures.	
	,	East: PEPCo generating station	
		South: Mostly wooded land with a few small structures	
		West: Several large buildings, most likely Ft. McNair housing	
1963	Subject	Coal piles are present. A small building and conveyor belts are	Aerial Photo
	Property	shown.	
	Adjacent	North: Small structures, most likely residential	
		East: PEPCo generating station	
		South: Cleared land with a large building on the Anacostia River	
		Waterfront	
1965	Subject	West: Several large buildings, most likely Ft. McNair housing A rail spur is present	Tonographia
1905	Property	A ran spur is present	Topographic Map
	Adjacent	North: Vacant	wap
	rajacom	East: PEPCo generating station	
		South: Three small square structures	
		West: Several large buildings, most likely Ft. McNair housing	
1970	Subject	Coal piles are present. A small building and conveyor belts are	Aerial Photo
	Property	shown. A large AST is on the southern portion of the property.	
	Adjacent	North: One rectangular building is shown on the northern portion	
	Ť	East: PEPCo generating station and PEPCo combustion turbine yard	
		South: Cleared land with a large building on the Anacostia River	1
		waterfront	
		West: Several large buildings, most likely Ft. McNair housing	
1971	Subject	A rail spur and a small building are shown. Also, the AST is shown	Topographic
and	Property	on the southern portion of the property.	Maps
1972	Adjacent	North: Vacant	
		East: PEPCo generating station South: Three small square structures	
		West: Several large buildings, most likely Ft. McNair housing	
1979	Subject	Coal piles are present. A small building and conveyor belts are	Topographic
*///	Property	shown. A large AST is on the southern portion of the property.	Map
	Adjacent	North: One rectangular building is shown on the northern portion	vivab
		(may be the former filling station)	
		East: PEPCo generating station and PEPCo combustion turbine yard	
		South: Large structure, most likely the current US Coast Guard	
		Headquarters office building	
		West: Several large buildings, most likely Ft. McNair housing	



Date	Location	Observation	Source
1980	j		Aerial Photo
	Property	(The coal piles and conveyor belts are no longer shown).	
	Adjacent	North: One rectangular building is shown on the northern portion	
1		(may be the former filling station)	
1		East: PEPCo generating station and PEPCo combustion turbine yard	
		South: Large rectangular structure, most likely the current US Coast	
		Guard Headquarters office building West: Several large buildings, most likely Ft. McNair housing	
1988	Subject	The AST is present	A . 1 5 EN
1900	Property	The AST is present	Aerial Photo
	Adjacent	North: One rectangular building is shown on the northern portion	
	rajacent	(may be the former filling station)	
		East: PEPCo generating station and PEPCo combustion turbine yard	
		South: Large rectangular structure, most likely the current US Coast	ļ
		Guard Headquarters office building	
		West: Cleared, vacant land	
1994	Subject Property	The AST is present.	Topographic Map
	Adjacent	North: One rectangular building is shown on the northern portion (may be the former filling station)	
		East: PEPCo generating station and PEPCo combustion turbine yard	
}		South: Large structure, most likely the current US Coast Guard	
		Headquarters office building	
		West: Large rectangular structure, most likely current Fort McNair	
2002	Subject	building AST is present as well as as as left as a first life.	
2002	Property	AST is present as well as an asphalt paved parking lot.	Aerial Photo
	Adjacent	North: One rectangular building is shown on the northern portion	1
		surrounded by an empty parking lot	
		East: PEPCo generating station and PEPCo combustion turbine yard	
		South: Large structure, most likely the current US Coast Guard	İ
		Headquarters office building	
		West: Large rectangular structure, most likely current Fort McNair	1
		building	

3.6 OTHER DOCUMENTS

URS also reviewed Sanborn Maps for the years 1984, 1988, 1990, 1991, 1992, and 1994 that covered the area of the subject property. From 1984 until 1994, the subject property is identified as a PEPCo storage yard. A fuel oil AST enclosed by a 6' dike is shown on the southern portion of the property. A small shed is shown next to the dike. There is a PEPCo parking lot with a private garage to the north, the PEPCo generating station and combustion turbine yard to the east, and a U.S. Government office building (most likely the existing US Coast Guard Headquarters) to the south. Adjacent properties to the north, east, and south primarily appear the same on each of the Sanborn Maps. However, use of the adjacent property to the west changes throughout time. The 1984 Sanborn map depicts US Government office buildings on the adjacent property to the west, the 1988 map depicts the property as a Government parking lot, and the 1990 through 1994 Sanborns portray the Ft. McNair National Defense University Academic Operations Center and associated parking lots. Photocopies of the Sanborn Maps are provided in Appendix B.



City directories were also reviewed for the subject property and surrounding properties for the years 1922 through 2000 (at approximately 5 year intervals). Between 1922 and 2000, the subject property is consistently identified as "address not listed in research source". Between 1922 and 1936, surrounding properties along 1st and 2nd Streets SW are described as either individual residences or vacant. From 1940 until 1969, all surrounding properties are listed as vacant. Between 1973 and 1993, the surrounding properties along V and 2nd Streets SW are identified as various types of office buildings such as the Electrical Security Corporation, Office Cleaning Inc., Westwood Management Corp, U.S. Railway Association, etc. Lastly, in the 2000 directory, the surrounding properties are identified as apartments, residences, and James Creek Marina along V Street SW and the U.S. Department of Transportation, U.S. Coast Guard Headquarters, and the National War College Alumni Association along 2nd Street SW. Photocopies of the city directories are provided in Appendix B.

3.7 HISTORICAL SUMMARY

Based on URS' review of historical documents, the subject property was used for coal pile storage from as early as 1948 until 1979. The coal was used to fuel the adjacent PEPCo generating station. A 1.9-million gallon aboveground storage tank (AST) containing fuel oil with an underground pipeline was constructed on the property as early as 1970 to replace coal as the fuel source for the generating station. The coal piles and associated conveyor belts were removed from the subject property sometime between 1979 and 1980. According to PEPCo personnel and prior reports, the AST was decommissioned in 1981 at the same time that the adjacent generating station was decommissioned. From 1980 until 2002, the subject property was used as a storage yard, parking lot, and for vehicle maintenance. Based on the long history of industrial use at the subject property, past activities have a potential to create a REC on the subject property. In particular, potential releases from the onsite underground pipeline have the potential to create a REC.

Furthermore, several adjacent properties were identified that have the potential to create a REC on the subject property. According to the 1990 Geomatrix soil assessment of the five PEPCo properties located at Buzzard Point, soil samples taken from the PEPCo storage yard (located three blocks north and upgradient of the subject property) and PEPCo/Chevron former gas station (located adjacent to the north and upgradient of the subject property) revealed the presence of TPH. In addition, releases from the adjacent PEPCo generating station and the active CT Yard (LUST Case # 93-051) have the potential to create a Recognized Environmental Condition on the subject property.

URS inspected the subject property on September 16, 2004. URS' site inspection included a walking inspection of the entire parcel. The weather was warm and sunny. Resumes for URS personnel involved in the site inspection, interviews, and the preparation of this report are presented in Appendix D. Photographs taken during URS' site inspection are provided in Appendix E.

4.1 CURRENT USES OF THE PROPERTY

The Property is used as an asphalt-paved parking lot currently leased out to the National Geospatial Intelligence Agency (NGIA).

4.2 SITE OBSERVATIONS

Key features of the Property are described below and the layout and relevant features of the subject property are shown on Figure 2. The Property is completely enclosed by a fence with two access points (one along 1st Street SW and one along 2nd Street SW). Each access point is guarded by a security located inside the parking lot. On the outside of the fence, the property is surrounded by a small grassy area followed by a public sidewalk. One small shed is located on the northeast corner of the property. The shed contains maintenance equipment such as brooms, salt, landscaping equipment, etc. that is used by the NGIA to maintain the parking lot. A second structure is located on the southern portion of the subject property next to the retired AST. The shed, which contains a fire pump, is within the dike and fenced area that encloses the AST. As mentioned earlier in the report, URS was unable enter the dike/fenced area containing the AST and the small fire pump shed. Both structures were approximately 10-feet-by-10-feet and size and constructed of sheet metal. Pole-mounted lights, as well as small vegetated areas were observed throughout the parking lot.

4.2.1 Easements and Utilities

Electricity is supplied to the subject property area by Potomac Electric Power Company and natural gas is supplied by Washington Gas. Washington Water and Sewer Authority supplies water and sewer service to the subject property area.

Two pole-mounted transformers, one on the north side and one on the east side, are located outside the fence along the edge of the property. Storm drains were also observed along the streets.

4.2.2 Stormwater

Stormwater flows into intake drains that are located along the edges of the parking lot within the fence.

4.2.3 Hazardous Substances and Wastes

During the site visit, URS did not observe hazardous wastes or activities that would be considered likely to generate hazardous wastes on the subject property.

4.2.4 Underground/Aboveground Storage Tanks

URS observed no evidence of current USTs on the subject property at the time of the site inspection. There is a 1.9-million gallon AST located on the southern portion of the subject property. The AST stored fuel oil that fed oil-fired steam generators at the adjacent PEPCo generating station. The fuel was fed to the generating station via an underground pipeline underneath 1st Street SW. The AST was decommissioned when the generating station became inactive in 1981 and the underground pipe was filled in. The AST is enclosed by a 6 foot concrete dike and a fence. From outside of the dike/fence barrier, URS could not observe evidence of stains or leaks in the vicinity of the AST. Past releases of fuel oil, if any, from the underground pipeline have the potential to create a REC on the subject property.

4.2.5 PCB-Containing Equipment

No potential PCB-containing equipment was observed on the subject property.

4.2.6 Solid Waste

URS did observe small amounts of solid waste on the subject property. A thorough inspection of the AST and surrounding area was limited due to a fence and 6' concrete dike. However, from the outside of the fence and dike, URS did observe some debris inside the vegetated area surrounding the retired AST. The materials consisted of typical roadside debris items such as bottles, paper, etc., as well as rusted piping that most likely was removed from the AST when it was decommissioned in the early 1980's. The debris observed near the AST is unlikely to create a Recognized Environmental Condition on the subject property.

4.2.7 Wastewater

No wastewaters were observed or reported to be generated on the subject property.

4.2.8 Wells

No wells were observed or were reported to have ever existed on the subject property.

4.2.9 Sumps, Pits, Ponds, and Lagoons

There are two identical pits/subgrade structures located near the AST on the southeastern portion of the subject property (see Figure 2 and Photo No. 6). Site representatives did not know the function or purpose of the pits. The pits are approximately 5-foot by 7-foot in size and consisted of a concrete lined vault covered by thick metal lids that allowed for access into the pits. URS was unable to remove the metal covers; however, the pit closest to the AST was partially uncovered. Standing water could be seen approximately 5 feet down. The water did not appear to have oily sheens or unusual odors.

No other sumps, lagoons or other surface impoundments were observed on the subject property during the site inspection. Although the exact use of the pits is unknown, the structures may have been used as oil water separators or were associated with the former underground pipeline in some way. The pits have the potential to create a REC on the subject property.

4.2.10 Other Physical Evidence of Contamination

No other evidence of contamination, including staining of the soil and puddles of water having floating oil, topographic anomalies and distressed vegetation were identified during the site inspection.

4.3 CURRENT USES OF ADJOINING PROPERTIES

Adjacent properties were observed as follows:

• North T Street SW, followed by vacant parking lot and a storage building (a

former gas station) which are owned by PEPCo, followed by S Street SW,

and Super Salvage salvage yard.

East/Northeast 1st Street SW, followed by the active PEPCo gas combustion turbine yard

(on the northern portion of the adjacent property) and the inactive PEPCO

generating station (on the southern portion of the adjacent property).

• South V Street SW, followed by the US Coast Guard Headquarters office

building, followed by the Anacostia River.

- Southeast Intersection of V and 1st Streets SW, followed by a vacant, vegetated lot.
- Southwest Intersection of V and 2nd Streets SW, followed by James Creek Marina.
- West/Northwest 2nd Street SW, followed by a Fort McNair building and associated parking lot.

4.4 SURROUNDING PROPERTIES OF POTENTIAL ENVIRONMENTAL CONCERN

A drive-by/walking inspection of adjacent properties identified sites that have the potential to create a Recognized Environmental Condition on the subject property. The following sites were considered suspect, and received specific consideration:

- the former PEPCo generating station and CT Yard (adjacent to the east) which is currently undergoing groundwater remediation for LUST Case # 93-051,
- the former PEPCo/Chevron gas station (adjacent to the north) which was identified as having TPH contamination in soil, based on sampling that was conducted in 1990,
- the former PEPCo storage yard (located at Q and 2nd Streets SW, three blocks north and upgradient of the subject property) which was also identified as having TPH contaminants in soil, and
- the Super Salvage scrap yard (located at R and 1st Streets SW, two blocks north and upgradient of the subject property) where large scale waste debris and scrap metal operations were observed being conducted over site soils; potential releases from the debris have potential to create a REC

These facilities are discussed further in Sections 3.7 and 5.1, respectively.

5.1 ENVIRONMENTAL DATABASE REVIEW

URS reviewed information gathered from several environmental databases through Environmental Data Resources, Inc. (EDR) to evaluate whether activities on or near the subject property have the potential to create a Recognized Environmental Condition on the subject property. EDR reviews databases compiled by Federal, state, and local governmental agencies. The complete list of databases reviewed by EDR is provided in EDR's report, which is included in Appendix F. It should be noted that this information is reported as URS received it from EDR, which in turn reports information as it is provided in various government databases. It is not possible for either URS or EDR to verify the accuracy or completeness of information contained in these databases. However, the use of and reliance on this information is a generally accepted practice in the conduct of environmental due diligence. A description of the databases searched and the information obtained is summarized below:

Table 2 Environmental Database Summary Buzzard Point 1st Street SW/V Street SW Washington DC

Type of Database/Date	Description of Database/Effective Date	Radius Searched	Number of Sites Identified
NPL	The National Priorities List identifies uncontrolled or abandoned hazardous waste sites. To appear on the NPL, sites must have met or surpassed a predetermined hazard ranking system score, been chosen as a state's top priority site, pose a significant health or environmental threat, or be a site where the EPA has determined that remedial action is more cost-effective than removal action. Effective Date – 4/04	1mile	0
CERCLIS	The Comprehensive Environmental Response, Compensation, and Liability Information System (CERCLIS) database identifies hazardous waste sites that require investigation and possible remedial action to mitigate potential negative impacts on human health or the environment.	0.5 mile	1
CERCLIS-NFRAP	No Further Remedial Action Planned (NFRAP). As of February 1995 CERCLIS sites designated NFRAP have been removed from CERCLIS. NFRAP sites may be sites where, following an initial investigation, no contamination was found, contamination was removed quickly without the need for the site to be placed on the NPL, or the contamination was not serious enough to require Federal Superfund action or NPL consideration. Effective Date – 5/04	0.25 mile	0

Type of Database/Date	Description of Database/Effective Date	Radius Searched	Number of Sites Identified
RCRIS TSD	Resource Conservation & Recovery Information System treatment, storage, or disposal sites	0.5 mile	0
	Effective Date – 6/04		
CORRACTS	Listing of RCRA facilities that are undergoing corrective action. Corrective actions may be required beyond the facility's boundary and can be required regardless of when the release occurred, even if it predates RCRA.	I mile	1
	Effective Date – 6/04		
RCRIS Large	RCRA-regulated hazardous waste generator notifiers list.	0.25 mile	0
Quantity Generators	Effective Date – 6/04		
RCRIS Small	RCRA-regulated hazardous waste generator notifiers list.	0.25 mile	2
Quantity Generators	Effective Date – 6/04		
ERNS	EPA's Emergency Response Notification System (ERNS) list contains reported spill records of oil and hazardous substances	Target Property	0
	Effective Date – 12/03		
SHWS	State Hazardous Waste/Superfund permanent list of priorities	N/A	N/A
	Effective Date – N/A		
LUST	List of information pertaining to all reported leaking underground storage tanks	0.5 mile	15
	Effective Date – 4/04		
UST	State underground storage tank sites listing	0.25 mile	6
	Effective Date – 4/04		

The actual subject property was not listed on any database searched by EDR. However, EDR mistakenly listed the PEPCo Buzzard Point Generating Station, located at 1st and V Street SW, as being on the subject property. The generating station appears on the UST, LUST, and RCRIS-SQG databases and is discussed in further detail below.

Comprehensive Environmental Response, Compensation and Liability System (CERCLIS)

There is one site listed in the CERCLIS database that is located within ½ mile of the subject property. The site is identified as Fort McNair and is located at 350 P Street SW (which is approximately 2600 feet northwest of the subject property). The CERCLIS site status is listed as "low" and was first determined to be a CERCLIS site in September of 1980. There is current remediation and monitoring at Fort McNair, but the site is in the apparent downgradient direction from the PEPCo Property. Due to the site's distance from the subject property, it is unlikely that this site would present a potential environmental condition on the subject property.

RCRA Corrective Action Activity (CORRACTS)

One site, the Southeast Federal Center located at 2nd and M Streets SW, is identified on the CORRACTS database as being within 1 mile of the subject property. The site is approximately

³/₄ mile north of the subject property. The site required the completion of several corrective actions in 1997 and 1998. Based on the distance from the subject property, it is unlikely that this site has created a Recognized Environmental Condition on the subject property.

RCRIS Small Quantity Generators (SQG)

There were 2 small quantity generators of hazardous waste identified on the database that are within ¼ mile of the Property. The closest is the inactive PEPCo Generating Station, located adjacent and upgradient to the subject property to the east. However, there have not been violations of hazardous waste generator requirements and the station has been inactive since 1981. The generating station also appeared on the open LUST database. The site is identified as LUST Case # 93-051, which is the catalyst for the ongoing groundwater remediation project being conducted at the generating station. Detailed information regarding this case is discussed in Section 3.4 and prior reports are included in Appendix A. Based on the adjacent location of the site and the ongoing groundwater remediation that has documented the presence of TPH and BTEX in both the soil and groundwater, it is likely that the generating plant has created a Recognized Environmental Condition on the subject property.

The second SQG site is identified as being the Super Salvage Inc. located at 1711 1st Street SW (approximately 800 feet north of the subject property). During the site reconnaissance, URS observed large amounts of waste debris and scrap metal operations being conducted over bare soils. Although, there have not been any violations involving the Super Salvage, based on the observed site operations, it possible that the site has created a REC on the subject property.

Leaking Underground Storage Tanks (LUST)

The database search identified 15 LUST facilities within a ½ mile radius of the subject property, with 7 of those facilities remaining "open" status (including the abovementioned generating station). A LUST site was identified as the Fort McNair parking lot at 103 3rd Street SW, approximately 1100 feet northwest and upgradient of the subject property. The case is listed as open, but is unlikely to create a REC based on distance and documented groundwater flow.

A LUST site with an open case was also identified at Home Moving & Storage located at 1812 Half Street SW, approximately 500 feet northeast of the subject property. Although there is no documented groundwater flow, due to the site's proximity to the Anacostia River (located several hundred feet southeast of the LUST Site), it is likely that groundwater for the Home Moving & Storage site would flow southeast towards the Anacostia River and away from the subject property. Therefore, it is unlikely that this LUST site presents a REC on the subject property.

The remaining four "open" LUST sites on the database are greater than ¼ mile northeast of the subject property and are located near the shoreline of the Anacostia River. The groundwater flow at these sites is most likely east-southeast and away from the subject property, and therefore unlikely to create a Recognized Environmental Condition on the subject property.

Underground Storage Tanks (UST)

There are 6 sites located within ¼ mile of the subject property that have registered USTs. The fact that a site is listed on this database does not necessarily indicate an environmental concern, only that the location has UST(s) in place.

Orphan Sites

URS reviewed the Orphan List Sites, which are sites that have not been geocoded based on lack of sufficient data regarding their exact location within the general area. The review of the Orphan List Sites did not identify properties that are likely to create a Recognized Environmental Condition on the subject property.

5.2 REGULATORY AGENCY CONTACT

Local governmental agencies frequently maintain information on sites of environmental concern where the local agency has been consulted, or informed of particular activities. Local agencies, including local fire departments, also maintain records concerning USTs and hazardous materials. URS sent Freedom of Information Act (FOIA) letters to the DC Department of Health, Environmental Health Administration and the DC Fire Department Public Affairs Office to receive any information that these agencies may have available. Responses from the two regulatory agencies were not received by the time this report was prepared. Copies of agency correspondence are provided in Appendix G.

URS conducted a Phase I Environmental Site Assessment of the PEPCo Buzzard Point property, identified as Squares 609 and 611, and comprising a city block bordered by T and V Streets SW and 1st and 2nd Streets SW in Washington DC, to evaluate the potential for a Recognized Environmental Condition to exist on the subject property from onsite or offsite activities. URS' conclusions are presented below.

6.1 ONSITE RECOGNIZED ENVIRONMENTAL CONDITIONS

Based on a review of available information, it is apparent that the subject property has a long history of industrial use. As a result, past activities conducted on the property (i.e. coal storage and fuel supply for the adjacent generating station) are of concern. In particular, potential leaks from the underground pipeline while it was still in use, as well as the pits that may have been oil water separators or were associated with the former underground pipeline in some way, have the potential to create a Recognized Environmental Condition on the subject property.

6.2 OFFSITE RECOGNIZED ENVIRONMENTAL CONDITIONS

Based on the review of available information, the following offsite properties were identified that are likely to create a Recognized Environmental Conditions on the subject property:


- the inactive PEPCo generating station (adjacent to the east and crossgradient) which is currently undergoing groundwater remediation for an open LUST Case # 93-051; groundwater and soil samples have revealed the presence of TPH and BTEX,
- the former gas station (adjacent to the north and upgradient) which was identified as having TPH contamination in soil after sampling was conducted in 1990,
- the former PEPCo storage yard (located at Q and 2nd Streets SW, three blocks north and upgradient) which was also identified has having TPH contaminants in soil, and
- the Super Salvage scrap yard (located at R and 1st Streets SW, two blocks north and upgradient of the subject property) where large scale waste debris and scrap metal operations were observed being conducted over site soils.


Releases from these sites have the potential to create a Recognized Environmental Condition on the subject property.

Literature:

- American Society for Testing and Materials (ASTM). Standard E1527-00, Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process, June 2000.
- Environmental Data Resources, Inc. 2004, The EDR Radius Map with GeoCheck, Pepco-Buzzard Point, 2nd Street SW/V Street SW, Washington, DC 20024, Inquiry Number: 01260740.11r, September 1, 2004.
- Environmental Data Resources, Inc. 2004, The EDR City Directory Abstract, Pepco-Buzzard Point, 2nd Street SW/V Street SW, Washington, DC 20024, Inquiry Number: 1260740.16, September 16, 2004.
- Environmental Data Resources, Inc. 2004, The EDR Historical Topographic Map Report Pepco-Buzzard Point, 2nd Street SW/V Street SW, Washington, DC 20024, Inquiry Number: 1260740.13, September 3, 2004.
- Environmental Data Resources, Inc. 2004, The EDR Aerial Photo Decade Package, Pepco-Buzzard Point, 2nd Street SW/V Street SW, Washington, DC 20024, Inquiry Number: 1260740.14, September 1, 2004.
- Environmental Data Resources, Inc. 2004, The EDR Sanborn Map Report, Pepco-Buzzard Point, 2nd Street SW/V Street SW, Washington, DC 20024, Inquiry Number: 1260740.12s, September 1, 2004.
- Geomatrix, Inc., Assessment of the Buzzard Point Properties, 1990.
- Potomac Electric Power Company (PEPCo), Buzzard Point Station LUST Case # 93-051, Progress Report, August 19, 2004
- U. S. Department of Agriculture Soil Conservation Service, Soil Survey of District of Columbia, July 1976.
- U.S. Geological Survey, 1965 (photo revised 1983), 7.5 Minute Topographic Map of the Alexandria, Virginia Quadrangle, Scale 1:24,000.
- TPH Technology, Incorporated, Corrective Action Plan, Remedial Specifications and Implementation Details, Buzzard Point Generating Station, Half & S Streets SW, Washington, DC, DC LUST Case # 93-051, March 10, 1995.

URS





LIMITED PHASE II ENVIRONMENTAL INVESTIGATION BUZZARD POINT 2ND STREET SW / V STREET SW, WASHINGTON, D.C.

Prepared for
Potomac Electric Power Company
701 Ninth Street, N.W.
Washington, D.C.

March 22, 2005

URS

URS Corporation, Inc. 200 Orchard Ridge Drive, Suite 101 Gaithersburg, Maryland 20878 URS Project No. 15297096 March 22, 2005

Mr. Shahid M. Anis Potomac Electric Power Company Environmental Management Services 701 Ninth Street, N.W. Washington, D.C. 20068

> Re: Limited Phase II Environmental Investigation Buzzard Point, 2nd Street SW/V Street SW Washington, D.C. URS Project No. 15297096

Dear Mr. Anis:

URS is pleased to present this letter report outlining the results of our Limited Phase II Investigation at the above-referenced property. This work was conducted in accordance with the proposal by and between URS and Potomac Electric Power Company (PEPCo) dated December 10, 2004.

1.0 BACKGROUND

URS conducted a Phase I Environmental Site Assessment (ESA) of the subject property (Draft Report dated October 13, 2004) for PEPCo that identified a long history of industrial use on the subject property. As a result, past activities conducted on the property (i.e. coal storage and fuel supply for the adjacent generating station) are of environmental concern. In particular, potential leaks from the underground pipeline while it was still in use, as well as pits that may have been oil water separators or were associated with the former underground pipeline in some way, have the potential to create a Recognized Environmental Condition on the subject property. In addition, the following offsite properties were identified that have the potential to create a Recognized Environmental Condition on the subject property:

- the inactive PEPCo generating station (adjacent to the east and crossgradient) which is currently undergoing groundwater remediation,
- the former gas station (adjacent to the north and upgradient) which was identified as having TPH contamination in soil,
- and the former PEPCo storage yard (located at Q and 2nd Streets SW, three blocks north and upgradient) which was also identified has having TPH contaminants in soil, and
- the Super Salvage scrap yard (located at R and 1st Streets SW, two blocks north and upgradient of the subject property) where large scale waste debris and scrap metal operations were observed being conducted over site soils.

Further investigation was recommended by the Phase I ESA to determine whether the above onsite and offsite concerns have created a Recognized Environmental Condition on the subject property.

The scope of work for the Limited Phase II Environmental Investigation is included as Attachment 1.

2.0 FIELD INVESTIGATION

Prior to field mobilization URS contacted the regional public utility location and mark-out service for Washington, D.C. to mark all onsite public underground utilities. Utility lines including a natural gas transmission line and cable television line were marked near the perimeter of the property. None of these utilities conflicted with the boring locations conducted.

On Saturday, January 15, and Sunday, January 16, 2005, URS Corporation and Vironex Environmental Field Services (Vironex) of Glen Burnie, Maryland, the Geoprobe contractor, mobilized to the subject property to conduct field activities. Photographs of field activities are included in Attachment 2. Based on previous investigations conducted in the area of the subject property, local topography, and URS' experience in the area of the subject property, it was estimated that groundwater would be encountered at approximately 15 feet or less below ground surface (bgs) at the subject property.

Sampling locations were selected based on accessibility and proximity to the identified environmental concerns. A total of 12 borings were completed as part of this investigation on the subject property. Four borings (B-1, B-2, B-3 and B-7) were conducted near the northern and eastern boundaries of the subject property that are nearest to the offsite concerns identified above. Three borings (B-4, B-5, and B-6) were conducted near the central portion of the property beneath the former coal storage area and rail spur. Three borings (B-8, B-9, and B-10) were conducted proximate to the onsite petroleum aboveground storage tank (AST), former underground oil pipeline, and concrete pits on the south side of the property. Two borings (B-11 and B-12) were conducted on the south side of the subject property downgradient of the petroleum AST.

At each boring location, a 2-inch diameter, 48-inch long sampler was hydraulically hammered below the ground surface to a depth of 32 feet, until groundwater was encountered, or it was determined that due to the consistent clay composition of the soils observed that groundwater would not be encountered in the boring. Because soils observed at Borings B-2, B-4, B-5, and B-10 were moist and no groundwater was initially encountered, temporary screened PVC pipe was installed at these locations in an attempt to obtain a sufficient groundwater sample volume. The following discusses the individual borings and sampling conducted:

• Borings B-1, B-2, and B-3 (Figure 1) were located near the northern property boundary in order to evaluate if contaminants are migrating onto the subject property from the offsite environmental concerns. At Boring B-1, located at the northwest corner of the subject property, groundwater was encountered at a depth of approximately 15 feet bgs. Soil was collected for laboratory analysis at a depth of 15 feet bgs from Boring B-1. Groundwater was also collected for laboratory analysis from this boring location. Boring B-2 was located near the north central portion of the subject property. A small volume of groundwater was encountered at this location at a depth of approximately 15 feet bgs. Soil was collected for laboratory analysis from a depth of 19 feet bgs. Groundwater was also collected for laboratory analysis from Boring B-2. Boring B-3 was located at the northeast corner of the

subject property. Groundwater was not encountered at this location. Soil was collected from a depth of 13 feet bgs at Boring B-3.

- Borings B-4, B-5, B-6, and B-7 were located near the central and eastern portions of the subject property. Groundwater was encountered at Boring B-4 at a depth of approximately 15 feet bgs. Soil was collected for laboratory analysis at a depth of 15 feet bgs from Boring B-4. Groundwater was also collected for laboratory analysis from this boring location. Groundwater was not encountered at Borings B-5, B-6 and B-7 most likely due to the dense clay layer that was encountered. Soil was collected for laboratory analysis at Borings B-5 and B-6 from a depth of 12 feet bgs and 20 feet bgs, respectively. Soil was collected for laboratory analysis at Boring B-7 at a depth of 15 feet bgs.
- Boring B-8 was located near the AST on the west side of the subject property. Groundwater was encountered at Boring B-8 at a depth of approximately 10 feet bgs. Soil was collected for laboratory analysis at a depth of 10 feet bgs from Boring B-8. Groundwater was also collected for laboratory analysis from this boring location. Boring B-9 was located on the east side of the AST and near the former underground petroleum pipeline. Groundwater was not encountered at Boring B-9. Soil was collected for laboratory analysis at Borings B-9 at a depth of 32 feet bgs. Boring B-10 was located adjacent to and downgradient of the concrete pit located on the southeast side of the subject property. Soil was collected for laboratory analysis at Boring B-10 at a depth of 16 feet bgs. Groundwater was also encountered at Boring B-10 and was collected for laboratory analysis.
- Borings B-11 and B-12 were located along the southern property boundary downgradient of the AST. Groundwater was encountered at both locations at a depth of approximately 12 feet bgs. Soil was collected for laboratory analysis at both B-11 and B-12 at a depth of 12 feet bgs. Groundwater was also collected for laboratory analysis at both of these boring locations.
- Sampling of the liquid contained in the two onsite concrete pits was conducted using a peristaltic pump and silicone sampling tubing that was placed down into the pit.

Following completion of each boring, the borings were either backfilled with the same material removed from the boring or plugged and abandoned with a cement-bentonite grout. The top 6 inches of the boring was filled with an asphalt patch for all borings that were located on the asphalt parking surface.

Groundwater and soils were collected into pre-cleaned glassware. Each sample container was transferred to an ice-filled cooler, and transported under chain of custody to Phase Separation Science, Inc., Baltimore, Maryland. Selected soil and groundwater samples were analyzed for analyzed for VOCs by EPA Method 8260B, semi-volatile organic compounds (SVOCs) by EPA Method 8270, Priority Pollutant (PP) Metals by EPA Method 6020, TPH Gasoline Range Organics and Diesel Range Organics (TPH-GRO and TPH-DRO) by USEPA Method 8015, and polychlorinated bi-phenyls (PCBs) by EPA Method 8082. Since groundwater could not be obtained

Mr. Shahid M. Anis March 22, 2005 Page 4

at all boring locations (especially near the central portion of the property), additional laboratory analysis other than that initially proposed was conducted on the samples collected from Boring B-4 per PEPCo's request. Additional sampling or further laboratory analysis was not conducted at other locations based on the absence of field indicators of contamination.

3.0 DISCUSSION

No visual or olfactory evidence of contamination was observed in any of the soils observed from any of the boring locations conducted onsite. Field screening of samples was performed on all soil samples at approximately 2-foot intervals using a photoionization detector. No readings above background were obtained for any of the samples. No sheens or odors were observed in any of the groundwater samples or in either of the aqueous samples that were collected from the two concrete pits on the subject property.

The soils encountered onsite primarily consisted of tan, brown, and reddish-brown sandy silt with trace clay to a depth of approximately 8 feet bgs. The soils encountered in the borings at depths below 8 feet were consistent at all of the locations and were comprised of a very dense tan clay and orangeish tan clay with trace fine-grained tan sand, a trace of tan silt, and occasional trace of small and medium-size cobbles. The dense clay material encountered near 8 feet bgs and below was likely the reason for the absence of groundwater in some of the borings.

TPH-GRO and TPH-DRO were not detected in either of the aqueous samples collected from the two concrete pits found onsite. The laboratory analysis is included in Attachment 3.

Summaries of analytical results can be found on Table 1 (water) and Table 2 (soil). Laboratory analysis of all groundwater samples collected indicated that antimony, arsenic and lead were detected in groundwater collected from location B-4 at concentrations higher than acceptable for tap water per EPA Risk-based Concentrations (RBCs). However, the arsenic levels are below the District of Columbia Municipal Regulations (DC criteria) levels, and DC has no criteria for antimony. Additionally, groundwater collected from B-11 (in the apparent downgradient direction of B-4) contained elevated levels of both arsenic and lead.

Laboratory analysis of all soil samples collected indicated that several materials were detected onsite at below-RBC levels. Two materials were detected at higher than RBC levels. Benzo (a) pyrene was detected at B-11. Benzo (a) pyrene is one of a group of compounds called polycyclic aromatic hydrocarbons (PAHs). They are not produced or used commercially but are very commonly found since they are formed as a result of incomplete combustion of organic materials. It is typically found at locations near coal tar, asphalt and vehicle exhaust. Arsenic was also found at the B-11 location at a concentration greater than the RBCs, as well as at boring locations B-3, B-4 and B-5. All of these detections may be indicative of the past onsite use of this property as a coal storage yard. For additional comparison, the average arsenic concentration reported by the USGS (in Element Concentrations in Soils and other Surficial Materials of the Conterminous United States) is 7.2 ppm.

4.0 CONCLUSIONS AND RECOMMENDATIONS

Based on the results of this investigation, there is evidence that soil and groundwater has been affected by releases of petroleum hydrocarbons, and the presence of combustion products and metals.

TPH was detected in groundwater at two locations (B-2, at the northern property boundary, and at B-11, downgradient of the AST on the southern portion of the property). Possible sources include releases from an offsite source or onsite historic petroleum transfer operations.

Elevated arsenic in site soils may be due to past site use regarding coal storage, although they may be indicative of localized background concentrations. The elevated arsenic and lead in groundwater may be from upgradient properties, including a former gas station and salvage yard, as the elevated concentrations are higher in the apparent upgradient locations, from prior onsite coal storage, or from area-wide sources. Groundwater in this area is not used for drinking water purposes.

Soil and groundwater conditions at the subject property would not be expected to affect the current land use, thus further investigation of the subject property does not appear to be warranted at this time. The site is currently covered by an asphalt parking lot. However, if development of the subject property requires contact with affected soil and groundwater, further soil and groundwater investigation would be required to evaluate the need for special handling of excavated soil and dewatering disposal.

5.0 LIMITATIONS

The results of this investigation apply only to the specific locations sampled and should not be used to predict conditions on other portions of the property. The results should not be used to predict soil or groundwater conditions at other locations or in the future. The results should be used only to meet the objective of this investigation as set forth in the scope of work.

If you have any questions regarding this report, or if URS can be of further assistance, please do not hesitate to call.

Sincerely,

URS CORPORATION

Roger Naylor

Environmental Scientist

Carol Maslanka

Senior Project Manager

Attachments

Buzzard Point Site, Washington, D.C. Sampling Summary - Water Table 1

·····	·		·	,														
EPA RBCs	None	None			\$ \$00	210			15	0.045	55,000	1,500	None	3.7*	730	180	180	11,000
DC Criteria	None	None			None	10.000			None	50	100	1,000	50	None	None	50	50	5,000
B-12	QN	Q	NA	, , , , , , , , , , , , , , , , , , ,	YY.	NA	NAN		NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
B-11	550	180	QZ	Ę	S S		R		£	9.6	17	91	1,900	2.1	17	11	6.4	780
B-10	£	Ð	£	Ę	3 5	2 2	AN		NA	NA	NA	ΝΑ	NA	NA	NA	NA	NA	NA
B-9	NS	SN	NS	O, V	SN	SN	SN		SZ	SN	SN	SN	NS	NS	SN	NS	NS	NS
B-8	Ð	S	NA	17	Y Z	NA	AN		NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
B-7	SN	SN	NS	Ν̈́Ω	SN	SN	SN		NS	SN	NS	NS	NS	SN	SN	NS	SN	NS
B-6	SN	SN	SN	NG	SN	SN	NS		NS	SN	NS	NS	SN	SN	SN	SN	SN	NS
B-5	SN	NS	SN	MG	BS	SN	NS		SN	SN	NS	SN	SN	NS	NS	NS	NS	NS
B-4	£	QN	Q	Č	10	1	NA		32	15	31	74	8,800	£	56	2	Ð	220
B-3	NS	SN	SN	NG	SX	SN	NS		SN	NS	NS	NS	NS	SN	NS	NS	NS	SN
B-2	ND	110	R	ΝĀ	Y N	NA	NA		NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
B-1	ND	R	NA	ΔN	NA	NA	NA		NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
WP	ND	Q	NA	ΔN	NA	NA	NA		NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
EP	Ð	Ð	NA	Z	NA.	NA	NA		NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
Boring/ Parameter	TPH-DRO	TPH-GRO	PCB	VOC Nanhthalene	Acetone	o-Xylene	SVOCs	PPMetals	Antimony	Arsenic	Chromium	Copper	Lead	Mercury	Nickel	Selenium	Silver	Zinc

Note: Only parameters detected are listed on table.

NA = not included in requested analysis NS = not sampled or no groundwater obtained ND = not detected above quantitation limit

Units in micrograms per liter (µg/L or parts per billion)
U.S. EPA Region III Risk-based Concentrations (RBCs) for tap water, 10/08/2004
DC Criteria = District of Columbia Municipal Regulations

* methylmercury

Buzzard Point Site, Washington, D.C. Sampling Summary - Soil Table 2

Boring/ Parameter	EP	WP	B-1	B-2	B-3	B-4	B-5	B-6	B-7	B-8	B-9	B-10	B-11	B-12	EPA RBCs
TPH-DRO	NS	SN	29	Ð	Ð	Ð	Q.	ND	ND	ND	QN.	N ON	Q.	Q	None
TPH-GRO	SN	SN	£	R	Ð	ON ON	ON.	ND	ON	ND	ND ND	N N	2.2	R	None
PCB	SN	NS	NA	Ð.	Q	N N	ND.	ND	QN	NA	ND	ND ND	ND	NA	
VOC			}												
Naphthalene	NS	NS	NA	NA	S	Ð	Q	NA	NA	NA	£	0.00	0.079	NA	20,000
SVOC													•••••		
Fluoranthene	NS	NS	NA	NA	Ð	0.055	Ð	NA	NA	NA	NA	NA	R	NA	41,000
Naphthalene	SN	SN	NA	NA	R	R	R	NA	NA	NA	NA	NA	3.2	NA	20,000
2-Methylnaphthalene	SN	NS	NA	NA	Ð	見	Ð	NA	NA	NA	NA	NA	1.1	NA	4,100
Dibenzofuran	NS	NS	NA	NA	R	£	Ð	NA	NA	NA	NA	NA	1.3	NA	2,000
Fluorene	NS	NS	AA	NA	£	£	£	NA	NA	NA	NA	NA	1.6	NA	41,000
Phenanthrene	SN	NS	NA	NA	£	R	£	ÄÄ	NA	NA	NA	NA	8.9	NA	None
Anthracene	SN	SN	NA	NA	Ð	R	£	NA	ΝĀ	NA	NA	NA	1.6	NA	310,000
Carbazole	NS	NS	ΑN	NA	R	R	£	NA	NA	NA	NA	NA	1.0	NA	140
Fluoranthene	SN	NS	NA	NA	Ð	見	Ð	NA	NA	NA	NA	NA	5.7	ŇA	39
Acenaphthylene	SN	NS	NA	NA	Ð	e E	Ð	NA	NA	NA	NA	NA	1.3	NA	61,000
Pyrene	SN	SN	NA	AA	Ð	0.048	£	NA	NA	NA	NA	NA	5.1	NA	31,000
Benzo (a) anthracene	SN	NS	NA	NA	£	N N	R	NA	NA	NA	NA	NA	2.1	NA	3.9
Benzo(b,k)fluoranthene	SN	SN	NA	NA	Ð	R	R	NA	NA	NA	NA	NA	2.8	NA	3.9
Benzo (a) pyrene	SN	NS	NA	NA	Ð	R	R	NA	NA	NA	NA	NA	1.7	NA	0.39
Chrysene	SN	NS	NA	NA	ON.	0.055	ON	NA	ŇA	NA	NA	NA	Q	NA	390
PPMetals															
Arsenic	SZ	SN	NA	NA	5.1	3.1	4.9	NA	NA	NA	NA	NA	0.6	NA	1.9
Chromium	SN	SN	NA	NA	61	12	21	NA	NA	NA	NA	NA	11	NA	1,500,000
Copper	SN	SN	NA	NA	17	1.7	22	NA	NA	NA	NA	NA	26	NA	41,000
Lead	SN	SN	NA	NA	13	84	45	NA	NA	NA	NA	NA	120	NA	None
Mercury	SN	NS	NA	NA	R	R	ON.	NA	NA	NA	NA	NA	0.24	NA	None
Nickel	NS	NS	NA	NA	12	17	9.3	NA	NA	NA	NA	NA	8.5	NA	20,000
Zinc	NS	NS	NA	NA	39	52	34	NA	NA	NA	NA	NA	29	NA	310,000

Note: Only parameters detected are listed on table. NA = not included in requested analysis NS = not sampled ND = not detected above quantitation limit

Units expressed in milligrams per kilogram (mg/kg or parts per million) U.S. EPA Region III Risk-based Concentrations (RBCs), industrial soil, 10/2004 DC Criteria are not available for soils at non-UST sites.

Attachment 1
Scope of Work



December 10, 2004

Ms. Gail S. Kingman Strategic Sourcing Potomac Electric Power Company 701 Ninth Street NW, Room 9441 Washington DC 20068-0001

Subject:

Limited Phase II Investigation

Buzzard Point Site Squares 609 and 611

2nd Street SW/V Street SW

Washington, D.C.

Proposal No. PHI- 005 revised

Dear Ms. Kingman:

As requested by Mr. Shahid Anis, URS Corporation (URS) is pleased to offer Potomac Electric Power Company (PEPCo) this proposal to conduct a Limited Phase II Investigation at the above-referenced property. URS conducted a Phase I Environmental Site Assessment (ESA) of the subject property on September 16, 2004 (draft report dated October 13, 2004). Based on a review of available information, it is apparent that the subject property has a long history of industrial use. As a result, past activities conducted on the property (i.e. coal storage and fuel supply for the adjacent generating station) are of concern. In particular, potential leaks from the underground pipeline while it was still in use, as well as the pits that may have been oil water separators or were associated with the former underground pipeline in some way, have the potential to create a Recognized Environmental Condition on the subject property.

In addition, the Phase I ESA identified the following offsite properties that are likely to create a Recognized Environmental Conditions on the subject property:

- the inactive PEPCo generating station (adjacent to the east and crossgradient) which is currently undergoing groundwater remediation;
- the former gas station (adjacent to the north and upgradient) which was identified as having TPH contamination in soil;
- the former PEPCo storage yard (located at Q and 2nd Streets SW) which was also identified
 has having TPH contaminants in soil; and
- the Super Salvage scrap yard (located at R and 1st Streets SW) where large scale waste debris and scrap metal operations were observed being conducted over site soils.

URS Corporation 200 Orchard Ridge Drive, Suite 101 Gaithersburg, MD 20878-1978 301-258-9780 Phone 301-869-8728 Fax



Ms. Gail Kingman Potomac Electric Power Company December 10, 2004 Page 2 of 6

A Limited Phase II investigation is recommended to evaluate potential impacts from the onsite and offsite concerns identified.

1.0 PROPOSED INVESTIGATION

URS proposes to conduct a Limited Phase II Investigation to evaluate potential impacts associated with the onsite historical uses and from the offsite concerns to the soil and groundwater beneath the subject property. The proposed Limited Phase II will include using direct-push drilling (e.g., Geoprobe) to acquire samples of subsurface soils and groundwater. The Phase II Investigation is not intended to assess the extent of contamination, if any. Rather, a limited number of samples will be collected to evaluate the presence or absence of subsurface contamination.

URS will subcontract with a qualified Geoprobe contractor and analytical laboratory for the proposed investigation.

URS proposes to conduct the following tasks for this investigation:

Task 1 – Utility Clearance

The public utility locating service (i.e., Miss Utility) will be called to mark public utilities. URS will review available site-specific utility plans and locate the proposed borings at locations that should not impact subsurface utilities. URS and our subcontractors will not be responsible for any damage to underground utilities.

Task 2 - Field Investigation

URS' Geoprobe subcontractor will mobilize to the subject property and will collect samples from approximately 12 boring locations as indicated on the attached figure. Three borings will be conducted proximate to the onsite oil storage tank, former underground oil pipeline and pits on the south side of the property. Four borings will be conducted near the northern and eastern boundaries of the subject property that are nearest to the offsite concerns identified above. Three borings will be conducted near the central portion of the property beneath the former coal storage area and rail spur. Two borings will be conducted on the south side of the subject property downgradient of the oil storage tank. Due to the presence of underground equipment, utilities and other obstructions, exact boring locations will be determined in the field prior to sampling. At each location, a truckmounted hydraulic sampling probe will be pushed or driven until groundwater is first encountered (if less than 30 feet). Using the dedicated soil sampling probe, soil samples will be obtained to the top of the water table as observed during sampling. One soil sample per boring exhibiting elevated



Ms. Gail Kingman Potomac Electric Power Company December 10, 2004 Page 3 of 6

levels of volatile organic compounds (VOCs) based on field screening with a photoionization detector (PID), or visual signs of contamination will be selected for subsequent laboratory analysis. If no signs of contamination are present in a boring, one representative soil sample from each boring will be selected for laboratory analysis.

Following soil sampling, the probe will be removed and equipped with the groundwater sampling probe and reintroduced into the borehole to obtain a groundwater sample. To avoid sample disturbance and loss of volatiles, the water sample will be collected using dedicated polypropylene bailers or tubing. The sample will be collected into pre-cleaned laboratory bottles. Groundwater is expected to be encountered at approximately 15 feet below ground surface (bgs). If no groundwater is encountered at a depth of 30 feet bgs or less, no groundwater samples will be collected.

In addition to the samples collected from the boring locations, one grab sample of the liquid contained in each of the two onsite pits will be collected for laboratory analysis.

The soil and water samples will be analyzed for VOCs by EPA Method 8260B, semi-volatile organic compounds (SVOCs) by EPA Method 8270, Priority Pollutant (PP) Metals by EPA Method 200.8, TPH Gasoline Range Organics and Diesel Range Organics (TPH-GRO and TPH-DRO) by USEPA Method 8015, and polychlorinated bi-phenyls (PCBs) by EPA Method 8082. Additional sampling will be considered if evidence of contamination is noted. For cost reasons, not all samples collected will be analyzed for all of these parameters. The proposed laboratory analysis for each sample location is shown in the table below.

Proposed Laboratory Analysis (soil and groundwater) Buzzard Point Site Washington, D.C.

Rioposed Sample Location - 4, 120 5	2.27 28. Proposed Parameters For Enboratory Analysis see
Borings 1, 4, 8 and 12	TPH-DRO, TPH-GRO
Borings 2, 6 and 7	TPH-DRO, TPH-GRO, PCBs
Borings 3, 5 and 11	TPH-DRO, TPH-GRO, VOCs, SVOCs, PP Metals, PCBs
Borings 9 and 10	TPH-DRO, TPH-GRO, VOCs, PCBs
Two Pits Beside Oil Tank (water only)	TPH-DRO, TPH-GRO



Ms. Gail Kingman Potomac Electric Power Company December 10, 2004 Page 4 of 6

All boring locations will be properly abandoned and the ground surface repaired to match existing grade upon completion of sampling.

Task 3 - Data Evaluation and Reporting

Upon receipt and evaluation of the analytical results, URS will prepare a letter report which discusses the field activities, drawings showing sampling locations and results obtained, and conclusions and recommendations. The analytical results will be compared to the Washington D.C. Soil and Groundwater Clean-up Standards. Depending on the results of the sampling, additional investigation involving the collection of additional soil and groundwater samples may be necessary.

2.0 SCHEDULE

URS is prepared to begin work shortly following authorization to proceed. Subject to utility clearance and Geoprobe subcontractor availability, soil and groundwater sampling activities can be completed within two weeks of site access. Offsite laboratory analysis will be completed in five business days. URS' draft report will be submitted within one week of receipt of final analytical data. In summary, the Phase II investigation will be completed in approximately four weeks from our receipt of authorization to proceed. The proposed schedule assumes that there will be no delays due to site access, equipment malfunctions, weather conditions or other events beyond URS' control. PEPCo shall arrange site access for URS personnel and subcontractor with the current tenant (National Geospatial Intelligence Agency) for completion of the fieldwork at a mutually acceptable time.

3.0 ESTIMATED FEE AND TERMS AND CONDITIONS

URS proposes to conduct the scope of services described in Section 1.0 on a time and expense basis as follows:

URS Labor:

Principal Engineer/Scientist
Project Engineer/Scientist
Industrial Hygienist
Project Engineer/Scientist
Graduate Engineer/Scientist
Word Processing/Graphics

Subtotal



Ms. Gail Kingman Potomac Electric Power Company December 10, 2004 Page 5 of 6

Subcontractors: (assumes 2-field days)

Geoprobe Sampling

(includes mobilization, disposable equipment, decon)

Premium for weekend work (\$400/day)

Subtotal

Laboratory Analysis

Groundwater, Soil, Pit Samples (as shown on page 3 of this proposal).

VOCs

SVOCs

PP metals

TPH-GRO

TPH-DRO

PCBs

Subtotal

Equipment and Expenses (assumes 2-days in field)

PID

Expenses

Subtotal

Total (URS Labor, Subs., Equipment and Expenses)


We will not exceed our cost estimate without prior authorization from the Client. Any variations to the schedule, scope of work, or site description may require a modification of the project fee. The fee quoted in this section is valid for a period of 30 days.

URS proposes to conduct the scope of services described in Section 2.0 in accordance with the same terms and conditions as the Phase I ESA that was conducted by URS.

Ms. Gail Kingman Potomac Electric Power Company December 10, 2004 Page 6 of 6

If you have any questions regarding this proposal or require any additional information, please do not hesitate to call. We look forward to assisting you on this project.

Sincerely, URS Corporation	
Carol Maslanka Senior Project Manager	Greg Deaver Vice President
By: Authorization By Party Guaranteeing Payment Limited Phase II Investigation Buzzard Point Site	
Printed Name and Title of Signatory	
Date	



Attachment 2
Site Photographs

PHOTOGRAPHIC LOG

Client Name:

Potomac Electric Power Company

Site Location:

Buzzard Point, 2nd Street and V Street, S.W., Washington, D.C.

Project No. 15297096.01000

Photo No.

Date: 1-15-05

Direction Photo Taken:

West-northwest

Description:

Boring being conducted on the central portion of the subject property.




Photo No. 2 **Date:** 1-16-05

Direction Photo Taken:

North

Description:

Boring B-3 being conducted on the northeast corner of the subject property.



PHOTOGRAPHIC LOG

Client Name:

Potomac Electric Power Company

Site Location:

Buzzard Point, 2nd Street and V Street, S.W., Washington, D.C.

Project No. 15297096.01000

Photo No.

Date: 1-16-05

Direction Photo Taken:

East

Description:

Groundwater being pumped from Boring B-10. Silicon tubing and a small pump are used to pump groundwater into sample bottles.



Photo No.


Date: 1-15-05

Direction Photo Taken:

Northeast

Description:

Boring B-9 being conducted near the southeast portion of the subject property.



PHOTOGRAPHIC LOG

Client Name:

Potomac Electric Power Company

Site Location:

Buzzard Point, 2nd Street and V Street, S.W., Washington, D.C.

Project No. 15297096.01000

Photo No.

Date: 1-15-05

Direction Photo Taken:

West

Description:

West pit located adjacent to the petroleum AST.




Photo No.


Date: 1-15-05

Direction Photo Taken:

East

Description:

East pit located adjacent to the fence near the southeast corner of the subject property.



PHOTOGRAPHIC LOG

Client Name:

Potomac Electric Power Company

Site Location:

Buzzard Point, 2nd Street and V Street, S.W., Washington, D.C.

Project No. 15297096.01000

Photo No.

Date: 1-15-05

Direction Photo Taken:

NA

Description:

Interior of west pit. Liquid is present in the pit approximately 8 feet below ground surface.




Photo No.


Date: 1-16-05

Direction Photo Taken:

Southeast

Description:

PVC tubing and silicon sampling tubing at Boring B-10 located on the southeast corner of the subject property.



ASSESSMENT OF THE BUZZARD POINT PROPERTIES

SUBMITTED TO:

POTOMAC ELECTRIC POWER COMPANY 2000 PENNSYLVANIA AVENUE, N.W. WASHINGTON, D.C. 20068

SUBMITTED BY:

GEOMATRIX, INC. 6801 KENILWORTH AVENUE, SUITE 100 RIVERDALE, MARYLAND 20737 (301) 779-5302

TABLE OF CONTENTS

									PA	GE
EXE	CUTIVE	SUMI	MARY			• • • • • • •				3
1.0	INTR	ODUCT	rion				•			
									•	_
	1.2	Puri	ose an	d Scop	e of W	ork				7
2.0	PREL	IMINA	ARY ASS	essmen'	r	· · · · · ·				4
	2.1	Desc	riptio	n of S	ite #1					4
	2.2	Use	of Site	e #1						6
	2.3	Desc	ription	n of S:	ite #2					7
	2.4	use	OF Site	e #2						7
	2.5	nesc	ription	nots:	ite #4					ģ
	2.6	use	Or STre	9 #4						9
	2.7	Site	e #3 and	3 5				.		9
	2.8	Sumn	mary of	site A	Activi	ties	• • • • •	· · · · · ·	• •	11
3.0	PIRL	D TNU	ESTIGAT	PTOM DI	onen au					
										13
	3.1	Site	#1							15
	3.2	Site	: #2							15
	3.3	Site	#4			• • • • • •			• •	16
4.0	ANAL	YTICA	L RESUI	Ts	* * * * * .	• • • • • •			• •	17
	4.1	Site	#1							17
	4.2	Site	#2						• •	17
	4.3	Site	#4			• • • • • • •	• • • • • •			20
5.0	CONC		N							
				• • • • • •		• • • • • •	• • • • • •	• • • • •	• •	21
				LI	ST OF	FIGURE	S			
	Tri caras	1.	a							
	Figur		Gener	al Loc	ation	of Site	es		•	2
	Figur		Site	I Layo	ut and	Sample	e Loca	tions	•	5
	Figur Figur		Site	z Layo	ut and	Sample	e Loca	tions		8
	rigui	4:	srce	4 ьауо	ut and	Bample	e Loca	tions.	•	10
		,		L	IST OF	TABLES				
	Table		Locati	on of	Sites.	* * * * * * *			1	
	Table	2:	Summar	y of A	ctivit	v. Use	&		**	
	mob1 t		Poten	tial C	ontami	nants.	• • • • •		12	
	Tablė	5:	Buzzar	a Poin	t Samp	ling/Ar	alysi:	S		
	Table	4:	Summar	am vof 1	nalutt	cal Res		• • • • •	14	
		_ •	in PP	й		· · · · · · ·	ourrs		18	
APPE	NDIX A	: QI	JESTION	NAIRE/	RESPON	SES				
nr P II.	B KIDN	. 14	ABORATO	KY ANA.	LYTICA	L RESUI	TS			

EXECUTIVE SUMMARY

Geomatrix, Inc. performed an assessment of five pieces of property owned by PEPCO and located in the Buzzard Point area of Southwest Washington, D.C. to determine if these sites were "environmentally clean". The assessment of the environmental status of the sites was determined based on the presence and concentration of the most likely potential contaminants that should be found at the sites.

As a part of the assessment, a questionnaire was prepared and submitted to company operating groups utilizing the sites. In addition, meetings were held with PEPCO personnel from Real Estate, Stores, and Environmental Affairs to discuss the history and uses of the sites. The information gathered, along with visits to the sites, were used to determine potential contaminants which might be found at the sites. The potential contaminants that were identified included Total Petroleum Hydrocarbons (TPH), PCBs, and Metals.

Soil samples were collected from 3 of the sites and analyzed for the potential contaminants. The other 2 sites, namely Sites 3 and 5, were not sampled because of on-going activities at these sites.

The analytical results showed Site 4 to be free of contamination. Site 1 was found to contain TPH at a concentration of 1440 ppm in one localized area previously occupied by a petroleum underground storage tank. Site 2 showed TPH concentrations ranging from 48 to 360 ppm. The origin and extent of TPH presence at these sites is not know with certainty. However, it is believed to have resulted from the use and activities at the sites.

1.0 INTRODUCTION

Geomatrix, Inc. was contracted by PEPCO to conduct an assessment of five properties located in the Buzzard Point area of S.W. Washington, D.C. to determine if the sites were environmentally clean. Table 1 gives the property locations and the area occupied and Figure 1 shows the general location and layout of the properties.

TABLE 1

SITE #	PEPCO #	LOCATION	AREA OCCUPIED (SQ. FT)
1	603	Q & 2 nd sts. sw	89,032
2	607	2 nd st., between s &	T Sts., SW 89,250
3	609 & 611	Between 1 st & 2 nd do T & V Streets, SW	
4	661	R & 1 st Sts., SW	299,800
5	665	1 st & V Sts., SW	100,800




Figure 1: General Location of Sites

GEOMATRIX, INC.

The sites were acquired by PEPCO over the past 20 years. Information regarding uses by previous owners of the properties is limited. It is, however, believed that the properties were not used for any activity, such as disposal or storage of waste material. The properties were used by PEPCO as storage yards for supplies and equipment, parking area, fuel filling stations, maintenance shops, offices, coal storage and electric power generation and transmission.

1.2 Purpose and Scope of Work

The purpose of the study was to conduct an assessment of each site to determine whether or not the soils at the sites were contaminated as a result of prior use.

The scope of work included (1) development of a questionnaire on prior site uses for completion by the company as part of
the assessment, (2) meetings and phone conversations with PEPCO
personnel who were "old timers" familiar with the sites and their
operation, and (3) development and implementation of a soil
sampling and analysis program at the sites.

2.0 PRELIMINARY ASSESSMENT

A comprehensive questionnaire was developed and distributed to various operating groups by PEPCO Real Estate and Environmental Affairs departments. Examples of the questionnaires and the responses received are given in Appendix A. In addition to the information provided on the questionnaire, several meetings and telephone conversations with various representatives of the company were held. Following which a detailed reconnaissance of each site was made to confirm and/or modify the information gathered. Based on the above, a field investigation program was developed for all sites.

2.1 DESCRIPTION OF SITE #1

Site 1 (PEPCO #SQ603) is located at Q and First Streets, SW. It occupies an area of approximately 89,032.33 square feet. A portion of the site is rented and occupied by a tunnel boring contractor and a building on the corner of Q and Second Streets.

The layout of the portion of Site 1 occupied and presently used by PEPCO is shown schematically on Figure 2. The site area is occupied by two buildings, namely a three story office and a large multi-bay warehouse. A covered parking area is located adjacent to the office building. This area previously contained an underground storage tank (UST).

A

SECOND SECOND

Another UST was also located in front of the main office building and entrance to the site. In addition, an active underground fuel oil storage tank is located approximately 5 feet in front of the office building. The vent/overflow pipe for this tank is located at one corner of the office building and oil stains and "speedy dry" were observed in the vicinity of this pipe. The remainder of the area is paved with asphalt black top and concrete. In some areas from which USTs have been removed, the asphalt and concrete show signs of settlement and fracturing.

2.2 USE OF SITE #1

The site is currently used as an office area and parking for meter readers. The site, in general, was used for storage of precast concrete material, plastic piping, conduits, cables and wires. The warehouse was used as a paint shop and storage area, and an empty oil tank is presently stored in front of one of the warehouse bay doors. The warehouse area was also rented for a very brief period to a trucking company.

The 2 USTs which were located at the site were used to supply fuel to PEPCO vehicles. The other UST is presently used to store heating oil for the building.

2.3 DESCRIPTION OF SITE #2

Site #2 (PEPCO Site #SQ 607) is located between First and Second and S and T Streets, SW. It occupies an area of approximately 89,250 square feet. The layout of the site is shown schematically on Figure 3. The site is completely fenced with restricted access via a key card operated gate from First Street. A small guard house is located inside the gate on the right and on the left a storage shed is located, an active gasoline pump island, and an active UST. In addition, behind the UST and along the R Street fence, there is a small, shallow concrete pit area.

A concrete pad, enclosed on 3 sides by concrete walls approximately 3 feet high, is located in the east central portion of the site. Several large diameter steel pipes were located adjacent to the pad. North of the concrete pad is a metal building and southeast of the building, conduits were located on the ground and on a flat bed trailer. Further east of the conduits and trailer and north of the guard house is an area covered with "blue stone" gravel. The remainder of the site is an unpayed area bounded by asphalt paved driveways.

2.4 USE OF SITE #2

The storage shed, gasoline island and UST area are currently used to store and supply motor oil and fuel to PEPCO vehicles. The small, shallow concrete pit area behind the UST is presently




Figure 3: Site 2 Layout and Sample Locations 8

used to store an asphalt gravel mix. The concrete pad was occupied by soils and other debris. Adjacent to this pad several large diameter steel pipes were stored. The other areas of Site #2 were used for miscellaneous storage and parking of vehicles.

2.5 DESCRIPTION OF SITE #4


Site #4 (PEPCO Site #SQ 661) is located between First and R Streets, SW. It occupies an area of approximately 69,375 square feet. The site is, at present, a vacant lot that is completely fenced (see Figure 4).

2.6 USE OF SITE #4

Based on information from PEPCO, the site was used for the storage of excavated soil from an adjacent area now occupied by two storage tanks. The stock pile of excavated soils was recently spread over the site and graded.

2.7 SITES #3 AND 5

As a result of responses to the questionnaires, meetings and discussions with PEPCO personnel and a site reconnaissance of Site #3, it was decided to defer complete assessment of these two sites for the following reasons:



R SARFFA

Site_4 Layout and Sample Locations

Figure 4:

10

- o Site #3 was actively being used by one of PEPCO's contractors, W.A. Chester, Inc., as a storage yard, parking area, and maintenance area for vehicles. As a result of Site #3's highly active status, any assessment made of the site could be subject to change due to on-going use of the site.
- o Site #5 is active in some areas and is being used as a substation. Therefore, as in the case of Site #3, a complete assessment at this time could be subject to change.

2.8 SUMMARY OF SITE ACTIVITIES

Based on the information provided by PEPCO by way of answers to the questionnaires, meetings and phone conversations coupled with site visits, a summary of activities and uses at the sites was developed and is given in Table 2. In general, all of the sites were used for storage of materials and support equipment. In addition to storage, Site #5 was an electric power generating plant. More recently power generation has been significantly reduced at the plant.

Storage from excavation metals, hydrocarbons gas turbines, and tanks lead, hydrocarbons oils, metals, PCBs metals, PCBs, oils TPH TPH, metals, PCBs, sulfur, and other coal derivatives lead, Petroleum Hydrocarbons CONTAMINANTS POTENTIAL oil leaks, TPH tar compounds metals, FCBs, hydrocarbons PCBs, SUMMARY OF SITE ACTIVITY, USE, AND POTENTIAL CONTAMINANTS Miscellaneous storage yard, fueling and parking of Storage of Precast Material Plastic Pipe, Conduits and By W.A. Chester, Inc. Staging area, vehicle main. Scrap pile, cables, oils & solvents, old coal storage Active substations Office, Fueling SITE USE vehicles Wires of to Soil metal pipe area concrete pad & storage of excavated earth open unpayed storage area parking area asphalt pit Entire area ACTIVITY Area 1 UST 2 UST Power Plant AREA conduits LSO Area & D Constr. Conduit T & D Constr. Meter Reader Office PEPCO OPERATION Generating Generating Contractor Stores Conduits TABLE 2: Stores Use Ħ GEOMATRIX, INC. SITE/SQUARE 3/609 & 611 1/603 NUMBER 2/607 5/665 4/661

3.0 FIELD INVESTIGATION PROGRAM

Following the assessment of the sites, Geomatrix developed and conducted a field sampling program. The field program included the selection of sample locations and depths, based on use, activities, and potential contaminants at the sites. The field sampling analysis program that was carried out at the sites is summarized in Table 3.

For Sites 2 and 4, a sampling grid was developed and laid out in accordance with the EPA Grid System for the verification of PCB clean up. A number of sample points were combined to form composite samples. The actual locations of the points and number of points per composite sample were modified in the field as necessary to ensure adequate coverage of the areas of interest.

Prior to sampling, an area was set up for decontamination of the sampling equipment. The following steps were taken to reduce the possibility of cross-contamination of the samples. The sampling equipment was decontaminated before taking samples and immediately following the collection of each composite sample. Decontamination was carried out by washing the split spoon sampler, the bowls, and mixing trowels in tap water and alconox (a biodegradable detergent), rinsing with clean tap water, spraying the sampling tools with hexane, rinsing with distilled water, and allowing them to air dry.

TABLE 3: BUZZARD POINT SAMPLING/ANALYSIS PROGRAM

	h+f	f r1	4 0	he4	3+4	h-l		فيوا
TPI	TPH	TPH	utra able	Haj,	TPH	TPH		EP TOX, TPH
D XX	ox, BTE	BTE	Me act	PCB	ox,	ox, PCB	TPH	×,
			Base Extr	e e				솭
								P-4
O &	4 O	73	13	73	73	73	01	63
ω π π π 1	ις τ 1 α 1	0	0	0	0	ò	Ö	0-2
		~~~~~	<del>,</del>					······································
61	-tt			9,46			πú	3,4
Н	w.	73	m	0,13	7,00	11	14,1	1,2,3,4
<del></del>				ιn ⊢l	······································			
								4,
m	r-i	m	m	യ	-44	-44		@ 1 2,3,4
	` *	**	••	4,,	4.	4	11.7	44 സ മാ
<del></del>				***************************************				
<b>9</b>	ø	t 0	t) B	t) (I)	t) 0	ដុំ	ti O	t e
rsog T	ing)	posi	posi	posi	posi	oosi	isos;	isoc
S E E	ki i	CO	CO E	Ç E	ÇŞ ÇŞ	Ç E	Comi	4-Composite
7,	74	<u></u>	+	v v	4		7	4-
y~l	74		#	rea	<b>9</b>	it N	ρņ	Lot
UST	UST	UST	sphe Pit		adre Pad	iduj	rkin rea	
·		•	Æ	δ. O	8	Ö	79 124	Open
٠	ĺ						1	
rf	+	62	6	73	73	64	77	₩.
	UST	UST 1 2-Composite 3 1,2 3-5 & EP TOX, 8-10 BTEX UST 2 2 Single 1 3,4 3-5 & EP TOX, BTEX	UST 1 2-Composite 3 1,2 3-5 & EP TOX, BTE2 UST 2 2 Single 1 3,4 3-5 & EP TOX, BTE3 UST 1-Composite 3 2 0-2 EP TOX, BTE3	UST 1         2-Composite         3         1,2         3-5 & EP Tox, BTE2           UST 2         2 - Single         1         3,4         3-5 & EP Tox, BTE2           UST         1-Composite         3         2         0-2         EP Tox, BTE2           Asphalt         1-Composite         3         3         0-2         Base Neur Extracta	UST 1 2-Composite 3 1,2 3-5 & 8-10 UST 2 2 - Single 1 3,4 3-5 & 8-10 UST 1-Composite 3 2 0-2 Asphalt 1-Composite 3 3 0-2 Open Area 6-Composite 4 8 9 5,6,9, 0-2	UST 1 2-Composite 3 1,2 3-5 & 8-10  UST 2 2 - Single 1 3,4 3-5 & 8-10  UST 1 1-Composite 3 2 0-2  Asphalt 1-Composite 3 3 0-2  Open Area 6-Composite 4 8 9 5,6,9, 0-2  Concrete 2-Composite 4 7,8 0-2	UST 1 2-Composite 3 1,2 3-5 & 8-10  UST 2 2 - Single 1 3,4 3-5 & 8-10  UST 1-Composite 3 2 0-2  Asphalt 1-Composite 3 3 0-2  Open Area 6-Composite 4 8 9 5,6,9, 0-2  Concrete 2-Composite 4 7,8 0-2  Conduits 1-Composite 4 10,13,16  Conduits 1-Composite 4 10,13,16	UST 1 2-Composite 3 1,2 3-5 & 8-10  UST 2 2 - Single 1 3,4 3-5 & 8-10  UST 1-Composite 3 2 0-2  Pit 1-Composite 3 3 0-2  Open Area 6-Composite 4 & 9 5,6,9, 0-2  Concrete 2-Composite 4 7,8 0-2  Conduits 1-Composite 4 11 0-2  Aspking 2-Composite 3 14,15 0-2

......

GEOMATRIX, INC.

A drill rig was used to collect the soil samples by driving a 2" diameter split spoon sampler approximately 2 feet into the ground. Portions of the sample recovered from the spoon was placed in a stainless steel bowl and thoroughly mixed with samples from the other sampling points to form a composite sample. The composited sample was placed in glass jars and stored at approximately 4°C and shipped to the lab for analysis.

## 3.1 <u>Site #1</u>

Two areas at Site #1 were sampled. Area 1 was located to the north of the office building. Two composite soil samples were collected from 3 sample points as shown on Figure 2. Sample 1 was made up of soil samples from a depth of 3 to 5 feet. Sample #2 was taken from the same 3 locations at depths of 8 to 10 feet.

Area 2 was located east and in front of the office building. Two single samples were collected; Sample #3 from a depth of 3 to 5 feet and the other, Sample #4 from 8 to 10 feet. Sample #3 had a strong petroleum hydrocarbon odor. This odor was not as pronounced in Sample #4.

## 3.2 <u>Site #2</u>

The sampling points for Site #2 were located based on the grid system. The sample locations and the number of sampling

points forming each composite is shown on Figure 3. Thirteen composite soil samples were collected from a depth of 0 to 2 feet.

A number of samples, namely Sample #1, 4, and 12, were not collected as originally planned. Samples #1 and #4, located in the vicinity of the UST and pump island, were not collected because of underground utilities in the vicinity of these locations. Sample #12 (a composite of 2 points) was combined with Sample #11 (a composite of 2 points) to form one composite sample for the vicinity of the trailer and conduits.

## 3.3 Site #4

The sampling points were determined and laid out based on the grid method used at Site #2. The sample locations and number of points associated with each composite sample are shown on Figure 4. Four composite soil samples were collected from a depth of 0 to 2 feet at the locations shown on Figure 4.

#### 4.0 ANALYTICAL RESULTS

The laboratory analytical results are given in Appendix B and are summarized in Table 4. The results are discussed below for each site.

## 4.1 SITE #1

The four soil samples collected from Site #1 were submitted for the following analysis: TPH, BTEX, and EP Toxicity (metals). The results showed no detectable concentration of BTEX or EP Toxicity metals for the two samples from Area 1. TPH of 32 ppm was, however, detected in Sample #1 only.

In Area 2, Sample #3 had a strong hydrocarbon odor and the analyses showed TPH of 1440 ppm and ethylbenzene of 1 ppm. No other BTEX parameters were detected and no EP Toxic metals were detected. Sample #4 showed no TPH, BTEX, and/or EP Toxic metals.

#### 4.2 <u>SITE #2</u>

The thirteen composite soil samples which were collected from Site #2 at a depth of 0 to 2 feet and were submitted for analysis of one or more of the following parameters, EP Toxicity, metals, TPH, PCB, and Base Neutral compounds. The results, see

TABLE 4: SUMMARY OF ANALYTICAL RESULTS IN PPH

Area   Sample   Sam																	
SAMPLE SAMPLE TEH B T E X PCB ABNE An Ba Cd CT TY ( M E T A 1 Ba DEPTH (		Àg			Î	^ * * * *	ĵ	Î	Î	Î	Î	Î	Î	Î	Î	Î	
SAMPLE   SAMPLE   TPH   B   T   E   X   PCB   ABNE   An   Ba   Cd   Cr   PD   FG	ĸ	S e				* *											,, <u>,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,</u>
SAMPLE SAMPLE TPH B T E X PCB ABNE AN BA Cd CT  1 3-5 32 -ND	臼	Hg				* * *											
SAMPLE   SAMPLE   TPH   B   T   E   X   PCB   ABNE   An   Ba   Cd   CT	Þŧ	44				*											<del></del>
SAMPLE   SAMPLE   TPH   B   T   E   K   PCB   ABNE   An   Ba   Cd	н	ដ				* *	Ĭ		1	1	1	1	Ŷ	Î	Î	1	
SAMPLE   SAMPLE   TPH   B   T   E   X   PCB   ABNE   AN   Ba	M	Ğ				* *											•
SAMPLE SAMPLE   TPH   B   T   E   X   PCB   ABNE   An	Ħ	සිය				* * *											
SAMPLE SAMPLE TPH B T E X PCB ABNE  1 3-5 32 -ND -		An	· Q	P		Q**		A/A	- OXI	-CN-				CN	CN	ON-	
SAMPLE SAMPLE TPH B T E X PCB  1 3-5 32 -ND-		ABNE *		N/A								N/A		M/A	N/A	N/A	
SAMPLE SAMPLE TPH B T E  1 3-5 32 -ND 2 8-10 -ND 3 3-5 1440 ND ND 1 2 8-10 -ND 2 0-2 170 -ND 5 0-2 240 -ND 6 0-2 240 -ND 7 0-2 240 -ND 6 0-2 240 -ND 7 0-2 240 -ND 10 0-2 110 -ND 11 0-2 110 -ND 11 0-2 110 -ND 11 0-2 110 -ND 11 1 0-2 110 -ND 11 1 0-2 110 -ND 11 1 0-2 110 -ND		PCB	N/A	N/A	A/N		Ŷ	î	2	B	B	B	2	且	B	8	
SAMPLE SAMPLE TPH B T TP		×	<u> </u>	î	ğ	^ <b>*</b>			î	Î	î	î	î	î	î	î	^=
SAMPLE SAMPLE TPH B  1 3-5 32 -ND- 2 8-10 -ND -ND 3 3-5 1440 ND 2 0-2 170 -ND- 5 0-2 240 -ND- 6 0-2 240 -ND- 7 0-2 240 -ND- 10 0-2 110 -ND- 11 0-2 100 -ND- 13 0-2 190 -ND-		凶			r-l	* *											
SAMPLE SAMPLE TEH  1 3-5 32 2 8-10 ND- 3 3-5 1440 3 3-5 1440 3 0-2 170 5 0-2 240 7 0-2 240 7 0-2 240 6 0-2 240 10 0-2 110 11 0-2 100		EH			<u>g</u>	*											
SAMPLE SAMPLE THE THE DEPTH THE DEPTH THE DEPTH THE DEPTH THE DEPTH THE THE THE THE THE THE THE THE THE T		μ	-									ÓŖ-				P	
* * * * * * * * * * * * * * * * * * *		ТРН	32	Ŕ	1440	QN	170	N/A-	240	240	360	130	240	014	100	190	4.8
<u> </u>		SAMPLE DEPTH	 	8-10	ក្នុ ស្វ	* ** ** **	02	2 - 0	0-2	0-2	0-2	0-2	0-2	0-2	0-2	0-2	
AREA UST 1 UST 1 UST 2 UST 2 WST 2 WST 2 WST PEN UST PEN TORAGE		SAMPLE #	r-1	73	m	***	7	m	ហ	ω	^	ω	O	0	다 다	es H	14
* * * ODØ \		AREA				- 4	UST	ASPHALT PIT	OPEN	STORAGE	1						
M H H H H H H M M M M		D H H H	н	Н	н	<del>,,,,,</del>	71	8				,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		***************************************			

GEOMATRIX, INC.

TABLE 4: SUMMARY OF ANALYTICAL RESULTS IN PPM, CONT'D

 (METALS)	Hg Se Ag		Î	**** **** ****				
<b>≯</b> 4	qa			*				
H H	ដ	·	1	*	0.1	۳. 0	1.0	1.0
TOXL	ន	<b></b>		* *				
E4	ಥ			* *				
M	An		N/A -ND-	* * *	R	-CRI-		
	ABNE *			*	Î	Î	Î	Î
	PCB		2	*				
	⋈ .	•	Î	*				
	田	************		*				
	€÷			*				
	B		阜	*	N/A-	N/A-	N/A-	N/A
	тен	64	190	*	ğ	ğ	Š	g
	SAMPLE SAMPLE # DEPTH		0-2	***	02	0-2	0 - 2	0-2
	SAMPLE #	s t	9	****	1	73	m	ঝ'
	E.			*	LOI	LOI	Loi	LOT
	AREA			***	OPEN LOT	OPEN LOT	OPEN	OPEN LOT
	STTS #	***************************************	<del>, </del>	* * *	4	4	4,	4'

ABNE* - Acid, Base, Neutral Extractables.

D**:- Detected; see Appendix B for list of parameters.

N/A - Not analyzed for this sample.

ND - Not detected.

ND - Not detected.

ND* - Bis(2-ethylhexyl) phthalate detected = 1.

;; ;, GEOMATRIX, INC.

Table 4, showed that of the parameters analyzed for, only TPH was detected. Ten of the thirteen samples showed TPH concentrations ranging from 100 ppm to 360 ppm as shown in Table 4.

## 4.3 <u>SITE #4</u>

The four composite soil samples collected from Site #4 at depths of 0 to 2 feet were submitted for EP Toxic metals and TPH analyses. The results (see Table 4) showed that none of these parameters were detected, except for chromium which was detected at what can be considered a trace amount of 0.1 ppm.

### 5.0 CONCLUSIONS

Based on the information provided by PEPCO and the field sampling and analyses program conducted at the sites, the following conclusions can be reached:

- o Site #4 can be considered free of contamination and "environmentally clean" with respect to the parameters that were analyzed for.
- o TPH is present in the soils at Sites #1 and #2.
- o The actual extent of TPH presence and concentration is not known for Area 2 at Site #1. In the case of Site #2, TPH presence appears to be fairly well distributed across the site.

APPENDIX C

**Site History** 

# **Buzzard Point**

S Street SW/1st Street SW Washington, DC 20024

Inquiry Number: 3660997.5

July 10, 2013

# The EDR Aerial Photo Decade Package



# **EDR Aerial Photo Decade Package**

Environmental Data Resources, Inc. (EDR) Aerial Photo Decade Package is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's professional researchers provide digitally reproduced historical aerial photographs, and when available, provide one photo per decade.

When delivered electronically by EDR, the aerial photo images included with this report are for ONE TIME USE ONLY. Further reproduction of these aerial photo images is prohibited without permission from EDR. For more information contact your EDR Account Executive.

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

## **Disclaimer - Copyright and Trademark Notice**

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report AS IS. Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2013 by Environmental Data Resources, Inc., All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.


# **Date EDR Searched Historical Sources:**

Aerial Photography July 10, 2013


# **Target Property:**


S Street SW/1st Street SW Washington, DC 20024


<u>Year</u>	<u>Scale</u>	<u>Details</u>	<u>Source</u>
1944	Aerial Photograph. Scale: 1"=250'	Panel #: 38077-G1, Alexandria, VA;/Flight Date: August 13, 1944	EDR
1949	Aerial Photograph. Scale: 1"=500'	Panel #: 38077-G1, Alexandria, VA;/Flight Date: March 04, 1949	EDR
1951	Aerial Photograph. Scale: 1"=250'	Panel #: 38077-G1, Alexandria, VA;/Flight Date: July 05, 1951	EDR
1957	Aerial Photograph. Scale: 1"=500'	Panel #: 38077-G1, Alexandria, VA;/Flight Date: July 25, 1957	EDR
1963	Aerial Photograph. Scale: 1"=500'	Panel #: 38077-G1, Alexandria, VA;/Flight Date: October 15, 1963	EDR
1968	Aerial Photograph. Scale: 1"=500'	Panel #: 38077-G1, Alexandria, VA;/Flight Date: October 31, 1968	EDR
1970	Aerial Photograph. Scale: 1"=500'	Panel #: 38077-G1, Alexandria, VA;/Flight Date: September 01, 1970	EDR
1977	Aerial Photograph. Scale: 1"=1000'	Panel #: 38077-G1, Alexandria, VA;/Flight Date: March 16, 1977	EDR
1983	Aerial Photograph. Scale: 1"=150'	Panel #: 38077-G1, Alexandria, VA;/Flight Date: July 09, 1983	EDR
1988	Aerial Photograph. Scale: 1"=500'	Panel #: 38077-G1, Alexandria, VA;/DOQQ - acquisition dates: April 05, 1988	EDR
1994	Aerial Photograph. Scale: 1"=750'	Panel #: 38077-G1, Alexandria, VA;/Flight Date: March 17, 1994	EDR
1998	Aerial Photograph. Scale: 1"=750'	Panel #: 38077-G1, Alexandria, VA;/Flight Date: February 09, 1998	EDR
2000	Aerial Photograph. Scale: 1"=750'	Panel #: 38077-G1, Alexandria, VA;/Flight Date: March 24, 2000	EDR
2005	Aerial Photograph. Scale: 1"=500'	Panel #: 38077-G1, Alexandria, VA;/Flight Year: 2005	EDR
2007	Aerial Photograph. Scale: 1"=500'	Panel #: 38077-G1, Alexandria, VA;/Flight Year: 2007	EDR
2008	Aerial Photograph. Scale: 1"=500'	Panel #: 38077-G1, Alexandria, VA;/Flight Year: 2008	EDR
2009	Aerial Photograph. Scale: 1"=500'	Panel #: 38077-G1, Alexandria, VA;/Flight Year: 2009	EDR
2011	Aerial Photograph. Scale: 1"=500'	Panel #: 38077-G1, Alexandria, VA;/Flight Year: 2011	EDR
2012	Aerial Photograph. Scale: 1"=500'	Panel #: 38077-G1, Alexandria, VA;/Flight Year: 2012	EDR












































# **Buzzard Point**

S Street SW/1st Street SW Washington, DC 20024

Inquiry Number: 3660997.3

July 11, 2013

# **Certified Sanborn® Map Report**



# **Certified Sanborn® Map Report**

7/11/13

Site Name:

**Client Name:** 

Buzzard Point S Street SW/1st Street SW Washington, DC 20024 Haley & Aldrich, Inc. 465 Medford Street Boston, MA 02129

EDR Inquiry # 3660997.3 Contact: Kristen Wright-Ng



The complete Sanborn Library collection has been searched by EDR, and fire insurance maps covering the target property location provided by Haley & Aldrich, Inc. were identified for the years listed below. The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by Sanborn Library LLC, the copyright holder for the collection.

## Certified Sanborn Results:

Site Name: Buzzard Point

Address: S Street SW/1st Street SW City, State, Zip: Washington, DC 20024

**Cross Street:** 

P.O. # 40223-001

Project: Buzzard Point

Certification # 7209-40E4-9105

### **Maps Provided:**

1998	1984
1994	1977
1992	1959
1991	1928
1990	
1988	



Sanborn® Library search results Certification # 7209-40E4-9105

The Sanborn Library includes more than 1.2 million Sanborn fire insurance maps, which track historical property usage in approximately 12,000 American cities and towns. Collections searched:

Library of Congress

University Publications of America

✓ EDR Private Collection

The Sanborn Library LLC Since 1866™

#### **Limited Permission To Make Copies**

Haley & Aldrich, Inc. (the client) is permitted to make up to THREE photocopies of this Sanborn Map transmittal and each fire insurance map accompanying this report solely for the limited use of its customer. No one other than the client is authorized to make copies. Upon request made directly to an EDR Account Executive, the client may be permitted to make a limited number of additional photocopies. This permission is conditioned upon compliance by the client, its customer and their agents with EDR's copyright policy; a copy of which is available upon request.

### **Disclaimer - Copyright and Trademark notice**

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2013 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

## Sanborn Sheet Thumbnails

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.



## 1998 Source Sheets



Volume 2, Sheet 267



Volume 2, Sheet 268



Volume 2, Sheet 271

#### 1994 Source Sheets



Volume 2, Sheet 267



Volume 2, Sheet 268



Volume 2, Sheet 271

## 1992 Source Sheets



Volume 2, Sheet 267



Volume 2, Sheet 268



Volume 2, Sheet 271

## 1991 Source Sheets



Volume 2, Sheet 267



Volume 2, Sheet 268



Volume 2, Sheet 271

## 1990 Source Sheets



Volume 2, Sheet 267



Volume 2, Sheet 268



Volume 2, Sheet 271

#### 1988 Source Sheets



Volume 2, Sheet 262



Volume 2, Sheet 267



Volume 2, Sheet 268



Volume 2, Sheet 271

## 1984 Source Sheets




Volume 2, Sheet 267



Volume 2, Sheet 268



Volume 2, Sheet 271



Volume 2, Sheet 262



Volume 2, Sheet 267



Volume 2, Sheet 268

## 1959 Source Sheets






Volume 2, Sheet 267


Volume 2, Sheet 268








Volume 2, Sheet 267


Volume 2, Sheet 268


























## **Buzzard Point**

S Street SW/1st Street SW Washington, DC 20024

Inquiry Number: 3660997.3

July 11, 2013

# **Certified Sanborn® Map Report**



## **Certified Sanborn® Map Report**

7/11/13

Site Name:

**Client Name:** 

Buzzard Point S Street SW/1st Street SW Washington, DC 20024 Haley & Aldrich, Inc. 465 Medford Street Boston, MA 02129

EDR Inquiry # 3660997.3 Contact: Kristen Wright-Ng



The complete Sanborn Library collection has been searched by EDR, and fire insurance maps covering the target property location provided by Haley & Aldrich, Inc. were identified for the years listed below. The certified Sanborn Library search results in this report can be authenticated by visiting www.edrnet.com/sanborn and entering the certification number. Only Environmental Data Resources Inc. (EDR) is authorized to grant rights for commercial reproduction of maps by Sanborn Library LLC, the copyright holder for the collection.

#### Certified Sanborn Results:

Site Name: Buzzard Point

Address: S Street SW/1st Street SW City, State, Zip: Washington, DC 20024

**Cross Street:** 

P.O. # 40223-001

Project: Buzzard Point

Certification # 7209-40E4-9105

#### **Maps Provided:**

1998	1984
1994	1977
1992	1959
1991	1928
1990	
1988	



Sanborn® Library search results Certification # 7209-40E4-9105

The Sanborn Library includes more than 1.2 million Sanborn fire insurance maps, which track historical property usage in approximately 12,000 American cities and towns. Collections searched:

Library of Congress

✓ University Publications of America

▼ EDR Private Collection

The Sanborn Library LLC Since  $1866^{TM}$ 

#### **Limited Permission To Make Copies**

Haley & Aldrich, Inc. (the client) is permitted to make up to THREE photocopies of this Sanborn Map transmittal and each fire insurance map accompanying this report solely for the limited use of its customer. No one other than the client is authorized to make copies. Upon request made directly to an EDR Account Executive, the client may be permitted to make a limited number of additional photocopies. This permission is conditioned upon compliance by the client, its customer and their agents with EDR's copyright policy; a copy of which is available upon request.

#### **Disclaimer - Copyright and Trademark notice**

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2013 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

#### Sanborn Sheet Thumbnails

This Certified Sanborn Map Report is based upon the following Sanborn Fire Insurance map sheets.



#### 1998 Source Sheets



Volume 2, Sheet 267



Volume 2, Sheet 268



Volume 2, Sheet 271

#### 1994 Source Sheets



Volume 2, Sheet 267



Volume 2, Sheet 268



Volume 2, Sheet 271

#### 1992 Source Sheets



Volume 2, Sheet 267



Volume 2, Sheet 268



Volume 2, Sheet 271



Volume 2, Sheet 267



Volume 2, Sheet 268



Volume 2, Sheet 271

## 1990 Source Sheets



Volume 2, Sheet 267



Volume 2, Sheet 268



Volume 2, Sheet 271

#### 1988 Source Sheets



Volume 2, Sheet 271



Volume 2, Sheet 267



Volume 2, Sheet 268

#### 1984 Source Sheets



Volume 2, Sheet 267



Volume 2, Sheet 268



Volume 2, Sheet 271



Volume 2, Sheet 267



Volume 2, Sheet 268

## 1959 Source Sheets






Volume 2, Sheet 267


Volume 2, Sheet 268








Volume 2, Sheet 267


Volume 2, Sheet 268





















3660997 - 3 page 13



3660997 - 3 page 14

# 1928 Certified Sanborn Map POTOMP POTOMAC AV. S.W. ST. S. W. R ST. S. W. 661 Certification # 7209-40E4-9105 City, ST, ZIP: ington DC 20024 EDR Inquiry: Order Date: Certification # 3660997.3 7/11/2013 11:17:04 AM 7209-40E4-9105 This Certified Sanborn Map combines the following sheets. Outlined areas indicate map sheets within the collection. 330 0 Feet 165 660 Volume 2, Sheet 267 267 268 Volume 2, Sheet 268

3660997 - 3 page 15



## **Buzzard Point**

S Street SW/1st Street SW Washington, DC 20024

Inquiry Number: 3660997.4

July 10, 2013

# **EDR** Historical Topographic Map Report



## **EDR Historical Topographic Map Report**

Environmental Data Resources, Inc.s (EDR) Historical Topographic Map Report is designed to assist professionals in evaluating potential liability on a target property resulting from past activities. EDRs Historical Topographic Map Report includes a search of a collection of public and private color historical topographic maps, dating back to the early 1900s.

**Thank you for your business.**Please contact EDR at 1-800-352-0050 with any questions or comments.

#### **Disclaimer - Copyright and Trademark Notice**

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report AS IS. Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2013 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.





TARGET QUAD

NAME: WEST WASHINGTON

MAP YEAR: 1885

SERIES: 15 SCALE: 1:62500 SITE NAME: Buzzard Point


ADDRESS: S Street SW/1st Street SW

Washington, DC 20024

LAT/LONG: 38.8683 / -77.0121

CLIENT: Haley & Aldrich, Inc.
CONTACT: Kristen Wright-Ng
INQUIRY#: 3660997.4

RESEARCH DATE: 07/10/2013





TARGET QUAD

NAME: MOUNT VERNON

MAP YEAR: 1894

SERIES: 30

SCALE: 1:125000

SITE NAME: Buzzard Point

ADDRESS: S Street SW/1st Street SW

Washington, DC 20024

LAT/LONG: 38.8683 / -77.0121





TARGET QUAD

NAME: Washington And Vicinity 4

Of 4

MAP YEAR: 1947

SERIES: 7.5 SCALE: 1:31680 SITE NAME: Buzzard Point


ADDRESS: S Street SW/1st Street SW

Washington, DC 20024

LAT/LONG: 38.8683 / -77.0121

CLIENT: Haley & Aldrich, Inc.
CONTACT: Kristen Wright-Ng
INQUIRY#: 3660997.4

RESEARCH DATE: 07/10/2013





**TARGET QUAD** 

NAME: ALEXANDRIA


MAP YEAR: 1951

SERIES: 7.5 SCALE: 1:24000 SITE NAME: Buzzard Point

ADDRESS: S Street SW/1st Street SW

Washington, DC 20024

LAT/LONG: 38.8683 / -77.0121





TARGET QUAD

NAME: ALEXANDRIA


MAP YEAR: 1956

SERIES: 7.5 SCALE: 1:24000 SITE NAME: Buzzard Point

LAT/LONG:

ADDRESS: S Street SW/1st Street SW

Washington, DC 20024 38.8683 / -77.0121





TARGET QUAD

NAME: ALEXANDRIA


MAP YEAR: 1965

SERIES: 7.5 SCALE: 1:24000 SITE NAME: Buzzard Point

ADDRESS: S Street SW/1st Street SW

Washington, DC 20024

LAT/LONG: 38.8683 / -77.0121





TARGET QUAD

NAME: ALEXANDRIA

MAP YEAR: 1971

PHOTOREVISED FROM: 1965

SERIES: 7.5 SCALE: 1:24000 SITE NAME: Buzzard Point


ADDRESS: S Street SW/1st Street SW

Washington, DC 20024

LAT/LONG: 38.8683 / -77.0121

CLIENT: Haley & Aldrich, Inc. CONTACT: Kristen Wright-Ng

INQUIRY#: 3660997.4 RESEARCH DATE: 07/10/2013





**TARGET QUAD** 

NAME: ALEXANDRIA

MAP YEAR: 1972

PHOTOINSPECTED FROM: 1965

SERIES: 7.5 SCALE: 1:24000 SITE NAME: Buzzard Point


ADDRESS: S Street SW/1st Street SW

Washington, DC 20024

LAT/LONG: 38.8683 / -77.0121

CLIENT: Haley & Aldrich, Inc.
CONTACT: Kristen Wright-Ng
INQUIRY#: 3660997.4

RESEARCH DATE: 07/10/2013





TARGET QUAD

NAME: ALEXANDRIA

MAP YEAR: 1983

PHOTOREVISED FROM: 1965

SERIES: 7.5 SCALE: 1:24000 SITE NAME: Buzzard Point


ADDRESS: S Street SW/1st Street SW

Washington, DC 20024

LAT/LONG: 38.8683 / -77.0121

CLIENT: Haley & Aldrich, Inc. CONTACT: Kristen Wright-Ng

INQUIRY#: 3660997.4 RESEARCH DATE: 07/10/2013





TARGET QUAD

NAME: ALEXANDRIA

MAP YEAR: 1994

SERIES: 7.5 SCALE: 1:24000 SITE NAME: Buzzard Point


ADDRESS: S Street SW/1st Street SW

Washington, DC 20024

LAT/LONG: 38.8683 / -77.0121

CLIENT: Haley & Aldrich, Inc.
CONTACT: Kristen Wright-Ng
INQUIRY#: 3660997.4

RESEARCH DATE: 07/10/2013





TARGET QUAD

NAME: ALEXANDRIA

MAP YEAR: 1994

SERIES: 15 SCALE: 1:50000 SITE NAME: Buzzard Point

ADDRESS: S Street SW/1st Street SW

Washington, DC 20024

LAT/LONG: 38.8683 / -77.0121

CLIENT: Haley & Aldrich, Inc.
CONTACT: Kristen Wright-Ng
INQUIRY#: 3660997.4

RESEARCH DATE: 07/10/2013

### **Buzzard Point**

S Street SW/1st Street SW Washington, DC 20024

Inquiry Number: 3660997.6

July 10, 2013

# **The EDR-City Directory Abstract**



#### **TABLE OF CONTENTS**

#### **SECTION**

**Executive Summary** 

**Findings** 

**City Directory Images** 

**Thank you for your business.**Please contact EDR at 1-800-352-0050 with any questions or comments.

#### **Disclaimer - Copyright and Trademark Notice**

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING. WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction orforecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2013 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc. or its affiliates is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

#### **EXECUTIVE SUMMARY**

### **DESCRIPTION**

Environmental Data Resources, Inc.'s (EDR) City Directory Abstract is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's City Directory Abstract includes a search and abstract of available city directory data. For each address, the directory lists the name of the corresponding occupant at five year intervals.

Business directories including city, cross reference and telephone directories were reviewed, if available, at approximately five year intervals for the years spanning 1922 through 2012. This report compiles information gathered in this review by geocoding the latitude and longitude of properties identified and gathering information about properties within 660 feet of the target property.

A summary of the information obtained is provided in the text of this report.

#### **RESEARCH SUMMARY**

The following research sources were consulted in the preparation of this report. An "X" indicates where information was identified in the source and provided in this report.

<u>Year</u>	Source	<u>TP</u>	<u>Adjoining</u>	Text Abstract	Source Image
2012	Cole Information Services	-	X	X	-
	Cole Information Services	Χ	X	X	-
2007	Cole Information Services	-	X	X	-
	Cole Information Services	Χ	X	X	-
2006	Haines Company, Inc.	-	X	X	-
	Haines Company, Inc.	Χ	X	X	-
2000	Haines & Company	-	X	X	-
1993	The Chesapeake and Potomac Telephone Company of Virginia	-	X	X	-
1983	The Chesapeake Potomac Telephone Co	-	X	X	-
1978	C&P Telephone	-	X	X	-
1973	The Chesapeake Potomac Telephone Co	-	X	X	-
1969	C&P Telephone	-	X	X	-
	C&P Telephone	Χ	X	X	-
1964	R. L. Polk & Co.	-	X	X	-
	R. L. Polk & Co.	Χ	X	X	-
1960	R. L. Polk & Co.	-	X	X	-
1954	R. L. Polk & Co.	-	X	X	-
1948	R. L. Polk & Co.	-	X	X	-
	R. L. Polk & Co.	Χ	X	X	-
1943	R. L. Polk & Co.	-	X	X	-
1940	R. L. Polk & Co.	-	X	X	-
1936	R. L. Polk & Co.	-	X	X	-
1931	R. L. Polk & Co.	-	X	X	-
1926	R. L. Polk & Co.	-	X	Χ	-

# **EXECUTIVE SUMMARY**

<u>Year</u>	<u>Source</u>	<u>TP</u>	<u>Adjoining</u>	Text Abstract	Source Image
1922	R. L. Polk & Co.	_	X	Χ	_

# **EXECUTIVE SUMMARY**

### **SELECTED ADDRESSES**

The following addresses were selected by the client, for EDR to research. An "X" indicates where information was identified.

<u>Address</u>	<u>Type</u>	<u>Findings</u>
1711 1st Street SW	Client Entered	X
1714 2nd Street SW	Client Entered	X
1930 1st Street SW	Client Entered	

### TARGET PROPERTY INFORMATION

### **ADDRESS**

S Street SW/1st Street SW Washington, DC 20024

### **FINDINGS DETAIL**

Target Property research detail.

### 1ST ST SW

#### 1711 1ST ST SW

<u>Year</u>	<u>Uses</u>	<u>Source</u>
2012	SUPER SALVAGE INC	Cole Information Services
2007	SUPER SALVAGE INC	Cole Information Services
2006	SUPER SALVAGE	Haines Company, Inc.
	SUPERSALVAGE	Haines Company, Inc.
1964	Buzzard Point Boat Yd	R. L. Polk & Co.
	Super Salvage Inc	R. L. Polk & Co.

#### 1714 1ST ST SW

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1948	Crockett Yuria	R. L. Polk & Co.

### 1st Street SW

### 1711 1st Street SW

<u>Year</u>	<u>Uses</u>	<u>Source</u>
2006	SUPER SALVAGE	Haines Company, Inc.
	SUPERSALVAGE	Haines Company, Inc.
1964	Buzzard Point Boat Yd	R. L. Polk & Co.
	Super Salvage Inc	R. L. Polk & Co.

### 1930 1st Street SW

<u>Year</u> <u>Uses</u> <u>Source</u>

# 2ND SW

#### 1714 2ND SW

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1969	WASHINGTON DELIVERIES INC	C&P Telephone

### **2ND ST SW**

### 1714 2ND ST SW

<u>Year</u>	<u>Uses</u>	<u>Source</u>
2006	ENRIQUEC LYON	Haines Company, Inc.
1964	Anacostia River	R. L. Polk & Co.
	Corinthian Yacht Club club hse	R. L. Polk & Co.
	Corinthian Yacht Club stewart hse	R. L. Polk & Co.
	Credit Union	R. L. Polk & Co.
	Stoll Louis J	R. L. Polk & Co.
	Washn Del Inc	R. L. Polk & Co.

# 2nd Street SW

### 1714 2nd Street SW

<u>Year</u>	<u>Uses</u>	<u>Source</u>
2006	ENRIQUEC LYON	Haines Company, Inc.
1969	WASHINGTON DELIVERIES INC	C&P Telephone
1964	Anacostia River	R. L. Polk & Co.
	Corinthian Yacht Club club hse	R. L. Polk & Co.
	Corinthian Yacht Club stewart hse	R. L. Polk & Co.
	Credit Union	R. L. Polk & Co.
	Stoll Louis J	R. L. Polk & Co.
	Washn Del Inc	R. L. Polk & Co.
	2006 1969	2006 ENRIQUEC LYON  1969 WASHINGTON DELIVERIES INC  1964 Anacostia River  Corinthian Yacht Club club hse  Corinthian Yacht Club stewart hse  Credit Union  Stoll Louis J

### **ADJOINING PROPERTY DETAIL**

The following Adjoining Property addresses were researched for this report. Detailed findings are provided for each address.

### 1 STH 2 SW

#### 1912 1 STH 2 SW

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1993	MOAYEDI Roxanna	The Chesapeake and Potomac Telephone Company of Virginia

### <u>1ST_SW</u>

#### 1805 1ST SW

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1943	1ST SW Contd	R. L. Polk & Co.
	Taylor Mary Mrs	R. L. Polk & Co.
1931	Taylor Jesse	R. L. Polk & Co.
1926	Taylor Jessie	R. L. Polk & Co.
1922	Taylor Jesse	R. L. Polk & Co.

#### 1817 1ST SW

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1931	Dungan Robt L	R. L. Polk & Co.
1926	Penn Wm	R. L. Polk & Co.
1922	Fenwick Geo D	R. L. Polk & Co.

#### 1821 1ST SW

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1943	Vacant	R. L. Polk & Co.
	cor Corinthian Yacht Club	R. L. Polk & Co.
	Anacostia River	R. L. Polk & Co.
	Unopened to Xenia	R. L. Polk & Co.
1931	Jackson Fannie Mrs	R. L. Polk & Co.
	1ST SW Contd	R. L. Polk & Co.
1926	Jackson Fannie Mrs	R. L. Polk & Co.
1922	Anderson Carl L	R. L. Polk & Co.

### 1901 1ST SW

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1926	Brown Lee	R. L. Polk & Co.

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1922	Kerns Lee coal	R. L. Polk & Co.

### 1927 1ST SW

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1931	Vacant	R. L. Polk & Co.
1926	Buchannan Clarence	R. L. Polk & Co.
1922	Vacant	R. L. Polk & Co.

### 1929 1ST SW

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1931	Vacant	R. L. Polk & Co.
1926	Nelson Wm	R. L. Polk & Co.
1922	Nelson Wm	R. L. Polk & Co.

### 1931 1ST SW

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1931	Vacant	R. L. Polk & Co.
1926	Brown Nettie	R. L. Polk & Co.
1922	Brown Percy	R. L. Polk & Co.

### 1ST ST SW

### 1648 1ST ST SW

<u>Year</u>	<u>Uses</u>	<u>Source</u>
2006	M & J CARRYOUT	Haines Company, Inc.

#### 1700 1ST ST SW

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1948	Wilkerson Louise Mrs	R. L. Polk & Co.

#### 1702 1ST ST SW

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1948	Washington Rose	R. L. Polk & Co.

### 1704 1ST ST SW

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1948	Johns Adorpus	R. L. Polk & Co.

#### 1706 1ST ST SW

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1948	Greene Geo	R. L. Polk & Co.

1716 1ST ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Gay Marvin R. L. Polk & Co.

1717 1ST ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Milton Jas R. L. Polk & Co.

1718 1ST ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Bradshaw Raymond R. L. Polk & Co.

1720 1ST ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Smith Jas T R. L. Polk & Co.

1722 1ST ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Jackson Anna Mrs R. L. Polk & Co.

1724 1ST ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Ware Isaac R. L. Polk & Co.

1725 1ST ST SW

Year Uses Source

1948 Southwest Nursery R. L. Polk & Co.

1726 1ST ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Davis Freeman R. L. Polk & Co.

1728 1ST ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Stephens Alphonso R. L. Polk & Co.

1730 1ST ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Brooks Willie R. L. Polk & Co.

1732 1ST ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Shann Prince A R. L. Polk & Co.

1734 1ST ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Hall Jos A R. L. Polk & Co.

1736 1ST ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Lindes Bennie E R. L. Polk & Co.

1738 1ST ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Bonner Edgar R. L. Polk & Co.

1740 1ST ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Lomax Melisia R. L. Polk & Co.

1742 1ST ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Martin Leonldas R. L. Polk & Co.

1800 1ST ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Wilson Otto C R. L. Polk & Co.

1802 1ST ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Amedeo Earl R. L. Polk & Co.

1804 1ST ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Simms Geo R. L. Polk & Co.

1805 1ST ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1940 Taylor Jesse1936 Taylor JesseR. L. Polk & Co.R. L. Polk & Co.

1806 1ST ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Humphrey Virginia R. L. Polk & Co.

#### 1810 1ST ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Joyner Joe R. L. Polk & Co.

1812 1ST ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Penn Wm R. L. Polk & Co.

1814 1ST ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Hamilton Wm R. L. Polk & Co.

1816 1ST ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Blair Horace R. L. Polk & Co.

1817 1ST ST SW

YearUsesSource1948Rollins GeoR. L. Polk & Co.1940Spaulding EdwR. L. Polk & Co.1936Bidwell John PR. L. Polk & Co.

Dale Alf C R. L. Polk & Co.

1818 1ST ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Albert Emizie R. L. Polk & Co.

1820 1ST ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Jackson Willie R. L. Polk & Co.

1821 1ST ST SW

<u>Year</u> <u>Uses</u> **Source** 1948 R. L. Polk & Co. Fines Thos 1940 R. L. Polk & Co. Simmonds Harold A R. L. Polk & Co. Anacostia River cor Corinthian Yacht Club R. L. Polk & Co. R. L. Polk & Co. Jackson Fannie Mrs R. L. Polk & Co. Unopened to Xenia R. L. Polk & Co. 1936 Jackson Fannie H Mrs

1822 1ST ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Woodland Bruce R. L. Polk & Co.

1824 1ST ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Holmes Arline R. L. Polk & Co.

1825 1ST ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1993 POWER Richard atty The Chesapeake and Potomac Telephone

Company of Virginia

1948 Thomas Maurice R. L. Polk & Co.

1826 1ST ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Watts Clarence R. L. Polk & Co.

1828 1ST ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Guin Arth R. L. Polk & Co.

1830 1ST ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Porter Chas R. L. Polk & Co.

1832 1ST ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Dority Henry R. L. Polk & Co.

1834 1ST ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Harley Jesse L R. L. Polk & Co.

1836 1ST ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Kellogg Harold R. L. Polk & Co.

1838 1ST ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Cephas Robt J R. L. Polk & Co.

1840 1ST ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Brown Henry R. L. Polk & Co.

1842 1ST ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Jefferson Edw R. L. Polk & Co.

1844 1ST ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Thomas Bennie R. L. Polk & Co.

1846 1ST ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Richardson Louise R. L. Polk & Co.

1848 1ST ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Stafford Tommie R. L. Polk & Co.

1850 1ST ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Anacostia River R. L. Polk & Co.

Unopened to Xenia R. L. Polk & Co.

1901 1ST ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1936 Kerns Lee E R. L. Polk & Co.

1927 1ST ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1936 Vacant R. L. Polk & Co.

1929 1ST ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1936 Vacant R. L. Polk & Co.

1931 1ST ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1936 Lewis Jas R R. L. Polk & Co.

### 1ST/POTOMAC AV

#### 1ST/POTOMAC AV

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1964	1ST/POTOMAC AV	R. L. Polk & Co.
1954	1ST/POTOMAC AV	R. L. Polk & Co.

# 1ST/R

### 1ST/R

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1964	1ST/R	R. L. Polk & Co.
	1ST/R	R. L. Polk & Co.
	1ST/R	R. L. Polk & Co.
1954	1ST/R	R. L. Polk & Co.
	1ST/R	R. L. Polk & Co.
	1ST/R	R. L. Polk & Co.
1948	1ST/R	R. L. Polk & Co.
	1ST/R	R. L. Polk & Co.
	1ST/R	R. L. Polk & Co.

### 1ST/S

### 1ST/S

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1964	1ST/S	R. L. Polk & Co.
	1ST/S	R. L. Polk & Co.
1954	1ST/S	R. L. Polk & Co.
	1ST/S	R. L. Polk & Co.
	1ST/S	R. L. Polk & Co.
1948	1ST/S	R. L. Polk & Co.
	1ST/S	R. L. Polk & Co.

### <u>1ST/T</u>

### 1ST/T

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1964	1ST/T	R. L. Polk & Co.
	1ST/T	R. L. Polk & Co.
1954	1ST/T	R. L. Polk & Co.
	1ST/T	R. L. Polk & Co.

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 1ST/T R. L. Polk & Co.
1ST/T R. L. Polk & Co.

2ND SW

1900 2ND SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1922 Ford Wm R. L. Polk & Co.

1904 2ND SW

<u>Year</u> <u>Uses</u> <u>Source</u>

 1931
 Anacostia River
 R. L. Polk & Co.

 Ford Wm
 R. L. Polk & Co.

 1926
 Ford Wm
 R. L. Polk & Co.

1912 2ND SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1926 Swan Robt R. L. Polk & Co.
 1922 Swann Robt S express R. L. Polk & Co.

**2ND ST SW** 

1905 2ND ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1993 Becon Services Corp The Chesapeake and Potomac Telephone

Company of Virginia

2ND/R

2ND/R

 Year
 Uses
 Source

 1964
 2ND/R
 R. L. Polk & Co.

 2ND/R
 R. L. Polk & Co.

2ND/R R. L. Polk & Co.
2ND/R R. L. Polk & Co.

2ND/S

1954

2ND/S

<u>Year</u> <u>Uses</u> <u>Source</u>

1964 2ND/S R. L. Polk & Co.

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1964	2ND/S	R. L. Polk & Co.
	2ND/S	R. L. Polk & Co.
1954	2ND/S	R. L. Polk & Co.
	2ND/S	R. L. Polk & Co.
	2ND/S	R. L. Polk & Co.
1948	2ND/S	R. L. Polk & Co.

### 2ND/T

### 2ND/T

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1964	2ND/T	R. L. Polk & Co.
	2ND/T	R. L. Polk & Co.
	2ND/T	R. L. Polk & Co.
1954	2ND/T	R. L. Polk & Co.
	2ND/T	R. L. Polk & Co.
	2ND/T	R. L. Polk & Co.
1948	2ND/T	R. L. Polk & Co.
	2ND/T	R. L. Polk & Co.

# HALF SW

### 1701 HALF SW

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1931	Norris Geo A	R. L. Polk & Co.
1926	Dungan Robt	R. L. Polk & Co.
1922	Dungan Wm G	R. L. Polk & Co.

### 1702 HALF SW

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1926	Fisher Wm R	R. L. Polk & Co.
1922	Penn W F	R. L. Polk & Co.

#### **1704 HALF SW**

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1926	Clarke Chas	R. L. Polk & Co.
1922	Clark Chas L	R. L. Polk & Co.

#### **1800 HALF SW**

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1943	Mc Crory Fannie L Mrs	R. L. Polk & Co.
1931	Shaw Walter	R. L. Polk & Co.
1926	Vacant	R. L. Polk & Co.
1922	Kolker A F gro	R. L. Polk & Co.

### **1802 HALF SW**

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1943	Howard Ella C Mrs	R. L. Polk & Co.
1931	Hall Eug	R. L. Polk & Co.
1926	Hall Eug	R. L. Polk & Co.
1922	Hall Eugene	R. L. Polk & Co.

#### 1804 HALF SW

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1973	JAKE SNIDER SIGN CO	The Chesapeake Potomac Telephone Co
	SNIDER JAKE SIGN CO	The Chesapeake Potomac Telephone Co
	POTOMAC Potomac Neon Sign Co	The Chesapeake Potomac Telephone Co
1969	POTOMAC Potomac Neon Sign Co	C&P Telephone
	JAKE SNIDER SIGN CO	C&P Telephone

#### **1806 HALF SW**

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1931	Vacant	R. L. Polk & Co.
1926	Nelson Dennis	R. L. Polk & Co.
1922	Nelson Dennis	R. L. Polk & Co.

### **1808 HALF SW**

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1931	Griggs Harry	R. L. Polk & Co.
1926	Glascoe Annie Mrs	R. L. Polk & Co.
1922	Mason Richd	R. L. Polk & Co.

### 1810 HALF SW

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1931	Jackson Walter	R. L. Polk & Co.
1926	Carter Jos	R. L. Polk & Co.
1922	Hackley Bettie Mrs	R. L. Polk & Co.

#### **1812 HALF SW**

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1973	UNITED EXPOSITION SERVICE CO	The Chesapeake Potomac Telephone Co
1969	UNITED CONVENTION SERVICE CO	C&P Telephone

### **1816 HALF SW**

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1973	GOLDEN Golden R Services	The Chesapeake Potomac Telephone Co
	MARJACK COMPANY INC THE	The Chesapeake Potomac Telephone Co
1969	ZEP MANUFACTURING CO	C&P Telephone

### **1820 HALF SW**

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1969	MARJACK COMPANew York INC THE	C&P Telephone
1931	Shorter John	R. L. Polk & Co.
1926	Cook Geo H	R. L. Polk & Co.
1922	Cook Geo H	R. L. Polk & Co.

### **1821 HALF SW**

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1943	Vacant	R. L. Polk & Co.
	Continues as Water	R. L. Polk & Co.
1931	Brown Louise	R. L. Polk & Co.
1926	Vacant	R. L. Polk & Co.
1922	Strother Annie Mrs	R. L. Polk & Co.

### **1822 HALF SW**

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1931	Vacant	R. L. Polk & Co.
1926	Hager Raymond	R. L. Polk & Co.
1922	Hager Raymond	R. L. Polk & Co.

### **1823 HALF SW**

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1931	Brown Saml	R. L. Polk & Co.
1926	Holter Carroll	R. L. Polk & Co.

#### **1824 HALF SW**

<u>Year</u>	<u>Uses</u>	Source
1983	Harrison Textile Co	The Chesapeake Potomac Telephone Co
1978	HARRISON Harrison Textile Co	C&P Telephone

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1973	HARRISON Harrison Textile Co	The Chesapeake Potomac Telephone Co
1969	MULTRONICS Mulvey Jas A auto parts	C&P Telephone
	MULTRONICS Mulvey Frank J auto parts	C&P Telephone
	MULTRONICS Mulvey Wm A atty	C&P Telephone
	NATIONAL AUTO SERVICE CO INC	C&P Telephone
	HARRISON Harrison Textile Co	C&P Telephone

### 1825 HALF SW

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1931	Agnew John H	R. L. Polk & Co.
1926	Small Carrie Mrs	R. L. Polk & Co.
1922	Jackson Julia Mrs	R. L. Polk & Co.

### 1900 HALF SW

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1926	Williams Geo	R. L. Polk & Co.

#### **1901 HALF SW**

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1931	Vacant	R. L. Polk & Co.
1922	Williams Geo coal	R. L. Polk & Co.

### 1916 HALF SW

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1922	Fugitt Isaac	R. L. Polk & Co.

### 1919 HALF SW

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1931	Continues as Water	R. L. Polk & Co.
	Fugett Isaac	R. L. Polk & Co.
1926	Fugett Isaac	R. L. Polk & Co.
	Williams Geo	R. L. Polk & Co.

# **HALF ST SW**

### 1800 HALF ST SW

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1940	Vacant	R. L. Polk & Co.
1936	Vacant	R. L. Polk & Co.

#### 1802 HALF ST SW

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1940	Vacant	R. L. Polk & Co.
	Vacant	R. L. Polk & Co.
1936	Broome Mamie Mrs nurse	R. L. Polk & Co.
	Mitchell Izie	R. L. Polk & Co.
	Brown Mabel J Mrs	R. L. Polk & Co.

#### 1804 HALF ST SW

<u>Year</u>	<u>Uses</u>	<u>Source</u>
2012	MASHACK FREDERICK IRON WORKS	Cole Information Services
2007	MASHACK FREDERICK IRON WORKS	Cole Information Services
2006	FREDERICK H	Haines Company, Inc.
	MASHACK	Haines Company, Inc.

#### **1812 HALF ST SW**

<u>Year</u>	<u>Uses</u>	<u>Source</u>
2012	ALTA BICYCLE SHARE	Cole Information Services

### 1816 HALF ST SW

<u> Year</u>	<u>Uses</u>	<u>Source</u>
2006	THE CRUCIBLE	Haines Company Inc.

#### 1821 HALF ST SW

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1940	Thomas Geo	R. L. Polk & Co.
	Continues as Water	R. L. Polk & Co.
1936	Continues as Water	R. L. Polk & Co.
	Davis Horace	R. L. Polk & Co.

### 1824 HALF ST SW

<u>Year</u>	<u>Uses</u>	<u>Source</u>
2012	LOCKSMITH	Cole Information Services
	ZIEGFIELDS & SECRETS	Cole Information Services
	EMERGENCY LOCKSMITH 24 HOUR	Cole Information Services
2006	LIMECLUB	Haines Company, Inc.

#### 1900 HALF ST SW

<u>Year</u>	<u>Uses</u>	<u>Source</u>
2012	ATRIUM CAFE	Cole Information Services
	ANDERSON LOCKSMITH SERVICE	Cole Information Services

<u>Year</u>	<u>Uses</u>	<u>Source</u>
2012	LOCKSMITH SERVICE	Cole Information Services
	ATRIUM CAFE	Cole Information Services
	ANDERSON LOCKSMITH SERVICE	Cole Information Services
	LOCKSMITH SERVICE	Cole Information Services
	ATRIUM CAFE	Cole Information Services
	ANDERSON LOCKSMITH SERVICE	Cole Information Services
	LOCKSMITH SERVICE	Cole Information Services
2006	CONSTR CORP	Haines Company, Inc.
	JAMES G DAVIS	Haines Company, Inc.
	JEMALS RIVERSIDE	Haines Company, Inc.
	SES CORP	Haines Company, Inc.

### POTOMAC/1ST

#### POTOMAC/1ST

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1964	POTOMAC/1ST	R. L. Polk & Co.
1960	POTOMAC/1ST	R. L. Polk & Co.

### R SW

### 101 R SW

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1973	KOSSOW Koustenis Bill & Co Inc prod	The Chesapeake Potomac Telephone Co
	KOSSOW Koustenis Produce Co Inc	The Chesapeake Potomac Telephone Co
1969	KOSSOW Koustenis Bill & Co Inc prod	C&P Telephone
	KOSSOW Koustenis Produce Co Inc	C&P Telephone

### 107 R SW

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1969	HARTMAN Hartman Bros Inc food	C&P Telephone

### 115 R SW

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1973	CENTER MARKET PROVISION CO INC	The Chesapeake Potomac Telephone Co
1969	CENTER MARKET PROVISION CO INC	C&P Telephone

### 133 R SW

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1969	DAIRYLAND FOODS INC	C&P Telephone

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1969	RELIANCE Remco Sales	C&P Telephone

### 135 R SW

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1973	ROLAND FOODS INC meats	The Chesapeake Potomac Telephone Co
	GLASS Glass Roland foods	The Chesapeake Potomac Telephone Co
1969	GLASS Glass Roland foods	C&P Telephone
	ROLAND FOODS mts	C&P Telephone

### 137 R SW

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1969	GRAND Grande Valley Products Inc	C&P Telephone

# R ST SW

#### 101 R ST SW

<u>Year</u>	<u>Uses</u>	<u>Source</u>
2012	SHIN SUNG SOUVENIR COMPANY WHOLESALE	Cole Information Services
2007	SHIN SUNG SOUVENIR CO	Cole Information Services
2006	TRADING COMPANY	Haines Company, Inc.
	SHINSUNG	Haines Company, Inc.
2000	SHIN SUNG SOUVENIRS	Haines & Company
1993	Shin Sung Trading Company I	The Chesapeake and Potomac Telephone Company of Virginia
1964	Koustenis Bill & Co Inc hotel sups	R. L. Polk & Co.

### 107 R ST SW

<u>Year</u>	<u>Uses</u>	Source
2000	No Current Listing	Haines & Company
1993	Willson H Colby Jr	The Chesapeake and Potomac Telephone Company of Virginia
1978	HARTMAN Hartman Foods Inc	C&P Telephone
1973	HARTMAN BROS INC	The Chesapeake Potomac Telephone Co
	Hartman Foods Inc	The Chesapeake Potomac Telephone Co

### 111 R ST SW

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1960	111 17 Under construction	R. L. Polk & Co.

#### 115 R ST SW

<u>Year</u>	<u>Uses</u>	<u>Source</u>
2012	GEORGETOWN FLOOR COVERING	Cole Information Services
	ALWAYS AFFECTIVE AVAILABLE EMERGENCY	Cole Information Services
2007	CENTER MARKET PROVISION CO INC	Cole Information Services
2006	CENTER MARKET	Haines Company, Inc.
	PROVISION CO INC	Haines Company, Inc.
2000	CENTER MARKET PROVISION CO	Haines & Company
1993	Center Market Provision Co Inc	The Chesapeake and Potomac Telephone Company of Virginia
1983	Center Market Provision Co Inc	The Chesapeake Potomac Telephone Co
1978	CENTER Center Market Provision Co Inc	C&P Telephone
1964	Tex Beef & Provision Co whol	R. L. Polk & Co.

### 117 R ST SW

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1960	111 17 Under construction	R. L. Polk & Co.

#### 123 R ST SW

<u>Year</u>	<u>Uses</u>	<u>Source</u>
2012	MULTI LOCKSMITH	Cole Information Services

### 131 R ST SW

<u>Year</u>	<u>Uses</u>	<u>Source</u>
2007	CENTURY 21	Cole Information Services
2006	CONTRACTORS INC	Haines Company, Inc.
	ITALO	Haines Company, Inc.
2000	ALL METROPOLITAN AREA SERVICES	Haines & Company
	MADIGAN William	Haines & Company
1983	VIENNA BEEF MANUFACTURING CO regional sales ofc	The Chesapeake Potomac Telephone Co
1964	June Dairy Products Co Inc whol	R. L. Polk & Co.
1960	Under construction	R. L. Polk & Co.

### 133 R ST SW

<u>Year</u>	<u>Uses</u>	<u>Source</u>
2000	No Current Listing	Haines & Company
1964	Dairyland Foods Inc whol	R. L. Polk & Co.
1960	Dairyland Foods Inc whol	R. L. Polk & Co.

#### 135 R ST SW

<u>Year</u>	<u>Uses</u>	<u>Source</u>
2007	LYON BAKERY INC	Cole Information Services
2006	LYON BAKERY INC	Haines Company, Inc.
2000	No Current Listing	Haines & Company
1993	Badge Mate	The Chesapeake and Potomac Telephone Company of Virginia
1983	ROLAND FOODS INC meats	The Chesapeake Potomac Telephone Co
	Glass Roland foods	The Chesapeake Potomac Telephone Co
1978	GLASS Glass Roland foods	C&P Telephone
	ROLAND FOODS INC meats	C&P Telephone
1964	Roland Foods Inc	R. L. Polk & Co.
1960	Furr Bros Poultry Co Inc whol	R. L. Polk & Co.

#### 137 R ST SW

<u>Year</u>	<u>Uses</u>	<u>Source</u>
2006	LEOTERRA LLC	Haines Company, Inc.
1964	Grande Valley Products Inc dairy products whol	R. L. Polk & Co.
1960	Grande Valley Products Inc dairy products whol	R. L. Polk & Co.

### R/HALF

### R/HALF

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1964	R/HALF	R. L. Polk & Co.
1960	R/HALF	R. L. Polk & Co.

# S ST SW

### 100 S ST SW

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1948	Stephens Alice	R. L. Polk & Co.

### 102 S ST SW

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1948	Williams Clarence	R. L. Polk & Co.

### 103 S ST SW

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1993	KONATE Alassane	The Chesapeake and Potomac Telephone Company of Virginia

#### 104 S ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Wells Shelton R. L. Polk & Co.

105 S ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Bldg NCHA ofe R. L. Polk & Co.

Syphax Communtty R. L. Polk & Co.

106 S ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Phillips Oscar R. L. Polk & Co.

108 S ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Henderson Chas R. L. Polk & Co.

110 S ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Witlserall Hattle R. L. Polk & Co.

112 S ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Williamison John R. L. Polk & Co.

114 S ST SW

<u>Year Uses</u> <u>Source</u>

1948 Adams Leonard R. L. Polk & Co.

116 S ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Woodard Jos R. L. Polk & Co.

117 S ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Butler Calvin R. L. Polk & Co.

118 S ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Smith Johnnie W R. L. Polk & Co.

#### 119 S ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Fortune Amos R. L. Polk & Co.

121 S ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Conley Robt R. L. Polk & Co.

123 S ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Vacant R. L. Polk & Co.

125 S ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Nelson Jos R. L. Polk & Co.

**36 S ST SW** 

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Cunningham Jas W R. L. Polk & Co.

**38 S ST SW** 

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Ruchard Charile R. L. Polk & Co.

40 S ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Holmes Clifford R. L. Polk & Co.

41 S ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Briscoe Lewis R. L. Polk & Co.

**42 S ST SW** 

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Logan Christine R. L. Polk & Co.

43 S ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Evans Samil R. L. Polk & Co.

**44 S ST SW** 

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Lester Walter R. L. Polk & Co.

45 S ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Harley Raymond R. L. Polk & Co.

**46 S ST SW** 

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Dunston Mary R. L. Polk & Co.

47 S ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Gilmore Andrew R. L. Polk & Co.

48 S ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Hall Bernard A R. L. Polk & Co.

49 S ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Bennette Harry R. L. Polk & Co.

**50 S ST SW** 

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Thomas Lee R. L. Polk & Co.

**51 S ST SW** 

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Danner Marv Mrs R. L. Polk & Co.

**52 S ST SW** 

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Biggers Will R. L. Polk & Co.

**53 S ST SW** 

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Weaver Aileen R. L. Polk & Co.

54 S ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Hood Olyus R. L. Polk & Co.

55 S ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Jackson Wm R. L. Polk & Co.

**56 S ST SW** 

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Reid Clarence R. L. Polk & Co.

**57 S ST SW** 

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Comedy Paul R. L. Polk & Co.

**58 S ST SW** 

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Sanford Willie R. L. Polk & Co.

**59 S ST SW** 

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Hakett Louise Mrs R. L. Polk & Co.

60 S ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Robertson Azalie Mr R. L. Polk & Co.

**61 S ST SW** 

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Plummer Clara R. L. Polk & Co.

**62 S ST SW** 

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Grant Helen W R. L. Polk & Co.

**63 S ST SW** 

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Bells Hope R. L. Polk & Co.

**64 S ST SW** 

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Addison Wm R. L. Polk & Co.

65 S ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Turner Edw R. L. Polk & Co.

**66 S ST SW** 

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Yarber Marvin R. L. Polk & Co.

**67 S ST SW** 

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Holmes Ruby Mrs R. L. Polk & Co.

**68 S ST SW** 

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Cooper John R. L. Polk & Co.

**69 S ST SW** 

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Allen Margueritta R. L. Polk & Co.

70 S ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Pliefer Vernon R. L. Polk & Co.

71 S ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Washington Ernest R. L. Polk & Co.

**72 S ST SW** 

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Overton Herman R. L. Polk & Co.

**73 S ST SW** 

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Peppers Ellison V R. L. Polk & Co.

**74 S ST SW** 

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Hollis Wm R. L. Polk & Co.

**75 S ST SW** 

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Taylor Wody R. L. Polk & Co.

76 S ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Dixon Darius R. L. Polk & Co.

78 S ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Jenkins Perry R. L. Polk & Co.

80 S ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Wilson Pearl R. L. Polk & Co.

82 S ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Anderson Robt R. L. Polk & Co.

**84 S ST SW** 

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Smith Annie R. L. Polk & Co.

86 S ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Hawkins Thos R. L. Polk & Co.

88 S ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Payne Adelaide F Mrs R. L. Polk & Co.

90 S ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Craven Ernest R. L. Polk & Co.

92 S ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Crawford Margt R. L. Polk & Co.

94 S ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Davis Pierce R. L. Polk & Co.

96 S ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Cole Aura R. L. Polk & Co.

98 S ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Wells Thos R. L. Polk & Co.

# S/HALF

#### S/HALF

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1964	S/HALF	R. L. Polk & Co.
1960	S/HALF	R. L. Polk & Co.
1948	S/HALF	R. L. Polk & Co.

# T SW

## 135 T SW

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1926	T STREET HILL SE Hillsdale From Sheridan Road	R. L. Polk & Co.
	Hunt Henry	R. L. Polk & Co.

#### 49 T SW

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1943	Day Wm H	R. L. Polk & Co.
1931	Day Wm H	R. L. Polk & Co.
1926	Day Bousi	R. L. Polk & Co.

# T ST SW

## 101 T ST SW

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1948	Hall Granville	R. L. Polk & Co.

## 103 T ST SW

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1948	Hooker Meansie	R. L. Polk & Co.

## 105 T ST SW

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1948	Hammond Benj	R. L. Polk & Co.

## 107 T ST SW

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1948	Gauhn Wm	R. L. Polk & Co.

3660997-6 Page 30

109 T ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Tucker Ronce R. L. Polk & Co.

111 T ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Lewis Jessie R. L. Polk & Co.

113 T ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Boyd Elsie T R. L. Polk & Co.

115 T ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Willis Laurence R. L. Polk & Co.

117 T ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Johnson Chas J R. L. Polk & Co.

119 T ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Mercer Maude R. L. Polk & Co.

**121 TSTSW** 

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Thomas Clayton R. L. Polk & Co.

**123 T ST SW** 

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Campbell Jos R. L. Polk & Co.

125 T ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Jacob Wm R. L. Polk & Co.

127 T ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Jackson Isabel R. L. Polk & Co.

129 T ST SW

<u>Year</u> <u>Uses</u> <u>Source</u>

1948 Jackson Warren R. L. Polk & Co.

3660997-6 Page 31

<u>Year</u>	<u>Uses</u>	<u>Source</u>
-------------	-------------	---------------

1948 Scott Wm R. L. Polk & Co.

## **49 T ST SW**

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1960	Vacant	R. L. Polk & Co.
1948	Tropical Oils Co	R. L. Polk & Co.
	veg oils	R. L. Polk & Co.
1940	Day Wm H	R. L. Polk & Co.
1936	Day Wm H	R. L. Polk & Co.

# T/HALF

## T/HALF

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1964	T/HALF	R. L. Polk & Co.
1960	T/HALF	R. L. Polk & Co.

## **T/WATER**

## T/WATER

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1964	T/WATER	R. L. Polk & Co.
1960	T/WATER	R. L. Polk & Co.

# **WATER ST SW**

# 50 WATER ST SW

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1993	DUCKETT William H Jr	The Chesapeake and Potomac Telephone Company of Virginia

# WATER/T

## WATER/T

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1960	WATER/T	R. L. Polk & Co.
1948	WATER/T	R. L. Polk & Co.

3660997-6 Page 32

## TARGET PROPERTY: ADDRESS NOT IDENTIFIED IN RESEARCH SOURCE

The following Target Property addresses were researched for this report, and the addresses were not identified in the research source.

# <u>Address Researched</u> <u>Address Not Identified in Research Source</u>

S Street SW/1st Street SW 2000, 1993, 1983, 1978, 1973, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922

# ADJOINING PROPERTY: ADDRESSES NOT IDENTIFIED IN RESEARCH SOURCE

The following Adjoining Property addresses were researched for this report, and the addresses were not identified in research source.

Address Researched	Address Not Identified in Research Source
1ST/POTOMAC AV	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1960, 1948, 1943, 1940, 1936, 1931, 1926, 1922
1ST/R	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1960, 1943, 1940, 1936, 1931, 1926, 1922
1ST/S	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1960, 1943, 1940, 1936, 1931, 1926, 1922
1ST/T	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1960, 1943, 1940, 1936, 1931, 1926, 1922
2ND/R	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1960, 1948, 1943, 1940, 1936, 1931, 1926, 1922
2ND/S	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1960, 1943, 1940, 1936, 1931, 1926, 1922
2ND/T	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1960, 1943, 1940, 1936, 1931, 1926, 1922
POTOMAC/1ST	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1954, 1948, 1943, 1940, 1936, 1931, 1926, 1922
R/HALF	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1954, 1948, 1943, 1940, 1936, 1931, 1926, 1922
S/HALF	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1954, 1943, 1940, 1936, 1931, 1926, 1922
T/HALF	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1954, 1948, 1943, 1940, 1936, 1931, 1926, 1922
T/WATER	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1954, 1948, 1943, 1940, 1936, 1931, 1926, 1922
WATER/T	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1954, 1943, 1940, 1936, 1931, 1926, 1922
100 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
101 R SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1964, 1960, 1954, 1948, 1943, 1940, 1936, 1931, 1926, 1922
101 R ST SW	2012, 2007, 1983, 1978, 1973, 1969, 1960, 1954, 1948, 1943, 1940, 1936, 1931, 1926, 1922
101 R ST SW	2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1948, 1943, 1940, 1936, 1931, 1926, 1922

Address Researched	Address Not Identified in Research Source
101 T ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
102 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
103 S ST SW	2012, 2007, 2006, 2000, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1948, 1943, 1940, 1936, 1931, 1926, 1922
103 T ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
104 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
105 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
105 T ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
106 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
107 R SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1964, 1960, 1954, 1948, 1943, 1940, 1936, 1931, 1926, 1922
107 R ST SW	2012, 2007, 2006, 1983, 1969, 1964, 1960, 1954, 1948, 1943, 1940, 1936, 1931, 1926, 1922
107 T ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
108 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
109 T ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
110 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
111 R ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1954, 1948, 1943, 1940, 1936, 1931, 1926, 1922
111 T ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
112 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
113 T ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
114 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
115 R SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1964, 1960, 1954, 1948, 1943, 1940, 1936, 1931, 1926, 1922
115 R ST SW	2012, 2007, 1973, 1969, 1960, 1954, 1948, 1943, 1940, 1936, 1931, 1926, 1922
115 R ST SW	2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1948, 1943, 1940, 1936, 1931, 1926, 1922
115 T ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
116 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922

Address Researched	Address Not Identified in Research Source
117 R ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1954, 1948, 1943, 1940, 1936, 1931, 1926, 1922
117 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
117 T ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
118 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
119 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
119 T ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
121 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
121 T ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
123 R ST SW	2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1948, 1943, 1940, 1936, 1931, 1926, 1922
123 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
123 T ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
125 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
125 T ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
127 T ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
129 T ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
131 R ST SW	2012, 2007, 1993, 1978, 1973, 1969, 1954, 1948, 1943, 1940, 1936, 1931, 1926, 1922
131 R ST SW	2012, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1948, 1943, 1940, 1936, 1931, 1926, 1922
133 R SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1964, 1960, 1954, 1948, 1943, 1940, 1936, 1931, 1926, 1922
133 R ST SW	2012, 2007, 2006, 1993, 1983, 1978, 1973, 1969, 1954, 1948, 1943, 1940, 1936, 1931, 1926, 1922
135 R SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1964, 1960, 1954, 1948, 1943, 1940, 1936, 1931, 1926, 1922
135 R ST SW	2012, 2007, 1973, 1969, 1954, 1948, 1943, 1940, 1936, 1931, 1926, 1922
135 R ST SW	2012, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1948, 1943, 1940, 1936, 1931, 1926, 1922
135 T SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1948, 1943, 1940, 1936, 1931, 1922
137 R SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1964, 1960, 1954, 1948, 1943, 1940, 1936, 1931, 1926, 1922

Address Researched	Address Not Identified in Research Source
137 R ST SW	2012, 2007, 2000, 1993, 1983, 1978, 1973, 1969, 1954, 1948, 1943, 1940, 1936, 1931, 1926, 1922
1648 1ST ST SW	2012, 2007, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1948, 1943, 1940, 1936, 1931, 1926, 1922
1700 1ST ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
1701 HALF SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1948, 1943, 1940, 1936
1702 1ST ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
1702 HALF SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1948, 1943, 1940, 1936, 1931
1704 1ST ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
1704 HALF SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1948, 1943, 1940, 1936, 1931
1706 1ST ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
1716 1ST ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
1717 1ST ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
1718 1ST ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
1720 1ST ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
1722 1ST ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
1724 1ST ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
1725 1ST ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
1726 1ST ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
1728 1ST ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
1730 1ST ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
1732 1ST ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
1734 1ST ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
1736 1ST ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
1738 1ST ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
1740 1ST ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922

Address Researched	Address Not Identified in Research Source
1742 1ST ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
1800 1ST ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
1800 HALF SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1948, 1940, 1936
1800 HALF ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1948, 1943, 1931, 1926, 1922
1802 1ST ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
1802 HALF SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1948, 1940, 1936
1802 HALF ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1948, 1943, 1931, 1926, 1922
1804 1ST ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
1804 HALF SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1964, 1960, 1954, 1948, 1943, 1940, 1936, 1931, 1926, 1922
1804 HALF ST SW	2012, 2007, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1948, 1943, 1940, 1936, 1931, 1926, 1922
1804 HALF ST SW	2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1948, 1943, 1940, 1936, 1931, 1926, 1922
1805 1ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1948, 1940, 1936
1805 1ST ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1948, 1943, 1931, 1926, 1922
1806 1ST ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
1806 HALF SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1948, 1943, 1940, 1936
1808 HALF SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1948, 1943, 1940, 1936
1810 1ST ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
1810 HALF SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1948, 1943, 1940, 1936
1812 1ST ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
1812 HALF SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1964, 1960, 1954, 1948, 1943, 1940, 1936, 1931, 1926, 1922
1812 HALF ST SW	2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1948, 1943, 1940, 1936, 1931, 1926, 1922
1814 1ST ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
1816 1ST ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
1816 HALF SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1964, 1960, 1954, 1948, 1943, 1940, 1936, 1931, 1926, 1922

Address Researched	Address Not Identified in Research Source
1816 HALF ST SW	2012, 2007, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1948, 1943, 1940, 1936, 1931, 1926, 1922
1817 1ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1948, 1943, 1940, 1936
1817 1ST ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1931, 1926, 1922
1818 1ST ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
1820 1ST ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
1820 HALF SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1964, 1960, 1954, 1948, 1943, 1940, 1936
1821 1ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1948, 1940, 1936
1821 1ST ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1931, 1926, 1922
1821 HALF SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1948, 1940, 1936
1821 HALF ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1948, 1943, 1931, 1926, 1922
1822 1ST ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
1822 HALF SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1948, 1943, 1940, 1936
1823 HALF SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1948, 1943, 1940, 1936, 1922
1824 1ST ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
1824 HALF SW	2012, 2007, 2006, 2000, 1993, 1964, 1960, 1954, 1948, 1943, 1940, 1936, 1931, 1926, 1922
1824 HALF ST SW	2012, 2007, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1948, 1943, 1940, 1936, 1931, 1926, 1922
1824 HALF ST SW	2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1948, 1943, 1940, 1936, 1931, 1926, 1922
1825 1ST ST SW	2012, 2007, 2006, 2000, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
1825 HALF SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1948, 1943, 1940, 1936
1826 1ST ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
1828 1ST ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
1830 1ST ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
1832 1ST ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
1834 1ST ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922

Address Researched	Address Not Identified in Research Source
1836 1ST ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
1838 1ST ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
1840 1ST ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
1842 1ST ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
1844 1ST ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
1846 1ST ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
1848 1ST ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
1850 1ST ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
1900 2ND SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1948, 1943, 1940, 1936, 1931, 1926
1900 HALF SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1948, 1943, 1940, 1936, 1931, 1922
1900 HALF ST SW	2012, 2007, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1948, 1943, 1940, 1936, 1931, 1926, 1922
1900 HALF ST SW	2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1948, 1943, 1940, 1936, 1931, 1926, 1922
1901 1ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1948, 1943, 1940, 1936, 1931
1901 1ST ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1948, 1943, 1940, 1931, 1926, 1922
1901 HALF SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1948, 1943, 1940, 1936, 1926
1904 2ND SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1948, 1943, 1940, 1936, 1922
1905 2ND ST SW	2012, 2007, 2006, 2000, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1948, 1943, 1940, 1936, 1931, 1926, 1922
1912 1 STH 2 SW	2012, 2007, 2006, 2000, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1948, 1943, 1940, 1936, 1931, 1926, 1922
1912 2ND SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1948, 1943, 1940, 1936, 1931
1916 HALF SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1948, 1943, 1940, 1936, 1931, 1926
1919 HALF SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1948, 1943, 1940, 1936, 1922
1927 1ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1948, 1943, 1940, 1936
1927 1ST ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1948, 1943, 1940, 1931, 1926, 1922
1929 1ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1948, 1943, 1940, 1936

Address Researched	Address Not Identified in Research Source
1929 1ST ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1948, 1943, 1940, 1931, 1926, 1922
1931 1ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1948, 1943, 1940, 1936
1931 1ST ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1948, 1943, 1940, 1931, 1926, 1922
36 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
38 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
40 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
41 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
42 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
43 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
44 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
45 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
46 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
47 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
48 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
49 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
49 T SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1948, 1940, 1936, 1922
49 T ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1954, 1943, 1931, 1926, 1922
50 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
50 WATER ST SW	2012, 2007, 2006, 2000, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1948, 1943, 1940, 1936, 1931, 1926, 1922
51 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
52 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
53 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
54 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
55 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922

Address Researched	Address Not Identified in Research Source
56 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
57 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
58 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
59 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
60 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
61 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
62 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
63 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
64 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
65 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
66 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
67 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
68 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
69 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
70 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
71 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
72 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
73 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
74 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
75 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
76 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
78 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
80 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
82 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922

Address Researched	Address Not Identified in Research Source
84 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
86 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
88 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
90 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
92 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
94 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
96 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922
98 S ST SW	2012, 2007, 2006, 2000, 1993, 1983, 1978, 1973, 1969, 1964, 1960, 1954, 1943, 1940, 1936, 1931, 1926, 1922

# APPENDIX D

**Regulatory Records Documentation** 


# **Buzzard Point**

S Street SW/1st Street SW Washington, DC 20024

Inquiry Number: 03660997.2r

July 10, 2013

# The EDR Radius Map™ Report with GeoCheck®



# **TABLE OF CONTENTS**

SECTION	PAGE
Executive Summary	ES1
Overview Map	2
Detail Map.	3
Map Findings Summary.	<b>4</b>
Map Findings	7
Orphan Summary	
Government Records Searched/Data Currency Tracking	GR-1
GEOCHECK ADDENDUM	
Physical Setting Source Addendum	A-1
Physical Setting Source Summary	
Physical Setting Source Map.	<b>A-6</b>
Physical Setting Source Map Findings.	A-7
Physical Setting Source Records Searched	A-14

**Thank you for your business.**Please contact EDR at 1-800-352-0050 with any questions or comments.

#### **Disclaimer - Copyright and Trademark Notice**

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2013 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E 1527-05) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

#### TARGET PROPERTY INFORMATION

#### **ADDRESS**

S STREET SW/1ST STREET SW WASHINGTON, DC 20024

#### **COORDINATES**

Latitude (North): 38.8683000 - 38° 52' 5.88" Longitude (West): 77.0121000 - 77° 0' 43.56"

Universal Tranverse Mercator: Zone 18 UTM X (Meters): 325434.0 UTM Y (Meters): 4303878.0

Elevation: 21 ft. above sea level

#### USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map: 38077-G1 ALEXANDRIA, VA DC MD

Most Recent Revision: 1994

North Map: 38077-H1 WASHINGTON WEST, DC MD VA

Most Recent Revision: 1983

Northeast Map: 38076-H8 WASHINGTON EAST, DC MD

Most Recent Revision: 1982

East Map: 38076-G8 ANACOSTIA, DC MD

Most Recent Revision: 1982

#### **AERIAL PHOTOGRAPHY IN THIS REPORT**

Portions of Photo from: 2011, 2012 Source: USDA

## TARGET PROPERTY SEARCH RESULTS

The target property was not listed in any of the databases searched by EDR.

## **DATABASES WITH NO MAPPED SITES**

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

## STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list	
	Processed Martineral Principal List Oites
NPL LIENS	Proposed National Priority List Sites
NI L LILING	Trederal Superiulia Liens
Federal Delisted NPL site lis	st
Delisted NPL	National Priority List Deletions
	·
Federal CERCLIS list	
FEDERAL FACILITY	Federal Facility Site Information listing
	•
Federal RCRA non-CORRA	CTS TSD facilities list
RCRA-TSDF	RCRA - Treatment, Storage and Disposal
	, ,
Federal institutional control	s / engineering controls registries
US INST CONTROL	Sites with Institutional Controls
	Land Use Control Information System
Federal ERNS list	
ERNS	Emergency Response Notification System
State- and tribal - equivalen	t CERCLIS
DC SHWS	This state does not maintain a SHWS list. See the Federal CERCLIS list and Federal
	NPL list.
State and tribal landfill and/	ar calid wasta diapagal sita lista
	or some waste disposar site lists
DC SWF/LF	•
	•
	Solid Waste Facility Listing
DC SWF/LF  State and tribal leaking stor	Solid Waste Facility Listing
DC SWF/LF  State and tribal leaking stor	Solid Waste Facility Listing  age tank lists
DC SWF/LF  State and tribal leaking stor	Solid Waste Facility Listing  age tank lists  Leaking Underground Storage Tanks on Indian Land
State and tribal leaking stor INDIAN LUST	Solid Waste Facility Listing  age tank lists  Leaking Underground Storage Tanks on Indian Land  torage tank lists  . Underground Storage Tanks on Indian Land
State and tribal leaking stor INDIAN LUST	Solid Waste Facility Listing  age tank lists  Leaking Underground Storage Tanks on Indian Land
State and tribal leaking stor INDIAN LUST	Solid Waste Facility Listing  age tank lists  Leaking Underground Storage Tanks on Indian Land  torage tank lists  Underground Storage Tanks on Indian Land Underground Storage Tank Listing
State and tribal leaking stor INDIAN LUST	Solid Waste Facility Listing  age tank lists  Leaking Underground Storage Tanks on Indian Land  torage tank lists  Underground Storage Tanks on Indian Land Underground Storage Tank Listing

#### ADDITIONAL ENVIRONMENTAL RECORDS

#### Local Brownfield lists

US BROWNFIELDS..... A Listing of Brownfields Sites

#### Local Lists of Landfill / Solid Waste Disposal Sites

DEBRIS REGION 9..... Torres Martinez Reservation Illegal Dump Site Locations

ODI...... Open Dump Inventory

#### Local Lists of Hazardous waste / Contaminated Sites

US CDL..... Clandestine Drug Labs

US HIST CDL...... National Clandestine Laboratory Register

#### Local Land Records

LIENS 2..... CERCLA Lien Information

#### Records of Emergency Release Reports

HMIRS..... Hazardous Materials Information Reporting System

#### Other Ascertainable Records

DOT OPS...... Incident and Accident Data

CONSENT..... Superfund (CERCLA) Consent Decrees

UMTRA..... Uranium Mill Tailings Sites US MINES..... Mines Master Index File

TRIS...... Toxic Chemical Release Inventory System

TSCA..... Toxic Substances Control Act

FTTS______FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide

Act)/TSCA (Toxic Substances Control Act)

HIST FTTS..... FIFRA/TSCA Tracking System Administrative Case Listing

SSTS..... Section 7 Tracking Systems

ICIS...... Integrated Compliance Information System

PADS..... PCB Activity Database System MLTS..... Material Licensing Tracking System RADINFO...... Radiation Information Database RMP..... Risk Management Plans

INDIAN RESERV...... Indian Reservations
SCRD DRYCLEANERS..... State Coalition for Remediation of Drycleaners Listing US AIRS...... Aerometric Information Retrieval System Facility Subsystem

PRP...... Potentially Responsible Parties

EPA WATCH LIST..... EPA WATCH LIST

US FIN ASSUR..... Financial Assurance Information PCB TRANSFORMER_____ PCB Transformer Registration Database COAL ASH DOE..... Steam-Electric Plant Operation Data

COAL ASH EPA..... Coal Combustion Residues Surface Impoundments List

LEAD SMELTERS..... Lead Smelter Sites

2020 COR ACTION............ 2020 Corrective Action Program List

#### **EDR HIGH RISK HISTORICAL RECORDS**

#### **EDR Exclusive Records**

EDR MGP..... EDR Proprietary Manufactured Gas Plants

#### **SURROUNDING SITES: SEARCH RESULTS**

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.

Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in **bold italics** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

#### STANDARD ENVIRONMENTAL RECORDS

#### Federal NPL site list

NPL: Also known as Superfund, the National Priority List database is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund program. The source of this database is the U.S. EPA.

A review of the NPL list, as provided by EDR, and dated 04/26/2013 has revealed that there is 1 NPL site within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
WASHINGTON NAVY YARD	1013 O STREET SE	ENE 1/2 - 1 (0.639 mi.)	0	7

#### Federal CERCLIS list

CERCLIS: The Comprehensive Environmental Response, Compensation and Liability Information System contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA). CERCLIS contains sites which are either proposed to or on the National Priorities List (NPL) and sites which are in the screening and assessment phase for possible inclusion on the NPL.

A review of the CERCLIS list, as provided by EDR, and dated 02/04/2013 has revealed that there is 1 CERCLIS site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
FORT MCNAIR	350 P STREET SW	NW 1/8 - 1/4 (0.202 mi.)	P81	203

#### Federal CERCLIS NFRAP site List

CERC-NFRAP: Archived sites are sites that have been removed and archived from the inventory of CERCLIS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list this site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. This decision does not necessarily mean that there is no hazard associated with a given site; it only means that, based upon available information, the location is not judged to be a potential NPL site.

A review of the CERC-NFRAP list, as provided by EDR, and dated 02/05/2013 has revealed that there are 3 CERC-NFRAP sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
WARRING, JAMES T SONS INC	1321 S CAPITOL ST SW	NNE 1/4 - 1/2 (0.256 mi.)	S93	229
Lower Elevation	Address	Direction / Distance	Map ID	Page
WASHINGTON D.C. SEWER MYSTERY	150 O STREET	NE 1/4 - 1/2 (0.329 mi.)	T96	231
NAVAL SUPPORT FACILITY ANACOST	2701 SOUTH CAPITOL STRE	SSW 1/4 - 1/2 (0.390 mi.)	100	233

#### Federal RCRA CORRACTS facilities list

CORRACTS: CORRACTS is a list of handlers with RCRA Corrective Action Activity. This report shows which nationally-defined corrective action core events have occurred for every handler that has had corrective action activity.

A review of the CORRACTS list, as provided by EDR, and dated 02/12/2013 has revealed that there is 1 CORRACTS site within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	<b>Direction / Distance</b>	Map ID	Page
WASHINGTON NAVY YARD	1013 O STREET SE	ENE 1/2 - 1 (0.639 mi.)	0	7

#### Federal RCRA generators list

RCRA-SQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

A review of the RCRA-SQG list, as provided by EDR, and dated 02/12/2013 has revealed that there are 2 RCRA-SQG sites within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
US COAST GUARD HSC-K	2100 SECOND STREET SW	SSW 1/8 - 1/4 (0.169 mi.)	N70	191
FORT MCNAIR	350 P STREET SW	NW 1/8 - 1/4 (0,202 mi.)	P81	203

RCRA-CESQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

A review of the RCRA-CESQG list, as provided by EDR, and dated 02/12/2013 has revealed that there are 9 RCRA-CESQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SUPER SALVAGE INC	1711 FIRST STREET SW	0 - 1/8 (0.000 mi.)	C12	65
USA MOTORS INC	45 Q STREET SW	NNE 0 - 1/8 (0.032 mi.)	D15	69
GOLD STAR SERVICES	39 Q STREET SW	NE 0 - 1/8 (0.047 mi.)	D20	92
SINGH TRANSMISSION C/O AUTOMOT	1505 SOUTH CAPITOL STRE	NNE 1/8 - 1/4 (0.126 mi.)	J51	160
NATIONALS PARK	1500 SOUTH CAPITOL STRE	NE 1/8 - 1/4 (0.163 mi.)	L61	181
Lower Elevation	Address	Direction / Distance	Map ID	Page
AUTO WARD INC.	129 Q STREET SW	NNW 0 - 1/8 (0.069 mi.)	F22	105
PAK-AMERICAN CORPORATION	1625 SOUTH CAPITOL STRE	ENE 0 - 1/8 (0.073 mi.)	G33	138
PEPCO BUZZARD POINT GENERATING	1ST & V STREETS SW	S 0 - 1/8 (0.077 mi.)	I34	143
PEPCO BUZZARD PT GENERATING ST	1ST V STS SW	S 0 - 1/8 (0.077 mi.)	<i>1</i> 35	145

#### State and tribal leaking storage tank lists

DC LUST: The Leaking Underground Storage Tank Incident Reports contain an inventory of reported leaking underground storage tank incidents. The data come from the Department of Consumer and Regulatory Affairs' District of Columbia LUST Cases list.

A review of the DC LUST list, as provided by EDR, and dated 04/10/2013 has revealed that there are 33 DC LUST sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
HOME MOVING & STORAGE	1812 HALF ST., SW	0 - 1/8 (0.000 mi.)	B5	63
SUPER SALVAGE, INC.	1711 1ST STREET., SW	0 - 1/8 (0.000 mi.)	C9	64
METRO BUILDING SUPPLY	50 Q STREET, SW	NNE 0 - 1/8 (0.027 mi.)	D13	68
OPPORTUNITY CONCRETE CORP	1601 S CAPITOL ST SW	NE 0 - 1/8 (0.073 mi.)	H30	135
STEUART INVESTMENT CO.	1724 S. CAPITOL ST, SE	NE 0 - 1/8 (0.094 mi.)	H41	153
Not reported	1620 SOUTH CAPITOL ST S	NE 0 - 1/8 (0.108 mi.)	J45	154
LAUNDROMAT	1530 1ST ST SW	N 0 - 1/8 (0.117 mi.)	K49	159
WASHINGTON REAL ESTATE INVESTM	1501 SOUTH CAPITOL STRE	NNE 1/8 - 1/4 (0.127 mi.)	J54	176
POTOMAC CAB COMPANY	1345 S CAPITOL ST SW	NNE 1/8 - 1/4 (0.235 mi.)	Q86	222
WEBER'S WHITE TRUCKS,INC.	1331 HALF ST SE	NNE 1/4 - 1/2 (0.359 mi.)	97	232
AMOCO	1244 SOUTH CAPITAL ST.	NNE 1/4 - 1/2 (0.371 mi.)	U98	233
PUBLIC STORAGE, INC.	1230 SOUTH CAPITOL ST.,	NNE 1/4 - 1/2 (0.393 mi.)	U101	253
PUBLIC STORAGE	1230 SOUTH CAPITOL STRE	NNE 1/4 - 1/2 (0.393 mi.)	U102	253
17 M ST. LLC/WMATA	17 M STREET, SE	NNE 1/4 - 1/2 (0.429 mi.)	V103	253
LERNER ENTERPRISES	20 M STREET, SE	NNE 1/4 - 1/2 (0.439 mi.)	V106	255
MONUMENT REALTY	55 M STREET	NNE 1/4 - 1/2 (0.451 mi.)	W109	257
SUNOCO	50 M STREET, SE	NNE 1/4 - 1/2 (0.456 mi.)	W110	257
80 M TRACKS LTD PARTNERS	80 M STREET, SE	NNE 1/4 - 1/2 (0.483 mi.)	W111	257
Lower Elevation	Address	Direction / Distance	Map ID	Page
PEPCO BUZZARD - TANK # 1	180 S STREET, SW	0 - 1/8 (0.000 mi.)	A2	62

Lower Elevation	Address	Direction / Distance	Map ID	Page
AT&T - 1714 2ND ST SW	1714 2ND STREET, SW	0 - 1/8 (0.000 mi.)	A4	63
WESTWOOD MANAGEMENT CORPORA	TIO 900 HALF ST SW	SE 0 - 1/8 (0.037 mi.)	E18	91
STEUART PETROLEUM	1721 S. CAPITOL STREET,	ENE 0 - 1/8 (0.072 mi.)	G25	130
625 SOUTH CAPITOL STREET LLC	1625 SOUTH CAPITOL STRE	NE 0 - 1/8 (0.073 mi.)	H32	138
PEPCO - BUZZARD POINT	33 V STREET, SW	S 0 - 1/8 (0.077 mi.)	137	149
NPS - JAMES CREEK MARINA	200 V STREET, SW	SSW 1/8 - 1/4 (0.168 mi.)	N68	190
DC MATERIALS CO./ FLORIDA ROCK	25 POTOMAC AVE, SE	NE 1/8 - 1/4 (0.173 mi.)	O71	195
VIRGINIA PAVING	60 P STREET, SE	NE 1/8 - 1/4 (0.193 mi.)	R79	202
DC SPORTS COMMISSION	60-80 O STREET, SE	NE 1/4 - 1/2 (0.306 mi.)	T94	230
DC DPW FLEET MANAGEMENT	125 O STREET, SE	NE 1/4 - 1/2 (0.325 mi.)	T95	231
BOWEN ELEMENTARY SCHOOL	101 M ST SW	N 1/4 - 1/2 (0.436 mi.)	104	254
ADMIRAL LIMOUSINE COMPANY	1245 1ST ST SE	NNE 1/4 - 1/2 (0.439 mi.)	105	254
GREENLEAF SENIOR GARDENS	1200 DELAWARE AV SW	N 1/4 - 1/2 (0.450 mi.)	108	256
21 L, LLC	21 L STREET, SW	N 1/4 - 1/2 (0.494 mi.)	112	258

#### State and tribal registered storage tank lists

DC UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Consumer & Regulatory Affairs' D.C. UST Database List.

A review of the DC UST list, as provided by EDR, and dated 04/10/2013 has revealed that there are 27 DC UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
BORGER MANAGEMENT, INC.	1812 HALF ST SW	0 - 1/8 (0.000 mi.)	B6	63
SUPER SALVAGE INC.	1711 1ST ST SW	0 - 1/8 (0.000 mi.)	C10	65
METRO BUILDING SUPPLY CO.	50 Q ST SW	NNE 0 - 1/8 (0.027 mi.)	D14	68
OPPORTUNITY CONCRETE GARAGE.	1601 S CAPITOL ST SW	NE 0 - 1/8 (0.073 mi.)	H29	134
FEDDERLINE.	1724 S CAPITOL ST SW	NE 0 - 1/8 (0.094 mi.)	H38	150
AMERADA HESS CORP.	1620 S CAPITOL ST SE	NE 0 - 1/8 (0.108 mi.)	J47	157
LAUNDROMAT	1530 1ST ST SW	N 0 - 1/8 (0.117 mi.)	K49	159
FIVE SAC SELF-STORAGE	1501 S CAPITOL ST SW10	NNE 1/8 - 1/4 (0.127 mi.)	J55	177
ANACOSTIA READY MIX PLANT	1522 S CAPITOL ST SE	NE 1/8 - 1/4 (0.130 mi.)	J57	180
BASEBALL STADIUM	1500 SOUTH CAPITOL ST S	NE 1/8 - 1/4 (0.163 mi.)	L62	182
DC PUBLIC SCHOOL SYSTEM	50 O ST SW	N 1/8 - 1/4 (0.189 mi.)	75	197
SYPHAX SCHOOL	1360 HALF ST SW	NNE 1/8 - 1/4 (0.228 mi.)	83	218
BOB SEGALL	1354 SOUTH CAPITOL ST S	NNE 1/8 - 1/4 (0.235 mi.)	Q84	219
POTOMAC CAB COMPANY	1345 S CAPITOL ST SW	NNE 1/8 - 1/4 (0.235 mi.)	Q86	222
Lower Elevation	Address	Direction / Distance	Map ID	Page
ATTIS	1714 2ND ST SW	0 - 1/8 (0.000 mi.)	А3	62
PEPCO	1ST & T ST SW	0 - 1/8 (0.000 mi.)	7	64
WESTWOOD MANAGEMENT CORPORAT	TIO 1900 HALF ST SW	SE 0 - 1/8 (0.037 mi.)	E18	91
CABCO INC.	129 Q ST SW	NNW 0 - 1/8 (0.069 mi.)	F23	130
STEUART PETROLEUM COMPANY.	1721 S CAPITOL ST SW	ENE 0 - 1/8 (0.072 mi.)	G26	131
GOOSE BAY AGGREGATE, INC.	2 S ST SW	E 0 - 1/8 (0.073 mi.)	28	133
SOLON AUTOMATED SERVICES	1625 S CAPITOL ST SW	NE 0 - 1/8 (0.073 mi.)	H31	138
PEPCO BUZZARD PT GENERATING ST	1ST VSTS SW	S 0 - 1/8 (0.077 mi.)	<i>1</i> 35	145
BUZZARD POINT FACILITY	180 S ST SW	S 0 - 1/8 (0.077 mi.)	136	149
JAMES CREEK MARINA	200 V ST SW	SSW 1/8 - 1/4 (0.168 mi.)	N69	191
D.C. MATERIALS CO.	25 POTOMAC AV SE	NE 1/8 - 1/4 (0.173 mi.)	072	195

Lower Elevation	Address	Direction / Distance	Map ID	Page
FORMER DISTRICT PAVING - ASPHA	60 P ST SE	NE 1/8 - 1/4 (0.193 mi.)	R77	198
CHANNEL SQUARE APARTMENTS	325 P ST SW	NW 1/8 - 1/4 (0.238 mi.)	87	223

DC AST: The Aboveground Storage Tank database contains registered ASTs. The data come from the Department of Consumer & Regulatory Affairs' D.C. AST Database List.

A review of the DC AST list, as provided by EDR, and dated 04/10/2013 has revealed that there is 1 DC AST site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
JONES TRANSPORTATION	1342 S CAPITOL ST SE	NNE 1/8 - 1/4 (0.239 mi.)	Q89	227

#### State and tribal voluntary cleanup sites

DC VCP: The Voluntary Cleanup Program oversees owner or developer initiated voluntary remediation of contaminated lands and buildings that return actual or potentially contaminated properties to productive uses.

A review of the DC VCP list, as provided by EDR, and dated 01/09/2013 has revealed that there is 1 DC VCP site within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
DC SPORT & ENTERTAINMENT COM	1500 S. CAPITAL ST. S.E	NE 1/8 - 1/4 (0.163 mi.)	L63	184

#### State and tribal Brownfields sites

DC BROWNFIELDS: A listing of potential brownfields site locations.

A review of the DC BROWNFIELDS list, as provided by EDR, and dated 11/20/2012 has revealed that there are 13 DC BROWNFIELDS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
Not reported	1824 HALF STREET, SW	0 - 1/8 (0.000 mi.)	B8	64
Not reported	1700 1ST STREET, SW	0 - 1/8 (0.000 mi.)	C11	65
Not reported	1724 SOUTH CAPITOL ST S	NE 0 - 1/8 (0.094 mi.)	H39	152
Not reported	1620 SOUTH CAPITOL ST S	NE 0 - 1/8 (0.108 mi.)	J45	154
Not reported	1236 SOUTH CAPITOL STRE	NNE 1/4 - 1/2 (0.387 mi.)	U99	233
PUBLIC STORAGE	1230 SOUTH CAPITOL STRE	NNE 1/4 - 1/2 (0.393 mi.)	U102	253
Not reported	0020 M STREET, SE	NNE 1/4 - 1/2 (0.439 mi.)	V107	256
Lower Elevation	Address	Direction / Distance	Map ID	Page
Not reported	100 S STREET, SW	0 - 1/8 (0.000 mi.)	1	61
PEPCO BUZZARD - TANK # 1	180 S STREET, SW	0 - 1/8 (0.000 mi.)	A2	62
AT&T - 1714 2ND ST SW	1714 2ND STREET, SW	0 - 1/8 (0.000 mi.)	A4	63
Not reported	1900 HALF STREET, SW	SE 0 - 1/8 (0.037 mi.)	E17	91
Not reported	100 V STREET, SW	S 1/8 - 1/4 (0.168 mi.)	M66	190
Not reported	0200 V STREET, SW	SSW 1/8 - 1/4 (0.168 mi.)	N67	190

#### ADDITIONAL ENVIRONMENTAL RECORDS

#### Local Lists of Registered Storage Tanks

DC HIST UST: During the process of the database upgrade, all facilities that the UST Program was unable to confirm their existence were removed from the working revelation UST Database before the conversion and put into an excel spreadsheet. These facilities became known as "Project Unknown". This listing is not current and has been not updated.

A review of the DC HIST UST list, as provided by EDR, and dated 12/31/1999 has revealed that there are 7 DC HIST UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
UNKNOWN	1620 1ST ST SW	N 0 - 1/8 (0.040 mi.)	F19	92
UNKNOWN	1615 1ST ST SW	N 0 - 1/8 (0.049 mi.)	F21	105
UNKNOWN	1513 HALF ST SW	NNE 0 - 1/8 (0.104 mi.)	43	154
LANSBURGH BROTHERS	10 P ST SW	NNE 1/8 - 1/4 (0.127 mi.)	L53	176
UNKNOWN	1400 S CAPITOL ST SE	NNE 1/8 - 1/4 (0.192 mi.)	Q76	197
UNKNOWN	1334 S CAPITOL ST SE	NNE 1/8 - 1/4 (0.241 mi.)	S91	227
Lower Elevation	Address	Direction / Distance	Map ID	Page
UNKNOWN	321 P ST SW	NW 1/8 - 1/4 (0.187 mi.)	P74	197

#### Other Ascertainable Records

RCRA NonGen / NLR: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA NonGen / NLR list, as provided by EDR, and dated 02/12/2013 has revealed that there are 10 RCRA NonGen / NLR sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
OPPORTUNITY CONCRETE CORP	1601 S CAPITOL ST SW	NE 0 - 1/8 (0.073 mi.)	H30	135
AMERADA HESS CORP	1620 SOUTH CAPITOL STRE	NE 0 - 1/8 (0.108 mi.)	J46	155
G S A CENTRAL SUPPORT FIELD OF	10 P STREET SW	NNE 1/8 - 1/4 (0.127 mi.)	L52	173
SERCO MANAGEMENT SERVICES	1501 SOUTH CAPITOL ST S	NNE 1/8 - 1/4 (0.130 mi.)	J56	177
1430 P STREET WAREHOUSE	1430 SOUTH CAPITOL STRE	NNE 1/8 - 1/4 (0.178 mi.)	L73	195
<b>CUSTOM TOWING &amp; AUTO REPAIR</b>	1345 SOUTH CAPITOL STRE	NNE 1/8 - 1/4 (0.235 mi.)	Q85	219
JONES TRANSPORTATION CO	1342 SOUTH CAPITOL STRE	NNE 1/8 - 1/4 (0.239 mi.)	Q88	223
WARRING, JAMES T SONS INC	1330 S CAPITOL ST SE	NNE 1/8 - 1/4 (0.242 mi.)	S92	228
Lower Elevation	Address	Direction / Distance	Map ID	Page
STEUART PETRO CO SO CAPITOL TE	1721 S CAPITOL ST NW	ENE 0 - 1/8 (0.072 mi.)	G27	131
DISTRICT PAVING CORPORATION	60 P STREET SE	NE 1/8 - 1/4 (0.193 mi.)	R78	200

DOD: Consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

A review of the DOD list, as provided by EDR, and dated 12/31/2005 has revealed that there is 1 DOD site within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
NAVAL STATION ANACOSTIA		0 - 1/8 (0.000 mi.)	0	7

FUDS: The Listing includes locations of Formerly Used Defense Sites Properties where the US Army Corps Of Engineers is actively working or will take necessary cleanup actions.

A review of the FUDS list, as provided by EDR, and dated 12/31/2011 has revealed that there is 1 FUDS site within approximately 1 mile of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
WASHINGTON NAVY YARD		NE 1/2 - 1 (0.646 mi.)	113	258

ROD: Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid the cleanup.

A review of the ROD list, as provided by EDR, and dated 12/18/2012 has revealed that there is 1 ROD site within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
WASHINGTON NAVY YARD	1013 O STREET SE	ENE 1/2 - 1 (0.639 mi.)	0	7

NJ MANIFEST: Hazardous waste manifest information.

A review of the NJ MANIFEST list, as provided by EDR, has revealed that there are 5 NJ MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
USA MOTORS INC	45 Q STREET SW	NNE 0 - 1/8 (0.032 mi.)	D15	69
GOLD STAR SERVICES	39 Q STREET SW	NE 0 - 1/8 (0.047 mi.)	D20	92
SINGH TRANSMISSION C/O AUTOMOT	1505 SOUTH CAPITOL STRE	NNE 1/8 - 1/4 (0.126 mi.)	J51	160
Lower Elevation	Address	Direction / Distance	Map ID	Page
AUTO WARD INC.	129 Q STREET SW	NNW 0 - 1/8 (0.069 mi.)	F22	105
PAK-AMERICAN CORPORATION	1625 SOUTH CAPITOL STRE	ENE 0 - 1/8 (0.073 mi.)	G33	138

PA MANIFEST: Hazardous waste manifest information.

A review of the PA MANIFEST list, as provided by EDR, has revealed that there are 2 PA MANIFEST sites within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
US COAST GUARD HSC-K	2100 SECOND STREET SW	SSW 1/8 - 1/4 (0.169 mi.)	N70	191
FORT MCNAIR	350 P STREET SW	NW 1/8 - 1/4 (0.202 mi.)	P81	203

NY MANIFEST: Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

A review of the NY MANIFEST list, as provided by EDR, has revealed that there are 2 NY MANIFEST sites within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
POTOMAC ELECT POWER CO/BUZZARD FORT MCNAIR	1ST & V ST/SW	S 1/8 - 1/4 (0.167 mi.)	M64	184
	<b>350 P STREET SW</b>	<b>NW 1/8 - 1/4 (0.202 mi.)</b>	<b><i>P</i>81</b>	<b>203</b>

#### **EDR HIGH RISK HISTORICAL RECORDS**

#### **EDR Exclusive Records**

EDR US Hist Auto Stat: EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR US Hist Auto Stat list, as provided by EDR, has revealed that there are 9 EDR US Hist Auto Stat sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
Not reported	45 Q ST SW	NNE 0 - 1/8 (0.032 mi.)	D16	90
GULF OIL CORP (BULK PLANT)	1724 S CAPITOL ST SE	NE 0 - 1/8 (0.094 mi.)	H40	152
Not reported	1505 S CAPITOL ST SW	NE 0 - 1/8 (0.094 mi.)	J42	153
TRANSMISSION S INC	1509 SOUTH CAPITOL TER	NNE 0 - 1/8 (0.123 mi.)	J50	159
BRIDGEWAY MOTORS	1343-45 S CAPITOL ST SE	NNE 1/8 - 1/4 (0.151 mi.)	L59	180
CAMPBELL S GARAGE	1327 S CAPITOL ST SE	NNE 1/8 - 1/4 (0.167 mi.)	L65	189
Not reported	1345 S CAPITOL ST SW	NNE 1/8 - 1/4 (0.221 mi.)	Q82	218
Not reported	1342 S CAPITOL ST SE	NNE 1/8 - 1/4 (0.239 mi.)	Q90	227
Lower Elevation	Address	Direction / Distance	Map ID	Page
Not reported	129 Q ST SW	NNW 0 - 1/8 (0.069 mi.)	F24	130

EDR US Hist Cleaners: EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR US Hist Cleaners list, as provided by EDR, has revealed that there are 5 EDR US

Hist Cleaners sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
Not reported	1546 1ST ST SW	N 0 - 1/8 (0.104 mi.)	K44	154
ASSOCIATED LAUNDRIES	1507 S CAPITOL ST SE	NE 0 - 1/8 (0.112 mi.)	J48	159
HOWARD S ODORIESS CLEANERS (PL	1347 S CAPITOL ST SE	NNE 1/8 - 1/4 (0.147 mi.)	L58	180
HOWARD S ODORLESS CLEANERS	1343 S CAPITOL ST SE	NNE 1/8 - 1/4 (0.151 mi.)	L60	181
Lower Elevation	Address	Direction / Distance	Map ID	Page
SMITH THEO N	234 3RD AVE SW	NW 1/8 - 1/4 (0.194 mi.)	80	203

Due to poor or inadequate address information, the following sites were not mapped. Count: 20 records.

Site Name Database(s)

MSP AVIATION DIV. WASHINGTON HIST UST

ANACOSTIA DRUM SITE CERCLIS-NFRAP CUSTIS & BROWN BARGE SPILL CERCLIS-NFRAP

LAUNDROMAT OF BONG YEE
DELWIN APARTMENTS
LUST
FT. MCNAIR, BLDG #37, TANK #5
LUST

SQUARE 669 LTD LUST PEPCO LUST ROADSIDE DEVELOPMENT, INC. LUST

PEPCO AST

WASHINGTON D C DEPT OF PUBLIC WORK RCRA-NLR,MANIFEST FEDERAL OFFICE BUILDING 8 (FOB 8) RCRA-NLR

LECKIE ELEMENTARY SCHOOL

KRAMER JUNIOR HIGH SCHOOL (PUBLIC

RCRA-CESQG

FASTERN SENIOR LIGH SCHOOL (PUBLIC)


RCRA-CESQG

EASTERN SENIOR HIGH SCHOOL (PUBLIC RCRA-CESQG BUZZARD POINT GENERATING STATION FINDS

BUZZARD POINT FACILITY FINDS
NATIONAL PARK SERVICE - EAST POTOM FINDS
I & R TRANSMISSION MANIFEST

THURGOOD MARSHALL ACADEMY MANIFEST

# **OVERVIEW MAP - 03660997.2r**



display and/or hide map information. The legend includes only those icons for the default map view.


SITE NAME: Buzzard Point ADDRESS: S Street SW/1st Street SW

LAT/LONG:

Washington DC 20024 38.8683 / 77.0121

CLIENT: Haley & Aldrich, Inc. CONTACT: Kristen Wright-Ng INQUIRY #: 03660997.2r DATE: July 10, 2013 4:25 pm

# **DETAIL MAP - 03660997.2r**



SITE NAME: Buzzard Point
ADDRESS: S Street SW/1st Street SW
Washington DC 20024
LAT/LONG: 38.8683 / 77.0121

CLIENT: Haley & Aldrich, Inc.
CONTACT: Kristen Wright-Ng
INQUIRY #: 03660997.2r
DATE: July 10, 2013 4:26 pm

# **MAP FINDINGS SUMMARY**

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
STANDARD ENVIRONMENT	AL RECORDS							
Federal NPL site list								
NPL Proposed NPL NPL LIENS	1.000 1.000 TP		0 0 NR	0 0 NR	0 0 NR	1 0 NR	NR NR NR	1 0 0
Federal Delisted NPL site	e list							
Delisted NPL	1.000		0	0	0	0	NR	0
Federal CERCLIS list								
CERCLIS FEDERAL FACILITY	0.500 0.500		0 0	1 0	0 0	NR NR	NR NR	1 0
Federal CERCLIS NFRAP site List								
CERC-NFRAP	0.500		0	0	3	NR	NR	3
Federal RCRA CORRACTS facilities list								
CORRACTS	1.000		0	0	0	1	NR	1
Federal RCRA non-CORRACTS TSD facilities list								
RCRA-TSDF	0.500		0	0	0	NR	NR	0
Federal RCRA generators list								
RCRA-LQG RCRA-SQG RCRA-CESQG	0.250 0.250 0.250		0 0 7	0 2 2	NR NR NR	NR NR NR	NR NR NR	0 2 9
Federal institutional controls / engineering controls registries								
US ENG CONTROLS US INST CONTROL LUCIS	0.500 0.500 0.500		0 0 0	0 0 0	0 0 0	NR NR NR	NR NR NR	0 0 0
Federal ERNS list								
ERNS	TP		NR	NR	NR	NR	NR	0
State- and tribal - equivalent CERCLIS								
DC SHWS	1.000		0	0	0	0	NR	0
State and tribal landfill and/or solid waste disposal site lists								
DC SWF/LF	0.500		0	0	0	NR	NR	0
State and tribal leaking storage tank lists								
DC LUST INDIAN LUST	0.500 0.500		13 0	5 0	15 0	NR NR	NR NR	33 0
State and tribal registered storage tank lists								
DC UST	0.250		16	11	NR	NR	NR	27

# **MAP FINDINGS SUMMARY**

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
DC AST INDIAN UST FEMA UST	0.250 0.250 0.250		0 0 0	1 0 0	NR NR NR	NR NR NR	NR NR NR	1 0 0
State and tribal voluntary	cleanup site	es						
DC VCP INDIAN VCP	0.500 0.500		0 0	1 0	0 0	NR NR	NR NR	1 0
State and tribal Brownfields sites								
DC BROWNFIELDS	0.500		8	2	3	NR	NR	13
ADDITIONAL ENVIRONMENTAL RECORDS								
Local Brownfield lists								
US BROWNFIELDS	0.500		0	0	0	NR	NR	0
Local Lists of Landfill / Solid Waste Disposal Sites								
DEBRIS REGION 9	0.500		0	0	0	NR	NR	0
ODI	0.500 0.500		0 0	0 0	0 0	NR NR	NR NB	0
INDIAN ODI 0.500 0 0 NR NR 0  Local Lists of Hazardous waste / Contaminated Sites								
US CDL	TP		NR	NR	NR	NR	NR	0
US HIST CDL	TP		NR	NR	NR	NR	NR	0
Local Lists of Registered	Storage Tan	ks						
DC HIST UST	0.250		3	4	NR	NR	NR	7
Local Land Records								
LIENS 2	TP		NR	NR	NR	NR	NR	0
Records of Emergency Release Reports								
HMIRS	TP		NR	NR	NR	NR	NR	0
Other Ascertainable Records								
RCRA NonGen / NLR DOT OPS DOD FUDS CONSENT ROD UMTRA US MINES TRIS TSCA FTTS HIST FTTS SSTS	0.250 TP 1.000 1.000 1.000 0.500 0.250 TP TP TP TP TP		3 NR 1 0 0 0 0 NR NR NR NR NR	7 NR 0 0 0 0 0 NR NR NR NR	NR NR 0 0 0 0 NR NR NR NR NR	NR NR 0 1 0 1 NR NR NR NR NR NR NR NR	NR NR NR NR NR NR NR NR NR NR NR NR	10 0 1 1 0 1 0 0 0 0 0

# **MAP FINDINGS SUMMARY**

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
ICIS	TP		NR	NR	NR	NR	NR	0
PADS	TP		NR	NR	NR	NR	NR	0
MLTS	TP		NR	NR	NR	NR	NR	0
RADINFO	TP		NR	NR	NR	NR	NR	0
FINDS	TP		NR	NR	NR	NR	NR	0
RAATS	TP		NR	NR	NR	NR	NR	0
RMP	TP		NR	NR	NR	NR	NR	0
NJ MANIFEST	0.250		4	1	NR	NR	NR	5 2
PA MANIFEST	0.250		0	2	NR	NR	NR	2
NY MANIFEST	0.250		0	2	NR	NR	NR	2
INDIAN RESERV	1.000		0	0	0	0	NR	0
SCRD DRYCLEANERS	0.500		0	0	0	NR	NR	0
US AIRS	TP		NR	NR	NR	NR	NR	0
PRP	TP		NR	NR	NR	NR	NR	0
EPA WATCH LIST	TP		NR	NR	NR	NR	NR	0
US FIN ASSUR PCB TRANSFORMER	TP TP		NR NR	NR NR	NR NR	NR NR	NR NR	0
COAL ASH DOE	TP		NR NR	NR NR	NR NR	NR NR	NR NR	0 0
COAL ASH EPA	0.500		0	0	0	NR	NR	0
LEAD SMELTERS	0.500 TP		NR	NR	NR	NR	NR	0
2020 COR ACTION	0.250		0	0	NR	NR	NR	0
EDR HIGH RISK HISTORICAL RECORDS								
EDR Exclusive Records								
EDR MGP	1.000		0	0	0	0	NR	0
EDR US Hist Auto Stat EDR US Hist Cleaners	0.250 0.250		5 2	4 3	NR NR	NR NR	NR NR	9 5

# NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

MAP FINDINGS Map ID

Direction Distance

**EDR ID Number** Elevation Site Database(s) **EPA ID Number** 

DOD **NAVAL STATION ANACOSTIA** DOD CUSA133908 Region N/A

**NAVAL STATION ANACOSTIA (County), DC** 

< 1/8 1 ft.

DOD:

Navy DOD Feature 1: Not reported Feature 2: Not reported Feature 3: URL: Not reported

Name 1: Naval Station Anacostia

Name 2: Not reported Name 3: Not reported

State: DC DOD Site: Yes

Tile name: **DCWASHINGTON** 

NPL **WASHINGTON NAVY YARD** Region 1013 O STREET SE ENE WASHINGTON NAVY YARD, DC 20374 1/2-1

**CORRACTS RCRA-LQG** 3372 ft. **US ENG CONTROLS** ROD **NY MANIFEST PA MANIFEST** 

NPL:

EPA ID: DC9170024310

EPA Region: 03 Υ Federal:

Final Date: 1998-07-28 00:00:00

Site Details:

WASHINGTON NAVY YARD Site Name:

Site Status: Final Site Zip: 203740001 WASHINGTON Site City:

Site State: DC Federal Site: Yes

DISTRICT OF COLUMBIA Site County:

EPA Region: 03 03/06/98 Date Proposed: Date Deleted: Not reported 07/28/98 Date Finalized:

Substance Details:

NPL Status: Currently on the Final NPL

Not reported Substance ID: Not reported Substance: CAS #: Not reported Pathway: Not reported Not reported Scoring:

NPL Status: Currently on the Final NPL

Substance ID:

ANTIMONY AND COMPOUNDS Substance:

CAS #: Not reported

NO PATHWAY INDICATED Pathway:

NPL

**CERCLIS** 

1000147680 DC9170024310 Map ID MAP FINDINGS

Direction Distance

Elevation Site Database(s) EPA ID Number

#### WASHINGTON NAVY YARD (Continued)

1000147680

**EDR ID Number** 

Scoring:

NPL Status: Currently on the Final NPL

Substance ID: A005

Substance: ARSENIC AND COMPOUNDS

CAS #: Not reported

Pathway: SURFACE WATER PATHWAY

Scoring: 4

NPL Status: Currently on the Final NPL

Substance ID: A011

Substance: BERYLLIUM AND COMPOUNDS

CAS #: Not reported

Pathway: SURFACE WATER PATHWAY

Scoring: 4

NPL Status: Currently on the Final NPL

Substance ID: A020

Substance: CHROMIUM AND COMPOUNDS

CAS #: Not reported

Pathway: SURFACE WATER PATHWAY

Scoring: 4

NPL Status: Currently on the Final NPL

Substance ID: A038

Substance: NICKEL AND COMPOUNDS

CAS #: Not reported

Pathway: NO PATHWAY INDICATED

Scoring: 1

NPL Status: Currently on the Final NPL

Substance ID: A046

Substance: POLYCHLORINATED BIPHENYLS

CAS #: 1336-36-3

Pathway: SURFACE WATER PATHWAY

Scoring: 4

NPL Status: Currently on the Final NPL

Substance ID: A048

Substance: SELENIUM AND COMPOUNDS

CAS #: Not reported

Pathway: NO PATHWAY INDICATED

Scoring: 1

NPL Status: Currently on the Final NPL

Substance ID: A049

Substance: SILVER AND COMPOUNDS

CAS #: Not reported

Pathway: SURFACE WATER PATHWAY

Scoring: 2

NPL Status: Currently on the Final NPL

Substance ID: C178

Substance: COPPER AND COMPOUNDS

CAS #: Not reported

Pathway: SURFACE WATER PATHWAY

Scoring: 2

Direction Distance Elevation

vation Site Database(s) EPA ID Number

#### **WASHINGTON NAVY YARD (Continued)**

1000147680

**EDR ID Number** 

NPL Status: Currently on the Final NPL

Substance ID: C247

Substance: ZINC AND COMPOUNDS

CAS #: Not reported

Pathway: SURFACE WATER PATHWAY

Scoring: 2

NPL Status: Currently on the Final NPL

Substance ID: C460 Substance: MERCURY CAS #: 7439-97-6

Pathway: SURFACE WATER PATHWAY

Scoring: 2

NPL Status: Currently on the Final NPL

Substance ID: D006

Substance: CADMIUM (CD) CAS #: 7440-43-9

Pathway: SURFACE WATER PATHWAY

Scoring: 4

NPL Status: Currently on the Final NPL

Substance ID: D008 Substance: LEAD (PB) CAS #: 7439-92-1

Pathway: SURFACE WATER PATHWAY

Scoring: 4

#### Summary Details:

Conditions at Proposal March 1998): The Washington Navy Yard WNY) is the oldest continuously operated Navy facility in the United States. It currently occupies 71.5 acres in the District of Columbia. The facility was opened officially on October 2, 1799. By 1812, it was well equipped for the purpose of shipbuilding and repair. During the 1800s, ordnance production, research, and other industrial activities were prevalent at the yard. In 1886, the WNY was redesignated as the Naval GunFactory. During the next 20 years considerable expansion of the WNY occurred. Production of ordnance remained the primary operational activity at the facility during this time. To accommodate the WNY, significant areas of adjacent marshlands werefilled in. In the 1940s, the primary role of the WNY shifted from production of ordnance to administrative activities. Although administrative activities became a large function of the WNY, all ordnance production still was monitored or tested at the facility. To accommodate the expanded activity, new administrative and research facilities were constructed on the eastern portion of the facility. In 1961, the WNY officially became an administrative facility. Activities currently conducted at the WNY include administration, supply and storage, and training. An historic center that is open to the public is also currently located at the WNY. Records documenting the wastes generated during ordnance production or the various other industrial processes that occurred at the WNY have not been located. However, based on the descriptions of the documented operations at the WNY the typical wastes generated can be reasonably determined. These wastes would include metals usedin ordnance production and paint-spraying; solvents used in cleaning; cyanide and phenols used in cooling processes; creosote used in wood treatment; petroleum products and wastes; and PCB-containing oils in storage tanks and electrical equipment. Contamination also likely occurred during storage and handling of raw materials. The storm water system draining the facility

Direction Distance Elevation

evation Site Database(s) EPA ID Number

## WASHINGTON NAVY YARD (Continued)

1000147680

**EDR ID Number** 

is contaminated with metals and PCBs, which can be attributed to the industrial processes and ordnance production that historically occurred at the facility. The storm water system leads to nine outfalls into the Anacostia River. Sediment sampling of the Anacostia River in the area of the WNY shows metals and PCB contamination. In addition, volatile and semi-volatile contaminants have been found in soils throughout the facility, although sufficient documentation does not exist to fully evaluate this contamination at this time. Status July 1998): Remedial activities currently in progress involve the investigation and removal of contaminated sediments from the stormwater system. The description of the site release) is based on information available at the time the site was scored. The description may change as additional information is gathered on the sources and extent of contamination. See 56 FR 5600, February 11, 1991, of subsequent FR notices.

Site Status Details:

NPL Status: Final
Proposed Date: 03/06/1998
Final Date: 07/28/1998
Deleted Date: Not reported

Narratives Details:

NPL Name: WASHINGTON NAVY YARD

City: WASHINGTON

State: DC

CERCLIS:

Site ID: 0300031 EPA ID: DC9170024310

Facility County: DISTRICT OF COLUMBIA Short Name: WASHINGTON NAVY YARD

Congressional District: 01
IFMS ID: 03SA
SMSA Number: Not reported
USGC Hydro Unit: 02070010
Federal Facility: Federal Facility
DMNSN Number: 63.30000

DMNSN Number: 63.30 Site Orphan Flag: N

RCRA ID: Not reported USGS Quadrangle: Not reported Site Init By Prog: Not reported NFRAP Flag: Not reported Parent ID: Not reported RST Code: Not reported

EPA Region: 03

Classification: Not reported

Site Settings Code: CL

NPL Status: Currently on the Final NPL

DMNSN Unit Code: ACRE
RBRAC Code: Not reported
RResp Fed Agency Code: USNV
Non NPL Status: Not reported
Non NPL Status Date: / /
Site Fips Code: 11001
CC Concurrence Date: / /

CC Concurrence FY: Not reported Alias EPA ID: Not reported

Direction Distance

Elevation Site Database(s) EPA ID Number

#### **WASHINGTON NAVY YARD (Continued)**

1000147680

**EDR ID Number** 

Site FUDS Flag: N

CERCLIS Site Contact Name(s):

 Contact ID:
 3270057.00000

 Contact Name:
 DAVID POLISH

 Contact Tel:
 (215) 814-3327

Contact Title: Community Involvement Coordinator

Contact Email: Not reported

 Contact ID:
 3000181.00000

 Contact Name:
 ROBERT W. STROUD

 Contact Tel:
 (215) 814-3366

Contact Title: Remedial Project Manager (RPM)

Contact Email: Not reported

 Contact ID:
 13003535.00000

 Contact Name:
 Joseph Vitello

 Contact Tel:
 (215) 814-3354

Contact Title: Site Assessment Manager (SAM)

Contact Email: Not reported

CERCLIS Site Alias Name(s):

Alias ID: 101

Alias Name: USN WASHINGTON NAVAL DIST BLDG 170

Alias Address: Not reported

WASHINGTON, DC

Alias ID: 103

Alias Name: WASHINGTON NAVY YARD

Alias Address: 901 M STREET, SE

WASHINGTON, DC 20003

Alias ID: 3270050

Alias Name: WASHINGTON NAVY YARD
Alias Address: 1014 N STREET SE SUITE 3207

WASHINGTON, DC 23185

Alias Comments: Not reported

Site Description: The Washington Navy Yard (WNY) covers 63.3 acres and borders the Anacostia

River in southeastern Washington, D.C. Commercial and vacant commercial properties along M Street border the facility on the north, commercial properties and a former industrial area along 11th Street on the east, the Southeast Federal Center (SEFC) on the west, and the Anacostia River on the south. The WNY consists primarily of buildings and other impervious surfaces with little vegetated area. The WNY's role throughout its two centuries of operation has been primarily ordnance production and research, but it also has included shipbuilding and repair, industrial development, and heavy equipment manufacturing. After World War II, the WNY's role shifted from manufacturing to administration. Currently, the WNY includes administrative, supply, and storage buildings; residences; training facilities; and museums. Buildings and other impervious surfaces cover approximately 95 percent of the area surfaces at the WNY. Eleven operable units for the WNY are identified on the EPA website. Site 4 is listed as Operable Unit 04. Site 4 includes Buildings 44, 46, 67, and 108 located in the central area of the WNY. Building 44 has been used for administrative offices and is now also used for the Navy Library. Building 46 is located on Harwood Street and was formerly a cartridge-case and metal-pressing shop but now contains the Navy Exhibit Center, a shop, and a warehouse. A sub-basement of Building 46 was reportedly used as a jail during the 19th century. The present-day Building 67 had formerly been designated as

Site

MAP FINDINGS

Database(s)

#### **WASHINGTON NAVY YARD (Continued)**

1000147680

**EDR ID Number** 

**EPA ID Number** 

two buildings-Building 66 at the southern end and Building 67 at the northern end. Building 67 was used as a cartridge case, metal-pressing shop, primer shop, and furnace room, and it is now an art gallery. Building 108, currently used for administrative purposes, had been used as an anchor shop, a cartridge-case shop, and the Naval Gun Factory Laboratory. The Naval Gun Factory Laboratory consisted of a Metals Engineering Branch, Chemistry Branch, Metallurgy Branch, and a Welding Engineering Branch. The primary mission of the laboratory was to support the Naval Gun Factory and Bureau of Ordnance. Because the laboratory was used to support ordnance manufacture-related issues, and not industrial processes, the amount of chemicals used is believed to have been insignificant. On July 16, 1997, the EPA and the Navy entered into a Consent Order to perform a RCRA Facility Investigation (RFI) at the WNY, to determine the nature and extent of potential releases of hazardous wastes, solid wastes, and/or hazardous constituents at or from the WNY. On March 6, 1998, the EPA proposed the WNY for listing on the Federal Facilities section of the National Priorities List (NPL). The WNY was added to the NPL through a final rule in the Federal Register on July 28, 1998. An Interagency agreement (Federal Facilities Agreement [FFA]) between EPA Region III, the District of Columbia, and the Navy was signed on June 30, 1999. With the final FFA in place, the Navy functions as the lead agency for the management and cleanup of the WNY IR sites. Effective on September 27, 1999, the FFA superseded the Resource Conservation and Recovery Act (RCRA) Final Administrative Order of Consent signed on July 16, 1997. Site 4 was identified in the FFA as Buildings 44, 46. 108 and 67 (Cartridge Case Shop). The current use for each Site 4 building is presented below: Building 44 - Administrative offices and Navy library Building 46 - Navy Exhibit Center, a shop, and a warehouse Building 67 - Art gallery Building 108 - Administrative offices Since Site 4 consists of buildings, pavement, or similar impervious surfaces, there is no current exposure to the soil at Site 4. The Naval Station Washington Master Plan indicates that the buildings will continue to be used at the WNY with proposed future uses for administrative offices and museum space consistent with current building uses. Therefore, it is unlikely that there will be exposure to soil at Site 4 in the future. A No Action Record of Decision (ROD) addressing Operable Unit 04 was completed in September 2004. Operable Unit 10: Site 10 consists of four discontinuous areas. The largest area is located in the north-central portion of the WNY, and is commonly called Admiral's Row. The site consists of 17 buildings, structures, and areas associated with Flag (admiral and captain) Housing and ceremonial uses. The buildings are currently used for residential purposes, except Building 1, which is used as administrative offices. The topography at Site 10 gradually slopes to the south toward the Anacostia River. The soil underlying the Site 10 area consists of non-native and man-made fill and naturally-deposited soil material. Approximately 35 percent of the ground surface is covered with pavement and buildings with most of the uncovered, grassy area focused in Leutze Park located west of Quarters B. Site 10 includes Quarters A through H, K through P, R through W, and Y; Building 1; Admiral Leutze Park; and the Latrobe Gate. Only four of the buildings (Quarters N, O, and U and Building 1) have been used for functions other than housing: -Quarters N and O were built in 1866 originally as Paint Shop #1 and remodeled into living quarters around 1900. - Quarters U (Building 195) was constructed in 1937 as a training building, and shortly before World War II it was used as an experimental-ammunition building by the Naval Research Laboratory. From about 1946 to 1950, the building was used by the WNY transportation department and then converted into the WNY Naval Reserve Center. In 1965, the building was converted into officer quarters and redesignated "Quarters U". - Building 1 (also referred to as "Quarters J") was constructed about 1840 to serve as the Commandant's Office and was used as administrative offices (intelligence

Site

#### MAP FINDINGS

Database(s)

EDR ID Number EPA ID Number

#### **WASHINGTON NAVY YARD (Continued)**

1000147680

office, post office, communications office, and credit union office) until about 1948, when it was remodeled into multiple living quarters and called Quarters J. In the early 2000's, it again underwent extensive remodeling and now serves as administrative offices. Investigations at the WNY have found some areas of lead-contaminated soil at Site 10. Past maintenance of these buildings with exterior lead-based paints and lead roofing materials is believed to be the source of lead contamination in soil. Before health hazards associated with lead were understood, lead was used in paint and many other products. Although the federal government banned lead-based paint from housing in 1978, many older homes still contain lead-based paint. In 1993, the Navy prepared a Preliminary Assessment (PA) report for the WNY. The 1993 PA used historical documents, personnel interviews, and consultation with the District and federal agencies to identify 16 areas of concern at the WNY requiring further study. Site 10 was one of the areas identified. In 1995, the Navy presented the results of the investigation of 13 sites and 2 areas of concern at WNY in the Site Investigation report for the WNY. This report included results for the Site 10 area. The field investigation related to Site 10 included the collection of groundwater, surface soil, and subsurface soil. The results of the investigation revealed that the primary ways people could be exposed to contaminants at Site 10 were by ingesting (accidentally swallowing) surface soil or subsurface soil. In 1998, soil sampling was conducted at Quarters A (Tingey House) to assess the presence of lead in surface soil. This sampling was performed as a precaution given the findings of lead in soil at other residential locations on the WNY (Site 10). Based on the results, Quarters A was added to Site 10. As part of the 1999 Facility-Wide Remedial Investigation (RI), a Facility-Wide Hydrogeologic Investigation was performed for 9 sites, including Site 10. The purpose of the investigation at Site 10 was to evaluate the presence of lead in groundwater as a result of previous soil sampling performed at Site 10 that indicated the elevated presence of lead in soil. This investigation included soil and groundwater sampling. The results of the investigation did not indicate unacceptable levels of lead in the groundwater, but recommended additional groundwater sampling for various constituents detected in soil (benzo (a) pyrene, copper and manganese). In 2002, a Phase II Investigation was conducted at Site 10 that involved subsurface soil sampling to delineate the vertical extent of the lead concentrations in soil. The investigation characterized the vertical extent of lead in soil to a depth of 4 feet below ground surface. Several samples were also analyzed for other metals and pesticides in order to provide data to complete the human health risk assessment. The data collected in this investigation was compiled and reported in the 2004 Focused RI for Site 10. In 2004, a Focused RI report for Site 10 was completed. This report compiled all data collected to date at Site 10 and provided a full characterization of the nature and extent of soil contamination. The data compiled included analytical results from groundwater samples and from more than 550 soil samples collected between 1995 and 2004. These data were used to assess potential risk to people and the environment and to establish whether or not the site is a source of lead contamination to groundwater. A Feasibility Study (FS) was recommended based on the potential hazards associated with people and plants being exposed to lead in soil at the site. In lieu of conducting a FS, and as a conservative and protective measure, a series of non time- critical removal actions were recommended for all areas within Site 10 with surface soil concentrations of lead greater than 400 parts per million (ppm). This is the conservative screening value established by EPA to be protective of children in a residential setting. Following the 2004 Focused RI, institutional controls (ICs) were put in place at Site 10 to reduce the chance people would be exposed to contaminants. These controls included restrictions on gardening by residents and training the WNY's professional

Site

#### MAP FINDINGS

Database(s)

EDR ID Number EPA ID Number

#### **WASHINGTON NAVY YARD (Continued)**

1000147680

gardener how to safely handle dirt, grass clippings and other plant materials that could contain lead. These restrictions were communicated to the residents and workers who lived or worked at these quarters in 2004 through a fact sheet and an information session. Subsequent residents and workers were notified as they moved in or were hired. Between late 2003 and early 2008, a series of removal actions were completed at Site 10. The removal actions consisted of excavating soil to depths of between 1 and 4 feet where surface soil is exposed and lead levels exceeded 400 ppm, and replacing it with clean backfill. The history and background of the buildings at Site 10 indicate that the soils beneath patios, walkways, pavements or buildings would not have been impacted by lead-based paint maintenance activities. Therefore, soils beneath these areas were not disturbed. As the excavations progressed, sampling was used to verify that soil concentrations exceeding 400 ppm had been successfully removed or to recommend additional excavation. Approximately 2,175 cubic yards of soil were removed and disposed of at a landfill at a cost of approximately \$5 million. As each quarters, or group of quarters, were successfully remediated, ICs were removed. After completion of the non-time-critical soil removal actions at Site 10, no unacceptable human health or ecological risks were identified that require future action. The Site 10 Removal Action Master Report incorporates the results of the removal actions and the 313 confirmatory soil samples for Site 10. The results of these confirmatory soil-sampling activities indicated the soil throughout Site 10 was successfully remediated to concentrations less than 400 ppm. On July 16, 1997, the EPA and the Navy entered into a Consent Order to perform a Resource Conservation and Recovery Act (RCRA) Facility Investigation (RFI) at the WNY to determine the nature and extent of potential releases of hazardous wastes, solid wastes, and/or hazardous constituents at or from the WNY. The EPA's jurisdiction to issue the Consent Order derived from authority vested in EPA by Section 7003 of RCRA, as amended by the Hazardous and Solid Waste Amendments of 1984. Pursuant to CERCLA authority, on March 6, 1998, the EPA proposed the WNY for listing on the Federal Facilities section of the National Priorities List (NPL) by publishing a proposed rule in the Federal Register. The Federal Register notice announced EPA's public comment period for the proposed listing of the WNY (and several other sites) from March 6, 1998, through May 5, 1998. The WNY was added to the NPL through a final rule in the Federal Register on July 28, 1998. An Interagency Agreement (Federal Facilities Agreement [FFA]) between EPA Region III, the District of Columbia, and the Navy was signed on June 30, 1999. In accordance with Executive Order 12580 and the National Contingency Plan, the Navy functions as the lead agency for the management and cleanup of the WNY Installation Restoration Program sites under CERCLA. EPA, the Navy, and the DDOE work together as part of the WNY cleanup team. Effective September 27, 1999, the FFA superseded the July 16, 1997 RCRA Order. Currently, WNY includes administrative, supply, and storage buildings; residences; training facilities; and museums. Buildings and other impervious surfaces cover approximately 95 percent of the area surfaces. Leutze Park, in the facility's north-central portion, is the only substantial vegetated area in this largely urban setting. Approximately 35 percent of the ground surface at Site 10 is covered with pavement and buildings with most of the uncovered, grassy area focused in Leutze Park. The buildings and grounds that make up Site 10 are currently used for residences (quarters) for Navy officers and their families, except Building 1 (administrative offices) and Leutze Park, which is a manicured grass park used for ceremonies. The potential future exposure scenarios evaluated in the Human Health Risk Assessment and Environmental Risk Assessment for Site 10 addressed by this ROD conservatively assume that the sites will continue to be used for residential purposes, and that the subsurface soil may be excavated at some point in time and become surface soil so that there is a complete exposure pathway with future residents. A ROD

Site

#### MAP FINDINGS

Database(s)

#### **WASHINGTON NAVY YARD (Continued)**

1000147680

**EDR ID Number** 

**EPA ID Number** 

addressing Operable Unit 10 was completed in September 2009. OU 13: Operable Unit (OU) 13 is comprised of contaminated soils at Sites 1, 2, 3, 7, 9, 11, and 13. Each site is described below. Site 1: Site 1 is located near the center of the WNY, and consists of the soil beneath Building 22 plus approximately 40 feet of the immediately surrounding area to the west, north, and east; and is bounded to the south by Site 2. Site 1 is covered by buildings, pavement, and other impervious surfaces, and is currently used as office space, a fitness center, restaurants, and shops. Building 22 was a foundry used for melting and casting from 1858 through 1915, then for metal machining and assembly operations of various guns until the 1960s, when it became the Naval Station Laundry. By 1975, Building 22 had become the Radiation Effects Facility (RADEF) Instrumentation Test Facility. In 1990, it became the Naval Investigative Service (NIS) forensic lab, in which light machining, darkroom photo processing, and electronics work were performed. An underground storage tank (UST) identified as an emergency generator (oil)/dry cleaning products tank was also located north of Building 22. Two other USTs were located in an area that is the southwest corner of the current Building 22. Site 2: Site 2 is located near the center of the WNY, south of Site 1, and consists of the soil beneath Buildings 33, 37, 39, 109, and 36; which are multistoried brick structures known as the Quadrangle Complex. The site also includes approximately 40 ft of the immediately surrounding area to the west, south, and east, and is adjoined by Site 1 on the north. Site 2 is covered by buildings, pavements, and other impervious surfaces, and is currently used as office space. Site 2, the Quadrangle Complex, is believed to be the site of the original WNY machine shop, and was constructed in phases between 1854 and 1860 (with the exception of Building 37). Building 37 was constructed as a toilet (bathroom) in 1899. Industrial operations in the Quadrangle Complex buildings ceased in the early 1960s, when the WNY Naval Gun Factory was closed. In the years after the factory's closure, the Quadrangle Complex buildings served primarily as storage facilities for the Navy Exchange System and the WNY Supply Department. A battery shop, containing automotive-type batteries, was believed to have been located in former Building 33A, a small cinderblock addition to Building 33. In the late 1990s, all of the Quadrangle Complex buildings were fully gutted and renovated within the original building footprints. The original floor slabs were removed, and soil was excavated within each of the buildings to at least 3 ft below grade. Abandoned utilities were removed, and new utilities were installed under a new reinforced concrete floor. During the excavation activities, a 1,000-gallon UST was discovered under Building 109. It was believed that the UST was used to store heating oil for the building. The UST was removed in 1996. Because there was some evidence of a release related to this tank, a site characterization investigation was conducted in accordance with the District of Columbia Department of Health (DCDOH) UST Division procedures and, after several rounds of groundwater monitoring, the case was closed out in 1998. The renovated buildings were installed with an under-slab ventilation system. Although a specific explanation as to the purpose of this system has not been found, one likely explanation is that it was installed as a protective measure for residual petroleum found in the soil during the UST site characterization. Site 3: Site 3 is also located near the center of the WNY, immediately east of Site 1. It consists of the area formerly occupied by Buildings 40 and 41. Buildings 40 and 41 were demolished in 1977; no buildings are currently located on the site, which is now a park. Buildings 40 and 41 were constructed in 1892 and 1859, respectively, and were previously connected to still-existing Building 76, which is located south of Site 3. In the 1950s, electroplating in Building 41 was performed on gun parts, using a number of plating solutions containing chrome, zinc, nickel, copper, brass, gold, silver, and rhodium, Electroplating operations in Building 41 consisted of three deep plating pits (one 75 ft deep

Site

MAP FINDINGS

Database(s)

#### **WASHINGTON NAVY YARD (Continued)**

1000147680

**EDR ID Number** 

**EPA ID Number** 

and two 60 ft deep) and a number of other plating and storage tanks. The deep pits were located approximately 60 feet north of Building 76. Buildings 40 and 41 were demolished owing to their contamination with acid fumes from the electroplating process. Much of the buildings' foundations, including the former electroplating pits, were left in place. The presence of remnant building foundations has been confirmed during the Phase II Remedial Investigation (RI), when large concrete and brick blocks were encountered in the Site 3 area during drilling activities. Some underground rooms reportedly are still intact under Dahlgren Avenue west of the area formerly occupied by the buildings. These underground rooms remain as underground void spaces; they are not used for any purpose and are not accessible for occupancy. Based on the historical review of Buildings 40 and 41, no spills or releases to the soil or groundwater have been documented at Site 3; however, the possibility exists that undocumented spills or releases may have occurred. Site 7: Site 7, located near the eastern boundary of WNY, consists of Building 126 and approximately 10 ft of the immediately surrounding are to the west, north, and east. Site 7 is covered by buildings, pavement, and other impervious surfaces, and is currently used as office space. Building 126 is approximately 65 years old and currently houses the Naval District Washington Security Division. From 1938 to 1950, Building 126 was the receiving station laundry, in which clothes were washed, starched, and pressed. According to the historical review, no dry-cleaning activities were performed in Building 126. Based on the historical review, no documented spills or releases to the soil or groundwater at Site 7 have been documented; however, the possibility exists that undocumented spills or releases may have occurred. Site 9, located in the northeastern corner of the WNY, consists of soil beneath Buildings 219 and 220 and approximately 10 to 50 ft of the immediately surrounding area. It is covered by buildings, pavement, and other impervious surfaces. Buildings 219 and 220 are four-story brick-and-concrete buildings that were constructed in 1944 and are currently used for office space. From 1944 through 1962, Building 219 was used as a gauge laboratory and machine shop for manufacturing precision instruments; for a period of time it was used as a U.S. Geological Survey (USGS) laboratory for the study of uranium and other radioactive raw materials on behalf of the Atomic Energy Commission. The floors of Building 219 were concrete and covered with creosoted wood blocks in the shop areas and asphalt tile in the administrative areas. Building 220 was used as an aviation ordnance shop to manufacture and test prototype aviation equipment such as bomb racks and rocket launchers. The shop comprised the following sections: woodworking, sheet metal fabricating and welding, heat treating (using a small on-floor grade cyanide heat-treating bath), instrument making (all types of precision instruments including bombsights and intervelometers), and general machining. Based on the historical review of activities at Buildings 219 and 220, no spills or releases to the soil or groundwater at Site 9 have been documented; however, the possibility exists that undocumented spills or releases may have occurred. Site 11: Site 11, located in the southeast corner of the WNY at the eastern extent of the Building 166 parking lot, consists of two former incinerators. Site 11 is entirely paved with asphalt and is not currently used. The incinerators were installed in 1967 and 1971 to burn classified materials from numerous government agencies in the Washington, D.C., area. Based on the fairly recent use of the incinerators on WNY (last 35 years) and the amount of covered area (from pavement, concrete, buildings, etc.) at WNY during that time, it is likely that any ash waste material from the incinerators was transported off-facility for disposal and not disposed of at WNY. Therefore, the potential release of contaminants associated with the incinerator is believed to be associated with the air emissions rather than soil and groundwater contamination from contacting buried ash material. Site 13: Site 13, located in north central section of the WNY, consists of the area

Site

#### MAP FINDINGS

Database(s)

EDR ID Number EPA ID Number

#### **WASHINGTON NAVY YARD (Continued)**

1000147680

around Building 290. The site is covered by a building with an unpaved (mulched), perimeter, and currently houses electrical equipment. Building 290 is suspected to have housed polychlorinated biphenyl (PCB)-containing equipment. Currently, WNY includes administrative, supply, and storage buildings; residences; training facilities; and museums. Buildings and other impervious surfaces cover approximately 95 percent of the area surfaces. Leutze Park, in the facility's north-central portion, is the only substantial vegetated area in this largely urban setting. Sites 1, 2, 7, and 9 currently have buildings on-site that are used as office space. Site 1 buildings are also used as a fitness center, restaurants, and shops. Site 3 is currently a park. Site 11 is not currently used, and is entirely paved with asphalt. Site 13 currently houses electrical equipment. The Naval Station Washington Master Plan details development and land use plans for the WNY. According to the Master Plan the future use of Sites 1, 2, 7, and 9 will remain consistent with current use and Sites 3 and 11 may be developed for office use in the future. The potential future exposure scenarios evaluated in the Human Health Risk Assessment for all seven sites addressed by this Record of Decision (ROD) conservatively assume that the subsurface soil will be excavated to a depth of 4 feet below ground surface and become surface soil, and that the sites will be redeveloped at some point for residential use. A ROD addressing OU13 was completed in December 2007. OU 14: Site 14 (Operating Unit 14) includes a single-story building (Building 292) on the WNY, located east of Willard Park, Building 292, currently used for storage, was formerly designated Electrical Substation "C" for the WNY. This site formerly included a transformer (on the west side of the building), and other electrical equipment that contained polychlorinated biphenyls (PCBs). Because the site is located near a storm sewer leading to Outfall 6, which discharges to the Anacostia River, the site may have contributed to historical sediment contamination in the sewer. Building 292 was also used to store unspecified maintenance materials for the bleacher seats formerly located west of Building 292. On July 16, 1997, the EPA and the Navy entered into a Consent Order to perform a Resource Conservation and Recovery Act (RCRA) Facility Investigation (RFI) at the WNY to determine the nature and extent of potential releases of hazardous wastes, solid wastes, and/or hazardous constituents at or from the WNY. The EPA's jurisdiction to issue the Consent Order derived from authority vested in EPA by Section 7003 of the RCRA, as amended by the Hazardous and Solid Waste Amendments of 1984. Pursuant to CERCLA authorities, on March 6, 1998, the EPA proposed the WNY for listing on the Federal Facilities section of the National Priorities List (NPL) by publishing a proposed rule in the Federal Register (volume 63, number 44, pages 11,340-11,345). The Federal Register notice announced EPA's public comment period for the proposed listing of the WNY (and several other sites) from March 6, 1998, through May 5, 1998. The WNY was added to the NPL through a final rule in the Federal Register on July 28, 1998 (volume 63, number 144, pages 40,182-40,188). An Interagency agreement (Federal Facilities Agreement [FFA]) between EPA Region III, the District of Columbia, and the Navy was signed on June 30, 1999. In accord with Executive Order 12580 and the National Oil and Hazardous Substances Pollution Contingency Plan (National Contingency Plan or NCP), the Navy functions as the lead agency for the management and cleanup of the WNY IR sites under CERCLA. Effective September 27, 1999, the FFA superseded the July 16, 1997 RCRA Order. Site 14 was identified in the FFA as Building 292. In 1995, Baker Environmental, Inc. (Baker) conducted a Site Investigation (SI) study on 13 sites and 2 Areas of Concern (AOCs), including Site 14. Surface soil samples and sub-basement surface water samples were collected during the investigation at Site 14 to assess the potential presence of PCBs originating from the electrical equipment previously located at Building 292. Surface soil samples at locations north. west, and south of Building 292 were field screened for PCBs during the SI.

Site

MAP FINDINGS

Database(s)

#### **WASHINGTON NAVY YARD (Continued)**

1000147680

**EDR ID Number** 

**EPA ID Number** 

Based on elevated PCB field screening results, four of these samples, collected from locations south of Building 292, were sent to a laboratory for PCB analysis, which indicated that PCBs were present in the surface soil. Based on the SI results, the Navy conducted a removal action in November 1997 to remove PCB-contaminated soil from a 28-by-22-foot area adjacent to, and south of, Building 292. Two separate excavation activities were performed, within the same excavation area, to fully remove PCB-contaminated soil. During these excavation activities, a display cannon on a 7-by-5-foot concrete pad was not moved; therefore, soil beneath the cannon was not evaluated for PCBs. Site 14 includes Building 292 and other asphalt and concrete-covered surfaces (e.g., pavement and sidewalks). The current use for the Site 14 building is storage. Since Site 14 consists of buildings, pavement, or similar impervious surfaces, there is no current exposure to the soil at Site 14. The Naval Station Washington Master Plan indicates that the future use of Site 14 will be as a concession stand with outdoor tables. The potential future exposure scenarios evaluated at Site 14 conservatively assumed that the subsurface soil will be excavated to a depth of 4 feet below ground surface and become surface soil. A Record of Decision (ROD) addressing Site 14 (OU14) was completed in October of 2005. Operable Unit (OU) 5: Site 5 (OU 05) is located in the northwestern portion of the WNY, encompassing the soil around Building 73. Site 5 primarily encompasses the soil around Building 73. Building 73 was constructed between 1898 and 1901 on the former site of Jeffers Square and Building 26. Building 73 originally served as the Secondary Mount Shop and contained machinery for assembling gun mounts and other miscellaneous activities. Starting in 1915, a portion of Building 73 was used to manufacture tubes that were used to launch torpedoes. Torpedoes themselves were not manufactured at this building. These manufacturing activities continued until the building was converted into the Boilermakers Shop Annex in 1949. The Boilermakers Shop Annex fabricated metal items such as girders, shields, and magazine guide tubes for rocket launchers. In 1952, a Welding Shop was added to the operations in Building 73. The Welding Shop in Building 73 housed transformers, generators, and an electric furnace. An aluminum shed was added to the building in 1955 to store oxygen and acetylene tanks. In the late 1950s, Building 73 was used as an aluminum cleaning facility. Ten tanks, approximately 6 feet wide, were located on the first floor of the building along the southern wall of the building. The degreaser tank, used as the first step of the aluminum cleaning process, was mounted in a pit approximately 4 feet below the concrete floor near the southwest corner of Building 73. Building 73 was converted to Administrative Offices in 1961. In 1965, the building was converted into storage space. After 1965, a classified disintegrator was installed in Building 73 to shred paper. During the 1970s or 1980s, the building served as a recreational facility and housed indoor tennis courts. In 1998 renovations began as a part of the Base Realignment and Closure (BRAC) -Naval Sea Command project, which involved converting Building 73 back to office space. It is anticipated that future use of Building 73 will remain as office space. The 1998 BRAC renovations included constructing the parking garage (Building 28) that is presently south of Building 73. The parking garage construction involved the demolition of two buildings (former Buildings 26 and 143). The entire area, including part of what is now Site 5, was excavated to varying depths, the soil was replaced with clean fill, and the surface was landscaped with mulch and shrubbery. Building 73 at Site 5 is currently used as office space. Building 28, which borders Site 5 to the south, is a parking garage. The area between the two buildings measures approximately 25 feet by 300 feet and consists of a concrete pedestrian walkway and landscaped planting areas with several benches. Future use of this area is expected to remain the same or similar (i.e., office, recreational, or industrial). Future use for residential purposes is possible, but is considered to be

Map ID MAP FINDINGS
Direction

Distance Elevation Site

Site Database(s) EPA ID Number

## WASHINGTON NAVY YARD (Continued)

1000147680

**EDR ID Number** 

unlikely. A Record of Decision addressing OU 05 (Site 5) was completed in September of 2006. OU 16: Site 16 (Operable Unit 06) is located in the south-central portion of the WNY, adjacent to the Anacostia River. Site 16 is a high-traffic area that is predominantly covered with asphalt, concrete, and buildings. Building 71 and the surrounding paved areas serve as restrooms and parking for visitors to the Navy Museum. The site also provides access to the adjacent Pier No. 2, where the display ship U.S.S. Barry is docked. Site 16 encompasses Building 71 and its former petroleum underground storage tanks (USTs), stormwater lines traversing the site, and an area where free-phase mercury was discovered in the subsurface soil. At one time, 13 petroleum USTs existed at Site 16, within and surrounding Building 71. Between November 1993 and March 1994, these USTs were either removed or abandoned in place. The USTs ranged in size from 550 to 10,000 gallons and contained waste oil, gasoline and diesel fuel. Currently, a corrective action plan (CAP) is being implemented at the Building 71 site under the Naval District Washington (NDW) UST Program through coordination with District of Columbia Department of the Environment (DDOE) UST Division. The CAP involves free-product removal and longterm groundwater monitoring. The stormwater lines that run through the site terminate at Outfalls 5 and 6. The main area of interest within Site 16 is a 12- x 12-foot (ft) area where free-phase mercury was discovered in 1996 in the subsurface soil and removed pursuant to the time-critical removal action performed in June 1999. The area where free-phase mercury was discovered in the subsurface is in the area of the former Building 146, which was built in 1916 and demolished in 1983. At various times throughout its existence, Building 146 housed an Airplane Motor Testing Shop, was used as a shipwright's shop, a diving school, and a public garage, and housed Navy administrative offices. The specific source of mercury release is unknown; however, gauges associated with diving apparatus may have contained mercury. Site 16 is predominantly covered with asphalt, concrete, and buildings, and is a high-traffic area for workers and visitors at the WNY. Building 71 and the surrounding paved areas serve as restrooms and parking for visitors to the Navy Museum. The site also provides access to the adjacent Pier No. 2, where the display ship U.S.S. Barry is docked. The Barry is also a destination for visitors to the WNY. Future use of this area is expected to be the same or similar (i.e., office, recreational, or industrial). Future use for residential purposes is possible, but is considered to be unlikely. A Record of Decision addressing OU 06 (Site 16) was completed in September of 2006.

#### **CERCLIS Assessment History:**

Action Code: 001

Action: DISCOVERY

Date Started: / /

Date Completed: 05/01/81
Priority Level: Not reported
Operable Unit: SITEWIDE

Primary Responsibility: EPA Fund-Financed

Planning Status: Not reported Urgency Indicator: Not reported Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 001

Action: PRELIMINARY ASSESSMENT

Date Started: 05/16/91 Date Completed: 05/16/91

Direction Distance

Elevation Site Database(s) EPA ID Number

## WASHINGTON NAVY YARD (Continued)

1000147680

**EDR ID Number** 

Priority Level: Deferred to RCRA (Subtitle C)

Operable Unit: SITEWIDE
Primary Responsibility: Federal Facilities
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 002

Action: PRELIMINARY ASSESSMENT

Date Started: 01/31/94

Date Completed: 09/14/94

Priority Level: Higher priority for further assessment

Operable Unit: SITEWIDE

Primary Responsibility: EPA Fund-Financed Planning Status: Not reported Urgency Indicator: Not reported Action Anomaly: EPA Fund-Financed Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 001

Action: HAZARD RANKING SYSTEM PACKAGE

Date Started: 09/01/95 Date Completed: 02/26/98

Priority Level: Being considered for proposal to the NPL

Operable Unit: SITEWIDE

Primary Responsibility: EPA Fund-Financed
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 001

Action: PROPOSAL TO NATIONAL PRIORITIES LIST

Date Started: / /

Date Completed: 03/06/98
Priority Level: Not reported
Operable Unit: SITEWIDE

Primary Responsibility: EPA Fund-Financed Planning Status: Not reported Urgency Indicator: Not reported Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 00°

Action: FINAL LISTING ON NATIONAL PRIORITIES LIST

Date Started: /

Date Completed: 07/28/98
Priority Level: Not reported
Operable Unit: SITEWIDE

Primary Responsibility: EPA Fund-Financed

Planning Status: Not reported
Urgency Indicator: Not reported

Direction Distance

Elevation Site Database(s) EPA ID Number

## WASHINGTON NAVY YARD (Continued)

1000147680

**EDR ID Number** 

Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 001

Action: FEDERAL FACILITY REMOVAL

06/02/99 Date Started: Date Completed: 06/16/99 Priority Level: Not reported Operable Unit: **SITEWIDE** Primary Responsibility: Federal Facilities Planning Status: Not reported Urgency Indicator: Not reported Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 001

Action: FEDERAL INTERAGENCY AGREEMENT

Date Started: 10/01/98
Date Completed: 06/30/99
Priority Level: Not reported
Operable Unit: SITEWIDE

Primary Responsibility: Federal Enforcement

Planning Status: Not reported Urgency Indicator: Not reported Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 001

Action: INTERAGENCY AGREEMENT NEGOTIATIONS

Date Started: 10/14/98 Date Completed: 06/30/99 Priority Level: Not reported Operable Unit: **SITEWIDE** Primary Responsibility: **Federal Facilities** Planning Status: Not reported Urgency Indicator: Not reported Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 00°

Action: ALTERNATIVE DISPUTE RESOLUTION

Date Started: 06/01/00
Date Completed: 12/30/00
Priority Level: Not reported
Operable Unit: SITEWIDE

Primary Responsibility: Federal Enforcement

Planning Status: Not reported Urgency Indicator: Not reported Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

MAP FINDINGS Map ID

Direction Distance

**EDR ID Number** Elevation Site Database(s) **EPA ID Number** 

## **WASHINGTON NAVY YARD (Continued)**

1000147680

800 Action Code:

FEDERAL FACILITY REMEDIAL INVESTIGATION/FEASIBILITY STUDY Action:

Date Started: 05/27/99 Date Completed: 09/28/04 Priority Level: Not reported SITE 4 Operable Unit:

Primary Responsibility: Federal Facilities Planning Status: Not reported Urgency Indicator: Not reported Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 013

Action: RECORD OF DECISION

Date Started: Date Completed: 09/28/04 Priority Level: Not reported SITE 4 Operable Unit:

Primary Responsibility: Federal Facilities Planning Status: Not reported Urgency Indicator: Not reported Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 017

FEDERAL FACILITY REMEDIAL INVESTIGATION/FEASIBILITY STUDY Action:

Date Started: 05/27/99 Date Completed: 10/14/05 Priority Level: Not reported Operable Unit: SITE 14 Federal Facilities Primary Responsibility: Planning Status: Not reported Urgency Indicator: Not reported Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 014

Action: RECORD OF DECISION

Date Started: 10/14/05 Date Completed: Priority Level: Not reported Operable Unit: SITE 14 Primary Responsibility: Federal Facilities Planning Status: Not reported Urgency Indicator: Not reported Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code:

Action: FEDERAL FACILITY REMEDIAL INVESTIGATION

Date Started: 11/01/05

Direction Distance

Elevation Site Database(s) EPA ID Number

## WASHINGTON NAVY YARD (Continued)

1000147680

**EDR ID Number** 

Date Completed: 12/23/05
Priority Level: Not reported
Operable Unit: NFA PHASE II SITES
Primary Responsibility: Federal Facilities
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 010

Action: FEDERAL FACILITY REMEDIAL INVESTIGATION/FEASIBILITY STUDY

Date Started: 05/27/99 Date Completed: 09/29/06 Priority Level: Not reported Operable Unit: BLDG 73 Primary Responsibility: **Federal Facilities** Planning Status: Not reported Urgency Indicator: Not reported Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 009

Action: FEDERAL FACILITY REMEDIAL INVESTIGATION/FEASIBILITY STUDY

Date Started: 05/26/00 Date Completed: 09/29/06 Priority Level: Not reported Operable Unit: BLDG 71-SITE 5 Primary Responsibility: Federal Facilities Planning Status: Not reported Urgency Indicator: Not reported Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 006

Action: RECORD OF DECISION

Date Started: / /
Date Completed: 09/29/06
Priority Level: Not reported
Operable Unit: BLDG 71-SITE 5
Primary Responsibility: Federal Facilities
Planning Status: Not reported
Urgency Indicator: Not reported

For detailed financial records, contact EDR for a Site Report.:

Not reported

Action Code: 007

Action Anomaly:

Action: RECORD OF DECISION

Date Started: //
Date Completed: 09/29/06
Priority Level: Not reported
Operable Unit: BLDG 73

Direction Distance

Elevation Site Database(s) EPA ID Number

#### **WASHINGTON NAVY YARD (Continued)**

1000147680

**EDR ID Number** 

Primary Responsibility: Federal Facilities
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 005

Action: FEDERAL FACILITY REMOVAL

Date Started: 12/05/06 Date Completed: 08/20/07 Priority Level: Not reported Operable Unit: SITE 6 Primary Responsibility: Federal Facilities Planning Status: Not reported Urgency Indicator: Not reported Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 002

Action: ENGINEERING EVALUATION/COST ANALYSIS

Date Started: 12/05/06
Date Completed: 08/20/07
Priority Level: Not reported
Operable Unit: SITE 6
Primary Responsibility: Federal Facilities
Planning Status: Not reported

Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 021

Action: RECORD OF DECISION

Date Started: / /

Date Completed: 12/20/07
Priority Level: Not reported

Operable Unit: NFA PHASE II SITES
Primary Responsibility: Federal Facilities
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 002

Action: FEDERAL FACILITY REMOVAL

Date Started: 06/01/04
Date Completed: 05/15/08
Priority Level: Not reported

Operable Unit:
Primary Responsibility:
Planning Status:
Urgency Indicator:

ADMIRALS QUARTERS
Federal Facilities
Not reported
Not reported

Direction Distance

Elevation Site Database(s) EPA ID Number

## WASHINGTON NAVY YARD (Continued)

1000147680

**EDR ID Number** 

Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 014

Action: FEDERAL FACILITY REMEDIAL INVESTIGATION/FEASIBILITY STUDY

Date Started: 10/12/01
Date Completed: 09/18/09
Priority Level: Not reported

Operable Unit: ADMIRALS QUARTERS

Primary Responsibility: Federal Facilities
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 020

Action: RECORD OF DECISION

Date Started: / /

Date Completed: 09/18/09
Priority Level: Not reported

Operable Unit:
Primary Responsibility:
Planning Status:
Urgency Indicator:
Action Anomaly:

ADMIRALS QUARTERS
Federal Facilities
Not reported
Not reported
Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 019

Action: FEDERAL FACILITY REMEDIAL INVESTIGATION/FEASIBILITY STUDY

Date Started: 03/31/06 Date Completed: 09/29/11 Priority Level: Not reported Operable Unit: SITE 17 Primary Responsibility: Federal Facilities Planning Status: Not reported Urgency Indicator: Not reported Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 025

Action: RECORD OF DECISION

Date Started:

Date Completed: 09/29/11
Priority Level: Not reported
Operable Unit: SITE 17
Primary Responsibility: Federal Facilities
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

MAP FINDINGS Map ID

Direction Distance

**EDR ID Number** Elevation Site Database(s) **EPA ID Number** 

## **WASHINGTON NAVY YARD (Continued)**

1000147680

Action Code: 001

Action: Restoration Advisory Board

Date Started: 10/15/97 Date Completed:

Priority Level: Not reported SITEWIDE Operable Unit: Primary Responsibility: Federal Facilities Planning Status: Not reported Urgency Indicator: Not reported Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 002

FEDERAL FACILITY REMEDIAL INVESTIGATION/FEASIBILITY STUDY Action:

Date Started: 03/25/99 Date Completed: 11

Priority Level: Not reported

Operable Unit: ANACOSTIA RIVER SEDIMENT

Federal Facilities Primary Responsibility: Planning Status: Not reported Urgency Indicator: Not reported Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 002

Action: FEDERAL FACILITY REMEDIAL DESIGN

10/01/01 Date Started: Date Completed: //

Priority Level: Not reported

Operable Unit: ANACOSTIA RIVER SEDIMENT

Primary Responsibility: Federal Facilities Planning Status: Not reported Not reported Urgency Indicator: Not reported Action Anomaly:

For detailed financial records, contact EDR for a Site Report.:

005 Action Code:

FEDERAL FACILITY REMEDIAL INVESTIGATION/FEASIBILITY STUDY Action:

Date Started: 07/30/04 Date Completed:

Priority Level: Not reported GROUNDWATER Operable Unit: Primary Responsibility: Federal Facilities Planning Status: Not reported Urgency Indicator: Not reported Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 001

Action: FEDERAL FACILITY REMEDIAL INVESTIGATION

Date Started: 03/29/06 Date Completed:

MAP FINDINGS Map ID

Direction Distance

**EDR ID Number** Elevation Site Database(s) **EPA ID Number** 

## **WASHINGTON NAVY YARD (Continued)**

1000147680

Operable Unit: SITE 6

Primary Responsibility: Federal Facilities Planning Status: Not reported Urgency Indicator: Not reported Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Action Code: 018

Action: FEDERAL FACILITY REMEDIAL INVESTIGATION/FEASIBILITY STUDY

Date Started: 05/15/06 Date Completed: 11 Priority Level: Not reported

Operable Unit: SITE 8 Primary Responsibility: Federal Facilities Planning Status: Not reported Urgency Indicator: Not reported

For detailed financial records, contact EDR for a Site Report.:

Not reported

Action Code: 006

Action Anomaly:

Action: FEDERAL FACILITY REMEDIAL INVESTIGATION/FEASIBILITY STUDY

Date Started: 07/01/06 Date Completed: 11

Priority Level: Not reported

Operable Unit: ANACOSTIA RIVER SEDIMENT

Primary Responsibility: **Federal Facilities** Planning Status: Not reported Urgency Indicator: Not reported Action Anomaly: Not reported

For detailed financial records, contact EDR for a Site Report.:

Federal Register Details:

Fed Register Date: 07/28/98 Fed Register Volume: 63 Page Number: 40182

Fed Register Date: 03/06/98 Fed Register Volume: 63 Page Number: 11340

> Click this hyperlink while viewing on your computer to access 102 additional US CERCLIS Financial: record(s) in the EDR Site Report.

#### CORRACTS:

EPA ID: DC9170024310

EPA Region: 03 Area Name: SITE 14 Actual Date: 19980217

Action: CA600SR - Stabilization Measures Implemented, Primary measure is

source removal and/or treatment

Direction Distance

Elevation Site Database(s) EPA ID Number

## WASHINGTON NAVY YARD (Continued)

1000147680

**EDR ID Number** 

NAICS Code(s): 92811

Original schedule date: Not reported Schedule end date: Not reported

EPA ID: DC9170024310

EPA Region: 03
Area Name: SITE 6
Actual Date: 19980217

Action: CA600SR - Stabilization Measures Implemented, Primary measure is

source removal and/or treatment

NAICS Code(s): 92811

**National Security** 

Original schedule date: Not reported Schedule end date: Not reported

EPA ID: DC9170024310

EPA Region: 03

 Area Name:
 OUTFALL 1

 Actual Date:
 19980611

 Action:
 CA611

 NAICS Code(s):
 92811

National Security

Original schedule date: 19971231 Schedule end date: Not reported

EPA ID: DC9170024310

EPA Region: 03
Area Name: SITE 10
Actual Date: 19980611
Action: CA611
NAICS Code(s): 92811

**National Security** 

Original schedule date: 19971231 Schedule end date: Not reported

EPA ID: DC9170024310

EPA Region: 03

Area Name: ENTIRE FACILITY

Actual Date: 19980612

Action: CA600SR - Stabilization Measures Implemented, Primary measure is

source removal and/or treatment

NAICS Code(s): 92811

National Security

Original schedule date: Not reported Schedule end date: Not reported

EPA ID: DC9170024310

EPA Region: 03

Area Name: ENTIRE FACILITY

Actual Date: 19970716

Action: CA100 - RFI Imposition

NAICS Code(s): 92811

National Security

Original schedule date: 19970306 Schedule end date: Not reported

MAP FINDINGS Map ID

Direction Distance

**EDR ID Number** Elevation Site Database(s) **EPA ID Number** 

## **WASHINGTON NAVY YARD (Continued)**

1000147680

EPA ID: DC9170024310

EPA Region: 03 Area Name: SITE 16 Actual Date: 19980814

Action: CA150 - RFI Workplan Approved

NAICS Code(s): 92811

**National Security** Original schedule date: Not reported Schedule end date: Not reported

DC9170024310 EPA ID:

EPA Region: 03

**ENTIRE FACILITY** Area Name:

Actual Date: 19960829

Action: CA070YE - RFA Determination Of Need For An RFI, RFI is Necessary

NAICS Code(s): 92811

National Security

Original schedule date: Not reported Schedule end date: Not reported

EPA ID: DC9170024310 EPA Region: 03 Area Name: **ENTIRE FACILITY** 

Actual Date: 19980922

Action: CA210SF - CA Responsibility Referred To A Non-RCRA Federal Authority,

Corrective Action at the facility or area referred to CERCLA

NAICS Code(s): 92811

> National Security Not reported

Original schedule date: Schedule end date: Not reported

EPA ID: DC9170024310

EPA Region: Area Name: SITE 14 19970929 Actual Date: CA611 Action: NAICS Code(s): 92811

**National Security** 

Original schedule date: Not reported Schedule end date: Not reported

EPA ID: DC9170024310

EPA Region: 03 Area Name: SITE 6 Actual Date: 19970929 Action: CA611 NAICS Code(s): 92811

**National Security** Original schedule date: Not reported Schedule end date: Not reported

EPA ID: DC9170024310

EPA Region: 03

Area Name: **ENTIRE FACILITY** Actual Date: 19960930

Action: CA075HI - CA Prioritization, Facility or area was assigned a high

corrective action priority

MAP FINDINGS Map ID

Direction Distance

Elevation Site Database(s) **EPA ID Number** 

**WASHINGTON NAVY YARD (Continued)** 

NAICS Code(s): 92811

**National Security** Original schedule date: Not reported Schedule end date: Not reported

EPA ID: DC9170024310

EPA Region: 03

Area Name: **OUTFALL 5** Actual Date: 19961026

Action: CA600SR - Stabilization Measures Implemented, Primary measure is

source removal and/or treatment

NAICS Code(s): 92811

**National Security** 

Original schedule date: Not reported Schedule end date: Not reported

EPA ID: DC9170024310

EPA Region: 03

Area Name: **OUTFALL 1** 19961026 Actual Date:

CA600SR - Stabilization Measures Implemented, Primary measure is Action:

source removal and/or treatment

NAICS Code(s): 92811

National Security Original schedule date: Not reported Not reported

EPA ID: DC9170024310

EPA Region:

Schedule end date:

**OUTFALL 10** Area Name: 19961026 Actual Date:

Action: CA600SR - Stabilization Measures Implemented, Primary measure is

source removal and/or treatment

NAICS Code(s): 92811

**National Security** 

Original schedule date: Not reported Schedule end date: Not reported

DC9170024310 EPA ID:

EPA Region: 03

**OUTFALL 10** Area Name: Actual Date: 19961026 Action: CA611 92811

NAICS Code(s):

**National Security** Original schedule date: Not reported Schedule end date: Not reported

EPA ID: DC9170024310

EPA Region: 03

Area Name: **OUTFALL 5** Actual Date: 19961026 Action: CA611 NAICS Code(s): 92811

**National Security** 

Original schedule date: Not reported Schedule end date: Not reported **EDR ID Number** 

1000147680

Direction Distance

Elevation Site Database(s) EPA ID Number

## WASHINGTON NAVY YARD (Continued)

1000147680

**EDR ID Number** 

EPA ID: DC9170024310

EPA Region: 03

Area Name: OUTFALL 2 Actual Date: 19981114

Action: CA600SR - Stabilization Measures Implemented, Primary measure is

source removal and/or treatment

NAICS Code(s): 92811

National Security

Original schedule date: Not reported Schedule end date: Not reported

EPA ID: DC9170024310

EPA Region: 03

Area Name: OUTFALL 1
Actual Date: 19981114

Action: CA600SR - Stabilization Measures Implemented, Primary measure is

source removal and/or treatment

NAICS Code(s): 92811

**National Security** 

Original schedule date: Not reported Schedule end date: Not reported

EPA ID: DC9170024310

EPA Region: 03

Area Name: OUTFALL 6 Actual Date: 19981114

Action: CA600SR - Stabilization Measures Implemented, Primary measure is

source removal and/or treatment

NAICS Code(s): 92811

**National Security** 

Original schedule date: Not reported Schedule end date: Not reported

EPA ID: DC9170024310

EPA Region: 03

Area Name: OUTFALL 9
Actual Date: 19981114

Action: CA600SR - Stabilization Measures Implemented, Primary measure is

source removal and/or treatment

NAICS Code(s): 92811

National Security

Original schedule date: Not reported Schedule end date: Not reported

EPA ID: DC9170024310

EPA Region: 03

Area Name: OUTFALL 8 Actual Date: 19981114

Action: CA600SR - Stabilization Measures Implemented, Primary measure is

source removal and/or treatment

NAICS Code(s): 92811

**National Security** 

Original schedule date: Not reported Schedule end date: Not reported

EPA ID: DC9170024310

EPA Region: 03

MAP FINDINGS Map ID

Direction Distance

**EDR ID Number** Elevation Site Database(s) **EPA ID Number** 

## **WASHINGTON NAVY YARD (Continued)**

1000147680

Area Name: **OUTFALL 3** Actual Date: 19981114

Action: CA600SR - Stabilization Measures Implemented, Primary measure is

source removal and/or treatment

NAICS Code(s): 92811

**National Security** 

Original schedule date: Not reported Schedule end date: Not reported

EPA ID: DC9170024310

EPA Region: 03

**OUTFALL 7** Area Name: Actual Date: 19981114

Action: CA600SR - Stabilization Measures Implemented, Primary measure is

source removal and/or treatment

NAICS Code(s): 92811

**National Security** 

Original schedule date: Not reported Schedule end date: Not reported

EPA ID: DC9170024310

EPA Region: 03

Area Name: SITE 13 Actual Date: Not reported

Action: CA110 - RFI Workplan Received

NAICS Code(s): 92811

**National Security** Original schedule date: 19981001 Schedule end date: Not reported

EPA ID: DC9170024310

EPA Region: 03 Area Name: SITE 11 Actual Date: Not reported

CA110 - RFI Workplan Received Action:

NAICS Code(s): 92811

**National Security** 

Original schedule date: 19981001 Schedule end date: Not reported

EPA ID: DC9170024310

EPA Region: 03 Area Name: SITE 7 Actual Date: Not reported

CA110 - RFI Workplan Received Action:

NAICS Code(s): 92811

**National Security** 

Original schedule date: 19981001 Schedule end date: Not reported

DC9170024310 EPA ID:

EPA Region:

**ENTIRE FACILITY** Area Name: Actual Date: Not reported

Action: CA150 - RFI Workplan Approved

NAICS Code(s): 92811

**National Security** 

Direction Distance

Elevation Site Database(s) EPA ID Number

## WASHINGTON NAVY YARD (Continued)

1000147680

**EDR ID Number** 

Original schedule date: 19971015 Schedule end date: Not reported

RCRA-LQG:

Date form received by agency: 03/01/2012

Facility name: WASHINGTON NAVY YARD
Facility address: 1013 O STREET SE; SUITE 100N

WASHINGTON NAVY YARD, DC 20374

EPA ID: DC9170024310

Mailing address: HARWOOD STREET SE

WASHINGTON NAVY YARD, DC 20374

Contact: STEVEN GODIO
Contact address: HARWOOD STREET SE

WASHINGTON NAVY YARD, DC 20374

Contact country: Not reported Contact telephone: (202) 433-7182

Telephone ext.: 7182

Contact email: STEVEN.GODIO@NAVY.MIL

EPA Region: 03 Land type: Federal

Classification: Large Quantity Generator

Description: Handler: generates 1,000 kg or more of hazardous waste during any

calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than

100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name: NACFAC WASHINGTON
Owner/operator address: O STREET SE; SUITE 100N

WASHINGTON NAVY YARD, DC 20374

Owner/operator country: US

Owner/operator telephone: (202) 433-7182 Legal status: Federal

Owner/Operator Type: Operator
Owner/Op start date: 10/01/1998
Owner/Op end date: Not reported

Owner/operator name: COMMANDER, NSA WASHINGTON
Owner/operator address: PARSONS AVENUE SE; SUITE 340
WASHINGTON NAVY YARD, DC 20374

Owner/operator country: US

Owner/operator telephone: (202) 433-3495
Legal status: Federal
Owner/Operator Type: Owner
Owner/Op start date: 10/01/1998
Owner/Op end date: Not reported

Direction Distance

Elevation Site Database(s) EPA ID Number

#### WASHINGTON NAVY YARD (Continued)

1000147680

**EDR ID Number** 

Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: No Transporter of hazardous waste: No Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: No Furnace exemption: No Used oil fuel burner: No Used oil processor: No User oil refiner: Nο Used oil fuel marketer to burner: No Used oil Specification marketer: No Used oil transfer facility: No Used oil transporter: No

## Historical Generators:

Date form received by agency: 03/01/2010

Facility name: WASHINGTON NAVY YARD Classification: Large Quantity Generator

Date form received by agency: 03/03/2008

Facility name: WASHINGTON NAVY YARD
Site name: NAVAL DISTRICT WASHINGTON

Classification: Large Quantity Generator

Date form received by agency: 04/04/2006

Facility name: WASHINGTON NAVY YARD Classification: Large Quantity Generator

Date form received by agency: 02/27/2004

Facility name: WASHINGTON NAVY YARD

Site name: HQ NAVAL DISTRICT WASHINGTON

Classification: Large Quantity Generator

Date form received by agency: 02/26/2002

Facility name: WASHINGTON NAVY YARD

Site name: HQ NAVAL DISTRICT WASHINGTON

Classification: Large Quantity Generator

Date form received by agency: 02/25/2000

Facility name: WASHINGTON NAVY YARD

Site name: HQ NAVAL DISTRICT WASHINGTON

Classification: Large Quantity Generator

Date form received by agency: 03/01/1998

Facility name: WASHINGTON NAVY YARD

Site name: HQ NAVAL DISTRICT WASHINGTON

Classification: Large Quantity Generator

Date form received by agency: 06/28/1995

Facility name: WASHINGTON NAVY YARD Classification: Large Quantity Generator

Date form received by agency: 02/28/1994

Direction Distance

Elevation Site Database(s) EPA ID Number

# WASHINGTON NAVY YARD (Continued)

1000147680

**EDR ID Number** 

Facility name: WASHINGTON NAVY YARD

Site name: NAVAL DISTRICT - WASHINGTON DC

Classification: Large Quantity Generator

Date form received by agency: 04/01/1992

Facility name: WASHINGTON NAVY YARD

Site name: NAVAL DISTRICT - WASHINGTON DC

Classification: Large Quantity Generator

Date form received by agency: 02/26/1985

Facility name: WASHINGTON NAVY YARD Classification: Large Quantity Generator

Hazardous Waste Summary:

Waste code: D001

Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF

LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT

WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D005 Waste name: BARIUM

Waste code: D008 Waste name: LEAD

Waste code: D009
Waste name: MERCURY

Waste code: D011
Waste name: SILVER

Waste code: D035

Waste name: METHYL ETHYL KETONE

Biennial Reports:

Last Biennial Reporting Year: 2013

Annual Waste Handled:

Waste code: D001

Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF

LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT

WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Amount (Lbs): 183

Waste code: D005
Waste name: BARIUM
Amount (Lbs): 97

Direction Distance Elevation

nce EDR ID Number ation Site Database(s) EPA ID Number

## WASHINGTON NAVY YARD (Continued)

1000147680

Waste code: D008
Waste name: LEAD
Amount (Lbs): 6735

Waste code: D009
Waste name: MERCURY

Amount (Lbs): 83

Waste code: D011
Waste name: SILVER
Amount (Lbs): 83

Waste code: D035

Waste name: METHYL ETHYL KETONE

Amount (Lbs): 97

Corrective Action Summary:

Event date: 08/29/1996

Event: RFA Determination Of Need For An RFI, RFI is Necessary;

Event date: 09/30/1996

Event: CA Prioritization, Facility or area was assigned a high corrective

action priority.

Event date: 10/26/1996 Event: CA611

Event date: 10/26/1996

Event: Stabilization Measures Implemented, Primary measure is source removal

and/or treatment (e.g., soil or waste excavation, in-situ soil

treatment, off-site treatment).

Event date: 07/16/1997 Event: RFI Imposition

Event date: 09/29/1997 Event: CA611

Event date: 02/17/1998

Event: Stabilization Measures Implemented, Primary measure is source removal

and/or treatment (e.g., soil or waste excavation, in-situ soil

treatment, off-site treatment).

Event date: 06/11/1998 Event: CA611

Event date: 06/12/1998

Event: Stabilization Measures Implemented, Primary measure is source removal

and/or treatment (e.g., soil or waste excavation, in-situ soil

treatment, off-site treatment).

Event date: 08/14/1998

Event: RFI Workplan Approved

Event date: 09/22/1998

Event: CA Responsibility Referred To A Non-RCRA Federal Authority, Corrective

Direction Distance

Elevation Site Database(s) EPA ID Number

## WASHINGTON NAVY YARD (Continued)

1000147680

**EDR ID Number** 

Action at the facility or area referred to CERCLA.

Event date: 11/14/1998

Event: Stabilization Measures Implemented, Primary measure is source removal

and/or treatment (e.g., soil or waste excavation, in-situ soil

treatment, off-site treatment).

Event date: Not reported

Event: RFI Workplan Approved

Event date: Not reported

Event: RFI Workplan Received

Facility Has Received Notices of Violations:

Regulation violated: SR - 4202.7(c), 4202.7(d).
Area of violation: Generators - Pre-transport

Date violation determined: 09/09/2005
Date achieved compliance: 10/13/2005
Violation lead agency: State

Enforcement action: WRITTEN INFORMAL

Enforcement action date: 09/21/2005
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 4202.6

Area of violation: Generators - Pre-transport

Date violation determined: 09/09/2005
Date achieved compliance: 10/13/2005
Violation lead agency: State

Enforcement action: WRITTEN INFORMAL

Enforcement action date: 09/21/2005
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 4200.10
Area of violation: Generators - General

Date violation determined: 09/09/2005
Date achieved compliance: 10/13/2005
Violation lead agency: State

Enforcement action: WRITTEN INFORMAL

Enforcement action date: 09/21/2005
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 40 CFR 265.50

Direction Distance Elevation

ation Site Database(s) EPA ID Number

## WASHINGTON NAVY YARD (Continued)

1000147680

**EDR ID Number** 

Area of violation: Generators - General

Date violation determined: 06/28/1995
Date achieved compliance: 01/23/2001
Violation lead agency: EPA

Enforcement action: FINAL 3008(A) COMPLIANCE ORDER

Enforcement action date: 09/30/1996
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: Not reported

Final penalty amount: Not reported Not reported Paid penalty amount: Not reported Not reported

Regulation violated: FR - 40 CFR 265.51(a)
Area of violation: Generators - General

Date violation determined: 05/15/1995
Date achieved compliance: 01/23/2001
Violation lead agency: EPA

Enforcement action: FINAL 3008(A) COMPLIANCE ORDER

Enforcement action date: 09/30/1996
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA

Proposed penalty amount: Not reported Final penalty amount: Not reported Paid penalty amount: Not reported

Regulation violated: FR - 40 CFR 262.12 Area of violation: Generators - General

Date violation determined: 02/26/1995
Date achieved compliance: 12/19/1996
Violation lead agency: EPA

Enforcement action: FINAL 3008(A) COMPLIANCE ORDER

Enforcement action date: 09/30/1996
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 40 CFR 265.174
Area of violation: Generators - General

Date violation determined: 02/26/1995
Date achieved compliance: 01/23/2001
Violation lead agency: EPA

Enforcement action: FINAL 3008(A) COMPLIANCE ORDER

Enforcement action date: 09/30/1996
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 40 CFR 265.16 Area of violation: Generators - General

Direction Distance

**EDR ID Number** Elevation Site Database(s) **EPA ID Number** 

## **WASHINGTON NAVY YARD (Continued)**

Paid penalty amount:

1000147680

Date violation determined: 02/26/1995 08/13/1998 Date achieved compliance: Violation lead agency: **EPA** 

FINAL 3008(A) COMPLIANCE ORDER Enforcement action:

Not reported

Enforcement action date: 09/30/1996 Enf. disposition status: Not reported Enf. disp. status date: Not reported Enforcement lead agency: **EPA** Proposed penalty amount: Not reported Final penalty amount: Not reported

FR - 40 CFR 262.34(a)(3) Regulation violated: Area of violation: Generators - Pre-transport

Date violation determined: 02/26/1995 08/13/1998 Date achieved compliance: **EPA** Violation lead agency:

Enforcement action: FINAL 3008(A) COMPLIANCE ORDER

Enforcement action date: 09/30/1996 Enf. disposition status: Not reported Enf. disp. status date: Not reported Enforcement lead agency: **EPA** Proposed penalty amount: Not reported Final penalty amount: Not reported Paid penalty amount: Not reported

Regulation violated: FR - 40 CFR 262.34(a)(2) Area of violation: Generators - Pre-transport

Date violation determined: 02/26/1995 08/13/1998 Date achieved compliance: Violation lead agency: **EPA** 

Enforcement action: FINAL 3008(A) COMPLIANCE ORDER

Enforcement action date: 09/30/1996 Enf. disposition status: Not reported Enf. disp. status date: Not reported Enforcement lead agency: **EPA** Proposed penalty amount: Not reported

Final penalty amount: Not reported Paid penalty amount: Not reported

Regulation violated: Not reported Area of violation: Generators - General

Date violation determined: 12/30/1988 Date achieved compliance: 05/12/1989 Violation lead agency: State

WRITTEN INFORMAL Enforcement action:

01/17/1989 Enforcement action date: Enf. disposition status: Not reported Enf. disp. status date: Not reported Enforcement lead agency: State Proposed penalty amount: Not reported

Final penalty amount: Not reported Paid penalty amount: Not reported

**Evaluation Action Summary:** 

Evaluation date: 12/13/2012

COMPLIANCE EVALUATION INSPECTION ON-SITE Evaluation:

Direction Distance

Elevation Site Database(s) EPA ID Number

## WASHINGTON NAVY YARD (Continued)

1000147680

**EDR ID Number** 

Area of violation:
Date achieved compliance:
Evaluation lead agency:
Not reported
Not reported
State

Evaluation date: 06/05/2012

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation:

Date achieved compliance:

Evaluation lead agency:

Not reported

Not reported

EPA

Evaluation date: 03/01/2012

Evaluation: NON-FINANCIAL RECORD REVIEW

Area of violation:

Date achieved compliance:

Evaluation lead agency:

Not reported

Not reported

State

Evaluation date: 01/20/2011

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 01/28/2010

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation:

Date achieved compliance:

Evaluation lead agency:

Not reported

Not reported

State

Evaluation date: 07/08/2008

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation:
Date achieved compliance:
Evaluation lead agency:
Not reported
Not reported
EPA

Evaluation date: 09/09/2005

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: Generators - General

Date achieved compliance: 10/13/2005 Evaluation lead agency: State

Evaluation date: 09/09/2005

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: Generators - Pre-transport

Date achieved compliance: 10/13/2005 Evaluation lead agency: State

Evaluation date: 01/23/2001

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation:

Date achieved compliance:

Evaluation lead agency:

Not reported

Not reported

EPA

Evaluation date: 06/28/1995

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: Generators - General

Date achieved compliance: 12/19/1996
Evaluation lead agency: EPA

Direction Distance

Elevation Site Database(s) EPA ID Number

## WASHINGTON NAVY YARD (Continued)

1000147680

**EDR ID Number** 

Evaluation date: 06/28/1995

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: Generators - General

Date achieved compliance: 08/13/1998 Evaluation lead agency: EPA

Evaluation date: 06/28/1995

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: Generators - Pre-transport

Date achieved compliance: 08/13/1998

Evaluation lead agency: EPA

Evaluation date: 06/28/1995

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: Generators - General

Date achieved compliance: 01/23/2001 Evaluation lead agency: EPA

Evaluation date: 05/15/1995

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: Generators - General

Date achieved compliance: 01/23/2001 Evaluation lead agency: EPA

Evaluation date: 09/29/1994

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation:

Date achieved compliance:

Evaluation lead agency:

Not reported

Not reported

State

Evaluation date: 05/12/1989

Evaluation: COMPLIANCE SCHEDULE EVALUATION

Area of violation: Generators - General

Date achieved compliance: 05/12/1989 Evaluation lead agency: State

Evaluation date: 12/30/1988

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: Generators - General

Date achieved compliance: 05/12/1989 Evaluation lead agency: State

Evaluation date: 07/17/1985

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation:

Date achieved compliance:

Evaluation lead agency:

Not reported

Not reported

State

US ENG CONTROLS:

EPA ID: DC9170024310 Site ID: 0300031

Name: WASHINGTON NAVY YARD

Address: 901 M STREET, SE

WASHINGTON, DC 203740001

EPA Region: 03

County: DISTRICT OF COLUMBIA

Event Code: Not reported Actual Date: 09/30/11

Direction Distance

Elevation Site Database(s) EPA ID Number

WASHINGTON NAVY YARD (Continued)

Action ID:

006

Action Name: RECORD OF DECISION
Action Completion date: 09/29/06

Operable Unit: 05 Contaminated Media : Soil

Engineering Control: No Further Action

Action ID: 007

Action Name: RECORD OF DECISION

Action Completion date: 09/29/06 Operable Unit: 06 Contaminated Media: Soil

Engineering Control: No Further Action

Action ID: 013

Action Name: RECORD OF DECISION

Action Completion date: 09/28/04 Operable Unit: 04 Contaminated Media: Soil

Engineering Control: No Further Action

Action ID: 014

Action Name: RECORD OF DECISION

Action Completion date: 10/14/05 Operable Unit: 14 Contaminated Media: Soil

Engineering Control: No Further Action

Action ID: 020

Action Name: RECORD OF DECISION

Action Completion date: 09/18/09 Operable Unit: 10

Contaminated Media : Subsurface Soil Engineering Control: No Further Action

Action ID: 020

Action Name: RECORD OF DECISION

Action Completion date: 09/18/09
Operable Unit: 10
Contaminated Media: Surface Soil
Engineering Control: No Further Action

Action ID: 021

Action Name: RECORD OF DECISION

Action Completion date: 12/20/07
Operable Unit: 13
Contaminated Media: Soil
Engineering Control: No Action

Action ID: 025

Action Name: RECORD OF DECISION

Action Completion date: 09/29/11
Operable Unit: 19
Contaminated Media : Soil
Engineering Control: No Action

**EDR ID Number** 

1000147680

Direction Distance

Elevation Site Database(s) EPA ID Number

## WASHINGTON NAVY YARD (Continued)

1000147680

**EDR ID Number** 

ROD:

Full-text of USEPA Record of Decision(s) is available from EDR.

NY MANIFEST:

EPA ID: DC9170024310

Country: USA

Mailing Name: UNITED STATES MILITARY
Mailing Contact: UNITED STATES MILITARY
Mailing Address: CSA NAVY YARD 10 P STREET

Mailing Address: GSA NAVY YARD-10 P STREET SW

Mailing Address 2: Not reported Mailing City: WASHINGTON

Mailing State: DC
Mailing Zip: 20407
Mailing Zip4: Not reported
Mailing Country: USA

Mailing Phone: 202-755-5636

Document ID: NYC1052469

Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC

Trans1 State ID: 42791A101 Trans2 State ID: NJ564TUH Generator Ship Date: 910628 Trans1 Recv Date: 910628 Trans2 Recy Date: 910711 TSD Site Recy Date: 910719 Part A Recv Date: 910715 Part B Recv Date: 910802 Generator EPA ID:

 Generator EPA ID:
 DC9170024310

 Trans1 EPA ID:
 ILD051060408

 Trans2 EPA ID:
 ILD051060408

 TSDF ID:
 NYD980753784

 Waste Code:
 F005 - UNKNOWN

Quantity: 00027
Units: P - Pounds
Number of Containers: 001

Container Type: DM - Metal drums, barrels

Handling Method: B Incineration, heat recovery, burning.

Specific Gravity: 100 Year: 91

NYA9581556 Document ID: Manifest Status: Completed copy 00000000 Trans1 State ID: Trans2 State ID: 00000000 Generator Ship Date: 890725 Trans1 Recv Date: 890725 Trans2 Recv Date: Not reported TSD Site Recv Date: 890725 Part A Recv Date: 890801 890809 Part B Recv Date:

 Generator EPA ID:
 DC9170024310

 Trans1 EPA ID:
 ILD051060408

 Trans2 EPA ID:
 Not reported

 TSDF ID:
 NYD980753784

Direction Distance

Elevation Site Database(s) EPA ID Number

## WASHINGTON NAVY YARD (Continued)

1000147680

**EDR ID Number** 

Waste Code: F003 - UNKNOWN

Quantity: 00027
Units: P - Pounds
Number of Containers: 001

Container Type: DM - Metal drums, barrels

Handling Method: R Material recovery of more than 75 percent of the total material.

Specific Gravity: 100 Year: 89

Document ID: NYA3328593 Manifest Status: Completed copy S-12529/0 Trans1 State ID: Trans2 State ID: Not reported Generator Ship Date: 880226 Trans1 Recv Date: 880226 Trans2 Recy Date: 880307 TSD Site Recv Date: 880310 Part A Recv Date: 880309 Part B Recv Date: 880318 Generator EPA ID: DC9170024310 Trans1 EPA ID: DCD981735244 Trans2 EPA ID: Not reported TSDF ID: NYD049836679

Waste Code: B007 - OTHER MISCELLANEOUS PCB WASTES

Quantity: 00004

Units: Y - Cubic yards* (.85 tons)

Number of Containers: 002

Container Type: CW - Wooden boxes

Handling Method: L Landfill.
Specific Gravity: 100
Waste Code: Not reported
Quantity: 00001

Units: Y - Cubic yards* (.85 tons)

Number of Containers: 001

Container Type: CM - Metal boxes, cases, roll-offs

Handling Method: L Landfill.
Specific Gravity: 100
Year: 88

Document ID: NYB8805087 Manifest Status: Not reported Trans1 State ID: PAD146714878 Not reported Trans2 State ID: 08/31/1998 Generator Ship Date: Trans1 Recv Date: 08/31/1998 Trans2 Recv Date: Not reported TSD Site Recv Date: 09/02/1998 Part A Recv Date: Not reported Part B Recv Date: Not reported Generator EPA ID: DC9170024310 NYD049836679 Trans1 EPA ID: Trans2 EPA ID: Not reported TSDF ID: XB58795PA

Waste Code: D008 - LEAD 5.0 MG/L TCLP

Quantity: 39860

Direction Distance

Elevation Site Database(s) EPA ID Number

# WASHINGTON NAVY YARD (Continued)

1000147680

**EDR ID Number** 

Units: P - Pounds

Number of Containers: 001

Container Type: CM - Metal boxes, cases, roll-offs

Handling Method: T Chemical, physical, or biological treatment.

Specific Gravity: 01.00 Year: 98

Document ID: NYB8805159 Manifest Status: Not reported Trans1 State ID: PAD146714878 Not reported Trans2 State ID: 10/19/1998 Generator Ship Date: Trans1 Recv Date: 10/19/1998 Trans2 Recv Date: Not reported TSD Site Recv Date: 10/21/1998 Part A Recy Date: Not reported Part B Recv Date: Not reported Generator EPA ID: DC9170024310 Trans1 EPA ID: NYD049836679 Trans2 EPA ID: Not reported TSDF ID: XA07713PA

Waste Code: D008 - LEAD 5.0 MG/L TCLP

Quantity: 21140 Units: P - Pounds

Number of Containers: 001

Container Type: CM - Metal boxes, cases, roll-offs

Handling Method: T Chemical, physical, or biological treatment.

Specific Gravity: 01.00 Year: 98

Document ID: NYC0223492

Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC

42790A057 Trans1 State ID: Trans2 State ID: T615KPNJ Generator Ship Date: 900430 Trans1 Recv Date: 900430 Trans2 Recv Date: 900511 TSD Site Recv Date: 900515 Part A Recv Date: 900831 Part B Recv Date: 900706

 Generator EPA ID:
 DC9170024310

 Trans1 EPA ID:
 ILD051060408

 Trans2 EPA ID:
 ILD051060408

 TSDF ID:
 NYD980753784

 Waste Code:
 F003 - UNKNOWN

Quantity: 00027 Units: P - Pounds Number of Containers: 001

Container Type: DM - Metal drums, barrels

Handling Method: B Incineration, heat recovery, burning.

Specific Gravity: 100 Year: 90

Document ID: NYC0298855

Direction Distance

**EDR ID Number** Elevation Site Database(s) **EPA ID Number** 

## **WASHINGTON NAVY YARD (Continued)**

1000147680

Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC

00000000 Trans1 State ID: 00000000 Trans2 State ID: Generator Ship Date: 900530 Trans1 Recv Date: 900530 Trans2 Recv Date: 900607 TSD Site Recv Date: 900612 Part A Recv Date: 900731 Part B Recv Date: 900627

Generator EPA ID: DC9170024310 Trans1 EPA ID: ILD051060408 Trans2 EPA ID: ILD051060408 TSDF ID: NYD980753784 Waste Code: F005 - UNKNOWN

Quantity: 00027 P - Pounds Units:

001 Number of Containers:

Container Type: DM - Metal drums, barrels

Handling Method: B Incineration, heat recovery, burning.

Specific Gravity: 100 Year: 90

Document ID: NYA9397124 Manifest Status: Completed copy Trans1 State ID: 4289A0454 Trans2 State ID: Not reported Generator Ship Date: 890329 Trans1 Recv Date: 890329 Trans2 Recv Date: Not reported TSD Site Recv Date: 890404 Part A Recv Date: 890405 Part B Recv Date: 890411 Generator EPA ID: DC9170024310 Trans1 EPA ID: ILD051060408

Trans2 EPA ID: Not reported TSDF ID: NYD980753784 Waste Code: F003 - UNKNOWN Quantity: 00144

Units: P - Pounds Number of Containers: 002

Container Type: DM - Metal drums, barrels

Handling Method: B Incineration, heat recovery, burning.

Specific Gravity: 100 89 Year:

NYC0378415 Document ID:

Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC

Trans1 State ID: 42790A057 Trans2 State ID: 506T4JNJ Generator Ship Date: 900731 Trans1 Recv Date: 900731 Trans2 Recv Date: 900811 TSD Site Recy Date: 900817 900906 Part A Recv Date: Part B Recv Date: 900907

Direction Distance

Elevation Site Database(s) EPA ID Number

## WASHINGTON NAVY YARD (Continued)

1000147680

**EDR ID Number** 

 Generator EPA ID:
 DC9170024310

 Trans1 EPA ID:
 ILD051060408

 Trans2 EPA ID:
 ILD051060408

 TSDF ID:
 NYD980753784

 Waste Code:
 F005 - UNKNOWN

Quantity: 00123 Units: P - Pounds Number of Containers: 002

Container Type: DM - Metal drums, barrels

Handling Method: B Incineration, heat recovery, burning.

Specific Gravity: 100 Year: 90

NYG1885977 Document ID: Manifest Status: Not reported Trans1 State ID: PAD987358587 Trans2 State ID: Not reported Generator Ship Date: 06/27/2001 Trans1 Recv Date: 06/27/2001 Trans2 Recv Date: Not reported TSD Site Recv Date: 06/28/2001 Part A Recv Date: Not reported Part B Recv Date: Not reported Generator EPA ID: DC9170024310 Trans1 EPA ID: NYD049836679 Trans2 EPA ID: Not reported TSDF ID: XN39249PA

Waste Code: B002 - PETROLEUM OIL WITH 50 BUT < 500 PPM PCB

Quantity: 05227

Units: K - Kilograms (2.2 pounds)

Number of Containers: 023

Container Type: DM - Metal drums, barrels

Handling Method: B Incineration, heat recovery, burning.

Specific Gravity: 01.00

Waste Code: B007 - OTHER MISCELLANEOUS PCB WASTES

Quantity: 00682

Units: K - Kilograms (2.2 pounds)

Number of Containers: 010

Container Type: DM - Metal drums, barrels

Handling Method: L Landfill.
Specific Gravity: 01.00
Year: 2001

Document ID: Not reported Manifest Status: Not reported NJ0000027193 Trans1 State ID: Trans2 State ID: NJD986576031 Generator Ship Date: 2008-03-27 2008-03-27 Trans1 Recv Date: Trans2 Recv Date: 2008-04-01 TSD Site Recv Date: 2008-04-02 Part A Recv Date: Not reported Part B Recv Date: Not reported DC9170024310 Generator EPA ID: Trans1 EPA ID: Not reported

Direction Distance

Elevation Site Database(s) EPA ID Number

## WASHINGTON NAVY YARD (Continued)

1000147680

**EDR ID Number** 

Trans2 EPA ID: Not reported
TSDF ID: NYD049836679
Waste Code: Not reported
Quantity: 522.0

Units: K - Kilograms (2.2 pounds)

Number of Containers: 5.0

Container Type: CF - Fiber or plastic boxes, cartons

Handling Method: L Landfill. Specific Gravity: 1.0 Year: 2008

Manifest Tracking Num: 000848170JJK

Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: Y
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N

Manifest Ref Num:
Alt Fac RCRA Id:
Alt Fac Sign Date:
Mgmt Method Type Code:
Not reported
Not reported
Not reported
H132

Document ID: NYC0497046

Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC

Trans1 State ID: 42790A057 Trans2 State ID: Not reported 900921 Generator Ship Date: 900921 Trans1 Recv Date: Trans2 Recv Date: Not reported TSD Site Recy Date: 901009 Part A Recv Date: 901012 Part B Recv Date: 901024

 Generator EPA ID:
 DC9170024310

 Trans1 EPA ID:
 ILD051060408

 Trans2 EPA ID:
 Not reported

 TSDF ID:
 NYD980753784

 Waste Code:
 F005 - UNKNOWN

Quantity: 00027 Units: P - Pounds

Number of Containers: 001

Container Type: DM - Metal drums, barrels

Handling Method: B Incineration, heat recovery, burning.

Specific Gravity: 100 Year: 90

Document ID: NYC0716646

Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC

 Trans1 State ID:
 427-91A10

 Trans2 State ID:
 NJ506TYJ

 Generator Ship Date:
 910219

 Trans1 Recv Date:
 910219

 Trans2 Recv Date:
 910228

 TSD Site Recv Date:
 910305

 Part A Recv Date:
 910305

Direction Distance Elevation

Elevation Site Database(s) EPA ID Number

# WASHINGTON NAVY YARD (Continued)

1000147680

**EDR ID Number** 

Part B Recv Date: 910321

 Generator EPA ID:
 DC9170024310

 Trans1 EPA ID:
 ILD051060408

 Trans2 EPA ID:
 ILD051060408

 TSDF ID:
 NYD980753784

 Waste Code:
 F005 - UNKNOWN

Quantity: 00027 Units: P - Pounds Number of Containers: 001

Container Type: DM - Metal drums, barrels

Handling Method: B Incineration, heat recovery, burning.

Specific Gravity: 100 Year: 91

Document ID: NYC0040724

Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC

Trans1 State ID: 42790A057 Trans2 State ID: T615KPNJ Generator Ship Date: 900122 Trans1 Recv Date: 900122 Trans2 Recv Date: 900201 TSD Site Recy Date: 900206 Part A Recv Date: 900129 Part B Recv Date: 900228

 Generator EPA ID:
 DC9170024310

 Trans1 EPA ID:
 ILD051060408

 Trans2 EPA ID:
 ILD051060408

 TSDF ID:
 NYD980753784

 Waste Code:
 F003 - UNKNOWN

Quantity: 00027
Units: P - Pounds
Number of Containers: 001

Container Type: DM - Metal drums, barrels

Handling Method: B Incineration, heat recovery, burning.

Specific Gravity: 100 Year: 90

Document ID: NYB7194258 Manifest Status: Completed copy Trans1 State ID: XB55806PA Trans2 State ID: Not reported Generator Ship Date: 960731 Trans1 Recv Date: 960731 Trans2 Recv Date: Not reported TSD Site Recv Date: 960801 Part A Recv Date: 960819 Part B Recv Date: 960819

 Generator EPA ID:
 DC9170024310

 Trans1 EPA ID:
 PAD987271020

 Trans2 EPA ID:
 Not reported

 TSDF ID:
 NYD049836679

Waste Code: D008 - LEAD 5.0 MG/L TCLP

Quantity: 13260 Units: P - Pounds Number of Containers: 001

Direction Distance

**EDR ID Number** Elevation Site Database(s) **EPA ID Number** 

#### **WASHINGTON NAVY YARD (Continued)**

1000147680

Container Type: CM - Metal boxes, cases, roll-offs

Handling Method: T Chemical, physical, or biological treatment.

Specific Gravity: 100 Year: 96

Document ID: NYA7986285 Completed copy Manifest Status: Trans1 State ID: 00000000 Trans2 State ID: 00000000 Generator Ship Date: 890111 Trans1 Recv Date: 890111 Trans2 Recv Date: Not reported TSD Site Recv Date: 890123 Part A Recv Date: 890118 Part B Recv Date: 890127 DC9170024310 Generator EPA ID:

Trans1 EPA ID: DCD981735244 Trans2 EPA ID: DCD981735244 TSDF ID: NYD049836679

Waste Code: B005 - PCB ARTICLES WITH 500 PPM OR > PCB

Quantity: 00750 Units: P - Pounds Number of Containers: 004

Container Type: CM - Metal boxes, cases, roll-offs Handling Method: B Incineration, heat recovery, burning.

Specific Gravity: 100 Year: 89

Document ID: NYC0880593

Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC

Trans1 State ID: 42791A101 Trans2 State ID: NJ564TUH 910419 Generator Ship Date: 910419 Trans1 Recv Date: Trans2 Recv Date: 910425 TSD Site Recv Date: 910430 Part A Recv Date: 910501 Part B Recv Date: 910515 Generator EPA ID:

DC9170024310 Trans1 EPA ID: ILD051060408 Trans2 EPA ID: ILD051060408 TSDF ID: NYD980753784 Waste Code: F005 - UNKNOWN

00027 Quantity: Units: P - Pounds Number of Containers: 001

Container Type: DM - Metal drums, barrels

Handling Method: B Incineration, heat recovery, burning.

Specific Gravity: 100 Year: 91

NYA9849497 Document ID:

Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC

Trans1 State ID: 42789A352

Direction Distance

Elevation Site Database(s) EPA ID Number

## WASHINGTON NAVY YARD (Continued)

1000147680

**EDR ID Number** 

Trans2 State ID: T631631SC 891212 Generator Ship Date: Trans1 Recv Date: 891212 Trans2 Recv Date: 891215 TSD Site Recv Date: 891219 Part A Recv Date: 891219 Part B Recv Date: 900108 Generator EPA ID: DC9170024310

 Trans1 EPA ID:
 ILD051060408

 Trans2 EPA ID:
 ILD051060408

 TSDF ID:
 NYD980753784

 Waste Code:
 F003 - UNKNOWN

Quantity: 00123
Units: P - Pounds

Number of Containers: 002

Container Type: DM - Metal drums, barrels

Handling Method: B Incineration, heat recovery, burning.

Specific Gravity: 100 Year: 89

Document ID: NYC0581163

Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC

Trans1 State ID: 42790A057 Trans2 State ID: T996LNNJ Generator Ship Date: 901128 Trans1 Recv Date: 901128 Trans2 Recv Date: 901206 TSD Site Recv Date: 901212 Part A Recv Date: 910102 Part B Recv Date: 910116 Generator EPA ID: DC9170024310 Trans1 EPA ID: ILD051060408 Trans2 EPA ID: ILD051060408 TSDF ID: NYD980753784

Waste Code: F005 - UNKNOWN
Quantity: 00123
Units: P - Pounds

Container Type: DM - Metal drums, barrels

Handling Method: B Incineration, heat recovery, burning.

002

Specific Gravity: 100 Year: 90

Number of Containers:

Document ID: NYC1233819

Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC

Trans1 State ID: 056401 Trans2 State ID: Not reported Generator Ship Date: 910923 910923 Trans1 Recv Date: Trans2 Recv Date: Not reported TSD Site Recv Date: 911004 Part A Recv Date: 911003 Part B Recv Date: 911028

 Part B Recv Date:
 911028

 Generator EPA ID:
 DC9170024310

 Trans1 EPA ID:
 ILD051060408

Direction Distance

Elevation Site Database(s) EPA ID Number

## WASHINGTON NAVY YARD (Continued)

1000147680

**EDR ID Number** 

Trans2 EPA ID: Not reported
TSDF ID: NYD980753784
Waste Code: F005 - UNKNOWN

Quantity: 00027 Units: P - Pounds Number of Containers: 001

Container Type: DM - Metal drums, barrels

Handling Method: B Incineration, heat recovery, burning.

Specific Gravity: 100 Year: 91

Click this hyperlink while viewing on your computer to access 21 additional NY_MANIFEST: record(s) in the EDR Site Report.

PA MANIFEST:

Year: 2011

Manifest Number: 006496765JJK

Manifest Type:

Generator EPA Id: DC9170024310 Generator Date: 07/26/2011 Mailing Address: Not reported Mailing City, St, Zip: Not reported Contact Name: Not reported Contact Phone: 202-433-7182 TSD Epa Id: PAD067098822 Not reported TSD Date: TSD Facility Name: CYCLE CHEM INC TSD Facility Address: 550 INDUSTRIAL DRIVE

TSD Facility City: LEWISBERRY

TSD Facility State: PA

Facility Telephone: Not reported

Page Number: 1
Line Number: 1
Waste Number: D001
Container Number: 1

Container Type: Fiberboard or plastic drums, barrels, kegs

Waste Quantity:

Unit: Pounds
Handling Code: Not reported
TSP EPA Id: Not reported
Date TSP Sig: Not reported

Year: 2011

Manifest Number: 008982378JJK

Manifest Type: T

Generator EPA Id: DC9170024310 Generator Date: 12/19/2011 Mailing Address: Not reported Mailing City, St, Zip: Not reported Contact Name: Not reported Contact Phone: 202-433-7182 TSD Epa Id: PAD067098822 TSD Date: Not reported TSD Facility Name: CYCLE CHEM INC TSD Facility Address: 550 INDUSTRIAL DRIVE

TSD Facility City: LEWISBERRY

TSD Facility State: PA

Direction Distance Elevation

ation Site Database(s) EPA ID Number

# WASHINGTON NAVY YARD (Continued)

1000147680

**EDR ID Number** 

Facility Telephone: Not reported

Page Number: 1
Line Number: 2
Waste Number: D011
Container Number: 1

Container Type: Fiberboard or plastic drums, barrels, kegs

Waste Quantity: 14
Unit: Pounds
Handling Code: Not reported
TSP EPA Id: Not reported
Date TSP Sig: Not reported

Year: 2011

Manifest Number: 008982125JJK

Manifest Type: T

Generator EPA Id: DC9170024310 Generator Date: 09/19/2011 Mailing Address: Not reported Mailing City, St, Zip: Not reported Contact Name: Not reported Contact Phone: 202-433-7182 TSD Epa Id: PAD067098822 TSD Date: Not reported TSD Facility Name: CYCLE CHEM INC 550 INDUSTRIAL DRIVE TSD Facility Address:

TSD Facility City: LEWISBERRY

TSD Facility State: PA
Facility Telephone: Not reported

Page Number: 1
Line Number: 3
Waste Number: NONE
Container Number: 1

Container Type: Metal drums, barrels, kegs

Waste Quantity: 30
Unit: Pounds
Handling Code: Not reported
TSP EPA Id: Not reported
Date TSP Sig: Not reported

Year: 2011

Manifest Number: 000843971JJK

Manifest Type: T

Generator EPA Id: DC9170024310 Generator Date: 08/25/2011 Mailing Address: Not reported Mailing City, St, Zip: Not reported Contact Name: Not reported Contact Phone: 202-433-7182 TSD Epa Id: PAD067098822 TSD Date: Not reported CYCLE CHEM INC TSD Facility Name: TSD Facility Address: 550 INDUSTRIAL DRIVE

TSD Facility City: LEWISBERRY

TSD Facility State: PA

Facility Telephone: Not reported

Page Number: 1 Line Number: 1

Distance Elevation

vation Site Database(s) EPA ID Number

## WASHINGTON NAVY YARD (Continued)

1000147680

**EDR ID Number** 

Waste Number: D008 Container Number: 1

Container Type: Metal drums, barrels, kegs

Waste Quantity: 300
Unit: Pounds
Handling Code: Not reported
TSP EPA Id: Not reported
Date TSP Sig: Not reported

Year: 2011

Manifest Number: 001052577GBF

Manifest Type: T

DC9170024310 Generator EPA Id: Generator Date: 12/14/2011 Mailing Address: Not reported Mailing City, St, Zip: Not reported Contact Name: Not reported Contact Phone: 202-433-7182 TSD Epa Id: PAD067098822 TSD Date: Not reported TSD Facility Name: CYCLE CHEM INC TSD Facility Address: 550 INDUSTRIAL DRIVE

TSD Facility City: LEWISBERRY

TSD Facility State: PA

Facility Telephone: Not reported

Page Number: 1
Line Number: 1
Waste Number: D008
Container Number: 2

Container Type: Metal drums, barrels, kegs

Waste Quantity: 500
Unit: Pounds
Handling Code: Not reported
TSP EPA Id: Not reported
Date TSP Sig: Not reported

Year: 2011

Manifest Number: 001052586GBF

Manifest Type: T

DC9170024310 Generator EPA Id: Generator Date: 12/14/2011 Mailing Address: Not reported Mailing City, St, Zip: Not reported Contact Name: Not reported Contact Phone: 202-433-7182 TSD Epa Id: PAD067098822 TSD Date: Not reported TSD Facility Name: CYCLE CHEM INC 550 INDUSTRIAL DRIVE

TSD Facility Address: 550 INDUSTRI
TSD Facility City: LEWISBERRY

TSD Facility State: PA
Facility Telephone: Not reported

Page Number: 1
Line Number: 1
Waste Number: D008
Container Number: 1

Container Type: Metal drums, barrels, kegs

Distance Elevation

ation Site Database(s) EPA ID Number

## WASHINGTON NAVY YARD (Continued)

1000147680

**EDR ID Number** 

Waste Quantity: 150
Unit: Pounds
Handling Code: Not reported
TSP EPA Id: Not reported
Date TSP Sig: Not reported

Year: 2011

Manifest Number: 006496765JJK

Manifest Type: T

Generator EPA Id: DC9170024310 Generator Date: 07/26/2011 Not reported Mailing Address: Not reported Mailing City, St, Zip: Contact Name: Not reported 202-433-7182 Contact Phone: PAD067098822 TSD Epa Id: TSD Date: Not reported CYCLE CHEM INC TSD Facility Name: TSD Facility Address: 550 INDUSTRIAL DRIVE

TSD Facility City: LEWISBERRY

TSD Facility State: PA

Facility Telephone: Not reported

Page Number: 1
Line Number: 2
Waste Number: NONE
Container Number: 1

Container Type: Metal drums, barrels, kegs

Waste Quantity: 40
Unit: Pounds
Handling Code: Not reported
TSP EPA Id: Not reported
Date TSP Sig: Not reported

Year: 2011

Manifest Number: 006496765JJK

Manifest Type: T

Generator EPA Id: DC9170024310 Generator Date: 07/26/2011 Mailing Address: Not reported Mailing City, St, Zip: Not reported Contact Name: Not reported Contact Phone: 202-433-7182 TSD Epa Id: PAD067098822 TSD Date: Not reported TSD Facility Name: CYCLE CHEM INC TSD Facility Address: 550 INDUSTRIAL DRIVE

TSD Facility City: LEWISBERRY

TSD Facility State: PA

Facility Telephone: Not reported

Page Number: 1
Line Number: 4
Waste Number: D008
Container Number: 1

Container Type: Metal drums, barrels, kegs

Waste Quantity: 35
Unit: Pounds
Handling Code: Not reported

Direction Distance

**EDR ID Number** Elevation Site Database(s) **EPA ID Number** 

#### **WASHINGTON NAVY YARD (Continued)**

1000147680

TSP EPA Id: Not reported Date TSP Sig: Not reported

2011 Year:

Manifest Number: 008982125JJK

Manifest Type:

Generator EPA Id: DC9170024310 Generator Date: 09/19/2011 Mailing Address: Not reported Mailing City, St, Zip: Not reported Contact Name: Not reported 202-433-7182 Contact Phone: PAD067098822 TSD Epa Id: TSD Date: Not reported CYCLE CHEM INC TSD Facility Name: TSD Facility Address: 550 INDUSTRIAL DRIVE

TSD Facility City: **LEWISBERRY** 

TSD Facility State: PΑ

Facility Telephone: Not reported

Page Number: Line Number: 2 D009 Waste Number: Container Number:

Container Type: Fiberboard or plastic drums, barrels, kegs

Waste Quantity: 38 Unit: Pounds Handling Code: Not reported TSP EPA Id: Not reported Date TSP Sig: Not reported

2011 Year:

Manifest Number: 008982378JJK

Manifest Type:

Generator EPA Id: DC9170024310 Generator Date: 12/19/2011 Mailing Address: Not reported Mailing City, St, Zip: Not reported Contact Name: Not reported 202-433-7182 Contact Phone: TSD Epa Id: PAD067098822 TSD Date: Not reported TSD Facility Name: CYCLE CHEM INC TSD Facility Address: 550 INDUSTRIAL DRIVE

TSD Facility City: **LEWISBERRY** 

TSD Facility State: PΑ

Facility Telephone: Not reported

Page Number: Line Number: Waste Number: D009 Container Number:

Container Type: Fiberboard or plastic drums, barrels, kegs

Waste Quantity: Unit: Pounds Handling Code: Not reported TSP EPA Id: Not reported Date TSP Sig: Not reported

Direction Distance

**EDR ID Number** Elevation Site Database(s) **EPA ID Number** 

## **WASHINGTON NAVY YARD (Continued)**

1000147680

Year: 2011

008982125JJK Manifest Number:

Manifest Type: Т

Generator EPA Id: DC9170024310 Generator Date: 09/19/2011 Mailing Address: Not reported Mailing City, St, Zip: Not reported Contact Name: Not reported Contact Phone: 202-433-7182 TSD Epa Id: PAD067098822 TSD Date: Not reported TSD Facility Name: CYCLE CHEM INC TSD Facility Address: 550 INDUSTRIAL DRIVE

TSD Facility City: **LEWISBERRY** 

TSD Facility State: PΑ

Facility Telephone: Not reported

Page Number: Line Number: Waste Number: D001 Container Number:

Container Type: Fiberboard or plastic drums, barrels, kegs

Waste Quantity:

Pounds Unit: Handling Code: Not reported TSP EPA Id: Not reported Date TSP Sig: Not reported

Year: 2011

008982378JJK Manifest Number:

Manifest Type:

Generator EPA Id: DC9170024310 Generator Date: 12/19/2011 Mailing Address: Not reported Mailing City, St, Zip: Not reported Not reported Contact Name: Contact Phone: 202-433-7182 TSD Epa Id: PAD067098822 TSD Date: Not reported CYCLE CHEM INC TSD Facility Name: 550 INDUSTRIAL DRIVE TSD Facility Address:

TSD Facility City: **LEWISBERRY** 

TSD Facility State: РΑ

Facility Telephone: Not reported

Page Number: Line Number: D001 Waste Number: Container Number:

Container Type: Fiberboard or plastic drums, barrels, kegs

Waste Quantity: 25 Unit: Pounds Handling Code: Not reported TSP EPA Id: Not reported Date TSP Sig: Not reported

Year: 2011

Manifest Number: 008982378JJK

Manifest Type:

Direction Distance

**EDR ID Number** Elevation Site Database(s) **EPA ID Number** 

## **WASHINGTON NAVY YARD (Continued)**

1000147680

Generator EPA Id: DC9170024310 Generator Date: 12/19/2011 Not reported Mailing Address: Mailing City, St, Zip: Not reported Contact Name: Not reported Contact Phone: 202-433-7182 TSD Epa Id: PAD067098822 TSD Date: Not reported TSD Facility Name: CYCLE CHEM INC TSD Facility Address: 550 INDUSTRIAL DRIVE

TSD Facility City: **LEWISBERRY** 

TSD Facility State: PΑ

Facility Telephone: Not reported

Page Number: Line Number: Waste Number: D001 Container Number:

Container Type: Fiberboard or plastic drums, barrels, kegs

Waste Quantity: Unit: Pounds

Handling Code: Not reported TSP EPA Id: Not reported Date TSP Sig: Not reported

Year: 2011

006496765JJK Manifest Number:

Manifest Type:

Generator EPA Id: DC9170024310 Generator Date: 07/26/2011 Mailing Address: Not reported Mailing City, St, Zip: Not reported Contact Name: Not reported Contact Phone: 202-433-7182 TSD Epa Id: PAD067098822 TSD Date: Not reported TSD Facility Name: CYCLE CHEM INC TSD Facility Address: 550 INDUSTRIAL DRIVE

TSD Facility City: **LEWISBERRY** 

TSD Facility State: PΑ

Facility Telephone: Not reported

Page Number: Line Number: 3 Waste Number: D001 Container Number:

Container Type: Fiberboard or plastic drums, barrels, kegs

Waste Quantity: 40 Unit: Pounds Handling Code: Not reported TSP EPA Id: Not reported Date TSP Sig: Not reported

Year: 2011

008982125JJK Manifest Number:

Manifest Type:

DC9170024310 Generator EPA Id: Generator Date: 09/19/2011 Mailing Address: Not reported

Direction Distance Elevation

ation Site Database(s) EPA ID Number

## WASHINGTON NAVY YARD (Continued)

1000147680

**EDR ID Number** 

Mailing City, St, Zip:
Contact Name:
Not reported
Contact Phone:
202-433-7182
TSD Epa Id:
PAD067098822
TSD Date:
Not reported
CYCLE CHEM INC
TSD Facility Address:
TSD INDUSTRIAL DRIVE

TSD Facility City: LEWISBERRY

TSD Facility State: PA

Facility Telephone: Not reported

Page Number: 1
Line Number: 4
Waste Number: NONE
Container Number: 3

Container Type: Metal drums, barrels, kegs

Waste Quantity: 1100
Unit: Pounds
Handling Code: Not reported
TSP EPA Id: Not reported
Date TSP Sig: Not reported

Year: 2011

Manifest Number: 008982125JJK

Manifest Type:

Generator EPA Id: DC9170024310 Generator Date: 09/19/2011 Mailing Address: Not reported Mailing City, St, Zip: Not reported Contact Name: Not reported Contact Phone: 202-433-7182 TSD Epa Id: PAD067098822 TSD Date: Not reported TSD Facility Name: CYCLE CHEM INC TSD Facility Address: 550 INDUSTRIAL DRIVE

TSD Facility City: LEWISBERRY

TSD Facility State: PA

Facility Telephone: Not reported

Page Number: 1
Line Number: 2
Waste Number: D011
Container Number: 2

Container Type: Fiberboard or plastic drums, barrels, kegs

Waste Quantity: 38
Unit: Pounds
Handling Code: Not reported
TSP EPA Id: Not reported
Date TSP Sig: Not reported

Year: 2010

Manifest Number: 006954692JJK

Manifest Type:

Generator EPA Id: DC9170024310
Generator Date: 11/09/2010
Mailing Address: Not reported
Mailing City,St,Zip: Not reported
Contact Name: Not reported
Contact Phone: 202-433-7182

Direction Distance

Elevation Site Database(s) EPA ID Number

## WASHINGTON NAVY YARD (Continued)

1000147680

**EDR ID Number** 

TSD Epa Id: PAD067098822
TSD Date: Not reported
TSD Facility Name: CYCLE CHEM INC
TSD Facility Address: 550 INDUSTRIAL DRIVE

TSD Facility City: LEWISBERRY

TSD Facility State: PA

Facility Telephone: Not reported

Page Number: 1
Line Number: 1
Waste Number: D008
Container Number: 1

Container Type: Metal drums, barrels, kegs

Waste Quantity: 100
Unit: Pounds
Handling Code: Not reported
TSP EPA Id: Not reported
Date TSP Sig: Not reported

Year: 2010

006499008JJK Manifest Number: Manifest Type: Т DC9170024310 Generator EPA Id: Generator Date: 07/29/2010 Mailing Address: Not reported Mailing City, St, Zip: Not reported Contact Name: Not reported Contact Phone: 202-433-7182 TSD Epa Id: PAD067098822 TSD Date: Not reported TSD Facility Name: CYCLE CHEM INC

TSD Facility City: LEWISBERRY

TSD Facility State: PA

TSD Facility Address:

Facility Telephone: Not reported

Page Number: 1
Line Number: 4
Waste Number: D002
Container Number: 1

Container Type: Fiberboard or plastic drums, barrels, kegs

550 INDUSTRIAL DRIVE

Waste Quantity: 4
Unit: Pounds
Handling Code: Not reported
TSP EPA Id: Not reported
Date TSP Sig: Not reported

Year: 2010

Manifest Number: 006499069JJK

Manifest Type:

Generator EPA Id: DC9170024310 Generator Date: 08/23/2010 Mailing Address: Not reported Mailing City, St, Zip: Not reported Contact Name: Not reported Contact Phone: 202-433-7182 TSD Epa Id: PAD067098822 TSD Date: Not reported TSD Facility Name: CYCLE CHEM INC

Direction Distance

**EDR ID Number** Elevation Site Database(s) **EPA ID Number** 

## **WASHINGTON NAVY YARD (Continued)**

1000147680

550 INDUSTRIAL DRIVE TSD Facility Address:

TSD Facility City: **LEWISBERRY** 

TSD Facility State: PΑ

Facility Telephone: Not reported

Page Number: Line Number: 4 NONE Waste Number: Container Number:

Container Type: Fiberboard or plastic drums, barrels, kegs

Waste Quantity: Unit: Pounds Handling Code: Not reported TSP EPA Id: Not reported Date TSP Sig: Not reported

Year: 2010

Manifest Number: 006499069JJK

Manifest Type: Т

Generator EPA Id: DC9170024310 08/23/2010 Generator Date: Mailing Address: Not reported Mailing City, St, Zip: Not reported Not reported Contact Name: 202-433-7182 Contact Phone: TSD Epa Id: PAD067098822 TSD Date: Not reported CYCLE CHEM INC TSD Facility Name: TSD Facility Address: 550 INDUSTRIAL DRIVE

TSD Facility City: **LEWISBERRY** 

TSD Facility State: PΑ

Facility Telephone: Not reported

Page Number: Line Number: Waste Number: D001 Container Number:

Container Type: Fiberboard or plastic drums, barrels, kegs

Waste Quantity: Unit: Pounds Handling Code: Not reported TSP EPA Id: Not reported Date TSP Sig: Not reported

> Click this hyperlink while viewing on your computer to access 56 additional PA MANIFEST: record(s) in the EDR Site Report.

DC BROWNFIELDS S108931551 1

100 S STREET, SW < 1/8 WASHINGTON, DC

1 ft.

BROWNFIELD:

PBF2004-0120 PB ID: Relative: Ownership: Private Lower Size (sf): Not reported Actual: Phase I: unknown 19 ft. Phase II: unknown

0011-0810 Lot: Square: 0602

N/A

Direction Distance

Elevation Site Database(s) EPA ID Number

(Continued) S108931551

Latitude/Longitude: 38.8682155 / -77.0121963

Notes: WS: Other

A2 PEPCO BUZZARD - TANK # 1 DC LUST \$108931574 180 S STREET, SW DC BROWNFIELDS N/A

< 1/8 WASHINGTON, DC

1 ft.

Site 1 of 3 in cluster A

 Relative:
 LUST:

 Lower
 Facility ID:
 2-002337

 Facility Type:
 Other

 Actual:
 Facility Status:
 Closed

17 ft. Product: Gasoline, Diesel
Notification Date: 8/27/1993

Ward: 6
Media Of Contamination: SOIL
Entry Date: 8/27/1993
Lust Number: 93094

BROWNFIELD:

PB ID: PBF2003-0034
Ownership: Private
Size (sf): Not reported
Phase I: unknown
Phase II: unknown
Lot: N
Square: 0605?

Latitude/Longitude: 38.92895304 / -76.97906441

Notes: WS: Other

A3 ATTIS DC UST U002108164 1714 2ND ST SW N/A

< 1/8 WASHINGTON, DC 20024 1 ft.

Site 2 of 3 in cluster A

Relative: UST:

Lower Facility ID: 2000084
Facility Description: False

Actual: Owner: AT&T COMMUNICATIONS

17 ft.
Tank ID:

Tank Status: Permanently Out of Use

Tank Capacity: 3500 Substance: Gasoline **EDR ID Number** 

Direction
Distance

Elevation Site Database(s) EPA ID Number

A4 AT&T - 1714 2ND ST SW DC LUST S108931573
1714 2ND STREET, SW DC BROWNFIELDS N/A

< 1/8 WASHINGTON, DC

1 ft.

Site 3 of 3 in cluster A

Relative: LUST:

Lower Facility ID: 2-000084

Facility Type: Other

Actual: Facility Status: Closed

17 ft. Product: Gasoline
Notification Date: 7/1/1992

Ward: 6
Media Of Contamination: Soil/GW
Entry Date: 7/1/1992
Lust Number: 92076

BROWNFIELD:

PB ID: PBF2003-0008

Ownership: Private
Size (sf): 25,612
Phase I: unknown
Phase II: unknown
Lot: 0007
Square: 0605

Latitude/Longitude: 38.86822262 / -77.01359292

Notes: WS: Other

B5 HOME MOVING & STORAGE DC LUST S105029670

1812 HALF ST., SW

< 1/8 WASHINGTON, DC

1 ft.

Site 1 of 3 in cluster B

Relative: LUST:

Higher Facility ID:

Facility Type: Other

Actual: Facility Status: Open

21 ft. Product: Gasoline
Notification Date: 12/6/1994

Ward: 6
Media Of Contamination: Soil/GW
Entry Date: 12/6/1994

2-004505

95015

B6 BORGER MANAGEMENT, INC. DC UST U003054693 1812 HALF ST SW N/A

< 1/8 WASHINGTON, DC 20024

1 ft.

Site 2 of 3 in cluster B

Lust Number:

Relative: UST:

Higher Facility ID: 2004505 Facility Description: False

Actual: Owner: BORGER MANAGEMENT, INC.

21 ft.

Tank ID:

Tank Status: Permanently Out of Use

N/A

**EDR ID Number** 

Direction Distance

**EDR ID Number** Elevation Site Database(s) **EPA ID Number** 

**BORGER MANAGEMENT, INC. (Continued)** 

Tank Capacity: 4000 Substance: Gasoline

**PEPCO** 

1ST & T ST SW WASHINGTON, DC 20024 < 1/8

1 ft.

7

UST:

Facility ID: 2000214 Relative: Facility Description: False Lower

Owner: POTOMAC ELECTRIC POWER COMPANY.

Actual: 18 ft.

Tank ID:

Tank Status: **Permanently Out of Use** 

Tank Capacity: 6000 Substance: Diesel

Tank ID:

Tank Status: **Permanently Out of Use** 

Tank Capacity: 6000 Substance: Diesel

**B8** 1824 HALF STREET, SW

WASHINGTON, DC < 1/8

1 ft.

Site 3 of 3 in cluster B

**BROWNFIELD:** Relative:

PB ID: Higher

Ownership: Private Actual: Size (sf): Not reported 21 ft. Phase I: unknown

Phase II: unknown Lot: 0001 Square: 0664

Latitude/Longitude: 38.91337093 / -76.98594752

Notes: WS: Other

DC LUST C9 SUPER SALVAGE, INC. S102834829

PBF2003-0015

**1711 1ST STREET., SW** 

< 1/8 WASHINGTON, DC

1 ft.

Site 1 of 4 in cluster C

LUST: Relative:

2-003504 Higher Facility ID: Facility Type: Other

Actual: Facility Status: Closed 22 ft. Product: Gasoline Notification Date: 10/13/1995

> Ward: 6

Media Of Contamination: SOIL N/A

U003054693

DC UST U003294414

DC BROWNFIELDS

N/A

S108931575

N/A

Direction Distance

**EDR ID Number** Elevation Site Database(s) **EPA ID Number** 

SUPER SALVAGE, INC. (Continued) S102834829

Entry Date: 10/13/1995 96030 Lust Number:

SUPER SALVAGE INC. C10 DC UST U003054563

1711 1ST ST SW N/A

< 1/8 WASHINGTON, DC 20024

1 ft.

Site 2 of 4 in cluster C

UST: Relative:

Facility ID: 2003504 Higher Facility Description: False

Actual: Owner: SUPER SALVAGE INC.

22 ft.

Tank ID:

Tank Status: **Permanently Out of Use** 

Tank Capacity: 2000 Substance: Gasoline

C11 DC BROWNFIELDS S108931572

1700 1ST STREET, SW N/A

WASHINGTON, DC < 1/8

1 ft. Site 3 of 4 in cluster C

**BROWNFIELD:** Relative:

PB ID: PBF2003-0026 Higher Ownership: Private Actual: Size (sf): Not reported 22 ft. Phase I: unknown Phase II:

unknown Lot: 0605 Unknown Square:

Latitude/Longitude: 38.91226503 / -76.9818002

Notes: WS: Other

C12 **SUPER SALVAGE INC** RCRA-CESQG 1001023400

1711 FIRST STREET SW < 1/8 WASHINGTON, DC 20024

1 ft.

Site 4 of 4 in cluster C

RCRA-CESQG: Relative: Date form received by agency: 02/10/2010

Higher SUPER SALVAGE INC Facility name:

Actual: Facility address: 1711 FIRST STREET SW 22 ft.

WASHINGTON, DC 20024 EPA ID:

DCR000000208 Mailing address: FIRST STREET SW WASHINGTON, DC 20024

Contact: STEPHEN MIDDLETHON Contact address: FIRST STREET SW

WASHINGTON, DC 20024

Contact country: US

Contact telephone: 202-488-7157 DCR000000208

Direction Distance Elevation

vation Site Database(s) EPA ID Number

#### SUPER SALVAGE INC (Continued)

1001023400

**EDR ID Number** 

Contact email: SCRAPBOY@NETZERO.NET

EPA Region: 03 Land type: Private

Classification: Conditionally Exempt Small Quantity Generator

Description: Handler: generates 100 kg or less of hazardous waste per calendar

month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from

the cleanup of a spill, into or on any land or water, of acutely

hazardous waste

Owner/Operator Summary:

Owner/operator name: KAPLAN ROBERT Owner/operator address: 3226 LUNHAM DR

SILVER SPRING, MD 20906

Owner/operator country: Not reported
Owner/operator telephone: (301) 598-7267

Legal status: Private
Owner/Operator Type: Owner

Owner/Op start date: Not reported Owner/Op end date: Not reported

Owner/operator name: KAPLAN ROBERT Owner/operator address: LUNHAM DR

SILVER SPRING, MD 20906

Owner/operator country: US

Owner/operator telephone: 301-598-7267
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 01/01/2010
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: No Transporter of hazardous waste: No Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: No Furnace exemption: No Used oil fuel burner: No Used oil processor: No User oil refiner: No Used oil fuel marketer to burner: No Used oil Specification marketer: No Used oil transfer facility: No Used oil transporter: No

Direction Distance

Elevation Site Database(s) EPA ID Number

## SUPER SALVAGE INC (Continued)

1001023400

**EDR ID Number** 

**Historical Generators:** 

Date form received by agency: 02/03/2000

Facility name: SUPER SALVAGE INC

Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 05/31/1995

Facility name: SUPER SALVAGE INC

Classification: Conditionally Exempt Small Quantity Generator

Hazardous Waste Summary:

Waste code: D001

Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF

LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT

WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D006 Waste name: CADMIUM

Waste code: D008
Waste name: LEAD

Waste code: D018
Waste name: BENZENE

Waste code: D035

Waste name: METHYL ETHYL KETONE

Waste code: D039

Waste name: TETRACHLOROETHYLENE

Waste code: D040

Waste name: TRICHLOROETHYLENE

Violation Status: No violations found

Evaluation Action Summary:

Evaluation date: 02/22/2012

Evaluation: NON-FINANCIAL RECORD REVIEW

Area of violation:

Date achieved compliance:

Evaluation lead agency:

Not reported

State

Evaluation date: 03/01/2011

Evaluation: NON-FINANCIAL RECORD REVIEW

Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 03/22/2002

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: Not reported Date achieved compliance: Not reported

Direction Distance

**EDR ID Number** Elevation Site Database(s) **EPA ID Number** 

SUPER SALVAGE INC (Continued)

1001023400

N/A

Evaluation lead agency: State

Evaluation date: 12/22/1998

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: Not reported Date achieved compliance: Not reported Evaluation lead agency: State

Evaluation date: 01/23/1996

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: Not reported Date achieved compliance: Not reported Evaluation lead agency: State

**METRO BUILDING SUPPLY** D13 DC LUST \$102835013

NNE **50 Q STREET. SW** 

WASHINGTON, DC < 1/8

0.027 mi.

Site 1 of 5 in cluster D 140 ft.

LUST: Relative:

Facility ID: 2-000575 Higher

Facility Type: Other Actual: Facility Status: NFA 25 ft. Product: Gasoline Notification Date: 6/28/1991

> Ward: Media Of Contamination: Soil/GW Entry Date: 6/28/1991 Lust Number: 91045

METRO BUILDING SUPPLY CO. DC UST U002108276 D14 N/A

NNE **50 Q ST SW** WASHINGTON, DC 20024 < 1/8

0.027 mi.

140 ft. Site 2 of 5 in cluster D

UST: Relative:

Facility ID: 2000575 Higher Facility Description: False

Actual: Owner: METRO BUILDING SUPPLY, CO

25 ft.

Tank ID:

Tank Status: **Permanently Out of Use** 

Tank Capacity: 4000 Substance: Diesel

Tank ID:

Tank Status: **Permanently Out of Use** 

Tank Capacity: 4000 Diesel Substance:

Tank ID:

Tank Status: **Permanently Out of Use** 

Tank Capacity: 2000

Direction Distance

**EDR ID Number** Elevation Site **EPA ID Number** Database(s)

#### **METRO BUILDING SUPPLY CO. (Continued)**

U002108276

Substance: Gasoline

D15 **USA MOTORS INC** RCRA-CESQG 1004681868 NNE **45 Q STREET SW** NJ MANIFEST DCR000500017

WASHINGTON, DC 20024 < 1/8

0.032 mi.

168 ft. Site 3 of 5 in cluster D

RCRA-CESQG: Relative:

Date form received by agency: 07/25/2011 Higher

**USA MOTORS INC** Facility name: Actual: Facility address: 45 Q STREET SW 25 ft.

WASHINGTON, DC 20024 EPA ID: DCR000500017

Mailing address: Q STREET SW

WASHINGTON, DC 20024 BALWINDER SINGH

Contact: Contact address: Q STREET SW

WASHINGTON, DC 20024

Contact country: US

Contact telephone: (202) 484-4155 Contact email: Not reported

EPA Region: 03 Land type: Private

Classification: Conditionally Exempt Small Quantity Generator

Handler: generates 100 kg or less of hazardous waste per calendar Description: month, and accumulates 1000 kg or less of hazardous waste at any time;

or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from

the cleanup of a spill, into or on any land or water, of acutely

hazardous waste

Owner/Operator Summary:

Owner/operator name: SINGH, BALWINDER Owner/operator address: 1439 FISHERS MILL COURT HERNDON, VA 20170

Owner/operator country: US Owner/operator telephone: (703) 450-9667 Legal status: Private Owner/Operator Type: Owner

Owner/Op start date: 11/01/2000 Owner/Op end date: Not reported

Owner/operator name: SINGH, BALWINDER Owner/operator address: 1439 FISHERS MILL COURT HERNDON, VA 20170

Owner/operator country: US

Owner/operator telephone: (703) 450-9667

Legal status: Private

Direction Distance

**EDR ID Number** Elevation Site Database(s) **EPA ID Number** 

#### **USA MOTORS INC (Continued)**

1004681868

Owner/Operator Type: Operator 11/01/2000 Owner/Op start date: Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: No Transporter of hazardous waste: No Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: Nο Furnace exemption: No Used oil fuel burner: No Used oil processor: No User oil refiner: No Used oil fuel marketer to burner: No Used oil Specification marketer: No Used oil transfer facility: No Used oil transporter: No

Historical Generators:

Date form received by agency: 11/07/2000

Facility name: USA MOTORS INC

Classification: Conditionally Exempt Small Quantity Generator

Hazardous Waste Summary:

Waste code: D001

IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF Waste name:

LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT

WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D018 Waste name: BENZENE

Waste code: D039

Waste name: **TETRACHLOROETHYLENE** 

Waste code: D040

Waste name: TRICHLOROETHYLENE

Violation Status: No violations found

**Evaluation Action Summary:** 

Evaluation date: 03/30/2012

Evaluation: NON-FINANCIAL RECORD REVIEW

Area of violation: Not reported Date achieved compliance: Not reported Evaluation lead agency: State

Evaluation date: 03/01/2011

Direction Distance

Elevation Site Database(s) EPA ID Number

#### **USA MOTORS INC (Continued)**

1004681868

**EDR ID Number** 

Evaluation: NON-FINANCIAL RECORD REVIEW

Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 08/29/2002

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation:

Date achieved compliance:

Evaluation lead agency:

Not reported

Not reported

State

NJ MANIFEST:

NJA5224187 Manifest Code: DCR000500017 EPA ID: Date Shipped: 01/19/2005 TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Transporter 3 EPA ID: Not reported Transporter 4 EPA ID: Not reported Transporter 5 EPA ID: Not reported Transporter 6 EPA ID: Not reported Transporter 7 EPA ID: Not reported Transporter 8 EPA ID: Not reported Transporter 10 EPA ID: Not reported Date Trans1 Transported Waste: 01/19/2005 Date Trans2 Transported Waste: Not reported Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Not reported Date Trans6 Transported Waste: Not reported Date Trans7 Transported Waste: Not reported Date Trans8 Transported Waste: Not reported Date Trans9 Transported Waste: Not reported Date Trans10 Transported Waste: Not reported 01/26/2005 Date TSDF Received Waste: Tranporter 1 Decal: Not reported Tranporter 2 Decal: Not reported Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported Transporter-3 EPA Facility Name: Not reported Transporter-4 EPA Facility Name: Not reported Transporter-5 EPA Facility Name: Not reported TSDF EPA Facility Name: Not reported Not reported QTY Units: Transporter SEQ ID: Not reported Transporter-1 Date: Not reported Waste SEQ ID: Not reported Waste Type Code 2: Not reported Not reported Waste Type Code 3: Waste Type Code 4: Not reported Waste Type Code 5: Not reported Waste Type Code 6: Not reported Date Accepted: Not reported Manifest Discrepancy Type: Not reported Data Entry Number: 03030521 Reference Manifest Number: Not reported

Distance Elevation

Site Database(s) EPA ID Number

#### **USA MOTORS INC (Continued)**

1004681868

**EDR ID Number** 

Was Load Rejected (Y/N): No

Reason Load Was Rejected:
Waste Code:
Manifest Year:

Quantity:
Unit:
Not reported

Manifest Code: NJA5070813 EPA ID: DCR000500017 Date Shipped: 03/17/2005 TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Transporter 3 EPA ID: Not reported Transporter 4 EPA ID: Not reported Transporter 5 EPA ID: Not reported Transporter 6 EPA ID: Not reported Transporter 7 EPA ID: Not reported Transporter 8 EPA ID: Not reported Not reported Transporter 10 EPA ID: Date Trans1 Transported Waste: 03/17/2005 Date Trans2 Transported Waste: Not reported Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Not reported Date Trans6 Transported Waste: Not reported Date Trans7 Transported Waste: Not reported Date Trans8 Transported Waste: Not reported Date Trans9 Transported Waste: Not reported Date Trans10 Transported Waste: Not reported Date TSDF Received Waste: 03/21/2005 Tranporter 1 Decal: Not reported Not reported Tranporter 2 Decal: Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported Transporter-3 EPA Facility Name: Not reported Not reported Transporter-4 EPA Facility Name: Not reported Transporter-5 EPA Facility Name: TSDF EPA Facility Name: Not reported QTY Units: Not reported Not reported Transporter SEQ ID: Transporter-1 Date: Not reported Waste SEQ ID: Not reported Waste Type Code 2: Not reported Waste Type Code 3: Not reported Not reported Waste Type Code 4: Waste Type Code 5: Not reported Waste Type Code 6: Not reported Date Accepted: Not reported Manifest Discrepancy Type: Not reported 05110521 Data Entry Number: Reference Manifest Number: Not reported Was Load Rejected (Y/N): No

Distance Elevation

Site Database(s) EPA ID Number

## **USA MOTORS INC (Continued)**

1004681868

**EDR ID Number** 

Reason Load Was Rejected:

Waste Code:

Manifest Year:

Quantity:

Unit:

Not reported

Manifest Code: NJA5213719 EPA ID: DCR000500017 Date Shipped: 05/19/2005 TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Transporter 3 EPA ID: Not reported Transporter 4 EPA ID: Not reported Transporter 5 EPA ID: Not reported Transporter 6 EPA ID: Not reported Transporter 7 EPA ID: Not reported Transporter 8 EPA ID: Not reported Transporter 10 EPA ID: Not reported 05/19/2005 Date Trans1 Transported Waste: Date Trans2 Transported Waste: Not reported Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Not reported Date Trans6 Transported Waste: Not reported Date Trans7 Transported Waste: Not reported Date Trans8 Transported Waste: Not reported Date Trans9 Transported Waste: Not reported Date Trans10 Transported Waste: Not reported Date TSDF Received Waste: 05/23/2005 Tranporter 1 Decal: Not reported Not reported Tranporter 2 Decal: Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported Transporter-3 EPA Facility Name: Not reported Transporter-4 EPA Facility Name: Not reported Not reported Transporter-5 EPA Facility Name: TSDF EPA Facility Name: Not reported QTY Units: Not reported Not reported Transporter SEQ ID: Transporter-1 Date: Not reported Waste SEQ ID: Not reported Waste Type Code 2: Not reported Waste Type Code 3: Not reported Waste Type Code 4: Not reported Not reported Waste Type Code 5: Waste Type Code 6: Not reported Date Accepted: Not reported Not reported Manifest Discrepancy Type: Data Entry Number: 06240521 Reference Manifest Number: Not reported Was Load Rejected (Y/N): No

Reason Load Was Rejected:

Not reported

Distance Elevation

Site Database(s) EPA ID Number

#### **USA MOTORS INC (Continued)**

1004681868

**EDR ID Number** 

Waste Code: Not reported Manifest Year: Not reported Quantity: Not reported Unit: Not reported Hand Code: Not reported

Manifest Code: NJA5068396 EPA ID: DCR000500017 Date Shipped: 07/06/2005 TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Transporter 3 EPA ID: Not reported Transporter 4 EPA ID: Not reported Not reported Transporter 5 EPA ID: Transporter 6 EPA ID: Not reported Transporter 7 EPA ID: Not reported Transporter 8 EPA ID: Not reported Transporter 10 EPA ID: Not reported Date Trans1 Transported Waste: 07/06/2005 Date Trans2 Transported Waste: Not reported Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Not reported Date Trans6 Transported Waste: Not reported Date Trans7 Transported Waste: Not reported Date Trans8 Transported Waste: Not reported Date Trans9 Transported Waste: Not reported Date Trans10 Transported Waste: Not reported Date TSDF Received Waste: 07/12/2005 Tranporter 1 Decal: Not reported Tranporter 2 Decal: Not reported Not reported Generator EPA Facility Name: Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported Transporter-3 EPA Facility Name: Not reported Transporter-4 EPA Facility Name: Not reported Transporter-5 EPA Facility Name: Not reported TSDF EPA Facility Name: Not reported QTY Units: Not reported Transporter SEQ ID: Not reported Transporter-1 Date: Not reported Waste SEQ ID: Not reported Waste Type Code 2: Not reported Waste Type Code 3: Not reported Waste Type Code 4: Not reported Waste Type Code 5: Not reported Not reported Waste Type Code 6: Date Accepted: Not reported Manifest Discrepancy Type: Not reported 08100521 Data Entry Number: Reference Manifest Number: Not reported Was Load Rejected (Y/N): No Not reported Reason Load Was Rejected:

Not reported

Waste Code:

Distance Elevation Site

Site Database(s) EPA ID Number

#### **USA MOTORS INC (Continued)**

1004681868

**EDR ID Number** 

Manifest Year: Not reported Quantity: Not reported Unit: Not reported Hand Code: Not reported

Manifest Code: NJA5068142 EPA ID: DCR000500017 Date Shipped: 09/12/2005 TSDF EPA ID: NJD002182897 TXR000050930 Transporter EPA ID: Transporter 2 EPA ID: Not reported Transporter 3 EPA ID: Not reported Transporter 4 EPA ID: Not reported Transporter 5 EPA ID: Not reported Not reported Transporter 6 EPA ID: Transporter 7 EPA ID: Not reported Transporter 8 EPA ID: Not reported Transporter 10 EPA ID: Not reported Date Trans1 Transported Waste: 09/12/2005 Date Trans2 Transported Waste: Not reported Not reported Date Trans3 Transported Waste: Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Not reported Date Trans6 Transported Waste: Not reported Date Trans7 Transported Waste: Not reported Date Trans8 Transported Waste: Not reported Date Trans9 Transported Waste: Not reported Date Trans10 Transported Waste: Not reported Date TSDF Received Waste: 09/20/2005 Tranporter 1 Decal: Not reported Tranporter 2 Decal: Not reported Generator EPA Facility Name: Not reported Not reported Transporter-1 EPA Facility Name: Transporter-2 EPA Facility Name: Not reported Transporter-3 EPA Facility Name: Not reported Transporter-4 EPA Facility Name: Not reported Transporter-5 EPA Facility Name: Not reported TSDF EPA Facility Name: Not reported Not reported QTY Units: Not reported Transporter SEQ ID: Transporter-1 Date: Not reported Waste SEQ ID: Not reported Waste Type Code 2: Not reported Waste Type Code 3: Not reported Waste Type Code 4: Not reported Waste Type Code 5: Not reported Waste Type Code 6: Not reported Not reported Date Accepted: Manifest Discrepancy Type: Not reported Data Entry Number: 10280521 Reference Manifest Number: Not reported Was Load Rejected (Y/N): No Reason Load Was Rejected: Not reported Waste Code: Not reported Manifest Year: Not reported

Distance Elevation Site

Site Database(s) EPA ID Number

#### **USA MOTORS INC (Continued)**

1004681868

**EDR ID Number** 

Quantity: Not reported Unit: Not reported Hand Code: Not reported

Manifest Code: NJA5250985 EPA ID: DCR000500017 Date Shipped: 10/26/2005 TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Transporter 3 EPA ID: Not reported Transporter 4 EPA ID: Not reported Transporter 5 EPA ID: Not reported Transporter 6 EPA ID: Not reported Not reported Transporter 7 EPA ID: Transporter 8 EPA ID: Not reported Transporter 10 EPA ID: Not reported 10/26/2005 Date Trans1 Transported Waste: Date Trans2 Transported Waste: Not reported Not reported Date Trans3 Transported Waste: Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Not reported Date Trans6 Transported Waste: Not reported Date Trans7 Transported Waste: Not reported Date Trans8 Transported Waste: Not reported Date Trans9 Transported Waste: Not reported Date Trans10 Transported Waste: Not reported Date TSDF Received Waste: 11/03/2005 Tranporter 1 Decal: Not reported Tranporter 2 Decal: Not reported Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported Not reported Transporter-2 EPA Facility Name: Transporter-3 EPA Facility Name: Not reported Transporter-4 EPA Facility Name: Not reported Transporter-5 EPA Facility Name: Not reported TSDF EPA Facility Name: Not reported QTY Units: Not reported Not reported Transporter SEQ ID: Transporter-1 Date: Not reported Waste SEQ ID: Not reported Waste Type Code 2: Not reported Waste Type Code 3: Not reported Waste Type Code 4: Not reported Waste Type Code 5: Not reported Waste Type Code 6: Not reported Date Accepted: Not reported Manifest Discrepancy Type: Not reported Data Entry Number: 12140535 Reference Manifest Number: Not reported Was Load Rejected (Y/N): No Reason Load Was Rejected: Not reported Waste Code: Not reported Manifest Year: Not reported

Not reported

Quantity:

Distance Elevation

tion Site Database(s) EPA ID Number

#### **USA MOTORS INC (Continued)**

1004681868

**EDR ID Number** 

Unit: Not reported Hand Code: Not reported

Manifest Code: NJA5255704 EPA ID: DCR000500017 Date Shipped: 12/16/2005 TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Transporter 3 EPA ID: Not reported Transporter 4 EPA ID: Not reported Transporter 5 EPA ID: Not reported Transporter 6 EPA ID: Not reported Transporter 7 EPA ID: Not reported Not reported Transporter 8 EPA ID: Transporter 10 EPA ID: Not reported Date Trans1 Transported Waste: 12/16/2005 Date Trans2 Transported Waste: Not reported Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Not reported Date Trans6 Transported Waste: Not reported Date Trans7 Transported Waste: Not reported Date Trans8 Transported Waste: Not reported Date Trans9 Transported Waste: Not reported Date Trans10 Transported Waste: Not reported Date TSDF Received Waste: 12/22/2005 Tranporter 1 Decal: Not reported Tranporter 2 Decal: Not reported Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported Not reported Transporter-3 EPA Facility Name: Transporter-4 EPA Facility Name: Not reported Transporter-5 EPA Facility Name: Not reported TSDF EPA Facility Name: Not reported QTY Units: Not reported Transporter SEQ ID: Not reported Not reported Transporter-1 Date: Waste SEQ ID: Not reported Waste Type Code 2: Not reported Not reported Waste Type Code 3: Not reported Waste Type Code 4: Waste Type Code 5: Not reported Waste Type Code 6: Not reported Date Accepted: Not reported Manifest Discrepancy Type: Not reported Data Entry Number: 02170622 Reference Manifest Number: Not reported Was Load Rejected (Y/N): Reason Load Was Rejected: Not reported Waste Code: Not reported Manifest Year: Not reported Quantity: Not reported Unit: Not reported

Distance Elevation

Site Database(s) **EPA ID Number** 

#### **USA MOTORS INC (Continued)**

1004681868

**EDR ID Number** 

Hand Code: Not reported

Manifest Code: 002090700SKS EPA ID: DCR000500017 Date Shipped: 08/26/2009 TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Not reported Transporter 3 EPA ID: Transporter 4 EPA ID: Not reported Transporter 5 EPA ID: Not reported Transporter 6 EPA ID: Not reported Transporter 7 EPA ID: Not reported Transporter 8 EPA ID: Not reported Not reported Transporter 10 EPA ID: Date Trans1 Transported Waste: 08/26/2009 Date Trans2 Transported Waste: Not reported Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Not reported Date Trans6 Transported Waste: Not reported Date Trans7 Transported Waste: Not reported Date Trans8 Transported Waste: Not reported Date Trans9 Transported Waste: Not reported Date Trans10 Transported Waste: Not reported Date TSDF Received Waste: 09/01/2009 Tranporter 1 Decal: Not reported Tranporter 2 Decal: Not reported Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported Transporter-3 EPA Facility Name: Not reported Not reported Transporter-4 EPA Facility Name: Transporter-5 EPA Facility Name: Not reported TSDF EPA Facility Name: Not reported QTY Units: Not reported Transporter SEQ ID: Not reported Transporter-1 Date: Not reported Not reported Waste SEQ ID: Not reported Waste Type Code 2: Waste Type Code 3: Not reported Waste Type Code 4: Not reported Waste Type Code 5: Not reported Waste Type Code 6: Not reported Date Accepted: Not reported Manifest Discrepancy Type: Not reported Data Entry Number: Not reported Reference Manifest Number: Not reported

Was Load Rejected (Y/N): No Reason Load Was Rejected: Not reported

Waste Code: D039

Manifest Year: 2009 New Jersey Manifest Data

Quantity: 14 G Unit: Hand Code: H020

Distance Elevation Site

e Database(s) EPA ID Number

### **USA MOTORS INC (Continued)**

1004681868

**EDR ID Number** 

Manifest Code: NJA5096032 DCR000500017 EPA ID: Date Shipped: 01/02/2004 TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Transporter 3 EPA ID: Not reported Not reported Transporter 4 EPA ID: Transporter 5 EPA ID: Not reported Transporter 6 EPA ID: Not reported Transporter 7 EPA ID: Not reported Transporter 8 EPA ID: Not reported Transporter 10 EPA ID: Not reported Date Trans1 Transported Waste: 01/02/2004 Date Trans2 Transported Waste: Not reported Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Not reported Date Trans6 Transported Waste: Not reported Date Trans7 Transported Waste: Not reported Date Trans8 Transported Waste: Not reported Date Trans9 Transported Waste: Not reported Date Trans10 Transported Waste: Not reported Date TSDF Received Waste: 01/14/2004 Tranporter 1 Decal: Not reported Tranporter 2 Decal: Not reported Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported Transporter-3 EPA Facility Name: Not reported Transporter-4 EPA Facility Name: Not reported Transporter-5 EPA Facility Name: Not reported TSDF EPA Facility Name: Not reported QTY Units: Not reported Not reported Transporter SEQ ID: Transporter-1 Date: Not reported Waste SEQ ID: Not reported Waste Type Code 2: Not reported Waste Type Code 3: Not reported Waste Type Code 4: Not reported Not reported Waste Type Code 5: Waste Type Code 6: Not reported Date Accepted: Not reported Manifest Discrepancy Type: Not reported 03120421 Data Entry Number: Reference Manifest Number: Not reported Was Load Rejected (Y/N): No Reason Load Was Rejected: Not reported Waste Code: Not reported Manifest Year: Not reported Quantity: Not reported Not reported Hand Code: Not reported

Manifest Code: NJA5117455

Distance Elevation

Site Database(s) EPA ID Number

#### **USA MOTORS INC (Continued)**

1004681868

**EDR ID Number** 

EPA ID: DCR000500017 Date Shipped: 02/17/2004 TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Transporter 3 EPA ID: Not reported Transporter 4 EPA ID: Not reported Transporter 5 EPA ID: Not reported Transporter 6 EPA ID: Not reported Transporter 7 EPA ID: Not reported Transporter 8 EPA ID: Not reported Transporter 10 EPA ID: Not reported Date Trans1 Transported Waste: 02/17/2004 Date Trans2 Transported Waste: Not reported Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Not reported Date Trans6 Transported Waste: Not reported Date Trans7 Transported Waste: Not reported Date Trans8 Transported Waste: Not reported Date Trans9 Transported Waste: Not reported Date Trans10 Transported Waste: Not reported Date TSDF Received Waste: 02/27/2004 Tranporter 1 Decal: Not reported Tranporter 2 Decal: Not reported Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported Transporter-3 EPA Facility Name: Not reported Transporter-4 EPA Facility Name: Not reported Transporter-5 EPA Facility Name: Not reported TSDF EPA Facility Name: Not reported QTY Units: Not reported Transporter SEQ ID: Not reported Transporter-1 Date: Not reported Waste SEQ ID: Not reported Waste Type Code 2: Not reported Waste Type Code 3: Not reported Waste Type Code 4: Not reported Waste Type Code 5: Not reported Not reported Waste Type Code 6: Not reported Date Accepted: Manifest Discrepancy Type: Not reported 03300422 Data Entry Number: Reference Manifest Number: Not reported Was Load Rejected (Y/N): No Reason Load Was Rejected: Not reported Waste Code: Not reported Manifest Year: Not reported Quantity: Not reported Unit: Not reported Hand Code: Not reported

Manifest Code: NJA5094874 EPA ID: DCR000500017

Elevation Site

Distance

ite Database(s) EPA ID Number

**USA MOTORS INC (Continued)** 

1004681868

**EDR ID Number** 

Date Shipped: 04/20/2004 NJD002182897 TSDF EPA ID: Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Transporter 3 EPA ID: Not reported Transporter 4 EPA ID: Not reported Transporter 5 EPA ID: Not reported Transporter 6 EPA ID: Not reported Transporter 7 EPA ID: Not reported Transporter 8 EPA ID: Not reported Transporter 10 EPA ID: Not reported Date Trans1 Transported Waste: 04/20/2004 Date Trans2 Transported Waste: Not reported Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Not reported Not reported Date Trans6 Transported Waste: Date Trans7 Transported Waste: Not reported Date Trans8 Transported Waste: Not reported Date Trans9 Transported Waste: Not reported Date Trans10 Transported Waste: Not reported Date TSDF Received Waste: 04/26/2004 Tranporter 1 Decal: Not reported Tranporter 2 Decal: Not reported Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported Transporter-3 EPA Facility Name: Not reported Transporter-4 EPA Facility Name: Not reported Not reported Transporter-5 EPA Facility Name: TSDF EPA Facility Name: Not reported QTY Units: Not reported Transporter SEQ ID: Not reported Transporter-1 Date: Not reported Waste SEQ ID: Not reported Waste Type Code 2: Not reported Waste Type Code 3: Not reported Waste Type Code 4: Not reported Waste Type Code 5: Not reported Waste Type Code 6: Not reported Date Accepted: Not reported Not reported Manifest Discrepancy Type: Data Entry Number: 05110421 Not reported Reference Manifest Number: Was Load Rejected (Y/N): No Reason Load Was Rejected: Not reported Waste Code: Not reported Manifest Year: Not reported Quantity: Not reported Unit: Not reported

 Manifest Code:
 NJA5039563

 EPA ID:
 DCR000500017

 Date Shipped:
 06/14/2004

Not reported

Hand Code:

Distance Elevation

n Site Database(s) EPA ID Number

## **USA MOTORS INC (Continued)**

1004681868

**EDR ID Number** 

TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Not reported Transporter 3 EPA ID: Transporter 4 EPA ID: Not reported Transporter 5 EPA ID: Not reported Transporter 6 EPA ID: Not reported Not reported Transporter 7 EPA ID: Transporter 8 EPA ID: Not reported Transporter 10 EPA ID: Not reported Date Trans1 Transported Waste: 06/14/2004 Date Trans2 Transported Waste: Not reported Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Not reported Date Trans6 Transported Waste: Not reported Not reported Date Trans7 Transported Waste: Date Trans8 Transported Waste: Not reported Date Trans9 Transported Waste: Not reported Date Trans10 Transported Waste: Not reported Date TSDF Received Waste: 06/16/2004 Tranporter 1 Decal: Not reported Not reported Tranporter 2 Decal: Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported Transporter-3 EPA Facility Name: Not reported Transporter-4 EPA Facility Name: Not reported Transporter-5 EPA Facility Name: Not reported Not reported TSDF EPA Facility Name: QTY Units: Not reported Transporter SEQ ID: Not reported Transporter-1 Date: Not reported Waste SEQ ID: Not reported Waste Type Code 2: Not reported Waste Type Code 3: Not reported Waste Type Code 4: Not reported Waste Type Code 5: Not reported Waste Type Code 6: Not reported Date Accepted: Not reported Manifest Discrepancy Type: Not reported Data Entry Number: 06250421 Reference Manifest Number: Not reported Was Load Rejected (Y/N): No Reason Load Was Rejected: Not reported Waste Code: Not reported Manifest Year: Not reported Quantity: Not reported Unit: Not reported Hand Code: Not reported

 Manifest Code:
 NJA5070147

 EPA ID:
 DCR000500017

 Date Shipped:
 08/03/2004

 TSDF EPA ID:
 NJD002182897

Direction Distance Elevation

Site Database(s) EPA ID Number

## **USA MOTORS INC (Continued)**

1004681868

**EDR ID Number** 

Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Transporter 3 EPA ID: Not reported Transporter 4 EPA ID: Not reported Transporter 5 EPA ID: Not reported Transporter 6 EPA ID: Not reported Transporter 7 EPA ID: Not reported Transporter 8 EPA ID: Not reported Not reported Transporter 10 EPA ID: Date Trans1 Transported Waste: 08/03/2004 Date Trans2 Transported Waste: Not reported Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Not reported Date Trans6 Transported Waste: Not reported Date Trans7 Transported Waste: Not reported Not reported Date Trans8 Transported Waste: Date Trans9 Transported Waste: Not reported Date Trans10 Transported Waste: Not reported 08/06/2004 Date TSDF Received Waste: Tranporter 1 Decal: Not reported Tranporter 2 Decal: Not reported Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported Transporter-3 EPA Facility Name: Not reported Transporter-4 EPA Facility Name: Not reported Transporter-5 EPA Facility Name: Not reported TSDF EPA Facility Name: Not reported QTY Units: Not reported Transporter SEQ ID: Not reported Transporter-1 Date: Not reported Waste SEQ ID: Not reported Waste Type Code 2: Not reported Waste Type Code 3: Not reported Waste Type Code 4: Not reported Waste Type Code 5: Not reported Waste Type Code 6: Not reported Date Accepted: Not reported Manifest Discrepancy Type: Not reported Data Entry Number: 08300425 Reference Manifest Number: Not reported Was Load Rejected (Y/N): No Reason Load Was Rejected: Not reported Waste Code: Not reported Manifest Year: Not reported Quantity: Not reported Unit: Not reported Hand Code: Not reported

 Manifest Code:
 NJA5071346

 EPA ID:
 DCR000500017

 Date Shipped:
 10/01/2004

 TSDF EPA ID:
 NJD002182897

 Transporter EPA ID:
 TXR000050930

Distance Elevation

Site Database(s) EPA ID Number

## **USA MOTORS INC (Continued)**

1004681868

**EDR ID Number** 

Transporter 2 EPA ID: Not reported Not reported Transporter 3 EPA ID: Transporter 4 EPA ID: Not reported Transporter 5 EPA ID: Not reported Transporter 6 EPA ID: Not reported Transporter 7 EPA ID: Not reported Transporter 8 EPA ID: Not reported Transporter 10 EPA ID: Not reported 10/01/2004 Date Trans1 Transported Waste: Date Trans2 Transported Waste: Not reported Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Not reported Date Trans6 Transported Waste: Not reported Date Trans7 Transported Waste: Not reported Date Trans8 Transported Waste: Not reported Not reported Date Trans9 Transported Waste: Date Trans10 Transported Waste: Not reported Date TSDF Received Waste: 10/07/2004 Tranporter 1 Decal: Not reported Tranporter 2 Decal: Not reported Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported Transporter-3 EPA Facility Name: Not reported Transporter-4 EPA Facility Name: Not reported Transporter-5 EPA Facility Name: Not reported TSDF EPA Facility Name: Not reported QTY Units: Not reported Transporter SEQ ID: Not reported Transporter-1 Date: Not reported Waste SEQ ID: Not reported Waste Type Code 2: Not reported Waste Type Code 3: Not reported Waste Type Code 4: Not reported Waste Type Code 5: Not reported Waste Type Code 6: Not reported Date Accepted: Not reported Manifest Discrepancy Type: Not reported Data Entry Number: 11030425 Reference Manifest Number: Not reported Was Load Rejected (Y/N): No Reason Load Was Rejected: Not reported Not reported Waste Code: Not reported Manifest Year: Quantity: Not reported Unit: Not reported Hand Code: Not reported

 Manifest Code:
 NJA5072111

 EPA ID:
 DCR000500017

 Date Shipped:
 11/19/2004

 TSDF EPA ID:
 NJD002182897

 Transporter EPA ID:
 TXR000050930

 Transporter 2 EPA ID:
 Not reported

Direction Distance Elevation

Site Database(s) EPA ID Number

## **USA MOTORS INC (Continued)**

1004681868

**EDR ID Number** 

Transporter 3 EPA ID: Not reported Not reported Transporter 4 EPA ID: Transporter 5 EPA ID: Not reported Transporter 6 EPA ID: Not reported Transporter 7 EPA ID: Not reported Transporter 8 EPA ID: Not reported Transporter 10 EPA ID: Not reported Date Trans1 Transported Waste: 11/19/2004 Date Trans2 Transported Waste: Not reported Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Not reported Date Trans6 Transported Waste: Not reported Date Trans7 Transported Waste: Not reported Date Trans8 Transported Waste: Not reported Date Trans9 Transported Waste: Not reported Not reported Date Trans10 Transported Waste: Date TSDF Received Waste: 11/24/2004 Tranporter 1 Decal: Not reported Tranporter 2 Decal: Not reported Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported Transporter-3 EPA Facility Name: Not reported Transporter-4 EPA Facility Name: Not reported Transporter-5 EPA Facility Name: Not reported TSDF EPA Facility Name: Not reported QTY Units: Not reported Transporter SEQ ID: Not reported Transporter-1 Date: Not reported Waste SEQ ID: Not reported Waste Type Code 2: Not reported Waste Type Code 3: Not reported Waste Type Code 4: Not reported Waste Type Code 5: Not reported Waste Type Code 6: Not reported Date Accepted: Not reported Manifest Discrepancy Type: Not reported Data Entry Number: 01050525 Reference Manifest Number: Not reported Was Load Rejected (Y/N): No Reason Load Was Rejected: Not reported Waste Code: Not reported Not reported Manifest Year: Quantity: Not reported Unit: Not reported Hand Code: Not reported

 Manifest Code:
 001848711SKS

 EPA ID:
 DCR000500017

 Date Shipped:
 02/12/2010

 TSDF EPA ID:
 NJD002182897

 Transporter EPA ID:
 TXR000050930

 Transporter 2 EPA ID:
 Not reported

 Transporter 3 EPA ID:
 Not reported

Direction Distance Elevation

on Site Database(s) EPA ID Number

## **USA MOTORS INC (Continued)**

1004681868

**EDR ID Number** 

Transporter 4 EPA ID: Not reported Not reported Transporter 5 EPA ID: Transporter 6 EPA ID: Not reported Transporter 7 EPA ID: Not reported Transporter 8 EPA ID: Not reported Not reported Transporter 10 EPA ID: Date Trans1 Transported Waste: 02/12/2010 Date Trans2 Transported Waste: Not reported Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Not reported Date Trans6 Transported Waste: Not reported Date Trans7 Transported Waste: Not reported Date Trans8 Transported Waste: Not reported Date Trans9 Transported Waste: Not reported Date Trans10 Transported Waste: Not reported 02/18/2010 Date TSDF Received Waste: Tranporter 1 Decal: Not reported Tranporter 2 Decal: Not reported Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported Transporter-3 EPA Facility Name: Not reported Transporter-4 EPA Facility Name: Not reported Transporter-5 EPA Facility Name: Not reported TSDF EPA Facility Name: Not reported QTY Units: Not reported Transporter SEQ ID: Not reported Transporter-1 Date: Not reported Waste SEQ ID: Not reported Waste Type Code 2: Not reported Waste Type Code 3: Not reported Waste Type Code 4: Not reported Waste Type Code 5: Not reported Waste Type Code 6: Not reported Date Accepted: Not reported Manifest Discrepancy Type: Not reported Data Entry Number: Not reported Reference Manifest Number: Not reported Was Load Rejected (Y/N): No

Reason Load Was Rejected: Not reported

Waste Code: D039

Manifest Year: 2010 New Jersey Manifest Data

Quantity: 15 Unit: G Hand Code: H020

Manifest Code: 003648596FLE EPA ID: DCR000500017 Date Shipped: 1/26/2011 TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: NJD071629976 TXR000050930 Transporter 3 EPA ID: Transporter 4 EPA ID: Not reported

Distance Elevation S

Site Database(s) EPA ID Number

**USA MOTORS INC (Continued)** 

1004681868

**EDR ID Number** 

Transporter 5 EPA ID: Not reported Not reported Transporter 6 EPA ID: Transporter 7 EPA ID: Not reported Transporter 8 EPA ID: Not reported Transporter 10 EPA ID: Not reported Not reported Date Trans1 Transported Waste: Not reported Date Trans2 Transported Waste: Not reported Date Trans3 Transported Waste: Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Not reported Date Trans6 Transported Waste: Not reported Date Trans7 Transported Waste: Not reported Date Trans8 Transported Waste: Not reported Date Trans9 Transported Waste: Not reported Date Trans10 Transported Waste: Not reported Date TSDF Received Waste: Not reported Not reported Tranporter 1 Decal: Tranporter 2 Decal: Not reported Generator EPA Facility Name: **USA MOTORS INC** 

Transporter-1 EPA Facility Name: SAFETY KLEEN SYSTEMS INC
Transporter-2 EPA Facility Name: SJ TRANSPORTATION COMPANY
Transporter-3 EPA Facility Name: SAFETY KLEEN SYSTEMS INC

Transporter-4 EPA Facility Name: Not reported Transporter-5 EPA Facility Name: Not reported

TSDF EPA Facility Name: SAFETY KLEEN SYSTEMS INC

QTY Units: gallons
Transporter SEQ ID: 1.00
Transporter-1 Date: 1/26/2011
Waste SEQ ID: 1.00
Waste Type Code 2: Not reported
Waste Type Code 3: Not reported
Waste Type Code 4: Not reported

Waste Type Code 5: Not reported Waste Type Code 6: Not reported 2/3/2011 Date Accepted: Manifest Discrepancy Type: Not reported Data Entry Number: Not reported Reference Manifest Number: Not reported Was Load Rejected (Y/N): Not reported Reason Load Was Rejected: Not reported Waste Code: D039

Manifest Year: 2011 New Jersey Manifest Data

Quantity:14.00Unit:gallonsHand Code:H020

Manifest Code: 001600365SKS EPA ID: DCR000500017 Date Shipped: 03/12/2009 TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Transporter 3 EPA ID: Not reported Transporter 4 EPA ID: Not reported Transporter 5 EPA ID: Not reported

Distance Elevation

Site Database(s) EPA ID Number

## **USA MOTORS INC (Continued)**

1004681868

**EDR ID Number** 

Transporter 6 EPA ID: Not reported Not reported Transporter 7 EPA ID: Transporter 8 EPA ID: Not reported Transporter 10 EPA ID: Not reported Date Trans1 Transported Waste: 03/12/2009 Not reported Date Trans2 Transported Waste: Date Trans3 Transported Waste: Not reported Not reported Date Trans4 Transported Waste: Date Trans5 Transported Waste: Not reported Date Trans6 Transported Waste: Not reported Date Trans7 Transported Waste: Not reported Date Trans8 Transported Waste: Not reported Date Trans9 Transported Waste: Not reported Date Trans10 Transported Waste: Not reported Date TSDF Received Waste: 03/16/2009 Tranporter 1 Decal: Not reported Not reported Tranporter 2 Decal: Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported Transporter-3 EPA Facility Name: Not reported Not reported Transporter-4 EPA Facility Name: Not reported Transporter-5 EPA Facility Name: TSDF EPA Facility Name: Not reported QTY Units: Not reported Transporter SEQ ID: Not reported Transporter-1 Date: Not reported Waste SEQ ID: Not reported Waste Type Code 2: Not reported Not reported Waste Type Code 3: Not reported Waste Type Code 4: Waste Type Code 5: Not reported Waste Type Code 6: Not reported Date Accepted: Not reported Not reported Manifest Discrepancy Type: Data Entry Number: Not reported Reference Manifest Number: Not reported

Was Load Rejected (Y/N): No

Reason Load Was Rejected: Not reported Waste Code: D039

Manifest Year: 2009 New Jersey Manifest Data

Quantity: 29
Unit: G
Hand Code: H020

Manifest Code: 000266120CEX EPA ID: DCR000500017 Date Shipped: 10/22/2009 TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Transporter 3 EPA ID: Not reported Transporter 4 EPA ID: Not reported Transporter 5 EPA ID: Not reported Transporter 6 EPA ID: Not reported

Distance Elevation

Site Database(s) EPA ID Number

## **USA MOTORS INC (Continued)**

1004681868

**EDR ID Number** 

Transporter 7 EPA ID: Not reported Not reported Transporter 8 EPA ID: Not reported Transporter 10 EPA ID: 10/22/2009 Date Trans1 Transported Waste: Date Trans2 Transported Waste: Not reported Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Not reported Not reported Date Trans5 Transported Waste: Date Trans6 Transported Waste: Not reported Date Trans7 Transported Waste: Not reported Date Trans8 Transported Waste: Not reported Date Trans9 Transported Waste: Not reported Date Trans10 Transported Waste: Not reported Date TSDF Received Waste: 10/28/2009 Tranporter 1 Decal: Not reported Tranporter 2 Decal: Not reported Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported Transporter-3 EPA Facility Name: Not reported Transporter-4 EPA Facility Name: Not reported Transporter-5 EPA Facility Name: Not reported Not reported TSDF EPA Facility Name: QTY Units: Not reported Transporter SEQ ID: Not reported Transporter-1 Date: Not reported Waste SEQ ID: Not reported Waste Type Code 2: Not reported Waste Type Code 3: Not reported Not reported Waste Type Code 4: Waste Type Code 5: Not reported Waste Type Code 6: Not reported Date Accepted: Not reported Manifest Discrepancy Type: Not reported Not reported Data Entry Number: Reference Manifest Number: Not reported

Was Load Rejected (Y/N): No

Reason Load Was Rejected: Not reported Waste Code: D039

Manifest Year: 2009 New Jersey Manifest Data

Quantity: 15 Unit: G Hand Code: H020

Manifest Code: 001910737SKS EPA ID: DCR000500017 Date Shipped: 05/08/2009 TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Transporter 3 EPA ID: Not reported Transporter 4 EPA ID: Not reported Transporter 5 EPA ID: Not reported Transporter 6 EPA ID: Not reported Transporter 7 EPA ID: Not reported

Direction Distance

Elevation Site Database(s) **EPA ID Number** 

## **USA MOTORS INC (Continued)**

1004681868

**EDR ID Number** 

Transporter 8 EPA ID: Not reported Not reported Transporter 10 EPA ID: Date Trans1 Transported Waste: 05/08/2009 Date Trans2 Transported Waste: Not reported Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Not reported Not reported Date Trans6 Transported Waste: Date Trans7 Transported Waste: Not reported Date Trans8 Transported Waste: Not reported Date Trans9 Transported Waste: Not reported Date Trans10 Transported Waste: Not reported Date TSDF Received Waste: 05/11/2009 Tranporter 1 Decal: Not reported Tranporter 2 Decal: Not reported Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported Transporter-3 EPA Facility Name: Not reported Transporter-4 EPA Facility Name: Not reported Transporter-5 EPA Facility Name: Not reported TSDF EPA Facility Name: Not reported QTY Units: Not reported Transporter SEQ ID: Not reported Transporter-1 Date: Not reported Waste SEQ ID: Not reported Waste Type Code 2: Not reported Waste Type Code 3: Not reported Waste Type Code 4: Not reported Waste Type Code 5: Not reported Waste Type Code 6: Not reported Date Accepted: Not reported Manifest Discrepancy Type: Not reported Data Entry Number: Not reported Not reported Reference Manifest Number:

Was Load Rejected (Y/N): No

Reason Load Was Rejected: Not reported

Waste Code: D039

Manifest Year: 2009 New Jersey Manifest Data

**USA MOTORS INC** 

Quantity: 13 Unit: G Hand Code: H020

D16 **45 Q ST SW** NNE

**EDR US Hist Auto Stat** 1015501451

N/A

< 1/8 0.032 mi.

WASHINGTON, DC 20024 Site 4 of 5 in cluster D

168 ft.

**EDR Historical Auto Stations:** Relative:

Name:

**USA MOTORS INC** Name: Higher

Year: 2001 Address: 45 Q ST SW

Actual: 25 ft.

Year: 2006

MAP FINDINGS Map ID

Direction Distance

**EDR ID Number** Elevation Site Database(s) **EPA ID Number** 

(Continued) 1015501451

Address: 45 Q ST SW

**USA MOTORS INC** Name:

Year: 2008 Address: 45 Q ST SW

**USA MOTORS INC** Name:

Year: 2010 Address: 45 Q ST SW

Name: **USA MOTORS INC** 

Year: 2012 45 Q ST SW Address:

E17 DC BROWNFIELDS \$108931576

SE 1900 HALF STREET, SW < 1/8 WASHINGTON, DC

0.037 mi.

196 ft. Site 1 of 2 in cluster E

BROWNFIELD: Relative:

PB ID: PBF2003-0071 Lower Ownership: Private

Actual: Size (sf): 110,988 11 ft. Phase I: unknown Phase II: unknown Lot: 0015

Square: 0666

38.87650263 / -77.00351471 Latitude/Longitude: Notes: WS: Other

E18 **WESTWOOD MANAGEMENT CORPORATION** DC LUST U003054158 1900 HALF ST SW DC UST N/A SE

< 1/8 WASHINGTON, DC 20024

0.037 mi.

196 ft. Site 2 of 2 in cluster E LUST:

Relative: Facility ID: 2-000221 Lower Facility Type: Other Actual: Facility Status:

Closed 11 ft. Product: Heating Oil Notification Date: Not reported

Media Of Contamination: Soil Not reported Entry Date: Lust Number: 95042

UST:

2000221 Facility ID: Facility Description: False

WESTWOOD MANAGEMENT CORPORATION Owner:

Tank ID:

Tank Status: **Permanently Out of Use** 

Tank Capacity: 300 N/A

Direction Distance

**EDR ID Number** Elevation Site Database(s) **EPA ID Number** 

**WESTWOOD MANAGEMENT CORPORATION (Continued)** 

U003054158

**NJ MANIFEST** 

Substance: Diesel

DC HIST UST \$110337839 F19 UNKNOWN N/A

1620 1ST ST SW North < 1/8 WASHINGTON, DC

0.040 mi.

Site 1 of 5 in cluster F 211 ft.

HIST UST: Relative:

Facility Id: 2003502*001 Higher Confirm Tank/Owner Address Found:Not reported

Actual: Confirn Tank/No Owner Found: Not reported 24 ft. Owner Found/No Tank: Not reported

No Owner/No Tank: Not reported Address Not Found:

yes Ltr Edc: Not reported

Tank Status: UNK Tank Capacity: Not reported

Product: unk

D20 **GOLD STAR SERVICES** RCRA-CESQG 1001122928 DCR000000711 NE 39 Q STREET SW **FINDS** 

< 1/8 WASHINGTON, DC 20024

0.047 mi.

247 ft. Site 5 of 5 in cluster D

RCRA-CESQG: Relative:

Date form received by agency: 06/08/2011 Higher

GOLD STAR SERVICES Facility name: Actual: Facility address: 39 Q STREET SW 24 ft. WASHINGTON, DC 20024

> EPA ID: DCR000000711

Q STREET SW

Mailing address: WASHINGTON, DC 20024

Contact: PRITMAN S GHUMAN

Contact address: Q STREET SW

WASHINGTON, DC 20024

US Contact country:

Contact telephone: 202-484-5555 Contact email: Not reported EPA Region: 03

Land type: Private

Classification: Conditionally Exempt Small Quantity Generator

Description: Handler: generates 100 kg or less of hazardous waste per calendar

month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of

any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely

Direction Distance Elevation

Site Database(s) **EPA ID Number** 

## **GOLD STAR SERVICES (Continued)**

1001122928

**EDR ID Number** 

hazardous waste

Owner/Operator Summary:

Owner/operator name: PRITMAN GHUMAN Owner/operator address: Q STREET SW

WASHINGTON, DC 20024

Owner/operator country:

Owner/operator telephone: Not reported Legal status: Private Owner/Operator Type: Operator 04/01/1998 Owner/Op start date: Owner/Op end date: Not reported

Owner/operator name: SEREKE NEWAY Owner/operator address: 39 Q STREET SW

WASHINGTON, DC 20024

Owner/operator country: US

Owner/operator telephone: Not reported Legal status: Private Owner/Operator Type: Operator 05/01/2003 Owner/Op start date: Owner/Op end date: Not reported

PRITMAN GHUMAN Owner/operator name: Owner/operator address: Q STREET SW

WASHINGTON, DC 20024

Owner/operator country: US

Owner/operator telephone: Not reported Legal status: Private Owner/Operator Type: Owner 04/01/1998 Owner/Op start date: Owner/Op end date: Not reported

SODHI JAGJIT SINGH Owner/operator name: Owner/operator address: 5612 WOOD TRUSH CT FAIRFAX, VA 22032

Owner/operator country: Not reported Owner/operator telephone: (703) 426-0328 Legal status: Private

Owner/Operator Type: Owner Owner/Op start date: 01/01/0001 Owner/Op end date: Not reported

Owner/operator name: **GHUMAN INC** Owner/operator address: 39 Q STREET SW

WASHINGTON, DC 20024

Owner/operator country: US

Owner/operator telephone: (202) 484-5555

Legal status:

Private Owner/Operator Type: Owner Owner/Op start date: 05/01/2003 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: Mixed waste (haz. and radioactive): No

Direction Distance

Elevation Site Database(s) EPA ID Number

## **GOLD STAR SERVICES (Continued)**

1001122928

**EDR ID Number** 

Recycler of hazardous waste: No Transporter of hazardous waste: No Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: No Furnace exemption: No Used oil fuel burner: No Used oil processor: Nο User oil refiner: No Used oil fuel marketer to burner: No Used oil Specification marketer: No Used oil transfer facility: No Used oil transporter: No

**Historical Generators:** 

Date form received by agency: 07/13/2009

Facility name: GOLD STAR SERVICES

Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 02/04/2004

Facility name: GOLD STAR SERVICES

Site name: GHUMAN INC.

Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 11/29/1996

Facility name: GOLD STAR SERVICES
Site name: SRL AUTO SERVICE INC

Classification: Conditionally Exempt Small Quantity Generator

Hazardous Waste Summary:

Waste code: D002

Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS

CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Waste code: D008 Waste name: LEAD

Waste code: F005

Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL

KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE,

2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF

LISTED IN FUUT, FUUZ, OR FUU4, AND STILL BUTTUMS FRUM THE REC

THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Facility Has Received Notices of Violations: Regulation violated: SR - 4202.7(e)

Area of violation: Generators - Pre-transport

Date violation determined: 03/26/2003 Date achieved compliance: 12/09/2008

Direction Distance

Elevation Site Database(s) EPA ID Number

## **GOLD STAR SERVICES (Continued)**

1001122928

**EDR ID Number** 

Violation lead agency: State

Enforcement action: WRITTEN INFORMAL

Enforcement action date: 04/07/2003
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 4200.6

Area of violation: Generators - General

Date violation determined: 03/26/1998
Date achieved compliance: 04/24/1998
Violation lead agency: State

Enforcement action: WRITTEN INFORMAL

Enforcement action date: 03/26/1998
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State

Proposed penalty amount: Not reported Final penalty amount: Not reported Paid penalty amount: Not reported

Regulation violated: SR - 4200.6(d)
Area of violation: Generators - General

Date violation determined: 03/26/1998
Date achieved compliance: 04/24/1998
Violation lead agency: State

Enforcement action: WRITTEN INFORMAL

Enforcement action date: 03/26/1998
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Paid penalty amount: Not reported
Paid penalty amount: Not reported

**Evaluation Action Summary:** 

Evaluation date: 06/08/2011

Evaluation: NON-FINANCIAL RECORD REVIEW

Area of violation:

Date achieved compliance:

Evaluation lead agency:

Not reported

Not reported

State

Evaluation date: 03/26/2003

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: Generators - Pre-transport

Date achieved compliance: 12/09/2008 Evaluation lead agency: State

Evaluation date: 03/26/1998

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: Generators - General

Date achieved compliance: 04/24/1998
Evaluation lead agency: State

Distance Elevation

Site Database(s) EPA ID Number

## **GOLD STAR SERVICES (Continued)**

1001122928

**EDR ID Number** 

Evaluation date: 01/07/1997

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation:

Date achieved compliance:

Evaluation lead agency:

Not reported

State

FINDS:

Registry ID: 110002504111

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NJ MANIFEST:

Manifest Code: NJA5068143 EPA ID: DCR000000711 Date Shipped: 09/12/2005 TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Transporter 3 EPA ID: Not reported Transporter 4 EPA ID: Not reported Transporter 5 EPA ID: Not reported Transporter 6 EPA ID: Not reported Transporter 7 EPA ID: Not reported Transporter 8 EPA ID: Not reported Transporter 10 EPA ID: Not reported Date Trans1 Transported Waste: 09/12/2005 Date Trans2 Transported Waste: Not reported Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Not reported Date Trans6 Transported Waste: Not reported Date Trans7 Transported Waste: Not reported Date Trans8 Transported Waste: Not reported Date Trans9 Transported Waste: Not reported Date Trans10 Transported Waste: Not reported 09/20/2005 Date TSDF Received Waste: Tranporter 1 Decal: Not reported Tranporter 2 Decal: Not reported Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported Transporter-3 EPA Facility Name: Not reported Transporter-4 EPA Facility Name: Not reported Transporter-5 EPA Facility Name: Not reported TSDF EPA Facility Name: Not reported QTY Units: Not reported Transporter SEQ ID: Not reported Transporter-1 Date: Not reported Waste SEQ ID: Not reported

Direction Distance Elevation

Site Database(s) EPA ID Number

## **GOLD STAR SERVICES (Continued)**

1001122928

**EDR ID Number** 

Waste Type Code 2: Not reported Not reported Waste Type Code 3: Not reported Waste Type Code 4: Waste Type Code 5: Not reported Waste Type Code 6: Not reported Date Accepted: Not reported Manifest Discrepancy Type: Not reported Data Entry Number: 10280521 Reference Manifest Number: Not reported Was Load Rejected (Y/N): No

Reason Load Was Rejected:

Waste Code:

Mot reported

Waste Code:

Mot reported

Not reported

Manifest Code: NJA5085568 EPA ID: DCR000000711 Date Shipped: 05/14/2004 TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Transporter 3 EPA ID: Not reported Transporter 4 EPA ID: Not reported Transporter 5 EPA ID: Not reported Transporter 6 EPA ID: Not reported Transporter 7 EPA ID: Not reported Transporter 8 EPA ID: Not reported Transporter 10 EPA ID: Not reported Date Trans1 Transported Waste: 05/14/2004 Date Trans2 Transported Waste: Not reported Not reported Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Date Trans5 Transported Waste: Not reported Date Trans6 Transported Waste: Not reported Date Trans7 Transported Waste: Not reported Date Trans8 Transported Waste: Not reported Date Trans9 Transported Waste: Not reported Date Trans10 Transported Waste: Not reported Date TSDF Received Waste: 05/21/2004 Tranporter 1 Decal: Not reported Tranporter 2 Decal: Not reported Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported Transporter-3 EPA Facility Name: Not reported Transporter-4 EPA Facility Name: Not reported Transporter-5 EPA Facility Name: Not reported TSDF EPA Facility Name: Not reported QTY Units: Not reported Transporter SEQ ID: Not reported Transporter-1 Date: Not reported Waste SEQ ID: Not reported Waste Type Code 2: Not reported

Distance Elevation

Site Database(s) EPA ID Number

## **GOLD STAR SERVICES (Continued)**

1001122928

**EDR ID Number** 

Waste Type Code 3: Not reported Waste Type Code 4: Not reported Not reported Waste Type Code 5: Waste Type Code 6: Not reported Date Accepted: Not reported Manifest Discrepancy Type: Not reported 06070422 Data Entry Number: Reference Manifest Number: Not reported

Was Load Rejected (Y/N):
Reason Load Was Rejected:
Waste Code:
Manifest Year:
Quantity:
Unit:
Hand Code:
No
No
Not reported
Not reported
Not reported
Not reported
Not reported

Manifest Code: NJA5040675 EPA ID: DCR000000711 Date Shipped: 07/07/2004 TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Transporter 3 EPA ID: Not reported Transporter 4 EPA ID: Not reported Transporter 5 EPA ID: Not reported Transporter 6 EPA ID: Not reported Transporter 7 EPA ID: Not reported Not reported Transporter 8 EPA ID: Transporter 10 EPA ID: Not reported 07/07/2004 Date Trans1 Transported Waste: Date Trans2 Transported Waste: Not reported Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Not reported Date Trans6 Transported Waste: Not reported Date Trans7 Transported Waste: Not reported Date Trans8 Transported Waste: Not reported Date Trans9 Transported Waste: Not reported Date Trans10 Transported Waste: Not reported 07/12/2004 Date TSDF Received Waste: Tranporter 1 Decal: Not reported Tranporter 2 Decal: Not reported Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported Transporter-3 EPA Facility Name: Not reported Transporter-4 EPA Facility Name: Not reported Transporter-5 EPA Facility Name: Not reported TSDF EPA Facility Name: Not reported QTY Units: Not reported Transporter SEQ ID: Not reported Transporter-1 Date: Not reported Waste SEQ ID: Not reported Waste Type Code 2: Not reported Waste Type Code 3: Not reported

Distance
Elevation Site Database(s)

## **GOLD STAR SERVICES (Continued)**

1001122928

**EDR ID Number** 

**EPA ID Number** 

Waste Type Code 4: Not reported Waste Type Code 5: Not reported Not reported Waste Type Code 6: Not reported Date Accepted: Manifest Discrepancy Type: Not reported 08200421 Data Entry Number: Reference Manifest Number: Not reported Was Load Rejected (Y/N): Nο

Reason Load Was Rejected:

Waste Code:

Manifest Year:

Quantity:

Unit:

Not reported

Manifest Code: NJA5071663 EPA ID: DCR000000711 Date Shipped: 08/16/2004 TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Transporter 3 EPA ID: Not reported Transporter 4 EPA ID: Not reported Transporter 5 EPA ID: Not reported Transporter 6 EPA ID: Not reported Transporter 7 EPA ID: Not reported Transporter 8 EPA ID: Not reported Not reported Transporter 10 EPA ID: 08/16/2004 Date Trans1 Transported Waste: Date Trans2 Transported Waste: Not reported Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Not reported Not reported Date Trans5 Transported Waste: Not reported Date Trans6 Transported Waste: Date Trans7 Transported Waste: Not reported Date Trans8 Transported Waste: Not reported Date Trans9 Transported Waste: Not reported Date Trans10 Transported Waste: Not reported Date TSDF Received Waste: 08/24/2004 Tranporter 1 Decal: Not reported Tranporter 2 Decal: Not reported Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported Transporter-3 EPA Facility Name: Not reported Transporter-4 EPA Facility Name: Not reported Transporter-5 EPA Facility Name: Not reported TSDF EPA Facility Name: Not reported QTY Units: Not reported Transporter SEQ ID: Not reported Transporter-1 Date: Not reported Waste SEQ ID: Not reported Waste Type Code 2: Not reported Waste Type Code 3: Not reported Waste Type Code 4: Not reported

Distance Elevation

Site Database(s) EPA ID Number

## **GOLD STAR SERVICES (Continued)**

1001122928

**EDR ID Number** 

Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: 09170422
Reference Manifest Number: Not reported

Was Load Rejected (Y/N): No

Reason Load Was Rejected:
Waste Code:
Waste Code:
Mot reported
Manifest Year:
Quantity:
Unit:
Not reported

Manifest Code: NJA5071347 EPA ID: DCR000000711 Date Shipped: 10/01/2004 TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Transporter 3 EPA ID: Not reported Transporter 4 EPA ID: Not reported Transporter 5 EPA ID: Not reported Transporter 6 EPA ID: Not reported Transporter 7 EPA ID: Not reported Transporter 8 EPA ID: Not reported Transporter 10 EPA ID: Not reported 10/01/2004 Date Trans1 Transported Waste: Date Trans2 Transported Waste: Not reported Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Not reported Not reported Date Trans6 Transported Waste: Date Trans7 Transported Waste: Not reported Date Trans8 Transported Waste: Not reported Date Trans9 Transported Waste: Not reported Date Trans10 Transported Waste: Not reported Date TSDF Received Waste: 10/07/2004 Tranporter 1 Decal: Not reported Not reported Tranporter 2 Decal: Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported Transporter-3 EPA Facility Name: Not reported Transporter-4 EPA Facility Name: Not reported Transporter-5 EPA Facility Name: Not reported TSDF EPA Facility Name: Not reported QTY Units: Not reported Transporter SEQ ID: Not reported Transporter-1 Date: Not reported Waste SEQ ID: Not reported Waste Type Code 2: Not reported Waste Type Code 3: Not reported Waste Type Code 4: Not reported Waste Type Code 5: Not reported

Distance Elevation

Site Database(s) EPA ID Number

## **GOLD STAR SERVICES (Continued)**

1001122928

**EDR ID Number** 

Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: 11030425
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No

Was Load Rejected (Y/N):

Reason Load Was Rejected:

Waste Code:

Mot reported

Manifest Year:

Quantity:

Unit:

Not reported

Manifest Code: NJA5069437 EPA ID: DCR000000711 Date Shipped: 11/09/2004 TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Transporter 3 EPA ID: Not reported Transporter 4 EPA ID: Not reported Transporter 5 EPA ID: Not reported Transporter 6 EPA ID: Not reported Transporter 7 EPA ID: Not reported Transporter 8 EPA ID: Not reported Transporter 10 EPA ID: Not reported Date Trans1 Transported Waste: 11/09/2004 Date Trans2 Transported Waste: Not reported Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Not reported Date Trans6 Transported Waste: Not reported Not reported Date Trans7 Transported Waste: Date Trans8 Transported Waste: Not reported Date Trans9 Transported Waste: Not reported Date Trans10 Transported Waste: Not reported Date TSDF Received Waste: 11/11/2004 Not reported Tranporter 1 Decal: Tranporter 2 Decal: Not reported Not reported Generator EPA Facility Name: Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported Transporter-3 EPA Facility Name: Not reported Transporter-4 EPA Facility Name: Not reported Transporter-5 EPA Facility Name: Not reported TSDF EPA Facility Name: Not reported QTY Units: Not reported Transporter SEQ ID: Not reported Transporter-1 Date: Not reported Waste SEQ ID: Not reported Waste Type Code 2: Not reported Waste Type Code 3: Not reported Waste Type Code 4: Not reported Waste Type Code 5: Not reported Waste Type Code 6: Not reported

Distance Elevation Site

Site Database(s) EPA ID Number

## **GOLD STAR SERVICES (Continued)**

1001122928

**EDR ID Number** 

Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: 01180525
Reference Manifest Number: Not reported

Was Load Rejected (Y/N): No

Reason Load Was Rejected:
Waste Code:
Manifest Year:
Quantity:
Unit:
Not reported

Manifest Code: NJA5224981 EPA ID: DCR000000711 Date Shipped: 12/29/2004 TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Transporter 3 EPA ID: Not reported Transporter 4 EPA ID: Not reported Transporter 5 EPA ID: Not reported Transporter 6 EPA ID: Not reported Transporter 7 EPA ID: Not reported Transporter 8 EPA ID: Not reported Transporter 10 EPA ID: Not reported Date Trans1 Transported Waste: 12/29/2004 Date Trans2 Transported Waste: Not reported Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Not reported Date Trans6 Transported Waste: Not reported Date Trans7 Transported Waste: Not reported Not reported Date Trans8 Transported Waste: Date Trans9 Transported Waste: Not reported Not reported Date Trans10 Transported Waste: Date TSDF Received Waste: 01/05/2005 Tranporter 1 Decal: Not reported Tranporter 2 Decal: Not reported Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported Not reported Transporter-3 EPA Facility Name: Transporter-4 EPA Facility Name: Not reported Transporter-5 EPA Facility Name: Not reported TSDF EPA Facility Name: Not reported QTY Units: Not reported Transporter SEQ ID: Not reported Transporter-1 Date: Not reported Waste SEQ ID: Not reported Waste Type Code 2: Not reported Waste Type Code 3: Not reported Waste Type Code 4: Not reported Waste Type Code 5: Not reported Waste Type Code 6: Not reported Date Accepted: Not reported

Distance EDR ID Number
Elevation Site EDR ID Number
Database(s) EPA ID Number

## **GOLD STAR SERVICES (Continued)**

1001122928

Manifest Discrepancy Type:
Data Entry Number:

Reference Manifest Number:
Was Load Rejected (Y/N):
Reason Load Was Rejected:

Not reported
Not reported
No Not reported

Waste Code:

Manifest Year:

Quantity:

Unit:

Not reported

Manifest Code: NJA5070814 EPA ID: DCR000000711 Date Shipped: 03/14/2005 TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Transporter 3 EPA ID: Not reported Transporter 4 EPA ID: Not reported Transporter 5 EPA ID: Not reported Transporter 6 EPA ID: Not reported Transporter 7 EPA ID: Not reported Transporter 8 EPA ID: Not reported Transporter 10 EPA ID: Not reported Date Trans1 Transported Waste: 03/14/2005 Date Trans2 Transported Waste: Not reported Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Not reported Date Trans6 Transported Waste: Not reported Date Trans7 Transported Waste: Not reported Date Trans8 Transported Waste: Not reported Not reported Date Trans9 Transported Waste: Not reported Date Trans10 Transported Waste: Date TSDF Received Waste: 03/21/2005 Tranporter 1 Decal: Not reported Tranporter 2 Decal: Not reported Not reported Generator EPA Facility Name: Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported Transporter-3 EPA Facility Name: Not reported Not reported Transporter-4 EPA Facility Name: Not reported Transporter-5 EPA Facility Name: TSDF EPA Facility Name: Not reported QTY Units: Not reported Transporter SEQ ID: Not reported Transporter-1 Date: Not reported Waste SEQ ID: Not reported Waste Type Code 2: Not reported Waste Type Code 3: Not reported Waste Type Code 4: Not reported Waste Type Code 5: Not reported Waste Type Code 6: Not reported Date Accepted: Not reported

Manifest Discrepancy Type:

Not reported

Distance Elevation Site

Database(s)

1001122928

**EDR ID Number** 

**EPA ID Number** 

#### **GOLD STAR SERVICES (Continued)**

Data Entry Number: 05110521
Reference Manifest Number: Not reported

Was Load Rejected (Y/N): No

Reason Load Was Rejected:
Waste Code:
Manifest Year:

Quantity:
Unit:
Not reported

Manifest Code: NJA5225356 EPA ID: DCR000000711 Date Shipped: 06/06/2005 TSDF EPA ID: NJD002182897 TXR000050930 Transporter EPA ID: Transporter 2 EPA ID: Not reported Transporter 3 EPA ID: Not reported Transporter 4 EPA ID: Not reported Transporter 5 EPA ID: Not reported Transporter 6 EPA ID: Not reported Transporter 7 EPA ID: Not reported Transporter 8 EPA ID: Not reported Transporter 10 EPA ID: Not reported Date Trans1 Transported Waste: 06/06/2005 Date Trans2 Transported Waste: Not reported Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Not reported Date Trans6 Transported Waste: Not reported Date Trans7 Transported Waste: Not reported Date Trans8 Transported Waste: Not reported Date Trans9 Transported Waste: Not reported Not reported Date Trans10 Transported Waste: 06/14/2005 Date TSDF Received Waste: Tranporter 1 Decal: Not reported Tranporter 2 Decal: Not reported Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported Transporter-3 EPA Facility Name: Not reported Transporter-4 EPA Facility Name: Not reported Not reported Transporter-5 EPA Facility Name: TSDF EPA Facility Name: Not reported QTY Units: Not reported Transporter SEQ ID: Not reported Transporter-1 Date: Not reported Waste SEQ ID: Not reported Waste Type Code 2: Not reported Waste Type Code 3: Not reported Waste Type Code 4: Not reported Waste Type Code 5: Not reported Waste Type Code 6: Not reported Date Accepted: Not reported Manifest Discrepancy Type: Not reported Data Entry Number: 07210521

Direction Distance

Elevation Site Database(s) EPA ID Number

GOLD STAR SERVICES (Continued) 1001122928

Reference Manifest Number: Not reported Was Load Rejected (Y/N): No

Reason Load Was Rejected:
Waste Code:
Manifest Year:
Quantity:
Unit:
Hand Code:
Not reported

F21 UNKNOWN DC HIST UST S110337833
North 1615 1ST ST SW N/A

North 1615 1ST ST SW < 1/8 WASHINGTON, DC

0.049 mi.

261 ft. Site 2 of 5 in cluster F

Relative: HIST UST:

Higher Facility Id: 2003501*001

Confirm Tank/Owner Address Found:Not reported

Actual: Confirn Tank/No Owner Found: Not reported

24 ft. Owner Found/No Tank: Not reported

No Owner/No Tank: yes

Address Not Found:

Ltr Edc:

Tank Status:

Not reported

Not reported

UNK

Tank Capacity:

Not reported

Product: unk

F22 AUTO WARD INC. RCRA-CESQG 1000495676
NNW 129 Q STREET SW FINDS DCD983969064

< 1/8 WASHINGTON, DC 20024 0.069 mi.

Actual:

18 ft.

365 ft. Site 3 of 5 in cluster F

Relative: RCRA-CESQG:

**Lower** Date form received by agency: 03/31/2011

Facility name: AUTO WARD INC.
Facility address: 129 Q STREET SW
WASHINGTON, DC 20024

EPA ID: DCD983969064

Mailing address: Q STREET SW WASHINGTON, DC 20024

Contact: MUHAMMAD SALEEM

Contact address: Q STREET SW

WASHINGTON, DC 20024

Contact country: US

Contact telephone: (NON) E G-IVEN
Contact email: Not reported

EPA Region: 03 Land type: Private

Classification: Conditionally Exempt Small Quantity Generator

Description: Handler: generates 100 kg or less of hazardous waste per calendar

month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous

**NJ MANIFEST** 

**EDR ID Number** 

Direction
Distance
Elevation

Site Database(s) EPA ID Number

## **AUTO WARD INC. (Continued)**

1000495676

**EDR ID Number** 

waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name: TIBER CREEK ASSOCIATES
Owner/operator address: 655 15TH ST NW STE 410
WASHINGTON, DC 20006

Owner/operator country: Not reported (202) 639-3813

Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: MUHAMMAD SALEEM

Owner/operator address: Q STREET

WASHINGTON, DC 20024

Owner/operator country: US

Owner/operator telephone: 202-484-2222
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 01/01/2000
Owner/Op end date: Not reported

Owner/operator name: MUHAMMAD SALEEM

Owner/operator address: Q STREET

WASHINGTON, DC 20024

Owner/operator country: US

Owner/operator telephone: 202-484-2222
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 01/01/2000
Owner/Op end date: Not reported

# Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: No Transporter of hazardous waste: No Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: No Furnace exemption: No Used oil fuel burner: No Used oil processor: No User oil refiner: No Used oil fuel marketer to burner: No Used oil Specification marketer: No

Direction Distance

Elevation Site Database(s) EPA ID Number

AUTO WARD INC. (Continued) 1000495676

Used oil transfer facility: No Used oil transporter: No

Historical Generators:

Date form received by agency: 05/12/2009
Facility name: AUTO WARD INC.

Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 08/19/1998
Facility name: AUTO WARD INC.

Site name: SAGA CORPORATION LINCOLN CAB ASSN Classification: Conditionally Exempt Small Quantity Generator

Hazardous Waste Summary:

Waste code: D001

Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF

LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT

WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D018
Waste name: BENZENE

Waste code: D035

Waste name: METHYL ETHYL KETONE

Waste code: D036

Waste name: NITROBENZENE

Waste code: D039

Waste name: TETRACHLOROETHYLENE

Waste code: D040

Waste name: TRICHLOROETHYLENE

Waste code: F005

Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL

KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE,

2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF

THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste code: F008

Waste name: PLATING BATH RESIDUES FROM THE BOTTOM OF PLATING BATHS FROM

ELECTROPLATING OPERATIONS WHERE CYANIDES ARE USED IN THE PROCESS.

Facility Has Received Notices of Violations:

Regulation violated: Not reported

Area of violation: Used Oil - Generators

Date violation determined: 12/09/2008
Date achieved compliance: 06/22/2009

**EDR ID Number** 

Distance Elevation

Site Database(s) EPA ID Number

## **AUTO WARD INC. (Continued)**

1000495676

**EDR ID Number** 

Violation lead agency: State Not reported Enforcement action: Enforcement action date: Not reported Enf. disposition status: Not reported Enf. disp. status date: Not reported Enforcement lead agency: Not reported Proposed penalty amount: Not reported Final penalty amount: Not reported Paid penalty amount: Not reported

Regulation violated: Not reported

Area of violation: TSD - General Facility Standards

Date violation determined: 12/09/2008 Date achieved compliance: 06/22/2009 Violation lead agency: State Enforcement action: Not reported Enforcement action date: Not reported Enf. disposition status: Not reported Enf. disp. status date: Not reported Enforcement lead agency: Not reported Not reported Proposed penalty amount: Final penalty amount: Not reported Paid penalty amount: Not reported

Regulation violated: Not reported

Area of violation: Used Oil - Applicability

Date violation determined: 12/09/2008 Date achieved compliance: 06/22/2009 Violation lead agency: State Enforcement action: Not reported Enforcement action date: Not reported Enf. disposition status: Not reported Enf. disp. status date: Not reported Enforcement lead agency: Not reported Proposed penalty amount: Not reported Final penalty amount: Not reported Paid penalty amount: Not reported

Regulation violated: SR - 262.41

Area of violation: Generators - Records/Reporting

Date violation determined: 04/04/1994
Date achieved compliance: 05/01/1996
Violation lead agency: State

Enforcement action: WRITTEN INFORMAL

Enforcement action date: 04/04/1994
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

**Evaluation Action Summary:** 

Evaluation date: 03/01/2011

Evaluation: NON-FINANCIAL RECORD REVIEW

Area of violation: Not reported Date achieved compliance: Not reported

Direction Distance

Elevation Site Database(s) EPA ID Number

**AUTO WARD INC. (Continued)** 

1000495676

**EDR ID Number** 

Evaluation lead agency: State

Evaluation date: 12/09/2008

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: Used Oil - Generators

Date achieved compliance: 06/22/2009 Evaluation lead agency: State

Evaluation date: 12/09/2008

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: TSD - General Facility Standards

Date achieved compliance: 06/22/2009 Evaluation lead agency: State

Evaluation date: 12/09/2008

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: Used Oil - Applicability

Date achieved compliance: 06/22/2009 Evaluation lead agency: State

Evaluation date: 08/13/1998

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation:

Date achieved compliance:

Evaluation lead agency:

Not reported

Not reported

State

Evaluation date: 01/23/1996

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation:

Date achieved compliance:

Evaluation lead agency:

Not reported

Not reported

State

Evaluation date: 01/16/1996

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation:

Date achieved compliance:

Evaluation lead agency:

Not reported
Not reported
State

Evaluation date: 04/04/1994

Evaluation: NON-FINANCIAL RECORD REVIEW Area of violation: Generators - Records/Reporting

Date achieved compliance: 05/01/1996 Evaluation lead agency: State

Evaluation date: 03/24/1994

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110002502140

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport,

Direction Distance Elevation

Site Database(s) EPA ID Number

## **AUTO WARD INC. (Continued)**

1000495676

**EDR ID Number** 

and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

PCS (Permit Compliance System) is a computerized management information system that contains data on National Pollutant Discharge Elimination System (NPDES) permit holding facilities. PCS tracks the permit, compliance, and enforcement status of NPDES facilities.

## NJ MANIFEST:

Manifest Code: 001799345SKS EPA ID: DCD983969064 Date Shipped: 06/18/2009 TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Transporter 3 EPA ID: Not reported Transporter 4 EPA ID: Not reported Transporter 5 EPA ID: Not reported Transporter 6 EPA ID: Not reported Transporter 7 EPA ID: Not reported Transporter 8 EPA ID: Not reported Transporter 10 EPA ID: Not reported 06/18/2009 Date Trans1 Transported Waste: Date Trans2 Transported Waste: Not reported Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Not reported Date Trans6 Transported Waste: Not reported Date Trans7 Transported Waste: Not reported Not reported Date Trans8 Transported Waste: Date Trans9 Transported Waste: Not reported Date Trans10 Transported Waste: Not reported Date TSDF Received Waste: 06/23/2009 Tranporter 1 Decal: Not reported Tranporter 2 Decal: Not reported Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported Transporter-3 EPA Facility Name: Not reported Transporter-4 EPA Facility Name: Not reported Transporter-5 EPA Facility Name: Not reported TSDF EPA Facility Name: Not reported QTY Units: Not reported Transporter SEQ ID: Not reported Transporter-1 Date: Not reported Waste SEQ ID: Not reported

Direction Distance Elevation

EDR ID Number
Site Database(s) EPA ID Number

## **AUTO WARD INC. (Continued)**

1000495676

Waste Type Code 2: Not reported Not reported Waste Type Code 3: Waste Type Code 4: Not reported Waste Type Code 5: Not reported Waste Type Code 6: Not reported Not reported Date Accepted: Manifest Discrepancy Type: Not reported Data Entry Number: Not reported Reference Manifest Number: Not reported

Was Load Rejected (Y/N): No

Reason Load Was Rejected: Not reported Waste Code: D001

Manifest Year: 2009 New Jersey Manifest Data

Quantity: 5
Unit: G
Hand Code: H020

Manifest Code: 002107476SKS EPA ID: DCD983969064 Date Shipped: 09/17/2009 TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Transporter 3 EPA ID: Not reported Transporter 4 EPA ID: Not reported Transporter 5 EPA ID: Not reported Transporter 6 EPA ID: Not reported Transporter 7 EPA ID: Not reported Transporter 8 EPA ID: Not reported Transporter 10 EPA ID: Not reported Date Trans1 Transported Waste: 09/17/2009 Date Trans2 Transported Waste: Not reported Not reported Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Date Trans5 Transported Waste: Not reported Date Trans6 Transported Waste: Not reported Date Trans7 Transported Waste: Not reported Date Trans8 Transported Waste: Not reported Date Trans9 Transported Waste: Not reported Date Trans10 Transported Waste: Not reported Date TSDF Received Waste: 09/22/2009 Tranporter 1 Decal: Not reported Tranporter 2 Decal: Not reported Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported Transporter-3 EPA Facility Name: Not reported Transporter-4 EPA Facility Name: Not reported Transporter-5 EPA Facility Name: Not reported TSDF EPA Facility Name: Not reported QTY Units: Not reported Transporter SEQ ID: Not reported Transporter-1 Date: Not reported Waste SEQ ID: Not reported Waste Type Code 2: Not reported

Distance Elevation

Site Database(s) EPA ID Number

# **AUTO WARD INC. (Continued)**

1000495676

**EDR ID Number** 

Waste Type Code 3: Not reported Not reported Waste Type Code 4: Waste Type Code 5: Not reported Waste Type Code 6: Not reported Date Accepted: Not reported Not reported Manifest Discrepancy Type: Data Entry Number: Not reported Reference Manifest Number: Not reported

Was Load Rejected (Y/N): No

Reason Load Was Rejected: Not reported Waste Code: D001

Manifest Year: 2009 New Jersey Manifest Data

Quantity: 5
Unit: G
Hand Code: H020

Manifest Code: 001196839SKS EPA ID: DCD983969064 Date Shipped: 04/28/2008 TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Transporter 3 EPA ID: Not reported Transporter 4 EPA ID: Not reported Transporter 5 EPA ID: Not reported Transporter 6 EPA ID: Not reported Transporter 7 EPA ID: Not reported Transporter 8 EPA ID: Not reported Transporter 10 EPA ID: Not reported Date Trans1 Transported Waste: 04/28/2008 Date Trans2 Transported Waste: Not reported Date Trans3 Transported Waste: Not reported Not reported Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Date Trans6 Transported Waste: Not reported Date Trans7 Transported Waste: Not reported Date Trans8 Transported Waste: Not reported Date Trans9 Transported Waste: Not reported Not reported Date Trans10 Transported Waste: Date TSDF Received Waste: 05/06/2008 Tranporter 1 Decal: Not reported Not reported Tranporter 2 Decal: Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported Transporter-3 EPA Facility Name: Not reported Transporter-4 EPA Facility Name: Not reported Transporter-5 EPA Facility Name: Not reported TSDF EPA Facility Name: Not reported QTY Units: Not reported Transporter SEQ ID: Not reported Transporter-1 Date: Not reported Waste SEQ ID: Not reported Waste Type Code 2: Not reported Waste Type Code 3: Not reported

Distance
Elevation Site

EDR ID Number
Database(s) EPA ID Number

## **AUTO WARD INC. (Continued)**

1000495676

Waste Type Code 4: Not reported Not reported Waste Type Code 5: Not reported Waste Type Code 6: Not reported Date Accepted: Manifest Discrepancy Type: Not reported Not reported Data Entry Number: Reference Manifest Number: Not reported Was Load Rejected (Y/N): Nο

Reason Load Was Rejected: Not reported Waste Code: D001

Manifest Year: 2008 New Jersey Manifest Data

Quantity: 6
Unit: G
Hand Code: H020

Manifest Code: NJA5069919 EPA ID: DCD983969064 Date Shipped: 02/04/2005 TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Transporter 3 EPA ID: Not reported Transporter 4 EPA ID: Not reported Transporter 5 EPA ID: Not reported Transporter 6 EPA ID: Not reported Transporter 7 EPA ID: Not reported Transporter 8 EPA ID: Not reported Transporter 10 EPA ID: Not reported 02/04/2005 Date Trans1 Transported Waste: Date Trans2 Transported Waste: Not reported Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Not reported Not reported Date Trans5 Transported Waste: Not reported Date Trans6 Transported Waste: Date Trans7 Transported Waste: Not reported Date Trans8 Transported Waste: Not reported Date Trans9 Transported Waste: Not reported Date Trans10 Transported Waste: Not reported Date TSDF Received Waste: 02/10/2005 Not reported Tranporter 1 Decal: Tranporter 2 Decal: Not reported Generator EPA Facility Name: Not reported Not reported Transporter-1 EPA Facility Name: Transporter-2 EPA Facility Name: Not reported Transporter-3 EPA Facility Name: Not reported Transporter-4 EPA Facility Name: Not reported Transporter-5 EPA Facility Name: Not reported TSDF EPA Facility Name: Not reported QTY Units: Not reported Transporter SEQ ID: Not reported Transporter-1 Date: Not reported Waste SEQ ID: Not reported Waste Type Code 2: Not reported Waste Type Code 3: Not reported Waste Type Code 4: Not reported

Distance EDR ID Number
Elevation Site EDR ID Number
Database(s) EPA ID Number

**AUTO WARD INC. (Continued)** 

1000495676

Waste Type Code 5: Not reported
Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: 04130521
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No

Reason Load Was Rejected:
Waste Code:
Manifest Year:
Quantity:
Unit:
Not reported

Manifest Code: NJA5222034 EPA ID: DCD983969064 Date Shipped: 04/29/2005 TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Not reported Transporter 2 EPA ID: Transporter 3 EPA ID: Not reported Transporter 4 EPA ID: Not reported Transporter 5 EPA ID: Not reported Transporter 6 EPA ID: Not reported Transporter 7 EPA ID: Not reported Transporter 8 EPA ID: Not reported Transporter 10 EPA ID: Not reported 04/29/2005 Date Trans1 Transported Waste: Date Trans2 Transported Waste: Not reported Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Not reported Not reported Date Trans6 Transported Waste: Not reported Date Trans7 Transported Waste: Date Trans8 Transported Waste: Not reported Date Trans9 Transported Waste: Not reported Date Trans10 Transported Waste: Not reported 05/05/2005 Date TSDF Received Waste: Tranporter 1 Decal: Not reported Not reported Tranporter 2 Decal: Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported Transporter-3 EPA Facility Name: Not reported Transporter-4 EPA Facility Name: Not reported Transporter-5 EPA Facility Name: Not reported TSDF EPA Facility Name: Not reported QTY Units: Not reported Transporter SEQ ID: Not reported Transporter-1 Date: Not reported Waste SEQ ID: Not reported Waste Type Code 2: Not reported Waste Type Code 3: Not reported Waste Type Code 4: Not reported Waste Type Code 5: Not reported

Distance Elevation Site

Databas

Database(s) EPA ID Number

## **AUTO WARD INC. (Continued)**

1000495676

**EDR ID Number** 

Waste Type Code 6: Not reported
Date Accepted: Not reported
Manifest Discrepancy Type: Not reported
Data Entry Number: 06020522
Reference Manifest Number: Not reported
Was Load Rejected (Y/N): No

Was Load Rejected (Y/N):

Reason Load Was Rejected:

Waste Code:

Manifest Year:

Quantity:

Unit:

Not reported

Manifest Code: NJA5068607 EPA ID: DCD983969064 Date Shipped: 07/19/2005 TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Transporter 3 EPA ID: Not reported Transporter 4 EPA ID: Not reported Transporter 5 EPA ID: Not reported Transporter 6 EPA ID: Not reported Transporter 7 EPA ID: Not reported Transporter 8 EPA ID: Not reported Transporter 10 EPA ID: Not reported Date Trans1 Transported Waste: 07/19/2005 Date Trans2 Transported Waste: Not reported Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Not reported Date Trans6 Transported Waste: Not reported Not reported Date Trans7 Transported Waste: Date Trans8 Transported Waste: Not reported Date Trans9 Transported Waste: Not reported Date Trans10 Transported Waste: Not reported Date TSDF Received Waste: 07/27/2005 Tranporter 1 Decal: Not reported Tranporter 2 Decal: Not reported Not reported Generator EPA Facility Name: Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported Transporter-3 EPA Facility Name: Not reported Transporter-4 EPA Facility Name: Not reported Transporter-5 EPA Facility Name: Not reported TSDF EPA Facility Name: Not reported QTY Units: Not reported Transporter SEQ ID: Not reported Transporter-1 Date: Not reported Waste SEQ ID: Not reported Waste Type Code 2: Not reported Waste Type Code 3: Not reported Waste Type Code 4: Not reported Waste Type Code 5: Not reported Waste Type Code 6: Not reported

Distance Elevation Site

**EDR ID Number** Database(s) **EPA ID Number** 

## **AUTO WARD INC. (Continued)**

1000495676

Date Accepted: Not reported Not reported Manifest Discrepancy Type: Data Entry Number: 09020521 Reference Manifest Number: Not reported Was Load Rejected (Y/N): No

Reason Load Was Rejected: Not reported Not reported Waste Code: Not reported Manifest Year: Quantity: Not reported Unit: Not reported Hand Code: Not reported

Manifest Code: NJA5250740 EPA ID: DCD983969064 Date Shipped: 10/11/2005 TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Transporter 3 EPA ID: Not reported Transporter 4 EPA ID: Not reported Transporter 5 EPA ID: Not reported Transporter 6 EPA ID: Not reported Transporter 7 EPA ID: Not reported Transporter 8 EPA ID: Not reported Transporter 10 EPA ID: Not reported Date Trans1 Transported Waste: 10/11/2005 Date Trans2 Transported Waste: Not reported Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Not reported Date Trans6 Transported Waste: Not reported Date Trans7 Transported Waste: Not reported Not reported Date Trans8 Transported Waste: Date Trans9 Transported Waste: Not reported Not reported Date Trans10 Transported Waste: Date TSDF Received Waste: 10/18/2005 Tranporter 1 Decal: Not reported Tranporter 2 Decal: Not reported Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported Not reported Transporter-3 EPA Facility Name: Transporter-4 EPA Facility Name: Not reported Transporter-5 EPA Facility Name: Not reported TSDF EPA Facility Name: Not reported QTY Units: Not reported Transporter SEQ ID: Not reported Transporter-1 Date: Not reported Waste SEQ ID: Not reported Waste Type Code 2: Not reported Waste Type Code 3: Not reported Waste Type Code 4: Not reported Waste Type Code 5: Not reported Waste Type Code 6: Not reported Date Accepted: Not reported

Map ID MAP FINDINGS Direction

Distance Elevation

Site Database(s) **EPA ID Number** 

### **AUTO WARD INC. (Continued)**

Unit:

Hand Code:

Manifest Discrepancy Type:

1000495676

**EDR ID Number** 

Not reported 12270521 Data Entry Number: Reference Manifest Number: Not reported Was Load Rejected (Y/N): No Reason Load Was Rejected: Not reported Not reported Waste Code: Not reported Manifest Year: Not reported Quantity:

Not reported

Not reported

Not reported

Manifest Code: 000339665SKS EPA ID: DCD983969064 Date Shipped: 06/04/2007 TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Transporter 3 EPA ID: Not reported Transporter 4 EPA ID: Not reported Transporter 5 EPA ID: Not reported Transporter 6 EPA ID: Not reported Transporter 7 EPA ID: Not reported Transporter 8 EPA ID: Not reported Transporter 10 EPA ID: Not reported Date Trans1 Transported Waste: 06/04/2007 Date Trans2 Transported Waste: Not reported Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Not reported Date Trans6 Transported Waste: Not reported Date Trans7 Transported Waste: Not reported Date Trans8 Transported Waste: Not reported Not reported Date Trans9 Transported Waste: Not reported Date Trans10 Transported Waste: Date TSDF Received Waste: 06/12/2007 Tranporter 1 Decal: Not reported Tranporter 2 Decal: Not reported Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported Transporter-3 EPA Facility Name: Not reported Not reported Transporter-4 EPA Facility Name: Not reported Transporter-5 EPA Facility Name: TSDF EPA Facility Name: Not reported QTY Units: Not reported Transporter SEQ ID: Not reported Transporter-1 Date: Not reported Waste SEQ ID: Not reported Waste Type Code 2: Not reported Waste Type Code 3: Not reported Waste Type Code 4: Not reported Waste Type Code 5: Not reported Waste Type Code 6: Not reported Date Accepted: Not reported

Manifest Discrepancy Type:

Direction Distance Elevation

on Site Database(s) EPA ID Number

### **AUTO WARD INC. (Continued)**

1000495676

**EDR ID Number** 

Data Entry Number: Not reported Reference Manifest Number: Not reported

Was Load Rejected (Y/N): No

Reason Load Was Rejected: Not reported Waste Code: D001

Manifest Year: 2007 New Jersey Manifest Data

 Quantity:
 7

 Unit:
 G

 Hand Code:
 H02

Manifest Code: NJA5036662 EPA ID: DCD983969064 Date Shipped: 03/04/2004 TSDF EPA ID: NJD002182897 TXR000050930 Transporter EPA ID: Transporter 2 EPA ID: Not reported Transporter 3 EPA ID: Not reported Transporter 4 EPA ID: Not reported Transporter 5 EPA ID: Not reported Transporter 6 EPA ID: Not reported Transporter 7 EPA ID: Not reported Transporter 8 EPA ID: Not reported Transporter 10 EPA ID: Not reported Date Trans1 Transported Waste: 03/04/2004 Date Trans2 Transported Waste: Not reported Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Not reported Date Trans6 Transported Waste: Not reported Date Trans7 Transported Waste: Not reported Date Trans8 Transported Waste: Not reported Date Trans9 Transported Waste: Not reported Not reported Date Trans10 Transported Waste: 03/05/2004 Date TSDF Received Waste: Tranporter 1 Decal: Not reported Tranporter 2 Decal: Not reported Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported Transporter-3 EPA Facility Name: Not reported Transporter-4 EPA Facility Name: Not reported Not reported Transporter-5 EPA Facility Name: TSDF EPA Facility Name: Not reported QTY Units: Not reported Transporter SEQ ID: Not reported Transporter-1 Date: Not reported Waste SEQ ID: Not reported Waste Type Code 2: Not reported Waste Type Code 3: Not reported Waste Type Code 4: Not reported Waste Type Code 5: Not reported Waste Type Code 6: Not reported Date Accepted: Not reported Manifest Discrepancy Type: Not reported Data Entry Number: 04020425

Map ID MAP FINDINGS
Direction

Distance Elevation Site

ite Database(s) EPA ID Number

# AUTO WARD INC. (Continued)

1000495676

**EDR ID Number** 

Reference Manifest Number: Not reported

Was Load Rejected (Y/N):

Reason Load Was Rejected:

Waste Code:

Manifest Year:

Quantity:

Unit:

Not reported

Manifest Code: NJA5039281 EPA ID: DCD983969064 Date Shipped: 05/21/2004 TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Transporter 3 EPA ID: Not reported Transporter 4 EPA ID: Not reported Transporter 5 EPA ID: Not reported Transporter 6 EPA ID: Not reported Transporter 7 EPA ID: Not reported Transporter 8 EPA ID: Not reported Transporter 10 EPA ID: Not reported Date Trans1 Transported Waste: 05/21/2004 Date Trans2 Transported Waste: Not reported Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Not reported Not reported Date Trans6 Transported Waste: Date Trans7 Transported Waste: Not reported Date Trans8 Transported Waste: Not reported Date Trans9 Transported Waste: Not reported Date Trans10 Transported Waste: Not reported 05/30/2004 Date TSDF Received Waste: Tranporter 1 Decal: Not reported Tranporter 2 Decal: Not reported Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported Not reported Transporter-2 EPA Facility Name: Transporter-3 EPA Facility Name: Not reported Not reported Transporter-4 EPA Facility Name: Transporter-5 EPA Facility Name: Not reported Not reported TSDF EPA Facility Name: Not reported QTY Units: Transporter SEQ ID: Not reported Transporter-1 Date: Not reported Waste SEQ ID: Not reported Waste Type Code 2: Not reported Waste Type Code 3: Not reported Waste Type Code 4: Not reported Waste Type Code 5: Not reported Waste Type Code 6: Not reported Date Accepted: Not reported Manifest Discrepancy Type: Not reported 06150421 Data Entry Number: Reference Manifest Number: Not reported

Map ID MAP FINDINGS
Direction

Distance Elevation Sit

Site Database(s) EPA ID Number

### **AUTO WARD INC. (Continued)**

1000495676

**EDR ID Number** 

Was Load Rejected (Y/N): No

Reason Load Was Rejected:

Waste Code:

Manifest Year:

Quantity:

Unit:

Not reported

Manifest Code: NJA5071665 EPA ID: DCD983969064 Date Shipped: 08/16/2004 TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Transporter 3 EPA ID: Not reported Transporter 4 EPA ID: Not reported Transporter 5 EPA ID: Not reported Transporter 6 EPA ID: Not reported Transporter 7 EPA ID: Not reported Transporter 8 EPA ID: Not reported Not reported Transporter 10 EPA ID: Date Trans1 Transported Waste: 08/16/2004 Date Trans2 Transported Waste: Not reported Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Not reported Date Trans6 Transported Waste: Not reported Date Trans7 Transported Waste: Not reported Date Trans8 Transported Waste: Not reported Date Trans9 Transported Waste: Not reported Date Trans10 Transported Waste: Not reported Date TSDF Received Waste: 08/24/2004 Tranporter 1 Decal: Not reported Not reported Tranporter 2 Decal: Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported Transporter-3 EPA Facility Name: Not reported Transporter-4 EPA Facility Name: Not reported Not reported Transporter-5 EPA Facility Name: TSDF EPA Facility Name: Not reported QTY Units: Not reported Transporter SEQ ID: Not reported Transporter-1 Date: Not reported Waste SEQ ID: Not reported Waste Type Code 2: Not reported Waste Type Code 3: Not reported Not reported Waste Type Code 4: Waste Type Code 5: Not reported Waste Type Code 6: Not reported Date Accepted: Not reported Manifest Discrepancy Type: Not reported 09170422 Data Entry Number: Reference Manifest Number: Not reported Was Load Rejected (Y/N): No

Direction Distance Elevation

Site Database(s) EPA ID Number

#### **AUTO WARD INC. (Continued)**

1000495676

**EDR ID Number** 

Reason Load Was Rejected:

Waste Code:

Manifest Year:

Quantity:

Unit:

Not reported

Manifest Code: NJA5069439 EPA ID: DCD983969064 Date Shipped: 11/09/2004 TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Transporter 3 EPA ID: Not reported Transporter 4 EPA ID: Not reported Transporter 5 EPA ID: Not reported Transporter 6 EPA ID: Not reported Transporter 7 EPA ID: Not reported Transporter 8 EPA ID: Not reported Transporter 10 EPA ID: Not reported 11/09/2004 Date Trans1 Transported Waste: Date Trans2 Transported Waste: Not reported Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Not reported Date Trans6 Transported Waste: Not reported Date Trans7 Transported Waste: Not reported Not reported Date Trans8 Transported Waste: Date Trans9 Transported Waste: Not reported Not reported Date Trans10 Transported Waste: Date TSDF Received Waste: 11/11/2004 Tranporter 1 Decal: Not reported Not reported Tranporter 2 Decal: Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported Transporter-3 EPA Facility Name: Not reported Transporter-4 EPA Facility Name: Not reported Not reported Transporter-5 EPA Facility Name: TSDF EPA Facility Name: Not reported QTY Units: Not reported Not reported Transporter SEQ ID: Transporter-1 Date: Not reported Waste SEQ ID: Not reported Waste Type Code 2: Not reported Waste Type Code 3: Not reported Waste Type Code 4: Not reported Not reported Waste Type Code 5: Waste Type Code 6: Not reported Date Accepted: Not reported Not reported Manifest Discrepancy Type: Data Entry Number: 01180525 Reference Manifest Number: Not reported Was Load Rejected (Y/N): No

Reason Load Was Rejected:

Not reported

Direction
Distance
Elevation

tion Site Database(s) EPA ID Number

### **AUTO WARD INC. (Continued)**

1000495676

**EDR ID Number** 

Waste Code:

Manifest Year:

Quantity:

Unit:

Not reported

Manifest Code: 001643717SKS EPA ID: DCD983969064 Date Shipped: 01/06/2009 TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Transporter 3 EPA ID: Not reported Transporter 4 EPA ID: Not reported Transporter 5 EPA ID: Not reported Transporter 6 EPA ID: Not reported Transporter 7 EPA ID: Not reported Transporter 8 EPA ID: Not reported Transporter 10 EPA ID: Not reported Date Trans1 Transported Waste: 01/06/2009 Date Trans2 Transported Waste: Not reported Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Not reported Date Trans6 Transported Waste: Not reported Date Trans7 Transported Waste: Not reported Date Trans8 Transported Waste: Not reported Date Trans9 Transported Waste: Not reported Date Trans10 Transported Waste: Not reported Date TSDF Received Waste: 01/20/2009 Tranporter 1 Decal: Not reported Tranporter 2 Decal: Not reported Not reported Generator EPA Facility Name: Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported Transporter-3 EPA Facility Name: Not reported Transporter-4 EPA Facility Name: Not reported Transporter-5 EPA Facility Name: Not reported TSDF EPA Facility Name: Not reported QTY Units: Not reported Transporter SEQ ID: Not reported Transporter-1 Date: Not reported Waste SEQ ID: Not reported Waste Type Code 2: Not reported Waste Type Code 3: Not reported Waste Type Code 4: Not reported Waste Type Code 5: Not reported Not reported Waste Type Code 6: Date Accepted: Not reported Manifest Discrepancy Type: Not reported Data Entry Number: Not reported Reference Manifest Number: Not reported Was Load Rejected (Y/N): No

Reason Load Was Rejected: Not reported Waste Code: D001

Map ID MAP FINDINGS
Direction

Distance Elevation

Site Database(s) EPA ID Number

### **AUTO WARD INC. (Continued)**

1000495676

**EDR ID Number** 

Manifest Year: 2009 New Jersey Manifest Data

Quantity: 6
Unit: G
Hand Code: H020

Manifest Code: NJA5307876 EPA ID: DCD983969064 Date Shipped: 01/05/2006 TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Transporter 3 EPA ID: Not reported Transporter 4 EPA ID: Not reported Transporter 5 EPA ID: Not reported Not reported Transporter 6 EPA ID: Transporter 7 EPA ID: Not reported Transporter 8 EPA ID: Not reported Transporter 10 EPA ID: Not reported Date Trans1 Transported Waste: 01/05/2006 Date Trans2 Transported Waste: Not reported Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Not reported Date Trans6 Transported Waste: Not reported Date Trans7 Transported Waste: Not reported Date Trans8 Transported Waste: Not reported Date Trans9 Transported Waste: Not reported Date Trans10 Transported Waste: Not reported Date TSDF Received Waste: 01/10/2006 Tranporter 1 Decal: Not reported Tranporter 2 Decal: Not reported Generator EPA Facility Name: Not reported Not reported Transporter-1 EPA Facility Name: Transporter-2 EPA Facility Name: Not reported Transporter-3 EPA Facility Name: Not reported Transporter-4 EPA Facility Name: Not reported Transporter-5 EPA Facility Name: Not reported TSDF EPA Facility Name: Not reported Not reported QTY Units: Not reported Transporter SEQ ID: Transporter-1 Date: Not reported Waste SEQ ID: Not reported Waste Type Code 2: Not reported Waste Type Code 3: Not reported Waste Type Code 4: Not reported Waste Type Code 5: Not reported Waste Type Code 6: Not reported Not reported Date Accepted: Manifest Discrepancy Type: Not reported Data Entry Number: 02280622 Reference Manifest Number: Not reported Was Load Rejected (Y/N): No Reason Load Was Rejected: Not reported Waste Code: Not reported Manifest Year: Not reported

Direction
Distance
Elevation

Site Database(s) EPA ID Number

### **AUTO WARD INC. (Continued)**

1000495676

**EDR ID Number** 

Quantity: Not reported Unit: Not reported Hand Code: Not reported

Manifest Code: NJA5308459 EPA ID: DCD983969064 Date Shipped: 03/29/2006 TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Transporter 3 EPA ID: Not reported Transporter 4 EPA ID: Not reported Transporter 5 EPA ID: Not reported Transporter 6 EPA ID: Not reported Not reported Transporter 7 EPA ID: Transporter 8 EPA ID: Not reported Transporter 10 EPA ID: Not reported 03/29/2006 Date Trans1 Transported Waste: Date Trans2 Transported Waste: Not reported Not reported Date Trans3 Transported Waste: Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Not reported Date Trans6 Transported Waste: Not reported Date Trans7 Transported Waste: Not reported Date Trans8 Transported Waste: Not reported Date Trans9 Transported Waste: Not reported Date Trans10 Transported Waste: Not reported Date TSDF Received Waste: 04/04/2006 Tranporter 1 Decal: Not reported Tranporter 2 Decal: Not reported Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported Not reported Transporter-2 EPA Facility Name: Transporter-3 EPA Facility Name: Not reported Transporter-4 EPA Facility Name: Not reported Transporter-5 EPA Facility Name: Not reported TSDF EPA Facility Name: Not reported QTY Units: Not reported Transporter SEQ ID: Not reported Transporter-1 Date: Not reported Waste SEQ ID: Not reported Waste Type Code 2: Not reported Waste Type Code 3: Not reported Waste Type Code 4: Not reported Waste Type Code 5: Not reported Waste Type Code 6: Not reported Date Accepted: Not reported Manifest Discrepancy Type: Not reported Data Entry Number: 05310621 Reference Manifest Number: Not reported Was Load Rejected (Y/N): No Reason Load Was Rejected: Not reported Waste Code: Not reported Manifest Year: Not reported

Not reported

Quantity:

Map ID MAP FINDINGS
Direction

Distance Elevation Site

Site Database(s) EPA ID Number

### **AUTO WARD INC. (Continued)**

1000495676

**EDR ID Number** 

Unit: Not reported Hand Code: Not reported

Manifest Code: NJA5256538 EPA ID: DCD983969064 Date Shipped: 06/19/2006 TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Transporter 3 EPA ID: Not reported Transporter 4 EPA ID: Not reported Transporter 5 EPA ID: Not reported Transporter 6 EPA ID: Not reported Transporter 7 EPA ID: Not reported Not reported Transporter 8 EPA ID: Transporter 10 EPA ID: Not reported Date Trans1 Transported Waste: 06/19/2006 Date Trans2 Transported Waste: Not reported Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Not reported Date Trans6 Transported Waste: Not reported Date Trans7 Transported Waste: Not reported Date Trans8 Transported Waste: Not reported Date Trans9 Transported Waste: Not reported Date Trans10 Transported Waste: Not reported Date TSDF Received Waste: 06/21/2006 Tranporter 1 Decal: Not reported Tranporter 2 Decal: Not reported Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported Not reported Transporter-3 EPA Facility Name: Transporter-4 EPA Facility Name: Not reported Transporter-5 EPA Facility Name: Not reported TSDF EPA Facility Name: Not reported QTY Units: Not reported Transporter SEQ ID: Not reported Not reported Transporter-1 Date: Waste SEQ ID: Not reported Waste Type Code 2: Not reported Not reported Waste Type Code 3: Waste Type Code 4: Not reported Waste Type Code 5: Not reported Waste Type Code 6: Not reported Date Accepted: Not reported Manifest Discrepancy Type: Not reported Data Entry Number: 08030625 Reference Manifest Number: Not reported Was Load Rejected (Y/N): Reason Load Was Rejected: Not reported Waste Code: Not reported Manifest Year: Not reported Quantity: Not reported Unit: Not reported

Direction Distance Elevation

on Site Database(s) EPA ID Number

#### **AUTO WARD INC. (Continued)**

1000495676

**EDR ID Number** 

Hand Code: Not reported

Manifest Code: 002303981SKS EPA ID: DCD983969064 Date Shipped: 06/03/2010 TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Not reported Transporter 3 EPA ID: Transporter 4 EPA ID: Not reported Transporter 5 EPA ID: Not reported Transporter 6 EPA ID: Not reported Transporter 7 EPA ID: Not reported Transporter 8 EPA ID: Not reported Not reported Transporter 10 EPA ID: Date Trans1 Transported Waste: 06/03/2010 Date Trans2 Transported Waste: Not reported Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Not reported Date Trans6 Transported Waste: Not reported Date Trans7 Transported Waste: Not reported Date Trans8 Transported Waste: Not reported Date Trans9 Transported Waste: Not reported Date Trans10 Transported Waste: Not reported Date TSDF Received Waste: 06/03/2010 Tranporter 1 Decal: Not reported Tranporter 2 Decal: Not reported Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported Transporter-3 EPA Facility Name: Not reported Not reported Transporter-4 EPA Facility Name: Transporter-5 EPA Facility Name: Not reported TSDF EPA Facility Name: Not reported QTY Units: Not reported Transporter SEQ ID: Not reported Transporter-1 Date: Not reported Not reported Waste SEQ ID: Not reported Waste Type Code 2: Waste Type Code 3: Not reported Waste Type Code 4: Not reported Waste Type Code 5: Not reported Waste Type Code 6: Not reported Date Accepted: Not reported Manifest Discrepancy Type: Not reported Data Entry Number: Not reported Reference Manifest Number: Not reported

Was Load Rejected (Y/N): No

Reason Load Was Rejected: Not reported

Waste Code: D039

Manifest Year: 2010 New Jersey Manifest Data

Quantity: 5
Unit: G
Hand Code: H020

Map ID MAP FINDINGS Direction

Distance Elevation Site

Database(s)

**AUTO WARD INC. (Continued)** 

1000495676

**EDR ID Number** 

**EPA ID Number** 

Manifest Code: 001388165SKS EPA ID: DCD983969064 Date Shipped: 09/03/2008 TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Transporter 3 EPA ID: Not reported Not reported Transporter 4 EPA ID: Transporter 5 EPA ID: Not reported Transporter 6 EPA ID: Not reported Transporter 7 EPA ID: Not reported Transporter 8 EPA ID: Not reported Transporter 10 EPA ID: Not reported Date Trans1 Transported Waste: 09/03/2008 Date Trans2 Transported Waste: Not reported Date Trans3 Transported Waste: Not reported Not reported Date Trans4 Transported Waste: Date Trans5 Transported Waste: Not reported Date Trans6 Transported Waste: Not reported Date Trans7 Transported Waste: Not reported Date Trans8 Transported Waste: Not reported Date Trans9 Transported Waste: Not reported Date Trans10 Transported Waste: Not reported Date TSDF Received Waste: 09/08/2008 Tranporter 1 Decal: Not reported Tranporter 2 Decal: Not reported Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported Transporter-3 EPA Facility Name: Not reported Transporter-4 EPA Facility Name: Not reported Transporter-5 EPA Facility Name: Not reported TSDF EPA Facility Name: Not reported QTY Units: Not reported Transporter SEQ ID: Not reported Transporter-1 Date: Not reported Waste SEQ ID: Not reported Waste Type Code 2: Not reported Waste Type Code 3: Not reported Waste Type Code 4: Not reported Not reported Waste Type Code 5: Waste Type Code 6: Not reported Date Accepted: Not reported Not reported Manifest Discrepancy Type: Data Entry Number: Not reported Reference Manifest Number: Not reported Was Load Rejected (Y/N): No Reason Load Was Rejected: Not reported

Waste Code: D001

Manifest Year: 2008 New Jersey Manifest Data

Quantity: 4 G Unit: H020 Hand Code:

Manifest Code: 000983507SKS Map ID MAP FINDINGS
Direction

Distance Elevation

Site Database(s) EPA ID Number

### **AUTO WARD INC. (Continued)**

1000495676

**EDR ID Number** 

EPA ID: DCD983969064 Date Shipped: 02/14/2008 TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Transporter 3 EPA ID: Not reported Transporter 4 EPA ID: Not reported Not reported Transporter 5 EPA ID: Transporter 6 EPA ID: Not reported Transporter 7 EPA ID: Not reported Transporter 8 EPA ID: Not reported Transporter 10 EPA ID: Not reported Date Trans1 Transported Waste: 02/14/2008 Date Trans2 Transported Waste: Not reported Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Not reported Date Trans6 Transported Waste: Not reported Date Trans7 Transported Waste: Not reported Date Trans8 Transported Waste: Not reported Date Trans9 Transported Waste: Not reported Date Trans10 Transported Waste: Not reported Date TSDF Received Waste: 02/18/2008 Tranporter 1 Decal: Not reported Tranporter 2 Decal: Not reported Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported Transporter-3 EPA Facility Name: Not reported Transporter-4 EPA Facility Name: Not reported Transporter-5 EPA Facility Name: Not reported TSDF EPA Facility Name: Not reported QTY Units: Not reported Transporter SEQ ID: Not reported Not reported Transporter-1 Date: Not reported Waste SEQ ID: Waste Type Code 2: Not reported Waste Type Code 3: Not reported Waste Type Code 4: Not reported Waste Type Code 5: Not reported Not reported Waste Type Code 6: Not reported Date Accepted: Manifest Discrepancy Type: Not reported Not reported Data Entry Number: Reference Manifest Number: Not reported Was Load Rejected (Y/N): No Reason Load Was Rejected: Not reported Waste Code: D001 Manifest Year: 2008 New Jersey Manifest Data Quantity: 11

Manifest Code: 000849335SKS EPA ID: DCD983969064

G

H020

Unit:

Hand Code:

Map ID MAP FINDINGS
Direction

Distance EDR ID Number
Elevation Site EDR ID Number
Database(s) EPA ID Number

**AUTO WARD INC. (Continued)** 

1000495676

Date Shipped: 10/09/2007 TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Transporter 3 EPA ID: Not reported Transporter 4 EPA ID: Not reported Transporter 5 EPA ID: Not reported Transporter 6 EPA ID: Not reported Transporter 7 EPA ID: Not reported Transporter 8 EPA ID: Not reported Transporter 10 EPA ID: Not reported Date Trans1 Transported Waste: 10/09/2007 Date Trans2 Transported Waste: Not reported Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Not reported Not reported Date Trans6 Transported Waste: Date Trans7 Transported Waste: Not reported Date Trans8 Transported Waste: Not reported Date Trans9 Transported Waste: Not reported Date Trans10 Transported Waste: Not reported Date TSDF Received Waste: 10/15/2007 Tranporter 1 Decal: Not reported Tranporter 2 Decal: Not reported Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported Transporter-3 EPA Facility Name: Not reported Transporter-4 EPA Facility Name: Not reported Not reported Transporter-5 EPA Facility Name: TSDF EPA Facility Name: Not reported QTY Units: Not reported Transporter SEQ ID: Not reported Transporter-1 Date: Not reported Waste SEQ ID: Not reported Waste Type Code 2: Not reported Waste Type Code 3: Not reported Waste Type Code 4: Not reported Waste Type Code 5: Not reported Waste Type Code 6: Not reported Not reported Date Accepted: Not reported Manifest Discrepancy Type: Data Entry Number: Not reported Not reported Reference Manifest Number: Was Load Rejected (Y/N): No Reason Load Was Rejected: Not reported Waste Code: Not reported Manifest Year: Not reported Quantity: Not reported Not reported Unit:

Not reported

Hand Code:

Direction Distance

Elevation Site Database(s) **EPA ID Number** 

F23 CABCO INC. DC UST U002108191 NNW 129 Q ST SW N/A

WASHINGTON, DC 20024 < 1/8

0.069 mi.

365 ft. Site 4 of 5 in cluster F

UST: Relative:

Facility ID: Lower 2000170 Facility Description: False

Actual: CABCO INC. Owner:

18 ft.

Tank ID:

Tank Status: **Temporarily Out of Use** 

Tank Capacity: 4000 Substance: Not Listed

Tank ID:

Tank Status: **Temporarily Out of Use** 

4000 Tank Capacity: Substance: Not Listed

Tank ID: 3

Tank Status: **Temporarily Out of Use** 

Tank Capacity: 6000 Substance: Not Listed

EDR US Hist Auto Stat 1015198835 F24

NNW 129 Q ST SW N/A

WASHINGTON, DC 20024 < 1/8

0.069 mi.

365 ft. Site 5 of 5 in cluster F

**EDR Historical Auto Stations:** Relative:

LINCOLN CAB AUTO REPAIR Name: Lower

Year: 1999

Actual: Address: 129 Q ST SW

18 ft.

Name: LINCOLN CAB AUTO REPAIR

Year: 2000 129 Q ST SW Address:

DC LUST \$103816900 G25 STEUART PETROLEUM

**ENE** 1721 S. CAPITOL STREET, SW < 1/8 WASHINGTON, DC

0.072 mi.

380 ft. Site 1 of 4 in cluster G

LUST: Relative:

Facility ID: 2-000640 Lower Facility Type: Gas Station Actual: Facility Status: Open

15 ft. Product: Gasoline, Heating Oil

Notification Date: 9/23/1987 Ward: Soil/GW Media Of Contamination:

Entry Date: 9/23/1987 N/A

**EDR ID Number** 

Direction Distance

Distance Elevation Site EDR ID Number Database(s) EPA ID Number

STEUART PETROLEUM (Continued)

S103816900

N/A

DCD980551022

Lust Number: 87012

G26 STEUART PETROLEUM COMPANY. DC UST U003763742

ENE 1721 S CAPITOL ST SW < 1/8 WASHINGTON, DC 20003

0.072 mi.

380 ft. Site 2 of 4 in cluster G

Relative: UST:

Lower Facility ID: 2000640
Facility Description: False

Actual: Owner: STEUART INVESTMENT CO. 15 ft.

Tank ID:

Tank Status: Permanently Out of Use

Tank Capacity: 1234934 Substance: Heating Oil

G27 STEUART PETRO CO SO CAPITOL TERMINAL RCRA NonGen / NLR 1000424041

ENE 1721 S CAPITOL ST NW < 1/8 WASHINGTON, DC 20024

0.072 mi.

380 ft. Site 3 of 4 in cluster G

Relative: RCRA NonGen / NLR:
Lower Date form received by agency: 11/14/1980

Lower Date form received by agency: 11/14/1980
Facility name: STEUART PETRO CO SO CAPITOL TERMINAL

Actual: Facility address: 1721 S CAPITOL ST NW

15 ft.

WASHINGTON, DC 20024

EPA ID: DCD980551022

Mailing address: 4646 40TH ST NW

WASHINGTON, DC 20016
Contact: ANDREW_S GARBUTT
Contact address: 1721 S CAPITOL ST NW

WASHINGTON, DC 20024

Contact country: US

Contact telephone: (202) 537-8900 Contact email: Not reported

EPA Region: 03

Land type: Facility is not located on Indian land. Additional information is not known.

Classification: Non-Generator

Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: STEUART INVESTMENT COMPANY

Owner/operator address: OWNERSTREET

OWNERCITY, AK 99999

Owner/operator country: Not reported
Owner/operator telephone: (215) 555-1212
Legal status: Private

Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: OPERNAME
Owner/operator address: OPERSTREET

Direction Distance Elevation

evation Site Database(s) EPA ID Number

### STEUART PETRO CO SO CAPITOL TERMINAL (Continued)

1000424041

**EDR ID Number** 

OPERCITY, AK 99999

Owner/operator country: Not reported
Owner/operator telephone: (215) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

### Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: Nο Transporter of hazardous waste: No Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: No Furnace exemption: No Used oil fuel burner: No Used oil processor: No User oil refiner: No Used oil fuel marketer to burner: Nο Used oil Specification marketer: No Used oil transfer facility: No Used oil transporter: No

# Hazardous Waste Summary:

Waste code: D000
Waste name: Not Defined

Waste code: D001

Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF

LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT

WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Facility Has Received Notices of Violations: Regulation violated: SR - 262.41

Area of violation: Generators - Records/Reporting

Date violation determined: 04/04/1994
Date achieved compliance: 04/18/1994
Violation lead agency: State

Enforcement action: WRITTEN INFORMAL

Enforcement action date: 04/04/1994
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 262.41(a)

Area of violation: Generators - Records/Reporting

Date violation determined: 03/06/1992

Direction Distance

Distance Elevation Site EDR ID Number

Database(s) EPA ID Number

# STEUART PETRO CO SO CAPITOL TERMINAL (Continued)

1000424041

Date achieved compliance: 03/27/1992 Violation lead agency: State

Enforcement action: WRITTEN INFORMAL

Enforcement action date: 03/06/1992
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:

Evaluation date: 04/04/1994

Evaluation: NON-FINANCIAL RECORD REVIEW Area of violation: Generators - Records/Reporting

Date achieved compliance: 04/18/1994 Evaluation lead agency: State

Evaluation date: 03/06/1992

Evaluation: NON-FINANCIAL RECORD REVIEW Area of violation: Generators - Records/Reporting

Date achieved compliance: 03/27/1992 Evaluation lead agency: State

Evaluation date: 02/20/1985

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation:

Date achieved compliance:

Evaluation lead agency:

Not reported

Not reported

State

28 GOOSE BAY AGGREGATE, INC.

East 2 S ST SW < 1/8 WASHING

WASHINGTON, DC 20024

0.073 mi. 383 ft.

Relative: UST:

Lower Facility ID: 2000503

Facility Description: False

Actual: Owner: HOWAT CONCRETE COMPANY, INC.

9 ft.

Tank ID: 1

Tank Status: Permanently Out of Use

Tank Capacity: 1000 Substance: Heating Oil

Tank ID: 2

Tank Status: Permanently Out of Use

Tank Capacity: 4000 Substance: Diesel

Tank ID: 3

Tank Status: Permanently Out of Use

Tank Capacity: 4000 Substance: Diesel DC UST

U002108259

N/A

Direction Distance

**EDR ID Number** Elevation Site Database(s) **EPA ID Number** 

**GOOSE BAY AGGREGATE, INC. (Continued)** 

U002108259

Tank ID:

**Permanently Out of Use** Tank Status:

4000 Tank Capacity: Substance: Diesel

H29 **OPPORTUNITY CONCRETE GARAGE.**  DC UST U002108295

N/A

ΝE 1601 S CAPITOL ST SW < 1/8 WASHINGTON, DC 20024

0.073 mi.

384 ft. Site 1 of 8 in cluster H

Relative:

UST:

Higher Facility ID: 2000638 Facility Description: False

Actual: Owner: 21 ft.

STEUART INVESTMENT, COMPANY

Tank ID:

Tank Status: **Permanently Out of Use** 

Tank Capacity: 1000 Used Oil Substance:

Tank ID: 2

Tank Status: **Permanently Out of Use** 

Tank Capacity: Substance: Used Oil

Tank ID: 3

Tank Status: **Permanently Out of Use** 

Tank Capacity: 3000 Substance: Heating Oil

Tank ID:

Tank Status: **Permanently Out of Use** 

Tank Capacity: 25000 Heating Oil Substance:

Tank ID:

Tank Status: **Permanently Out of Use** 

Tank Capacity: 2000 Substance: Heating Oil

Tank ID:

Tank Status: **Permanently Out of Use** 

Tank Capacity: 3000 Substance: Gasoline

Tank ID:

**Tank Status: Permanently Out of Use** 

Tank Capacity: Substance: Not Listed

Direction Distance

Elevation Site Database(s) EPA ID Number

H30 OPPORTUNITY CONCRETE CORP RCRA NonGen / NLR 1000495667
NE 1601 S CAPITOL ST SW FINDS DCD9839689

1601 S CAPITOL ST SW FINDS DCD983968975 WASHINGTON, DC DC LUST

< 1/8 0.073 mi.

384 ft. Site 2 of 8 in cluster H

Relative: RCRA NonGen / NLR:

Higher Date form received by agency: 02/18/2000

Facility name: OPPORTUNITY CONCRETE CORP

Actual: Facility address: 1601 S CAPITOL ST SW WASHINGTON, DC 200030000

EPA ID: DCD983968975

Contact: JOSEPH J PENTOLINO

Contact address: Not reported

Not reported
Contact country: Not reported
Contact telephone: (202) 269-3300

Contact telephone: (202) 269-3300
Contact email: Not reported
EPA Region: 03
Land type: Private
Classification: Non-Generator

Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: OPPORTUNITY CONCRETE CORP

Owner/operator address: 1601 S CAPITOL ST SW

WASHINGTON, DC 20003

Owner/operator country: Not reported
Owner/operator telephone: (202) 488-4138
Legal status: Private
Owner/Operator Type: Owner

Owner/Op start date: Not reported Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: No Transporter of hazardous waste: No Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: Nο Furnace exemption: No Used oil fuel burner: No Used oil processor: No User oil refiner: No Used oil fuel marketer to burner: No Used oil Specification marketer: No Used oil transfer facility: No Used oil transporter: No

Historical Generators:

Date form received by agency: 03/16/1992

Facility name: OPPORTUNITY CONCRETE CORP

Classification: Not a generator, verified

Hazardous Waste Summary:

**EDR ID Number** 

Direction Distance

Elevation Site Database(s) EPA ID Number

# **OPPORTUNITY CONCRETE CORP (Continued)**

1000495667

**EDR ID Number** 

Waste code: D001

Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF

LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT

WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D018
Waste name: BENZENE

Waste code: D039

Waste name: TETRACHLOROETHYLENE

Facility Has Received Notices of Violations: Regulation violated: SR - 262.41

Area of violation: Generators - Records/Reporting

Date violation determined: 04/04/1994
Date achieved compliance: 04/18/1994
Violation lead agency: State

Enforcement action: WRITTEN INFORMAL

Enforcement action date: 04/04/1994
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:

Evaluation date: 07/21/2000

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation:

Date achieved compliance:

Evaluation lead agency:

Not reported

State

Evaluation date: 04/04/1994

Evaluation: NON-FINANCIAL RECORD REVIEW Area of violation: Generators - Records/Reporting

Date achieved compliance: 04/18/1994 Evaluation lead agency: State

FINDS:

Registry ID: 110002502051

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits

Direction Distance Elevation

Site Database(s) EPA ID Number

### **OPPORTUNITY CONCRETE CORP (Continued)**

1000495667

**EDR ID Number** 

issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

PCS (Permit Compliance System) is a computerized management information system that contains data on National Pollutant Discharge Elimination System (NPDES) permit holding facilities. PCS tracks the permit, compliance, and enforcement status of NPDES facilities.

ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

LUST:

Facility ID: 0-000000

Facility Type: Industrial Former Fuel Termina

Facility Status: Open

Product: Heating Oil, Gasoline, Diesel

Notification Date: 3/21/2013 Ward: 6 Media Of Contamination: Soil/GW

Entry Date: 4/4/2013 Lust Number: 2013006

Facility ID: 2-000638
Facility Type: Other
Facility Status: Closed
Product: Gasoline
Notification Date: 11/30/1993

Ward: 6
Media Of Contamination: SOIL
Entry Date: 11/30/1993
Lust Number: 94012

Direction Distance

**EDR ID Number** Elevation Site Database(s) **EPA ID Number** 

H31 **SOLON AUTOMATED SERVICES** DC UST U002109477

N/A

N/A

1000905832

DC0000444547

NE 1625 S CAPITOL ST SW WASHINGTON, DC 20003 < 1/8

0.073 mi.

384 ft. Site 3 of 8 in cluster H

UST: Relative:

Facility ID: 2004778 Lower

Facility Description: False

Actual: Owner: POTOMAC DEVELOPMENT

19 ft.

Tank ID:

Tank Status: **Permanently Out of Use** 

Tank Capacity: 1000

Substance: Hazardous Substance

H32 **625 SOUTH CAPITOL STREET LLC** DC LUST S113402155

**1625 SOUTH CAPITOL STREET SOUTHWEST** NE

< 1/8 WASHINGTON, DC

0.073 mi.

384 ft. Site 4 of 8 in cluster H

LUST: Relative:

Facility ID: -000000 Lower

Facility Type: Industrial former fuel termina

Actual: Facility Status: Open

19 ft. Product:

Heating Oil, Gasoline, Diesel

Notification Date: 3/28/2013

Ward: Media Of Contamination: Soil/GW 4/4/2013 Entry Date: Lust Number: 2013005

G33 **PAK-AMERICAN CORPORATION** RCRA-CESQG **1625 SOUTH CAPITOL STREET SW ENE** NJ MANIFEST

WASHINGTON, DC 20024 < 1/8

0.073 mi.

388 ft. Site 4 of 4 in cluster G

RCRA-CESQG: Relative:

Date form received by agency: 01/31/2012 Lower

PAK-AMERICAN CORPORATION Facility name: Actual: Facility address: 1625 SOUTH CAPITOL STREET SW

12 ft.

WASHINGTON, DC 20024

EPA ID: DC0000444547 Mailing address:

L STREET SE WASHINGTON, DC 20024

Contact: IMRAN BUTT Contact address: L STREET SE

WASHINGTON, DC 20024

Contact country:

202-488-4844 Contact telephone: Contact email: Not reported EPA Region: 03 Private Land type:

Classification: Conditionally Exempt Small Quantity Generator

Description: Handler: generates 100 kg or less of hazardous waste per calendar

month, and accumulates 1000 kg or less of hazardous waste at any time;

Direction Distance Elevation

Site Database(s) EPA ID Number

# PAK-AMERICAN CORPORATION (Continued)

1000905832

**EDR ID Number** 

or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name: PAK-AMERICAN CORPORATION Owner/operator address: SOUTH CAPITOL STREET SW

WASHINGTON, DC 20024

Owner/operator country: US

Owner/operator telephone: 202-488-4844
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 01/01/2001
Owner/Op end date: Not reported

Owner/operator name: PAK-AMERICAN CORPORATION
Owner/operator address: SOUTH CAPITOL STREET SW
WASHINGTON, DC 20024

Owner/operator country: US

Owner/operator telephone: (202) 488-4844

Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 01/01/2001
Owner/Op end date: Not reported

### Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: No Transporter of hazardous waste: No Treater, storer or disposer of HW: Nο Underground injection activity: No On-site burner exemption: No Furnace exemption: No Used oil fuel burner: No Used oil processor: No User oil refiner: No Used oil fuel marketer to burner: No Used oil Specification marketer: No Used oil transfer facility: No Used oil transporter: No

#### **Historical Generators:**

Date form received by agency: 03/07/2011

Facility name: PAK-AMERICAN CORPORATION

Classification: Conditionally Exempt Small Quantity Generator

Direction Distance Elevation

evation Site Database(s) EPA ID Number

# PAK-AMERICAN CORPORATION (Continued)

1000905832

**EDR ID Number** 

Date form received by agency: 03/20/2000

Facility name: PAK-AMERICAN CORPORATION

Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 06/20/1994

Facility name: PAK-AMERICAN CORPORATION

Classification: Conditionally Exempt Small Quantity Generator

Hazardous Waste Summary:

Waste code: D001

Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF

LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT

WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D006
Waste name: CADMIUM

Waste code: D008 Waste name: LEAD

Waste code: D018
Waste name: BENZENE

Waste code: D027

Waste name: 1,4-DICHLOROBENZENE

Waste code: D039

Waste name: TETRACHLOROETHYLENE

Waste code: D040

Waste name: TRICHLOROETHYLENE

Violation Status: No violations found

Evaluation Action Summary:

Evaluation date: 01/22/2013

Evaluation: NON-FINANCIAL RECORD REVIEW

Area of violation:

Date achieved compliance:

Evaluation lead agency:

Not reported

Not reported

State

Evaluation date: 01/31/2012

Evaluation: NON-FINANCIAL RECORD REVIEW

Area of violation:

Date achieved compliance:

Evaluation lead agency:

Not reported

Not reported

State

Evaluation date: 03/07/2011

Evaluation: NON-FINANCIAL RECORD REVIEW

Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Map ID MAP FINDINGS
Direction

Distance

Elevation Site Database(s) EPA ID Number

### **PAK-AMERICAN CORPORATION (Continued)**

1000905832

**EDR ID Number** 

Evaluation date: 04/12/2001

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation:

Date achieved compliance:

Evaluation lead agency:

Not reported

State

Evaluation date: 10/27/1998

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation:

Date achieved compliance:

Evaluation lead agency:

Not reported

State

### NJ MANIFEST:

Manifest Code: NJA5213680 EPA ID: DC0000444547 Date Shipped: 04/21/2005 TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Transporter 3 EPA ID: Not reported Transporter 4 EPA ID: Not reported Transporter 5 EPA ID: Not reported Transporter 6 EPA ID: Not reported Transporter 7 EPA ID: Not reported Transporter 8 EPA ID: Not reported Not reported Transporter 10 EPA ID: Date Trans1 Transported Waste: 04/21/2005 Not reported Date Trans2 Transported Waste: Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Not reported Date Trans6 Transported Waste: Not reported Date Trans7 Transported Waste: Not reported Date Trans8 Transported Waste: Not reported Date Trans9 Transported Waste: Not reported Date Trans10 Transported Waste: Not reported Date TSDF Received Waste: 04/28/2005 Tranporter 1 Decal: Not reported Tranporter 2 Decal: Not reported Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported Transporter-3 EPA Facility Name: Not reported Transporter-4 EPA Facility Name: Not reported Not reported Transporter-5 EPA Facility Name: Not reported TSDF EPA Facility Name: QTY Units: Not reported Transporter SEQ ID: Not reported Transporter-1 Date: Not reported Waste SEQ ID: Not reported Waste Type Code 2: Not reported Not reported Waste Type Code 3: Waste Type Code 4: Not reported Not reported Waste Type Code 5: Not reported Waste Type Code 6: Date Accepted: Not reported Manifest Discrepancy Type: Not reported Data Entry Number: 06160525

Direction Distance Elevation

n Site Database(s) EPA ID Number

### **PAK-AMERICAN CORPORATION (Continued)**

1000905832

**EDR ID Number** 

Reference Manifest Number: Not reported

Was Load Rejected (Y/N): No

Reason Load Was Rejected:
Waste Code:
Manifest Year:
Quantity:
Unit:
Not reported

Manifest Code: NJA5223389 EPA ID: DC0000444547 Date Shipped: 07/13/2005 TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Transporter 3 EPA ID: Not reported Transporter 4 EPA ID: Not reported Transporter 5 EPA ID: Not reported Transporter 6 EPA ID: Not reported Transporter 7 EPA ID: Not reported Transporter 8 EPA ID: Not reported Transporter 10 EPA ID: Not reported Date Trans1 Transported Waste: 07/13/2005 Date Trans2 Transported Waste: Not reported Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Not reported Date Trans6 Transported Waste: Not reported Date Trans7 Transported Waste: Not reported Date Trans8 Transported Waste: Not reported Date Trans9 Transported Waste: Not reported Date Trans10 Transported Waste: Not reported 07/20/2005 Date TSDF Received Waste: Not reported Tranporter 1 Decal: Tranporter 2 Decal: Not reported Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported Transporter-3 EPA Facility Name: Not reported Not reported Transporter-4 EPA Facility Name: Transporter-5 EPA Facility Name: Not reported Not reported TSDF EPA Facility Name: Not reported QTY Units: Transporter SEQ ID: Not reported Transporter-1 Date: Not reported Waste SEQ ID: Not reported Waste Type Code 2: Not reported Waste Type Code 3: Not reported Waste Type Code 4: Not reported Waste Type Code 5: Not reported Not reported Waste Type Code 6: Date Accepted: Not reported Manifest Discrepancy Type: Not reported 08240521 Data Entry Number: Reference Manifest Number: Not reported

MAP FINDINGS Map ID

Direction Distance

**EDR ID Number** Elevation Site **EPA ID Number** Database(s)

**PAK-AMERICAN CORPORATION (Continued)** 

1000905832

Was Load Rejected (Y/N): No

Reason Load Was Rejected: Not reported Waste Code: Not reported Manifest Year: Not reported Quantity: Not reported Not reported Unit: Hand Code: Not reported

PEPCO BUZZARD POINT GENERATING STATION 134 **1ST & V STREETS SW** 

**RCRA-CESQG** 1004681879 DCR000500140

South < 1/8

WASHINGTON, DC 20024

0.077 mi.

409 ft. Site 1 of 4 in cluster I

Relative:

RCRA-CESQG:

Lower

Date form received by agency: 02/26/2009

PEPCO BUZZARD POINT GENERATING STATION Facility name:

Actual: 15 ft.

Facility address: 1ST & V STREETS SW

WASHINGTON, DC 20024

EPA ID: DCR000500140 SHIRLEY HARMON Contact:

NORTH 17TH STREET SUITE 1600 Contact address:

ARLINGTON, VA 22209

Contact country:

Contact telephone: (703) 253-1799

SHARMON@PEPCOENGERY.COM Contact email:

03 EPA Region: Land type: Private

Classification: Conditionally Exempt Small Quantity Generator

Description: Handler: generates 100 kg or less of hazardous waste per calendar

month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from

the cleanup of a spill, into or on any land or water, of acutely

hazardous waste

Owner/Operator Summary:

POTOMAC POWER RESOURSE, LLC Owner/operator name:

Owner/operator address: Not reported Not reported Owner/operator country: Not reported

Owner/operator telephone: Not reported Legal status: Private Owner/Operator Type: Owner Owner/Op start date: 12/15/2000 Owner/Op end date: Not reported

Direction Distance

Elevation Site Database(s) EPA ID Number

# PEPCO BUZZARD POINT GENERATING STATION (Continued)

1004681879

**EDR ID Number** 

Owner/operator name: POTOMAC POWER RESOURSE, LLC

Owner/operator address:

Owner/operator country:

Owner/operator telephone:

Legal status:

Owner/Operator Type:

Not reported

Not reported

Private

Operator

Owner/Op start date: 12/15/2000
Owner/Op end date: Not reported

#### Handler Activities Summary:

U.S. importer of hazardous waste: Nο Mixed waste (haz. and radioactive): No Recycler of hazardous waste: No Transporter of hazardous waste: No Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: No Furnace exemption: No Used oil fuel burner: No Used oil processor: Nο User oil refiner: No Used oil fuel marketer to burner: No Used oil Specification marketer: No Used oil transfer facility: No Used oil transporter: Nο

### Historical Generators:

Date form received by agency: 02/26/2002

Facility name: PEPCO BUZZARD POINT GENERATING STATION

Site name: PPR BUZZARD POINT

Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 02/15/2001

Facility name: PEPCO BUZZARD POINT GENERATING STATION

Site name: PPR BUZZARD POINT GEN STATION

Classification: Large Quantity Generator

#### Hazardous Waste Summary:

Waste code: D001

Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF

LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT

WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D002

Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS

CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE

DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Direction Distance

**EDR ID Number** Elevation Site **EPA ID Number** Database(s)

# PEPCO BUZZARD POINT GENERATING STATION (Continued)

1004681879

D008 Waste code: Waste name: **LEAD** D009 Waste code: Waste name: **MERCURY** 

Violation Status: No violations found

**Evaluation Action Summary:** 

Evaluation date: 03/01/2012

Evaluation: NON-FINANCIAL RECORD REVIEW

Area of violation: Not reported Date achieved compliance: Not reported Evaluation lead agency: State

Evaluation date: 06/27/2005

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: Not reported Date achieved compliance: Not reported Evaluation lead agency: State

135 PEPCO BUZZARD PT GENERATING ST RCRA-CESQG 1000175304 DCD000819508

1ST V STS SW RAATS

DC UST < 1/8 WASHINGTON, DC 20068

0.077 mi.

South

Site 2 of 4 in cluster I 409 ft.

RCRA-CESQG: Relative:

Date form received by agency: 02/26/2010 Lower PEPCO BUZZARD POINT FACILITY Facility name:

Actual: Facility address: 1ST & V STREETS SW 15 ft.

WASHINGTON, DC 200240000 EPA ID: DCD000819508

Mailing address: NINTH STREET NW

WASHINGTON, DC 200680000

GHIRMAY BEHRE Contact: Contact address: NINTH STREET NW

WASHINGTON, DC 200680000

Contact country: US

Contact telephone: (202) 331-6197

Contact email: GBERHE@PEPCO.COM

EPA Region: 03 Land type: Private

Classification: Conditionally Exempt Small Quantity Generator

Description: Handler: generates 100 kg or less of hazardous waste per calendar

month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste: or 100 kg or less of

any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely

hazardous waste

Direction Distance Elevation

tion Site Database(s) EPA ID Number

# PEPCO BUZZARD PT GENERATING ST (Continued)

1000175304

**EDR ID Number** 

Owner/Operator Summary:

Owner/operator name: POTOMAC ELECTRIC POWER COMPANY

Owner/operator address: 701 NINTH STREET NW

WASHINGTON, DC 20068

Owner/operator country: US

Owner/operator telephone: Not reported Legal status: Private Owner/Operator Type: Owner Owner/Op start date: 01/01/1900 Owner/Op end date: Not reported

Owner/operator name: PEPCO
Owner/operator address: Not reported
Not reported

Owner/operator country: US

Owner/operator telephone: Not reported Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 01/01/1900
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: No Transporter of hazardous waste: No Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: No Furnace exemption: No Used oil fuel burner: No Used oil processor: No User oil refiner: No Used oil fuel marketer to burner: No Used oil Specification marketer: No Used oil transfer facility: No Used oil transporter: No

**Historical Generators:** 

Date form received by agency: 05/09/2008

Facility name: PEPCO BUZZARD POINT FACILITY

Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 03/01/2004

Facility name: PEPCO BUZZARD POINT FACILITY

Site name: PEPCO BUZZARD POINT GENERATING STATION

Classification: Large Quantity Generator

Date form received by agency: 02/28/2002

Facility name: PEPCO BUZZARD POINT FACILITY

Site name: PEPCO BUZZARD POINT GENERATING STATION Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 02/15/2001

Facility name: PEPCO BUZZARD POINT FACILITY

Classification: Large Quantity Generator

Direction Distance

Elevation Site Database(s) EPA ID Number

# PEPCO BUZZARD PT GENERATING ST (Continued)

1000175304

**EDR ID Number** 

Date form received by agency: 02/14/2001

Facility name: PEPCO BUZZARD POINT FACILITY

Classification: Large Quantity Generator

Date form received by agency: 02/22/2000

Facility name: PEPCO BUZZARD POINT FACILITY

Site name: PEPCO BUZZARD POINT GENERATING STATION

Classification: Large Quantity Generator

Date form received by agency: 02/20/1998

Facility name: PEPCO BUZZARD POINT FACILITY

Site name: PEPCO BUZZARD POINT GENERATING STATION

Classification: Large Quantity Generator

Date form received by agency: 11/19/1980

Facility name: PEPCO BUZZARD POINT FACILITY

Classification: Not a generator, verified

Date form received by agency: 08/18/1980

Facility name: PEPCO BUZZARD POINT FACILITY

Classification: Small Quantity Generator

Hazardous Waste Summary:

Waste code: D006
Waste name: CADMIUM

Waste code: D008 Waste name: LEAD

Waste code: D009
Waste name: MERCURY

Violation Status: No violations found

Evaluation Action Summary:

Evaluation date: 03/01/2012

Evaluation: NON-FINANCIAL RECORD REVIEW

Area of violation:
Date achieved compliance:
Evaluation lead agency:
Not reported
State

Evaluation date: 03/04/2011

Evaluation: NON-FINANCIAL RECORD REVIEW

Area of violation:

Date achieved compliance:

Evaluation lead agency:

Not reported

Not reported

State

Evaluation date: 06/27/2005

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation:

Date achieved compliance:

Evaluation lead agency:

Not reported

Not reported

State

Evaluation date: 06/27/1991

Evaluation: FOCUSED COMPLIANCE INSPECTION

Area of violation: Not reported

Direction Distance Elevation

tance EDR ID Number vation Site Database(s) EPA ID Number

PEPCO BUZZARD PT GENERATING ST (Continued)

Date achieved compliance: Not reported

Evaluation lead agency: EPA

Evaluation date: 02/08/1984

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

UST:

Facility ID: 2000609 Facility Description: False

Owner: PEPCO ENERGY SERVICES INC

Tank ID:

Tank Status: Permanently Out of Use

Tank Capacity: 2000 Substance: Used Oil

Tank ID: 2

Tank Status: Permanently Out of Use

Tank Capacity: 2000 Substance: Used Oil

Tank ID: 3

Tank Status: Permanently Out of Use

Tank Capacity: 2000 Substance: Used Oil

Tank ID: 4

Tank Status: Permanently Out of Use

Tank Capacity: 2000 Substance: Used Oil

Tank ID: 5

Tank Status: Permanently Out of Use

Tank Capacity: 10000 Substance: Heating Oil

Tank ID: 6

Tank Status: Permanently Out of Use

Tank Capacity: 10000 Substance: Heating Oil

Tank ID: 7

Tank Status: Permanently Out of Use

Tank Capacity: 2000 Substance: Gasoline

Tank ID: 8

Tank Status: Permanently Out of Use

1000175304

MAP FINDINGS Map ID

Direction Distance

**EDR ID Number** Elevation Site Database(s) **EPA ID Number** 

PEPCO BUZZARD PT GENERATING ST (Continued)

Tank Capacity: 500

Hazardous Substance Substance:

Tank ID:

Tank Status: **Permanently Out of Use** 

4000 Tank Capacity: Substance: Diesel

Tank ID: 10

Tank Status: **Permanently Out of Use** 

4000 Tank Capacity: Substance: Diesel

136 **BUZZARD POINT FACILITY** 

South 180 S ST SW

WASHINGTON, DC 20024 < 1/8

0.077 mi.

409 ft. Site 3 of 4 in cluster I

UST: Relative:

Facility ID: 2002337 Lower

Facility Description: False

Actual: Owner: POTOMAC ELECTRIC POWER COMPANY.

15 ft.

Tank ID:

Tank Status: **Permanently Out of Use** 

6000 Tank Capacity: Substance: Gasoline

Tank ID:

Tank Status: **Permanently Out of Use** 

Tank Capacity: 6000 Substance: Gasoline

Tank ID:

Tank Status: **Permanently Out of Use** 

Tank Capacity: 20000 Substance: Gasoline

DC LUST \$107520980 137 **PEPCO - BUZZARD POINT** N/A

South 33 V STREET, SW WASHINGTON, DC < 1/8

0.077 mi.

409 ft. Site 4 of 4 in cluster I

LUST: Relative:

Facility ID: 2-000609 Lower Facility Type: Other

Actual: Facility Status: Closed 15 ft.

Product: Gasoline, Diesel, Heating Oil

Notification Date: 8/29/1991

Ward: 6 1000175304

DC UST U003054341

N/A

MAP FINDINGS Map ID

Direction Distance

Elevation Site Database(s) **EPA ID Number** 

PEPCO - BUZZARD POINT (Continued)

Media Of Contamination:

Entry Date: Lust Number: Soil 8/29/1991

2-000609 Facility ID: Facility Type: Other Facility Status: Closed Product: Waste Oil Notification Date: 7/31/1992 Ward:

91071

Soil/GW Media Of Contamination: Entry Date: 7/31/1992 Lust Number: 92083

Facility ID: 2-000609 Facility Type: Other

Facility Status: NFA-DCRBCA Gasoline, Diesel Product: Notification Date: 1/29/1993

Ward: 6

Media Of Contamination: Soil/GW Entry Date: 1/29/1993 Lust Number: 93051

2-000609 Facility ID: Other Facility Type: Facility Status: Closed Product: Waste Oil Notification Date: 10/13/1993

Ward: 6 Media Of Contamination: SOIL Entry Date: 10/13/1993 Lust Number: 94005

H38 FEDDERLINE. DC UST U003763743 N/A

NE 1724 S CAPITOL ST SW WASHINGTON, DC 20003 < 1/8

0.094 mi.

496 ft. Site 5 of 8 in cluster H

Relative:

UST:

Higher Facility ID: 2000663 Facility Description: False

Actual: Owner: STEUART INVESTMENT CO.

23 ft.

Tank ID:

Tank Status: **Permanently Out of Use** 

Tank Capacity: 4000 Substance: Diesel

Tank ID:

**Tank Status: Permanently Out of Use** 

Tank Capacity: 4000 Substance: Gasoline

Tank ID: 3 **EDR ID Number** 

S107520980

Direction Distance Elevation

ion Site Database(s) EPA ID Number

FEDDERLINE. (Continued)

Tank Status: Permanently Out of Use

Tank Capacity: 4000 Substance: Gasoline

Tank ID:

Tank Status: Permanently Out of Use

Tank Capacity: 4000 Substance: Gasoline

Tank ID: 5

Tank Status: Permanently Out of Use

Tank Capacity: 4000 Substance: Used Oil

Tank ID:

Tank Status: Permanently Out of Use

Tank Capacity: 4000 Substance: Used Oil

Tank ID: 7

Tank Status: Permanently Out of Use

Tank Capacity: 4000 Substance: Used Oil

Tank ID: 8

Tank Status: Permanently Out of Use

Tank Capacity: 4000 Substance: Used Oil

Tank ID: 9

Tank Status: Permanently Out of Use

Tank Capacity: 4000 Substance: Used Oil

Tank ID: 10

Tank Status: Permanently Out of Use

Tank Capacity: 4000 Substance: Used Oil

Tank ID: 11

Tank Status: Permanently Out of Use

Tank Capacity: 4000 Substance: Used Oil

Tank ID: 12

Tank Status: Permanently Out of Use

Tank Capacity: 4000 Substance: Used Oil **EDR ID Number** 

U003763743

MAP FINDINGS Map ID

Direction Distance

**EDR ID Number** Elevation Site Database(s) **EPA ID Number** 

FEDDERLINE. (Continued) U003763743

Tank ID: 13

Tank Status: **Permanently Out of Use** 

Tank Capacity: 4000 Substance: Used Oil

Tank ID:

Tank Status: **Permanently Out of Use** 

Tank Capacity: 4000 Substance: Used Oil

DC BROWNFIELDS \$108276627 1724 SOUTH CAPITOL ST SE N/A

H39

NE < 1/8 WASHINGTON, DC

0.094 mi.

496 ft. Site 6 of 8 in cluster H

BROWNFIELD: Relative:

PB ID: PBF2004-0190 Higher

Ownership: OPM Actual: Size (sf): 42,208 23 ft. Phase I: unknown Phase II: unknown

Lot: 0004 Square: 708

Latitude/Longitude: 38.876746 / -77.008537

Notes: Not reported

1009001835 H40 **GULF OIL CORP (BULK PLANT) EDR US Hist Auto Stat** N/A

1724 S CAPITOL ST SE NE WASHINGTON, DC < 1/8

0.094 mi.

496 ft. Site 7 of 8 in cluster H

EDR Historical Auto Stations: Relative:

**GULF OIL CORP OFC** Higher Name:

Year:

Actual: GASOLINE AND OIL SERVICE STATIONS Type:

23 ft.

Name: GULF OIL CORP (BULK PLANT)

Year: 1948

Type: GASOLINE AND OIL SERVICE STATIONS

Name: GULF OIL CORP BULK PLANT

Year: 1954

Type: **GASOLINE STATIONS** 

Direction Distance

Elevation Site Database(s) EPA ID Number

H41 STEUART INVESTMENT CO. DC LUST S102834832

N/A

**EDR ID Number** 

NE 1724 S. CAPITOL ST, SE < 1/8 WASHINGTON, DC

0.094 mi.

496 ft. Site 8 of 8 in cluster H

Relative: LUST:

Higher Facility ID: 2-000663
Facility Type: Other

Actual: Facility Status: Closed
23 ft. Product: M
Notification Date: 6/2/1997

Ward: 6
Media Of Contamination: Soil/GW
Entry Date: 6/2/1997
Lust Number: 97070

_____

J42 EDR US Hist Auto Stat 1015239120 NE 1505 S CAPITOL ST SW EDR US Hist Auto Stat N/A

NE 1505 S CAPITOL ST SW < 1/8 WASHINGTON, DC 20003

0.094 mi.

497 ft. Site 1 of 11 in cluster J

Relative: EDR Historical Auto Stations:
Higher Name: AUTOMOTIVE CARE CTR INC

Year: 2004

Actual: Address: 1505 S CAPITOL ST SW

23 ft.

Name: AUTOMOTIVE CARE CENTER INC

Year: 2005

Address: 1505 S CAPITOL ST SW

Name: AUTOMOTIVE CARE CENTER INC

Year: 2006

Address: 1505 S CAPITOL ST SW

Name: AUTOMOTIVE CARE CENTER INC

Year: 2007

Address: 1505 S CAPITOL ST SW

Name: AUTOMOTIVE CARE CENTER INC

Year: 2008

Address: 1505 S CAPITOL ST SW

Name: AUTOMOTIVE CARE CENTER INC

Year: 2009

Address: 1505 S CAPITOL ST SW

Name: AUTOMOTIVE CARE CTR INC

Year: 2010

Address: 1505 S CAPITOL ST SW

Direction Distance

**EDR ID Number** Elevation Site Database(s) **EPA ID Number** 

43 **UNKNOWN** DC HIST UST S110337803 NNE

N/A

**1513 HALF ST SW** WASHINGTON, DC < 1/8

0.104 mi. 547 ft.

HIST UST: Relative:

2003154*001 Higher Facility Id:

Confirm Tank/Owner Address Found:yes Actual: Confirn Tank/No Owner Found:

Not reported 30 ft. Owner Found/No Tank: Not reported No Owner/No Tank: Not reported

Address Not Found: yes

Ltr Edc: Not reported Tank Status: UNK Tank Capacity: Not reported

Product: unk

K44 **EDR US Hist Cleaners** 1014998268

N/A

N/A

**DC BROWNFIELDS** 

North 1546 1ST ST SW < 1/8 WASHINGTON, DC 20024

0.104 mi.

551 ft. Site 1 of 2 in cluster K

**EDR Historical Cleaners:** Relative:

SHULMANS LAUNDRAMAT Higher Name:

Year: 2004

Actual: Address: 1546 1ST ST SW

23 ft.

J45 DC LUST S106983188

NE **1620 SOUTH CAPITOL ST SE** 

< 1/8 WASHINGTON, DC

0.108 mi.

568 ft. Site 2 of 11 in cluster J

LUST: Relative:

Facility ID: 2-000066 Higher

Facility Type: Commercial

Actual: Facility Status: Open

24 ft. Product: Gasoline, Diesel, Heating Oil, Varsol

Notification Date: 6/1/2005

Ward: 6

Media Of Contamination: Soil/GW 6/1/2005 Entry Date: Lust Number: 2005039

**BROWNFIELD:** 

PB ID: PBF2003-0035

OPM Ownership: Size (sf): 83,333 Phase I: unknown Phase II: unknown Lot: 808 Square: 708

Latitude/Longitude: 38.90135059 / -77.03835899 Notes: **ODMPED: Redevelopment Initiative** 

PBF2004-0092 PB ID:

Direction Distance

Elevation Site Database(s) **EPA ID Number** 

(Continued) S106983188

OPM Ownership: Size (sf): 57,630 Phase I: unknown Phase II: unknown Lot: 804 Square: 708

38.91190842 / -77.00904504 Latitude/Longitude: Notes: ODMPED: Redevelopment Initiative

PB ID: PBF2004-0103 Ownership: Private Size (sf): 83,333+15,881 Phase I: unknown Phase II: unknown Lot: 0808-0807-0804

Square: 0708

Latitude/Longitude: 38.91192729 / -77.00904472

Notes: WS: Other

RCRA NonGen / NLR

J46 **AMERADA HESS CORP** ΝE **1620 SOUTH CAPITOL STREET SE** 

< 1/8 WASHINGTON, DC 20003

0.108 mi.

568 ft. Site 3 of 11 in cluster J

RCRA NonGen / NLR: Relative: Date form received by agency: 09/19/2011 Higher

Facility name: AMERADA HESS CORP

Actual: Facility address: 1620 SOUTH CAPITOL STREET SE 24 ft.

WASHINGTON, DC 20003

EPA ID: DCD045493814 Mailing address: SOUTH CAPITOL STREET SE

WASHINGTON, DC 20003

Contact: TOM WHITTAKER

Contact address: SOUTH CAPITOL STREET SE

WASHINGTON, DC 20003

Contact country: US

Contact telephone: (201) 750-6000 Contact email: Not reported

EPA Region:

Classification: Non-Generator

Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: AMERADA HESS CORPORATION

Owner/operator address: **OWNERSTREET** 

OWNERCITY, AK 99999 Not reported Owner/operator country:

Owner/operator telephone: (215) 555-1212 Legal status: Private Owner/Operator Type: Owner Owner/Op start date: Not reported Owner/Op end date: Not reported

Owner/operator name: **OPERNAME** Owner/operator address: **OPERSTREET** 

OPERCITY, AK 99999

**EDR ID Number** 

1000352847

DCD045493814

**FINDS** 

Distance Elevation Site

Site Database(s) EPA ID Number

# AMERADA HESS CORP (Continued)

1000352847

**EDR ID Number** 

Owner/operator country:

Owner/operator telephone:

Legal status:

Owner/Operator Type:

Owner/Op start date:

Owner/Op end date:

Not reported

Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: No Transporter of hazardous waste: Nο Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: No Furnace exemption: No Used oil fuel burner: No Used oil processor: No User oil refiner: No Used oil fuel marketer to burner: No Used oil Specification marketer: Nο Used oil transfer facility: No Used oil transporter: No

Historical Generators:

Date form received by agency: 08/18/1980

Facility name: AMERADA HESS CORP Classification: Not a generator, verified

Hazardous Waste Summary:

Waste code: D001

Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF

LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT

WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Violation Status: No violations found

FINDS:

Registry ID: 110002499760

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that

Direction Distance

Elevation Site Database(s) EPA ID Number

# AMERADA HESS CORP (Continued)

1000352847

**EDR ID Number** 

discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

PCS (Permit Compliance System) is a computerized management information system that contains data on National Pollutant Discharge Elimination System (NPDES) permit holding facilities. PCS tracks the permit, compliance, and enforcement status of NPDES facilities.

 J47
 AMERADA HESS CORP.
 DC UST
 U002108146

 NE
 1620 S CAPITOL ST SE
 N/A

NE 1620 S CAPITOL ST SE < 1/8 WASHINGTON, DC 20003

0.108 mi.

568 ft. Site 4 of 11 in cluster J

Relative: UST:

Higher

Facility ID: 2000066
Facility Description: False

Actual: Owner:

DOUGLAS DEVELOPMENT

24 ft.

Tank ID: 1

Tank Status: Permanently Out of Use

Tank Capacity: 420000 Substance: Heating Oil

Tank ID: 2

Tank Status: Permanently Out of Use

Tank Capacity: 483000 Substance: Heating Oil

Tank ID: 3

Tank Status: Permanently Out of Use

Tank Capacity: 378000 Substance: Heating Oil

Tank ID: 4

Tank Status: Permanently Out of Use

Tank Capacity: 25200 Substance: Heating Oil

Tank ID: 5

Tank Status: Permanently Out of Use

Tank Capacity: 25200 Substance: Heating Oil

Tank ID: 6

Tank Status: Permanently Out of Use

Tank Capacity: 25200 Substance: Heating Oil

Direction Distance

**EDR ID Number** Elevation Site Database(s) **EPA ID Number** 

**AMERADA HESS CORP. (Continued)** 

Tank ID:

**Permanently Out of Use** Tank Status:

Tank Capacity: 25200 Substance: Heating Oil

Tank ID:

Tank Status: **Permanently Out of Use** 

Tank Capacity: 25200 Substance: Heating Oil

Tank ID:

Tank Status: **Permanently Out of Use** 

25200 Tank Capacity: Substance: Unknown

Tank ID:

**Permanently Out of Use** Tank Status:

Tank Capacity: 25200 Substance: Heating Oil

Tank ID:

Tank Status: **Permanently Out of Use** 

Tank Capacity: 10000 Substance: Heating Oil

Tank ID: 12

Tank Status: **Permanently Out of Use** 

Tank Capacity: 100000 Substance: Heating Oil

Tank ID: 13

**Permanently Out of Use** Tank Status:

100000 Tank Capacity: Heating Oil Substance:

Tank ID:

**Permanently Out of Use** Tank Status:

100000 Tank Capacity: Substance: Heating Oil

Tank ID: 15

**Tank Status: Permanently Out of Use** 

Tank Capacity: 315000 Substance: Heating Oil U002108146

Direction Distance

**EDR ID Number** Elevation Site Database(s) **EPA ID Number** 

J48 **ASSOCIATED LAUNDRIES EDR US Hist Cleaners** 1009133302 NE N/A

1507 S CAPITOL ST SE

< 1/8 WASHINGTON, DC

0.112 mi.

594 ft. Site 5 of 11 in cluster J

**EDR Historical Cleaners:** Relative:

Higher Name: ASSOCIATED LAUNDRIES

Year: 1948 Actual:

LAUNDRIES Type: 24 ft.

K49 **LAUNDROMAT** DC LUST North 1530 1ST ST SW DC UST

< 1/8 WASHINGTON, DC 20024

0.117 mi.

620 ft. Site 2 of 2 in cluster K

LUST: Relative:

Facility ID: 9-000590 Higher Facility Type: Commercial

Actual: Facility Status: Closed 21 ft. Product: Heating Oil Notification Date: 11/1/2002

> Ward: Media Of Contamination: Soil 11/8/2002 Entry Date: Lust Number: 2003047

UST:

Facility ID: 9000590 Facility Description: False

Owner: RUBY W LEE LIVING TRUST

Tank ID:

Tank Status: **Permanently Out of Use** 

Tank Capacity: 2000 Substance: Heating Oil

J50

**EDR US Hist Auto Stat** 1009002308 TRANSMISSION S INC NNE 1509 SOUTH CAPITOL TER SW N/A

< 1/8 WASHINGTON, DC

0.123 mi.

650 ft. Site 6 of 11 in cluster J

EDR Historical Auto Stations: Relative:

Higher Name: TRANSMISSION S INC

Year: 1964

Actual: AUTOMOBILE REPAIRING Type:

25 ft.

U003885949

N/A

Direction Distance

Distance Elevation Site EDR ID Number

EDR ID Number

EPA ID Number

J51 SINGH TRANSMISSION C/O AUTOMOTIVE CARE CENTRE RCRA-CESQG 1000858623
NNE 1505 SOUTH CAPITOL STREET SW NJ MANIFEST DCD983971391

1/8-1/4 WASHINGTON, DC 20024

0.126 mi.

667 ft. Site 7 of 11 in cluster J

Relative:

RCRA-CESQG:

Higher Date form received by agency: 08/03/2011

Facility name: SINGH TRANSMISSION C/O AUTOMOTIVE CARE CENTRE
Facility address: 1505 SOUTH CAPITOL STREET SW

Actual: Facility address: 25 ft.

WASHINGTON, DC 20024

EPA ID: DCD983971391

Mailing address: SOUTH CAPITOL STREET SW

WASHINGTON, DC 20024

Contact: INDERJIT SINGH

Contact address: SOUTH CAPITOL STREET SW

WASHINGTON, DC 20024

Contact country: US

Contact telephone: 202-554-6877 Contact email: Not reported

EPA Region: 03 Land type: Private

Classification: Conditionally Exempt Small Quantity Generator

Description: Handler: generates 100 kg or less of hazardous waste per calendar

month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from

the cleanup of a spill, into or on any land or water, of acutely

hazardous waste

Owner/Operator Summary:

Owner/operator name: SINGH TRANSMISSION C/O AUTO CARE CENTRE

Owner/operator address: SOUTH CAPITOL ST SW

WASHINGTON, DC 20024

Owner/operator country: US

Owner/operator telephone: 202-554-6877
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 01/01/2000
Owner/Op end date: Not reported

Owner/operator name: AUTOMOTIVE CARE CENTER INC

Owner/operator address: SOUTH CAPITOL ST SW

WASHINGTON, DC 20024

Owner/operator country: US

Owner/operator telephone: 202-554-6877
Legal status: Private
Owner/Operator Type: Operator

Owner/Op start date: 01/01/2000
Owner/Op end date: Not reported

Direction Distance

Elevation Site Database(s) EPA ID Number

# SINGH TRANSMISSION C/O AUTOMOTIVE CARE CENTRE (Continued)

1000858623

**EDR ID Number** 

Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): Nο Recycler of hazardous waste: No Transporter of hazardous waste: No Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: No Furnace exemption: No Used oil fuel burner: No Used oil processor: No User oil refiner: Nο Used oil fuel marketer to burner: No Used oil Specification marketer: No Used oil transfer facility: No Used oil transporter: No

# **Historical Generators:**

Date form received by agency: 09/02/1998

Facility name: SINGH TRANSMISSION C/O AUTOMOTIVE CARE CENTRE

Site name: AUTOMOTIVE CARE CENTER INC

Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 01/10/1995

Facility name: SINGH TRANSMISSION C/O AUTOMOTIVE CARE CENTRE

Site name: AUTOMOTIVE CARE CENTER INC

Classification: Not a generator, verified

Hazardous Waste Summary:

Waste code: D001

Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF

LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT

WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D009
Waste name: MERCURY

Facility Has Received Notices of Violations:

Regulation violated: SR - 262.41

Area of violation: Generators - Records/Reporting

Date violation determined: 04/04/1994
Date achieved compliance: 06/09/1994
Violation lead agency: State

Enforcement action: WRITTEN INFORMAL

Enforcement action date: 04/04/1994
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Direction Distance

Elevation Site Database(s) EPA ID Number

# SINGH TRANSMISSION C/O AUTOMOTIVE CARE CENTRE (Continued)

1000858623

**EDR ID Number** 

**Evaluation Action Summary:** 

Evaluation date: 08/03/2011

Evaluation: NON-FINANCIAL RECORD REVIEW

Area of violation:

Date achieved compliance:

Evaluation lead agency:

Not reported

Not reported

State

Evaluation date: 08/06/2004

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation:

Date achieved compliance:

Evaluation lead agency:

Not reported

State

Evaluation date: 08/26/1998

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: Not reported Date achieved compliance: Not reported Evaluation lead agency: State

Evaluation date: 07/26/1996

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation:

Date achieved compliance:

Evaluation lead agency:

Not reported

Not reported

State

Evaluation date: 04/04/1994

Evaluation: NON-FINANCIAL RECORD REVIEW Area of violation: Generators - Records/Reporting

Date achieved compliance: 06/09/1994 Evaluation lead agency: State

Evaluation date: 09/17/1993

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation:

Date achieved compliance:

Evaluation lead agency:

Not reported
Not reported
State

NJ MANIFEST:

NJA5095756 Manifest Code: EPA ID: DCD983971391 Date Shipped: 01/02/2004 TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Not reported Transporter 3 EPA ID: Transporter 4 EPA ID: Not reported Transporter 5 EPA ID: Not reported Transporter 6 EPA ID: Not reported Transporter 7 EPA ID: Not reported Transporter 8 EPA ID: Not reported Transporter 10 EPA ID: Not reported Date Trans1 Transported Waste: 01/02/2004 Date Trans2 Transported Waste: Not reported Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Not reported Date Trans6 Transported Waste: Not reported

Map ID MAP FINDINGS
Direction

Distance Elevation

Site Database(s) EPA ID Number

# SINGH TRANSMISSION C/O AUTOMOTIVE CARE CENTRE (Continued)

1000858623

**EDR ID Number** 

Date Trans7 Transported Waste: Not reported Date Trans8 Transported Waste: Not reported Date Trans9 Transported Waste: Not reported Date Trans10 Transported Waste: Not reported Date TSDF Received Waste: 01/14/2004 Tranporter 1 Decal: Not reported Tranporter 2 Decal: Not reported Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported Transporter-3 EPA Facility Name: Not reported Transporter-4 EPA Facility Name: Not reported Transporter-5 EPA Facility Name: Not reported TSDF EPA Facility Name: Not reported QTY Units: Not reported Transporter SEQ ID: Not reported Not reported Transporter-1 Date: Waste SEQ ID: Not reported Waste Type Code 2: Not reported Waste Type Code 3: Not reported Waste Type Code 4: Not reported Waste Type Code 5: Not reported Waste Type Code 6: Not reported Date Accepted: Not reported Manifest Discrepancy Type: Not reported 03120421 Data Entry Number: Reference Manifest Number: Not reported Was Load Rejected (Y/N): No

Reason Load Was Rejected:

Waste Code:

Manifest Year:

Quantity:

Unit:

Not reported

Manifest Code: NJA5097058 EPA ID: DCD983971391 Date Shipped: 02/11/2004 TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Transporter 3 EPA ID: Not reported Transporter 4 EPA ID: Not reported Transporter 5 EPA ID: Not reported Transporter 6 EPA ID: Not reported Transporter 7 EPA ID: Not reported Transporter 8 EPA ID: Not reported Not reported Transporter 10 EPA ID: Date Trans1 Transported Waste: 02/11/2004 Date Trans2 Transported Waste: Not reported Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Not reported Date Trans6 Transported Waste: Not reported Date Trans7 Transported Waste: Not reported

Date Trans8 Transported Waste:

Direction Distance Elevation

Site Database(s) **EPA ID Number** 

# SINGH TRANSMISSION C/O AUTOMOTIVE CARE CENTRE (Continued)

Not reported

1000858623

**EDR ID Number** 

Date Trans9 Transported Waste: Not reported Date Trans10 Transported Waste: Not reported Date TSDF Received Waste: 02/17/2004 Tranporter 1 Decal: Not reported Tranporter 2 Decal: Not reported Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported Transporter-3 EPA Facility Name: Not reported Transporter-4 EPA Facility Name: Not reported Transporter-5 EPA Facility Name: Not reported TSDF EPA Facility Name: Not reported QTY Units: Not reported Transporter SEQ ID: Not reported Transporter-1 Date: Not reported Not reported Waste SEQ ID: Waste Type Code 2: Not reported Waste Type Code 3: Not reported Waste Type Code 4: Not reported Waste Type Code 5: Not reported Waste Type Code 6: Not reported Date Accepted: Not reported Manifest Discrepancy Type: Not reported Data Entry Number: 03220421 Reference Manifest Number: Not reported Was Load Rejected (Y/N): Nο

Reason Load Was Rejected: Not reported Waste Code: Not reported Not reported Manifest Year: Not reported Quantity: Unit: Not reported Not reported Hand Code:

Manifest Code: NJA5094875 EPA ID: DCD983971391 Date Shipped: 04/22/2004 TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Transporter 3 EPA ID: Not reported Transporter 4 EPA ID: Not reported Transporter 5 EPA ID: Not reported Transporter 6 EPA ID: Not reported Transporter 7 EPA ID: Not reported Transporter 8 EPA ID: Not reported Transporter 10 EPA ID: Not reported 04/22/2004 Date Trans1 Transported Waste: Not reported Date Trans2 Transported Waste: Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Not reported Date Trans6 Transported Waste: Not reported Date Trans7 Transported Waste: Not reported Date Trans8 Transported Waste: Not reported

Direction Distance Elevation

Site Database(s) EPA ID Number

# SINGH TRANSMISSION C/O AUTOMOTIVE CARE CENTRE (Continued)

1000858623

**EDR ID Number** 

Date Trans9 Transported Waste: Not reported Date Trans10 Transported Waste: Not reported Date TSDF Received Waste: 04/26/2004 Tranporter 1 Decal: Not reported Tranporter 2 Decal: Not reported Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported Not reported Transporter-2 EPA Facility Name: Transporter-3 EPA Facility Name: Not reported Transporter-4 EPA Facility Name: Not reported Transporter-5 EPA Facility Name: Not reported TSDF EPA Facility Name: Not reported QTY Units: Not reported Transporter SEQ ID: Not reported Transporter-1 Date: Not reported Waste SEQ ID: Not reported Not reported Waste Type Code 2: Waste Type Code 3: Not reported Waste Type Code 4: Not reported Waste Type Code 5: Not reported Waste Type Code 6: Not reported Date Accepted: Not reported Not reported Manifest Discrepancy Type: Data Entry Number: 05110421 Reference Manifest Number: Not reported Was Load Rejected (Y/N): No Reason Load Was Rejected: Not reported Waste Code: Not reported

Reason Load Was Rejected:
Waste Code:
Manifest Year:

Quantity:
Unit:
Not reported

Manifest Code: NJA5039280 DCD983971391 EPA ID: Date Shipped: 06/03/2004 TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Transporter 3 EPA ID: Not reported Transporter 4 EPA ID: Not reported Transporter 5 EPA ID: Not reported Transporter 6 EPA ID: Not reported Transporter 7 EPA ID: Not reported Transporter 8 EPA ID: Not reported Transporter 10 EPA ID: Not reported Date Trans1 Transported Waste: 06/03/2004 Not reported Date Trans2 Transported Waste: Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Not reported Date Trans6 Transported Waste: Not reported Date Trans7 Transported Waste: Not reported Date Trans8 Transported Waste: Not reported Date Trans9 Transported Waste: Not reported

Direction Distance Elevation

Site Database(s) EPA ID Number

# SINGH TRANSMISSION C/O AUTOMOTIVE CARE CENTRE (Continued)

1000858623

**EDR ID Number** 

Date Trans10 Transported Waste: Not reported 06/08/2004 Date TSDF Received Waste: Not reported Tranporter 1 Decal: Not reported Tranporter 2 Decal: Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported Not reported Transporter-3 EPA Facility Name: Transporter-4 EPA Facility Name: Not reported Transporter-5 EPA Facility Name: Not reported TSDF EPA Facility Name: Not reported QTY Units: Not reported Transporter SEQ ID: Not reported Transporter-1 Date: Not reported Waste SEQ ID: Not reported Waste Type Code 2: Not reported Not reported Waste Type Code 3: Waste Type Code 4: Not reported Waste Type Code 5: Not reported Waste Type Code 6: Not reported Date Accepted: Not reported Manifest Discrepancy Type: Not reported Data Entry Number: 06230421 Reference Manifest Number: Not reported Was Load Rejected (Y/N): No Reason Load Was Rejected: Not reported Waste Code: Not reported

Reason Load Was Rejected:
Waste Code:
Manifest Year:
Quantity:
Unit:
Not reported

Manifest Code: NJA5071664 EPA ID: DCD983971391 Date Shipped: 08/26/2004 TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Not reported Transporter 3 EPA ID: Transporter 4 EPA ID: Not reported Transporter 5 EPA ID: Not reported Not reported Transporter 6 EPA ID: Transporter 7 EPA ID: Not reported Transporter 8 EPA ID: Not reported Transporter 10 EPA ID: Not reported Date Trans1 Transported Waste: 08/26/2004 Date Trans2 Transported Waste: Not reported Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Not reported Date Trans6 Transported Waste: Not reported Date Trans7 Transported Waste: Not reported Date Trans8 Transported Waste: Not reported Date Trans9 Transported Waste: Not reported Date Trans10 Transported Waste: Not reported

Direction Distance Elevation

n Site Database(s) EPA ID Number

# SINGH TRANSMISSION C/O AUTOMOTIVE CARE CENTRE (Continued)

1000858623

**EDR ID Number** 

Date TSDF Received Waste: 09/01/2004 Tranporter 1 Decal: Not reported Not reported Tranporter 2 Decal: Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported Transporter-3 EPA Facility Name: Not reported Not reported Transporter-4 EPA Facility Name: Transporter-5 EPA Facility Name: Not reported TSDF EPA Facility Name: Not reported QTY Units: Not reported Transporter SEQ ID: Not reported Transporter-1 Date: Not reported Waste SEQ ID: Not reported Waste Type Code 2: Not reported Waste Type Code 3: Not reported Not reported Waste Type Code 4: Waste Type Code 5: Not reported Waste Type Code 6: Not reported Date Accepted: Not reported Manifest Discrepancy Type: Not reported Data Entry Number: 10010422 Not reported Reference Manifest Number: Was Load Rejected (Y/N): No Reason Load Was Rejected: Not reported Not reported Waste Code: Manifest Year: Not reported Quantity: Not reported Unit: Not reported Hand Code: Not reported

Manifest Code: NJA5071348 EPA ID: DCD983971391 Date Shipped: 10/01/2004 TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Transporter 3 EPA ID: Not reported Not reported Transporter 4 EPA ID: Not reported Transporter 5 EPA ID: Transporter 6 EPA ID: Not reported Transporter 7 EPA ID: Not reported Transporter 8 EPA ID: Not reported Transporter 10 EPA ID: Not reported Date Trans1 Transported Waste: 10/01/2004 Date Trans2 Transported Waste: Not reported Date Trans3 Transported Waste: Not reported Not reported Date Trans4 Transported Waste: Date Trans5 Transported Waste: Not reported Date Trans6 Transported Waste: Not reported Date Trans7 Transported Waste: Not reported Date Trans8 Transported Waste: Not reported Date Trans9 Transported Waste: Not reported Date Trans10 Transported Waste: Not reported Date TSDF Received Waste: 10/07/2004

Direction Distance Elevation

Site Database(s) EPA ID Number

# SINGH TRANSMISSION C/O AUTOMOTIVE CARE CENTRE (Continued)

1000858623

**EDR ID Number** 

Tranporter 1 Decal: Not reported Tranporter 2 Decal: Not reported Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported Transporter-3 EPA Facility Name: Not reported Transporter-4 EPA Facility Name: Not reported Not reported Transporter-5 EPA Facility Name: TSDF EPA Facility Name: Not reported QTY Units: Not reported Transporter SEQ ID: Not reported Transporter-1 Date: Not reported Waste SEQ ID: Not reported Waste Type Code 2: Not reported Waste Type Code 3: Not reported Waste Type Code 4: Not reported Not reported Waste Type Code 5: Waste Type Code 6: Not reported Date Accepted: Not reported Manifest Discrepancy Type: Not reported Data Entry Number: 11030425 Reference Manifest Number: Not reported Was Load Rejected (Y/N): No

Was Esda Was Rejected:
Waste Code:
Waste Code:
Mot reported
Manifest Year:
Quantity:
Unit:
Not reported

Manifest Code: NJA5069438 EPA ID: DCD983971391 Date Shipped: 11/09/2004 TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Transporter 3 EPA ID: Not reported Transporter 4 EPA ID: Not reported Not reported Transporter 5 EPA ID: Not reported Transporter 6 EPA ID: Transporter 7 EPA ID: Not reported Not reported Transporter 8 EPA ID: Not reported Transporter 10 EPA ID: Date Trans1 Transported Waste: 11/09/2004 Date Trans2 Transported Waste: Not reported Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Not reported Not reported Date Trans5 Transported Waste: Date Trans6 Transported Waste: Not reported Date Trans7 Transported Waste: Not reported Date Trans8 Transported Waste: Not reported Date Trans9 Transported Waste: Not reported Date Trans10 Transported Waste: Not reported 11/11/2004 Date TSDF Received Waste: Tranporter 1 Decal: Not reported

Direction Distance Elevation

Site Database(s) EPA ID Number

# SINGH TRANSMISSION C/O AUTOMOTIVE CARE CENTRE (Continued)

1000858623

**EDR ID Number** 

Tranporter 2 Decal: Not reported Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported Transporter-3 EPA Facility Name: Not reported Transporter-4 EPA Facility Name: Not reported Transporter-5 EPA Facility Name: Not reported Not reported TSDF EPA Facility Name: QTY Units: Not reported Transporter SEQ ID: Not reported Transporter-1 Date: Not reported Waste SEQ ID: Not reported Waste Type Code 2: Not reported Waste Type Code 3: Not reported Waste Type Code 4: Not reported Waste Type Code 5: Not reported Not reported Waste Type Code 6: Date Accepted: Not reported Manifest Discrepancy Type: Not reported Data Entry Number: 01180525 Reference Manifest Number: Not reported Was Load Rejected (Y/N): No Reason Load Was Rejected: Not reported

Reason Load Was Rejected:
Waste Code:
Manifest Year:

Quantity:
Unit:
Not reported

Manifest Code: NJA5224982 DCD983971391 EPA ID: Date Shipped: 12/28/2004 TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Transporter 3 EPA ID: Not reported Transporter 4 EPA ID: Not reported Transporter 5 EPA ID: Not reported Not reported Transporter 6 EPA ID: Not reported Transporter 7 EPA ID: Transporter 8 EPA ID: Not reported Transporter 10 EPA ID: Not reported Date Trans1 Transported Waste: 12/28/2004 Date Trans2 Transported Waste: Not reported Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Not reported Not reported Date Trans6 Transported Waste: Date Trans7 Transported Waste: Not reported Date Trans8 Transported Waste: Not reported Date Trans9 Transported Waste: Not reported Date Trans10 Transported Waste: Not reported Date TSDF Received Waste: 01/05/2005 Tranporter 1 Decal: Not reported Tranporter 2 Decal: Not reported

Direction Distance Elevation

ration Site Database(s) EPA ID Number

# SINGH TRANSMISSION C/O AUTOMOTIVE CARE CENTRE (Continued)

1000858623

**EDR ID Number** 

Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported Transporter-3 EPA Facility Name: Not reported Transporter-4 EPA Facility Name: Not reported Transporter-5 EPA Facility Name: Not reported TSDF EPA Facility Name: Not reported Not reported QTY Units: Transporter SEQ ID: Not reported Transporter-1 Date: Not reported Waste SEQ ID: Not reported Waste Type Code 2: Not reported Waste Type Code 3: Not reported Waste Type Code 4: Not reported Waste Type Code 5: Not reported Waste Type Code 6: Not reported Not reported Date Accepted: Manifest Discrepancy Type: Not reported Data Entry Number: 01310521 Reference Manifest Number: Not reported Was Load Rejected (Y/N): No

Was Load Rejected (Y/N):

Reason Load Was Rejected:

Waste Code:

Manifest Year:

Quantity:

Unit:

Hand Code:

Not reported

Manifest Code: NJA5069918 EPA ID: DCD983971391 Date Shipped: 02/04/2005 TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Transporter 3 EPA ID: Not reported Transporter 4 EPA ID: Not reported Transporter 5 EPA ID: Not reported Transporter 6 EPA ID: Not reported Not reported Transporter 7 EPA ID: Not reported Transporter 8 EPA ID: Transporter 10 EPA ID: Not reported Date Trans1 Transported Waste: 02/04/2005 Date Trans2 Transported Waste: Not reported Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Not reported Date Trans6 Transported Waste: Not reported Date Trans7 Transported Waste: Not reported Date Trans8 Transported Waste: Not reported Date Trans9 Transported Waste: Not reported Not reported Date Trans10 Transported Waste: Date TSDF Received Waste: 02/10/2005 Tranporter 1 Decal: Not reported Tranporter 2 Decal: Not reported Generator EPA Facility Name: Not reported

Map ID MAP FINDINGS Direction

Distance Elevation

Site Database(s) **EPA ID Number** 

# SINGH TRANSMISSION C/O AUTOMOTIVE CARE CENTRE (Continued)

1000858623

**EDR ID Number** 

Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported Transporter-3 EPA Facility Name: Not reported Transporter-4 EPA Facility Name: Not reported Transporter-5 EPA Facility Name: Not reported TSDF EPA Facility Name: Not reported QTY Units: Not reported Not reported Transporter SEQ ID: Transporter-1 Date: Not reported Waste SEQ ID: Not reported Waste Type Code 2: Not reported Waste Type Code 3: Not reported Waste Type Code 4: Not reported Waste Type Code 5: Not reported Waste Type Code 6: Not reported Date Accepted: Not reported Manifest Discrepancy Type: Not reported Data Entry Number: 04130521 Reference Manifest Number: Not reported

Was Load Rejected (Y/N): No

Reason Load Was Rejected: Not reported Waste Code: Not reported Not reported Manifest Year: Quantity: Not reported Unit: Not reported Hand Code: Not reported

Manifest Code: NJA5070815 DCD983971391 EPA ID: Date Shipped: 03/14/2005 TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Transporter 3 EPA ID: Not reported Transporter 4 EPA ID: Not reported Transporter 5 EPA ID: Not reported Transporter 6 EPA ID: Not reported Transporter 7 EPA ID: Not reported Transporter 8 EPA ID: Not reported Not reported Transporter 10 EPA ID: Date Trans1 Transported Waste: 03/14/2005 Not reported Date Trans2 Transported Waste: Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Not reported Date Trans6 Transported Waste: Not reported Date Trans7 Transported Waste: Not reported Date Trans8 Transported Waste: Not reported Date Trans9 Transported Waste: Not reported Date Trans10 Transported Waste: Not reported 03/21/2005 Date TSDF Received Waste: Tranporter 1 Decal: Not reported Tranporter 2 Decal: Not reported Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported

Direction Distance Elevation

Site Database(s) EPA ID Number

# SINGH TRANSMISSION C/O AUTOMOTIVE CARE CENTRE (Continued)

1000858623

**EDR ID Number** 

Transporter-2 EPA Facility Name: Not reported Transporter-3 EPA Facility Name: Not reported Transporter-4 EPA Facility Name: Not reported Transporter-5 EPA Facility Name: Not reported TSDF EPA Facility Name: Not reported Not reported QTY Units: Not reported Transporter SEQ ID: Not reported Transporter-1 Date: Waste SEQ ID: Not reported Waste Type Code 2: Not reported Waste Type Code 3: Not reported Waste Type Code 4: Not reported Waste Type Code 5: Not reported Waste Type Code 6: Not reported Date Accepted: Not reported Manifest Discrepancy Type: Not reported Data Entry Number: 05110521 Reference Manifest Number: Not reported Was Load Rejected (Y/N): No

Waste Code:
Waste Code:
Waste Code:
Mot reported
Manifest Year:
Quantity:
Unit:
Not reported

Manifest Code: NJA5225357 EPA ID: DCD983971391 06/06/2005 Date Shipped: TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Transporter 3 EPA ID: Not reported Transporter 4 EPA ID: Not reported Transporter 5 EPA ID: Not reported Transporter 6 EPA ID: Not reported Transporter 7 EPA ID: Not reported Transporter 8 EPA ID: Not reported Transporter 10 EPA ID: Not reported Date Trans1 Transported Waste: 06/06/2005 Date Trans2 Transported Waste: Not reported Not reported Date Trans3 Transported Waste: Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Not reported Date Trans6 Transported Waste: Not reported Date Trans7 Transported Waste: Not reported Date Trans8 Transported Waste: Not reported Date Trans9 Transported Waste: Not reported Date Trans10 Transported Waste: Not reported Date TSDF Received Waste: 06/14/2005 Tranporter 1 Decal: Not reported Tranporter 2 Decal: Not reported Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported

Direction Distance

**EDR ID Number** Elevation Site Database(s) **EPA ID Number** 

# SINGH TRANSMISSION C/O AUTOMOTIVE CARE CENTRE (Continued)

1000858623

Transporter-3 EPA Facility Name: Not reported Transporter-4 EPA Facility Name: Not reported Transporter-5 EPA Facility Name: Not reported TSDF EPA Facility Name: Not reported QTY Units: Not reported Not reported Transporter SEQ ID: Not reported Transporter-1 Date: Not reported Waste SEQ ID: Waste Type Code 2: Not reported Waste Type Code 3: Not reported Waste Type Code 4: Not reported Waste Type Code 5: Not reported Not reported Waste Type Code 6: Date Accepted: Not reported Manifest Discrepancy Type: Not reported Data Entry Number: 07210521 Not reported Reference Manifest Number: Was Load Rejected (Y/N): No

Reason Load Was Rejected:

Not reported Waste Code: Not reported Manifest Year: Not reported Quantity: Not reported Unit: Not reported Hand Code: Not reported

**G S A CENTRAL SUPPORT FIELD OFFICE** 

RCRA NonGen / NLR 1000101059 **FINDS** DC8470090020

NNE **10 P STREET SW** 1/8-1/4 WASHINGTON, DC

0.127 mi.

L52

672 ft. Site 1 of 10 in cluster L

RCRA NonGen / NLR:

Relative: Higher

Date form received by agency: 03/09/2007

Facility name:

Actual: 26 ft.

**GSA - CENTRAL SUPPORT FIELD OFFICE** Facility address: 10 P STREET SW

WASHINGTON, DC 20407

DC8470090020 EPA ID: Mailing address: P STREET SW

WASHINGTON, DC 20407

Contact: JOHN DOLLINS Contact address: P STREET SW

WASHINGTON, DC 20407

Contact country: US

Contact telephone: (202) 755-9459 Contact email: Not reported

EPA Region: 03

Land type: Facility is not located on Indian land. Additional information is not known.

Classification: Non-Generator

Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

**OPERNAME** Owner/operator name: Owner/operator address: OPERSTREET

OPERCITY, AK 99999

Owner/operator country: Not reported

Direction Distance

Elevation Site Database(s) EPA ID Number

# G S A CENTRAL SUPPORT FIELD OFFICE (Continued)

1000101059

**EDR ID Number** 

Owner/operator telephone: (215) 555-1212
Legal status: Federal
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: US GOVERNMENT
Owner/operator address: OWNERSTREET

OWNERCITY, AK 99999 Not reported

Owner/operator telephone: (215) 555-1212
Legal status: Federal
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

#### Handler Activities Summary:

Owner/operator country:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: No Transporter of hazardous waste: Nο Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: No Furnace exemption: No Used oil fuel burner: Nο Used oil processor: No User oil refiner: No Used oil fuel marketer to burner: No Used oil Specification marketer: No Used oil transfer facility: Nο Used oil transporter: No

# Historical Generators:

Date form received by agency: 09/28/1987

Facility name: GSA - CENTRAL SUPPORT FIELD OFFICE Site name: G S A CENTRAL SUPPORT FIELD OFFICE

Classification: Small Quantity Generator

# Hazardous Waste Summary:

Waste code: D000
Waste name: Not Defined

Waste code: D001

Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF

LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT

WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D002

Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS

CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN

Map ID MAP FINDINGS
Direction

Distance
Elevation Site

EDR ID Number
Database(s) EPA ID Number

# G S A CENTRAL SUPPORT FIELD OFFICE (Continued)

1000101059

OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Facility Has Received Notices of Violations:

Regulation violated: SR - 262.41(a)

Area of violation: Generators - Records/Reporting

Date violation determined: 03/06/1992
Date achieved compliance: 03/25/1992
Violation lead agency: State

Enforcement action: WRITTEN INFORMAL

Enforcement action date: 03/06/1992
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

**Evaluation Action Summary:** 

Evaluation date: 03/06/1992

Evaluation: NON-FINANCIAL RECORD REVIEW Area of violation: Generators - Records/Reporting

Date achieved compliance: 03/25/1992 Evaluation lead agency: State

Evaluation date: 01/12/1990

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation:

Date achieved compliance:

Evaluation lead agency:

Not reported

State

FINDS:

Registry ID: 110002498994

Environmental Interest/Information System

NCDB (National Compliance Data Base) supports implementation of the Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) and the Toxic Substances Control Act (TSCA). The system tracks inspections in regions and states with cooperative agreements, enforcement actions, and settlements.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Direction Distance

Elevation Site Database(s) EPA ID Number

L53 LANSBURGH BROTHERS DC HIST UST S110337387

N/A

**EDR ID Number** 

NNE 10 P ST SW 1/8-1/4 WASHINGTON, DC

0.127 mi.

672 ft. Site 2 of 10 in cluster L

Relative: HIST UST:

Higher Facility Id: 0000253*001

Confirm Tank/Owner Address Found:yes

Actual: Confirn Tank/No Owner Found: Not reported 26 ft. Owner Found/No Tank: Not reported

No Owner/No Tank: Not reported Address Not Found: Not reported

Ltr Edc: yes
Tank Status: POU
Tank Capacity: 1000
Product: Gas

Facility Id: 0000253*002

Confirm Tank/Owner Address Found yes

Confirn Tank/No Owner Found:

Not reported

Owner Found/No Tank:

No Owner/No Tank:

Address Not Found:

Not reported

Not reported

Not reported

Ltr Edc: yes
Tank Status: POU
Tank Capacity: 1000
Product: Gas

Facility Id: 0000253*003

Confirm Tank/Owner Address Found:yes

Confirn Tank/No Owner Found:

Owner Found/No Tank:

No Owner/No Tank:

Address Not Found:

Not reported

Not reported

Not reported

Not reported

Ltr Edc: yes
Tank Status: POU
Tank Capacity: 1000
Product: Gas

J54 WASHINGTON REAL ESTATE INVESTMENT INSURANCE

NNE 1501 SOUTH CAPITOL STREET, SW

1/8-1/4 WASHINGTON, DC

0.127 mi.

672 ft. Site 8 of 11 in cluster J

Relative: LUST:

Higher Facility ID: 2-000210
Facility Type: Commercial

Actual: Facility Status: Closed
25 ft. Product: Gasoline
Notification Date: 11/2/2001

Ward: 6
Media Of Contamination: Soil
Entry Date: 11/8/2001
Lust Number: 2002014

DC LUST S105260082

N/A

Direction Distance

Elevation Site Database(s) **EPA ID Number** 

J55 **FIVE SAC SELF-STORAGE** DC UST U003294411 NNE 1501 S CAPITOL ST SW10 P ST SW N/A

1/8-1/4 WASHINGTON, DC 20003

0.127 mi.

672 ft. Site 9 of 11 in cluster J

UST: Relative:

Facility ID: Higher 2000210 Facility Description: False

Actual: Owner: FIVE SAC SELF-STORAGE CORPORATION ET AL

25 ft.

Tank ID:

Tank Status: **Permanently Out of Use** 

Tank Capacity: 12000 Substance: Heating Oil

Tank ID:

Tank Status: **Permanently Out of Use** 

Tank Capacity: 1000 Substance: Gasoline

Tank ID: 3

**Tank Status: Permanently Out of Use** 

Tank Capacity: 1000 Substance: Gasoline

Tank ID:

Tank Status: **Permanently Out of Use** 

Tank Capacity: 1000 Substance: Gasoline

SERCO MANAGEMENT SERVICES J56 NNE 1501 SOUTH CAPITOL ST SW 1/8-1/4

WASHINGTON, DC 20024

0.130 mi.

Site 10 of 11 in cluster J 684 ft.

Relative:

RCRA NonGen / NLR:

Date form received by agency: 08/06/2008 Higher

Facility name: SERCO MANAGEMENT SERVICES Actual: Facility address: 1501 SOUTH CAPITOL ST SW 25 ft. WASHINGTON, DC 20024

> EPA ID: DC0000266130

SOUTH CAPITOL ST SW Mailing address:

WASHINGTON, DC 20024

Contact: PAUL GAUTIER

Contact address: SOUTH CAPITOL ST SW

WASHINGTON, DC 20024

Contact country: US

Contact telephone: (202) 863-7770 Contact email: Not reported EPA Region: 03 Land type: Private Classification: Non-Generator

Description: Handler: Non-Generators do not presently generate hazardous waste 1000886515

DC0000266130

RCRA NonGen / NLR

**FINDS** 

**EDR ID Number** 

Direction Distance Elevation

on Site Database(s) EPA ID Number

# **SERCO MANAGEMENT SERVICES (Continued)**

1000886515

**EDR ID Number** 

Owner/Operator Summary:

Owner/operator name: CSN MANAGEMENT CORP
Owner/operator address: 14000 CONNECTICUT AVE

KENSINGTON, MD 20895

Owner/operator country: Not reported
Owner/operator telephone: (301) 984-9400

Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 01/01/0001
Owner/Op end date: Not reported

Owner/operator name: CSN MANAGEMENT CORP
Owner/operator address: 14000 CONNECTICUT AVE
KENSINGTON, MD 20895

Owner/operator country: US

Owner/Operator telephone: (301) 984-9400
Legal status: Private
Owner/Operator Type: Operator
Operator Operator Operator

Owner/Op start date: 01/01/1901
Owner/Op end date: Not reported

# Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: No Transporter of hazardous waste: No Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: No Furnace exemption: No Used oil fuel burner: No Used oil processor: No User oil refiner: No Used oil fuel marketer to burner: No Used oil Specification marketer: No Used oil transfer facility: No Used oil transporter: No

# Historical Generators:

Date form received by agency: 01/09/2002

Facility name: SERCO MANAGEMENT SERVICES

Classification: Not a generator, verified

Date form received by agency: 10/27/1999

Facility name: SERCO MANAGEMENT SERVICES

Classification: Small Quantity Generator

# Facility Has Received Notices of Violations:

Regulation violated: SR - 4401.23-4401.29

Area of violation: Generators - Records/Reporting

Date violation determined: 02/25/1999
Date achieved compliance: 03/24/1999
Violation lead agency: State

Enforcement action: WRITTEN INFORMAL

Enforcement action date: 02/25/1999

Direction Distance

**EDR ID Number** Elevation Site Database(s) **EPA ID Number** 

# **SERCO MANAGEMENT SERVICES (Continued)**

1000886515

Enf. disposition status: Not reported Enf. disp. status date: Not reported State Enforcement lead agency: Proposed penalty amount: Not reported Final penalty amount: Not reported Paid penalty amount: Not reported

Regulation violated: SR - 4403

Area of violation: Generators - Records/Reporting

Date violation determined: 02/25/1999 Date achieved compliance: 03/24/1999 Violation lead agency: State

WRITTEN INFORMAL Enforcement action:

Enforcement action date: 02/25/1999 Enf. disposition status: Not reported Enf. disp. status date: Not reported Enforcement lead agency: State Proposed penalty amount: Not reported Final penalty amount: Not reported Paid penalty amount: Not reported

Regulation violated: SR - 4200.6

Area of violation: Generators - General

Date violation determined: 02/25/1999 Date achieved compliance: 03/24/1999 Violation lead agency: State

Enforcement action: WRITTEN INFORMAL

Enforcement action date: 02/25/1999 Enf. disposition status: Not reported Enf. disp. status date: Not reported Enforcement lead agency: State Proposed penalty amount: Not reported Final penalty amount: Not reported Paid penalty amount: Not reported

**Evaluation Action Summary:** 

Evaluation date: 11/01/1999

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: Not reported Date achieved compliance: Not reported Evaluation lead agency: State

Evaluation date: 02/25/1999

COMPLIANCE EVALUATION INSPECTION ON-SITE Evaluation:

Area of violation: Generators - General

Date achieved compliance: 03/24/1999 Evaluation lead agency: State

Evaluation date: 02/25/1999

COMPLIANCE EVALUATION INSPECTION ON-SITE Evaluation:

Generators - Records/Reporting Area of violation:

Date achieved compliance: 03/24/1999 Evaluation lead agency: State

FINDS:

Registry ID: 110002498477

Direction Distance

Elevation Site Database(s) **EPA ID Number** 

**SERCO MANAGEMENT SERVICES (Continued)** 

1000886515

**EDR ID Number** 

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and

corrective action activities required under RCRA.

**ANACOSTIA READY MIX PLANT J57** 

Facility ID:

DC UST U003763748

N/A

**1522 S CAPITOL ST SE** NE 1/8-1/4 WASHINGTON, DC 20003

0.130 mi.

688 ft. Site 11 of 11 in cluster J

UST: Relative:

Higher

2000764

Facility Description: False

Actual: Owner: GENSTAR STONE PRODUCTS CO

25 ft.

Tank ID:

Tank Status: **Permanently Out of Use** 

Tank Capacity: 15000 Substance: Diesel

L58 **HOWARD S ODORIESS CLEANERS (PLANT)**  **EDR US Hist Cleaners** 1009133672

**EDR US Hist Auto Stat** 

N/A

1009003409

N/A

1347 S CAPITOL ST SE NNE 1/8-1/4 WASHINGTON, DC

0.147 mi.

774 ft. Site 3 of 10 in cluster L

**EDR Historical Cleaners:** Relative:

Name: HOWARD S ODORIESS CLEANERS (PLANT) Higher

Year:

Actual: Type: **CLOTHES PRESSERS AND CLEANERS** 

25 ft.

NNE

L59 **BRIDGEWAY MOTORS** 

1/8-1/4 WASHINGTON, DC

0.151 mi.

795 ft. Site 4 of 10 in cluster L

EDR Historical Auto Stations: Relative:

1343-45 S CAPITOL ST SE

**BRIDGEWAY MOTORS** Name: Higher

Year: 1960

Actual: Type: **AUTOMOBILE REPAIRING** 

26 ft.

TC03660997.2r Page 180

Direction Distance

**EDR ID Number** Elevation Site **EPA ID Number** Database(s)

L60 **HOWARD S ODORLESS CLEANERS EDR US Hist Cleaners** 1009133102 N/A

NNE 1343 S CAPITOL ST SE 1/8-1/4 WASHINGTON, DC

0.151 mi.

Site 5 of 10 in cluster L 795 ft.

Type:

Relative:

**EDR Historical Cleaners:** 

Higher

Name: HOWARD S ODORLESS CLEANERS

Year: 1931

Actual: 26 ft.

**CLEANERS-GARMENTS CURTAINS AND DRAPERIES** 

Name: HOWARD S ODORLESS CLEANERS INC OFFICE

Year: 1940

**CLOTHES PRESSERS AND CLEANERS** Type:

L61 **NATIONALS PARK** RCRA-CESQG 1014388462 DCR000503359

ΝE 1500 SOUTH CAPITOL STREET SE

WASHINGTON, DC 20003 1/8-1/4

0.163 mi.

Site 6 of 10 in cluster L 859 ft.

RCRA-CFSQG: Relative:

Higher

Date form received by agency: 12/21/2010

Facility name: NATIONALS PARK

Actual: 25 ft.

1500 SOUTH CAPITOL STREET SE Facility address:

WASHINGTON, DC 200031507

EPA ID: DCR000503359

SOUTH CAPITOL STREET SE Mailing address:

WASHINGTON, DC 200031507

Contact: FRANK GAMBINO

Contact address: SOUTH CAPITAL STREET SE

WASHINGTON, DC 200031507

Contact country: US

Contact telephone: 202-640-7000

Contact email: FGAMBINO@LERNER.COM

EPA Region: 03 Land type: Private

Classification: Conditionally Exempt Small Quantity Generator

Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time;

or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from

the cleanup of a spill, into or on any land or water, of acutely

hazardous waste

Owner/Operator Summary:

Owner/operator name: WASHINGTON CONVENTION & SPORTS AUTHORITY

Owner/operator address: MOUNT VERNON PLACE NW

WASHINGTON, DC 20056

Owner/operator country: US

Owner/operator telephone: Not reported

Direction Distance

Elevation Site Database(s) EPA ID Number

**NATIONALS PARK (Continued)** 

1014388462

**EDR ID Number** 

Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 03/08/2008
Owner/Op end date: Not reported

Owner/operator name: WASHINGTON NATIONALS STADIUM LLC

Owner/operator address: SOUTH CAPITAL STREET SE

WASHINGTON, DC 20003

Owner/operator country: US

Owner/operator telephone: Not reported Legal status: Private Owner/Operator Type: Operator Owner/Op start date: 03/30/2008 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: No Transporter of hazardous waste: No Treater, storer or disposer of HW: Nο Underground injection activity: No On-site burner exemption: No Furnace exemption: No Used oil fuel burner: No Used oil processor: No User oil refiner: No Used oil fuel marketer to burner: No Used oil Specification marketer: No Used oil transfer facility: No Used oil transporter: No

Hazardous Waste Summary:

Waste code: D009
Waste name: MERCURY

Violation Status: No violations found

**Evaluation Action Summary:** 

Evaluation date: 02/22/2012

Evaluation: NON-FINANCIAL RECORD REVIEW

Area of violation:

Date achieved compliance:

Evaluation lead agency:

Not reported

State

L62 BASEBALL STADIUM
NE 1500 SOUTH CAPITOL ST SE
1/8-1/4 WASHINGTON, DC 20001

0.163 mi.

859 ft. Site 7 of 10 in cluster L

Relative: UST:

Higher Facility ID: 9000736
Facility Description: False
Actual: Owner: UNKNOWN

25 ft.

Tank ID: 1

TC03660997.2r Page 182

DC UST U004051757

N/A

Direction Distance

**EDR ID Number** Elevation Site Database(s) **EPA ID Number** 

**BASEBALL STADIUM (Continued)** 

U004051757

Tank Status: **Permanently Out of Use** 

10000 Tank Capacity: Not Listed Substance:

Tank ID:

Tank Status: **Permanently Out of Use** 

Tank Capacity: 1000 Substance: Unknown

Tank ID:

**Permanently Out of Use** Tank Status:

Tank Capacity: Substance: Unknown

Tank ID:

Tank Status: **Permanently Out of Use** 

Tank Capacity: 500 Substance: Other

Tank ID:

**Permanently Out of Use** Tank Status:

Tank Capacity: 500 Substance: Other

Tank ID:

Tank Status: **Permanently Out of Use** 

Tank Capacity: 10000 Substance: Diesel

Tank ID:

Tank Status: **Permanently Out of Use** 

Tank Capacity: 10000 Substance: Diesel

Tank ID:

Tank Status: **Permanently Out of Use** 

Tank Capacity: 1000 Unknown Substance:

Tank ID:

Tank Status: **Permanently Out of Use** 

Tank Capacity: 1000 Substance: Unknown

Tank ID: 10

Tank Status: **Permanently Out of Use** 

Tank Capacity: 10000 Substance: Unknown

Direction Distance

**EDR ID Number** Elevation Site Database(s) **EPA ID Number** 

**BASEBALL STADIUM (Continued)** U004051757

Tank ID: 11

Tank Status: **Permanently Out of Use** 

550 Tank Capacity: Substance: Not Listed

Tank ID: 12

Tank Status: **Permanently Out of Use** 

Tank Capacity: 3000 Substance: Not Listed

L63 DC SPORT & ENTERTAINMENT COM DC VCP S107994790

NE 1500 S. CAPITAL ST. S.E WASHINGTON, DC 20003 1/8-1/4

0.163 mi.

859 ft. Site 8 of 10 in cluster L

VCP: Relative:

Higher Facility ID: VCP2006-008

Square Number: 2, 703,704,705,7065-8,11,15,37-39,53,54,

Actual: Ward:

25 ft. Zoning Type: Special-Stadium

Contamination Type: BTEX,TPH. PAH, Metals

Contamination Media: Soil/GW Size: 19.70 **Enrolled Date:** 4/6/05 Cleanup Current Status: Active Complete Date: 6/22/10

POTOMAC ELECT POWER CO/BUZZARD PT STATIO NY MANIFEST S111445484 M64 N/A

1ST & V ST/SW South 1/8-1/4 WASHINGTON, DC 20024

Country:

0.167 mi.

Site 1 of 2 in cluster M 880 ft.

NY MANIFEST: Relative: EPA ID: DCD000819508 Lower

USA Actual: Mailing Name: POTOMAC ELECT POWER CO/BUZZARD PT STATIO

9 ft. Mailing Contact: R E STUDDS

Mailing Address: 1ST & V STREET SW

Mailing Address 2: Not reported WASHINGTON Mailing City:

Mailing State: DC Mailing Zip: 20024 Mailing Zip4: Not reported Mailing Country: USA

Mailing Phone: 202-388-2414

Document ID: Not reported Manifest Status: Not reported Trans1 State ID: NJD080631369 Trans2 State ID: NJD071629976 Generator Ship Date: 2008-01-22 Trans1 Recy Date: 2008-01-22

N/A

Direction Distance

**EDR ID Number** Elevation Site Database(s) **EPA ID Number** 

# POTOMAC ELECT POWER CO/BUZZARD PT STATIO (Continued)

S111445484

Trans2 Recv Date: 2008-01-29 2008-02-11 TSD Site Recv Date: Part A Recv Date: Not reported Part B Recv Date: Not reported Generator EPA ID: DCR000500140 Trans1 EPA ID: Not reported Trans2 EPA ID: Not reported TSDF ID: NYD049836679 Waste Code: Not reported Quantity: 400.0 Units: P - Pounds

Number of Containers: 1.0 Container Type:

DM - Metal drums, barrels

Handling Method: T Chemical, physical, or biological treatment.

Specific Gravity: Year: 2008

Manifest Tracking Num: 000152567VES

Import Ind: Ν Export Ind: Ν Ν Discr Quantity Ind: Discr Type Ind: Ν Discr Residue Ind: Ν Discr Partial Reject Ind: Ν Discr Full Reject Ind:

Manifest Ref Num: Not reported Alt Fac RCRA Id: Not reported Alt Fac Sign Date: Not reported Mgmt Method Type Code: H132

Document ID: NYB9481347 Manifest Status: Not reported Trans1 State ID: NJD080631369 Trans2 State ID: Not reported 12/03/2001 Generator Ship Date: Trans1 Recv Date: 12/03/2001 Trans2 Recv Date: Not reported TSD Site Recv Date: 12/11/2001 Part A Recv Date: Not reported Part B Recv Date: Not reported Generator EPA ID: DCR000500140 Trans1 EPA ID: NYD049836679 Trans2 EPA ID: Not reported TSDF ID: 321146459

D008 - LEAD 5.0 MG/L TCLP Waste Code:

00390 Quantity: Units: P - Pounds Number of Containers: 001

Container Type: DM - Metal drums, barrels

Handling Method: L Landfill. Specific Gravity: 01.00 Year: 2001

Not reported Document ID: Manifest Status: Not reported Trans1 State ID: NJD080631369

Direction Distance Elevation

vation Site Database(s) EPA ID Number

# POTOMAC ELECT POWER CO/BUZZARD PT STATIO (Continued)

S111445484

**EDR ID Number** 

Trans2 State ID: NJD071629976 2008-01-22 Generator Ship Date: Trans1 Recv Date: 2008-01-22 Trans2 Recv Date: 2008-01-29 TSD Site Recv Date: 2008-02-11 Part A Recv Date: Not reported Part B Recv Date: Not reported DCR000500140 Generator EPA ID: Trans1 EPA ID: Not reported Trans2 EPA ID: Not reported TSDF ID: NYD049836679 Waste Code: Not reported Quantity: 400.0 Units: P - Pounds

Number of Containers: 1.0

Container Type: DM - Metal drums, barrels

Handling Method: T Chemical, physical, or biological treatment.

Specific Gravity: 1.0 Year: 2008

Manifest Tracking Num: 000152567VES

Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N

Manifest Ref Num:
Alt Fac RCRA Id:
Not reported
H132

Mgmt Method Type Code: H132

Document ID: Not reported Not reported Manifest Status: NJD080631369 Trans1 State ID: NJD071629976 Trans2 State ID: Generator Ship Date: 2008-01-22 Trans1 Recv Date: 2008-01-22 Trans2 Recv Date: 2008-01-29 TSD Site Recv Date: 2008-02-11 Part A Recv Date: Not reported Part B Recv Date: Not reported DCR000500140 Generator EPA ID: Trans1 EPA ID: Not reported Trans2 EPA ID: Not reported TSDF ID: NYD049836679 Waste Code: Not reported Quantity: 400.0 P - Pounds Units:

Number of Containers: 1.0

Container Type: DM - Metal drums, barrels

Handling Method: T Chemical, physical, or biological treatment.

Specific Gravity: 1.0 Year: 2008

Manifest Tracking Num: 000152567VES

Import Ind:

Direction Distance Elevation

ion Site Database(s) EPA ID Number

# POTOMAC ELECT POWER CO/BUZZARD PT STATIO (Continued)

S111445484

**EDR ID Number** 

Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N

Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H132

EPA ID: DCR000500140

Country: USA

Mailing Name: MIRANT COMPANY
Mailing Contact: VERNON CABLE
Mailing Address: 1 STREET & V STREET

Mailing Address 2: Not reported Mailing City: WASHINGTON

Mailing State: DC
Mailing Zip: 20024
Mailing Zip4: Not reported
Mailing Country: USA

Mailing Phone: Not reported

Document ID: Not reported Manifest Status: Not reported Trans1 State ID: NJD080631369 Trans2 State ID: NJD071629976 Generator Ship Date: 2008-01-22 Trans1 Recv Date: 2008-01-22 Trans2 Recy Date: 2008-01-29 TSD Site Recv Date: 2008-02-11 Part A Recv Date: Not reported Not reported Part B Recv Date: DCR000500140 Generator EPA ID: Trans1 EPA ID: Not reported Trans2 EPA ID: Not reported NYD049836679 TSDF ID: Waste Code: Not reported Quantity: 400.0

Number of Containers: 1.0

Units:

Container Type: DM - Metal drums, barrels

Handling Method: T Chemical, physical, or biological treatment.

P - Pounds

Specific Gravity: 1.0 Year: 2008

Manifest Tracking Num: 000152567VES

Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N

Manifest Ref Num: Not reported Alt Fac RCRA Id: Not reported

Direction Distance

Elevation Site Database(s) EPA ID Number

# POTOMAC ELECT POWER CO/BUZZARD PT STATIO (Continued)

S111445484

**EDR ID Number** 

Alt Fac Sign Date: Not reported Mgmt Method Type Code: H132

Document ID: NYB9481347 Manifest Status: Not reported Trans1 State ID: NJD080631369 Trans2 State ID: Not reported Generator Ship Date: 12/03/2001 Trans1 Recv Date: 12/03/2001 Trans2 Recv Date: Not reported 12/11/2001 TSD Site Recv Date: Part A Recv Date: Not reported Part B Recv Date: Not reported DCR000500140 Generator EPA ID: Trans1 EPA ID: NYD049836679 Trans2 EPA ID: Not reported TSDF ID: 321146459

Waste Code: D008 - LEAD 5.0 MG/L TCLP

Quantity: 00390
Units: P - Pounds
Number of Containers: 001

Container Type: DM - Metal drums, barrels

Handling Method: L Landfill.
Specific Gravity: 01.00
Year: 2001

Document ID: Not reported Manifest Status: Not reported Trans1 State ID: NJD080631369 Trans2 State ID: NJD071629976 Generator Ship Date: 2008-01-22 Trans1 Recv Date: 2008-01-22 2008-01-29 Trans2 Recv Date: TSD Site Recv Date: 2008-02-11 Part A Recv Date: Not reported Part B Recv Date: Not reported DCR000500140 Generator EPA ID: Trans1 EPA ID: Not reported Trans2 EPA ID: Not reported TSDF ID: NYD049836679 Waste Code: Not reported Quantity: 400.0 P - Pounds Units:

Number of Containers: 1.0

Container Type: DM - Metal drums, barrels

Handling Method: T Chemical, physical, or biological treatment.

Specific Gravity: 1.0 Year: 2008

Manifest Tracking Num: 000152567VES

Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N

Direction Distance

**EDR ID Number** Elevation Site Database(s) **EPA ID Number** 

#### POTOMAC ELECT POWER CO/BUZZARD PT STATIO (Continued)

S111445484

Discr Full Reject Ind: Ν

Manifest Ref Num: Not reported Alt Fac RCRA Id: Not reported Alt Fac Sign Date: Not reported Mgmt Method Type Code: H132

Document ID: Not reported Manifest Status: Not reported Trans1 State ID: NJD080631369 Trans2 State ID: NJD071629976 2008-01-22 Generator Ship Date: Trans1 Recv Date: 2008-01-22 Trans2 Recv Date: 2008-01-29 TSD Site Recv Date: 2008-02-11 Part A Recv Date: Not reported Part B Recv Date: Not reported DCR000500140 Generator EPA ID: Trans1 EPA ID: Not reported Trans2 EPA ID: Not reported TSDF ID: NYD049836679 Waste Code: Not reported Quantity: 400.0 Units: P - Pounds

Number of Containers: 1.0

Container Type: DM - Metal drums, barrels

Handling Method: T Chemical, physical, or biological treatment.

Specific Gravity: 1.0 2008 Year:

Manifest Tracking Num: 000152567VES

Import Ind: N **Export Ind:** Ν Discr Quantity Ind: Ν Discr Type Ind: Ν Discr Residue Ind: Ν Discr Partial Reject Ind: Ν Discr Full Reject Ind: Ν

Manifest Ref Num: Not reported Alt Fac RCRA Id: Not reported Not reported Alt Fac Sign Date: Mgmt Method Type Code: H132

**CAMPBELL S GARAGE** 1327 S CAPITOL ST SE WASHINGTON, DC

1/8-1/4 0.167 mi.

L65

NNE

881 ft. Site 9 of 10 in cluster L

**EDR Historical Auto Stations:** Relative:

CAMPBELL S AUTO SERVICE Name: Higher

Year:

Actual: Type: **AUTOMOBILE REPAIRING** 

28 ft.

Name: **CAMPBELL S GARAGE** 

Year:

AUTOMOBILE REPAIRING Type:

1009003453

N/A

**EDR US Hist Auto Stat** 

Direction Distance

Elevation Site Database(s) EPA ID Number

M66 DC BROWNFIELDS S108931552

South 100 V STREET, SW N/A

1/8-1/4 WASHINGTON, DC

0.168 mi.

885 ft. Site 2 of 2 in cluster M

Relative: BROWNFIELD:

Lower PB ID: PBF2003-0082 Ownership: Private

Actual: Size (sf): Not reported
9 ft. Phase I: unknown
Phase II: unknown

Phase II: unknown
Lot: N
Square: Unknown

Latitude/Longitude: 38.86461519 / -77.01220805

Notes: WS: Other

SSW 0200 V STREET, SW 1/8-1/4 WASHINGTON, DC

0.168 mi.

886 ft. Site 1 of 4 in cluster N

Relative: BROWNFIELD:

 Lower
 PB ID:
 PBF2003-0081

 Ownership:
 Private

 Actual:
 Size (sf):
 16000

 9 ft.
 Phase I:
 unknown

 Phase II:
 unknown

 Lot:
 0001

 Square:
 0612

Latitude/Longitude: 38.86462529 / -77.01320834

Notes: WS: Other

 N68
 NPS - JAMES CREEK MARINA
 DC LUST
 \$104918563

 SSW
 200 V STREET, SW
 N/A

1/8-1/4 WASHINGTON, DC

0.168 mi.

886 ft. Site 2 of 4 in cluster N

Relative: LUST:

 Lower
 Facility ID:
 2-000028

 Facility Type:
 Federal

 Actual:
 Facility Status:
 Closed

9 ft. Product: Gasoline, Diesel Notification Date: 9/17/1992

Ward: 6
Media Of Contamination: Soil/GW
Entry Date: 9/17/1992
Lust Number: 92093

Direction Distance

Elevation Site Database(s) **EPA ID Number** 

**N69 JAMES CREEK MARINA** DC UST U002108109 N/A

SSW 200 V ST SW

1/8-1/4 WASHINGTON, DC 20024

0.168 mi.

886 ft. Site 3 of 4 in cluster N

UST: Relative:

Facility ID: 2000028 Lower Facility Description: False

Actual: NATIONAL CAPITAL PARKS EAST Owner:

9 ft.

Tank ID:

Tank Status: **Permanently Out of Use** 

Tank Capacity: 2000 Substance: Gasoline

Tank ID:

Tank Status: **Currently in Use** 

Tank Capacity: 10000 Substance: Gasoline

Tank ID:

**Tank Status: Currently in Use** 

Tank Capacity: 10000 Substance: Diesel

N70 **US COAST GUARD HSC-K** RCRA-SQG 1009216733 SSW 2100 SECOND STREET SW PA MANIFEST DCR000500629

1/8-1/4 0.169 mi.

892 ft. Site 4 of 4 in cluster N

RCRA-SQG: Relative:

Date form received by agency: 01/26/2006 Lower

WASHINGTON, DC 20593

Facility name: US COAST GUARD HSC-K Actual: Facility address: 2100 SECOND STREET SW

9 ft. **ROOM 732** 

WASHINGTON, DC 20593

DCR000500629 EPA ID: SECOND STREET SW Mailing address:

**ROOM 732** 

WASHINGTON, DC 20593 Contact: PATRICIA A GOLDEN

Contact address: SECOND STREET SW ROOM 732

WASHINGTON, DC 20593

Contact country: US

202-267-0540 Contact telephone:

Contact email: PGOLDEN@COMDT.USCG.MIL

EPA Region: 03 Land type: Federal

Classification: Small Small Quantity Generator

Handler: generates more than 100 and less than 1000 kg of hazardous Description:

waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of

hazardous waste at any time

Direction Distance Elevation

Site Database(s) EPA ID Number

## **US COAST GUARD HSC-K (Continued)**

1009216733

**EDR ID Number** 

Owner/Operator Summary:

Owner/operator name: USCG HQ HEALTH SERVICES DIVISION

Owner/operator address: Not reported

Not reported

Owner/operator country: US

Owner/operator telephone: Not reported Legal status: Federal Owner/Operator Type: Operator Owner/Op start date: 02/10/2004 Owner/Op end date: Not reported

Owner/operator name: TRANSPOINT BUILDING COMPANY

Owner/operator address: Not reported Not reported

Owner/operator country: US

Owner/operator telephone: Not reported Legal status: Federal Owner/Operator Type: Owner Owner/Op start date: 02/10/2004 Owner/Op end date: Not reported

#### Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: No Transporter of hazardous waste: No Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: No Furnace exemption: No Used oil fuel burner: No Used oil processor: No User oil refiner: No Used oil fuel marketer to burner: No Used oil Specification marketer: No Used oil transfer facility: No Used oil transporter: No

#### Hazardous Waste Summary:

Waste code: D008 Waste name: LEAD

Waste code: D011
Waste name: SILVER

# Facility Has Received Notices of Violations:

Regulation violated: Not reported

Area of violation: Generators - Records/Reporting

Date violation determined: 07/24/2008
Date achieved compliance: 03/26/2009
Violation lead agency: State
Enforcement action: Not reported
Enf. disposition status: Not reported
Enf. disp. status date: Not reported

Direction Distance

Elevation Site Database(s) EPA ID Number

# US COAST GUARD HSC-K (Continued)

1009216733

**EDR ID Number** 

Enforcement lead agency: Not reported Proposed penalty amount: Not reported Final penalty amount: Not reported Paid penalty amount: Not reported

**Evaluation Action Summary:** 

Evaluation date: 01/11/2013

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation:
Date achieved compliance:
Evaluation lead agency:
Not reported
State

Evaluation date: 08/04/2010

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation:

Date achieved compliance:

Evaluation lead agency:

Not reported

EPA

Evaluation date: 07/24/2008

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: Generators - Records/Reporting

Date achieved compliance: 03/26/2009 Evaluation lead agency: State

PA MANIFEST:

Year: 2006 Manifest Number: PAH199091

Manifest Type:

DCR000500629 Generator EPA Id: 05/19/2006 Generator Date: Mailing Address: Not reported Not reported Mailing City, St, Zip: Contact Name: Not reported Contact Phone: Not reported TSD Epa Id: PAD067098822 TSD Date: Not reported TSD Facility Name: CYCLE CHEM INC TSD Facility Address: 550 INDUSTRIAL DRIVE

TSD Facility City: LEWISBERRY

TSD Facility State: PA

Facility Telephone: 202-267-0540

Page Number: 1
Line Number: 1
Waste Number: D011
Container Number: 1

Container Type: Fiberboard or plastic drums, barrels, kegs

Waste Quantity: 5

Unit: Gallons (liquids only)

Handling Code: Not reported TSP EPA Id: Not reported Date TSP Sig: Not reported

Year: 2006 Manifest Number: PAH199091 Manifest Type: T

Generator EPA Id: DCR000500629 Generator Date: 05/19/2006

Direction Distance

**EDR ID Number** Elevation Site Database(s) **EPA ID Number** 

## **US COAST GUARD HSC-K (Continued)**

1009216733

Mailing Address: Not reported Not reported Mailing City, St, Zip: Contact Name: Not reported Contact Phone: Not reported PAD067098822 TSD Epa Id: TSD Date: Not reported TSD Facility Name: CYCLE CHEM INC 550 INDUSTRIAL DRIVE TSD Facility Address:

TSD Facility City: **LEWISBERRY** 

TSD Facility State: PΑ

202-267-0540 Facility Telephone:

Page Number: Line Number: 3 Waste Number: NONE Container Number:

Container Type: Fiberboard or plastic drums, barrels, kegs

Waste Quantity:

Unit: Gallons (liquids only)

Handling Code: Not reported Not reported TSP EPA Id: Date TSP Sig: Not reported

2006 Year: Manifest Number: PAH199091

Manifest Type:

DCR000500629 Generator EPA Id: Generator Date: 05/19/2006 Mailing Address: Not reported Mailing City, St, Zip: Not reported Contact Name: Not reported Contact Phone: Not reported TSD Epa Id: PAD067098822 TSD Date: Not reported TSD Facility Name: CYCLE CHEM INC 550 INDUSTRIAL DRIVE TSD Facility Address:

TSD Facility City: **LEWISBERRY** 

TSD Facility State: PΑ

202-267-0540 Facility Telephone:

Page Number: Line Number: 2 D008 Waste Number: Container Number:

Container Type: Fiberboard or plastic drums, barrels, kegs

Waste Quantity: Unit: Pounds Handling Code: Not reported TSP EPA Id: Not reported Date TSP Sig: Not reported

Direction Distance

Elevation Site Database(s) EPA ID Number

O71 DC MATERIALS CO./ FLORIDA ROCKS DC LUST U003294418
NE 25 POTOMAC AVE, SE N/A

NE 25 POTOMAC AVE, SE 1/8-1/4 WASHINGTON, DC

0.173 mi.

Actual:

914 ft. Site 1 of 2 in cluster O

Relative: LUST:

Lower Facility ID: 2-000271

Facility Type: Other Facility Status: Open

9 ft. Product: Heating Oil, Diesel

Notification Date: 8/23/1995
Ward: 6
Media Of Contamination: Soil
Entry Date: 8/23/1995
Lust Number: 95078

 O72
 D.C. MATERIALS CO.
 DC UST
 U003763728

 NE
 25 POTOMAC AV SE
 N/A

1/8-1/4 WASHINGTON, DC 20003

0.173 mi.

914 ft. Site 2 of 2 in cluster O

Relative: UST:

Lower Facility ID: 2000271

Facility Description: False

Actual: Owner: DC MATERIALS CO.

9 ft.

Tank ID: 1

Tank Status: Permanently Out of Use

Tank Capacity: 12000 Substance: Diesel

Tank ID: 2

Tank Status: Permanently Out of Use

Tank Capacity: 5000 Substance: Diesel

L73 1430 P STREET WAREHOUSE RCRA NonGen / NLR 1007879325

NNE 1430 SOUTH CAPITOL STREET SE 1/8-1/4 WASHINGTON, DC 20003

0.178 mi.

940 ft. Site 10 of 10 in cluster L

Relative: RCRA NonGen / NLR:

Higher Date form received by agency: 03/04/2008

Facility name: 1430 P STREET WAREHOUSE

Actual: Facility address: 1430 SOUTH CAPITOL STREET SE

29 ft. WASHINGTON, DC 20003

EPA ID: DCR000500462

Mailing address: SOUTH CAPITOL STREET SE

AOC - US CAPITOL BLDG WASHINGTON, DC 20515

Contact: EDDY E JOSEPH

Contact address: SOUTH CAPITAL STREET SE AOC - US CAPITOL BLDG

WASHINGTON, DC 20515

Contact country: US

DCR000500462

Direction Distance

Elevation Site Database(s) EPA ID Number

# 1430 P STREET WAREHOUSE (Continued)

1007879325

**EDR ID Number** 

Contact telephone: 202-226-4791

Contact email: EJOSEPH@AOC.GOV

EPA Region: 03

Classification: Non-Generator

Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: ARCHITECT OF THE CAPITOL

Owner/operator address: US CAPITOL BLDG

WASHINGTON, DC 20515

Owner/operator country: US

Owner/operator telephone: Not reported Legal status: Private Owner/Operator Type: Operator Owner/Op start date: 10/19/1983 Owner/Op end date: Not reported

Owner/operator name: GUEST SERVICES INC
Owner/operator address: 3055 PROSPERITY AVENUE

FAIRFAX, VA 22031

Owner/operator country: US

Owner/operator telephone: Not reported Legal status: Private Owner/Operator Type: Owner Owner/Op start date: 10/19/1983 Owner/Op end date: Not reported

#### Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: No Transporter of hazardous waste: No Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: No Furnace exemption: No Used oil fuel burner: No Used oil processor: No User oil refiner: No Used oil fuel marketer to burner: No Used oil Specification marketer: No Used oil transfer facility: No Used oil transporter: No

# Universal Waste Summary:

Waste type: Batteries
Accumulated waste on-site: Yes

Generated waste on-site: Not reported

Waste type: Lamps Accumulated waste on-site: Yes

Generated waste on-site: Not reported

#### **Historical Generators:**

Date form received by agency: 03/04/2008

Direction Distance

**EDR ID Number** Elevation Site Database(s) **EPA ID Number** 

1430 P STREET WAREHOUSE (Continued)

1007879325

Facility name: 1430 P STREET WAREHOUSE Classification: Not a generator, verified

Date form received by agency: 12/13/2004

Facility name: 1430 P STREET WAREHOUSE

Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

UNKNOWN P74 DC HIST UST S110338186 N/A

NW 321 P ST SW 1/8-1/4 WASHINGTON, DC

0.187 mi.

986 ft. Site 1 of 2 in cluster P

HIST UST: Relative:

Facility Id: 2005155*001 Lower Confirm Tank/Owner Address Found:Not reported

Actual: Confirn Tank/No Owner Found: Not reported 13 ft. Owner Found/No Tank: Not reported

No Owner/No Tank: Not reported

Address Not Found: yes

Ltr Edc: Not reported Tank Status: UNK Tank Capacity: Not reported

Product: unk

75 DC PUBLIC SCHOOL SYSTEM DC UST U002109496 N/A

North **50 O ST SW** 

1/8-1/4 WASHINGTON, DC 20024

0.189 mi. 996 ft.

UST: Relative:

Facility ID: 2005107 Higher

Facility Description: False

Actual: OFF OF PUBLIC EDUCATION FACILITIES MODERNIZATION Owner:

21 ft.

Tank ID:

Tank Status: **Currently in Use** 

Tank Capacity: 15000 Substance: Heating Oil

Q76 **UNKNOWN** DC HIST UST \$110337749

NNE 1400 S CAPITOL ST SE 1/8-1/4 WASHINGTON, DC

0.192 mi.

1013 ft. Site 1 of 8 in cluster Q

HIST UST: Relative:

2004776*001 Facility Id: Higher Confirm Tank/Owner Address Found:Not reported

Actual: Confirn Tank/No Owner Found: yes

29 ft. Owner Found/No Tank: Not reported

No Owner/No Tank: Not reported Address Not Found: Not reported N/A

Direction Distance

**EDR ID Number** Elevation Site Database(s) **EPA ID Number** 

**UNKNOWN** (Continued) S110337749

Ltr Edc: Not reported Tank Status: UNK Tank Capacity: Not reported

Product: unk

R77 **FORMER DISTRICT PAVING - ASPHALT** DC UST U002108225 N/A

ΝE **60 P ST SE** 

1/8-1/4 WASHINGTON, DC 20003

0.193 mi.

1021 ft. Site 1 of 3 in cluster R

UST: Relative:

Lower Facility ID: 2000310 Facility Description: False

Actual: **ROUBIN ASSOCIATES** Owner:

17 ft.

Tank ID:

Tank Status: **Permanently Out of Use** 

Tank Capacity: 2000 Substance: Gasoline

Tank ID: 2

Tank Status: **Permanently Out of Use** 

Tank Capacity: 2000 Substance: Diesel

Tank ID: 3

Tank Status: **Permanently Out of Use** 

Tank Capacity: 10000 Substance: Heating Oil

Tank ID:

Tank Status: **Permanently Out of Use** 

Tank Capacity: 10000 Heating Oil Substance:

Tank ID:

Tank Status: **Permanently Out of Use** 

Tank Capacity: 15000 Substance: Other

Tank ID:

Tank Status: **Permanently Out of Use** 

Tank Capacity: 1000 Substance: Gasoline

Tank ID:

**Tank Status: Permanently Out of Use** 

Tank Capacity: 2000 Substance: Gasoline

Direction
Distance
Elevation

stance EDR ID Number evation Site Database(s) EPA ID Number

FORMER DISTRICT PAVING - ASPHALT (Continued)

Tank ID: 8

Tank Status: Permanently Out of Use

Tank Capacity: 7000 Substance: Heating Oil

Tank ID:

Tank Status: Permanently Out of Use

Tank Capacity: 10000 Substance: Gasoline

Tank ID: 10

Tank Status: Permanently Out of Use

Tank Capacity: 10000 Substance: Other

Tank ID: 11

Tank Status: Permanently Out of Use

Tank Capacity: 10000 Substance: Used Oil

Tank ID: 12

Tank Status: Permanently Out of Use

Tank Capacity: 10000 Substance: Heating Oil

Tank ID: 13

Tank Status: Permanently Out of Use

Tank Capacity: 10000 Substance: Other

Tank ID: 14

Tank Status: Permanently Out of Use

Tank Capacity: 5000 Substance: Other

Tank ID: 15

Tank Status: Permanently Out of Use

Tank Capacity: 5000 Substance: Heating Oil

Tank ID: 16

Tank Status: Permanently Out of Use

Tank Capacity: 5000 Substance: Heating Oil

Tank ID: 17

Tank Status: Permanently Out of Use

Tank Capacity: 5000

U002108225

Direction Distance

**EDR ID Number** Elevation Site Database(s) **EPA ID Number** 

#### FORMER DISTRICT PAVING - ASPHALT (Continued)

U002108225

Substance: Used Oil

Tank ID: 18

Tank Status: **Permanently Out of Use** 

Tank Capacity: 5000 Substance: Heating Oil

Tank ID: 19

Tank Status: **Permanently Out of Use** 

5000 Tank Capacity: Substance: Heating Oil

**R78** DISTRICT PAVING CORPORATION RCRA NonGen / NLR 1000419754 **FINDS** DCD116197286

NE **60 P STREET SE** 

1/8-1/4 WASHINGTON, DC 20003

0.193 mi.

1021 ft. Site 2 of 3 in cluster R

RCRA NonGen / NLR: Relative:

Date form received by agency: 02/01/1996 Lower

DISTRICT PAVING CORPORATION Facility name:

Actual: Facility address: 60 P STREET SE 17 ft.

WASHINGTON, DC 20003 EPA ID:

DCD116197286

Mailing address: P STREET SE WASHINGTON, DC 20003

Contact: ROY BURKE

Contact address: P STREET SE

WASHINGTON, DC 20003

Contact country: US

Contact telephone: 202-529-5100 Contact email: Not reported EPA Region: 03 Land type: Private Classification: Non-Generator

Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: **OPERNAME** Owner/operator address: **OPERSTREET** 

OPERCITY, AK 99999

Owner/operator country: Not reported Owner/operator telephone: (215) 555-1212 Legal status: Private Owner/Operator Type: Operator Owner/Op start date: Not reported Owner/Op end date: Not reported

ROUBIN ANGEL Owner/operator name:

LEE HIGHWAY SUITE 700 Owner/operator address:

FAIRFAX, VA 22030

Owner/operator country: US

Owner/operator telephone: 703-573-9350 Legal status: Private

Owner/Operator Type: Owner

Direction Distance

**EDR ID Number** Elevation Site Database(s) **EPA ID Number** 

## **DISTRICT PAVING CORPORATION (Continued)**

1000419754

Owner/Op start date: 02/01/1996 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: No Transporter of hazardous waste: No Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: No Furnace exemption: Nο Used oil fuel burner: No Used oil processor: No User oil refiner: No Used oil fuel marketer to burner: No Used oil Specification marketer: No Used oil transfer facility: No Used oil transporter: No

#### Historical Generators:

Date form received by agency: 08/26/1986

Facility name: DISTRICT PAVING CORPORATION

Site name: ROUBIN JANCIRO INC Classification: Not a generator, verified

Hazardous Waste Summary:

Waste code: F002

Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE,

METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE,

CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND

1,1,2-TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE LISTED IN F001, F004, OR F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND

SPENT SOLVENT MIXTURES.

Facility Has Received Notices of Violations:

Regulation violated: Not reported

Area of violation: Generators - General

Date violation determined: 05/25/1989 Date achieved compliance: 03/02/1990 Violation lead agency: State

Enforcement action: WRITTEN INFORMAL

Enforcement action date: 06/02/1989 Enf. disposition status: Not reported Enf. disp. status date: Not reported Enforcement lead agency: State Proposed penalty amount: Not reported Final penalty amount: Not reported Paid penalty amount: Not reported

Regulation violated: Not reported

Area of violation: Generators - General

Direction Distance

**EDR ID Number** Elevation Site Database(s) **EPA ID Number** 

# **DISTRICT PAVING CORPORATION (Continued)**

1000419754

Date violation determined: 05/25/1989 03/02/1990 Date achieved compliance: Violation lead agency: State Enforcement action: Not reported Enforcement action date: Not reported Not reported Enf. disposition status: Not reported Enf. disp. status date: Not reported Enforcement lead agency: Proposed penalty amount: Not reported Final penalty amount: Not reported Paid penalty amount: Not reported

**Evaluation Action Summary:** 

Evaluation date: 05/25/1989

COMPLIANCE EVALUATION INSPECTION ON-SITE Evaluation:

Area of violation: Generators - General

Date achieved compliance: 03/02/1990

Evaluation lead agency: State

Evaluation date: 07/30/1987

COMPLIANCE EVALUATION INSPECTION ON-SITE Evaluation:

Area of violation: Not reported Date achieved compliance: Not reported Evaluation lead agency: State

FINDS:

Registry ID: 110006183557

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and

corrective action activities required under RCRA.

R79 **VIRGINIA PAVING** DC LUST S103534574 ΝE **60 P STREET, SE** WASHINGTON, DC

1/8-1/4 0.193 mi.

Site 3 of 3 in cluster R 1021 ft.

LUST: Relative:

Facility ID: 2-000310 Lower Facility Type: Other

Actual: Facility Status:

NFA-DCRBCA 17 ft.

Product: Diesel Notification Date: 7/28/1998

Ward: Media Of Contamination: Soil 7/28/1998 Entry Date: Lust Number: 98086

N/A

Direction Distance

Elevation Site Database(s) EPA ID Number

80 SMITH THEO N EDR US Hist Cleaners 1009133769 NW 234 3RD AVE SW EDR US Hist Cleaners N/A

1/8-1/4 WASHINGTON, DC

0.194 mi. 1024 ft.

Relative: EDR Historical Cleaners:

Lower Name: SMITH THEO N

Year: 1926

Actual: Type: DYERS AND CLEANERS

12 ft.

Name: SMITH THEO N

Year: 1931

Type: CLOTHES PRESSERS AND CLEANERS

 P81
 FORT MCNAIR
 CERCLIS
 1000481199

 NW
 350 P STREET SW
 RCRA-SQG
 DC8210021004

 1/8-1/4
 WASHINGTON, DC 20319
 PA MANIFEST

1/8-1/4 0.202 mi.

0.202 ml.

1067 ft. Site 2 of 2 in cluster P

Relative: CERCLIS: Lower Site ID: 0300030

EPA ID: DC8210021004

Actual: Facility County: DISTRICT OF COLUMBIA

13 ft. Short Name: FORT MCNAIR

Congressional District: 01

IFMS ID: Not reported

SMSA Number: 8840

USGC Hydro Unit: 02070010

Federal Facility: Federal Facility

DMNSN Number: 0.00000

Site Orphan Flag: N

RCRA ID: Not reported USGS Quadrangle: Not reported Site Init By Prog: Not reported NFRAP Flag: Not reported Parent ID: Not reported RST Code: Not reported

RST Code: No EPA Region: 03

Classification: Not reported
Site Settings Code: Not reported
NPL Status: Not on the NPL
DMNSN Unit Code: Not reported
RBRAC Code: Not reported
RResp Fed Agency Code: USAR

Non NPL Status: Other Cleanup Activity: State-Lead Cleanup

Non NPL Status Date: 02/07/92 Site Fips Code: 11001 CC Concurrence Date: //

CC Concurrence FY: Not reported Alias EPA ID: Not reported Site FUDS Flag: Not reported

CERCLIS Site Alias Name(s):

Alias ID:

Alias Name: USA FT MCNAIR
Alias Address: 350 P STREET SW

WASHINGTON, DC 20319

**EDR ID Number** 

NY MANIFEST

MAP FINDINGS Map ID Direction

Distance

Elevation Site Database(s) **EPA ID Number** 

#### **FORT MCNAIR (Continued)**

1000481199

**EDR ID Number** 

Alias ID: 3270049 Alias Name: FORT MCNAIR 350 P STREET, S.W. Alias Address: WASHINGTON, DC 20407

Alias Comments: Not reported

**CERCLIS Assessment History:** 

Site Description: Not reported

Action Code: 001

Action: DISCOVERY Date Started: 11 Date Completed: 09/01/80 Priority Level: Not reported SITEWIDE Operable Unit: Primary Responsibility: **EPA Fund-Financed** 

Planning Status: Not reported Urgency Indicator: Not reported Action Anomaly: Not reported

Action Code: 001

Action: PRELIMINARY ASSESSMENT

Date Started: Date Completed: 02/07/92

Low priority for further assessment Priority Level:

Operable Unit: **SITEWIDE** Primary Responsibility: Federal Facilities Planning Status: Not reported Urgency Indicator: Not reported Action Anomaly: Not reported

RCRA-SQG:

Date form received by agency: 02/16/2010

FORT LESLIE J MCNAIR Facility name: Facility address: 4TH & P STREETS SW

WASHINGTON, DC 20319

EPA ID: DC8210021004

Mailing address: STEWART ROAD BLDG 313 RM 4

FORT MYER

**ARLINGTON, VA 222111199** 

Contact: MARK LUCKERS

STEWART ROAD BLDG 313 RM 4 FORT MYER Contact address:

**ARLINGTON, VA 222111199** 

Contact country: US

Contact telephone: 703-696-2012

Contact email: MARK.LUCKERS@US.ARMY.MIL

EPA Region: 03 Land type: Federal

Classification: Small Small Quantity Generator

Description: Handler: generates more than 100 and less than 1000 kg of hazardous

> waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of

hazardous waste at any time

Direction Distance

Elevation Site Database(s) EPA ID Number

FORT MCNAIR (Continued) 1000481199

Owner/Operator Summary:

Owner/operator name: US ARMY
Owner/operator address: Not reported

DC

Owner/operator country: US

Owner/operator telephone: Not reported Legal status: Federal Owner/Operator Type: Operator Owner/Op start date: 01/01/1990 Owner/Op end date: Not reported

Owner/operator name: US DEPT OF DEFENSE

Owner/operator address: Not reported

DC

Owner/operator country: US

Owner/operator telephone: Not reported Legal status: Federal Owner/Operator Type: Owner Owner/Op start date: 01/01/1990 Owner/Op end date: Not reported

#### Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: No Transporter of hazardous waste: No Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: No Furnace exemption: No Used oil fuel burner: No Used oil processor: No User oil refiner: No Used oil fuel marketer to burner: No Used oil Specification marketer: No Used oil transfer facility: No Used oil transporter: No

#### **Historical Generators:**

Date form received by agency: 02/15/2002

Facility name: FORT LESLIE J MCNAIR

Site name: FORT LESLIE J MCNAIR MDW US ARMY

Classification: Small Quantity Generator

Date form received by agency: 02/29/2000

Facility name: FORT LESLIE J MCNAIR

Site name: FORT LESLIE J MCNAIR MDW US ARMY

Classification: Small Quantity Generator

Date form received by agency: 04/09/1985

Facility name: FORT LESLIE J MCNAIR

Site name: FORT LESLIE J MCNAIR MDW US ARMY

Classification: Small Quantity Generator

Hazardous Waste Summary:

Direction Distance

Elevation Site Database(s) EPA ID Number

FORT MCNAIR (Continued) 1000481199

Waste code: D001

Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF

LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT

WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D002

Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS

CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED. THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Waste code: D009
Waste name: MERCURY

Facility Has Received Notices of Violations: Regulation violated: SR - 4203.5

Area of violation: Generators - Records/Reporting

Date violation determined: 03/01/1998
Date achieved compliance: 04/22/1998
Violation lead agency: State

Enforcement action: WRITTEN INFORMAL

Enforcement action date: 03/01/1998
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported

Final penalty amount: Not reported Not reported Not reported Not reported Not reported

**Evaluation Action Summary:** 

Evaluation date: 11/16/2012

Evaluation: NON-FINANCIAL RECORD REVIEW

Area of violation: Not reported Date achieved compliance: Not reported Evaluation lead agency: State

Evaluation date: 01/28/2011

Evaluation: NON-FINANCIAL RECORD REVIEW

Area of violation: Not reported Date achieved compliance: Not reported Evaluation lead agency: State

Evaluation date: 05/27/2010

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: Not reported Date achieved compliance: Not reported Evaluation lead agency: State

Evaluation date: 03/01/1998

Direction Distance

Elevation Site Database(s) EPA ID Number

FORT MCNAIR (Continued) 1000481199

Evaluation: NON-FINANCIAL RECORD REVIEW Area of violation: Generators - Records/Reporting

Date achieved compliance: 04/22/1998 Evaluation lead agency: State

PA MANIFEST:

Year: 2011

Manifest Number: 006955787JJK

Manifest Type: T

Generator EPA Id: DC8210021004 Generator Date: 08/03/2011 Mailing Address: Not reported Mailing City, St, Zip: Not reported Contact Name: Not reported 202-475-1540 Contact Phone: TSD Epa Id: PAD067098822 TSD Date: Not reported CYCLE CHEM INC TSD Facility Name: TSD Facility Address: 550 INDUSTRIAL DRIVE

TSD Facility City: LEWISBERRY

TSD Facility State: PA

Facility Telephone: Not reported

Page Number: 1
Line Number: 2
Waste Number: XXXX
Container Number: 1

Container Type: Fiber or plastic boxes, cartons, cases

Waste Quantity: 400
Unit: Pounds
Handling Code: Not reported
TSP EPA Id: Not reported
Date TSP Sig: Not reported

Year: 2011

Manifest Number: 006955727JJK

Manifest Type:

Generator EPA Id: DC8210021004 07/06/2011 Generator Date: Mailing Address: Not reported Not reported Mailing City, St, Zip: Contact Name: Not reported Contact Phone: 202-475-1540 TSD Epa Id: PAD067098822 TSD Date: Not reported TSD Facility Name: CYCLE CHEM INC TSD Facility Address: 550 INDUSTRIAL DRIVE

TSD Facility City: LEWISBERRY

TSD Facility State: PA

Facility Telephone: Not reported

Page Number: 1 Line Number: 1 Waste Number: D018 Container Number: 1

Container Type: Metal drums, barrels, kegs

Waste Quantity: 90
Unit: Pounds
Handling Code: Not reported
TSP EPA Id: Not reported

Direction Distance Elevation

stance EDR ID Number evation Site Database(s) EPA ID Number

#### **FORT MCNAIR (Continued)**

1000481199

Date TSP Sig: Not reported

Year: 2011

Manifest Number: 006955787JJK

Manifest Type:

Generator EPA Id: DC8210021004 Generator Date: 08/03/2011 Mailing Address: Not reported Mailing City, St, Zip: Not reported Contact Name: Not reported Contact Phone: 202-475-1540 TSD Epa Id: PAD067098822 TSD Date: Not reported TSD Facility Name: CYCLE CHEM INC TSD Facility Address: 550 INDUSTRIAL DRIVE

TSD Facility City: LEWISBERRY

TSD Facility State: PA

Facility Telephone: Not reported

Page Number: 1
Line Number: 4
Waste Number: NONE

Container Number: 1

Container Type: Fiber or plastic boxes, cartons, cases

Waste Quantity: 40
Unit: Pounds
Handling Code: Not reported
TSP EPA Id: Not reported
Date TSP Sig: Not reported

Year: 2011

Manifest Number: 006955727JJK

Manifest Type: T

Generator EPA Id: DC8210021004 07/06/2011 Generator Date: Not reported Mailing Address: Mailing City, St, Zip: Not reported Contact Name: Not reported Contact Phone: 202-475-1540 TSD Epa Id: PAD067098822 TSD Date: Not reported TSD Facility Name: CYCLE CHEM INC TSD Facility Address: 550 INDUSTRIAL DRIVE

TSD Facility City: LEWISBERRY

TSD Facility State: PA

Facility Telephone: Not reported

Page Number: 1
Line Number: 1
Waste Number: D001
Container Number: 1

Container Type: Metal drums, barrels, kegs

Waste Quantity: 90
Unit: Pounds
Handling Code: Not reported
TSP EPA Id: Not reported
Date TSP Sig: Not reported

Year: 2011

Direction Distance Elevation

ation Site Database(s) EPA ID Number

FORT MCNAIR (Continued)

1000481199

**EDR ID Number** 

Manifest Number: 006955727JJK

Manifest Type: T

Generator EPA Id: DC8210021004 Generator Date: 07/06/2011 Mailing Address: Not reported Mailing City, St, Zip: Not reported Contact Name: Not reported Contact Phone: 202-475-1540 TSD Epa Id: PAD067098822 TSD Date: Not reported TSD Facility Name: CYCLE CHEM INC TSD Facility Address: 550 INDUSTRIAL DRIVE

TSD Facility City: LEWISBERRY

TSD Facility State: PA

Facility Telephone: Not reported

Page Number: 1
Line Number: 2
Waste Number: D001
Container Number: 1

Container Type: Fiber or plastic boxes, cartons, cases

Waste Quantity: 610
Unit: Pounds
Handling Code: Not reported
TSP EPA Id: Not reported
Date TSP Sig: Not reported

Year: 2011

Manifest Number: 006955788JJK

Manifest Type: T

Generator EPA Id: DC8210021004 Generator Date: 08/03/2011 Mailing Address: Not reported Mailing City, St, Zip: Not reported Contact Name: Not reported Contact Phone: 202-475-1540 TSD Epa Id: PAD067098822 TSD Date: Not reported TSD Facility Name: CYCLE CHEM INC 550 INDUSTRIAL DRIVE TSD Facility Address:

TSD Facility City: LEWISBERRY

TSD Facility State: PA

Facility Telephone: Not reported

Page Number: 1
Line Number: 3
Waste Number: NONE

Container Number: 3

Container Type: Metal drums, barrels, kegs

Waste Quantity: 800
Unit: Pounds
Handling Code: Not reported
TSP EPA Id: Not reported
Date TSP Sig: Not reported

Year: 2011

Manifest Number: 006955788JJK

Manifest Type:

Generator EPA Id: DC8210021004

Direction
Distance
Flevation

Elevation Site Database(s) EPA ID Number

FORT MCNAIR (Continued)

1000481199

**EDR ID Number** 

Generator Date: 08/03/2011 Mailing Address: Not reported Mailing City, St, Zip: Not reported Contact Name: Not reported Contact Phone: 202-475-1540 TSD Epa Id: PAD067098822 TSD Date: Not reported TSD Facility Name: CYCLE CHEM INC TSD Facility Address: 550 INDUSTRIAL DRIVE

TSD Facility City: LEWISBERRY

TSD Facility State: PA

Facility Telephone: Not reported

Page Number: 1
Line Number: 1
Waste Number: D001
Container Number: 2

Container Type: Metal drums, barrels, kegs

Waste Quantity: 550
Unit: Pounds
Handling Code: Not reported
TSP EPA Id: Not reported
Date TSP Sig: Not reported

Year: 2011

Manifest Number: 006955727JJK

Manifest Type: Generator EPA Id: DC8210021004 Generator Date: 07/06/2011 Mailing Address: Not reported Mailing City, St, Zip: Not reported Contact Name: Not reported Contact Phone: 202-475-1540 TSD Epa Id: PAD067098822 TSD Date: Not reported TSD Facility Name: CYCLE CHEM INC TSD Facility Address: 550 INDUSTRIAL DRIVE

TSD Facility City: LEWISBERRY

TSD Facility State: PA

Facility Telephone: Not reported

Page Number: 1
Line Number: 4
Waste Number: D001
Container Number: 1

Container Type: Fiberboard or plastic drums, barrels, kegs

Waste Quantity: 12
Unit: Pounds
Handling Code: Not reported
TSP EPA Id: Not reported
Date TSP Sig: Not reported

Year: 2011

Manifest Number: 006503257JJK

Manifest Type:

Generator EPA Id: DC8210021004
Generator Date: 02/25/2011
Mailing Address: Not reported
Mailing City,St,Zip: Not reported

Direction Distance

Elevation Site Database(s) EPA ID Number

## FORT MCNAIR (Continued)

1000481199

**EDR ID Number** 

Contact Name: Not reported
Contact Phone: 202-475-1540
TSD Epa Id: PAD067098822
TSD Date: Not reported
TSD Facility Name: CYCLE CHEM INC
TSD Facility Address: 550 INDUSTRIAL DRIVE

TSD Facility City: LEWISBERRY

TSD Facility State: PA

Facility Telephone: Not reported

Page Number: 1
Line Number: 1
Waste Number: D008
Container Number: 1

Container Type: Metal drums, barrels, kegs

Waste Quantity: 200
Unit: Pounds
Handling Code: Not reported
TSP EPA Id: Not reported
Date TSP Sig: Not reported

Year: 2011

Manifest Number: 006955787JJK

Manifest Type: T

Generator EPA Id: DC8210021004 Generator Date: 08/03/2011 Mailing Address: Not reported Mailing City, St, Zip: Not reported Contact Name: Not reported Contact Phone: 202-475-1540 PAD067098822 TSD Epa Id: TSD Date: Not reported TSD Facility Name: CYCLE CHEM INC TSD Facility Address: 550 INDUSTRIAL DRIVE

TSD Facility City: LEWISBERRY

TSD Facility State: PA

Facility Telephone: Not reported

Page Number: 1
Line Number: 1
Waste Number: D001
Container Number: 1

Container Type: Fiber or plastic boxes, cartons, cases

Waste Quantity: 480
Unit: Pounds
Handling Code: Not reported
TSP EPA Id: Not reported
Date TSP Sig: Not reported

Year: 2011

Manifest Number: 006955788JJK

Manifest Type:

Generator EPA Id: DC8210021004
Generator Date: 08/03/2011
Mailing Address: Not reported
Mailing City,St,Zip: Not reported
Contact Name: Not reported
Contact Phone: 202-475-1540
TSD Epa Id: PAD067098822

Direction Distance

Elevation Site Database(s) EPA ID Number

FORT MCNAIR (Continued)

1000481199

**EDR ID Number** 

TSD Date: Not reported
TSD Facility Name: CYCLE CHEM INC
TSD Facility Address: 550 INDUSTRIAL DRIVE

TSD Facility City: LEWISBERRY

TSD Facility State: PA

Facility Telephone: Not reported

Page Number: 1
Line Number: 4
Waste Number: NONE
Container Number: 1

Container Type: Fiberboard or plastic drums, barrels, kegs

Waste Quantity: 3
Unit: Pounds
Handling Code: Not reported
TSP EPA Id: Not reported
Date TSP Sig: Not reported

Year: 2011

Manifest Number: 006955788JJK

Manifest Type: T

Generator EPA Id: DC8210021004 Generator Date: 08/03/2011 Not reported Mailing Address: Mailing City, St, Zip: Not reported Contact Name: Not reported 202-475-1540 Contact Phone: TSD Epa Id: PAD067098822 TSD Date: Not reported TSD Facility Name: CYCLE CHEM INC TSD Facility Address: 550 INDUSTRIAL DRIVE

TSD Facility City: LEWISBERRY

TSD Facility State: PA

Facility Telephone: Not reported

Page Number: 1
Line Number: 2
Waste Number: D002
Container Number: 1

Container Type: Fiberboard or plastic drums, barrels, kegs

Waste Quantity: 50
Unit: Pounds
Handling Code: Not reported
TSP EPA Id: Not reported
Date TSP Sig: Not reported

Year: 2011

Manifest Number: 006955787JJK

Manifest Type: T

Generator EPA Id: DC8210021004 Generator Date: 08/03/2011 Mailing Address: Not reported Mailing City, St, Zip: Not reported Contact Name: Not reported Contact Phone: 202-475-1540 TSD Epa Id: PAD067098822 TSD Date: Not reported TSD Facility Name: CYCLE CHEM INC TSD Facility Address: 550 INDUSTRIAL DRIVE

Direction
Distance

Elevation Site Database(s) EPA ID Number

FORT MCNAIR (Continued)

1000481199

**EDR ID Number** 

TSD Facility City: LEWISBERRY TSD Facility State: PA

Facility Telephone: Not reported

Page Number: 1
Line Number: 3
Waste Number: NONE
Container Number: 1

Container Type: Wooden boxes, cartons, cases

Waste Quantity: 310
Unit: Pounds
Handling Code: Not reported
TSP EPA Id: Not reported
Date TSP Sig: Not reported

Year: 2011

Manifest Number: 006955727JJK

Manifest Type: T

Generator EPA Id: DC8210021004 Generator Date: 07/06/2011 Mailing Address: Not reported Mailing City, St, Zip: Not reported Contact Name: Not reported Contact Phone: 202-475-1540 TSD Epa Id: PAD067098822 TSD Date: Not reported TSD Facility Name: CYCLE CHEM INC TSD Facility Address: 550 INDUSTRIAL DRIVE

TSD Facility City: LEWISBERRY

TSD Facility State: PA

Facility Telephone: Not reported

Page Number: 1
Line Number: 3
Waste Number: D001
Container Number: 1

Container Type: Fiberboard or plastic drums, barrels, kegs

Waste Quantity: 40
Unit: Pounds
Handling Code: Not reported
TSP EPA Id: Not reported
Date TSP Sig: Not reported

Year: 2008

Manifest Number: 000839960JJK

Manifest Type: T

Generator EPA Id: DC8210021004 02/05/2008 Generator Date: Mailing Address: Not reported Mailing City, St, Zip: Not reported Contact Name: Not reported Contact Phone: 202-475-1540 PAD067098822 TSD Epa Id: TSD Date: Not reported TSD Facility Name: CYCLE CHEM INC TSD Facility Address: 550 INDUSTRIAL DRIVE

TSD Facility City: LEWISBERRY

TSD Facility State: PA

Facility Telephone: Not reported

Direction Distance

**EDR ID Number** Elevation Site Database(s) **EPA ID Number** 

**FORT MCNAIR (Continued)** 

1000481199

Page Number: 1 Line Number: 4 D001 Waste Number: Container Number:

Container Type: Fiberboard or plastic drums, barrels, kegs

Waste Quantity: Unit: Pounds Handling Code: Not reported TSP EPA Id: Not reported Date TSP Sig: Not reported

2008 Year:

000839960JJK Manifest Number:

Manifest Type:

Generator EPA Id: DC8210021004 Generator Date: 02/05/2008 Mailing Address: Not reported Mailing City,St,Zip: Not reported Contact Name: Not reported Contact Phone: 202-475-1540 TSD Epa Id: PAD067098822 TSD Date: Not reported TSD Facility Name: CYCLE CHEM INC TSD Facility Address: 550 INDUSTRIAL DRIVE

TSD Facility City: **LEWISBERRY** 

TSD Facility State: PΑ

Facility Telephone: Not reported

Page Number: Line Number: D001 Waste Number: Container Number:

Container Type: Fiberboard or plastic drums, barrels, kegs

Waste Quantity: Unit: Pounds Handling Code: Not reported TSP EPA Id: Not reported Date TSP Sig: Not reported

Year: 2008

000839960JJK Manifest Number:

Manifest Type: Т

Generator EPA Id: DC8210021004 Generator Date: 02/05/2008 Mailing Address: Not reported Mailing City, St, Zip: Not reported Contact Name: Not reported Contact Phone: 202-475-1540 PAD067098822 TSD Epa Id: TSD Date: Not reported TSD Facility Name: CYCLE CHEM INC TSD Facility Address: 550 INDUSTRIAL DRIVE

TSD Facility City: **LEWISBERRY** 

TSD Facility State: PΑ

Facility Telephone: Not reported

Page Number: Line Number: 2 Waste Number: D002

Direction Distance

Elevation Site Database(s) EPA ID Number

FORT MCNAIR (Continued)

1000481199

**EDR ID Number** 

Container Number: 1

Container Type: Fiberboard or plastic drums, barrels, kegs

Waste Quantity: 5
Unit: Pounds
Handling Code: Not reported
TSP EPA Id: Not reported
Date TSP Sig: Not reported

Year: 2008

Manifest Number: 000839960JJK

Manifest Type: T

Generator EPA Id: DC8210021004 02/05/2008 Generator Date: Mailing Address: Not reported Mailing City, St, Zip: Not reported Contact Name: Not reported Contact Phone: 202-475-1540 TSD Epa Id: PAD067098822 TSD Date: Not reported TSD Facility Name: CYCLE CHEM INC TSD Facility Address: 550 INDUSTRIAL DRIVE

TSD Facility City: LEWISBERRY

TSD Facility State: PA

Facility Telephone: Not reported

Page Number: 1
Line Number: 3
Waste Number: D001
Container Number: 1

Container Type: Fiberboard or plastic drums, barrels, kegs

Waste Quantity: 150
Unit: Pounds
Handling Code: Not reported
TSP EPA Id: Not reported
Date TSP Sig: Not reported

Year: 2006

Manifest Number: 000553685JJK

Manifest Type: T

Generator EPA Id: DC8210021004 Generator Date: 11/20/2006 Mailing Address: Not reported Mailing City, St, Zip: Not reported Contact Name: Not reported Contact Phone: Not reported TSD Epa Id: PAD010154045 TSD Date: Not reported

TSD Facility Name: ENVIRITE OF PENNSYLVANIA INC

TSD Facility Address: 730 VOGELSONG ROAD

TSD Facility City: YORK
TSD Facility State: PA

Facility Telephone: 202-475-1540

Page Number: 1
Line Number: 1
Waste Number: D008
Container Number: 1

Container Type: Dump truck

Waste Quantity: 22

Direction Distance

**EDR ID Number** Elevation Site Database(s) **EPA ID Number** 

# **FORT MCNAIR (Continued)**

1000481199

Unit: Tons (2000 Pounds)

Handling Code: Not reported TSP EPA Id: Not reported Date TSP Sig: Not reported

Year: 2006

Manifest Number: 000553677JJK

Manifest Type:

Generator EPA Id: DC8210021004 Generator Date: 11/14/2006 Mailing Address: Not reported Mailing City, St, Zip: Not reported Contact Name: Not reported Contact Phone: Not reported PAD010154045 TSD Epa Id: TSD Date: Not reported

TSD Facility Name: **ENVIRITE OF PENNSYLVANIA INC** 

TSD Facility Address: 730 VOGELSONG ROAD

TSD Facility City: YORK TSD Facility State: PΑ

202-475-1540 Facility Telephone:

Page Number: 1 Line Number: Waste Number: D008 Container Number:

Container Type: Dump truck

Waste Quantity: 22

Unit: Tons (2000 Pounds) Handling Code: Not reported TSP EPA Id: Not reported Date TSP Sig: Not reported

> Click this hyperlink while viewing on your computer to access 17 additional PA MANIFEST: record(s) in the EDR Site Report.

NY MANIFEST:

DC8210021004 EPA ID:

Country: USA

UNITED STATES MILITARY-MILITARY DISTRICT Mailing Name: Mailing Contact: UNITED STATES MILITARY-MILITARY DISTRICT

Mailing Address: OF WA-DRMO-BLDG 2517-STOP 566

Mailing Address 2: Not reported Mailing City: FORT BELVOIR

Mailing State: VA 22060 Mailing Zip: Mailing Zip4: Not reported Mailing Country: USA

Mailing Phone: 703-664-6331

Document ID: NYA4110502 Manifest Status: Completed copy Trans1 State ID: P101628(I Trans2 State ID: TM21813PA 870612 Generator Ship Date: Trans1 Recv Date: 870612 Trans2 Recv Date: 870612

Direction Distance Elevation

evation Site Database(s) EPA ID Number

#### **FORT MCNAIR (Continued)**

1000481199

**EDR ID Number** 

 TSD Site Recv Date:
 870615

 Part A Recv Date:
 870625

 Part B Recv Date:
 870623

 Generator EPA ID:
 DC8210021004

 Trans1 EPA ID:
 ILD099202681

 Trans2 EPA ID:
 PAD064035819

 TSDF ID:
 NYD049836679

Waste Code: F002 - HALO SOLV + STILL BOTTOMS FM REC OF SOLV

Quantity: 00015

Units: G - Gallons (liquids only)* (8.3 pounds)

Number of Containers: 001

Container Type: DM - Metal drums, barrels

Handling Method: B Incineration, heat recovery, burning.

Specific Gravity: 100 Year: 87

Document ID: NYB1577304 Manifest Status: Completed copy 11277PNY Trans1 State ID: Trans2 State ID: Not reported Generator Ship Date: 920527 Trans1 Recy Date: 920527 Trans2 Recv Date: Not reported TSD Site Recv Date: 920529 Part A Recv Date: Not reported Part B Recv Date: 920615 Generator EPA ID: DC8210021004 NYD980769947 Trans1 EPA ID: Trans2 EPA ID: Not reported TSDF ID: NYD049836679

Waste Code: B007 - OTHER MISCELLANEOUS PCB WASTES

Quantity: 01234

Units: K - Kilograms (2.2 pounds)

Number of Containers: 009

Container Type: DM - Metal drums, barrels

Handling Method: L Landfill.
Specific Gravity: 100
Year: 92

Document ID: NYB9705366 Manifest Status: Not reported Trans1 State ID: PAD146714878 Not reported Trans2 State ID: 09/30/2002 Generator Ship Date: Trans1 Recv Date: 09/30/2002 Trans2 Recv Date: Not reported TSD Site Recv Date: 10/01/2002 Part A Recv Date: Not reported Part B Recv Date: Not reported Generator EPA ID: DC8210021004 NYD049836679 Trans1 EPA ID: Trans2 EPA ID: Not reported TSDF ID: XW49139PA

Waste Code: D008 - LEAD 5.0 MG/L TCLP

Quantity: 06200

Direction Distance

Elevation Site Database(s) EPA ID Number

FORT MCNAIR (Continued) 1000481199

Units: P - Pounds

Number of Containers: 001

Container Type: CM - Metal boxes, cases, roll-offs

Handling Method: L Landfill.
Specific Gravity: 01.00
Year: 2002

Document ID: NYB9705375 Manifest Status: Not reported Trans1 State ID: PAD146714878 Not reported Trans2 State ID: 09/30/2002 Generator Ship Date: Trans1 Recv Date: 09/30/2002 Trans2 Recv Date: Not reported TSD Site Recv Date: 10/01/2002 Part A Recv Date: Not reported Part B Recv Date: Not reported Generator EPA ID: DC8210021004 NYD049836679 Trans1 EPA ID: Trans2 EPA ID: Not reported TSDF ID: XT40231PA

Waste Code: D008 - LEAD 5.0 MG/L TCLP

Quantity: 05980 Units: P - Pounds

Number of Containers: 001

Container Type: CM - Metal boxes, cases, roll-offs

Handling Method: L Landfill.
Specific Gravity: 01.00
Year: 2002

Q82 EDR US Hist Auto Stat 1015211638

NNE 1345 S CAPITOL ST SW 1/8-1/4 WASHINGTON, DC 20003

0.221 mi.

1167 ft. Site 2 of 8 in cluster Q

Relative: EDR Historical Auto Stations:

Higher Name: CALL CARL EXXON SERVICE CNTR

Year: 2004

Actual: Address: 1345 S CAPITOL ST SW

29 ft.

83 SYPHAX SCHOOL DC UST U003865158 NNE 1360 HALF ST SW N/A

1/8-1/4 WASHINGTON, DC 20024

0.228 mi. 1203 ft.

Relative: UST:

Higher Facility ID: 9000534
Facility Description: False
Actual: Owner: MANA INC.

28 ft.

Tank ID:

Tank Status: Permanently Out of Use

Tank Capacity: 20000

N/A

Direction Distance

Elevation Site Database(s) EPA ID Number

SYPHAX SCHOOL (Continued) U003865158

Substance: Heating Oil

Q84 BOB SEGALL DC UST U003054111

NNE 1354 SOUTH CAPITOL ST SE 1/8-1/4 WASHINGTON, DC 20003

0.235 mi.

1242 ft. Site 3 of 8 in cluster Q

Relative: UST:

Higher Facility ID: 2000081 Facility Description: False

Actual: Owner: BOB SEGALL 28 ft.

Tank ID:

Tank Status: Permanently Out of Use

Tank Capacity: 1000 Substance: Gasoline

Q85 CUSTOM TOWING & AUTO REPAIR RCRA NonGen / NLR 1001487033

NNE 1345 SOUTH CAPITOL STREET SW

1/8-1/4 WASHINGTON, DC

0.235 mi.

1242 ft. Site 4 of 8 in cluster Q

Relative: RCRA NonGen / NLR:

Higher Date form received by agency: 05/17/2002

Facility name: CUSTOM TOWING & AUTO REPAIR
Actual: Facility address: 1345 SOUTH CAPITOL STREET SW

28 ft. WASHINGTON, DC 20003

EPA ID: DCR000001818

Mailing address: SOUTH CAPITOL STREET SW

WASHINGTON, DC 20003

Contact: VERNON COOPER
Contact address: SOUTH CAPITOL STREET SW

WASHINGTON, DC 20003

Contact country: US

Contact telephone: (202) 488-4822
Contact email: Not reported
EPA Region: 03

Land type: 03

Classification: Non-Generator

Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: MOORE STEPHANIE D

Owner/operator address: 1345 SOUTH CAPITOL STREET SW

WASHINGTON, DC 20003

Owner/operator country: Not reported
Owner/operator telephone: (202) 488-4822
Legal status: Private

Owner/Operator Type: Owner
Owner/Op start date: 01/01/0001
Owner/Op end date: Not reported

Owner/operator name: MOORE STEPHANIE D

Owner/operator address: 1345 SOUTH CAPITOL STREET SW

**EDR ID Number** 

N/A

**FINDS** 

DCR000001818

Direction Distance Elevation

ance EDR ID Number vation Site Database(s) EPA ID Number

#### **CUSTOM TOWING & AUTO REPAIR (Continued)**

1001487033

WASHINGTON, DC 20003

Owner/operator country: Not reported
Owner/operator telephone: (202) 488-4822
Legal status: Private
Owner/Operator Type: Owner

Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

## Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: Nο Transporter of hazardous waste: No Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: No Furnace exemption: No Used oil fuel burner: No Used oil processor: No User oil refiner: No Used oil fuel marketer to burner: Nο Used oil Specification marketer: No Used oil transfer facility: No Used oil transporter: No

#### Historical Generators:

Date form received by agency: 02/09/1999

Facility name: CUSTOM TOWING & AUTO REPAIR

Classification: Conditionally Exempt Small Quantity Generator

# Hazardous Waste Summary:

Waste code: D001

Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF

LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT

WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D006
Waste name: CADMIUM

Waste code: D008 Waste name: LEAD

Waste code: D018
Waste name: BENZENE

Waste code: D027

Waste name: 1,4-DICHLOROBENZENE

Waste code: D039

Waste name: TETRACHLOROETHYLENE

Waste code: D040

Direction Distance

Elevation Site Database(s) EPA ID Number

## **CUSTOM TOWING & AUTO REPAIR (Continued)**

1001487033

**EDR ID Number** 

Waste name: TRICHLOROETHYLENE

Waste code: D001

Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF

LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT

WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D006
Waste name: CADMIUM

Waste code: D008 Waste name: LEAD

Waste code: D018
Waste name: BENZENE

Waste code: D027

Waste name: 1,4-DICHLOROBENZENE

Waste code: D039

Waste name: TETRACHLOROETHYLENE

Waste code: D040

Waste name: TRICHLOROETHYLENE

Violation Status: No violations found

**Evaluation Action Summary:** 

Evaluation date: 05/17/2002

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation:

Date achieved compliance:

Evaluation lead agency:

Not reported

Not reported

State

Evaluation date: 07/10/2001

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: Not reported Date achieved compliance: Not reported Evaluation lead agency: State

Evaluation date: 05/20/1999

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation:

Date achieved compliance:

Evaluation lead agency:

Not reported

Not reported

State

FINDS:

Registry ID: 110002505094

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of

Direction Distance

**EDR ID Number** Elevation Site Database(s) **EPA ID Number** 

# **CUSTOM TOWING & AUTO REPAIR (Continued)**

1001487033

events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Q86 **POTOMAC CAB COMPANY** DC LUST U002108095 **NNE** 1345 S CAPITOL ST SW DC UST N/A WASHINGTON, DC 20003 1/8-1/4

0.235 mi.

Site 5 of 8 in cluster Q 1242 ft.

Relative: Higher

LUST: Facility ID: Facility Type:

Actual: 28 ft.

Commercial Facility Status: Open

Product: Diesel, Heating Oil

2-000014

Notification Date: 5/17/2007

Ward:

Media Of Contamination: Soil/GW Entry Date: 5/16/2007 Lust Number: 2007021

Facility ID: 2-000014 Facility Type: Other Facility Status: Closed Product: Gasoline Notification Date: 7/20/1989

Ward: 6 Media Of Contamination: Soil Entry Date: 7/20/1989 Lust Number: 89048

UST:

Facility ID: 2000014 Facility Description: False

POTOMAC CAB CO Owner:

Tank ID:

Tank Status: **Permanently Out of Use** 

Tank Capacity: Not reported Substance: Other

Tank ID:

Tank Status: **Permanently Out of Use** 

Tank Capacity: 550 Substance: Gasoline

Tank ID:

Tank Status: **Permanently Out of Use** 

Tank Capacity: 550 Substance: Gasoline

Tank ID: 4

Direction Distance

**EDR ID Number** Elevation Site Database(s) **EPA ID Number** 

POTOMAC CAB COMPANY (Continued) U002108095

Tank Status: **Permanently Out of Use** 

Tank Capacity: 2000 Substance: Diesel

Tank ID:

Tank Status: **Permanently Out of Use** 

Tank Capacity: 1000 Substance: Used Oil

**CHANNEL SQUARE APARTMENTS** DC UST U003294408 87 N/A

NW 325 P ST SW

1/8-1/4 WASHINGTON, DC 20024

0.238 mi. 1255 ft.

UST: Relative:

Facility ID: 2000207 Lower

Facility Description: False

Actual: SOUTHWEST HOUSING RENEWAL CO Owner:

13 ft.

Tank ID:

**Permanently Out of Use** Tank Status:

15000 Tank Capacity: Substance: Heating Oil

Tank ID:

Tank Status: **Currently In Use** 

Tank Capacity: 10000 Substance: Heating Oil

Q88 JONES TRANSPORTATION CO 1342 SOUTH CAPITOL STREET SE NNE

1/8-1/4 WASHINGTON, DC 20003

0.239 mi.

28 ft.

1260 ft. Site 6 of 8 in cluster Q RCRA NonGen / NLR:

Relative: Higher Date form received by agency: 02/02/2004

Facility name: JONES TRANSPORTATION CO Actual: Facility address: 1342 SOUTH CAPITOL STREET SE

WASHINGTON, DC 20003 EPA ID: DCR000000539

Mailing address: SOUTH CAPITOL STREET SE WASHINGTON, DC 20003

JAMES JONES Contact:

Contact address: SOUTH CAPITOL STREET SE

WASHINGTON, DC 20003

Contact country: US

(202) 554-2301 Contact telephone: Contact email: Not reported EPA Region: 03 Land type: Private Classification: Non-Generator

Handler: Non-Generators do not presently generate hazardous waste Description:

1001217868

DCR00000539

RCRA NonGen / NLR

FINDS

Direction Distance

Elevation Site Database(s) EPA ID Number

#### **JONES TRANSPORTATION CO (Continued)**

1001217868

**EDR ID Number** 

Owner/Operator Summary:

Owner/operator name: JONES JAMES

Owner/operator address: 1342 SOUTH CAPITOL STREET SE

WASHINGTON, DC 20003

Owner/operator country: Not reported Owner/operator telephone: (202) 554-2301

Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 01/01/0001
Owner/Op end date: Not reported

Owner/operator name: JONES JAMES

Owner/operator address: 1342 SOUTH CAPITOL STREET SE

WASHINGTON, DC 20003

Owner/operator country:

Owner/operator telephone:

Legal status:

Owner/Operator Type:

Owner/Op start date:

Owner/Op end date:

Not reported

Not reported

Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: No Transporter of hazardous waste: No Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: No Furnace exemption: No Used oil fuel burner: No Used oil processor: No User oil refiner: No Used oil fuel marketer to burner: No Used oil Specification marketer: No Used oil transfer facility: No Used oil transporter: No

Historical Generators:

Date form received by agency: 04/04/2000

Facility name: JONES TRANSPORTATION CO

Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 11/27/1995

Facility name: JONES TRANSPORTATION CO

Classification: Conditionally Exempt Small Quantity Generator

Hazardous Waste Summary:

Waste code: D039

Waste name: TETRACHLOROETHYLENE

Waste code: D039

Waste name: TETRACHLOROETHYLENE

Map ID MAP FINDINGS
Direction

Distance Elevation

vation Site Database(s) EPA ID Number

# JONES TRANSPORTATION CO (Continued)

1001217868

**EDR ID Number** 

Facility Has Received Notices of Violations:

Regulation violated: SR - 4202.7(e), 4403 Area of violation: Generators - Pre-transport

Date violation determined: 05/08/1998
Date achieved compliance: 06/12/1998
Violation lead agency: State

Enforcement action: WRITTEN INFORMAL

Enforcement action date: 05/08/1998
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 4203.1

Area of violation: Generators - Records/Reporting

Date violation determined: 05/08/1998
Date achieved compliance: 06/12/1998
Violation lead agency: State

Enforcement action: WRITTEN INFORMAL

Enforcement action date: 05/08/1998
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 4203.9

Area of violation: Generators - Records/Reporting

Date violation determined: 05/08/1998
Date achieved compliance: 06/12/1998

Violation lead agency: State

Enforcement action: WRITTEN INFORMAL

Enforcement action date: 05/08/1998
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - 4202.7(e), 4401.23
Area of violation: Generators - Pre-transport

Date violation determined: 05/08/1998
Date achieved compliance: 06/12/1998
Violation lead agency: State

Enforcement action: WRITTEN INFORMAL

Enforcement action date: 05/08/1998
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Distance

Elevation Site Database(s) EPA ID Number

# JONES TRANSPORTATION CO (Continued)

1001217868

**EDR ID Number** 

Regulation violated: SR - 4203.5

Area of violation: Generators - Records/Reporting

Date violation determined: 05/08/1998
Date achieved compliance: 06/12/1998
Violation lead agency: State

Enforcement action: WRITTEN INFORMAL

Enforcement action date: 05/08/1998
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

**Evaluation Action Summary:** 

Evaluation date: 02/02/2004

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation:

Date achieved compliance:

Evaluation lead agency:

Not reported

State

Evaluation date: 11/28/2001

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation:

Date achieved compliance:

Evaluation lead agency:

Not reported

Not reported

State

Evaluation date: 05/08/1998

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: Generators - Records/Reporting

Date achieved compliance: 06/12/1998 Evaluation lead agency: State

Evaluation date: 05/08/1998

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: Generators - Pre-transport

Date achieved compliance: 06/12/1998 Evaluation lead agency: State

FINDS:

Registry ID: 110002503960

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Direction Distance

**EDR ID Number** Elevation Site Database(s) **EPA ID Number** 

Q89 JONES TRANSPORTATION DC AST U003763779 NNE

1342 S CAPITOL ST SE N/A

1/8-1/4 WASHINGTON, DC 20003

0.239 mi.

1260 ft. Site 7 of 8 in cluster Q

Relative:

Facility ID: 2004774 Higher Owner: R A BIGGS

Actual: 28 ft.

Tank ID:

Tank Status: Currently in Use

Tank Capacity: 500 Substance: Used Oil AST: True

Q90 EDR US Hist Auto Stat 1015211258 NNE 1342 S CAPITOL ST SE N/A

1/8-1/4 WASHINGTON, DC 20003

0.239 mi.

1260 ft. Site 8 of 8 in cluster Q

**EDR Historical Auto Stations:** Relative:

Name: **AAMCO TRANSMISSIONS** Higher

Year: 2005

Actual: 1342 S CAPITOL ST SE Address:

28 ft.

AAMCO TRANSMISSIONS Name:

Year:

Address: 1342 S CAPITOL ST SE

DC HIST UST \$110337722 **S91 UNKNOWN** 

NNE 1334 S CAPITOL ST SE 1/8-1/4 WASHINGTON, DC

0.241 mi.

Site 1 of 3 in cluster S 1271 ft.

HIST UST: Relative:

Facility Id: 2004773*001 Higher

Confirm Tank/Owner Address Found:Not reported Actual: Confirn Tank/No Owner Found: Not reported 28 ft. Owner Found/No Tank: Not reported Not reported No Owner/No Tank:

Address Not Found: yes

Ltr Edc: Not reported

Tank Status: UNK

Tank Capacity: Not reported

Product: unk N/A

Direction Distance

Elevation Site Database(s) **EPA ID Number** 

**S92** WARRING, JAMES T SONS INC RCRA NonGen / NLR 1000362121 NNE 1330 S CAPITOL ST SE DCD000746909

1/8-1/4 WASHINGTON, DC 20003

0.242 mi.

1277 ft. Site 2 of 3 in cluster S

Relative:

RCRA NonGen / NLR:

Higher Date form received by agency: 08/18/1980

Facility name: WARRING, JAMES T SONS INC Actual: Facility address: 1330 S CAPITOL ST SE 28 ft.

WASHINGTON, DC 20003

EPA ID: DCD000746909

Mailing address: 1321 S CAPITOL ST SW

WASHINGTON, DC 20003

VINCENT WARRING Contact: Contact address: 1330 S CAPITOL ST SE

WASHINGTON, DC 20003

Contact country: US

(202) 488-1528 Contact telephone: Contact email: Not reported

EPA Region: 03

Classification: Non-Generator

Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

**OPERNAME** Owner/operator name: **OPERSTREET** Owner/operator address:

OPERCITY, AK 99999

Owner/operator country: Not reported Owner/operator telephone: (215) 555-1212 Legal status: Private

Owner/Operator Type: Operator Not reported Owner/Op start date: Owner/Op end date: Not reported

WARRING, JAMES T SONS INC Owner/operator name:

Owner/operator address: OWNERSTREET

OWNERCITY, AK 99999

Owner/operator country: Not reported Owner/operator telephone: (215) 555-1212

Legal status: Private Owner/Operator Type: Owner Owner/Op start date: Not reported Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: No Transporter of hazardous waste: No Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: No Furnace exemption: No Used oil fuel burner: No Used oil processor: No User oil refiner: No Used oil fuel marketer to burner: No **EDR ID Number** 

Direction Distance

**EDR ID Number** Elevation Site Database(s) **EPA ID Number** 

#### WARRING, JAMES T SONS INC (Continued)

1000362121

Used oil Specification marketer: No Used oil transfer facility: No Used oil transporter: No

Violation Status: No violations found

S93 WARRING, JAMES T SONS INC **CERC-NFRAP** 1000221667 NNE 1321 S CAPITOL ST SW DCD042278994 RCRA NonGen / NLR

1/4-1/2 WASHINGTON, DC 20003

0.256 mi.

1352 ft. Site 3 of 3 in cluster S

CERC-NFRAP: Relative:

0300026 Higher Site ID:

Federal Facility: Not a Federal Facility Actual: NPL Status: Not on the NPL

27 ft. Non NPL Status: NFRAP-Site does not qualify for the NPL based on existing information

CERCLIS-NFRAP Site Alias Name(s):

Alias Name: WARRING DRUM Alias Address: Not reported

JAMES T WARRING & SONS INC Alias Name:

Not reported Alias Address:

WASHINGTON, DC

CERCLIS-NFRAP Assessment History:

ARCHIVE SITE Action:

Date Started: // Date Completed: 03/01/80 Priority Level: Not reported

SITE INSPECTION Action:

02/01/80 Date Started: 03/01/80 Date Completed:

Priority Level: NFRAP-Site does not qualify for the NPL based on existing information

Action: DISCOVERY

Date Started: Date Completed: 09/01/79 Priority Level: Not reported

Action: PRELIMINARY ASSESSMENT

Date Started: Date Completed: 11/01/79

Low priority for further assessment Priority Level:

RCRA NonGen / NLR:

Date form received by agency: 08/18/1980

WARRING, JAMES T SONS INC Facility name: Facility address: 1321 S CAPITOL ST SW

WASHINGTON, DC 20003

EPA ID: DCD042278994 Contact: VINCENT WARRING Contact address: 1321 S CAPITOL ST SW

WASHINGTON, DC 20003

Direction Distance

Elevation Site Database(s) EPA ID Number

#### WARRING, JAMES T SONS INC (Continued)

1000221667

**EDR ID Number** 

Contact country: US

Contact telephone: (202) 488-1528 Contact email: Not reported

EPA Region: 03

Classification: Non-Generator

Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: JAMES T WARRING SONS INC

Owner/operator address: OWNERSTREET

OWNERCITY, AK 99999

Owner/operator country: Not reported
Owner/operator telephone: (215) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: OPERNAME
Owner/operator address: OPERSTREET

OPERCITY, AK 99999

Owner/operator country:

Owner/operator telephone:

Legal status:

Owner/Operator Type:

Owner/Op start date:

Owner/Op end date:

Not reported

Not reported

Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: No Transporter of hazardous waste: No Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: No Furnace exemption: No Used oil fuel burner: No Used oil processor: No User oil refiner: No Used oil fuel marketer to burner: No Used oil Specification marketer: No Used oil transfer facility: No Used oil transporter: No

Violation Status: No violations found

T94 DC SPORTS COMMISSION DC LUST \$108276553
NE 60-80 O STREET, SE N/A

1/4-1/2 WASHINGTON, DC

0.306 mi.

1615 ft. Site 1 of 3 in cluster T

Relative: LUST:

Lower Facility ID: 0-000000

Facility Type: Baseball Stadium-Lot 703

Actual: Facility Status: NFA-DCRBCA
15 ft. Product: NFA-DCRBCA
Heating Oil, Diesel

Direction Distance

**EDR ID Number** Elevation Site Database(s) **EPA ID Number** 

DC SPORTS COMMISSION (Continued)

Notification Date: 5/16/2006 Ward: 6 Media Of Contamination: Soil Entry Date: 5/18/2006 Lust Number: 2006029

T95 DC DPW FLEET MANAGEMENT DC LUST S104918497 N/A

NE 125 O STREET, SE 1/4-1/2 WASHINGTON, DC

0.325 mi.

Site 2 of 3 in cluster T 1718 ft.

LUST: Relative:

Facility ID: 2-000617 Lower Facility Type: DPW Actual: Facility Status: Open 12 ft. Product: Diesel Notification Date: 8/20/1998

Ward: Media Of Contamination: Soil/GW Entry Date: 8/20/1998 Lust Number: 98097

**T96** WASHINGTON D.C. SEWER MYSTERY SPILL **CERC-NFRAP** 1003108869 DCN000305637

NE **150 O STREET** 

WASHINGTON, DC 20032 1/4-1/2

0.329 mi.

1739 ft. Site 3 of 3 in cluster T

CERC-NFRAP: Relative: Site ID: 0305637 Lower

Federal Facility: Not a Federal Facility Actual: Not on the NPL NPL Status:

15 ft. Non NPL Status: NFRAP-Site does not qualify for the NPL based on existing information

**CERCLIS-NFRAP Site Contact Details:** 

Contact Sequence ID: 13304765.00000 Person ID: 3000119.00000

Contact Sequence ID: 13304766.00000 Person ID: 3000194.00000

CERCLIS-NFRAP Assessment History:

Action: DISCOVERY Date Started: // Date Completed: 01/15/02 Priority Level: Not reported

PRELIMINARY ASSESSMENT Action:

Date Started: 01/15/02 Date Completed: 08/01/02

Priority Level: NFRAP-Site does not qualify for the NPL based on existing information

Action: REMOVAL ASSESSMENT

Date Started: 01/08/01 S108276553

Direction Distance

**EDR ID Number** Elevation Site Database(s) **EPA ID Number** 

# WASHINGTON D.C. SEWER MYSTERY SPILL (Continued)

1003108869

U003054219

N/A

DC LUST

DC UST

Date Completed: 08/01/02 Priority Level: Not reported

Action: ARCHIVE SITE

Date Started: Date Completed: 08/19/02 Priority Level: Not reported

Action: REMOVAL ASSESSMENT

2-000704

Date Started: 12/19/00 12/20/00 Date Completed: Priority Level: Not reported

97 WEBER'S WHITE TRUCKS,INC.

NNE 1331 HALF ST SE

1/4-1/2 0.359 mi. 1895 ft.

WASHINGTON, DC 20003

Relative: Higher

LUST: Facility ID:

Facility Type: Other Actual: Facility Status: Closed 24 ft. Product: Gasoline Notification Date: 1/26/1998

Ward: 6 Media Of Contamination: Soil 1/26/1998 Entry Date: Lust Number: 98029

UST:

Facility ID: 2000704 Facility Description: False

Owner: WEBER'S WHITE TRUCKS,INC.

Tank ID:

**Permanently Out of Use** Tank Status:

2000 Tank Capacity: Substance: Gasoline

Tank ID:

Tank Status: **Permanently Out of Use** 

Tank Capacity: 1000 Substance: Gasoline

Direction Distance

**EDR ID Number** Elevation Site Database(s) **EPA ID Number** 

**U98 AMOCO** DC LUST 1001276588

NNE 1244 SOUTH CAPITAL ST. SE N/A 1/4-1/2 WASHINGTON, DC

0.371 mi.

1957 ft. Site 1 of 4 in cluster U

LUST: Relative:

2-000105 Higher Facility ID: Facility Type: Gas Station Actual: Facility Status: Closed 23 ft. Product: Gasoline Notification Date: 2/26/2002

> Ward: 6 Media Of Contamination: Soil/GW Entry Date: 2/26/2002 Lust Number: 2002035

Facility ID: 2-000105 Facility Type: Gas Station Facility Status: Closed Product: Gasoline Notification Date: 2/9/1994 Ward: 6 Soil/GW Media Of Contamination:

Entry Date: 2/9/1994 Lust Number: 94047

U99 DC BROWNFIELDS S108931562

1236 SOUTH CAPITOL STREET, SE NNE N/A

1/4-1/2 WASHINGTON, DC

0.387 mi.

2046 ft. Site 2 of 4 in cluster U

**BROWNFIELD:** Relative:

PB ID: PBF2004-0127 Higher Ownership: Private

Actual: 1500 Size (sf): 22 ft. Phase I: unknown Phase II: unknown 0046 Lot:

> Square: 38.8758 / -77.009 Latitude/Longitude: Notes: WS/Other: 11-01-07

100 **NAVAL SUPPORT FACILITY ANACOSTIA CERC-NFRAP** 1000481655

SSW **2701 SOUTH CAPITOL STREET SE** RCRA NonGen / NLR DC4170000901 WASHINGTON, DC 20373 1/4-1/2 **NJ MANIFEST** NY MANIFEST

0.390 mi. 2057 ft.

CERC-NFRAP: Relative:

0304418 Site ID: Lower Federal Facility: Federal Facility Actual: Not on the NPL NPL Status:

8 ft. Non NPL Status: NFRAP-Site does not qualify for the NPL based on existing information

0700

**CERCLIS-NFRAP Site Contact Details:** 

Contact Sequence ID: 3386837.00000

Direction Distance

Elevation Site Database(s) EPA ID Number

# NAVAL SUPPORT FACILITY ANACOSTIA (Continued)

1000481655

**EDR ID Number** 

Person ID: 3000181.00000

CERCLIS-NFRAP Site Alias Name(s):

Alias Name: ANACOSTIA NAVAL STATION
Alias Address: 2701 SOUTH CAPITOL STREET SW

WASHINGTON, DC 22214

CERCLIS-NFRAP Assessment History:

Action: DISCOVERY

Date Started: / /
Date Completed: 06/06/91
Priority Level: Not reported

Action: ARCHIVE SITE

Date Started: //
Date Completed: 06/06/91
Priority Level: Not reported

Action: PRELIMINARY ASSESSMENT

Date Started: / /

Date Completed: 08/26/96

Priority Level: NFRAP-Site does not qualify for the NPL based on existing information

RCRA NonGen / NLR:

Date form received by agency: 01/21/2011

Facility name: NAVAL SUPPORT FACILITY ANACOSTIA Facility address: 2701 SOUTH CAPITOL STREET SE

WASHINGTON, DC 20373

EPA ID: DC4170000901 Mailing address: O STREET SE

SUITE 100N

WASHINGTON NAVY YARD, DC 20374

Contact: STEVEN GODIO

Contact address: O STREET SE SUITE 100N

WASHINGTON NAVY YARD, DC 20374

Contact country:

Contact telephone: (202) 433-7182

Contact email: STEVEN.GODIO@NAVY.MIL

EPA Region: 03
Land type: Federal
Classification: Non-Generator

Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: NAVFAC WASHINGTON
Owner/operator address: O ST SE SUITE 100N
WASHINGTON, DC 20374

Owner/operator country: US

Owner/operator telephone: 202-433-7182
Legal status: Federal
Owner/Operator Type: Operator
Owner/Op start date: 10/01/1998
Owner/Op end date: Not reported

Owner/operator name: COMMANDANT NDW

Direction Distance

**EDR ID Number** Elevation Site Database(s) **EPA ID Number** 

# **NAVAL SUPPORT FACILITY ANACOSTIA (Continued)**

1000481655

Owner/operator address: DAHLGREEN AVE SE WASHINGTON, DC 20374

Owner/operator country: US

202-433-2670 Owner/operator telephone: Legal status: Federal Owner/Operator Type: Owner 10/01/1998 Owner/Op start date: Owner/Op end date: Not reported

Owner/operator name: COMMANDANT NAVAL DISTRICT

Owner/operator address: DAHLGREN AVENUE SE

WASHINGTON NAVY YARD, DC 20374

Owner/operator country: US

Owner/operator telephone: (202) 433-7182 Legal status: Federal Owner/Operator Type: Owner

10/01/1998 Owner/Op start date: Owner/Op end date: Not reported

COMMANDANT, NAVAL DISTRICT WASHINGTON Owner/operator name:

Owner/operator address: DAHLGREN AVE, SE. WASHINGTON, DC 20374

Owner/operator country: US

Owner/operator telephone: Not reported Legal status: Federal Owner/Operator Type: Owner Owner/Op start date: 10/01/1998 Owner/Op end date: Not reported

NAVFAC WASHINGTONTON Owner/operator name: DAHLGREN AVENUE, SE. Owner/operator address:

WASHINGTON, DC 20374

Owner/operator country:

Owner/operator telephone: Not reported Legal status: Federal Operator Owner/Operator Type: Owner/Op start date: 10/01/1998 Owner/Op end date: Not reported

Owner/operator name: NACFAC WASHINGTON Owner/operator address: O STREET SE SUITE 100N

WASHINGTON NAVY YARD, DC 20374

Owner/operator country: Not reported Not reported Owner/operator telephone: Legal status: Federal Owner/Operator Type: Operator Owner/Op start date: 10/01/1998 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: No Transporter of hazardous waste: Nο Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: No

Direction Distance

Elevation Site Database(s) EPA ID Number

# NAVAL SUPPORT FACILITY ANACOSTIA (Continued)

1000481655

**EDR ID Number** 

Furnace exemption: No Used oil fuel burner: No Used oil processor: No User oil refiner: No Used oil fuel marketer to burner: No Used oil Specification marketer: No Used oil transfer facility: No Used oil transporter: No

Historical Generators:

Date form received by agency: 03/01/2010

Facility name: NAVAL SUPPORT FACILITY ANACOSTIA

Classification: Large Quantity Generator

Date form received by agency: 03/03/2008

Facility name: NAVAL SUPPORT FACILITY ANACOSTIA

Classification: Large Quantity Generator

Date form received by agency: 04/04/2006

Facility name: NAVAL SUPPORT FACILITY ANACOSTIA

Classification: Large Quantity Generator

Date form received by agency: 02/27/2004

Facility name: NAVAL SUPPORT FACILITY ANACOSTIA
Site name: HQ NDW NAVAL STATION ANACOSTIA

Classification: Large Quantity Generator

Date form received by agency: 02/26/2002

Facility name: NAVAL SUPPORT FACILITY ANACOSTIA
Site name: HQ NDW NAVAL STATION ANACOSTIA

Classification: Small Quantity Generator

Date form received by agency: 02/25/2000

Facility name: NAVAL SUPPORT FACILITY ANACOSTIA
Site name: HQ NDW NAVAL STATION ANACOSTIA

Classification: Large Quantity Generator

Date form received by agency: 03/01/1998

Facility name: NAVAL SUPPORT FACILITY ANACOSTIA
Site name: HQ NDW NAVAL STATION ANACOSTIA

Classification: Large Quantity Generator

Date form received by agency: 02/14/1996

Facility name: NAVAL SUPPORT FACILITY ANACOSTIA
Site name: U S NAVAL DISTRICT WASH ANACOSTIA

Classification: Large Quantity Generator

Date form received by agency: 05/08/1990

Facility name: NAVAL SUPPORT FACILITY ANACOSTIA

Site name: ANACOSTIA NAVAL STATION Classification: Large Quantity Generator

Hazardous Waste Summary:

Waste code: D001

Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF

LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS

Map ID MAP FINDINGS
Direction

Distance EDR ID Number Elevation Site EDR ID Number Database(s) EPA ID Number

# NAVAL SUPPORT FACILITY ANACOSTIA (Continued)

1000481655

CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D002

Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS

CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Waste code: D003

Waste name: A MATERIAL IS CONSIDERED TO BE A REACTIVE HAZARDOUS WASTE IF IT IS

NORMALLY UNSTABLE, REACTS VIOLENTLY WITH WATER, GENERATES TOXIC GASES WHEN EXPOSED TO WATER OR CORROSIVE MATERIALS, OR IF IT IS CAPABLE OF DETONATION OR EXPLOSION WHEN EXPOSED TO HEAT OR A FLAME. ONE EXAMPLE

OF SUCH WASTE WOULD BY WASTE GUNPOWDER.

Waste code: D007
Waste name: CHROMIUM

Waste code: D008 Waste name: LEAD

Waste code: D009
Waste name: MERCURY

Waste code: D011
Waste name: SILVER

Waste code: D018
Waste name: BENZENE

Waste code: P030

Waste name: CYANIDES (SOLUBLE CYANIDE SALTS), NOT OTHERWISE SPECIFIED

Waste code: D001

Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF

LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT

WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D002

Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS

CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE

DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Direction Distance Elevation

n Site Database(s) EPA ID Number

# NAVAL SUPPORT FACILITY ANACOSTIA (Continued)

1000481655

**EDR ID Number** 

Waste code: D008
Waste name: LEAD

Waste code: D018
Waste name: BENZENE

Waste code: D035

Waste name: METHYL ETHYL KETONE

Waste code: D001

Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF

LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT

WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Waste code: D002

Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS

CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

Waste code: D003

Waste name: A MATERIAL IS CONSIDERED TO BE A REACTIVE HAZARDOUS WASTE IF IT IS

NORMALLY UNSTABLE, REACTS VIOLENTLY WITH WATER, GENERATES TOXIC GASES WHEN EXPOSED TO WATER OR CORROSIVE MATERIALS, OR IF IT IS CAPABLE OF DETONATION OR EXPLOSION WHEN EXPOSED TO HEAT OR A FLAME. ONE EXAMPLE

OF SUCH WASTE WOULD BY WASTE GUNPOWDER.

Waste code: D005 Waste name: BARIUM

Waste code: D006
Waste name: CADMIUM

Waste code: D007

Waste name: CHROMIUM

Waste code: D008 Waste name: LEAD

Waste code: D009
Waste name: MERCURY

Waste code: D011 Waste name: SILVER

Waste code: D018
Waste name: BENZENE

Waste code: D026 Waste name: CRESOL

Direction Distance Elevation

stance EDR ID Number evation Site Database(s) EPA ID Number

#### NAVAL SUPPORT FACILITY ANACOSTIA (Continued)

1000481655

Waste code: D029

Waste name: 1,1-DICHLOROETHYLENE

Waste code: D035

Waste name: METHYL ETHYL KETONE

Waste code: D039

Waste name: TETRACHLOROETHYLENE

Waste code: D040

Waste name: TRICHLOROETHYLENE

Waste code: F001

Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING:

TETRACHLOROETHYLENE, TRICHLOROETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE, AND CHLORINATED

FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED

IN F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE

SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste code: F002

Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE,

METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE,

CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND

1,1,2-TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE LISTED IN F001, F004, OR F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND

SPENT SOLVENT MIXTURES.

Waste code: F003

Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL

ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL

ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT

MIXTURES.

Waste code: F005

Waste name: THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL

KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE,

2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF

THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste code: F008

Waste name: PLATING BATH RESIDUES FROM THE BOTTOM OF PLATING BATHS FROM

ELECTROPLATING OPERATIONS WHERE CYANIDES ARE USED IN THE PROCESS.

Direction Distance

Elevation Site Database(s) EPA ID Number

# NAVAL SUPPORT FACILITY ANACOSTIA (Continued)

1000481655

**EDR ID Number** 

Waste code: P030

Waste name: CYANIDES (SOLUBLE CYANIDE SALTS), NOT OTHERWISE SPECIFIED

Waste code: P044

Waste name: DIMETHOATE

Waste code: U121

Waste name: METHANE, TRICHLOROFLUORO-

Waste code: U247

Waste name: BENZENE, 1,1'-(2,2,2-TRICHLOROETHYLIDENE)BIS[4- METHOXY-

Facility Has Received Notices of Violations:

Regulation violated: FR - 40cfr262.34(a)(2)
Area of violation: Generators - Pre-transport

Date violation determined: 09/24/2002
Date achieved compliance: 09/13/2004
Violation lead agency: EPA
Enforcement action: Not reported

Enforcement action.

Enforcement action date:

Enf. disposition status:

Enf. disp. status date:

Enforcement lead agency:

Proposed penalty amount:

Proposed penalty amount:

Not reported

Regulation violated: FR - 40cfr273.14

Area of violation: Generators - Pre-transport

Date violation determined: 09/24/2002
Date achieved compliance: 09/13/2004
Violation lead agency: EPA

Enforcement action: Not reported Not reported Enforcement action date: Not reported Enf. disposition status: Enf. disp. status date: Not reported Enforcement lead agency: Not reported Proposed penalty amount: Not reported Final penalty amount: Not reported Paid penalty amount: Not reported

Regulation violated: SR - 9 vac 20-60-450.B Area of violation: Transporters - General

Date violation determined: 02/24/2000
Date achieved compliance: 03/15/2000
Violation lead agency: State

Enforcement action: WRITTEN INFORMAL

Enforcement action date: 03/09/2000
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: FR - 40 CFR 286.7(a)(7)

Area of violation: LDR - General

Direction Distance

Elevation Site Database(s) EPA ID Number

# NAVAL SUPPORT FACILITY ANACOSTIA (Continued)

1000481655

**EDR ID Number** 

Date violation determined: 06/28/1995
Date achieved compliance: 08/18/1998
Violation lead agency: EPA

Enforcement action: INITIAL 3008(A) COMPLIANCE

Enforcement action date: 09/30/1996
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: Not reported

Froposed penalty amount: Not reported Final penalty amount: Not reported Paid penalty amount: Not reported Not reported

Regulation violated: FR - 40 CFR 265.16
Area of violation: Generators - General

Date violation determined: 06/28/1995
Date achieved compliance: 08/18/1998
Violation lead agency: EPA

Enforcement action: INITIAL 3008(A) COMPLIANCE

Enforcement action date: 09/30/1996
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: Not reported

Final penalty amount: Not reported Not reported Not reported Not reported Not reported

Regulation violated: FR - 40 CFR262.34(a)(2)
Area of violation: Generators - Pre-transport

Date violation determined: 06/28/1995
Date achieved compliance: 08/18/1998
Violation lead agency: EPA

Enforcement action: INITIAL 3008(A) COMPLIANCE

Enforcement action date: 09/30/1996
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: Not reported

Froposed penalty amount: Not reported Final penalty amount: Not reported Paid penalty amount: Not reported Not reported

Regulation violated: FR - 40 CFR 262.34(a)(3)
Area of violation: Generators - Pre-transport

Date violation determined: 06/28/1995
Date achieved compliance: 08/18/1998
Violation lead agency: EPA

Enforcement action: INITIAL 3008(A) COMPLIANCE

Enforcement action date: 09/30/1996
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: EPA
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:

Evaluation date: 01/28/2010

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Direction Distance

Elevation Site Database(s) EPA ID Number

#### NAVAL SUPPORT FACILITY ANACOSTIA (Continued)

1000481655

**EDR ID Number** 

Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation load agonoy.

Evaluation date: 08/05/2008

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 07/12/2004

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation:

Date achieved compliance:

Evaluation lead agency:

Not reported

Not reported

EPA

Evaluation date: 09/24/2002

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: Generators - Pre-transport

Date achieved compliance: 09/13/2004 Evaluation lead agency: EPA

Evaluation date: 02/24/2000

Evaluation: NON-FINANCIAL RECORD REVIEW

Area of violation: Transporters - General

Date achieved compliance: 03/15/2000 Evaluation lead agency: State

Evaluation date: 06/28/1995

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: Generators - General

Date achieved compliance: 08/18/1998 Evaluation lead agency: EPA

Evaluation date: 06/28/1995

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: LDR - General Date achieved compliance: 08/18/1998 Evaluation lead agency: EPA

Evaluation date: 06/28/1995

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation: Generators - Pre-transport

Date achieved compliance: 08/18/1998 Evaluation lead agency: EPA

NJ MANIFEST:

Manifest Code: NJA5093804 DC4170000901 EPA ID: Date Shipped: 02/12/2004 TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Transporter 3 EPA ID: Not reported Not reported Transporter 4 EPA ID: Transporter 5 EPA ID: Not reported Transporter 6 EPA ID: Not reported Transporter 7 EPA ID: Not reported

Map ID MAP FINDINGS
Direction

Distance Elevation

Site Database(s) EPA ID Number

# NAVAL SUPPORT FACILITY ANACOSTIA (Continued)

1000481655

**EDR ID Number** 

Transporter 8 EPA ID: Not reported Not reported Transporter 10 EPA ID: Date Trans1 Transported Waste: 02/12/2004 Date Trans2 Transported Waste: Not reported Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Not reported Not reported Date Trans6 Transported Waste: Date Trans7 Transported Waste: Not reported Date Trans8 Transported Waste: Not reported Date Trans9 Transported Waste: Not reported Date Trans10 Transported Waste: Not reported Date TSDF Received Waste: 02/17/2004 Tranporter 1 Decal: Not reported Tranporter 2 Decal: Not reported Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported Transporter-3 EPA Facility Name: Not reported Transporter-4 EPA Facility Name: Not reported Transporter-5 EPA Facility Name: Not reported TSDF EPA Facility Name: Not reported Not reported QTY Units: Transporter SEQ ID: Not reported Transporter-1 Date: Not reported Not reported Waste SEQ ID: Waste Type Code 2: Not reported Waste Type Code 3: Not reported Waste Type Code 4: Not reported Waste Type Code 5: Not reported Waste Type Code 6: Not reported Date Accepted: Not reported Manifest Discrepancy Type: Not reported Data Entry Number: 03220421 Not reported Reference Manifest Number:

Was Load Rejected (Y/N):

Reason Load Was Rejected:

Waste Code:

Manifest Year:

Quantity:

Unit:

Not reported

Manifest Code: NJA5117313 EPA ID: DC4170000901 Date Shipped: 02/12/2004 TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Transporter 3 EPA ID: Not reported Transporter 4 EPA ID: Not reported Transporter 5 EPA ID: Not reported Transporter 6 EPA ID: Not reported Transporter 7 EPA ID: Not reported Transporter 8 EPA ID: Not reported

Direction Distance Elevation

Site Database(s) **EPA ID Number** 

#### **NAVAL SUPPORT FACILITY ANACOSTIA (Continued)**

1000481655

**EDR ID Number** 

Transporter 10 EPA ID: Not reported 02/12/2004 Date Trans1 Transported Waste: Date Trans2 Transported Waste: Not reported Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Not reported Date Trans6 Transported Waste: Not reported Not reported Date Trans7 Transported Waste: Date Trans8 Transported Waste: Not reported Date Trans9 Transported Waste: Not reported Date Trans10 Transported Waste: Not reported Date TSDF Received Waste: 02/17/2004 Tranporter 1 Decal: Not reported Tranporter 2 Decal: Not reported Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported Not reported Transporter-2 EPA Facility Name: Transporter-3 EPA Facility Name: Not reported Transporter-4 EPA Facility Name: Not reported Transporter-5 EPA Facility Name: Not reported TSDF EPA Facility Name: Not reported QTY Units: Not reported Not reported Transporter SEQ ID: Transporter-1 Date: Not reported Waste SEQ ID: Not reported Waste Type Code 2: Not reported Waste Type Code 3: Not reported Waste Type Code 4: Not reported Waste Type Code 5: Not reported Not reported Waste Type Code 6: Date Accepted: Not reported Manifest Discrepancy Type: Not reported Data Entry Number: 03220421 Reference Manifest Number: Not reported No

Was Load Rejected (Y/N):

Reason Load Was Rejected: Not reported Waste Code: Not reported Manifest Year: Not reported Quantity: Not reported Unit: Not reported Hand Code: Not reported

Manifest Code: NJA5094714 EPA ID: DC4170000901 Date Shipped: 04/09/2004 TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Transporter 3 EPA ID: Not reported Transporter 4 EPA ID: Not reported Transporter 5 EPA ID: Not reported Transporter 6 EPA ID: Not reported Transporter 7 EPA ID: Not reported Transporter 8 EPA ID: Not reported Transporter 10 EPA ID: Not reported

Direction Distance Elevation

Site Database(s) **EPA ID Number** 

# **NAVAL SUPPORT FACILITY ANACOSTIA (Continued)**

1000481655

**EDR ID Number** 

Date Trans1 Transported Waste: 04/09/2004 Date Trans2 Transported Waste: Not reported Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Not reported Date Trans6 Transported Waste: Not reported Date Trans7 Transported Waste: Not reported Not reported Date Trans8 Transported Waste: Date Trans9 Transported Waste: Not reported Date Trans10 Transported Waste: Not reported 04/16/2004 Date TSDF Received Waste: Tranporter 1 Decal: Not reported Tranporter 2 Decal: Not reported Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported Not reported Transporter-3 EPA Facility Name: Transporter-4 EPA Facility Name: Not reported Transporter-5 EPA Facility Name: Not reported TSDF EPA Facility Name: Not reported QTY Units: Not reported Transporter SEQ ID: Not reported Transporter-1 Date: Not reported Waste SEQ ID: Not reported Waste Type Code 2: Not reported Waste Type Code 3: Not reported Waste Type Code 4: Not reported Waste Type Code 5: Not reported Waste Type Code 6: Not reported Not reported Date Accepted: Manifest Discrepancy Type: Not reported Data Entry Number: 05100425 Reference Manifest Number: Not reported

Was Load Rejected (Y/N): No

Reason Load Was Rejected: Not reported Waste Code: Not reported Manifest Year: Not reported Quantity: Not reported Unit: Not reported Hand Code: Not reported

Manifest Code: NJA5039421 EPA ID: DC4170000901 Date Shipped: 06/02/2004 TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Transporter 3 EPA ID: Not reported Transporter 4 EPA ID: Not reported Transporter 5 EPA ID: Not reported Transporter 6 EPA ID: Not reported Transporter 7 EPA ID: Not reported Transporter 8 EPA ID: Not reported Transporter 10 EPA ID: Not reported Date Trans1 Transported Waste: 06/02/2004

Direction Distance Elevation

Site Database(s) **EPA ID Number** 

Not reported

# **NAVAL SUPPORT FACILITY ANACOSTIA (Continued)**

Date Trans2 Transported Waste:

1000481655

**EDR ID Number** 

Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Not reported Date Trans6 Transported Waste: Not reported Date Trans7 Transported Waste: Not reported Date Trans8 Transported Waste: Not reported Not reported Date Trans9 Transported Waste: Date Trans10 Transported Waste: Not reported Date TSDF Received Waste: 06/08/2004 Not reported Tranporter 1 Decal: Tranporter 2 Decal: Not reported Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported Transporter-3 EPA Facility Name: Not reported Not reported Transporter-4 EPA Facility Name: Transporter-5 EPA Facility Name: Not reported TSDF EPA Facility Name: Not reported QTY Units: Not reported Transporter SEQ ID: Not reported Transporter-1 Date: Not reported Waste SEQ ID: Not reported Waste Type Code 2: Not reported Waste Type Code 3: Not reported Not reported Waste Type Code 4: Waste Type Code 5: Not reported Waste Type Code 6: Not reported Date Accepted: Not reported Manifest Discrepancy Type: Not reported Data Entry Number: 06230421 Reference Manifest Number: Not reported

Was Load Rejected (Y/N): No

Reason Load Was Rejected: Not reported Not reported Waste Code: Not reported Manifest Year: Quantity: Not reported Unit: Not reported Hand Code: Not reported

Manifest Code: NJA5037926 EPA ID: DC4170000901 Date Shipped: 08/04/2004 TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Transporter 3 EPA ID: Not reported Not reported Transporter 4 EPA ID: Transporter 5 EPA ID: Not reported Transporter 6 EPA ID: Not reported Transporter 7 EPA ID: Not reported Transporter 8 EPA ID: Not reported Transporter 10 EPA ID: Not reported 08/04/2004 Date Trans1 Transported Waste: Date Trans2 Transported Waste: Not reported

Map ID MAP FINDINGS Direction

Distance Elevation

Site Database(s) **EPA ID Number** 

#### **NAVAL SUPPORT FACILITY ANACOSTIA (Continued)**

1000481655

**EDR ID Number** 

Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Not reported Date Trans6 Transported Waste: Not reported Date Trans7 Transported Waste: Not reported Date Trans8 Transported Waste: Not reported Date Trans9 Transported Waste: Not reported Date Trans10 Transported Waste: Not reported Date TSDF Received Waste: 08/15/2004 Tranporter 1 Decal: Not reported Tranporter 2 Decal: Not reported Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported Transporter-3 EPA Facility Name: Not reported Transporter-4 EPA Facility Name: Not reported Transporter-5 EPA Facility Name: Not reported TSDF EPA Facility Name: Not reported QTY Units: Not reported Transporter SEQ ID: Not reported Transporter-1 Date: Not reported Waste SEQ ID: Not reported Waste Type Code 2: Not reported Waste Type Code 3: Not reported Waste Type Code 4: Not reported Waste Type Code 5: Not reported Waste Type Code 6: Not reported Date Accepted: Not reported Manifest Discrepancy Type: Not reported 09150421 Data Entry Number: Reference Manifest Number: Not reported Was Load Rejected (Y/N): No

Reason Load Was Rejected: Not reported Waste Code: Not reported Not reported Manifest Year: Quantity: Not reported Unit: Not reported Hand Code: Not reported

Manifest Code: NJA5071207 EPA ID: DC4170000901 Date Shipped: 09/22/2004 TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Transporter 3 EPA ID: Not reported Transporter 4 EPA ID: Not reported Not reported Transporter 5 EPA ID: Transporter 6 EPA ID: Not reported Transporter 7 EPA ID: Not reported Transporter 8 EPA ID: Not reported Transporter 10 EPA ID: Not reported Date Trans1 Transported Waste: 09/22/2004 Date Trans2 Transported Waste: Not reported Date Trans3 Transported Waste: Not reported

Direction Distance Elevation

Site EDR ID Number

EDR ID Number

EPA ID Number

#### **NAVAL SUPPORT FACILITY ANACOSTIA (Continued)**

1000481655

Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Not reported Date Trans6 Transported Waste: Not reported Date Trans7 Transported Waste: Not reported Date Trans8 Transported Waste: Not reported Date Trans9 Transported Waste: Not reported Not reported Date Trans10 Transported Waste: 09/24/2004 Date TSDF Received Waste: Tranporter 1 Decal: Not reported Tranporter 2 Decal: Not reported Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported Transporter-3 EPA Facility Name: Not reported Transporter-4 EPA Facility Name: Not reported Transporter-5 EPA Facility Name: Not reported Not reported TSDF EPA Facility Name: QTY Units: Not reported Transporter SEQ ID: Not reported Transporter-1 Date: Not reported Waste SEQ ID: Not reported Waste Type Code 2: Not reported Waste Type Code 3: Not reported Waste Type Code 4: Not reported Waste Type Code 5: Not reported Waste Type Code 6: Not reported Date Accepted: Not reported Manifest Discrepancy Type: Not reported Data Entry Number: 10270422 Reference Manifest Number: Not reported Was Load Rejected (Y/N): No

Reason Load Was Rejected:
Waste Code:
Manifest Year:

Quantity:

Not reported

Not reported

Hand Code:

Manifest Code: NJA5071986 DC4170000901 EPA ID: Date Shipped: 11/15/2004 TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Transporter 3 EPA ID: Not reported Transporter 4 EPA ID: Not reported Transporter 5 EPA ID: Not reported Not reported Transporter 6 EPA ID: Transporter 7 EPA ID: Not reported Transporter 8 EPA ID: Not reported Not reported Transporter 10 EPA ID: Date Trans1 Transported Waste: 11/15/2004 Date Trans2 Transported Waste: Not reported Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Not reported

Map ID MAP FINDINGS
Direction

Distance Elevation

Site Database(s) EPA ID Number

#### **NAVAL SUPPORT FACILITY ANACOSTIA (Continued)**

1000481655

**EDR ID Number** 

Date Trans5 Transported Waste: Not reported Date Trans6 Transported Waste: Not reported Date Trans7 Transported Waste: Not reported Date Trans8 Transported Waste: Not reported Date Trans9 Transported Waste: Not reported Date Trans10 Transported Waste: Not reported Date TSDF Received Waste: 11/18/2004 Tranporter 1 Decal: Not reported Tranporter 2 Decal: Not reported Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported Transporter-3 EPA Facility Name: Not reported Transporter-4 EPA Facility Name: Not reported Transporter-5 EPA Facility Name: Not reported TSDF EPA Facility Name: Not reported Not reported QTY Units: Transporter SEQ ID: Not reported Transporter-1 Date: Not reported Waste SEQ ID: Not reported Waste Type Code 2: Not reported Waste Type Code 3: Not reported Waste Type Code 4: Not reported Waste Type Code 5: Not reported Waste Type Code 6: Not reported Date Accepted: Not reported Manifest Discrepancy Type: Not reported Data Entry Number: 01110521 Reference Manifest Number: Not reported

Was Load Rejected (Y/N): No

Reason Load Was Rejected:

Waste Code:

Manifest Year:

Quantity:

Unit:

Not reported

Manifest Code: NJA5222171 EPA ID: DC4170000901 Date Shipped: 05/31/2005 TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Transporter 3 EPA ID: Not reported Transporter 4 EPA ID: Not reported Transporter 5 EPA ID: Not reported Transporter 6 EPA ID: Not reported Not reported Transporter 7 EPA ID: Transporter 8 EPA ID: Not reported Transporter 10 EPA ID: Not reported Date Trans1 Transported Waste: 05/31/2005 Date Trans2 Transported Waste: Not reported Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Not reported

Map ID MAP FINDINGS Direction

Distance Elevation

Site Database(s) **EPA ID Number** 

# **NAVAL SUPPORT FACILITY ANACOSTIA (Continued)**

1000481655

**EDR ID Number** 

Date Trans6 Transported Waste: Not reported Date Trans7 Transported Waste: Not reported Date Trans8 Transported Waste: Not reported Date Trans9 Transported Waste: Not reported Date Trans10 Transported Waste: Not reported 06/06/2005 Date TSDF Received Waste: Tranporter 1 Decal: Not reported Tranporter 2 Decal: Not reported Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported Transporter-3 EPA Facility Name: Not reported Transporter-4 EPA Facility Name: Not reported Transporter-5 EPA Facility Name: Not reported TSDF EPA Facility Name: Not reported QTY Units: Not reported Transporter SEQ ID: Not reported Transporter-1 Date: Not reported Waste SEQ ID: Not reported Waste Type Code 2: Not reported Waste Type Code 3: Not reported Waste Type Code 4: Not reported Waste Type Code 5: Not reported Waste Type Code 6: Not reported Date Accepted: Not reported Not reported Manifest Discrepancy Type: Data Entry Number: 07010521 Reference Manifest Number: Not reported Was Load Rejected (Y/N):

No

Not reported Reason Load Was Rejected: Waste Code: Not reported Manifest Year: Not reported Not reported Quantity: Unit: Not reported Hand Code: Not reported

Manifest Code: NJA5223276 EPA ID: DC4170000901 08/12/2005 Date Shipped: TSDF EPA ID: NJD002182897 Transporter EPA ID: TXR000050930 Transporter 2 EPA ID: Not reported Not reported Transporter 3 EPA ID: Transporter 4 EPA ID: Not reported Transporter 5 EPA ID: Not reported Transporter 6 EPA ID: Not reported Transporter 7 EPA ID: Not reported Not reported Transporter 8 EPA ID: Transporter 10 EPA ID: Not reported Date Trans1 Transported Waste: 08/12/2005 Date Trans2 Transported Waste: Not reported Date Trans3 Transported Waste: Not reported Date Trans4 Transported Waste: Not reported Date Trans5 Transported Waste: Not reported Date Trans6 Transported Waste: Not reported

Direction Distance

Elevation Site Database(s) **EPA ID Number** 

# **NAVAL SUPPORT FACILITY ANACOSTIA (Continued)**

1000481655

**EDR ID Number** 

Date Trans7 Transported Waste: Not reported Not reported Date Trans8 Transported Waste: Date Trans9 Transported Waste: Not reported Date Trans10 Transported Waste: Not reported Date TSDF Received Waste: 08/17/2005 Tranporter 1 Decal: Not reported Not reported Tranporter 2 Decal: Generator EPA Facility Name: Not reported Transporter-1 EPA Facility Name: Not reported Transporter-2 EPA Facility Name: Not reported Transporter-3 EPA Facility Name: Not reported Transporter-4 EPA Facility Name: Not reported Not reported Transporter-5 EPA Facility Name: TSDF EPA Facility Name: Not reported QTY Units: Not reported Transporter SEQ ID: Not reported Transporter-1 Date: Not reported Waste SEQ ID: Not reported Waste Type Code 2: Not reported Waste Type Code 3: Not reported Waste Type Code 4: Not reported Waste Type Code 5: Not reported Not reported Waste Type Code 6: Date Accepted: Not reported Manifest Discrepancy Type: Not reported Data Entry Number: 09130521 Reference Manifest Number: Not reported Was Load Rejected (Y/N): No

Reason Load Was Rejected: Not reported Waste Code: Not reported Manifest Year: Not reported Quantity: Not reported Not reported Unit: Hand Code: Not reported

NY MANIFEST:

DC4170000901 EPA ID:

Country: USA

UNITED STATES MILITARY Mailing Name:

Mailing Contact:

1311 10TH ST BLDG 175 STE 102 Mailing Address:

Mailing Address 2: Not reported Mailing City: WASHINGTON

Mailing State: DC Mailing Zip: 20374 Mailing Zip4: 5095 Mailing Country: USA

Mailing Phone: 202-433-7182

Document ID: NYB1905030

Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC

Trans1 State ID: P13954ILL Trans2 State ID: PC4291 Generator Ship Date: 910305

Direction Distance

**EDR ID Number** Elevation Site Database(s) **EPA ID Number** 

# NAVAL SUPPORT FACILITY ANACOSTIA (Continued)

1000481655

Trans1 Recv Date: 910305 Trans2 Recv Date: 910321 TSD Site Recv Date: 910322 Part A Recv Date: 910325 Part B Recv Date: 910403 DC4170000901 Generator EPA ID: Trans1 EPA ID: ILD099202681 Trans2 EPA ID: Not reported

NYD049836679 Waste Code: D002 - NON-LISTED CORROSIVE WASTES

Quantity: 00085

G - Gallons (liquids only)* (8.3 pounds) Units:

Number of Containers: 001

TSDF ID:

Container Type: DM - Metal drums, barrels

Handling Method: B Incineration, heat recovery, burning.

Specific Gravity: 100 Year: 91

NYB7539714 Document ID:

Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC

Trans1 State ID: Not reported Trans2 State ID: MAINEV620 Generator Ship Date: 960201 Trans1 Recv Date: 960201 Trans2 Recv Date: 960220 TSD Site Recy Date: 960223 Part A Recv Date: 960304 Part B Recv Date: 960304 DC4170000901 Generator EPA ID: DCD981735244 Trans1 EPA ID: Trans2 EPA ID: DCD981735244 TSDF ID: NYD048148175

D009 - MERCURY 0.2 MG/L TCLP Waste Code:

00030 Quantity: P - Pounds Units: Number of Containers: 001

Container Type: DF - Fiberboard or plastic drums (glass)

Handling Method: R Material recovery of more than 75 percent of the total material.

Specific Gravity: 100 Waste Code: Not reported 80000 Quantity: Units: P - Pounds

Number of Containers: 001

Container Type: DF - Fiberboard or plastic drums (glass)

Handling Method: R Material recovery of more than 75 percent of the total material.

Specific Gravity: 100 Waste Code: Not reported Quantity: 02400 P - Pounds Units:

Number of Containers: 002

Container Type: DM - Metal drums, barrels

Handling Method: R Material recovery of more than 75 percent of the total material.

Specific Gravity: 100 Year: 96

Direction Distance

**EDR ID Number** Elevation Site Database(s) **EPA ID Number** 

U101 PUBLIC STORAGE, INC. DC LUST S103816846 1230 SOUTH CAPITOL ST., SE N/A

NNE 1/4-1/2 WASHINGTON, DC

0.393 mi.

2075 ft. Site 3 of 4 in cluster U

LUST: Relative:

Facility ID: 2-000067 Higher Facility Type: Other Actual: Facility Status: NFA 22 ft.

Product: Diesel Notification Date: 8/12/1996 Ward: 6

Media Of Contamination: Soil/GW 8/12/1996 Entry Date: Lust Number: 96092

U102 **PUBLIC STORAGE** 

S108931560 DC LUST 1230 SOUTH CAPITOL STREET, SE **DC BROWNFIELDS NNE** N/A

WASHINGTON, DC 1/4-1/2

0.393 mi.

2075 ft. Site 4 of 4 in cluster U

LUST: Relative:

Facility ID: 2-000067 Higher

Facility Type: Other Actual: Facility Status: Closed 22 ft. Product: Diesel Notification Date: 8/21/1989

> Ward: 6 Media Of Contamination: Soil 8/21/1989 Entry Date: Lust Number: 89044

**BROWNFIELD:** 

PB ID: PBF2003-0085 Ownership: Private Size (sf): 15198 Phase I: unknown Phase II: unknown Lot: 0044 Square: 0700

Latitude/Longitude: 38.87588418 / -77.00909325

WS/Other: 11-01-07 Notes:

V103 17 M ST. LLC/WMATA DC LUST \$109028312 N/A

NNE 17 M STREET, SE 1/4-1/2 WASHINGTON, DC

0.429 mi.

2265 ft. Site 1 of 3 in cluster V

LUST: Relative:

Facility ID: 2-000712 Higher Facility Type: Other Actual: Facility Status: Open

21 ft. Product: Gasoline, Diesel

4/28/1992 Notification Date:

Ward: 6

TC03660997.2r Page 253

Direction Distance

Distance Elevation Site EDR ID Number

EDR ID Number

EPA ID Number

17 M ST. LLC/WMATA (Continued)

Media Of Contamination: Soil/GW
Entry Date: 4/28/1992
Lust Number: 92048

_____

104 BOWEN ELEMENTARY SCHOOL DC LUST U003764149

North 101 M ST SW DC UST N/A

1/4-1/2 WASHINGTON, DC 20024

0.436 mi. 2302 ft.

Relative: LUST: Lower Facility ID:

Facility ID: 9-000357
Facility Type: DC Govt - School

Actual: Facility Status: Closed

9 ft. Product: Heating Oil
Notification Date: 9/19/2001

 Ward:
 6

 Media Of Contamination:
 Soil

 Entry Date:
 9/19/2001

 Lust Number:
 2001075

UST:

Facility ID: 9000357
Facility Description: False

Owner: OFF OF PUBLIC EDUCATION FACILITIES MODERNIZATION

Tank ID: 1

Tank Status: Permanently Out of Use

Tank Capacity: 5000 Substance: Heating Oil

105 ADMIRAL LIMOUSINE COMPANY DC LUST U003053734

NNE 1245 1ST ST SE DC UST N/A
1/4-1/2 WASHINGTON, DC 20003 DC HIST UST

0.439 mi. 2317 ft.

Actual:

20 ft.

Relative: LUST: Lower Facility

Facility ID: 0-000164
Facility Type: Other
Facility Status: Closed
Product: Gasoline

Notification Date: 11/17/1997
Ward: 6
Media Of Contamination: Soil
Entry Date: 11/17/1997
Lust Number: 98009

UST:

Facility ID: 164
Facility Description: False

Owner: WILLCO CONSTRUCTION CO

Tank ID:

Tank Status: Permanently Out of Use

S109028312

Direction Distance

**EDR ID Number** Elevation Site Database(s) **EPA ID Number** 

# **ADMIRAL LIMOUSINE COMPANY (Continued)**

U003053734

Tank Capacity: 1000 Substance: Diesel

Tank ID:

**Permanently Out of Use** Tank Status:

Tank Capacity: 2000 Substance: Gasoline

HIST UST:

Facility Id: 0000164*001 Confirm Tank/Owner Address Found:Not reported Confirn Tank/No Owner Found: Not reported

Owner Found/No Tank: yes

No Owner/No Tank: Not reported Address Not Found: Not reported Ltr Edc: Not reported Tank Status: Not reported Tank Capacity: 1000 Product: Diesel

0000164*002 Facility Id: Confirm Tank/Owner Address Found:Not reported Confirn Tank/No Owner Found: Not reported

Owner Found/No Tank: yes

No Owner/No Tank: Not reported Address Not Found: Not reported Ltr Edc: Not reported Tank Status: Not reported Tank Capacity: 2000 Product: Gas

V106 **LERNER ENTERPRISES** NNE 20 M STREET, SE

1/4-1/2 WASHINGTON, DC 0.439 mi.

2320 ft. Site 2 of 3 in cluster V

LUST: Relative:

Facility ID: 0-000000 Higher Facility Type: Commercial Actual: Facility Status: Closed

21 ft. Product: Gasoline, Diesel

Notification Date: 8/6/2001

Ward:

Soil/GW Media Of Contamination: Entry Date: 8/8/2001 Lust Number: 2001060

Facility ID: 2-000712 Facility Type: Other Facility Status: Closed Product: Heating Oil Notification Date: 10/13/1988

Ward: 6 Media Of Contamination: Soil

10/13/1988 Entry Date:

DC LUST \$102834858

N/A

Direction Distance

**EDR ID Number** Elevation Site Database(s) **EPA ID Number** 

**LERNER ENTERPRISES (Continued)** 

Lust Number:

S102834858

89001

V107 DC BROWNFIELDS S110337133

0020 M STREET, SE N/A

1/4-1/2 WASHINGTON, DC

0.439 mi.

NNE

2320 ft. Site 3 of 3 in cluster V

**BROWNFIELD:** Relative: PB ID: PBF2003-0090 Higher

Ownership: Private Actual: Size (sf): 22313 21 ft. Phase I: unknown

Phase II: unknown 0804 Lot: Square: 0698

Latitude/Longitude: 38.87647086 / -77.00821881

Notes: WS: Other

U003764081 108 **GREENLEAF SENIOR GARDENS** DC LUST

1200 DELAWARE AV SW North WASHINGTON, DC 20024 1/4-1/2

0.450 mi. 2378 ft.

Actual:

14 ft.

LUST: Relative: Facility ID: Lower

9-000276 Facility Type: Commercial Facility Status: Closed Product: Heating Oil Notification Date: 7/29/1998

Ward: Media Of Contamination: Soil Entry Date: 7/29/1998 Lust Number: 98089

UST:

Facility ID: 9000276 Facility Description: False

Owner: **GREENLEAF SENIOR GARDENS** 

Tank ID:

Tank Status: **Permanently Out of Use** 

Tank Capacity: 20000 Heating Oil Substance:

Tank ID:

Tank Status: **Currently In Use** 

Tank Capacity: 10000 Substance: Heating Oil

HIST UST:

Facility Id: 2001254*001

Confirm Tank/Owner Address Found:yes

DC UST

DC HIST UST

N/A

Direction Distance

**EDR ID Number** Elevation Site Database(s) **EPA ID Number** 

**GREENLEAF SENIOR GARDENS (Continued)** 

U003764081

DC LUST S108276566

DC LUST \$103817101

N/A

N/A

Confirn Tank/No Owner Found: Not reported Not reported Owner Found/No Tank: No Owner/No Tank: Not reported

Address Not Found: yes

Not reported Ltr Edc: Tank Status: CIU Tank Capacity: 2500 Product: HtOI

W109 MONUMENT REALTY

NNE **55 M STREET** 1/4-1/2 WASHINGTON, DC

0.451 mi.

2379 ft. Site 1 of 3 in cluster W

LUST: Relative:

Facility ID: 0-000000 Higher Facility Type: Commercial Actual:

Facility Status: NFA 22 ft. Product: Gasoline. Diesel

Notification Date: 11/27/2006

Ward: Media Of Contamination: GW Entry Date: 11/27/2006 Lust Number: 2007007

W110 SUNOCO

NNE 50 M STREET, SE 1/4-1/2 WASHINGTON, DC

0.456 mi.

Site 2 of 3 in cluster W 2406 ft.

LUST: Relative:

Facility ID: 2-000735 Higher

Lust Number:

Facility Type: Other Actual: Facility Status: Closed 22 ft. Product: Gasoline 3/1/1988 Notification Date:

> Ward: 6 Media Of Contamination: Soil 3/1/1988 Entry Date:

88003

W111 DC LUST S105029694 **80 M TRACKS LTD PARTNERS** N/A

NNE 80 M STREET. SE 1/4-1/2 WASHINGTON, DC

0.483 mi.

2548 ft. Site 3 of 3 in cluster W

LUST: Relative:

2-000968 Facility ID: Higher Facility Type: Commercial Actual: Facility Status: Closed

23 ft. Product: Heating Oil Notification Date: 11/30/1999

Direction Distance

Elevation Site Database(s) **EPA ID Number** 

80 M TRACKS LTD PARTNERS (Continued)

S105029694

**EDR ID Number** 

Ward: 6 Media Of Contamination: Soil 11/30/1999 Entry Date: Lust Number: 2000019

112

DC LUST S108276550 21 L, LLC 21 L STREET, SW North N/A

1/4-1/2 WASHINGTON, DC 0.494 mi.

2609 ft.

LUST: Relative:

0-000000 Lower Facility ID: Facility Type: Other Actual: Facility Status: Open 19 ft. Product: Gasoline

Notification Date: 12/2/2005 Ward:

Soil/GW Media Of Contamination: 12/2/2005 Entry Date: Lust Number: 2006007

113 **WASHINGTON NAVY YARD FUDS** 1012129558 N/A

ΝE 1/2-1

WASHINGTON, DC, DC

0.646 mi. 3409 ft.

FUDS: Relative:

Federal Facility ID: DC9799F1332 Lower FUDS #: C03DC0917

Actual: INST ID: 56373 7 ft.

WASHINGTON NAVY YARD Facility Name: WASHINGTON, DC City:

State: DC EPA Region: 03

DISTRICT OF COLUMBIA County:

Congressional District: 98

US Army District: Baltimore District (NAB)

Fiscal Year: 2011

410-962-2809 Telephone: NPL Status: Not Listed RAB: Not reported CTC: 52.6 **FEDERAL** Current Owner: Current Prog: Not reported Not reported Future Prog:

Description: During the period of Navy use, between 1797 and 1962, the site was

called the Naval Weapons Plant, Washington, D.C., and was used for the production of various types of weapons, administrative, and industrial purposes. During World War II, the Navy erected 82 buildings consisting mainly of shops and warehouses as well as ground structures. During the period of Navy use, the site was called the U.S. Navy Yard, the U.S. Naval Gun Factory, the Naval Weapons Plant, and finally the Washington Navy Yard. The site was originally acquired for use as a Naval ship building facility but was transformed into a

Map ID
Direction
Distance

Elevation

Site

MAP FINDINGS

Database(s)

EDR ID Number EPA ID Number

#### **WASHINGTON NAVY YARD (Continued)**

1012129558

gun factory in the late 1800's. Through World Wars I and II the site produced naval ordnance and weapons as well as repaired damaged equipment and developed new types of ordnance. The site was not under other than DOD control during this period of DOD use. The United States Government acquired a total of 12 6.8 acres fee in various parcels, between 1797 and 1942, for use by the Navy. On 31 May 1962, the westerly portion of the site (60.5 acres) with improvements was reported excess to the needs of the Navy. The 60.5 acres was a portion of the plant located on "M" Street, between 1st and 11th Streets, S.E. General Services Administration (GSA) accepted the 60.5 acres property and improvements on 1 October 1963. There were no restoration provisions in the transfer documents. There were 47 structures erected on the portion of the site which was conveyed to GSA. In 1989, approximately 5.2 acres including one building was transferred back to the Navy. GSA retains ownership of the remaining 55.3 acres. GSA currently uses the site for storage, administrative, maintenance and miscellaneous purposes. The remaining 71.5 acre (66.3 + 5.2) portion of the site is currently under control of the Navy. The site is currently known as the Washington Navy Yard.

Count: 20 records. ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
WASHINGTON	1003866892	ANACOSTIA DRUM SITE	11TH STREET BRIDGE & GOOD HOPE	20020	CERCLIS-NFRAP
WASHINGTON	1004681738	KRAMER JUNIOR HIGH SCHOOL (PUBLIC	17TH & Q STREETS SE	20020	RCRA-CESQG
WASHINGTON	1004681767	EASTERN SENIOR HIGH SCHOOL (PUBLIC	1700 EAST CAPITOL STREET	20003	RCRA-CESQG
WASHINGTON	1004681864	I & R TRANSMISSION	1002 1ST ST	20003	MANIFEST
WASHINGTON	1007060082	PEPCO	M & HALF ST SE	20003	AST
WASHINGTON	1007091892	WASHINGTON D C DEPT OF PUBLIC WORK	14TH STREET BRIDGE	20032	RCRA-NLR,MANIFEST
WASHINGTON	1014388351	LECKIE ELEMENTARY SCHOOL	4200 MARTIN LUTHER KING AVENUE	20032	RCRA-NLR
WASHINGTON	1014388363	FEDERAL OFFICE BUILDING 8 (FOB 8)	2ND & C STREETS SW	20024	RCRA-NLR
WASHINGTON	1015733126	CUSTIS & BROWN BARGE SPILL	12TH AND WATER STREETS, SW	20024	CERCLIS-NFRAP
VASHINGTON	1015810237	NATIONAL PARK SERVICE - EAST POTOM	1100 OHIO DRIVE SW		FINDS
WASHINGTON	1015810260	BUZZARD POINT FACILITY	701 NINTH STREET, N.W.		FINDS
VASHINGTON	1016116148	BUZZARD POINT GENERATING STATION	1ST STREET & V STREET SOUTHWES		FINDS
VASHINGTON	S103816821	FT. MCNAIR, BLDG #37, TANK #5	103 3RD STREET		LUST
SUITLAND	S104640913	MSP AVIATION DIV. WASHINGTON	ANDREW'S AIR FORCE BASE	20020	HIST UST
WASHINGTON	S105260067	ROADSIDE DEVELOPMENT, INC.	1400 O STREET		LUST
WASHINGTON	S105738284	LAUNDROMAT OF BONG YEE	1520 FIRST STREET		LUST
VASHINGTON	S105980890	DELWIN APARTMENTS	4223 FIRST STREET		LUST
WASHINGTON	S107420436	PEPCO	HALF & M STS, SE		LUST
VASHINGTON	S107420439	SQUARE 669 LTD	NORTH CAPITOL STREET AND P STR		LUST
VASHINGTON	S111770332	THURGOOD MARSHALL ACADEMY	2427 MARTIN LUTHER KING JR HWY	20020	MANIFEST

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

**Number of Days to Update:** Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

#### STANDARD ENVIRONMENTAL RECORDS

#### Federal NPL site list

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 04/26/2013 Source: EPA
Date Data Arrived at EDR: 05/09/2013 Telephone: N/A

Number of Days to Update: 62 Next Scheduled EDR Contact: 07/22/2013
Data Release Frequency: Quarterly

**NPL Site Boundaries** 

Sources

EPA's Environmental Photographic Interpretation Center (EPIC)

Telephone: 202-564-7333

EPA Region 1 EPA Region 6

Telephone 617-918-1143 Telephone: 214-655-6659

EPA Region 3 EPA Region 7

Telephone 215-814-5418 Telephone: 913-551-7247

EPA Region 4 EPA Region 8

Telephone 404-562-8033 Telephone: 303-312-6774

EPA Region 5 EPA Region 9

Telephone 312-886-6686 Telephone: 415-947-4246

EPA Region 10

Telephone 206-553-8665

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 04/26/2013 Source: EPA
Date Data Arrived at EDR: 05/09/2013 Telephone: N/A

Number of Days to Update: 62 Next Scheduled EDR Contact: 07/22/2013
Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991 Date Data Arrived at EDR: 02/02/1994 Date Made Active in Reports: 03/30/1994

Number of Days to Update: 56

Source: EPA Telephone: 202-564-4267 Last EDR Contact: 08/15/2011

Next Scheduled EDR Contact: 11/28/2011 Data Release Frequency: No Update Planned

#### Federal Delisted NPL site list

**DELISTED NPL: National Priority List Deletions** 

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 04/26/2013 Date Data Arrived at EDR: 05/09/2013 Date Made Active in Reports: 07/10/2013

Number of Days to Update: 62

Source: EPA Telephone: N/A

Last EDR Contact: 05/09/2013 Next Scheduled EDR Contact: 07/22/2013

Data Release Frequency: Quarterly

#### Federal CERCLIS list

CERCLIS: Comprehensive Environmental Response, Compensation, and Liability Information System

CERCLIS contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). CERCLIS contains sites which are either proposed to or on the National Priorities List (NPL) and sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 02/04/2013 Date Data Arrived at EDR: 03/01/2013 Date Made Active in Reports: 03/13/2013

Number of Days to Update: 12

Source: EPA Telephone: 703-412-9810 Last EDR Contact: 05/29/2013

Next Scheduled EDR Contact: 09/09/2013 Data Release Frequency: Quarterly

FEDERAL FACILITY: Federal Facility Site Information listing

A listing of National Priority List (NPL) and Base Realignment and Closure (BRAC) sites found in the Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) Database where EPA Federal Facilities Restoration and Reuse Office is involved in cleanup activities.

Date of Government Version: 07/31/2012 Date Data Arrived at EDR: 10/09/2012 Date Made Active in Reports: 12/20/2012

Number of Days to Update: 72

Source: Environmental Protection Agency

Telephone: 703-603-8704 Last EDR Contact: 07/08/2013

Next Scheduled EDR Contact: 10/21/2013 Data Release Frequency: Varies

#### Federal CERCLIS NFRAP site List

CERCLIS-NFRAP: CERCLIS No Further Remedial Action Planned

Archived sites are sites that have been removed and archived from the inventory of CERCLIS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list this site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. This decision does not necessarily mean that there is no hazard associated with a given site; it only means that, based upon available information, the location is not judged to be a potential NPL site.

Date of Government Version: 02/05/2013 Date Data Arrived at EDR: 03/01/2013 Date Made Active in Reports: 03/13/2013

Number of Days to Update: 12

Source: EPA

Telephone: 703-412-9810 Last EDR Contact: 05/29/2013

Next Scheduled EDR Contact: 05/09/2013 Data Release Frequency: Quarterly

#### Federal RCRA CORRACTS facilities list

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 02/12/2013 Date Data Arrived at EDR: 02/21/2013 Date Made Active in Reports: 02/27/2013

Number of Days to Update: 6

Source: EPA

Telephone: 800-424-9346 Last EDR Contact: 07/01/2013

Next Scheduled EDR Contact: 10/14/2013 Data Release Frequency: Quarterly

#### Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 02/12/2013 Date Data Arrived at EDR: 02/15/2013 Date Made Active in Reports: 02/27/2013

Number of Days to Update: 12

Source: Environmental Protection Agency

Telephone: 800-438-2474 Last EDR Contact: 07/01/2013

Next Scheduled EDR Contact: 10/14/2013 Data Release Frequency: Quarterly

#### Federal RCRA generators list

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 02/12/2013 Date Data Arrived at EDR: 02/15/2013 Date Made Active in Reports: 02/27/2013

Number of Days to Update: 12

Source: Environmental Protection Agency

Telephone: 800-438-2474 Last EDR Contact: 07/01/2013

Next Scheduled EDR Contact: 10/14/2013 Data Release Frequency: Quarterly

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 02/12/2013 Date Data Arrived at EDR: 02/15/2013 Date Made Active in Reports: 02/27/2013

Number of Days to Update: 12

Source: Environmental Protection Agency

Telephone: 800-438-2474 Last EDR Contact: 07/01/2013

Next Scheduled EDR Contact: 10/14/2013 Data Release Frequency: Quarterly

RCRA-CESQG: RCRA - Conditionally Exempt Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 02/12/2013 Date Data Arrived at EDR: 02/15/2013 Date Made Active in Reports: 02/27/2013

Number of Days to Update: 12

Source: Environmental Protection Agency

Telephone: 800-438-2474 Last EDR Contact: 07/01/2013

Next Scheduled EDR Contact: 10/14/2013 Data Release Frequency: Varies

#### Federal institutional controls / engineering controls registries

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 03/14/2013 Date Data Arrived at EDR: 03/29/2013 Date Made Active in Reports: 05/10/2013

Number of Days to Update: 42

Source: Environmental Protection Agency

Telephone: 703-603-0695 Last EDR Contact: 06/10/2013

Next Scheduled EDR Contact: 09/23/2013 Data Release Frequency: Varies

US INST CONTROL: Sites with Institutional Controls

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 03/14/2013 Date Data Arrived at EDR: 03/29/2013 Date Made Active in Reports: 05/10/2013

Number of Days to Update: 42

Source: Environmental Protection Agency

Telephone: 703-603-0695 Last EDR Contact: 06/10/2013

Next Scheduled EDR Contact: 09/23/2013 Data Release Frequency: Varies

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 12/09/2005 Date Data Arrived at EDR: 12/11/2006 Date Made Active in Reports: 01/11/2007

Number of Days to Update: 31

Source: Department of the Navy Telephone: 843-820-7326 Last EDR Contact: 05/20/2013

Next Scheduled EDR Contact: 09/02/2013 Data Release Frequency: Varies

Federal ERNS list

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 12/31/2012 Date Data Arrived at EDR: 01/17/2013 Date Made Active in Reports: 02/15/2013

Number of Days to Update: 29

Source: National Response Center, United States Coast Guard

Telephone: 202-267-2180 Last EDR Contact: 07/01/2013

Next Scheduled EDR Contact: 10/14/2013 Data Release Frequency: Annually

State- and tribal - equivalent CERCLIS

SHWS: This state does not maintain a SHWS list. See the Federal CERCLIS list and Federal NPL list.

State Hazardous Waste Sites. State hazardous waste site records are the states' equivalent to CERCLIS. These sites may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are identified along with sites where cleanup will be paid for by potentially responsible parties. Available information varies by state.

Date of Government Version: N/A Date Data Arrived at EDR: N/A Date Made Active in Reports: N/A Number of Days to Update: 0 Source: Department of Health Telephone: 202-535-2500 Last EDR Contact: 05/28/2013

Next Scheduled EDR Contact: 09/09/2013 Data Release Frequency: No Update Planned

#### State and tribal landfill and/or solid waste disposal site lists

SWF/LF: Solid Waste Facility Listing

The Solid Waste Disposal Division is responsible for disposing of the District's approximately 203,000 tons of municipal solid waste (trash). Since the District does not have landfills, collected waste is deposited at two solid waste transfer stations and then taken out of the city by contractor vehicles to a waste-to-energy plant and landfill in Virginia.

Date of Government Version: 11/18/2010 Date Data Arrived at EDR: 11/19/2010 Date Made Active in Reports: 12/10/2010

Number of Days to Update: 21

Source: Department of Public Works

Telephone: 202-673-6833 Last EDR Contact: 04/19/2013

Next Scheduled EDR Contact: 08/05/2013

Data Release Frequency: No Update Planned

#### State and tribal leaking storage tank lists

LUST: District of Columbia LUST Cases

Leaking Underground Storage Tank Incident Reports. LUST records contain an inventory of reported leaking underground storage tank incidents. Not all states maintain these records, and the information stored varies by state.

Date of Government Version: 04/10/2013 Date Data Arrived at EDR: 04/11/2013 Date Made Active in Reports: 05/07/2013

Number of Days to Update: 26

Source: Department of the Environment

Telephone: 202-442-5977 Last EDR Contact: 06/10/2013

Next Scheduled EDR Contact: 09/23/2013 Data Release Frequency: Quarterly

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land
A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 09/28/2012 Date Data Arrived at EDR: 11/01/2012 Date Made Active in Reports: 04/12/2013

Number of Days to Update: 162

Source: EPA Region 1 Telephone: 617-918-1313 Last EDR Contact: 05/01/2013

Next Scheduled EDR Contact: 08/12/2013 Data Release Frequency: Varies

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 02/06/2013 Date Data Arrived at EDR: 02/08/2013 Date Made Active in Reports: 04/12/2013

Number of Days to Update: 63

Source: EPA Region 4 Telephone: 404-562-8677 Last EDR Contact: 04/29/2013

Next Scheduled EDR Contact: 08/12/2013 Data Release Frequency: Semi-Annually

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 09/12/2011 Date Data Arrived at EDR: 09/13/2011 Date Made Active in Reports: 11/11/2011

Number of Days to Update: 59

Source: EPA Region 6 Telephone: 214-665-6597 Last EDR Contact: 04/29/2013

Next Scheduled EDR Contact: 08/12/2013 Data Release Frequency: Varies

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 12/31/2012 Date Data Arrived at EDR: 02/28/2013 Date Made Active in Reports: 04/12/2013

Number of Days to Update: 43

Source: EPA Region 7 Telephone: 913-551-7003 Last EDR Contact: 04/29/2013

Next Scheduled EDR Contact: 08/12/2013 Data Release Frequency: Varies

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 08/27/2012 Date Data Arrived at EDR: 08/28/2012 Date Made Active in Reports: 10/16/2012

Number of Days to Update: 49

Source: EPA Region 8 Telephone: 303-312-6271 Last EDR Contact: 04/29/2013

Next Scheduled EDR Contact: 08/12/2013 Data Release Frequency: Quarterly

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 03/01/2013 Date Data Arrived at EDR: 03/01/2013 Date Made Active in Reports: 04/12/2013

Number of Days to Update: 42

Source: Environmental Protection Agency

Telephone: 415-972-3372 Last EDR Contact: 04/29/2013

Next Scheduled EDR Contact: 08/12/2013 Data Release Frequency: Quarterly

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 02/05/2013 Date Data Arrived at EDR: 02/06/2013 Date Made Active in Reports: 04/12/2013

Number of Days to Update: 65

Source: EPA Region 10 Telephone: 206-553-2857 Last EDR Contact: 04/29/2013

Next Scheduled EDR Contact: 08/12/2013 Data Release Frequency: Quarterly

#### State and tribal registered storage tank lists

UST: Underground Storage Tank Database List

Registered Underground Storage Tanks. UST's are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA) and must be registered with the state department responsible for administering the UST program. Available information varies by state program.

Date of Government Version: 04/10/2013 Date Data Arrived at EDR: 04/11/2013 Date Made Active in Reports: 05/07/2013

Number of Days to Update: 26

Source: Department of the Environment

Telephone: 202-442-5977 Last EDR Contact: 06/10/2013

Next Scheduled EDR Contact: 06/24/2013 Data Release Frequency: Quarterly

AST: List of Aboveground Storage Tanks Aboveground storage tank locations.

Date of Government Version: 04/10/2013 Date Data Arrived at EDR: 04/11/2013 Date Made Active in Reports: 05/07/2013

Number of Days to Update: 26

Source: Department of the Environment

Telephone: 202-727-7218 Last EDR Contact: 06/10/2013

Next Scheduled EDR Contact: 09/23/2013 Data Release Frequency: No Update Planned

INDIAN UST R7: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

Date of Government Version: 12/31/2012 Date Data Arrived at EDR: 02/28/2013 Date Made Active in Reports: 04/12/2013

Number of Days to Update: 43

Source: EPA Region 7 Telephone: 913-551-7003 Last EDR Contact: 04/29/2013

Next Scheduled EDR Contact: 08/12/2013 Data Release Frequency: Varies

INDIAN UST R6: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

Date of Government Version: 05/10/2011 Date Data Arrived at EDR: 05/11/2011 Date Made Active in Reports: 06/14/2011

Number of Days to Update: 34

Source: EPA Region 6 Telephone: 214-665-7591 Last EDR Contact: 04/29/2013

Next Scheduled EDR Contact: 08/12/2013 Data Release Frequency: Semi-Annually

INDIAN UST R5: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 08/02/2012 Date Data Arrived at EDR: 08/03/2012 Date Made Active in Reports: 11/05/2012

Number of Days to Update: 94

Source: EPA Region 5 Telephone: 312-886-6136 Last EDR Contact: 04/29/2013

Next Scheduled EDR Contact: 08/12/2013 Data Release Frequency: Varies

INDIAN UST R4: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 02/06/2013 Date Data Arrived at EDR: 02/08/2013 Date Made Active in Reports: 04/12/2013

Number of Days to Update: 63

Source: EPA Region 4 Telephone: 404-562-9424 Last EDR Contact: 04/29/2013

Next Scheduled EDR Contact: 08/12/2013
Data Release Frequency: Semi-Annually

INDIAN UST R1: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 09/28/2012 Date Data Arrived at EDR: 11/07/2012 Date Made Active in Reports: 04/12/2013

Number of Days to Update: 156

Source: EPA, Region 1 Telephone: 617-918-1313 Last EDR Contact: 04/29/2013

Next Scheduled EDR Contact: 08/12/2013 Data Release Frequency: Varies

INDIAN UST R8: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 08/27/2012 Date Data Arrived at EDR: 08/28/2012 Date Made Active in Reports: 10/16/2012

Number of Days to Update: 49

Source: EPA Region 8 Telephone: 303-312-6137 Last EDR Contact: 04/29/2013

Next Scheduled EDR Contact: 08/12/2013 Data Release Frequency: Quarterly

INDIAN UST R10: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 02/05/2013 Date Data Arrived at EDR: 02/06/2013 Date Made Active in Reports: 04/12/2013

Number of Days to Update: 65

Source: EPA Region 10 Telephone: 206-553-2857 Last EDR Contact: 04/29/2013

Next Scheduled EDR Contact: 08/12/2013 Data Release Frequency: Quarterly

INDIAN UST R9: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 02/21/2013 Date Data Arrived at EDR: 02/26/2013 Date Made Active in Reports: 04/12/2013

Number of Days to Update: 45

Source: EPA Region 9 Telephone: 415-972-3368 Last EDR Contact: 04/29/2013

Next Scheduled EDR Contact: 08/12/2013 Data Release Frequency: Quarterly

FEMA UST: Underground Storage Tank Listing

A listing of all FEMA owned underground storage tanks.

Date of Government Version: 01/01/2010 Date Data Arrived at EDR: 02/16/2010 Date Made Active in Reports: 04/12/2010

Number of Days to Update: 55

Source: FEMA

Telephone: 202-646-5797 Last EDR Contact: 04/18/2013

Next Scheduled EDR Contact: 07/29/2013 Data Release Frequency: Varies

#### State and tribal voluntary cleanup sites

INDIAN VCP R1: Voluntary Cleanup Priority Listing

A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 09/28/2012 Date Data Arrived at EDR: 10/02/2012 Date Made Active in Reports: 10/16/2012

Number of Days to Update: 14

Source: EPA, Region 1 Telephone: 617-918-1102 Last EDR Contact: 07/02/2013

Next Scheduled EDR Contact: 10/14/2013 Data Release Frequency: Varies

INDIAN VCP R7: Voluntary Cleanup Priority Lisitng

A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008 Date Data Arrived at EDR: 04/22/2008 Date Made Active in Reports: 05/19/2008

Number of Days to Update: 27

Source: EPA, Region 7 Telephone: 913-551-7365 Last EDR Contact: 04/20/2009

Next Scheduled EDR Contact: 07/20/2009 Data Release Frequency: Varies

VCP: Voluntary Cleanup Program Sites

The Voluntary Cleanup Program oversees owner or developer initiated voluntary remediation of contaminated lands and buildings that return actual or potentially contaminated properties to productive uses.

Date of Government Version: 01/09/2013 Date Data Arrived at EDR: 03/28/2013 Date Made Active in Reports: 03/29/2013

Number of Days to Update: 1

Source: Department of the Environment

Telephone: 202-535-1337 Last EDR Contact: 05/28/2013

Next Scheduled EDR Contact: 09/09/2013 Data Release Frequency: Varies

#### State and tribal Brownfields sites

BROWNFIELDS: Brownfields Site Database
A listing of potential brownfields site locations.

Date of Government Version: 11/20/2012 Date Data Arrived at EDR: 03/29/2013 Date Made Active in Reports: 05/07/2013

Number of Days to Update: 39

Source: Department of the Environment

Telephone: 202-535-1337 Last EDR Contact: 06/18/2013

Next Scheduled EDR Contact: 10/07/2013

Data Release Frequency: Varies

#### ADDITIONAL ENVIRONMENTAL RECORDS

#### Local Brownfield lists

US BROWNFIELDS: A Listing of Brownfields Sites

Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties takes development pressures off of undeveloped, open land, and both improves and protects the environment. Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on brownfields properties assessed or cleaned up with grant funding as well as information on Targeted Brownfields Assessments performed by EPA Regions. A listing of ACRES Brownfield sites is obtained from Cleanups in My Community. Cleanups in My Community provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

Date of Government Version: 12/10/2012 Date Data Arrived at EDR: 12/11/2012 Date Made Active in Reports: 12/20/2012

Number of Days to Update: 9

Source: Environmental Protection Agency Telephone: 202-566-2777

Last EDR Contact: 06/25/2013

Next Scheduled EDR Contact: 10/07/2013 Data Release Frequency: Semi-Annually

#### Local Lists of Landfill / Solid Waste Disposal Sites

ODI: Open Dump Inventory

An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985 Date Data Arrived at EDR: 08/09/2004 Date Made Active in Reports: 09/17/2004

Number of Days to Update: 39

Source: Environmental Protection Agency Telephone: 800-424-9346

Telephone: 800-424-9346 Last EDR Contact: 06/09/2004 Next Scheduled EDR Contact: N/A

Data Release Frequency: No Update Planned

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations

A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009 Date Data Arrived at EDR: 05/07/2009 Date Made Active in Reports: 09/21/2009

Number of Days to Update: 137

Source: EPA, Region 9 Telephone: 415-947-4219 Last EDR Contact: 04/29/2013

Next Scheduled EDR Contact: 08/12/2013
Data Release Frequency: No Update Planned

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands

Location of open dumps on Indian land.

Date of Government Version: 12/31/1998 Date Data Arrived at EDR: 12/03/2007 Date Made Active in Reports: 01/24/2008

Number of Days to Update: 52

Source: Environmental Protection Agency

Telephone: 703-308-8245 Last EDR Contact: 05/03/2013

Next Scheduled EDR Contact: 08/19/2013 Data Release Frequency: Varies

#### Local Lists of Hazardous waste / Contaminated Sites

US CDL: Clandestine Drug Labs

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 03/04/2013 Date Data Arrived at EDR: 03/12/2013 Date Made Active in Reports: 05/10/2013

Number of Days to Update: 59

Source: Drug Enforcement Administration

Telephone: 202-307-1000 Last EDR Contact: 06/03/2013

Next Scheduled EDR Contact: 09/16/2013 Data Release Frequency: Quarterly

US HIST CDL: National Clandestine Laboratory Register

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 09/01/2007 Date Data Arrived at EDR: 11/19/2008 Date Made Active in Reports: 03/30/2009

Number of Days to Update: 131

Source: Drug Enforcement Administration Telephone: 202-307-1000

Last EDR Contact: 03/23/2009

Next Scheduled EDR Contact: 06/22/2009 Data Release Frequency: No Update Planned

#### Local Lists of Registered Storage Tanks

HIST UST: Historical UST Listing

During the process of the database upgrade, all facilities that the UST Program was unable to confirm their existence were removed from the working revelation UST Database before the conversion and put into an excel spreadsheet. These facilities became known as "Project Unknown". This listing is not current and has been not updated.

Date of Government Version: 12/31/1999 Date Data Arrived at EDR: 06/25/2010 Date Made Active in Reports: 07/16/2010

Number of Days to Update: 21

Source: Department of the Environment Telephone: 202-535-1950 Last EDR Contact: 06/24/2010

Next Scheduled EDR Contact: 10/11/2010
Data Release Frequency: No Update Planned

#### Local Land Records

LIENS 2: CERCLA Lien Information

A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 02/06/2013 Date Data Arrived at EDR: 04/25/2013 Date Made Active in Reports: 05/10/2013

Number of Days to Update: 15

Source: Environmental Protection Agency Telephone: 202-564-6023

Last EDR Contact: 04/29/2013

Next Scheduled EDR Contact: 08/12/2013 Data Release Frequency: Varies

#### Records of Emergency Release Reports

HMIRS: Hazardous Materials Information Reporting System

Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 12/31/2012 Date Data Arrived at EDR: 01/03/2013 Date Made Active in Reports: 02/27/2013

Number of Days to Update: 55

Source: U.S. Department of Transportation Telephone: 202-366-4555

Last EDR Contact: 07/01/2013

Next Scheduled EDR Contact: 10/14/2013 Data Release Frequency: Annually

#### Other Ascertainable Records

#### RCRA NonGen / NLR: RCRA - Non Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 02/12/2013 Date Data Arrived at EDR: 02/15/2013 Date Made Active in Reports: 02/27/2013

Number of Days to Update: 12

Source: Environmental Protection Agency

Telephone: 800-438-2474 Last EDR Contact: 07/01/2013

Next Scheduled EDR Contact: 10/14/2013 Data Release Frequency: Varies

#### DOT OPS: Incident and Accident Data

Department of Transporation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 07/31/2012 Date Data Arrived at EDR: 08/07/2012 Date Made Active in Reports: 09/18/2012

Number of Days to Update: 42

Source: Department of Transporation, Office of Pipeline Safety

Telephone: 202-366-4595 Last EDR Contact: 05/07/2013

Next Scheduled EDR Contact: 08/19/2013 Data Release Frequency: Varies

#### DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 12/31/2005 Date Data Arrived at EDR: 11/10/2006 Date Made Active in Reports: 01/11/2007

Number of Days to Update: 62

Source: USGS

Telephone: 888-275-8747 Last EDR Contact: 04/19/2013

Next Scheduled EDR Contact: 07/29/2013 Data Release Frequency: Semi-Annually

#### FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 12/31/2011 Date Data Arrived at EDR: 02/26/2013 Date Made Active in Reports: 03/13/2013

Number of Days to Update: 15

Source: U.S. Army Corps of Engineers

Telephone: 202-528-4285 Last EDR Contact: 06/10/2013

Next Scheduled EDR Contact: 09/23/2013 Data Release Frequency: Varies

#### CONSENT: Superfund (CERCLA) Consent Decrees

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 12/31/2011 Date Data Arrived at EDR: 01/15/2013 Date Made Active in Reports: 03/13/2013

Number of Days to Update: 57

Source: Department of Justice, Consent Decree Library

Telephone: Varies

Last EDR Contact: 06/25/2013

Next Scheduled EDR Contact: 10/14/2013 Data Release Frequency: Varies

#### ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 12/18/2012 Date Data Arrived at EDR: 03/13/2013 Date Made Active in Reports: 04/12/2013

Number of Days to Update: 30

Source: EPA

Telephone: 703-416-0223 Last EDR Contact: 06/11/2013

Next Scheduled EDR Contact: 09/23/2013 Data Release Frequency: Annually

#### UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 09/14/2010 Date Data Arrived at EDR: 10/07/2011 Date Made Active in Reports: 03/01/2012

Number of Days to Update: 146

Source: Department of Energy Telephone: 505-845-0011 Last EDR Contact: 05/28/2013

Next Scheduled EDR Contact: 09/09/2013 Data Release Frequency: Varies

#### US MINES: Mines Master Index File

Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 02/05/2013 Date Data Arrived at EDR: 04/18/2013 Date Made Active in Reports: 05/10/2013

Number of Days to Update: 22

Source: Department of Labor, Mine Safety and Health Administration

Telephone: 303-231-5959 Last EDR Contact: 06/04/2013

Next Scheduled EDR Contact: 09/16/2013 Data Release Frequency: Semi-Annually

#### TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2009 Date Data Arrived at EDR: 09/01/2011 Date Made Active in Reports: 01/10/2012

Number of Days to Update: 131

Source: EPA

Telephone: 202-566-0250 Last EDR Contact: 05/29/2013

Next Scheduled EDR Contact: 09/09/2013 Data Release Frequency: Annually

#### TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2006 Date Data Arrived at EDR: 09/29/2010 Date Made Active in Reports: 12/02/2010

Number of Days to Update: 64

Source: EPA

Telephone: 202-260-5521 Last EDR Contact: 06/25/2013

Next Scheduled EDR Contact: 10/07/2013 Data Release Frequency: Every 4 Years

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act) FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA,

TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009 Date Data Arrived at EDR: 04/16/2009 Date Made Active in Reports: 05/11/2009

Number of Days to Update: 25

Source: EPA/Office of Prevention, Pesticides and Toxic Substances

Telephone: 202-566-1667 Last EDR Contact: 05/28/2013

Next Scheduled EDR Contact: 09/09/2013 Data Release Frequency: Quarterly

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act) A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009 Date Data Arrived at EDR: 04/16/2009 Date Made Active in Reports: 05/11/2009

Number of Days to Update: 25

Source: EPA Telephone: 202-566-1667 Last EDR Contact: 05/28/2013

Next Scheduled EDR Contact: 09/09/2013 Data Release Frequency: Quarterly

#### HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing

A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006 Date Data Arrived at EDR: 03/01/2007 Date Made Active in Reports: 04/10/2007

Number of Days to Update: 40

Source: Environmental Protection Agency

Telephone: 202-564-2501 Last EDR Contact: 12/17/2007

Next Scheduled EDR Contact: 03/17/2008 Data Release Frequency: No Update Planned

#### HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing

A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006 Date Data Arrived at EDR: 03/01/2007 Date Made Active in Reports: 04/10/2007

Number of Days to Update: 40

Source: Environmental Protection Agency

Telephone: 202-564-2501 Last EDR Contact: 12/17/2008

Next Scheduled EDR Contact: 03/17/2008 Data Release Frequency: No Update Planned

#### SSTS: Section 7 Tracking Systems

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 12/31/2009 Date Data Arrived at EDR: 12/10/2010 Date Made Active in Reports: 02/25/2011

Number of Days to Update: 77

Source: EPA

Telephone: 202-564-4203 Last EDR Contact: 04/29/2013

Next Scheduled EDR Contact: 08/12/2013 Data Release Frequency: Annually

## ICIS: Integrated Compliance Information System

The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 07/20/2011 Date Data Arrived at EDR: 11/10/2011 Date Made Active in Reports: 01/10/2012

Number of Days to Update: 61

Source: Environmental Protection Agency

Telephone: 202-564-5088 Last EDR Contact: 04/15/2013

Next Scheduled EDR Contact: 07/29/2013 Data Release Frequency: Quarterly

## PADS: PCB Activity Database System

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 11/01/2012
Date Data Arrived at EDR: 01/16/2013
Date Made Active in Reports: 05/10/2013

Number of Days to Update: 114

Source: EPA

Telephone: 202-566-0500 Last EDR Contact: 04/19/2013

Next Scheduled EDR Contact: 07/29/2013 Data Release Frequency: Annually

#### MLTS: Material Licensing Tracking System

MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 03/14/2013 Date Data Arrived at EDR: 03/20/2013 Date Made Active in Reports: 07/10/2013

Number of Days to Update: 112

Source: Nuclear Regulatory Commission

Telephone: 301-415-7169 Last EDR Contact: 07/10/2013

Next Scheduled EDR Contact: 09/23/2013 Data Release Frequency: Quarterly

#### RADINFO: Radiation Information Database

The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 04/09/2013 Date Data Arrived at EDR: 04/11/2013 Date Made Active in Reports: 05/10/2013

Number of Days to Update: 29

Source: Environmental Protection Agency

Telephone: 202-343-9775 Last EDR Contact: 04/11/2013

Next Scheduled EDR Contact: 07/22/2013 Data Release Frequency: Quarterly

#### FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 03/08/2013 Date Data Arrived at EDR: 03/21/2013 Date Made Active in Reports: 07/10/2013

Number of Days to Update: 111

Source: EPA

Telephone: (215) 814-5000 Last EDR Contact: 06/13/2013

Next Scheduled EDR Contact: 09/23/2013 Data Release Frequency: Quarterly

#### RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995 Date Data Arrived at EDR: 07/03/1995 Date Made Active in Reports: 08/07/1995

Number of Days to Update: 35

Source: EPA

Telephone: 202-564-4104 Last EDR Contact: 06/02/2008

Next Scheduled EDR Contact: 09/01/2008 Data Release Frequency: No Update Planned

RMP: Risk Management Plans

When Congress passed the Clean Air Act Amendments of 1990, it required EPA to publish regulations and guidance for chemical accident prevention at facilities using extremely hazardous substances. The Risk Management Program Rule (RMP Rule) was written to implement Section 112(r) of these amendments. The rule, which built upon existing industry codes and standards, requires companies of all sizes that use certain flammable and toxic substances to develop a Risk Management Program, which includes a(n): Hazard assessment that details the potential effects of an accidental release, an accident history of the last five years, and an evaluation of worst-case and alternative accidental releases; Prevention program that includes safety precautions and maintenance, monitoring, and employee training measures; and Emergency response program that spells out emergency health care, employee training measures and procedures for informing the public and response agencies (e.g the fire department) should an accident occur.

Date of Government Version: 05/08/2012 Date Data Arrived at EDR: 05/25/2012 Date Made Active in Reports: 07/10/2012

Number of Days to Update: 46

Source: Environmental Protection Agency

Telephone: 202-564-8600 Last EDR Contact: 04/29/2013

Next Scheduled EDR Contact: 08/12/2013

Data Release Frequency: Varies

#### **BRS: Biennial Reporting System**

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2011 Date Data Arrived at EDR: 02/26/2013 Date Made Active in Reports: 04/19/2013

Number of Days to Update: 52

Source: EPA/NTIS Telephone: 800-424-9346 Last EDR Contact: 05/30/2013

Next Scheduled EDR Contact: 09/09/2013 Data Release Frequency: Biennially

#### INDIAN RESERV: Indian Reservations

This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2005 Date Data Arrived at EDR: 12/08/2006 Date Made Active in Reports: 01/11/2007

Number of Days to Update: 34

Source: USGS

Telephone: 202-208-3710 Last EDR Contact: 04/19/2013

Next Scheduled EDR Contact: 07/29/2013 Data Release Frequency: Semi-Annually

#### SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing

The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 03/07/2011 Date Data Arrived at EDR: 03/09/2011 Date Made Active in Reports: 05/02/2011

Number of Days to Update: 54

Source: Environmental Protection Agency

Telephone: 615-532-8599 Last EDR Contact: 05/06/2013

Next Scheduled EDR Contact: 08/05/2013 Data Release Frequency: Varies

#### LEAD SMELTER 2: Lead Smelter Sites

A list of several hundred sites in the U.S. where secondary lead smelting was done from 1931and 1964. These sites may pose a threat to public health through ingestion or inhalation of contaminated soil or dust

Date of Government Version: 04/05/2001 Date Data Arrived at EDR: 10/27/2010 Date Made Active in Reports: 12/02/2010

Number of Days to Update: 36

Source: American Journal of Public Health

Telephone: 703-305-6451 Last EDR Contact: 12/02/2009 Next Scheduled EDR Contact: N/A

Data Release Frequency: No Update Planned

LEAD SMELTER 1: Lead Smelter Sites

A listing of former lead smelter site locations.

Date of Government Version: 01/29/2013 Date Data Arrived at EDR: 02/14/2013 Date Made Active in Reports: 02/27/2013

Number of Days to Update: 13

Source: Environmental Protection Agency

Telephone: 703-603-8787 Last EDR Contact: 07/03/2013

Next Scheduled EDR Contact: 10/21/2013 Data Release Frequency: Varies

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List

A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 08/17/2010 Date Data Arrived at EDR: 01/03/2011 Date Made Active in Reports: 03/21/2011

Number of Days to Update: 77

Source: Environmental Protection Agency

Telephone: N/A

Last EDR Contact: 06/14/2013

Next Scheduled EDR Contact: 09/23/2013 Data Release Frequency: Varies

COAL ASH DOE: Sleam-Electric Plan Operation Data

A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2005 Date Data Arrived at EDR: 08/07/2009 Date Made Active in Reports: 10/22/2009

Number of Days to Update: 76

Source: Department of Energy Telephone: 202-586-8719 Last EDR Contact: 04/18/2013

Next Scheduled EDR Contact: 07/29/2013 Data Release Frequency: Varies

PCB TRANSFORMER: PCB Transformer Registration Database

The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 02/01/2011 Date Data Arrived at EDR: 10/19/2011 Date Made Active in Reports: 01/10/2012

Number of Days to Update: 83

Source: Environmental Protection Agency

Telephone: 202-566-0517 Last EDR Contact: 05/03/2013

Next Scheduled EDR Contact: 08/12/2013 Data Release Frequency: Varies

US FIN ASSUR: Financial Assurance Information

All owners and operators of facilities that treat, store, or dispose of hazardous waste are required to provide proof that they will have sufficient funds to pay for the clean up, closure, and post-closure care of their facilities.

Date of Government Version: 03/04/2013 Date Data Arrived at EDR: 03/15/2013 Date Made Active in Reports: 05/10/2013

Number of Days to Update: 56

Source: Environmental Protection Agency

Telephone: 202-566-1917 Last EDR Contact: 05/20/2013

Next Scheduled EDR Contact: 09/02/2013 Data Release Frequency: Quarterly

EPA WATCH LIST: EPA WATCH LIST

EPA maintains a "Watch List" to facilitate dialogue between EPA, state and local environmental agencies on enforcement matters relating to facilities with alleged violations identified as either significant or high priority. Being on the Watch List does not mean that the facility has actually violated the law only that an investigation by EPA or a state or local environmental agency has led those organizations to allege that an unproven violation has in fact occurred. Being on the Watch List does not represent a higher level of concern regarding the alleged violations that were detected, but instead indicates cases requiring additional dialogue between EPA, state and local agencies - primarily because of the length of time the alleged violation has gone unaddressed or unresolved.

Date of Government Version: 12/31/2012 Date Data Arrived at EDR: 02/18/2013 Date Made Active in Reports: 05/10/2013

Number of Days to Update: 81

Source: Environmental Protection Agency

Telephone: 617-520-3000 Last EDR Contact: 05/10/2013

Next Scheduled EDR Contact: 08/26/2013 Data Release Frequency: Quarterly

US AIRS MINOR: Air Facility System Data A listing of minor source facilities.

Date of Government Version: 01/23/2013 Date Data Arrived at EDR: 01/30/2013 Date Made Active in Reports: 05/10/2013 Number of Days to Update: 100 Source: EPA Telephone: 202-564-5962 Last EDR Contact: 06/25/2013

Next Scheduled EDR Contact: 10/14/2013 Data Release Frequency: Annually

US AIRS (AFS): Aerometric Information Retrieval System Facility Subsystem (AFS)

The database is a sub-system of Aerometric Information Retrieval System (AIRS). AFS contains compliance data on air pollution point sources regulated by the U.S. EPA and/or state and local air regulatory agencies. This information comes from source reports by various stationary sources of air pollution, such as electric power plants, steel mills, factories, and universities, and provides information about the air pollutants they produce. Action, air program, air program pollutant, and general level plant data. It is used to track emissions and compliance data from industrial plants.

Date of Government Version: 01/23/2013 Date Data Arrived at EDR: 01/30/2013 Date Made Active in Reports: 05/10/2013

Number of Days to Update: 100

Source: EPA

Telephone: 202-564-5962 Last EDR Contact: 06/25/2013

Next Scheduled EDR Contact: 10/14/2013 Data Release Frequency: Annually

2020 COR ACTION: 2020 Corrective Action Program List

The EPA has set ambitious goals for the RCRA Corrective Action program by creating the 2020 Corrective Action Universe. This RCRA cleanup baseline includes facilities expected to need corrective action. The 2020 universe contains a wide variety of sites. Some properties are heavily contaminated while others were contaminated but have since been cleaned up. Still others have not been fully investigated yet, and may require little or no remediation. Inclusion in the 2020 Universe does not necessarily imply failure on the part of a facility to meet its RCRA obligations.

Date of Government Version: 11/11/2011 Date Data Arrived at EDR: 05/18/2012 Date Made Active in Reports: 05/25/2012

Number of Days to Update: 7

Source: Environmental Protection Agency

Telephone: 703-308-4044 Last EDR Contact: 05/17/2013

Next Scheduled EDR Contact: 08/26/2013 Data Release Frequency: Varies

FEDLAND: Federal and Indian Lands

Federally and Indian administrated lands of the United States. Lands included are administrated by: Army Corps of Engineers, Bureau of Reclamation, National Wild and Scenic River, National Wildlife Refuge, Public Domain Land, Wilderness, Wilderness Study Area, Wildlife Management Area, Bureau of Indian Affairs, Bureau of Land Management, Department of Justice, Forest Service, Fish and Wildlife Service, National Park Service.

Date of Government Version: 12/31/2005 Date Data Arrived at EDR: 02/06/2006 Date Made Active in Reports: 01/11/2007

Number of Days to Update: 339

Source: U.S. Geological Survey Telephone: 888-275-8747 Last EDR Contact: 04/19/2013

Next Scheduled EDR Contact: 07/29/2013

Data Release Frequency: N/A

PRP: Potentially Responsible Parties

A listing of verified Potentially Responsible Parties

Date of Government Version: 12/18/2012
Date Data Arrived at EDR: 04/04/2013
Date Made Active in Reports: 07/10/2013

Number of Days to Update: 97

Source: EPA

Telephone: 202-564-6023 Last EDR Contact: 07/03/2013

Next Scheduled EDR Contact: 10/14/2013 Data Release Frequency: Quarterly

**EDR HIGH RISK HISTORICAL RECORDS** 

**EDR Exclusive Records** 

#### EDR MGP: EDR Proprietary Manufactured Gas Plants

The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A Source: EDR, Inc.
Date Data Arrived at EDR: N/A Telephone: N/A
Date Made Active in Reports: N/A Last EDR Contact: N/A

Number of Days to Update: N/A Next Scheduled EDR Contact: N/A

Data Release Frequency: No Update Planned

#### EDR US Hist Auto Stat: EDR Exclusive Historic Gas Stations

EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A Source: EDR, Inc.
Date Data Arrived at EDR: N/A Telephone: N/A
Date Made Active in Reports: N/A Last EDR Contact: N/A

Number of Days to Update: N/A Next Scheduled EDR Contact: N/A Data Release Frequency: Varies

#### EDR US Hist Cleaners: EDR Exclusive Historic Dry Cleaners

EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A Source: EDR, Inc.
Date Data Arrived at EDR: N/A Telephone: N/A
Date Made Active in Reports: N/A Last EDR Contact: N/A

Number of Days to Update: N/A

Next Scheduled EDR Contact: N/A

Data Release Frequency: Varies

EDR US Hist Cleaners: EDR Proprietary Historic Dry Cleaners - Cole

Date of Government Version: N/A

Date Data Arrived at EDR: N/A

Date Made Active in Reports: N/A

Last EDR Contact: N/A

Number of Days to Update: N/A Next Scheduled EDR Contact: N/A Data Release Frequency: Varies

EDR US Hist Auto Stat: EDR Proprietary Historic Gas Stations - Cole

Date of Government Version: N/A

Date Data Arrived at EDR: N/A

Date Made Active in Reports: N/A

Last EDR Contact: N/A

Number of Days to Update: N/A Next Scheduled EDR Contact: N/A

Data Release Frequency: Varies

#### OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data

Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 05/20/2013 Date Data Arrived at EDR: 05/21/2013 Date Made Active in Reports: 06/27/2013

Number of Days to Update: 37

Source: Department of Energy & Environmental Protection

Telephone: 860-424-3375 Last EDR Contact: 05/21/2013

Next Scheduled EDR Contact: 09/02/2013 Data Release Frequency: Annually

NJ MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 12/31/2011 Date Data Arrived at EDR: 07/19/2012 Date Made Active in Reports: 08/28/2012

Number of Days to Update: 40

Source: Department of Environmental Protection

Telephone: N/A

Last EDR Contact: 04/19/2013

Next Scheduled EDR Contact: 07/29/2013 Data Release Frequency: Annually

NY MANIFEST: Facility and Manifest Data

Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD

facility.

Date of Government Version: 05/01/2013 Date Data Arrived at EDR: 05/09/2013 Date Made Active in Reports: 07/10/2013

Number of Days to Update: 62

Source: Department of Environmental Conservation

Telephone: 518-402-8651 Last EDR Contact: 05/09/2013

Next Scheduled EDR Contact: 08/19/2013
Data Release Frequency: Annually

PA MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 12/31/2011 Date Data Arrived at EDR: 07/23/2012 Date Made Active in Reports: 09/18/2012

Number of Days to Update: 57

Source: Department of Environmental Protection

Telephone: 717-783-8990 Last EDR Contact: 04/23/2013

Next Scheduled EDR Contact: 08/05/2013 Data Release Frequency: Annually

RI MANIFEST: Manifest information

Hazardous waste manifest information

Date of Government Version: 12/31/2011 Date Data Arrived at EDR: 06/22/2012 Date Made Active in Reports: 07/31/2012

Number of Days to Update: 39

Source: Department of Environmental Management

Telephone: 401-222-2797 Last EDR Contact: 05/28/2013

Next Scheduled EDR Contact: 09/09/2013 Data Release Frequency: Annually

WI MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 12/31/2011 Date Data Arrived at EDR: 07/19/2012 Date Made Active in Reports: 09/27/2012

Number of Days to Update: 70

Source: Department of Natural Resources

Telephone: N/A

Last EDR Contact: 06/28/2013

Next Scheduled EDR Contact: 09/30/2013 Data Release Frequency: Annually

Oil/Gas Pipelines: This data was obtained by EDR from the USGS in 1994. It is referred to by USGS as GeoData Digital Line Graphs from 1:100,000-Scale Maps. It was extracted from the transportation category including some oil, but primarily gas pipelines.

Electric Power Transmission Line Data Source: Rextag Strategies Corp. Telephone: (281) 769-2247

U.S. Electric Transmission and Power Plants Systems Digital GIS Data

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

#### AHA Hospitals:

Source: American Hospital Association, Inc.

Telephone: 312-280-5991

The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing

Source: Centers for Medicare & Medicaid Services

Telephone: 410-786-3000

A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services,

a federal agency within the U.S. Department of Health and Human Services.

#### **Nursing Homes**

Source: National Institutes of Health

Telephone: 301-594-6248

Information on Medicare and Medicaid certified nursing homes in the United States.

#### Public Schools

Source: National Center for Education Statistics

Telephone: 202-502-7300

The National Center for Education Statistics' primary database on elementary

and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

Private Schools

Source: National Center for Education Statistics

Telephone: 202-502-7300

The National Center for Education Statistics' primary database on private school locations in the United States.

Daycare Centers: Child Care Facilities Source: Department of Health Telephone: 202-442-5888

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 2003 & 2011 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002 and 2005 from the U.S. Fish and Wildlife Service.

Scanned Digital USGS 7.5' Topographic Map (DRG)

Source: United States Geologic Survey

A digital raster graphic (DRG) is a scanned image of a U.S. Geological Survey topographic map. The map images are made by scanning published paper maps on high-resolution scanners. The raster image is georeferenced and fit to the Universal Transverse Mercator (UTM) projection.

## STREET AND ADDRESS INFORMATION

© 2010 Tele Atlas North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

## **GEOCHECK®- PHYSICAL SETTING SOURCE ADDENDUM**

#### **TARGET PROPERTY ADDRESS**

BUZZARD POINT S STREET SW/1ST STREET SW WASHINGTON, DC 20024

#### TARGET PROPERTY COORDINATES

Latitude (North): 38.8683 - 38° 52′ 5.88″ Longitude (West): 77.0121 - 77° 0′ 43.56″

Universal Tranverse Mercator: Zone 18 UTM X (Meters): 325434.0 UTM Y (Meters): 4303878.0

Elevation: 21 ft. above sea level

#### **USGS TOPOGRAPHIC MAP**

Target Property Map: 38077-G1 ALEXANDRIA, VA DC MD

Most Recent Revision: 1994

North Map: 38077-H1 WASHINGTON WEST, DC MD VA

Most Recent Revision: 1983

Northeast Map: 38076-H8 WASHINGTON EAST, DC MD

Most Recent Revision: 1982

East Map: 38076-G8 ANACOSTIA, DC MD

Most Recent Revision: 1982

EDR's GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

Assessment of the impact of contaminant migration generally has two principal investigative components:

- 1. Groundwater flow direction, and
- 2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata.

## GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

## **GROUNDWATER FLOW DIRECTION INFORMATION**

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).


#### **TOPOGRAPHIC INFORMATION**


Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

#### TARGET PROPERTY TOPOGRAPHY

General Topographic Gradient: General SE

#### SURROUNDING TOPOGRAPHY: ELEVATION PROFILES





Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

## GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

#### **HYDROLOGIC INFORMATION**

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

**FEMA FLOOD ZONE** 

FEMA Flood Electronic Data

Target Property County WASHINGTON, DC

YES - refer to the Overview Map and Detail Map

Flood Plain Panel at Target Property: 1100010025B - FEMA Q3 Flood data

Additional Panels in search area: 1100010030B - FEMA Q3 Flood data

**NATIONAL WETLAND INVENTORY** 

NWI Electronic

NWI Quad at Target Property

Data Coverage

ALEXANDRIA YES - refer to the Overview Map and Detail Map

#### **HYDROGEOLOGIC INFORMATION**

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

#### Site-Specific Hydrogeological Data*:

Search Radius: 1.25 miles

Location Relative to TP: 1/4 - 1/2 Mile NW
Site Name: Usa Ft Mcnair
Site EPA ID Number: DC8210021004
Groundwater Flow Direction: NOT AVAILABLE.
Inferred Depth to Water: 1.5 meters to 3 meters.

Hydraulic Connection: Information is not available about the hydraulic connection between

aquifers underlying the site.

Sole Source Aquifer: No information about a sole source aquifer is available
Data Quality: Information is inferred in the CERCLIS investigation report(s)

#### **AQUIFLOW**®

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

LOCATION GENERAL DIRECTION

MAP ID FROM TP GROUNDWATER FLOW

Not Reported

## GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

#### **GROUNDWATER FLOW VELOCITY INFORMATION**

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

#### **GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY**

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

#### **ROCK STRATIGRAPHIC UNIT**

#### **GEOLOGIC AGE IDENTIFICATION**

Era: Mesozoic Category: Stratified Sequence

System: Cretaceous
Series: Lower Cretaceous

Code: IK (decoded above as Era, System & Series)

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

#### DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps. The following information is based on Soil Conservation Service STATSGO data.

No detail available.

#### LOCAL / REGIONAL WATER AGENCY RECORDS

EDR Local/Regional Water Agency records provide water well information to assist the environmental professional in assessing sources that may impact ground water flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

## WELL SEARCH DISTANCE INFORMATION

DATABASE SEARCH DISTANCE (miles)

Federal USGS 1.000

Federal FRDS PWS Nearest PWS within 1 mile

#### FEDERAL USGS WELL INFORMATION

MAP ID WELL ID LOCATION FROM TP

# **GEOCHECK[®] - PHYSICAL SETTING SOURCE SUMMARY**

## FEDERAL USGS WELL INFORMATION


MAP ID	WELL ID	LOCATION FROM TP
1 2	USGS40000230780 USGS40000230831	1/4 - 1/2 Mile NE 1/2 - 1 Mile SSE

#### FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION

		LOCATION
MAP ID	WELL ID	FROM TP
No PWS System	Found ———	

Note: PWS System location is not always the same as well location.

## PHYSICAL SETTING SOURCE MAP - 03660997.2r



SITE NAME: Buzzard Point ADDRESS: S Street SW/1st Street SW

Washington DC 20024 LAT/LONG: 38.8683 / 77.0121

CLIENT: Haley & Aldrich, In CONTACT: Kristen Wright-Ng Haley & Aldrich, Inc. INQUIRY #: 03660997.2r DATE: July 10, 2013 4:27 pm

Map ID Direction Distance

Elevation Database EDR ID Number

NE FED USGS USGS40000230780

1/4 - 1/2 Mile Lower

Org. Identifier: USGS-MD

Formal name: USGS Maryland Water Science Center

Monloc Identifier: USGS-385219077002201

Monloc name: AX Ac 1 Monloc type: Well

Monloc desc: Not Reported

02070010 Drainagearea value: Not Reported Huc code: Contrib drainagearea: Not Reported Drainagearea Units: Not Reported 38.8719444 Contrib drainagearea units: Not Reported Latitude: Longitude: -77.0061111 Sourcemap scale: 24000 Horiz Acc measure: Horiz Acc measure units: seconds

Horiz Collection method: Global positioning system (GPS), uncorrected

Horiz coord refsys: NAD83 Vert measure val: 13.49
Vert measure units: feet Vertacc measure val: .04

Vert accmeasure units: feet

Vertcollection method: Differential Global Positioning System (GPS)r

Vert coord refsys: NAVD88 Countrycode:

Aquifername: Not Reported
Formation type: Quaternary Alluvium
Aquifer type: Unconfined single aquifer

Construction date: 20040410 Welldepth: 20 Welldepth units: ft Wellholedepth: 20

Wellholedepth units: ft

Ground-water levels, Number of Measurements: 0

2 SSE FED USGS USGS40000230831

US

1/2 - 1 Mile Higher

Org. Identifier: USGS-VA

Formal name: USGS Virginia Water Science Center

Monloc Identifier: USGS-385128077001601

Monloc name: 54U 2C
Monloc type: Well
Monloc desc: Not Reported
Huc code: 02070010

Drainagearea value: Not Reported Drainagearea Units: Not Reported Contrib drainagearea: Not Reported Contrib drainagearea units: Not Reported 38.8578903 Latitude: -77.0041425 24000 Longitude: Sourcemap scale: Horiz Acc measure: Horiz Acc measure units: seconds

Horiz Collection method: Interpolated from map

Horiz coord refsys: NAD83 Vert measure val: 20.00 Vert measure units: feet Vertacc measure val: 10

Vert accmeasure units: feet

Vertcollection method: Interpolated from topographic map

Vert coord refsys: NGVD29 Countrycode: US

Aquifername: Not Reported Formation type: Not Reported

Aquifer type: Not Reported
Construction date: Not Reported

Construction date:Not ReportedWelldepth:398Welldepth units:ftWellholedepth:398Wellholedepth units:ft

Ground-water levels, Number of Measurements: 484

Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1970-05-28	3.45		 1970-05-28	3.45	
1970-05-01	19.74		1970-05-01	19.74	
1970-03-02	42.18		1970-03-02	42.18	
1970-01-27	25.09		1970-01-27	25.09	
1969-12-01	48.05		1969-12-01	48.05	
1969-10-28	46.62		1969-10-28	46.62	
1969-09-29	39.66		1969-09-29	39.66	
1969-08-27	26.14		1969-08-27	26.14	
1969-07-31	35.10		1969-07-31	35.10	
1969-06-27	49.33		1969-06-27	49.33	
1969-05-28	48.80		1969-05-28	48.80	
1969-04-30	48.36		1969-04-30	48.36	
1969-03-27	48.03		1969-03-27	48.03	
1969-03-27	47.45		1969-03-27	46.03 47.45	
1969-01-27	46.14		1969-01-27	46.14	
1969-01-02	44.18		1969-01-02	44.18	
1968-10-30	49.79		1968-10-30	49.79	
1968-09-26	50.49		1968-09-26	50.49	
1968-08-26	51.50		1968-08-26	51.50	
1968-07-29	49.45		1968-07-29	49.45	
1968-06-27	47.61		1968-06-27	47.61	
1968-05-29	47.11		1968-05-29	47.11	
1968-04-29	47.41		1968-04-29	47.41	
1968-03-26	46.79		1968-03-26	46.79	
1968-02-26	47.28		1968-02-26	47.28	
1968-01-28	47.41		1968-01-28	47.41	
1967-12-26	47.52		1967-12-26	47.52	
1967-11-28	47.93		1967-11-28	47.93	
1967-10-27	48.18		1967-10-27	48.18	
1967-09-27	48.61		1967-09-27	48.61	
1967-08-29	49.00		1967-08-29	49.00	
1967-07-28	48.14		1967-07-28	48.14	
1967-06-26	46.99		1967-06-26	46.99	
1967-06-01	46.25		1967-06-01	46.25	
1967-04-28	46.09		1967-04-28	46.09	
1967-04-03	46.25		1967-04-03	46.25	
1967-02-27	46.64		1967-02-27	46.64	
1967-01-31	47.03		1967-01-31	47.03	
1966-12-30	47.09		1966-12-30	47.09	
1966-12-01	47.43		1966-12-01	47.43	
1966-11-01	47.89		1966-11-01	47.89	
1966-10-03	48.88		1966-10-03	48.88	
1966-08-30	48.94		1966-08-30	48.94	
1966-08-01	47.52		1966-08-01	47.52	
1966-07-01	45.45		1966-07-01	45.45	
1966-06-01	44.26		1966-06-01	44.26	
1966-05-04	44.41		1966-05-04	44.41	
1966-04-04	44.93		1966-04-04	44.93	
1000 04 04					
1965-12-30	46.26		1965-12-30	46.26	

Ground-wate	er levels, conti			Foot holow	Foot to
Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1965-08-31	48.04		1965-08-31	48.04	
1965-07-30	47.02		1965-07-30	47.02	
1965-06-29	45.81		1965-06-29	45.81	
1965-06-02	44.79		1965-06-02	44.79	
1965-04-30	44.32		1965-04-30	44.32	
1965-03-31	44.41		1965-03-31	44.41	
1965-02-04	44.76		1965-02-04	44.76	
1964-12-30	45.19		1964-12-30	45.19	
1964-11-30	45.67		1964-11-30	45.67	
1964-10-29	45.86		1964-10-29	45.86	
1964-10-06	46.21		1964-10-06	46.21	
1964-09-03	46.13		1964-09-03	46.13	
1964-07-31	45.06		1964-07-31	45.06	
1964-06-29	43.36		1964-06-29	43.36	
1964-06-01	41.83		1964-06-01	41.83	
1964-05-01	40.62		1964-05-01	40.62	
1964-04-02	40.98		1964-04-02	40.98	
1964-02-28	41.01		1964-02-28	41.01	
1964-02-03	41.57		1964-02-03	41.57	
1963-12-30	42.39		1963-12-30	42.39	
1963-12-02	42.98		1963-12-02	42.98	
1963-10-25	43.84		1963-12-02	43.84	
1963-10-23	43.51		1963-10-23	43.51	
1963-10-02	43.60		1963-10-02	43.60	
1963-06-30	43.80		1963-06-30	43.80	
1963-07-31			1963-06-28	39.14	
	39.14				
1963-05-29 1963-05-01	38.45 38.59		1963-05-29 1963-05-01	38.45 38.59	
1963-03-01	38.76		1963-03-01	38.76	
1963-03-29	38.87		1963-03-01	38.87	
1963-03-01	39.53		1963-02-01	39.53	
1963-02-01	39.99		1963-02-01	39.99	
1962-11-30	41.28		1962-11-30	41.28	
1962-11-30	42.32		1962-11-30	42.32	
1962-10-31			1962-10-31	43.57	
1962-10-02	43.57 43.26			43.26	
1962-06-31	43.26 42.24		1962-08-31 1962-07-31	43.26 42.24	
1962-07-31	40.98		1962-07-31	40.98	
1962-06-29	39.72		1962-06-29	39.72	
1962-04-30	39.72		1962-04-30	39.32	
1962-04-30			1962-04-30	39.85	
	39.85			40.34	
1962-02-27	40.34		1962-02-27	40.3 <del>4</del> 41.15	
1962-01-31	41.15 42.00		1962-01-31	42.00	
1961-12-29			1961-12-29		
1961-12-01	43.16		1961-12-01	43.16	
1961-10-31	44.51 45.19		1961-10-31	44.51	
1961-10-02	45.18		1961-10-02	45.18	
1961-09-01	44.71		1961-09-01 1961-07-38	44.71	
1961-07-28	43.38		1961-07-28	43.38	
1961-06-29	41.94		1961-06-29	41.94	
1961-05-29	41.71		1961-05-29	41.71	
1961-05-01	41.71		1961-05-01	41.71	
1961-03-31	43.08		1961-03-31	43.08	
1961-03-01	44.84 46.10		1961-03-01	44.84 46.10	
1961-02-01	46.19		1961-02-01	46.19	

Ground-wate	er levels, conti				Factbalan	F
Date	Feet below Surface	Feet to Sealevel		Date	Feet below Surface	Feet to Sealevel
1960-12-01	49.79			1960-12-01	49.79	
1960-10-31	50.62			1960-10-31	50.62	
1960-10-31	50.02			1960-09-30	50.02	
1960-08-31	46.85			1960-08-31	46.85	
1960-08-02	45.51			1960-08-02	45.51	
1960-06-30	43.98			1960-06-30	43.98	
1960-06-01	42.95			1960-06-01	42.95	
1960-05-04	42.88			1960-05-04	42.88	
1960-04-04	42.83			1960-04-04	42.83	
1960-02-29	44.51			1960-02-29	44.51	
1960-02-02	45.26			1960-02-02	45.26	
1959-04-01	41.73			1959-04-01	41.73	
1959-02-27	40.81			1959-02-27	40.81	
1959-02-02	41.89			1959-02-02	41.89	
1958-12-31	42.72			1958-12-31	42.72	
1958-12-03	43.83			1958-12-03	43.83	
1958-10-31	45.08			1958-10-31	45.08	
1958-10-01	46.59			1958-10-01	46.59	
1958-09-30	46.07			1958-09-30	46.07	
1958-09-03	46.95			1958-09-03	46.95	
1958-07-31	46.24			1958-07-31	46.24	
1958-06-30	45.51			1958-06-30	45.51	
1958-05-29	45.33			1958-05-29	45.33	
1958-03-31	46.53			1958-03-31	46.53	
1958-02-28	47.22			1958-02-28	47.22	
1958-01-31	48.20			1958-01-31	48.20	
1958-01-02	49.61			1958-01-02	49.61	
1957-12-09	50.55			1957-12-09	50.55	
1957-10-31	53.37			1957-10-31	53.37	
1957-09-30	56.37			1957-09-30	56.37	
1957-09-03	55.26			1957-09-03	55.26	
1957-07-31	53.13			1957-07-31	53.13	
1957-07-01	49.41			1957-07-01	49.41	
1957-05-31	45.46			1957-05-31	45.46	
1957-05-01	44.71			1957-05-01	44.71	
1957-04-01	45.31			1957-04-01	45.31	
1957-03-01	45.71			1957-03-01	45.71	
1957-01-31	46.71			1957-01-31	46.71	
1956-12-31	47.36			1956-12-31	47.36	
1956-12-11	48.11			1956-12-11	48.11	
1956-10-08				1956-10-08		
1956-08-31	50.31			1956-08-31	50.31	
1956-08-01	49.49			1956-08-01	49.49	
1956-04-26	46.80			1956-04-26	46.80 47.66	
1956-03-01 1956-01-31	47.66 48.71			1956-03-01 1956-01-31	48.71	
1956-01-18	48.60			1956-01-31	48.60	
1955-11-03	50.45			1955-11-03	50.45	
1955-11-03	49.99			1955-08-31	49.99	
1955-08-04	48.89			1955-08-04	48.89	
1955-07-01	46.51			1955-07-01	46.51	
1955-06-01	45.29			1955-06-01	45.29	
1955-05-06	45.04			1955-05-06	45.04	
1955-03-15	45.96			1955-03-15	45.96	
1955-02-16	46.51			1955-02-16	46.51	
	-					

Ground-wate	er levels, conti			Foot bolow	Foot to
Date	Feet below Surface	Feet to Sealevel	Date	Feet below Surface	Feet to Sealevel
1954-12-21	47.71		1954-12-21	47.71	
1954-11-16	48.42		1954-11-16	48.42	
1954-10-06	48.28		1954-10-06	48.28	
1954-09-07	47.51		1954-09-07	47.51	
1954-08-06	45.80		1954-08-06	45.80	
1954-04-30	40.99		1954-04-30	40.99	
1954-04-02	42.11		1954-04-02	42.11	
1954-03-02	42.86		1954-03-02	42.86	
1954-01-29	43.78		1954-01-29	43.78	
1954-01-19	43.71		1954-01-19	43.71	
1942-07-20	45.50		1942-07-20	45.50	
1942-07-03	45.72		1942-07-03	45.72	
1942-05-21	48.23		1942-05-21	48.23	
1942-04-21	45.41		1942-04-21	45.41	
1942-04-13	45.01		1942-04-13	45.01	
1942-04-06	45.77		1942-04-06	45.77	
1942-03-23	46.60		1942-03-23	46.60	
1942-03-16	46.46		1942-03-16	46.46	
1942-03-09	46.56		1942-03-09	46.56	
1942-03-02	46.36		1942-03-02	46.36	
1942-02-09	46.14		1942-02-09	46.14	
1942-02-02	46.13		1942-02-02	46.13	
1942-01-26	46.46		1942-01-26	46.46	
1942-01-05	46.45		1942-01-05	46.45	
1941-12-29	46.36		1941-12-29	46.36	
1941-12-22	46.53		1941-12-22	46.53	
1941-12-01	47.93		1941-12-01	47.93	
1941-11-17	49.01		1941-11-17	49.01	
1941-11-10	48.88		1941-11-10	48.88	
1941-11-03	49.51		1941-11-03	49.51	
1941-10-27	50.49		1941-10-27	50.49	
1941-10-20	50.54		1941-10-20	50.54	
1941-10-13	50.58		1941-10-13	50.58	
1941-09-29	51.16		1941-09-29	51.16	
1941-09-22	52.18		1941-09-22	52.18	
1941-09-08	48.30		1941-09-08	48.30	
1941-09-02	48.79		1941-09-02	48.79	
1941-08-25	48.74		1941-08-25	48.74	
1941-08-18	49.45		1941-08-18	49.45	
1941-07-14	47.48		1941-07-14	47.48	
1941-07-07	44.10		1941-07-07	44.10	
1941-06-30	42.95		1941-06-30	42.95	
1941-06-16	42.68		1941-06-16	42.68	
1941-06-02	41.75		1941-06-02	41.75	
1941-05-12	39.42		1941-05-12	39.42	
1941-04-26	37.77		1941-04-26	37.77	
1941-04-14	36.62		1941-04-14	36.62	
1941-04-07	36.36		1941-04-07	36.36	
1941-03-31	36.34		1941-03-31	36.34	
1941-03-24	36.44		1941-03-24	36.44	
1941-03-17	36.41		1941-03-17	36.41	
1941-03-03	36.86		1941-03-03	36.86	
1941-02-24	37.69		1941-02-24	37.69	
1941-02-17 1941-02-10	37.88 38.98		1941-02-17 1941-02-10	37.88 38.98	
1341-02-10	30.30		1341-02-10	30.30	

Ground-wate	er levels, conti	nued.				
	Feet below	Feet to			Feet below	Feet to
Date	Surface	Sealevel	Date		Surface	Sealevel
1941-01-06	40.52		1941-0	)1-06	40.52	
1940-12-30	39.52		1940-1	2-30	39.52	
1940-11-25	40.66		1940-1	1-25	40.66	
1940-11-04	41.14		1940-1	1-04	41.14	
1940-10-21	41.19		1940-1	0-21	41.19	
1940-09-23	41.49		1940-0	9-23	41.49	
1940-08-30	40.34		1940-0	)8-30	40.34	
1940-08-19	39.94		1940-0	)8-19	39.94	
1940-08-05	39.27		1940-0	)8-05	39.27	
1940-07-22	39.60		1940-0	)7-22	39.60	
1940-07-08	40.06		1940-0	7-08	40.06	
1940-06-27	40.52		1940-0	)6-27	40.52	
1940-06-05	42.46		1940-0	)6-05	42.46	
1940-05-29	43.06		1940-0	)5-29	43.06	
1940-05-22	43.86		1940-0	)5-22	43.86	
1940-05-15	44.89		1940-0	)5-15	44.89	
1940-05-08	45.81		1940-0	)5-08	45.81	
1940-05-01	46.64		1940-0	)5-01	46.64	
1940-04-23	47.77		1940-0	)4-23	47.77	
1940-04-17	48.95		1940-0	)4-17	48.95	
1940-04-10	50.07		1940-0	)4-10	50.07	
1940-04-03	51.48		1940-0	)4-03	51.48	
1940-03-27	52.90		1940-0	)3-27	52.90	
1940-03-20	54.01		1940-0	)3-20	54.01	
1940-03-13	55.68		1940-0	)3-13	55.68	
1940-03-06	57.20		1940-0	)3-06	57.20	
1940-02-29	59.00		1940-0	)2-29	59.00	

## AREA RADON INFORMATION

EPA Region 3 Statistical Summary Readings for Zip Code: 20024

Number of sites tested: 92.

Maximum Radon Level: 37.4 pCi/L. Minimum Radon Level: 0.2 pCi/L.

pCi/L	pCi/L	pCi/L	pCi/L	pCi/L	pCi/L
<4	4-10	10-20	20-50	50-100	>100
86 (93.48%)	4 (4.35%)	0 (0.00%)	2 (2.17%)	0 (0.00%)	0 (0.00%)

## PHYSICAL SETTING SOURCE RECORDS SEARCHED

#### **TOPOGRAPHIC INFORMATION**

USGS 7.5' Digital Elevation Model (DEM)

Source: United States Geologic Survey

EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5 minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

Scanned Digital USGS 7.5' Topographic Map (DRG)

Source: United States Geologic Survey

A digital raster graphic (DRG) is a scanned image of a U.S. Geological Survey topographic map. The map images are made by scanning published paper maps on high-resolution scanners. The raster image is georeferenced and fit to the Universal Transverse Mercator (UTM) projection.

#### HYDROLOGIC INFORMATION

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 2003 & 2011 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002 and 2005 from the U.S. Fish and Wildlife Service.

#### HYDROGEOLOGIC INFORMATION

AQUIFLOW^R Information System

Source: EDR proprietary database of groundwater flow information

EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

#### **GEOLOGIC INFORMATION**

Geologic Age and Rock Stratigraphic Unit

Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map. USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database

Source: Department of Agriculture, Natural Resources Conservation Services

The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

SSURGO: Soil Survey Geographic Database

Source: Department of Agriculture, Natural Resources Conservation Services (NRCS)

Telephone: 800-672-5559

SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Services, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

## PHYSICAL SETTING SOURCE RECORDS SEARCHED

#### LOCAL / REGIONAL WATER AGENCY RECORDS

FEDERAL WATER WELLS

PWS: Public Water Systems

Source: EPA/Office of Drinking Water

Telephone: 202-564-3750

Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data

Source: EPA/Office of Drinking Water

Telephone: 202-564-3750

Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: USGS National Water Inventory System (NWIS)

This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

#### OTHER STATE DATABASE INFORMATION

#### **RADON**

Area Radon Information

Source: USGS

Telephone: 703-356-4020

The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones

Source: EPA

Telephone: 703-356-4020

Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor

radon levels.

EPA Region 3 Statistical Summary Readings

Source: Region 3 EPA Telephone: 215-814-2082

Radon readings for Delaware, D.C., Maryland, Pennsylvania, Virginia and West Virginia.

## OTHER

Airport Landing Facilities: Private and public use landing facilities

Source: Federal Aviation Administration, 800-457-6656

Epicenters: World earthquake epicenters, Richter 5 or greater

Source: Department of Commerce, National Oceanic and Atmospheric Administration

#### STREET AND ADDRESS INFORMATION

© 2010 Tele Atlas North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

COMPREHENSIVE SITE ASSESSMENT
POTOMAC ELECTRIC POWER COMPANY
BUZZARD POINT STATION
1ST AND V STREETS, S.W.
WASHINGTON, D.C.
FACILITY ID#: 2-000609
DC LUST CASE#: 93-051
TPH PROJECT#: J93058.01
AUGUST 11, 1993

#### Prepared For:

Potomac Electric Power Company 1900 Pennsylvania Avenue, N.W. Washington, D.C. 20068-0001

#### Prepared By:

TPH Technology, Incorporated 2017 Renard Court Annapolis, Maryland 21401 (410)224-9300



2017 Renard Court • Annapolis, Md. 21401 • (410) 224-9300 Bokimere (410) 841-5618 • Fax (410) 573-0535

#### EXECUTIVE SUMMARY

COMPREHENSIVE SITE ASSESSMENT (CSA) REPORT
BUZZARD POINT STATION
1ST AND V STREET, S.W.
WASHINGTON, D.C.
FACILITY ID #: 2-000609
DC LUST CASE #: 93-051
TPH PROJECT #: J93058.01

TPH Technology, Incorporated (TPH, Inc.) has conducted a Comprehensive Site Assessment at the Potomac Electric Power Company's (PEPCO) Buzzard Point Generating Station, located at 1" and "V" Street, S.W., Washington, D.C. This investigation was initiated pursuant to a written directive issued by the District of Columbia, Department of Consumer and Regulatory Affairs; Environmental Regulation Administration; Pesticides, Hazardous Waste and Underground Storage Tank Branch's (DCRA). This directive was made in response to the January 29, 1993, discovery of free phase (liquid) hydrocarbons by PEPCO personnel in an existing groundwater observation well. The assessment was conducted in accordance with DCRA Specifications.

The existing observation well was located in the combustion turbine area at the northern portion of the generating station. This well was installed in the early 1970's in response to a leak in an underground #2 fuel oil line. The northern combustion turbine area (NCTA) was the focal point of this investigation.

The Buzzard Point Generating Station had been used for generating electric power since 1928. The surrounding area consists primarily of commercial establishments and governmental institutions. Multifamily residences are located several blocks north of the site. Underground utilities include telephone, natural gas, water, fuel oil lines, sanitary sewers and storm sewers. Of these utilities, sanitary and storm sewers are greater than six feet in depth. The depth of sanitary sewers range from 8 to 12 feet depth.

The site is located in the Atlantic Coastal Plain Physiographic Province. The stratigraphy of the site is characterized by silty sand and gravel of the Pamlico Formation. The depth to groundwater ranges from ≈15 to 20 feet below grade. The groundwater flow direction appears to be to the southwest.

The site assessment included a shallow soil gas survey, the installation of eleven groundwater monitoring wells, sampling and analysis of soil and groundwater, a survey of sensitive receptors, and total fluids and vacuum extraction remedial feasibility testing.

Using the information provided by the shallow soil gas survey, soil vapor isoconcentration maps were drafted to determine relative "hot spots" of petroleum-impacted soil in the NCTA. These maps were then used to aid in the placement of the groundwater monitoring wells. Additional data required for placement of the monitoring wells included knowing the location and depth of the many underground utilities at the site.

During the installation of eleven monitoring wells, soil samples were collected using grab and split spoon sampling methods. These samples were analyzed in the field with a photoionization device (PID) to quantify the Volatile Organic Compound (VOC) concentration(s) of the samples. VOC concentrations in the samples generally increased with depth to the water table surface of 15 to 20 feet depth. The highest VOC concentration(s) in soil samples were found in samples collected across the water table surface. The highest VOC concentrations in soil samples ranged from 233 ppm (MW-10) to >8,900 ppm (MW-2).

A portion of the soil sample(s) exhibiting the highest VOC concentration(s) from each monitoring well location was prepared for laboratory analysis. These soil samples were analyzed for Total Petroleum Hydrocarbons (TPH), and Benzene, Toluene, Ethylbenzene and Xylene (BTEX). According to the laboratory Reports of Analysis, the soil samples showed the presence of diesel and gasoline-derived hydrocarbons.

TPH concentrations ranged from 881 milligrams/kilogram (mg/kg; MW-3) to 30,700 mg/kg (MW-8). Total BTEX concentrations ranged from 243.9 micrograms/kilogram ( $\mu$ g/kg; MW-4) to 1,500,300  $\mu$ g/kg (MW-5). The laboratory Reports of Analysis indicated that the TPH concentrations measured in the soil samples collected from MW-2, MW-4, MW-5, MW-6, MW-9 and MW-10 were derived from gasoline. The TPH in the soil samples from MW-3, MW-7, MW-8, MW-11 and MW-12 were derived from diesel fuel.

During a May 1993, groundwater sampling event of MW-1 through MW-9 (MW-10 through MW-12 were not present during May 1993), free phase petroleum product was measured on the groundwater in MW-1, MW-2 and MW-7; these wells were not sampled due to the presence of product. MW-1 had a detectable product skim; MW-2 had 0.36' of product; MW-7 possessed 0.01' of product. Laboratory analysis of groundwater samples collected from the other six site wells in May 1993 (MW-3, MW-4, MW-5, MW-6, MW-8 and MW-9) indicated that Total BTEX concentrations ranged from 9,032 micrograms/liter ( $\mu$ g/l; MW-3) to 41,210  $\mu$ g/l (MW-5). Naphthalene concentrations ranged from 236

 $\mu$ g/l (MW-3) to 525  $\mu$ g/l (MW-4). TPH concentrations ranged from 65.1 mg/l (MW-3) to 215.0 mg/l (MW-9).

Groundwater samples were collected from MW-10, MW-11 and MW-12 between July 16 and July 22, 1993. Laboratory analysis of these groundwater samples indicated that Total BTEX ranged from 1,476.1  $\mu g/l$  (MW-11) to 81,408  $\mu g/l$  (MW-12). Naphthalene concentrations ranged from 124  $\mu g/l$  (MW-11) to 279  $\mu g/l$  (MW-10). TPH concentrations ranged from 15.5 mg/l (MW-11) to 64.2 mg/l (MW-12). The laboratory analytical results indicated that the hydrocarbons resembled a mixture of gasoline and diesel fuel constituents.

During a July 14, 1993, gauging event, MW-1, MW-2, MW-5, MW-7, MW-8, and MW-9 were found to have floating free phase petroleum. The petroleum accumulations were measured to be less than 0.01' in MW-1, 0.16' in MW-2, 0.38' in MW-5, 0.01' in MW-7, 0.03' in MW-8 and 0.45' in MW-9.

The risk assessment of this site included an evaluation of potential sensitive receptors and hydrocarbon migration routes. Possible receptors and/or conduits of VOCs are storm sewers (13'-19' depth) and sanitary sewers (8'-12' depth); these utilities may be at risk for hydrocarbon impact. However, VOCs were not detected in any subsurface structures (i.e. utility manways) in the vicinity of the study area during April and May 1993, site visits. It should be noted that the storm sewer system at the site eventually discharges into the Anacostia River. The Anacostia River is a downgradient receptor located within 1,000 feet of the site. There are no drinking water wells located within a 1000-foot radius of the site. All buildings surveyed in the immediate area (within 1000 feet) use public-supplied water. Public drinking water is supplied to this area by the Government of the District of Columbia, Department of Public Works, Water and Sewer Utility Administration (DC DPW). The DC DPW derives its water supply from the Army Corps of Engineers, who obtain the water from the Potomac River, located to the northeast of the District of Columbia.

The information gathered to date indicates that a plume of free phase (liquid) and dissolved phase hydrocarbons exists under the combustion turbine area. This plume appears to exist from the property boundaries along "S" and Half Streets and encompasses the NCTA. The downgradient extent of the plume (specifically the free phase plume) has not been fully delineated to the southwest and west. The groundwater flow, as measured in this investigation is to the southwest under a relatively flat hydraulic gradient of 0.001 foot per foot (ft/ft).

An area reconnaissance revealed the location of a vacant lot northeast of the site, directly across the intersection of Half Street and "S" Street. A review of DCRA files indicated that the vacant lot was a former fuel terminal operated by Steuart Petroleum, and that site assessment and remedial activities are in

A CONTROL OF THE PROPERTY OF T

process. Based on the information available in DCRA files concerning the Steuart Petroleum site, the following needs to be mentioned:

- the Steuart Petroleum property had been used as a fuel terminal for the storage and distribution of gasoline and fuel oil products from the early 1930's to its closing in 1989,
- 2) free phase petroleum, consisting of mixtures of #2 fuel oil and gasoline, has been found in the subsurface under the site,
- 3) approximately 2,717 gallons of liquid product was estimated to have been recovered at the site between 01/88 and 03/89,
- 4) the liquid phase product plume under the site, based on April 1992, gauging data, extended beyond the Steuart Petroleum property and has migrated under the intersection of "S" Street and Half Street, and had not been fully defined,
- 5) the groundwater flow is primarily to the west, with some of the measured flow being southwesterly toward PEPCO,
- 6) a petroleum hydrocarbon recovery system is currently in operation at the property.

In order to evaluate the site's potential for remediation, as well as evaluate the use of groundwater and product recovery and vacuum extraction technologies, a remedial feasibility test using both technologies was performed on MW-2 in July 1993. During this test, total fluids (groundwater and product) were pumped from MW-2 in order to quantify hydraulic conditions of the water table Vacuum extraction test data was used to determine the effective vacuum influence that can be maintained at the site, and the air flow that can be extracted from the soil using existing Further data evaluation was used to determine the potential hydrocarbon mass recovery rate that can be expected if a pump and treat and vacuum extraction remedial program was implemented at the site. The remedial feasibility test indicated that groundwater recovery and vacuum extraction can be used effectively to remove hydrocarbons from the subsurface at a relatively high recovery rate.

Based on the information and data obtained during this investigation, it appears that the risks to human health and the environment from this site are moderate due to the depth of the observed hydrocarbons in the soils and groundwater. The deeper portions of the storm and sanitary sewers may become impacted as a result of hydrocarbons that may migrate toward these utilities.

Some additional delineation is needed to confirm the extent and the exact source(s) of the subsurface hydrocarbons present at the PEPCO site.

# CORRECTIVE ACTION PLAN REMEDIAL SPECIFICATIONS AND IMPLEMENTATION DETAILS BUZZARD POINT GENERATING STATION HALF & S STREETS, SW, WASHINGTON, DC DC LUST CASE# 93-051 March 10, 1995

#### PREPARED FOR:

Potomac Electric Power Company (PEPCO) 7th Floor 1900 Pennsylvania Avenue, NW Washington, D.C. 20068-0001 (202)331-6489 (202)872-2142/2227 FAX

#### PREPARED BY:

TPH Technology, Incorporated 2017 Renard Court Annapolis, Maryland 21401 (410)224-9300 (410)573-0535 FAX

# CORRECTIVE ACTION PLAN REMEDIAL SPECIFICATIONS AND IMPLEMENTATION DETAILS BUZZARD POINT GENERATING STATION HALF & S STREETS, SW, WASHINGTON, DC DC LUST CASE# 93-051

#### TABLE OF CONTENTS

		SECTIO	NC									P	AGE
1.0	INTRODUC SUMMARY 2.1	OF ASSES	SMENT RESU RIPTION RELEASE H SITE DESCI SUBSURFAI TOPOGRAP REGIONAL	JLTS ISTORY RIPTION CE UTILITIES HY & DRAINAC								 	2
•	2.2	2.1.7 SITE ASSE 2.2.1	HYDROGEO SSMENT AC SOIL GAS.	LOGY TIVITIES & RES WELL INSTALL	ULTS	OIL QUAL	 TY ASSES	SMENT				  	6 8 8
		2.2.2 2.2.3 2.2.4 2.2.5	PRODUCT & ASSESSME SUMMARY 2.2.5.1 2.2.5.1	GING & WATER WATER QUAIN NT OF GROUNE OF REMEDIAL GROUNDWATE SOIL VAPOR V	LITY CHARA DWATER SU FEASIBILITY IR AND PRO ACUUM EX	ACTERIZA URFACE & Y TESTINO ODUCT EX (TRACTIOI	TION PRODUCT TRACTION	PLUME .				 	14 16 17 17
	2.3	2.3.1 2.3.2 2.3.3 2.3.4	ABSENCE OF REDUCTION REDUCTION AREAS TAR	REAS TARGETE OF FREE-PHASE I OF ADSORBE I OF SOLUBLE RGETED FOR RE	PRODUCT D HYDROCAR HYDROCAR EMEDIATION	ARBONS RBONS						 	18 20 21
3.0 4.0	PROPOSED 4.1	PRODUCT 4.1.1 4.1.2	METHOD . PUMPING SY PRODUCT F	YSTEM								 	23 24 24 25
	4.2	4.2.1 4.2.2 4.2.3 GROUNDW	SVE PLUME SVE SYSTE AIR/VAPOR	BING M VACUUM PU EMISSION TRE	JMP	DINTS						 	., 28 ., 28 ., 29 ., 30
	4.4	OPERATIO 4.4.1 4.4.2	N & MAINTE SYSTEM OI PROFESSIO 4.4.2.1 4.4.2.2	NANCE AND PI PERATION & M NAL SERVICES QUARTERLY RI DATA MANAG	ROFESSION, AINTENANC  EPORT TEX EMENT ANI	AL SERVICE	TATION					 	31 31 33 33
5.0	SCHEDULE	OF TIMETA	ABLE			• • • • • • •						 	34
TABLES	TABLE 1: TABLE 2: TABLE 3: TABLE 4: TABLE 5: TABLE 6:	SOIL LABO GROUNDW GROUNDW PERMITS A	PRATORY TE /ATER LABO /ATER LABO REQUIRED FO	STING RESULTS STING RESULTS RATORY TESTI RATORY TESTI OR CAP IMPLEME PLAN IMPLEME	S (TOTAL P NG RESULT NG RESULT JENTATION	PETROLEUM IS (BTEX/M IS (TOTAL	M HYDROC NAPHTHAL PETROLEI	ARBONS,N ENE/MTBE JM HYDRO	MW-18 TO } CARBONS	MW-24)		 	10 12 12
FIGURES													
	FIGURE 2: FIGURE 3: FIGURE 4:	GROUNDW HYDROCA VACUUM	RBON OCCU	ATION MAP (2/ RRENCE MAP ( DURING TESTIN IR PRODUCT LII	2/17/95) . G						 	 	13
APPENDICE	ES APPENDIX APPENDIX APPENDIX	₿:	HYDROGRA	STRATIGRAPHY PHS, CONCEN' RY TESTING RE	TRATION V	. TIME GR	APHS & G	AUGING 8		5 ДАТАВА	SE		

# CORRECTIVE ACTION PLAN REMEDIAL SPECIFICATIONS AND IMPLEMENTATION DETAILS BUZZARD POINT GENERATING STATION HALF & S STREETS, SW, WASHINGTON, DC DC LUST CASE# 93-051

#### 1.0 INTRODUCTION

This document has been prepared pursuant to the District of Columbia, Department of Consumer and Regulatory Affairs, Environmental Regulation Administration, Underground Storage Tank Management Branch (DCRA's) written directive dated November 2, 1994. The Directive required PEPCO to submit a Corrective Action Plan Report (CAP Report) which "addresses all phases of on-site contamination". This task was completed with the submittal of a draft report, dated December 2, 1994, and entitled "Final Preliminary Corrective Action Plan, Remedial Specifications and Implementation Details".

The Directive also required PEPCO to continue to monitor all wells, remove free phase (product) as observed, and submit monthly project status/free product recovery reports until case closure. These tasks are in the implementation process.

The Directive further identified two areas in Buzzard Point requiring additional assessment. The first area was identified as the former gasoline fueling area located at 180 S Street, SW (PEPCO/Chevron site). The second area was the active above-ground storage tank farm (AST farm). The assessment of these areas were conducted concurrent with the finalization of the CAP and the information gained from the assessment is presented herein, along with the reiteration of previous assessment information, and re-iteration of the CAP. The report has been prepared as the final document for the Comprehensive Site Assessment and Corrective Action Plan requirements as set forth by DC UST Regulations, DC Municipal Regulations, Title 20, Chapter 62.

The results of all work completed between April 1993 and July 1993 were reported in a Comprehensive Site Assessment (CSA) Report, dated August 11, 1993. An Addendum to the CSA Report was then submitted November 8, 1993, which reported the results of an off-site assessment located at the former 20,000-gallon UST property (180 S Street), west of the CT Yard. A third document was then submitted June 3, 1994 which summarized the results of first quarter 1994 assessment activities and discussed the results of work completed between April 1993 and April 1994.

Included herein is an overview of the results of soil and groundwater quality assessment activities completed at the Combustion Turbine Yard (CT Yard) between April 1993 and February 1995, and the results of additional subsurface assessment activities and the AST farm and former gasoline fueling area (PEPCO/Chevron Site) completed between December 1994 and February 1995. The CT Yard assessment activities included a soil gas survey, installation of sixteen 4"-diameter monitoring wells, sampling and analysis of soil, groundwater and free-phase product samples, and periodic gauging and bailing of product accumulations in twelve of the sixteen wells. The results of the work completed through October 1994 indicated that the free-phase product plume covered a relatively larger area than



the original reported petroleum release volume would suggest. The results of the work also indicated that portions of the product plume were of a gasoline-like origin; however, the only reported petroleum release within the CT Yard was #2 heating fuel oil. Recent assessment activities, including the installation of seven additional 2"-diameter monitoring wells and associated soil and groundwater sampling and analyses, were completed in and around the AST farm and the PEPCO/Chevron site (180 S Street). This recent work was performed in an attempt to identify potential contributing sources of the free-phase petroleum products previously identified in the wells within CT Yard boundaries.

#### 2.0 SUMMARY OF ASSESSMENT RESULTS

#### 2.1 SITE DESCRIPTION

#### 2.1.1 RELEASE HISTORY

In 1968, a 4"-diameter underground pipeline was installed at the CT Yard to supply the combustion turbines with fuel oil from the AST farm located to the north of the CT Yard and S Street, SW. During early 1970's, a fuel oil pipeline leak was detected and repaired. A 15"diameter monitoring well (MW-1) was then installed near the location of the leak. On January 29, 1993, PEPCO personnel discovered the presence of a liquid petroleum product in MW-1, and notified the DCRA. The DCRA then requested that a sample of the petroleum product be collected and analyzed for characterization, and recommended that a submersible pump be lowered into the well and the liquid petroleum be pumped from the well. On February 1, 1993, PEPCO collected a sample of the petroleum product from MW-1, and submitted such to an independent laboratory for analysis. According to the laboratory Report of Analysis, the sample was a "bi-phase" liquid: the top layer of the sample was a petroleum product and the bottom layer was "aqueous". The aqueous portion of the sample was analyzed for Benzene, Toluene, Ethylbenzene, and total Xylenes (BTEX), Volatile Petroleum Hydrocarbons and Semi-Volatile Hydrocarbons (TPHC). The BTEX concentration in the aqueous sample was 2,120 micrograms/liter ( $\mu g/l$ ). The TPHC concentration in the aqueous sample was 60,000  $\mu g/l$  TPH-Volatile and 160,000  $\mu$ g/l TPH-Semivolatile (or 220,000  $\mu$ g/l TPHC). The petroleum product layer was analyzed for flash point; flash was observed at 162°F. A copy of the Report of Analysis was provided in PEPCO's August 1993 Report to the DCRA.

On February 23, 1993, PEPCO sumitted a letter to DCRA stating that DCRA's recommendations for laboratory analysis and pump installation had been followed, and PEPCO planned to continue the pumping and recovery of petroleum product until May 1993, in an effort to determine whether or not the product would dissipate with pumping. If after May 1, dissipation of the product seemed unlikely, PEPCO would make a determination as to whether a Comprehensive Site Assessment and a Corrective Action Plan would be necessary. After review of PEPCO's proposed plan for continued pumping of the petroleum product, the DCRA issued a directive requiring a Comprehensive Site Assessment and Free Product Abatement (FPA) until further notice. In response to the written directive, PEPCO initiated the Comprehensive Site Assessment in May 1993.

#### 2.1.2 SITE DESCRIPTION

The CT Yard is located at "Half & S Streets", SW, Washington, DC (38°52'00" latitude and 77°00'40" longitude). The facility consists of five operating or activity areas. Facilities within these areas are depicted in Figure 1, and are discussed in greater detail below.

Area 1: power station, switchyard, and combustion turbine area,

Area 2: retired #6 fuel oil tank and laydown area,

Area 3: gasoline fueling and conduit building area,

Area 4: #2 fuel oil tank yard, and

Area 5: screen house area.

Area 1 consists of the power station, switchyard and combustion turbine area, and is at the center of the five operating areas. The power station consists of six retired oil-fired steam generators and related equipment. The power station was fueled by coal prior to the use of oil. This power plant was activated in 1928 and continued operation until 1981. The switchyard was historically used as the power station's coal yard prior to becoming the switchyard. The CT Yard consists of 16 combustion turbines, associated equipment and work trailers. The CT Yard serves as a substation when not used for generating power during periods of peak demand. The CT Yard and switchyard are the primary areas of interest of this investigation and remediation project.

The retired #6 fuel oil tank and laydown area is west of the decommissioned power station. The retired #6 fuel oil tank is a 1.9-Million gallon AST, used to fuel the oil-fired steam generators via an underground pipeline buried under First Street. This tank was taken out of service when the power station was decommissioned in 1981. A fire fighting foam house is located next to the retired #6 fuel tank. This fire fighting foam house is still operable. The remaining portion of this area is used for storage by a private contractor and by the Federal Bureau of Investigation for vehicle storage. Prior to the construction of the #6 fuel oil tank and foam house, this area was used as a coal yard.

North of the retired #6 fuel oil tank area and west of the CT Yard is the former gasoline fueling and old conduit building area (PEPCO/Chevron site or 180 S Street site). This area consisted of a former maintenance building now used for storage, and an unmanned gasoline distribution area. The gasoline distribution area was supplied with gasoline via a 20,000gallon underground fiberglass reinforced plastic storage tank (assessed within the November 1993 Report). This tank was removed in early August 1993 as part of a scheduled cost cutting measure and not due to any known release problems. The tank had passed structural integrity pressure testing on July 31, 1992. DCRA directed that this area be assessed after initiating assessment of the CT Yard. Subsequent to the submittal of an assessment report for this site to the DCRA, DCRA issued a letter approving conditional closing of this case. However, the recent DCRA Directive issued in November 1994 required that the "180 S Street" site be assessed. Since this time, it was determined that the former gasoline fueling area site and the PEPCO/Chevron site are the same exact site at 180 S Street. In order to support the findings of the initial assessment and provide further areal wide information, an additional monitoring well (MW-21) was installed in this area in close proximity to MW-13 (installed to initially assess the property and used to gain the initial conditional closure).




FIGURE 1: SITE MAP

North of the CT Yard is the AST farm. This area contains two .411-million gallon ASTs, two truck unloading pads, and a fire fighting foam house. The ASTs service the combustion turbines in the CT Yard via an underground pipeline located beneath the eastern half of S Street between First and Half Streets, SW. This area was recently assessed to determine if it represented a potential source of the free-phase petroleum found beneath the CT Yard. Six monitoring wells were recently installed in the area of the ASTs and between the ASTs and the CT Yard along the northern side of S Street (MW-18, 19, 20, 22, 23 and 24).

East of the decommissioned power station is the screen house. This building was used to supply cooling water to the power station and was decommissioned at the same time as the power station (1981).

#### 2.1.3 SUBSURFACE UTILITIES

The CT Yard is heavily covered by overhead utilities and underlain by underground utilities, the latter being mainly high-voltage electrical lines and #2 heating oil lines. Telephone services are supplied via underground lines serviced by Bell Atlantic. The telephone and electric lines servicing the PEPCO substation site are located underground. The site is supplied water by the District of Columbia, Department of Public Works, Water and Sewer Utility Administration (DC DPW). Water mains are located approximately 4' to 6' beneath the center of Half, First, S and T Streets. Specifically, T Street is the "southern" border of the CT Yard. Sanitary and storm sewer mains, maintained by the DC DPW, are located 8' to 12' beneath the center of Half, First, S and T Streets. The storm sewers flow west towards Second Street where they empty into a  $\approx 7 \frac{1}{2}$ ' diameter storm sewer main which then discharges southerly to the Anacostia River. Several smaller storm drain systems are located in the centers of S and T Streets. These storm sewers flow east and discharge into the Anacostia River. Natural gas is supplied by Washington Gas Energy Systems, Inc.

#### 2.1.4 TOPOGRAPHY & DRAINAGE

The elevation of the CT Yard is  $\approx 20'$  above mean sea level. The site gently slopes towards the south-southwest towards the Anacostia River. Surface water from the site is controlled by curb-side gutters and storm sewers. Surface run-off from the site is directed primarily to the west (to Second Street).

#### 2.1.5 REGIONAL GEOLOGY

The site is located in the Atlantic Coastal Plain Physiographic Province. According to the USGS "Geologic Map of Washington, D.C. and Vicinity," the site is located on the Pamlico Formation and Recent Alluvium. The Pamlico Formation is composed of gravel, sand and silt, and fill.

#### 2.1.6 LOCAL GEOLOGY

Soil samples collected during assessment activities indicated that the texture and lithology of the soil beneath the CT Yard are consistent with the Pamlico Formation. Some areas of the site have been cut and re-filled with fill as the historical use of the Buzzard Point area was at one time residential. The soil beneath the site was primarily silty sand with minor amounts of gravel. Coarse-grained gravel layers were encountered in the eastern half of the study area at  $\approx 25'$  depth, and underlain by a red-brown clay. With increased distance to the west, the soil lithology becomes more clayey. All soil borings were terminated upon reaching this clay material, if encountered, or 25' to 27' depth to maintain well depth consistency. The vadose zone soil is composed of stratified silty loam and clayey silts. The water table aquifer sediments consist of fine to medium grain sand with minor fractions of silt and gravel; again, in the western direction, an increased portion of clay can be discerned in the water table sediments.

The lithologic profile of the former PEPCO/Chevron site, as defined by the drilling and soil sampling of MW-13 and MW-21, was characterized by a firm, silty, red clay fill to a depth of 25' which is underlain by a medium to coarse grained, water-saturated sand. This area differs from that described for most of the CT Yard and likely reflects a fill zone created during removal and over-excavation of the former USTs from this area and historical land use. Appendix A provides a table summarizing the lithologic profile of all monitoring wells installed at the PEPCO facilities, along with the geologic and well construction logs of MW-18 through MW-24.

#### 2.1.7 HYDROGEOLOGY

Based on gauging data collected between May 1993 and February 1995, the depth to groundwater beneath the site has averaged  $\approx$  19' below grade with a range between 15½' to 20½' due to topography and seasonal fluctuations. Between November 1993 and February 1995, the elevation of the groundwater surface has fluctuated within an average range of  $\approx$  3', with the highest water level being recorded in the March-April 1994 time period, and the lowest being recorded most recently in February 1995. The groundwater flow direction is to the west-southwest under a hydraulic gradient of 0.0003 to 0.001 foot per foot (ft/ft, depending on time of year and depth of water table surface). Steeper gradients were measured during May to August 1993; smaller gradients were measured during February to May 1994.

Figure 2 provides a contoured groundwater elevation map of the study area. Please note, previous reports have used different elevation datums to construct groundwater elevation maps. Per DCRA Policy, top of well casing (TOC) elevations are to be surveyed to a USGS benchmark, as was completed for the June 1994 Report. However, because the surface elevation is  $\approx 20'$ , and the depth to the water table surface near 20', corrected water table elevations are actually below mean sea level (e.g. negative elevation). To relieve confusion, Figure 2's groundwater map uses a benchmark datum arbitrarily affixed with a relative elevation of 50' from which site wells (or TOCs) have been surveyed.




FIGURE 2: GROUNDWATER ELEVATION MAP (2/17/95)
0.10 CONTOUR INTERVALS

Based upon pumping test data obtained in July 1993 from MW-2, the transmissivity (T) of the water table aquifer is 18,620 gallons per day per foot (gpd/ft). The hydraulic conductivity is 2,325 gallons per day per square foot (gpd/ft²), using a saturated thickness of 8' [25' to top of clay depth - 17' average depth to water during time of pumping test = 8' saturated thickness]. The natural pore velocity ( $V_{nat}$ ) of the water table aquifer is estimated to be on the order of ½ to 1½ feet per day (≈ 170 to 565 feet per year), assuming an effective porosity ( $\Phi_{a}$ ) of 0.2.

#### 2.2 SITE ASSESSMENT ACTIVITIES & RESULTS

### 2.2.1 SOIL GAS, WELL INSTALLATION & SOIL QUALITY ASSESSMENT

Before subsurface exploration work was initiated in early 1993, a product sample was collected from MW-1 (the existing 15" diameter well) and analyzed for Polychlorinated Biphenyls (PCBs) and flashpoint. Laboratory analysis of this sample did not detect the presence of PCBs at or above the laboratory detection limits. Flash was observed at 55°C (131°F).

The initial site assessment at the CT Yard included a shallow soil gas survey (SGS). The purpose of the SGS was to analyze soil pore vapor at  $3\frac{1}{2}$  to 10' depth for the presence of BTEX, Total Volatile Hydrocarbons (TVHC,  $C_4$  -  $C_9$ ), and Total Semi-volatile Hydrocarbons (TVHC  $C_{10}$  -  $C_{25}$ ). Soil gas samples were collected from 52 locations in and around the CT Yard. Based on the distribution of hydrocarbon concentrations in SGS sample locations, proposed locations of eight monitoring wells were selected. The methodology and results of the survey are reported in the August 1993 Report.

Between May 10 and 13, 1993, eight monitoring wells (MW-2 through MW-9) were installed in the CT Yard using hollow stem auger (HSA) drilling methods. Three additional monitoring wells were installed in the CT Yard using HSA methods on July 6 and 22, 1993 (MW-10, MW-11 and MW-12). On October 11, 1993, MW-13 was installed using HSA methods in the confines of the former tankfield of the 20,000-gallon UST located on the 180 S Street. MW-13 was discontinued for site assessment purposes in July 1994 pursuant to PEPCO's receipt of DCRA's "letter of compliance" approving closure of the 20,000-gallon UST site project. However, as stated above and latter in this report, this site/case was re-opened per the DCRA Directive to assess 180 S Street (PEPCO/Chevron site) which had also contained two additional USTs used for gasoline and diesel storage. Between January 25 and 31, 1994, MW-14, 15, 16 and 17 were installed within and immediately outside the walls of the CT Yard using HSA methods. The existing 15" diameter observation well was designated as MW-1. Subsequent to the November 2, 1994 DCRA Directive, seven additional monitoring wells (MW-18, 19, 20, 21, 22, 23 and 24) were installed using HSA techniques in the AST farm and the above mentioned 180 S Street site (former PEPCO/Chevron fueling area) between January 27 and 30, 1995.

During drilling operations of the above wells, soil samples were collected using split spoon and grab sampling methods, and screened in the field for the presence of VOCs using a photoionization device (PID) and the headspace analysis technique. Each sample jar was filled to approximately 3/4 capacity to create a headspace. Additionally, from each well location, a portion of the soil sample exhibiting the highest VOC concentration or the soil sample collected across the apparent groundwater surface (if all soil samples exhibited less than detection limits for VOC within a borehole) was submitted to a laboratory for analysis of BTEX and TPHC, using EPA Methods 8240 and 8015, respectively. Soil samples from MW-18 through MW-24 were also analyzed for Naphthalene.

Appendix A summarizes the soil profile, soil quality data and approximate screened intervals of MW-2 through MW-24. A geologic and well construction log for MW-1 and an assessment of its soil quality was not produced during installation by PEPCO. Well logs for MW-2 through MW-17 are available in the August and November 1993, and June 1994 Reports. Well logs for MW-18 through MW-24 are contained in Appendix A. Laboratory Reports of Analysis for soil samples obtained from MW-2 through MW-17 are contained in previous reports.

Analytical testing results for soil samples collected during the recent supplemental assessment using MW-18 through MW-24 are summarized in Tables 1 and 2. As shown, the soil samples selected for laboratory analysis (exhibiting the maximum volatile vapor readings during field screening) consistently were encountered at or about the depth of the water table surface (e.g. 20' to 22' depth), suggesting migration of these compounds from a distal source via the groundwater surface. The highest BTEX concentration was identified in the sample collected from MW-20 at 20' to 22' depth (1.028 milligrams per kilogram (mg/kg)). Benzene was generally non-detectable in all of the samples collected from MW-18 through MW-24, with the exceptions of the soil samples collected at 20' to 22' from MW-23 and 24. The maximum TPHC concentration was detected in the sample obtained from MW-20 (2350 mg/kg TPHC-Gasoline Range Organics, or TPHC-GRO). Detectable TPHC compounds, primarily measured and reported as Diesel Range Organics (DRO), were also found in the samples collected from MW-19, 23 and 24. Naphthalene was found in four of the seven soil samples (MW-19, 20, 23 and 24) ranging to a high of 0.356 mg/kg in MW-20.

Minor indications of adsorbed phase hydrocarbons (measured as VOCs using the PID-headspace method) were encountered at shallower depths (10' to 15' depths) in MW-19, 20 and 23, as summarized in Appendix A's Soil Quality & Lithology Table. Even in consideration of these areas of hydrocarbon presence, there was a general lack of qualitative or quantitative data indicating that the AST farm or the former PEPCO/Chevron site are major contributing source(s) of the hydrocarbons on and within the water table beneath the CT Yard.

All soil cuttings resulting from the drilling operations were stockpiled on-site. A composite soil sample was collected from the stockpiles and analyzed for disposal characteristics after the "May 1993" wells were installed. These analyses included: BTEX, TPH, EOX (Extractable Organic Halogens), PCBs, TCLP (Toxicity Characteristic Leaching Procedure)-Metals, Corrosivity (pH), Ignitability (Flashpoint), % Moisture (% Solids) and Reactivity (with water, sulfide and cyanide. PEPCO has disposed of all soil generated during drilling activities.

Soil Analytical Testing Results for MW-18 through MW-24. PEPCO-Buzzard Point.

Sample Identification	Sample Identification   MW 18/10 21 #   444/10/1	Affair do con con service	MW 40/20 20 5: THE TAIL INSPIRE SHE	nititalene)			
	╁	WW-19/ZU-ZZ TT.	MW-20/20-22 ft.	MW-21/25-27	MW22/20-22	MW23/20-22	MW24/20-22
Benzene	Į pą	lod					
Ethylbenzene	10.4	200	iba .	ā	Ιbα	1.38	403
Tolitono		2.68	260	pd	pq	44.8	207
plonic	iba	jba	lbq	þd	iod		
Xylenes	pd	þal	768	7	3	Da l	B
Total BTEX	pal	89.2	4 020	1.87	þa	141	93.1
Naphthalene	lod	27.4	1,040	1.87	þáj	187.18	198.13
	5	1/7	356	pd	lbq	27.7	79.9
Notes: Results reporte	Results reported in ug/kg. parts-per-billion		A mothod	. 7 7			
Method SW 846 8240	8240		Dar velow method quantitation levels.	Itation levels.			
able-2 Soil Analytical	Teefing Decition III	141 40 41					
Sample Identification	MAN 48140 24 44	W-19 through MW-	24(Total Petroleum	Hydrocarbons)			
MW-21/25-27 ft. MW-20/20-22 ft. MW-21/25-27	1113-619-6111	MW-19/20-22 ft.	MW-20/20-22 ft.	MW-21/25-27	MW22/20-22	MW23/20-22	MW24/20-22
Diesel Fuel	100	000					77
Gasoline	2 2	000	B	þq	Ē	7.5	900
Heavy Oil	50 .0	ğ .	2530	pdq	lpd	led	125.0
Jet Fuel	50 50	-ba	Ιbα	jbq	<u>pd</u>	pal	3 3
Kerosene	3	<u></u>	מַּן	pd	pg	hal	3 1
Mineral Oil	בל בל	Da	jbq;	<u>pd</u>	bai	į	3
Naptho	Iba	]ba	pd.	pq	bal	- FG	- Da
l'Adpuid	iba	jbq	pa	154	1 1	-50	iba
Paint Ininner	þď	þd	Pal	7 3	iha i	pdi	pd
Stoddard Solvent	ba	hal	7 7	3	jba	jbq	ğ
Total Unknown	pal		יילו	iba	pd	bd	pa
			- Da	ba	pd	þď	pa
Notes: Reported in ma/Kg parts-ner-million	Ka parts-per-millio	100					ř
Method 8015 Modif	dif.	ב קר	perow memod quantitation limits.	imits.			
		_					

#### 2.2.2 WELL GAUGING & WATER QUALITY ASSESSMENT

With the exception of recently installed MW-18 through MW-24, relative elevations of the site wells' top of casings (TOCs) and grade level were surveyed by a licensed surveyor using an established USGS elevation benchmark. Elevation measurements for MW-18 through MW-24 were tied into the previously established site elevation grid, but the benchmark was affixed with an arbitrary datum of 50' to allow for easily understandable groundwater elevations. This was done because the depth to the water table surface is  $\approx 20'$ , and corrected water table elevations were historically near zero elevation or negative elevation (e.g. below mean sea level).

Depths to product (if present) and groundwater have been measured ≈ 36 times between May 1993 and February 1995. Measurements were made using an audible, oil/water interface probe, and were taken from the north rim of the TOCs with 0.01' accuracy. The relative groundwater elevations in the wells were calculated by subtracting the measured depth to groundwater in a well from the respective TOC elevation. If free-phase product was present, the depth to groundwater was calculated by subtracting the measured depth to groundwater from the TOC elevation and adding the value of product thickness multiplied by product specific gravity. The in-situ specific gravity of the product in MW-2 was measured to be 0.86. Appendix B provides hydrographs for all site wells depicting the groundwater surface fluctuations and product accumulation fluctuations. Appendix B also provides the groundwater gauging and sampling database from which the hydrographs are based.

Groundwater quality in site wells has been assessed twice in most wells in the study area, except for the more recent MW-18 through MW-24. Because most site wells contain freephase product, repeated groundwater sampling (e.g. quarterly schedule) was not imperative to assess groundwater quality. Groundwater sampling events were conducted on May 19, 1993 (sampling of MW-3, 4, 5, 6, 8 and 9), July 14 and 23, 1993 (MW-10, 11 and 12), October 19, 1993 (MW-13), February 24, 1994 (MW-3, 4, 6, 8-14 and 17) and January 1995 (MW-18, MW-19, MW-20, MW-21, MW-22, MW-23 and MW-24). During the May 1993 event, MW-1, 2 and 7 contained free-phase product and were not sampled, MW-10 through MW-17 did not exist at the time. During the July 1993 events, only MW-10, 11 and 12 were sampled as part of the expansion of the monitoring well network. During the October 1993 event, only MW-13 was sampled as part of the assessment of the 20,000gallon UST site. During the February 1994 event, MW-1, 2, 5, 7, 15 and 16 contained product and groundwater samples were not collected. During the May, July and October 1993 events, BTEX, Naphthalene and TPHC were analyzed using EPA Methods 624 and 8015M. During the February 1995 event, BTEX, Naphthalene, TPHC and Methyl-tert Butyl Ether (MTBE) were analyzed using the same EPA Methods.

The results of the sampling events are depicted graphically in Appendix B; the database for the groundwater quality results are also tabulated within the gauging and sampling database of Appendix B. Copies of the laboratory Reports of Analysis for historical sampling events are provided in the August and November 1993, and June 1994 Reports. Tables 3 and 4 present a summary of water quality data obtained from MW-18 through MW-24. Copies of the laboratory results for these analyses are contained in Appendix C. The analytical results are also displayed on the hydrocarbon plume map presented as Figure 3.

Groundwater Quality for MW-18 through MW-24, PEPCO Buzzard Point (2/8/95)

Sample Identification							
	MW-18	MW-19	MW-20	MW-21	MW-22	MW-23	MW-24
Benzene	22.4	pd	10.8	1.23	<u>P</u>	161	754
Ethylbenzene	þd	64.6	443	jbq	bd	2610	1170
Toluene	1.45	bd	pq	1.16	Ibq	288	lod
Xylenes	þd	þd	1310	þq	3.62	11600	1020
Total BTEX	23.85	64.6	1763.8	2.39	3.62	14659	2944
Naphthalene	2.49	171	171	2.1	pal	651	738
MTBE	lþd	pd	lpd	85.1	þd	Jbq	]bq
Notes: Results reported in ug/L, parts-per-billion.	n ug/L, parts-per-	æ	QL=below method quantitation limits	ation limits.			
Method 624							
						- management of the second	
Table 4 Groundwater Analytical Results (Total Petroleum Hydrocarbons)	ialytical Results (	Total Petroleum H	ydrocarbons)				
Sample Identification	MW-18	MW-19	MW-20	MW-21	MW-22	MW.23	AC INTAN
Diesel Fuel	1.14	144	þd	pq	pq	log log	164
Gasoline	-ba	lbq	15	bd	pq	267	2
Heavy Oil	pd	]bq	þd	jbq	bal	pd	, c
Jet Fuel	þd	pd	þd	þd	Įbą	Įpq.	Pol
Kerosene	pdį	þq	lþq	þd	pq	bal	5 6
Mineral Oil	Jbq	pd	þd	lpd	pdi	bal	ָבָּבְּיבָרָבְיבָּיבְיבָּיבְיבָּיבְיבָיבְיבָיבְיבָיבְיבָיבְיבְיבָיבְיבְיבְיבְיבְיבְיבְיבְיבְיבְיבְיבְיבְי
Naptha	þd	þd	þď	þď	pq	hal	7 2
Paint Thinner	þd	þq	þá	bal	þa	100	
Stoddard Solvent	þd	- Ibq	jbq	pal	pol	7	מַלַ
Total Unknown	þþq	þd	þd	þd	DQ.	- Jod	50 2
							7
Notes: Results reported in mg/L, parts-per-million.	n mg/L, parts-per		BQL=below method quantitation limits	tation limits			
Method 8015 Modif	1					-	




FIGURE 3: HYDROCARBON OCCURRENCE MAP (2/17/95)
CONTOUR INTERVALS (FEET)

As shown in Tables 3 and 4, dissolved hydrocarbon constituent were identified in water samples collected from all seven newly installed wells. The highest BTEX concentration measured in the recent monitoring well samples was in the sample collected from MW-23 (14.659 milligrams per liter, mg/l); the lowest was 0.00289 mg/l BTEX, as measured in the sample collected from MW-21, located at the 180 S Street site (former PEPCO/Chevron site). Total dissolved BTEX concentrations less than 0.1 mg/l were found in the water samples collected from MW-18, MW-19, MW-21 and MW-22. The remaining three wells contained 1.7638 mg/l (MW-20), 2.444 mg/l (MW-24) and 14.659 mg/l (MW-23).

Naphthalene, a common component of most fuel oils (including gasoline), was detected in groundwater samples from MW-18, MW-19, MW-20, MW-21, MW-23 and MW-24 ranging to a high of 0.738 mg/l in MW-24.

Dissolved Total Petroleum Hydrocarbon (TPHC) compounds characteristic of diesel fuel range organics (TPHC-DRO) were detected in the groundwater samples obtained from MW-18 (1.14 mg/l), MW-19 (144 mg/l) and MW-24 (164 mg/l). Gasoline range TPHC compounds (TPHC-GRO) were found at concentrations of 15 mg/l (MW-20) and 267 mg/l (MW-23).

#### 2.2.3 PRODUCT & WATER QUALITY CHARACTERIZATION

Product characterization analyses were performed on product samples collected from MW-1, 2, 5, 7, 15 and 16 on February 24, 1994. Please note that these six wells were the only wells to contain product on this date. Subsequent gauging events have indicated that product is typically present in all but four of the CT Yard's 16 "on-site" wells (MW-3, 4, 12 and 14). This February 1994 sampling event (groundwater and product sampling) was performed in response to DCRA's request for mutual site assessments between PEPCO and Steuart Investment Company (SIC), representatives of the owner/operator of former petroleum handling facilities on the property located immediately northeast (and hydraulically up-gradient) of the CT Yard and immediately east of the AST farm. The results of the February 1994 sampling event, and a discussion of the implications of the results are provided in the June 1994 Report, and in SIC's Report, dated June 24, 1994 (prepared by Greentree Compliance Incorporated (GCI), consultant to SIC). The product characterization activities resulted in the following conclusions and/or items of concern:

- The products in PEPCO site wells were a mixture of diesel-range distillates (e.g. #2 heating oil) and gasoline-derived compounds. The majority of the diesel-range product was concentrated in the vicinity of MW-1 and 2 (the original release location of the #2 heating oil) with ≈ 75% or more of fuel oil and 25% or less of gasoline. Gasoline components represented 70% to 90% of the products in the samples collected from MW-5, 7, 15 and 16.
- The gasoline components in the above wells were identified to be of 1980s vintage by SIC and GCI's subcontracted laboratory, World Geosciences Incorporated (WGI). MW-16 product's gasoline contribution (≈90%) was identified by WGI to be early to mid-1980s, and is similar to the gasoline contribution to one of SIC's most down-gradient wells (SIC MW-24). The product in SIC wells also contains 1970s vintage gasoline (not originating from SIC historical operations), and pre-1970 gasoline (which was derived from historical operations at the SIC property).

- The 1970s/1980s vintage gasoline products in PEPCO and SIC wells has been determined to not originate from any historical PEPCO activity within the CT Yard-Buzzard Point Facility. Further, such did not originate from any historical activity within the SIC property.
- PEPCO MW-9 and 12 were impacted by minimally degraded fuel oil, with some characteristics indicating their source is from the same/similar source impacting MW-5 and 16.
- The dissolved hydrocarbons in SIC's MW-25 water sample appeared to be derived from fuel oil associated with free product in PEPCO MW-15.
- Portions of the soluble hydrocarbons concentration signatures of the groundwater in MW-4 and 6 are similar to that displayed in MW-9 and 12, but MW-9 and 12 lack a fuel oil contribution.
- The gasoline source impacting MW-8 is different than the gasoline source which impacted MW-4, 6, 9 and 12. Portions of MW-8's gasoline signature are similar to that in MW-3 and 10, and SIC MW-24.
- The gasoline contributions to the groundwater in MW-17 could be a mixture of that from MW-3, 8 and 10, with that from MW-4, 6, 9 and 12.
- The water sample from PEPCO's MW-11 had predominately Benzene, and its hydrocarbon source was not indicative of a gasoline or fuel oil sources.

In consideration of the water quality beneath the CT Yard, the February 1994 groundwater analytical results of MW-3, 4, 6, 8-14 and 17 also indicated the following. By March-May 1994, MW-6, 8, 9, 10, 11 and 17 had since developed free-phase product. The groundwater surface had increase to its recorded high during early April 1994, and then began to decline by late-April 1994, and continued to decline through late-June 1994. Groundwater level fluctuations remained within a relatively small range between late-June 1994 through September, when in October 1994, the fluid levels began to decline. The water table surface in February 1995 is the lowest recorded water level.

At the time of this writing, liquid-phase hydrocarbons have not been observed in any of the seven recently installed monitoring wells (MW-18 through MW-24). Groundwater quality data obtained from MW-18 through MW-24 are the basis of the following general observations and conclusions regarding the nature and origin of the hydrocarbons in the CT Yard.

Benzene typically represents a very low proportion (average of <4%) of the BTEX suite in groundwater samples exhibiting total BTEX concentrations 0.1 mg/l (i.e. MW-20, MW-23 and MW-24). The absence of dissolved Benzene is consistent with the BTEX ratios of associated soil samples and is likely the result of weathering of an aged gasoline product and/or an indication of a non-volatile hydrocarbon source (i.e. diesel fuel) for these compounds.



- Elevated dissolved BTEX concentrations detected in MW-20 and MW-23 are found in combination with the presence of elevated Naphthalene concentrations (171 and 651 mg/l, respectively) and dissolved TPHC-GRO concentrations (15 and 267 mg/l, respectively) suggesting a mixed weathered gasoline/diesel fuel source.
- MW-18, located on the hydraulically up-gradient portion of the AST farm, contained dissolved hydrocarbon compounds at a concentration of 0.02385 mg/l BTEX, 0.00249 mg/l naphthalene and 1.14 mg/l TPHC-DRO, suggesting some degree of area-wide groundwater degradation and potential up-gradient source(s).
- MW-21, located within the tank pit excavation of the former PEPCO/Chevron site (drilled near MW-13, but screened into the lower regions of the water table aquifer, with MW-13 screened in the backfill material of the former 20,000-gallon UST tankfield), exhibited near non-detect BTEX concentration of 0.00289 mg/l BTEX. MTBE was also detected in this well's water sample at 0.0851 mg/l, suggesting minimal leaching from residual vadose zone source material in this area.

#### 2.2.4 ASSESSMENT OF GROUNDWATER SURFACE & PRODUCT PLUME

Based on the ≈36 groundwater gauging events conducted between May 1993 and February 1995, the groundwater surface has been well characterized. Figure 2 provides a contoured water table elevation map based on gauging data collected in February 1995. Figure 3 provides a contoured product accumulation-hydrocarbon occurrence map, based on product accumulations measured in site wells on February 17, 1995, and TPHC concentrations measured in January 1995 (of MW-18 through MW-24). Please note, the product accumulation in site wells is a reflection of the extent of product within the subsurface, but does not reflect the actual thickness found in the native soil. Typically, the product thickness in the soil is on the order of 6% to 30% of the product accumulation in a typical 4"-diameter monitoring well. The relativity of the actual thickness within the soil, as compared to that which can be measured in monitoring wells was not measured at this site. However, based on site geology, the ratio of actual thickness (within the soil) versus apparent thickness (within the well(s)) may be on the order of 20% to 30% (e.g. 0.2 to 0.3). Based on the extent of the free-phase petroleum plume, as depicted in Figure 3, the average product thickness in site wells in and immediately adjacent to the CT Yard is ≈0.27'. Thus, the actual thickness in the water table aguifer soil is ≈0.05' to ≈0.08'. The product plume encompasses an area of at least 17,200 square feet. Assuming that the porosity of the water table aquifer is ≈ 25 to 35%, the product plume on February 17, 1995, and as depicted in Figure 3, represented 1,600 to 3,600 gallons of petroleum. Please note, the product plume is not defined east of MW-16 and west of MW-15. Additional delineation of the plume in the area between MW-8 and MW-14 is proposed to be addressed during corrective action activities, as discussed later in this document.




**Environment Management Services** 

Certified Mail - 70011140000299426668

June 7, 2002

Mr. Kofi Berko, Ph.D. DC Department of Health EHA/UST Division 51 N St., NE, 3rd Floor Washington, DC 20002



Re: LUST Case # 93-051 - Buzzard Point Station

Dear Dr. Berko:

This letter and attachments 1-8 constitute Pepco's progress report on the status of the groundwater remediation project at Buzzard Point Station. The attachments were prepared by TPH Technology, Inc. for Pepco. As DOH is well aware, Pepco remains fully committed to its goal of remediating of petroleum product at Buzzard Point Station. However, based on a review of the past year recovery operation and results of recent well gauging and sampling of selected wells, Pepco strongly believes that the free phase product has been removed to the maximum extent practical by application of two remediation systems in place since 1996. Accordingly, Pepco is seeking approval to move to a passive remediation phase in removing the de minimus amount of petroleum that remains at this site.

From January 1996 - November 1999, a soil vapor extraction - product pumping system operated at Buzzard Point station to address the petroleum contamination underneath the combustion turbine area. This system removed approximately 6925 gallons of petroleum. By November 1999, the rate of recovery was so slow due to lack of petroleum that the system was deactivated. Monitoring and gauging of the wells continued while alternative measures were studied for recovery of remaining mass of petroleum at the site. In May 2001, a portable high vacuum pump and treat system was installed to recover product from two monitoring wells (MW-5 and 11) that contained the largest amount of product. This system operated on MW-5 from mid May - June 2001 and then operated on MW-11 from July 2001-April 2002. In total, the system removed an estimated 1.5 million gallons of groundwater and 1,350 gallons of petroleum from the two wells. Groundwater sampling of selected wells and gauging of all wells were conducted February - April 2002 (Attachment 1 and 2 respectively). The recovery system was removed from service on April 2 in order to allow ground condition to stabilize while a review of the past year recovery data is conducted to determine the next feasible course of actions.

A review of the past year recovery operation indicates that the vacuum enhanced pump and treat system has removed the free phase product from the two wells, MW-5 and 11 that contained the largest amount of petroleum, to the maximum extend practical. This system was originally installed to operate on MW-5 and 11 for two (2) months. However, with severe regional draught, causing a large drop in groundwater table, which in turn exposed the entrapped product in the soil below groundwater table, the operation of this system was extended to eleven (11) months to maximize the recovery of product. Based on the April 2, 2002 gauging data, the thickness of product in MW-5 was Zero and in MW-11 was 0.01 feet. In addition, the pump could not sustain a longer-term operation without tripping. The natural iron content of the local groundwater cause clogging of the pump and associated equipment and further operation of this system requires a prolonged funding for O&M with unappreciable recovery rates.

Attachment 1 shows the sampling data for seven wells (MW-4, 5, 6, 9, 10, 17, 25), the same care ditat were sampled in November 2000. The results show that the benzene level is below 0.5 mg/l for all wells except MW-25, and although it is above the drinking water standards, it has significantly decreased from the November 2000 sampling event. The Toluene Ethyl benzene and Hylenes levels for all cells are below the drinking water standards. Eleven wells (MW-3,12, 14, 18, 19, 20, 21, 22, 26, 27, 28) were free of product during both the November 2000 and February 2002 gaugings and were not sampled. Five wells (MW-2, 7, 11, 15, 24) contained free phase product and were not sampled. The product thickness in GVPs was also exaggerated because they are constructed of 1 ½" casing that display overstated thickness. To confirm such thickness, those wells and GVPs containing product were gauged again May 31- June 7 and the results were significantly lower as shown in Table 1.

Attachment 3 shows the hydrograph of selected wells and the relationship between groundwater table elevation and product thickness. Attachment 4 is the groundwater flow and petroleum plume map based solely on the February gauging. Attachments 5 and 6 are respectively summary of recovery operation data and graphs. Attachments 7 and 8 are respectively summary of discharge results and analysis of influent and effluent samples collected during the recovery operation.

In requesting to move to a passive remediation phase, the following factors were also evaluated:
a) drinking water to the area is supplied by the city, therefore, groundwater is not used as potable water and there is no drinking water well on-site or in its vicinity, b) due to a flat gradient at the site, groundwater has no flow movement to leach the contamination outside the site boundary, c) the groundwater table is in average 20 feet below grade and flows toward west, southwest of the site and away from the Anacostia River, d) the remediation site is located in an industrial area surrounded mostly by parking lots. There is no residential property in the vicinity of the site.

Therefore, the remaining contamination at this site poses no potential risk to public health or the environment at present or in foreseeable future.

In light of the aforementioned information, Pepco is seeking approval from DOH to implement the following measures:

Weekly gauging of the wells and GVPs that contained product based on Table 1.

Weekly bailing of the subject wells to recover free phase product and proper disposal of recovered product. V

Installation of absorbent booms in the wells to remove free phase product and replacement of the booms during the weekly gauging.  $\sqrt{\phantom{a}}$ 

✓ Semi-annual groundwater sampling of the subject wells and GVPs that will not contain product.

Quarterly submittal of a status report to DOH.

Evaluating the effect of passive remediation after a year.

Closure of the wells that did not contain product based on the February-April 2002 gb N/D we comprehensive well gauging. comprehensive well gauging.

Pepco looks forward to DOHs' approval of the proposed alternative. Please contact me at (202) 331-6641 if you have any questions, comments, or need additional information.

Sincerely,

Fariba Mahvi

Sr. Engineer,

**Environment Management Services** 

Enclosure

Project Identification: Sample Identification: Date Received: Analysis Date:	95052 MW4 02/21/2002 02/26/2002	USEPA Method: Client Identification: Client Telephone: Client Fax:	8260 & 8015 TPH Technologies 410-437-7500 410-437-9547	Analyst: Lab File: Sample Date:	MM 22602.D14 02/19/2002
COMPOUND	DETECTION LIMIT	TEST UNIT	TEST VALUE	1 - 1	~: ~: 001
Benzene	5	ug/L	444	0.444 mg/led	12 > 5 PPb 0.005 PPm
Toluene	5	ug/L	81.4	0 (	0.005 Pm
Ethylbenzene	5	ug/L	94.2	•	• • • • • • • • • • • • • • • • • • • •
m&p-Xylene	5	ug/L	118		
o-Xylene	5	ug/L	16	• •	
TPH GRO	100	ug/L	7080	70.80	

Project Identification: Sample Identification: Date Received: Analysis Date:	95052 MW5 02/21/2002 02/26/2002	USEPA Method: Client Identification: Client Telephone: Client Fax:	8260 & 8015 TPH Technologies 410-437-7500 410-437-9547	Analyst: Lab File: Sample Date:	MM 22602.D15 02/19/2002
COMPOUND	DETECTION LIMIT	TEST UNIT	TEST VALUE		
Benzene -	<b>5</b> ·		/		
Toluene.	5	ug/L	408		
Ethylbenzene	5	ug/L	89.2		
m&p-Xviene	5	ug/L	149 /		
o-Xylene	5	ug/L	252		
- <b></b>	•	ug/L	12.9		
TPH GRO	100	ug/L	11220 / 1/2.0	Po	

Project Identification: Sample Identification: Date Received: Analysis Date:	95052 MW-6 3/8/2002 3/12/2002	USEPA Method: Client Identification: Client Telephone: Client Fax:	8260 & 8015 TPH Technologies 410-437-7500 410-437-9547	Analyst: Lab File: Sample Date:	MM 31202.D16 3/5/2002
COMPOUND	DETECTION LIMIT	TEST UNIT	TEST VALUE		
Benzene -	5	ug/L	162 .16		
Toluene	5	ug/L	7.6		
Ethylbenzene	5	ug/t.	ND		
m&p-Xylene	5	ug/L	7.11		
o-Xylene	5	ug/L	ND		
Naphthalene	5	ug/L	ND		
TPH GRO	100	ug/L	1100, 1/		
TPH DRO	500	ug/L	ND		

Project Identification: Sample Identification: Date Received: Analysis Date:	95052 MW-9 3/8/2002 3/12/2002	USEPA Method: Client Identification: Client Telephone: Client Fax:	8260 & 8015 TPH Technologies 410-437-7500 410-437-9547	Analyst: Lab File: Sample Date:	MM 31202.D17 3/5/2002
COMPOUND	DETECTION LIMIT	TEST UNIT	TEST VALUE		
		_	44.6 = 0.0 44 22.4 = 1.0 2.2	a ppm	
Benzene .	5	ug/L	44.6 = O.O.T.	Lua Bo	
Toluene	5	₽g/L	22.4 = 2.4	• · · · · · · · · · · · · · · · · · · ·	
Ethylbenzene	5	ug/L	1680		•
m&p-Xylene	5	ug/L	3120		
o-Xylene	5	υg/L	26.8		
Naphthalene	5	ug/L	256		
TPH GRO .	100	ug/L	11980 119.00	>100 ppm	
TPH DRO	500	ndv.	ND,		

Project Identification: Sample Identification: Date Received: Analysis Date:	95052 MW10 02/21/2002 02/26/2002	USEPA Method: Client Identification: Client Telephone: Client Fax:	8260 & 8015 TPH Technologies 410-437-7500 410-437-9547	Analyst: Lab File: Sample Date:	MM 22602.D16 02/19/2002
COMPOUND	DETECTION LIMIT	TEST UNIT	TEST VALUE		
Berzene	 5	ug/L	294 = 0.294 26.4 = 0.024		
Toluene	5	ug/L	28.4 0.62.6	4	
Ethylbenzene	5	ug/L	32.6		
m&p-Xylene	5	ug/L	43.2		
o-Xylene	5	ug/L	NO '		
TPH GRO	100	ug/L	(4860) 48L	ppm >100	سوم

Project identification: Sample identification: Date Received: Analysis Date:	95052 MW-17 3/8/2002 3/12/2002	USEPA Method: Client Identification: Client Telephone: Client Fax:	8260 & 8015 TPH Technologies 410-437-7500 410-437-9547	Analyst: Lab File: Sample Date:	MM 31202.D18 3/5/2002
COMPOUND	DETECTION LINET	TEST UNIT	TEST VALUE		
Benzene — Toluene Ethylbenzene m&p-Xylene o-Xylene Naphthalene	5 5 5 5 5 5 5	ug/L ug/L ug/L ug/L ug/L ug/L	260 ND ND ND ND ND	,	
TPH GRO TPH DRO	100 500	ug/L ug/L	2800 28 ND	< 100 lbm	

Project Identification: Sample Identification: Date Received: Analysis Date:	95052 MW25 02/21/2002 02/26/2002	USEPA Method: Client Identification: Client Telephone: Client Fax:	8260 & 8015 TPH Technologies 410-437-7500 410-437-9547	Analyst: Lab File: Sample Date:	MM 22602.D17 02/19/2002
COMPOUND	DETECTION LIMIT	TEST UNIT	TEST VALUE		<b>.</b> .
~		ug/L	1040	LOU PPL	> 0.005 PAh.
Benzene	5		80.8	1.01 (15	
Toluene		ug/L		•	
Ethylbenzene	5	nāv.	8.81		
m&p-Xylene	5	ug/L	46.2		
o-Xylene	5	ug/L	22.6		
TPH GRO	100	ug/L	2500 2	5 4 160ppn	-

PECEIVE MAR - 6 2002 BY: WARD Z


701 Ninth Street N.W. Washington, D. C. 20068

**Environment Management Services** 

Certified Mail - 7003 1680 0004 9661 9536 Return Receipt Requested

August 19, 2004

Mr. Million Demissie DC DOH/ERA Underground Storage Tank Division 51 N Street, NE, 3rd Floor Washington, DC 20002



Re: Buzzard Point Station - Lust Case # 93-051

Dear Mr. Demissie:

This letter and Attachments 1-3 constitute Pepco's progress report on the status of the groundwater remediation project at Buzzard Point Station. This report provides a summary of the site activities for the period of April - July 2004. It also contains the analytical results of groundwater samples collected from the three down gradient wells in July and August 2004. Please note that two attempts to collect a sample from one of the downgradient wells (MW-26) failed due to lack of enough water in the well. Therefore, the well was allowed to recharge and a sample was collected on August 5, 2004.

During the period of April - July 2004, gauging of all GVPs and MWs except the non detects was conducted. The gauging data is included in Attachment 1. All GVPs and MWs were free of product. MW-11 that has historically contained product in the past, did not contain any free product during this period.

The three down-gradient wells, MW-12, MW-14, and MW-26 were sampled and the analytical results are included in Attachment 2. The results showed a little change since the March 2004 sampling event. The Benzene level in MW-14 and 26 and the Toluene, Ethyl benzene and Xylene levels in all three wells remained below the Maximum Contaminants Levels (MCLs) for drinking water. The GRO and DRO levels in all three wells remain at or below 1 ppm, the District of Columbia Water Quality Standards for TPH level in groundwater. Since May 2003, the three downgradient wells have been sampled every quarter and the results have been consistently below the regulatory standards, specifically in MW-14, which is located outside the station. The results indicate that the contamination is confined to the site and due to a flat gradient, groundwater has no flow movement to leach the contamination outside the site boundary.

Attachment 3 includes two groundwater gradient maps, based on the March 9, 2004 and June 17, 2004 well gauging data.

We will continue with gauging and bailing of the GVPs and wells. In September 2004, we will conduct semi-annual sampling of all GVPs and MWs except the non detect wells. The sampling results will be used to evaluate the effectiveness of passive remediation and to plan for the next course of action that will address the remediation of remaining petroleum at this site. A remediation plan will be prepared and submitted to your office for review and approval.

Please contact me at (202) 331-6641 if you have any questions or need additional information.

Sincerely,

Fariba Mahvi

Sr. Engineer,

**Environment Management Services** 

Attachments

Well	Date	Elevation	Denth to	Denth to	Product	Water	Bonzano	Toluene	Teas	Vidence	TOTEV	Tono	1000	1
71511		Lievalion	Product	Water		Elevation		Loinalle	Ethyl Benzene	Xylenes	BIEX	GRO	DRO	MTBE
				expressed	in feet	, and tation	<del> </del>			ation expr	essod In	ma/l	-L	1
						******	<del>                                     </del>		CONCENT	acion expi	0556U 11	i iiig/i		
				··-			†						<del></del>	
GVP01	Oct.23, 2002	46.28			0.00	26.25	5	1			T	T	T	Т
	Nov.07	46.28			trace	26.30	)			1		<b>—</b>	<del> </del>	<del> </del>
	Nov. 14	46.28		***	trace	26.35		I			1	1	1	<del> </del>
	Nov. 21	46.28			trace	26.63						1		1
ļ	Dec. 09	46,28							,			1		1
	Dec. 19	46.28		<del></del>									1	1
	Dec. 27	46.28			+			<u> </u>						
	Jan. 07-2003	46.28										1		1
	Jan. 27	46.28	<del></del>	20.11	0.03	26.17	<u> </u>				1			1
	Feb. 10	46.28		20.23	0.00	26.05						1	1	1
	March. 05	46.28		19.23	0.00	27.05		1			<del>                                     </del>	<del>                                     </del>	<b></b>	<del> </del>
	March.18	46.28			0.00	27.13				1	1	<b> </b>	1	†
<u></u>	April. 01	46.28			0.00					<u> </u>	1	1	1	
	April.17	46.28			0.00	27.31	Ţ					<del> </del>	1	
	April.28	46.28			0.00	27.27					<b> </b>	1	<u> </u>	<del>                                     </del>
	May. 20	46.28			0.00	27.44	1	1		I		1	<del>                                     </del>	1
L	June, 03	46.28	18.60			27.68				l		1	i	1
	June. 10	46.28	18.44			27.84						1	1	
<u> </u>	June. 23	46.28	17.91		trace .	28.37			L			I		1
<u> </u>	July, 15	46.28	18.11	18.11	0.00	28.17						<u> </u>	1	1
<u> </u>	July, 24	46.28	18.59	18.59	0	27.69				l		1.		
ļ	August. 07						0.76	0.14	0.96	1	3.46	20	11	< 0.02
ļ	August, 26	46.28	19.05			27.23							L	
<u> </u>	Sept. 16	46.28	18.95	18.95	0	27.33								1
	March. 2004		ļ		ļ. <u></u>	<u> </u>	No sample	. Well cap o	ould not be	removed.				
				<u> </u>							Ţ			
	<u> </u>													
GVP02	Oct. 23-2002	44.41	18.13	18.13		26.28							i	
	Nov. 07	44.41	18.10	18.10		26.31								
	Nov. 14	44.41	18.01	18.01		26,40								
	Nov. 21	44.41	17.72	17.72	0.00	26,69								
<b></b>	Dec. 09	44.41	18.37	18.39	0.02	26.02								
	Dec. 19	44.41	18.01	18.01	0.00	26.40								
<u> </u>	Dec. 27	44.41	17.94	17,94	0.00	26,47								
<u>.</u>	Jan. 07-2003 Jan. 27	Could not ro	17.51	17.51	0.00	26.90								
ļ	February, 10	Could not re												
	March, 05	44.41	18.66	18.66	0.00	25.75								
	March. 18	44.41 44.41	18.48	18.48	0.00	25.93								
	April, 01	44.41 44.41	17.18	17.18	0.00	27.23					<u> </u>			<u></u> ]
	April, 17	44,41	16.94	16.94	0.00	27.47	ļ							
<del></del>	April. 28	44.41	16.03 17.19	16.03 17.19	0.00	28.38								L
- :	May. 20	44.41	16.93		0.00	27.22	·							
	June. 03	44.41	16.93	16.93 16.78	0.00	27.48						<b></b>		<u> </u>
	June. 10	44.41	16.61	16.78 16.61	0.00	27.63								<b> </b>
·	June. 23	44.41	16.02			27.80								
	July, 15	44.41	16.02	16.02		28,39								
	July. 24	44.41	16.74	16,18 16,74	0.00	28.23 27.67								
	August, 07	74.41	10.74	10./4	0.00	27.67	0040	2.5						
	August. 26	44.41	17.25	17.25	trace	47.75	0.018	0.01	0.48	0.32	0.828	5.2	23	< 10
	Sept. 16	44.41	17.23	17.25	0.01	27.16								
	Mar.08, 2004	44.41	11.07	17.71	0.01	27.33 26.70	0,015			0.00~	~ ~~~			ليييا
	June. 17	44.41	16.58	16.58	0.00		0,015	0.01	0.22	0.087	0.332	9	42	0.02
	June. 30	44.41	17.62	17.62	0.00	27.83 26.79								
	July. 09	44.41	17.23	17.23	0.00									
	1227.22	77.71	17.23	11.23	0.00	27.18				····	•			
GVP03	Oct. 23-2002	44.24	49.00	40.00										
~,, ,,	Nov. 07	44.24	18.03 17.80	18.03	0.00	26.21								
	Nov. 14	44.24		17.80		26.44								
····	Nov. 21	44.24	17.89	17.89		26.35								
	Dec. 09	44.24	17.60	17.60	0.00	26.64								
	Dec. 19	44.24	18.33	18.33	0.00	25.91	l							
	Dec. 19		17.93	17.93	0.00	26.31								
~	Jan. 07-2003	44.24	17.88	17.89	0.01	26.35								
	Jan. 27	44.24	17.42	17.42	0.00	26.82								
····	February.10		18.25	18.25	0.00	25.99	0.17	0.079	0.38	0.542	1,171	4.9	20	<0.02
	July, 24	44.24	18.82	18.82	0.00	25.42								
	August, 07	44.24	16.78	16.78	0.00	27.46								
·	August, 26		4700				0.08	0.058	0.34	0.71	1.188	5.5	26	<0.05
	Mar. 29, 2004	44.24	17.26	17.27	0.01	26.97								
	Wai. 29, 2004	44.24		17.92		26.32	0.12	0.099	0.58	1,1	1.899	8.9	34	< 0.1
		<u>l</u> .						<u> </u>						

Well	Date	Elevation	Depth to	Depth to	Product	Water	Benzene	Toluene	Ethyl	Xylenes	BTEX	IGRO	DRO	мтве
			Product	Water	Thickness	Elevation	1	1.2.2.2.2	Benzene	7.5101100	- CIEN	10110	10110	MIDE
			Values	expressed	i in feet		1			ation expr	essed in	mg/l	· · · · · · · · · · · · · · · · · · ·	<u> </u>
			ļ							I	T	T	1	Τ
GVP03	A-51 22	<del>                                     </del>	1	<u> </u>								1	1	<del>                                     </del>
continue	April, 22 d May, 14	44.24												1
COMMING	dune. 17	44.24							ļ	ļ	Ļ			T
<u> </u>	June. 30	44.24								<u> </u>	<del> </del>	<del> </del>		
<b></b>	July. 09	44.24						<del>- </del>	<del></del>		ļ <u>.</u>	<del></del>	<u> </u>	<u> </u>
			1	1	1 0.00	20.30		<del> </del>		<del> </del> -	<del> </del>	<del>↓</del>	<del> </del>	
				<del> </del>	<del> </del>	<del> </del>		<del> </del>	<del> </del>	<del> </del>	<del> </del>			
GVP04	Oct. 23-2002	43.15	16.92	16.92	trace	26.23		·	<del> </del>	<del> </del>	<del> </del>	<del> </del>	<del>                                     </del>	<del> </del>
	Nov. 07	43.15	16.86	16.86	trace	26.29		<del>                                     </del>		<del>                                     </del>	<del> </del>	<del> </del>	<del> </del>	<del> </del>
	Nov. 14	43.15			trace	26.31		1	<b></b>	<del>                                     </del>	<del> </del>	<del> </del>	<del> </del>	<del> </del>
	Nov. 21	43.15									1	<del> </del>	<del> </del>	-
<u> </u>	Dec. 09	43.15									1	1	<b>†</b>	<del> </del>
ļ	Dec. 19 Dec. 27	43.15 43.15									I		<u> </u>	
ļ	Jan. 07-2003							ļ			<u> </u>		<u> </u>	
<del></del>	Jan. 27	43.15						<del> </del>		<u> </u>	ļ	ļ	ļ	
<b> </b>	February, 10							<del> </del>		<u> </u>			ļ	<del> </del>
	March, 05	43.15	16.10					<del> </del>		<del> </del>		<del> </del>	<del> </del>	<del> </del>
	March, 18	43.15	16.11						<del> </del>	<u> </u>	<del> </del>	<del> </del>	<del> </del>	<del> </del>
	April. 01	43.15	18.81	18.81	0.00	24.34		1		<u> </u>	<del> </del>	t	<del> </del>	-
<u> </u>	April, 17	43.15				24.26					<del>                                     </del>		<del> </del>	
<b></b>	April. 28	43.15	16.02		trace	27.13						I		1
ļ	May. 20	43.15				27.38								
<u> </u>	June, 03 June, 10	43.15 43.15	15.60 15.35		0.00									
	June. 23	43.15	14,89	10.30	trace trace	27.80		ļ			ļ	<u> </u>		
	July, 15	43.15	15.05	15.05	trace	28.26 28.10						ļ		
	July. 24	43.15	15.63					<del> </del>			<del> </del>	<u> </u>	ļ	ļ
	August, 08			1	0.00		< 0.13	< 0.05	0.2	0.33	0.71	14	52	< 0.1
	August, 26	43.15	16.11	16.11	trace	27.04		1	U.2	0.00	<u></u>			V 0.1
	Sept. 16	43.15	15.92			27.23		· · · · · ·						
	Mar.09, 2004	43.15		16.56		26.59	0.2	0.019	0.11	0.27	0.599	7	20	< 0.02
	April. 22 May. 14	43.15	16.47	16.47		26.68								
·	June, 17	43.15 43.15	16.57 16.63	16.57 16.63	0.00	26.58								
	June. 30	43.15	16.42	16.42	0.00	26.52 26.73								L
	July. 09	43.15	16.14	16.14		27.01		<u> </u>				<b> </b>		<u> </u>
					1	21,01						<b> </b>		<u> </u>
												<del></del>		<del> </del>
GVP05	Jan.15-2003	45.80	18.75	18.75		27.05								$\vdash$
	Jan. 28	45,80	19.14	19.14		26.66	0.18	<0.005	0.019	0.04	0.244	1.8	2.6	<0.01
	July. 24 August. 06	45.80	17.56	17.56	0.00	28.24								
	August, 26	45.8	18.11	40.44			0.059	<0.005	0.011	0.022		1.2	2.9	< 0.01
	Mar. 11, 2004	45.8	10.11	18.11 18.68	0	27,69	0.047	- 0000						
	April. 22	45.8	18,6	18.6	0	27.12 27.20	0.047	< 0.005	0.011	0.016	0.079	4.7	3,9	< 0.01
	May. 14	45.8	18.6	18.6	0	27.20								
	June. 17	45.8	18.53	18.53	0	27.27								
	June. 30	45.8	18.73	18.73	0	27.07							-	
	July. 09	45.8	18.37	18.37	0	27.43						-		
	-					[								
GVP06	Oct 22 2000	<u>  </u>												
GYPUO	Oct. 23-2002 Nov. 07	44.24	18.05	18.05	trace	26,19								
	Nov. 14	44.24 44.24	17.98 17.91	17.98 17.91		26.26		L						
	Nov. 21	44.24	17.70	17.70	0.00	26.33				· ·				
	Dec. 09	44.24	17.92	17.70	0.00	26.54 26.30								
	Dec. 19	44,24	17.75	17.75	0.02	26.49								
	Dec. 27	44.24	17.65	17.65	0.00	26.59		<del></del>						
	Jan. 07-2003	44.24	17.39	17.39	0.00	26.85			•••••					
	Jan. 27	44.24	17.64	17.65	0.01	26.59		<del></del>						
	February.10	44.24	17.85	17.85	0.00	26.39		.	<del>-</del>		1		~	
	March. 18	44.24	16.90	16.90	0.00	27.34								
<del></del>	April, 01	44.24	16,01	16.01	0.00	28.23					1			
	April, 17 April, 28	44.24	15.87	15.87	0.00	28.37								
	May. 20	44.24 44.24	16.67 16.67	16.67		27.57								
	June.03	44.24	16.41	16.67 16.41	0.00	27.57						<u> </u>		
	June, 10	44.24	16.28	16.28		27.83 27.96								
···	June. 23	44.24	15.72	15.72		28.52						<del></del> +		
	July, 15	44.24	15.72	15.72		28.52								
								<del></del>						
								t			. !			

Well	Date	Elevation	Depth to			Water	Benzene	Toluene	Ethyl	Xylenes	BTEX	GRO	DRO	МТВЕ
ļ			Product	Water	Thickness	Elevation		1	Benzene	1	1	7	<del> </del> -	771,02
		- <b> </b>	Values	expressed	In feet				Concentr	ation expre	ssed in	mg/l		L
		<del>- </del> -	<del> </del>	<del> </del>								T	1	<u> </u>
GVP06	July, 24	44.24	46.00	40.00			ļ	<u> </u>						
continue		44,24	16.00	16.00	0.00	28.24			<u> </u>	<del> </del>	ļ			
Continue	August, 26	44.24	16.56	16 56	trace	27.68		< 0.01	0.35	0.086	<u> </u>	5	5.	1 < 0.02
	Sept. 16	44.24						<del> </del>		<del> </del>	ļ		ļ	
	Oct. 30	44.24					<del> </del>	<del>                                     </del>	<del> </del>		<del> </del>	<b>├</b>	<del> </del>	
	Nov. 7	44.24					<del> </del>	<del> </del>	<del> </del>	ļ	<del> </del>	<del> </del>	<del> </del>	
	Nov. 20	44.24						<b></b>	<del> </del>	·	<u> </u>	<del> </del>	<del> </del>	<del> </del>
	Dec. 4	44.24	16.57	16.57	0.00			<del> </del>		<del> </del>		<del> </del>	<del> </del>	-
	Dec. 11	44.24	16.57					T	<del> </del>			<del> </del>	<del> </del>	
	Feb. 09, 200				0.00			1				1	<del>                                     </del>	+
<u>.                                    </u>	Feb. 19	44.24			0.00								<del>                                     </del>	<del>                                     </del>
	March, 11	44.24		17.11		27.13	0.01	0.01	0.14	0.028	0.188	3.2	<del>                                     </del>	< 0.02
<del></del>	April 5	44.24	17.05	17.05	0.00	27.19								
	April. 22 May. 14	44.24 44.24	17.05	17.05	0									1
	June. 17	44.24	17.13 16.95	17.13 16.95	0									
	June. 30	44.24	17.15	17.15	0					<u> </u>				1
	July. 09	44.24	16.95	16.95	0.00	27.09 27.29			<del> </del>			ļ	<u> </u>	<u> </u>
	33.73.33	1	10.00	10.33	0.00	21.29	~~~~	<del> </del>		<b> </b>			ļ	<del></del>
												· · · · · · · · · · · · · · · · · · ·	<u> </u>	ļ
GVP07	Jan.15-2003	45.78	18.70	18.70	0.00	27.08		<del>                                     </del>			<del> </del>	<b> </b>	<del> </del>	<del> </del>
	Jan. 27	45.78	18.94	18.93	0.00	26.85		<b></b>				<b> </b>		<del> </del>
	March, 05	45.78	16.20	16.20	0.00	29.58						<u> </u>	ļ <del></del>	<del> </del>
	March. 18	45.78	18.30	18.30	0.00	27.48								<del>                                     </del>
	April. 01	45.78	18.12	18.12	0.00	27.66								<del> </del>
	April. 17	45.78	17.91	17.91	0.00	27.87								<del> </del>
	April. 28	45.78	18.06	18.06	0.00	27.72								<b>†</b>
	May. 20	45.78	18.06	18.06	0.00	27.72		~~~						<del>                                     </del>
	June. 03 June. 10	45.78 45.78	17.71	17.71	0.00	28.07								
	June. 23	45.78	17.76 17.15	17.76 17.15		28.02								
	July. 15	45.78	17.15	17.15	0.00	28.63 28.63								
	July. 24	45.78	17.38	17.39	0.00	28.39								
	August, 06			11.00	0.01	20.00	0.36	0.028	< 0.025	0.052	0.465		~	
	August, 26	45.78	18.86	18.86	0.00	26.92	0.50	0.02.0	× 0.025	0.0021	0.465	3.1	7.9	< 0.05
	Sept. 6	45.78	18.05	18.05	0.00	27.73				<del></del>				
	Oct. 30	45.78	17.95	17.95	0.00	27.83						·		<b> </b>
	Nov. 7	45.78	17.95	17.95	0.00	27.83								<del> </del>
***************************************	Nov. 20	45.78	18.00	18.00	0.00	27.78								
	Dec. 4	45.78	18.02	18.02	0.00	27.76							-2	
	Dec. 11	45.78	18,00	18.00	0.00	27.78								
	Feb.9, 2004 Feb. 19	45.78	18,43	18.43	0.00	27.35								
	Mar. 11	45.78 45.78	18.45	18.45	0,00	27.33								
	April. 5	45.78	18.54	18.49 18.54	0.00	27.29	0.21	0.019	0.01	0.038	0.277	3.4	3.7	< 0.02
	April. 22	45.78	18.54	18.54	0.00	27.24 27.24								
• • • • • • • • • • • • • • • • • • • •	May. 14	45.78	18.43	18.43	0.00	27.35								
	June. 17	45.78	18.50	18.50	0.00	27.28								
	June. 30	45.78	17.53	17.53	0.00	28.25								
	July. 09	45.78	17,44	17.44	0.00	28.34								
VP08	Jan.15-2003	43.71	16.43	16.43	0.00	27.28								
	Monitoring disc	continued in F	ebruary 200	3 per DC-U	ST Division	approval.								
	-													
VP09	log 45 cocc		<del></del>				T							
VPUS	Jan.15-2003	44.23	17.48	17.48	0.00	26.75								
	Monitoring disc	A ui panuruck	ebruary 200	3 per DC-U	ST Division	approval.								
VP10	Jan. 15-2003	43.75	18.25	10.00										
	Monitoring disc		10.20 ebases 200	18.25	0.00	25.50								
	1	- minuou III F	Columny 200	o her no-0	O I DIVISION	арргоуан,								
	1													
VP11	Jan. 15-2003	40.06	13.60	13.60	0,00	26 46			<del></del>	l.				
	Jan. 27	40.06	14.14	14.14	0.00	26,46 25.92	0.013	0.005						
	May. 20	40.06	12.76	12.76	0.00	27.30	0.013	0.005	0.005	0.01	0.033	0.38	1	0.01
<del></del>	June. 03	40.06	12.51	12.70	0.00	27.55	···  -				<del></del> -		1	
	June. 10	40.06	12.51	12.51 t		27.55		<del></del>						
	June. 23	40.06	12.76	12.76	0.00	27.30		<del></del>						
	July. 15	40.06	12.76	12.76	0.00	27.30			<del></del>					
											1			

Well	Date	Elevation	Depth to	Depth to	Product	Water	Benzene	Toluene	Ethyl	Xylenes	BTEY	GBO	DRO	MTBE
			Product	Water	Thickness			110100116	Benzene	7.7.005	10.00	GRO	DICO	MITE
	<u> </u>		Values	expressed	in feet					ation expr	essed in	mg/i	J	<u>.L</u>
	<del> </del>								T	T	1		T	T
0.754	<del>                                     </del>		ļ											<del> </del>
GVP11	July. 23 August. 08	40.06	12.70	12.70	0.00	27.36	<del></del>							1
continued	August, 26	40.06	13.13	4040	14	ļ		< 0.005	< 0.005	< 0.01	0.03	0.46	0.82	< 0.01
<b></b>	Oct. 30	40,06			trace	26.93			.	ļ	<u> </u>			
ļ	Nov. 7	40.06						<del> </del>	ļ	<b> </b>	<del> </del>		ļ	
<b></b>	Nov. 20	40.06	12,95						<u> </u>	ļ	<del> </del>			
	Dec. 4	40.06							<del> </del>	<del> </del>	·			
	Dec. 11	40.06							<del> </del>	ļ				
	Feb. 9, 2004	40.06	13.40					<del>                                     </del>	╅	<del> </del> -	<del></del>	ļ		
	Feb. 19	40.06		13.45				<del></del>		<del> </del>	<del> </del>	<del></del>	<u> </u>	
	March. 8	40.06		13.51			< 0.005	< 0.005	< 0.005	< 0.005	<del> </del>	< 0.1	0.3	< 0.01
	April. 5	40.06	13,62	13.62	0.00	26 44			1-3335	1	1	~ 0.1	0.0	7 0.01
	Monitoring dis	continued in .	April 2004 p	er DC - US	T division a	proval.			1		<del> </del>			
	<u> </u>							1						
	I													
MW01	Jan.15-2003	46,51	19.85		•				]					
	Jan. 27	46,51	20.51	20.53	0.02	25.98	16 inch in	diameter. N	ot monitore	d under thi	s project.			
MW002	Oct. 23-2002	40.00	40.05	- 20.00										
INTYUUZ	Nov. 07	42.93 42.93	16.35						<u> </u>	<u> </u>				
•	Nov. 14	42.93	16.32 16.29	16.32 16.29	trace	26.61		ļ	ļ	<u> </u>	<b>  </b>			
	Nov. 21	42.93	15.96	15.97		26.64 26.96			<del> </del>		ļ			
	Dec. 09	42.93	16.65	16.66	0,01 0,01	26.96 26.27			<del> </del>	<del> </del>	<del> </del>			
	Dec. 19	42.93	16.26	16.26	0.00	26.27			<del> </del>	L	<del> </del>			
	Dec. 27	42.93	16.21	16.22	0.01	26.71			<del> </del>					
	Jan. 07-2003	42.93	15.75	15.76	0.01	27.17			<del> </del>					
	Jan. 27	42.93	16.58	16.60	0.02	26.33			<del>                                     </del>		<del> </del>			
	February.10	42.93	16.73	16.74	0.01	26.19				~~~~				
	March, 05	42,93	15.54	15.54	0.00	27.39								
	March.18	42.93	15.58	15.58	0,00	27.35					1			
	April. 01	42.93	15.37	15.37	0.00	27.56							~~~~	
	April. 17	42.93	15.30	15.30	0.00	27.63								
	April. 28	42.93	15.45	15.45	0.00	27.48								
· · · · · · · · · · · · · · · · · · ·	May. 20 June. 03	42.93 42.93	15.20 15.07	15.20 15.07	0.00	27.73			ļ					
	June. 10	42.93	14.81	14.81	0.00	27.86 28.12			<u> </u>		ļ			
	June. 23	42.93	14.51	14.51	frace	28.42			<u> </u>					
	July. 15	42.93	14.63	14.63		28.30			<del>                                     </del>					
	July. 24	42.93	15.02	15.02	0.00	27.91			<b> </b>		<del>                                     </del>			
	August. 05					21.01	0.14	< 0.01	< 0.025	0.096	0.271	8.1	690	< 0.02
	August. 26	42.93	15.53	15.54	0.01	27.39		- 0,01	10.020	0.000	0.2.11	- 0.1		V.02
	Sept 16	42.93	15.36	15.36	0.00	27.57								
	Oct. 30	42.93	15.35	15.35	0.00	27.58								
	Nov. 7	42.93	15.35	15.35	0.00	27.58					-			
	Nov. 20	42.93	15.40	15.40	0.00	27,53								
	Dec. 4	42.93	15.43	15.43	0.00	27.50								
	Dec. 11 Feb. 9, 2004	42.93	15.44	15.44	0.00	27.49								
	Feb. 19	42.93 42.93	15.95 15.95	15.95	0.00	26.98						I		
	March, 9	42.93	10.80	15.95 16.09	0.00	26.98 26.84	- 0000	- 0.005	- 0 005	1001		l		
	Mar. 31	42.93	16.06	16.09	0.00	26.84	0.065	< 0.005	< 0.005	< 0.01	<b></b>	31	1100	< 0.01
	April. 5	42.93	16.10	16.10	0.00	26.83	<del></del>		ļI					<del>.</del>
	April. 22	42.93	15.96	15.96	0.00	26.97			<u> </u>		<b></b>		<del></del> -	
	May. 14	42.93	16.04	16.04	0.00	26.89	<del></del>		·			<u> </u> -		
	June. 17	42.93	16.27	16.27	0.00	26.66			<del>  </del>					
	June. 30	42.93	16.05	16.05	0.00	26.88	·		<del></del>					
	July. 09	42.93	16.44	16.44	0.00	26,49					-			
	T										+	<del></del>		
	Jan.15-2003	45.94	18.94	18.94	0.00	27.00					<del></del>			
	Jan. 27	45.94	19.31	19.32	0.01	26.62								
	March, 05	45.94	18.84	18.84	0.00	27.10							1	
	March.18	45.94	18.54	18.54	0.00	27.40								
	April 01	45.94	18.63	18.63	0.00	27.31								
	April. 17	45.94	18.42	18.42	0.00	27.52	<u> </u>							
	April. 28	45.94	18.33	18.33	0.00	27.61								
	May. 20	45.94	18.33	18.33	0.00	27.61								
	June. 03	45.94	18.04	18.04	0.00	27.90								
	June.10	45.94	18.03	18.03		27.91								
	June. 23	45,94	17.55	17.55	0.00	28.39								
	July. 15	45.94	18.10	18.10	race	27.84			T	Ι				
	L								[	j	Γ			

Well	Date	Elevation	Depth to	Depth to	Product	Water	Benzene	Toluene	Ethyl	Xylenes	BTEX	IGRO	DRO	MTBE
-		<b> </b>		Water	Thickness	Elevation			Benzene				1	1
	~ <del> </del> ~~~~~	<del> </del>	Values	expressed	in feet	T	ļ	·	Concentr	ation expre	ssed in	mg/l		
-		<del>                                     </del>		<del> </del>	<del></del>	ļ								
MW003	July. 23	45.94	17.69	17.69	0.00	28.25	<del> </del>		ļ	ļ	ļ		ļ <u>.</u>	L
continued		1	1	.,,,,,,	2, 0.00	20.20	4	< 0.005	- 0 04°			<u> </u>		<u> </u>
	August, 26	45.94	18.28	18.29	0.01	27.65	0.000	0.005	< 0.045	0.065	0.183	2.7	9.2	< 0.01
	Mar. 8, 2004	1			1	27.00	Not sampl	ed. Buried ι	Inder erave	<u> </u>	<del> </del>	<del> </del>	ļ	
					1	<del> </del>	- tot oumpi	T Dune (	T grave	i.			<b> </b> -	<del> </del> -
					1					<del></del>				-
MW004	Jan.15-2003	46.20	19.26	19.26	0.00	26.94			<u> </u>		ļ			<del> </del>
	Jan. 27	46.20	19.71	19.71	0.00		0.9	0.15	0.31	0.54	1.9	8	7.2	< 0.1
	August, 07						0.24			0.51		8.4	3.4	<0.02
<u> </u>	August, 26	46.20	18.68	18.68									V. 1	-0.02
<u> </u>	Oct. 30 Nov. 7	46.20	18.60	18.60		27.60								
<u>                                     </u>	Nov. 20	46.20 46.20	18.60 18.70	18.60		27.60								
-	Dec. 4	46.20	18.75	18.70 18.75		27.50								
	Dec. 11	46.20	18.75	18.75		27.45 27.45								
	Feb.9, 2004	46.20	19.20	19.20		27.00	<del></del> -	ļ						
	Feb. 19	46.20	19.23	19.23	0.00	26.97	·							
	March. 9	46.20		19.31		26.89	0.068	0.12	0.036	0.11		2.5		10.00
	March.31	46.20	18.32	18.32		27.88	0.000	V. 12	0.030	0.11		2.5	3.1	< 0.05
	April, 5	46.20	18.32	18.32		27.88	-		<b></b>					
	April. 22	46.20	19.27	19.27	0.00	26.93				<del></del>				
	May. 14	46.20	19.25	19.25	0.00	26.95								
	June. 17	46.20	19.41	19.41	0.00	26.79								
ļ	June, 30	46.20	19.18	19.18		27.02								
	July. 09	46.20	18.92	18.92	0.00	27.28								
	-													
MW005	Oct. 23-2002	45.88	19.28	19.28	0.00									
	Nov. 07	45.88	19.23	19.23	0.00	26.60 26.65								
	Nov. 14	45.88	19.19	19.19		26.69								
	Nov. 21	45.88	18.91	18.91		26.97								
	Dec. 09	45.88	19.51	19.51		26.37								
	Dec. 19	45.88	19.17	19.17	0.00	26.71								
	Dec. 27	45.88	19.10	19.10	0.00	26.78								
	Jan. 07-2003	45.88	18.70	18.70	0.00	27.18								
	Jan. 27	45.88	14.41	14.42	0.01	31.46								
	February.10	45.88	19.65	19.65	0.00	26.23								
	March, 05 March, 18	45.88	18.48	18.48	0.00	27.40								
· · · · · · · · · · · · · · · · · · ·	April. 01	45.88 45.88	18.43 18.24	18.43	0.00	27.45								
	April. 17	45.88	18.18	18.24 18.18	0.00	27.64								
	April. 28	45.88	18.31	18.31	0.00	27,70 27.57								
	May. 20	45.88	18.12	18.12	0.00	27.76					I			
	June. 03	45.88	17.91	17.91	0.00	27.97			<del></del>		——			
	June. 10	45,88	17.71	17.71	trace	28.17								
	June. 23	45.88	17.41	17.41	trace	28.47								
	July. 15	45.88	16.90	16.90	trace	28.98					<del></del>			
····	July. 23	45.88	17.80	17.80	trace	28.08						<del></del> -		
	August. 07						1.1	0.34	0.7	1.2	3.34	12	37	0.01
	August. 26	45.88	18.38	18.38		27.50			·					
	Sept. 16 Oct. 30	45.88	18.26	18.26	0.00	27.62								
	Nov. 7	45.88	18.28	18.28	0.00	27.60								
	Nov. 7	45.88 45.88	18.30	18.30	0.00	27.58								
	Dec. 4	45.88	18.33 18.38	18.33 18.38	0.00	27.55						$\Box$		
	Dec. 11	45.88	18.40	18.38	0.00	27.50								
	Feb.9, 2004	45.88	18.85	18.85	0.00	27.48 27.03	<del></del>							
	Feb. 19	45.88	18.85	18.85	0.00	27.03			<del></del>					
	March. 09	45.88	. 5.00	18.45	0.00	27.43	0.34	0.12	0.34	<del>,</del>				0.05
	March, 31	45.88	18.95	18.95	0.00	26.93	0.04	U. 12	0.24	0.42		15	70	0.05
	April. 5	45.88	18.95	18.95	0.00	26.93	<del></del>	<del>-</del>				<del></del>		
	April. 22	45.88	18.84	18.84	0.00	27.04			<del></del> -			<del></del> -		
	May. 14	45.88	18,92	18.92	0.00	26,96		<del></del>		<del></del>			<del></del>	
	June. 17	45.88	18.90	18.90	0.00	26.98					<del></del>			
	June. 30	45.88	18,68	18.68	0.00	27.20		~ <del>-</del>					<del></del>	
	July. 09	45.88	18.74	18.74	0.00	27.14			<del></del>		<del></del>			
											-		<del></del>	
												<del></del>		
	Jan. 15-2003	46.26	19.09	19.09	0.00	27.17			<del></del>	<del></del>		<del> </del> -	-	
	Jan. 27	46.26	19.70	19.71	0.01	26.55					<del></del>	<del></del>		
	March, 05	46.26	17.97	17.97 t		28.29								
	March, 18	46.26	18.12	18.12 t	race I	28.14						<del></del>		

Well	Date	Elevation	Product	Water	Thickness	Water Elevation	Benzene	Toluene	Ethyl	Xylenes	BTEX	GRO	DRO	MTBE
	·	<b></b>		expressed	Infoot	Elevation	ļ	<u> </u>	Benzene	ـــــــل	ــــــــــــــــــــــــــــــــــــــ	<u> </u>	1	
		<del> </del>	1 1 1 1 1 1 1	expiesseu	T TOOL		<del> </del>	·	Concentr	ation expre	essed in	mg/l		
				1	<del> </del>	<del> </del>	<del> </del>	<del> </del>	<del> </del>	<del> </del>	<del> </del>	ļ	<del> </del>	<del> </del>
					†		<del> </del>	<del> </del>	<b>!</b>	<del> </del>	<del> </del>	<del> </del>	<del> </del>	<del> </del>
WW006	April. 01	46.26	<del></del>	+		28.57			†——	1	┼─┈		<del> </del>	<del> </del>
continued	<del></del>	46.26									1		<del> </del>	<del> </del>
	April. 28 May. 20	46.26 46.26			<del></del>									<del> </del>
	June. 03	46.26	18.17	18.27 18.17				ļ	<u> </u>					
	June. 10	46.26	17.81		trace	28.09 28.45		<del>                                     </del>	ļ	<del> </del> -				
	June. 23	46.26	17.75		trace	28.51			<del> </del>	<del> </del>	<del> </del>			
	July. 15	46.26		17.62	trace	28.64			<b></b>	<del></del>			<del> </del>	<del> </del>
	July, 24	46.26	17.95	17.95	trace	28.31		1	<u> </u>		<del>                                     </del>		<del> </del>	<del> </del>
	August, 07 August, 26	46.06	40.74	42.57			0.033	0.005	0.005	0.01	0.053	0.52	5.3	0.01
	Sept. 16	46.26 46.26	18.71 17.14	18.71 17.14		27.55								
	Oct. 30	46.26	18.33	18.33		29.12 27.93		<del> </del>	ļ					
	Nov. 7	46.26	18.35	18.35		27.93	<del></del>	<del> </del>						
	Nov. 20	46.26	18.53	18.53	0.00	27.73				<u> </u>			ļ	
	Dec. 4	46.26	18.60	18.60	0.00	27.66	·						ļ	
	Dec. 11	46.26	18.60	18.60	0.00	27.66				·				
	Feb. 9, <b>2004</b> Feb. 19	46.26 46.26	19.25	19.25	0.00	27.01							-	
	March. 9	46.26	19.25	19.25 19.18	0.00	27.01	- 0.005							
	March.31	46.26	19.27	19.18	0.00	27.08 26.99	< 0.005	< 0.005	< 0.005	< 0.005		0.28	6	0.01
	April. 5	46.26	18.95	18.95	0.00	27.31								
	April. 22	46.26	19.13	19.13	0.00	27.13				~				
	May. 14	46.26	19.10	19.10	0.00	27.16								
	June. 17	46.26	19.02	19.02	0.00	27.24								
	June, 30 July, 09	Not Gauged. Not Gauged.	Blocked by	equipment										
<u>-</u>	ouiy. 03	Not Gaugett.	DIOCKEO DY	equipment	·									
	Oct. 23-2002	45.07	18.51	18.51	trace	26.56								
	Nov. 07	45.07	18.47	18.47		26.60								
	Vov. 14	45.07	18.44	18.45	0.01	26.62								
	Nov. 21 Dec. 09	45.07	18.12	18.12		26.95								
	Dec. 19	45.07 45.07	18.82	18.82	0.00	26.25								
	Dec. 13	45.07	18.44 18.38	18.45 18.38	0.00	26.62								
	lan. 07-2003	45.07	17.93	17.93	0.00	26.69 27.14								
J	lan. 27	45.07	18.77	18.78	0.01	26.29								
	ebruary.10	45.07	18.92	18.92	0.00	26.15								
	March, 05	45.07	17.73	17.73	0.00	27.34							-	
	March, 18 April. 01	45.07 45.07	17.72	17.72	0.00	27.35								
	\pril. 17	45.07	17.51 17.26	17.51 17.26	0.00	27,56								
	pril. 28	45.07	17.65	17.65	0.00	27.81 27.42								
N	fay. 20	45.07	17.38	17.38	0.00	27.69	·							
	une. 03	45.07	17.28	17.28	0.00	27.79								———
	une. 10	45.07	17.04	17.04 t	race	28.03								
	une. 23	45.07	16.70	16.70	0.00	28.37				<del>-</del>			<del></del>	
	uly. 15 uly. 24	45.07 45.07	16.42 17.15	16.42 t		28.65								
	uly. 31	45.07	17.13	17,151	race	27.92	0,68	0.000						
A	ugust. 26	45.07	17.77	17.79	0.02	27.28	0.65	0.028	0.35	0.24		9.5	25	< 0.05
	ept. 16	45.07	17.55	17.55	0.00	27.52			<del></del>	<del></del>		——- <u> </u>		
·	ct. 30	45.07	17.60	17.60	0.00	27.47								
	lov. 7	45.07	17.60	17.60	0.00	27.47				<del></del>	<del></del>	<del> </del> -		
	ov. 20 ec. 4	45.07	17.67	17.67	0.00	27.40								
	ec. 11	45.07 45.07	17.70 17.70	17.70	0.00	27.37								
	eb. 9, 2004	45.07	18.30	17.70 18.30	0.00	27.37								
	eb.19	45.07	18.32	18.32	0.00	26.77 26.75								
	larch.10	45.07		18.3		26.77	1.3	0.046	0.3	0.22				
	arch. 31	45.07	18.30	18.30	0.00	26.77		3.040	V.3	0.22		9.7	20	0.05
	pril. 5	45.07	18.30	18.30	0.00	26.77						<del></del>		
	pril. 22	45.07	16.03	16.03	0.00	29.04				<del></del>				
	ay. 14	45.07	18.24	18.24	0.00	26.83							<del></del>	
	ine. 17 ne. 30	45.07 lot gauged. B	18.05	18.05	0.00	27.02								
		lot gauged. B	locked by e	guipment		<del></del>			L					
	<del>~```</del>	gg	ioched by e	quipriretti	<del></del>	<del></del>								
							~				——			
		l					1							

New   Col. 23-2002	Well	Date	Elevation	Depth to	Depth to	Product	Water	Benzen	e Toluene	Ethyl	Vidence	lotev	1000	1000	
Name				Product	Water	Thickness			10.00.14		Ayrenes	BIEN	GRO	DRO	MTBE
MW008				Values	expressed	in feet		<del>                                     </del>			ation expr	essed in	ma/t		
Nov. 07	ļ							1			1	T	1	T	T
Nov. 07	<del> </del>	<del></del>	<del> </del>	ļ	<del> </del>	<u> </u>	ļ						T		<del></del>
Nov. 07	MWoos	Oct 23-2002	41.70	15.04	750			<u> </u>						1	
Nov. 14	-			·		trace			<del> </del>		ļ				1
Nov. 21				<del></del>	15.20	trace				ļ		<del> </del>	<u> </u>		
Dec. 09					14.84	trace			+	<del> </del>	<del> </del>	<u> </u>	<b> </b>	ļ	
Dec. 19									<del> </del>	· · · · · · · · · · · · · · · · · · ·	<del> </del>	<del> </del>	ļ	<u> </u>	
Dec. 27   41.76   15.10   15.11   0.01   26.67											<del> </del>	<del> </del>	ļ		<del> </del>
Jan. 07-2003   41-76   14-63   14-63   0.00   27-15			41.78	15.10	15.11	0.01				<del> </del>	<del> </del> -	<del> </del>	<del> </del>	ļ	-
February,10					14.63				1		·	<del> </del>		<del> </del>	<del>                                     </del>
March 05												<del> </del>	<del> </del>	<del> </del>	<del> </del>
March: 18									1	1		<del> </del>	<del>                                     </del>		<del> </del>
April. 01	<u> </u>				14.34									<b> </b>	<del>                                     </del>
Agril. 17	, ,														
April, 28				14.20	14.26				·						1
May, 20										<b></b>					
June 03						·			+						ļ
June, 10												ļ			ļ
June 23			41.78					<del>                                     </del>	<del> </del>			<del> </del>			<b></b>
July, 16			41.78		13.41	0.00			1						<del> </del>
July, 24	+			13.38	13.38				1					<del></del> -	<del> </del>
August 26			41.78	13,99	13.99	0.00			1						<del>                                     </del>
Rugust 29								0.02	7 0.013	0.02	0.035		4.2	190	< 0.02
Oct. 30															1
Nov. 7	·····														1
Nov. 20															
Dec. 4	·····						27.53								
Dec. 11									<b>+</b>						
Feb. 9,2004								~	<u> </u>						
Feb. 19			41.78												
April. 2		Feb. 19		14.76	14.76				1						
April. 22 41.78   14.96   14.96   0.00   26.82							26.98	< 0.005	< 0.005	0.011	0.025		3.5	240	< 0.01
May, 14															* 0.01
June 17															
June, 30															
MW009									<b> </b>						
MW009 Jan. 15-2003 42.82 15.91 15.91 0.00 26.91															
Jan. 27				10.10	10.10	0.00	23.63		<del> </del>						
Jan. 27	·····	"-							<del>                                     </del>						
Jan. 27	MW009	Jan.15-2003	42.82	15.91	15.91	0.00	26.91	<del></del>	<del>  </del>						
March. 18			42.82	16.42					<del>                                     </del>						
March. 18				15.57				<del></del>	<del>                                     </del>				+		
April. 17						race			l						
April. 28															
May. 20															
June 10		1													•
June. 10															
June 23								·	<b></b>	T					
July 15	·									.					
July 24								<del></del>							
July 31									<del></del>						
August 26	·					9.00	41.37	0.045	0.03	3.6	47		— <u></u>		
Sept. 16			42.82	15.40	15.40 t	race	27.42	3.570	0.03	3.0	4.(	—— <u> </u> -	19	9.3	< U.U5
Oct. 30         42.82         13.27         13.27         0.00         29.55           Nov. 7         42.82         13.27         13.27         0.00         29.55           Nov. 20         42.82         15.30         15.30         0.00         27.52           Dec. 4         42.82         15.30         15.30         0.00         27.52           Dec. 11         42.82         15.30         15.30         0.00         27.52           Feb. 9, 2004         42.82         16.80         16.80         0.00         26.02           Feb. 19         42.82         16.80         16.80         0.00         26.02           March.09         42.82         15.92         26.90         0.054         < 0.05					15.27				<del>  -</del>				+		
Nov. 20		·				0.00									
Dec. 4	<del></del>						29.55					-+			
Dec. 11														<del></del>	
Feb. 9, 2004   42.82   16.80   16.80   0.00   26.02	<del></del>	**************************************													
Feb. 19															
March,09     42.82     15.92     26.90     0.054     < 0.05     1.9     2     45     14     < 0.1       April, 5     42.82     15.94     15.94     0.00     25.88     15.82     15.82     15.82     15.82     15.82     15.82     15.82     15.82     15.82     15.82     15.82     15.82     15.82     15.82     15.82     15.82     15.82     15.82     15.82     15.82     15.83     15.83     15.83     15.83     15.83     15.84     15.84     15.84     15.84     15.84     15.84     15.84     15.84     15.84     15.84     15.84     15.84     15.84     15.84     15.84     15.84     15.84     15.84     15.84     15.84     15.84     15.84     15.84     15.84     15.84     15.84     15.84     15.84     15.84     15.84     15.84     15.84     15.84     15.84     15.84     15.84     15.84     15.84     15.84     15.84     15.84     15.84     15.84     15.84     15.84     15.84     15.84     15.84     15.84     15.84     15.84     15.84     15.84     15.84     15.84     15.84     15.84     15.84     15.84     15.84     15.84     15.84     15.84     15.84     15.84<									<u>-</u>						
April. 5 42.82 15.94 15.94 0.00 25.88 4 14 < 0.1  April. 22 42.82 15.82 15.82 0.00 27.00 4 15.93 15.93 0.00 26.89  June. 17 42.82 16.04 16.04 0.00 26.78  June. 30 42.82 15.84 15.84 0.00 26.98				10.00		0.00		0.052	1005						
April. 22     42.82     15.82     15.82     0.00     27.00       May. 14     42.82     15.93     15.93     0.00     26.89       June. 17     42.82     16.04     16.04     0.00     26.78       June. 30     42.82     15.84     15.84     0.00     26.98				15 04		0.00		U.U54	< 0.05	1.9	2	$-\bot$	45	14	< 0.1
May. 14 42.82 15.93 15.93 0.00 26.89  June. 17 42.82 16.04 16.04 0.00 26.78  June. 30 42.82 15.84 15.84 0.00 26.98						~							$\Box$		
June. 17         42.82         16.04         16.04         0.00         26.78           June. 30         42.82         15.84         15.84         0.00         26.98															
June. 30 42.82 15.84 15.84 0.00 26.98															
		July. 09			~~~~				<del></del>						
												<del></del>  -			
		L							<del>+</del>	t-				- +	

Well	Date	Elevation	Depth to	Depth to		Water	Benzen	e Toluene	Ethyl	Xylenes	BTEX	IGRO	DRO	МТВЕ
ļ		·· <del>]</del>	Product	Water	Thicknes	Elevation	n		Benzene		1=1=1	10.10	10110	IM FOL
ļ		<del> </del>	Values	expressed	In feet	·			Concent	ration exp	ressed In	mg/l		<del></del>
<del> </del>		<del> </del>	<del> </del>	<del> </del>	<del> </del>	<del> </del> -	<u> </u>						I	T
MW010	Jan. 15-2003	46.52	19.19	19.19	0.00	27.3	<del></del>	<del></del>		<u> </u>				
	Jan. 27	46.52								+		<b>├</b>	ļ	
	March, 05	46.52			trace	27.4		<del></del>	<del></del>	<del> </del>		<del> </del>		
	March, 18	46.52								<del> </del>	<del> </del>	<del> </del> -		
	April. 01	46.52	18.90					<del> </del>	<del> </del>	<del> </del>		<del> </del>	- <del> </del>	-
	April. 17	46.52	18.79					<del></del>		<del>                                     </del>	<del> </del>	<del> </del>	<del> </del>	
	April. 28	46.52	18.55			27.9	7	-		<del> </del>	<del>                                     </del>	<del> </del>	╂───	<del> </del>
	May. 20	46.52							<b>—</b>	1	┪┈┈	<del> </del>	+	┪
<del></del>	June. 03	46.52	18.28								1	<del> </del>	<del> </del>	<del> </del>
<b></b>	June. 10 June. 23	46.52 46.52	18.21			28.3							<del>                                     </del>	<del> </del>
	July. 15	46.52	17.82 17.36	17.82 17.36		28.7		<u> </u>					<del></del>	<del>                                     </del>
<del></del>	July, 24	46.52	17.90		trace	29.1			<del> </del>					
,	August 07	1 10.02	17.00	17.50	uace	28.6	<del></del>							
	August, 26	46.52	18.50	18.50	frace	28.0	0.3	3 0.0	0.056	0.1	0.546	7.4	5.5	< 0.02
	Sept. 16	46.52	18.58	18.58	0.00	27.9		<del>-</del>		<del> </del>			<b></b>	ļ
	Oct. 30	46.52	18.60	18.60	0.00			<del> </del>	<del></del>	<del> </del>	<b>_</b>	<u> </u>		ļ
	Nov. 7	46.52	18.60	18.60	0.00	27.9		<del> </del>	<del></del>	<del> </del>	<del> </del>	<del></del>		
ļ	Nov. 20	46.52	18.60	18.60	0.00	27.9		<del>- </del>		,	<del>  </del>	<b> </b>	<del> </del>	
ļ	Dec. 4	46.52	18.62	18.62	0.00	27.90	)	1	1	<del> </del>	┪	<u> </u>		<del> </del> -
<u> </u>	Dec. 11	46.52	18.62	18.62	0.00	27.90				1	1		<del>                                     </del>	
	Feb. 9, 2004 Feb. 19	46.52	18.80	18.80	0.00	27.72					1			
····	March, 09	46.52 46.52	18.83	18.83	0.00	27.69							·	
	April. 5	46.52	19.20	19.19 19.20		27.33		0.02	7 0.045	0.01	$oxed{oxed}$	9.7	7.4	< 0.02
	April. 22	46.52	19.20	19.20	0.00	27.32 27.41		<del> </del>			<b>↓</b>			
	May. 14	46.52	19.16	19.16	0.00	27.36		<del> </del>	-		ļ			
	June. 17	46.52	19.18	19.18	0.00	27.34	<u> </u>	<del> </del>	<del> </del>		<del>  </del>			
	June. 30	46.52	19.00	19.00	0.00	27.52		<del> </del>						
<u> </u>	July. 09	46.52	18.87	18.87	0.00	27.65		<del> </del>	<del> </del>		<del>  </del>			
								<del> </del>			<del>                                     </del>	-		
MW011	0-4 00 0000							1	1					
MAAAA 4.1	Oct. 23-2002 Nov. 07	42.76	16.58	16.67	0.09	26.09					1			
	Nov. 14	42.76 42.76	16.54	16.58	0.04	26.18							~	
····	Nov. 21	42.76	16.52 16.18	16.52		26.24								
····	Dec. 09	42.76	16.93	16.22 16.99	0.04 0.06	26.54 25.77		<del> </del>						
	Dec. 19	42.76	16.52	16.52	0.00	26.24	<del> </del>	<del> </del>	- <del> </del>					
	Dec. 27	42.76	16.49	16.49	0.00	26.27	<del> </del>	ļ	<del> </del>					
	Jan. 07-2003	42.76	15.99	15.99	0.00	26.77	<b></b>	<del> </del>	<del>                                     </del>		├──┼			
	Jan. 27	42.76	16.91	16.94	0.03	25.82	·····	<del> </del>	<del>                                     </del>					
	February.10	42.76	17.05	17.09	0.04	25.67				<del>~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~</del>				
	March, 05	42.76	15.78	15.78	0.00	26.98					<del>  </del>			
	March, 18	42.76	15.82	15.89	0.07	26.87							<del>1</del>	
<del></del>	April. 01 April. 17	42.76 42.76	15.65	15.81	0.16	26.95							~	
	April. 28	42.76	15.58 15.76	15.68	0.10	27.08								
	May. 20	42.76	15.47	15.83 15.47	0.07	26.93								
	June. 03	42.76	15.29	15.34	0.00	27.29			<b></b>					
	June. 10	42.76	15.06	15.06 t		27.42 27.70			<del> </del>					
	June. 23	42.76	14.78	14.78 t		27.70			<del> </del>					
	July. 15	42.76	14.96	15.10	0.14	27.66			<del> </del>				<u>-</u>	
	July. 24	42.76	15.23	15.70	0.47	27.06			<del>  </del>		—— <u>—</u>	<del></del>		
	July. 31						Well was n	ot sampled	Product lev	el > 0 01'				
	August. 26	42.76	15.88	16.13	0.25	26.63			10000164		<del></del>	<del></del>		
	Sept. 16	42.76	15.65	15.67	0.02	27.09					<del></del>	+		
	Oct. 30 Nov. 7	42.76	15.65	15.70	0.05		Bailed. Inst	alled boom			<del></del>	<del></del>		
	Nov. 20	42.76	15.65	15.65	0.00	27.11						-+		
	Dec. 4	42.76 42.76	15.77 16.00	15.77	0.00	26.99								
	Dec. 11	42.76	15.76	16.04	0.04		Bailed. Rep	laced boor	n.					
	Feb. 9, 2004	42.76	16.25	15.76	0.00	27.00	بـــــــــ		L					
	Feb. 19	42.76	16.27	16.25 16.27	0.00	20.01	No product	Replaced	роош.					
	March. 8			17.21	0.00	26.49	Mallyraa	t com=1- 1	Charle 11	1		$\prod$		
	March, 31	42.76	16.40	16.40	0.00	26.36	ven was no	л sampled	Product lev	ei > 0.01'				
	April. 5	42.76	16.40	16.40	0.00	26.36	<del></del>	· · · · · · · · ·				<b></b> ↓		
	April. 22	42.76	16.17	16.17	0.00	26.59	Bailed		<del>  </del>					
	May. 14	42.76	16.27	16.27	0.00	26.49	Bailed, Rep	aced boso	<u> </u>					
	June. 17	42.76	16.35	16.35	0.00	26.41	Janea. Neb	SOCO DOOL	11.		—— <u> </u>	<b></b> -⊢		
	June. 30	42.76	15.42	15.42	0.00	27.34	Bailed, Rep	laced boon	<u> </u>			<del></del> -		
	July. 09	42.76	16.22	16.22	0.00	26.54	Bailed, Rep	aced boon	<u> </u>		-+		<del></del>	
											<del>-</del> -			
	L	<u>_</u>											+	
													1	

e Arden

.

Well	Date	Elevation	Depth to	Depth to	Product	Water	Benzene	Toluene	Ethyl	Yulanas	lercy	Topo	1000	1
			Product	Water	Thicknes:		) Derizerii	9 10108110	Benzene	Xylenes	BIEX	GRO	DRO	MTBE
<u></u>	<u> </u>	<u> </u>	Values	expressed	ln feet		1			ration expr	essed b	ma/l	<u> </u>	
									1	1	1	1	<del></del>	1
4414/040	1 45 0000	<del> </del>								<b>—</b>	1	<del></del>		<del> </del>
MW012	Jan.15-2003 Jan. 27	40.81		-4	<del></del>							T	<del> </del>	<del>                                     </del>
	March, 05	40.81				<del></del>								
<del> </del>	March, 18	40.81										$\mathbf{L}^{-}$		
	April. 01	40.81			<del></del>						ļ			
<b> </b>	April. 17	40.81	13.41					<del>- </del>		ļ				
	April. 28	40.81						<del>-</del>			ļ	ļ		
<u> </u>	March. 05	40.81						<b></b>		<del> </del>	<u> </u>			
	March, 18	40.81								<del> </del>	<del> </del>			
	April. 01	40.81							<del>-  </del>	<del> </del>	<del> </del>		<del></del>	
	April. 17	40.81	13.41					<del> </del>	<del>- </del> -	<del> </del>	<del> </del>	<del> </del>		
	April. 28	40.81	13.32	13.32				<del> </del>		<del> </del>	<del> </del>	<del> </del>	<del> </del>	-
ļ	May. 20	40.81		13.42	0.00	27.3	9	<u> </u>	<del></del>	<del> </del>	<del> </del>	<del> </del>		
	May. 28	40.81	13,16	13.16			5 < 0.005	< 0.005	< 0.005	< 0.005	<del> </del>	< 0.1	< 0.11	< 0.01
	June. 03	40.81	13.09				2			11111	<del> </del>	- <u>-</u>	1	10.01
	June. 10	40.81	13.20							T	1	<del> </del>		<b>+</b>
	June. 23	40.81	12.65								1	<del> </del>	<del> </del>	
	July, 24	40.81	13.3	13.33	0	27.48						1	1	<del> </del>
	July, 31 August, 26	40.04	40.07	46.63				< 0.005	0.076	< 0.01		0.4	0.9	3 < 0.01
	Sept. 16	40.81 40.81	13.87	13.87		26,94								
<del></del>	Oct. 30	40.81	13.65 13.6	13.65 13.6				1	ļ					
<u> </u>	Nov. 7	40.81	13.6	13.6				-	<del></del>					
	Nov. 13	70,01	13.0	13.0	<u>-</u>	27.21		L C 005	10000	1.000	ļ		<u> </u>	
T	Nov. 20	40.81	13.67	13.67	o	27.14	< 0.005	< 0.005	< 0.005	< 0.01	ļ	< 0.1	0.20	3 < 0.01
	Dec. 4	40.81	13.67	13.67	0			<del> </del>		<del> </del>		ļ	<u> </u>	
	Dec.11	40.81	13.7	13.7	0	27.11		<del>                                     </del>	<del></del>		<b></b>		<del> </del>	-
	Feb. 9, 2004	40.81	14.2	14.2	0	26.61		<del> </del>	<del>                                     </del>	<b></b>			<del> </del>	
	Feb. 19	40.81	14.25	14.25	O	26.56		<del>                                     </del>	<del> </del>				<del> </del>	
	March, 08	40.81		14.29			< 0.005	< 0.005	< 0.005	< 0.01		< 0.1	< 0.1	< 0.1
	April. 5	40.81	15.07	15.07	Ö	25.74		T		- 0.07	<del></del>	20.1	1 0.1	~ 0.1
	April. 22	40.81	14.2	14.2	. 0	26.61		T	1			<del> </del>	<del> </del>	
	May. 14	40.81	14.28	14.28	0	26.53			1			<del>                                     </del>	<del> </del>	1
	June 17	40.81	14,44	14.44	0	26.37							<del></del>	
	June, 30	40.81	14.02	14.02	0	26.79						<del> </del>	<del>                                     </del>	
	July. 09 July. 16	40.81	14.25	14.25	0	26.56					-			
	July. 10	40.81		14.09		26.72	0.046	< 0.005	0.1	< 0.01	0.161	0.57	1	< 0.1
	<del> </del>													
MW013	Monitoring was	discontinue	in 1994 no	r DC-UST (	Videlon opp	ranul		<u> </u>	<b></b>	<u>.</u>				
··		T	1	1000011	JAMES OF APP	OYAI.	<del> </del>		<del> </del>					<u> </u>
							<del> </del>						ļ	
MW014	Jan.15-2003	41.79	14.19	14.19	0.00	27.60		·					ļ	
	Jan. 27	41.79	15.62	15.63	0.01	26.16		ļ						<b> </b>
	March. 05	41.79	12.08	12.08	0.00	29.71		<del></del>						<del>                                     </del>
	March. 18	41.79	13,44	13.44	0.00	28.35			<del> </del>					<del>                                     </del>
	April. 01	41.79	12.32	12.32	0.00	29.47			<del>                                     </del>					<del>  </del>
····	April. 17	41.79	12.22	12.22	0.00	29.57			1			· · · · · · · · · · · · · · · · · · ·		ł
	April. 28	41.79	13.45	13.45	0.00	28.34			1					<del>                                     </del>
···	May. 20	41.79	12.49	12.49	0.00	29.30			T					<del>  </del>
	May. 28	41.79	11.00	11.00	0.00		< 0.005	< 0.005	< 0.005	< 0.005		< 0.1	< 0.1	< 0.01
	June. 03	41.79	12.20	12.20	0.00	29.59								<del> </del>
	June. 10 June. 23	41.79	12.18	12,18	0.00	29.61								-
~	June. 23 July. 15	41.79	11.10	11,10	0.00	30.69								
	July. 24	41.79	10.85	10.85	0.00	30.94			<u> </u>					
	August 05	41.79	13,86	13.86	0.00	27.93								
	August, 26	41.79	14.75	14 75			< 0.005	< 0.005	< 0.005	< 0.01		< 0.1	< 0.1	< 0.01
	Sept. 16	41.79	14,64	14.75		27.04			<del>                                     </del>	]				
	Oct. 30	41.79	14.38	14.38	0.00	27.15 27.41								
	Nov. 7	41.79	14.40	14.40	0.00	27.41			1					
	Nov. 13			17.70	0.00	61.09	< 0.005	< 0.005	20.005	4004				الــــا
	Nov. 20	41.79	14.03	14.03	0.00	27.76	- 0.000	~ 0.005	< 0.005	< 0.01		< 0.1	< 0.1	< 0.01
	Dec. 4	41.79	14.05	14.05	0.00	27.74			<del>  </del>					ļl
	Dec. 11	41.79	14.05	14.05	0.00	27.74			<del> </del>					<b>  </b>
	Feb. 9, 2004	41.79	13.98	13.98	0.00	27.81			<del>                                     </del>					
	Feb. 19	41.79	14.00	14.00	0.00	27.79			<del> </del>					<b>  </b>
	March, 10	41.79		14.44			< 0.005	< 0.005	< 0.005	< 0.01		< 0.1	- 00	< 0.01
												- U, I	U.Z	\ U.U I
	April, 5	41.79	13.56	13.56	0.00	28.23			1	•				1
	April. 5 April. 22	41.79 41.79	14.05	14.05	0.00	27.74								
	April, 5 April, 22 May, 14	41.79 41.79 41.79	14.05 14.74	14.05 14.74	0.00	27.74 27.05								
	April. 5 April. 22	41.79 41.79	14.05	14.05	0.00	27.74								

Acres and

1

Well	Date	Elevation	Depth to	Depth to	Product	Water	Benzen	Toluene		Xylenes	BTEX	GRO	DRO	MTBE
	· <del> </del>	<del>                                     </del>		Water expressed	Thickness	Elevation	ļ	ᆚ	Веплепе					
	<b>-</b>		Values	expressed	10 1961	<del></del>	ļ	<del></del>	Concent	ration exp	ressed in	mg/l		
		<del> </del>	<del> </del>	<del> </del>	<del> </del>	<del> </del>	<u> </u>				-	ļ		
MW014	June, 30	41.79	14.97	14.97	0.00	26.82		<del> </del>			<del> </del>			
continued	July. 09	41.79								<del> </del>	<u> </u>	ļ		
**	July 14	41.79		15.01			< 0.005	< 0.005	< 0.005	< 0.01	<del>- </del> -	1		
		1			1		10,000	1.0.000	1.0.000	V.0.01	<del>                                     </del>	< 0.1	< 0.1	< 0.01
				1		T		<del></del>	<del></del>	<del> </del>				
MW015	Oct. 23-2002	44.63	18.05	18.05	trace	26.58		<del> </del>		<del> </del>		<del> </del>		
	Nov. 07	44.63	17.98					<del>                                     </del>	<del></del>	<del> </del>	<del></del>	<del> </del>		
	Nov. 14	44.63	17.90		trace	26.73		<b>-</b>		<del> </del> -	<del> </del>	<del> </del>		
~~~~	Nov. 21	44.63	17.68		0.02						<del> </del>	<del> </del>	<del></del>	
	Dec. 09	44.63	18.05	18.09								 		
	Dec. 19 Dec. 27	44.63 44.63	17.81	17.81	0.00							1	1	
	Jan. 07-2003	44.63	17.72 17.41	17.74								Ι		
	Jan. 27	44.63	17.84	17.41 17.87		27.22		 	<u> </u>			Ľ		
	Feb. 10	44.63	18.05	18.08		26.76			-	ļ <u>.</u>				
	March. 05	44.63	17.15	17.16		26.55 27.47		-├		ļ			-l	<u> </u>
	March. 18	44.63	16.97	16.97	0.00	27.66		 	 	 -				
	April. 01	44.63	16.81	16.81	0.00	27.82		 	 	 	·		 	
	April. 17	44.63	16.64	16.64		27.99		 	 	 	 -	ļ	 	
	April. 28	44.63	16.81	16.81	0.00	27.82		 	+		1	 	 	+
	May. 20	44.63	16.71	16.71	0.00	27.92		 	 	 	 	 -	 	
	June. 03	44.63	16.53	16.53	0.00	28.10		1	1	 	 	 	1	+
	June. 10	44.63	16.50	16.50	0.00	28,13		1	1	<u> </u>	 		†	+
	June. 23	44.63	15.93	15.93		28.70					1		 	+
	July. 15 July. 24	44.63	15.90	15.90		28.73					1		1	
	August, 5	44.63	16.22	16.22	0.00	28.41		<u> </u>						1
	August. 26	44.63	16.80	16 90	0.00		0.026	< 0.01	0.15	0.1	0.286	5.5	9:	5 < 0.02
	Sept. 16	44.63	61.37	16.80 16.37	0.00	27.83		ļ						
	Oct. 30	44.63	16.70	16.70	0.00	28.26 27.93	·····	 			<u></u>		<u> </u>	1
	Nov. 7	44.63	16.70	16.70	0.00	27.93		 	 				L	
	Nov. 20	44.63	16.73	16.73	0.00	27.90		 	· 				 _	
	Dec. 4	44.63	16.37	16.37	0.00	28.26		 	 		 		 	
	Dec. 11	44.63	16.78	16.78	0.00	27.85		 	 		├ ──			
	Feb. 9, 2004	44.63	17.22	17.22	0.00	27.41	~~~~		 				 	
	Feb. 19	44.63	17.22	17.22	0.00	27.41		 	1		1	 -	 	+
	March, 10	44.63		17.40		27.23	0.041	< 0.005	< 0.04	< 0.048		6.8	180	< 0.01
	April. 5	44.63	17.33	17.33	0.00	27.30			1				1	1-0,01
	April. 22 May. 14	44.63 44.63	17.26	17.26	0.00	27.37								
	June. 17	44.63	17.25 17.33	17.25	0.00	27.38								1
	June. 30	44.63	17.35	17.33 17.35	0.00	27.30			ļ					
	July, 09	44.63	15.22	15.22	0.00	27.28 29.41			ļ					
			10.22	10.22	V.00	29.41			f		<u> </u>			<u> </u>
									 					<u> </u>
W016 .	Jan.15-2003	44.15	16.76	16.76	0.00	27.39			 		-			
	Jan. 27	44.15	17.10	17.11	0.01	27.04			 					
	March, 05	44.15	16.47	16.47	0.00	27.68								
	March. 18	44.15	16.35	16.35	0.00	27.80								
	April. 01	44.15	16.11	16.11	0.00	28.04			1 1					
	April. 17	44.15	15.98	15.98	0.00	28.17								—
	April. 28 May. 20	44.15	16.30	16.30	0.00	27.85							·~~~	
	June. 03	44.15 44.15	16.24	16.24	0.00	27.91								
	June. 10	44.15	15.93 15.93	15.93	0.00	28.22		~···	<u> </u>					
	une. 23	44.15	16.24	15.93 t		28.22								
	July. 15	44.15	15.47	15.47 t		27.91 28.68			 					
	July. 24	44.15	15.74	15.74	0									
	August. 5		19.171	13.14	<u>'</u>	28.41	0.24	0.085	0.000		0.704			<u> </u>
	August. 26	44.15	16.34	16.34 t	race	27.81	0.24	0.085	0.086	0.32	0.731	9.8	3	< 0.05
	Sept. 16	44.15	15.74	15.74	0	28.41			 - 					
	Oct. 30	44.15	16.25	16.25	0	27.90		~-	 			l		
	lov. 7	44.15	16.25	16.25	ŏ	27.90			 					
	lov. 20	44.15	16.33	16.33	0	27.82			 				····	
	Dec. 4	44.15	16.37	16.37	0	27.78			 					
	Dec. 11	44.15	16.37	16.37	0	27.78								
	eb. 9, 2004	44.15	16.65	16.65	0	27.50					-			
	eb. 19	44.15	16.65	16.65	0	27.50								
	March, 11	44.15		16.81		27.34	0.18	0.066	0.053	0.22		8.2	2.5	< 0.05
	pril. 5	44.15	17.82	17.82	0	26.33								
	príl. 22 1ay. 14	44.15	17.82	17.82	0	26.33								
—— <u> ^</u>	nay. 14	44.15	17.8	17.8	0	26.35								
<u>_</u>				1_		1						+		

Well	Date	Elevation			Product	Water	Benzene	Toluene	Ethyl	Xylenes	BTEX	GRO	DRO	MTBE
		<u> </u>			Thickness	Elevation			Benzene					
		ļ	Values	expressed	In feet				Concentr	ation expre	ssed in	mg/l		
		ļ		ļ	<u> </u>	<u>ļ.</u>	ļ	<u> </u>						
	1	44.45	77.0	/= -	ļ		ļ	<u> </u>			<u> </u>	<u> </u>	<u> </u>	
MW016	June. 17	44.15						<u> </u>					ļ	<u> </u>
continuec	f June. 30 July. 09	44.15 44.15						 	 	 	<u> </u>	ļ		
-	Jesy. US	44.13	10.31	10.37	<u>_</u>	21,10	 	 	 	ļ		ļ		<u> </u>
					 				- , -	<u> </u>		<u> </u>	ļ	
MW017	Jan.15-2003	Buried unde	r frozen dirt	and could i	of he gava	1 ort	 	 		ļ	 	ļ	 	
11111011	July. 24	42.26			trace	27.38	 				 	 	 	
	August 26	42.26		15.41	0			 	 					
	Oct. 30	42.26												
	Nov. 7	42.26						<u> </u>						
	Nov. 20	42.26	15.07	15.07	0.00									1
	Dec. 4	`42.26		15.07	0,00									1
(2	Dec. 11	42.26		15.1	0.00									
	Feb. 9, 2004	42.26		15.65	0.00									L
	Feb. 19	42.26		15.67	0.00			ļ						<u> </u>
	April. 5	42.26		15.85	0.00	26.41		ļ	ļ <u></u>					
	Not gauged. B	uncu under	gravel.	 		 	 	 					<u> </u>	ļ
	- 	 				 	 		 					
MW018	Jan.15-2003	49.98	23.02	23.03	0.01	26.95								
	Jan. 27	49.98	23.09	23.10	0.01	26.88		 	l					
 .	March. 05	49.98	22.41	22.41	0.00			 		<u></u>		ļ	· · · · · · · · · · · · · · · · · · ·	
	March. 18	49.98	22.70	22.70	0.00		1	1						
	April. 01	49.98	22.62	22.62	0.00	27.36		I						
	April. 17	49.98	22.52	22.52	0.00	27.46		L						
	April. 28	49.98	22.23	22.23	0.00									
	May. 20	49.98	22.34	22.34	0.00									
	June. 03	49.98	21.83	21.83	0.00									
	June. 10 June. 23	49.98	22.02 22.34	22.02		27.96								
	July. 15	49.98 49.98	21.27	22.34 21.27	0.00	27.64							***************************************	<u> </u>
	July. 24	49.98	21.43	21.43	tenco	28.71 28.55								
	August, 06	40.00	21,70	21.43	wave	20.55	< 0.005	< 0.005	< 0.005	< 0.01	0.025	0.14	0.82	< 0.01
·····	August. 26	49.98	21.96	21.96	frace	28.02	10.000	V 0.000	V 0.000	<u> </u>	0.023		0.02	V 0.01
	Sept. 16	49.98	22.11	22.11	0.00	27.87						····		
	Oct. 30	49.98	22.00	22.00	0.00	27.98								-
	Nov. 7	49.98	22.00	22.00	0.00	27.98								
	Nov. 20	49.98	21.95	21.95	0.00	28.03								
	Dec. 4	49.98	21.97	21.97	0.00	28.01								
	Dec. 11	49.92	22.00	22,00	0.00	27.92								
	Feb. 9, 2004	49.92	22.35	22.35	0.00	27.57								
····	Feb. 19 March, 11	49.92 49.92	22.30	22.30 25.40	0.00	27.62	- 0 00°	- 0.005	. 2 625					
	April. 5	49.92	22.57	22.57	0.00		< 0.005	< 0.005	< 0.005	< 0.01		0.2	0.93	< 0.01
	Monitoring disc	continued in	Andi 2004 n	or DC-UST	division ann	Z1.33		·						
	INIONINOTHING GIOC	2011411400	ψι 12004 p	61 50-001	urrision app	y Oyai.								
•	1													<u> </u>
MW019	Jan.15-2003	46.38	19.50	19.50	0.00	26.88								
	Jan. 27	46.38	19.70	19.72	0.02	26.66								
	March. 05	46.38	18.69	18.69	0.00	27.69			·					
	March, 18	46.38	19.10	19.11	0.01	27.27								
	April. 01	46.38	18.96	18.96	0.00	27.42								
	April. 17	46.38	18.67	18.67	0.00	27.71								
	April. 29	46.38	18.77	18.77	0.00	27.61	~~~~							
<u> </u>	May. 20	46.38	18.80	18.80	0.00	27.58								
	June. 03	46.38	18.51	18.51	0.00	27.87								
	June. 10	46.38	18.51	18.51		27.87								
	June, 23 July, 15	46.38 46.38	18.80	18.80 17.80	0.00	27.58		<u> </u>						
	July, 15 July, 24	46.38	17.80 18.05	18.05	0.00	28.58								
·	August. 06	40.00	10.03	10.00	0.00	28.33	0.007	< 0.005	< 0.005	< 0.030	0.027		07	Z 0 040
•	August. 26	46.38	18.58	18.58	0.00	27.80	0.007	~ v.v∪5	~ U.UUD	< 0.010	0.027	8	27	< 0.010
	Oct. 30	46.38	18.60	18.60	0.00	27.80	·							-
	Nov. 7	46.38	18.60	18.60	0.00	27.78								
	Nov. 20	46.38	18.53	18.53	0.00	27.78		ļ						
*****	Dec. 4	46.38	18.53	18.53	0.00	27.85								
	Dec. 11	46.38	18.53	18.53	0.00	27.85								
	Feb. 9, 2004	46.38	19.00	19.00	0.00	27.38								
	Feb. 19	46.38	19.00	19.00	0.00	27.38								
	March, 11	46.38		19.16		27.22	0.1	< 0.005	< 0.005	< 0.010		3.5	32	< 0.010
	April. 5	46.38	18.86	18.86	0.00	27,52								

Well	Date	Elevation	Depth to	Depth to	Product	Water	Benzene	Toluene	Ethyl	Xylenes	BTEX	GRO	DRO	МТВЕ
			Product	Water	Thicknes	s Elevation	1 201120110	110100111	Benzene	17.57.07.00	1 TILL	1000	- DICO	MIDE
			Values	expressed	In feet		+			ation expre	essed in	ma/l		
<u></u>		 	<u> </u>					T			1	T	T	
241470.40	1 . 11 . 00		ļ	ļ				T			1			
MW019 continued	April. 22 I May. 14	46.38												_
COMMITTER	June, 17	46.38						<u> </u>						
	June. 30	46.38 46.38									1			
	July. 09	46.38						<u> </u>		<u> </u>		<u> </u>		
ļ	July. 09	40.30	19.25	19.25	0.00	27.1	3			<u> </u>	ļ			
ļ				<u> </u>	ļ						1.			
MW020	Jan.15-2003	46.09	40.00	40.00						ļ				
17177020	Jan. 27	46.09												
<u> </u>	March, 05	46.09			0.0									T
 	March, 18	46.09									<u> </u>			
<u> </u>	April. 01	46.09		18.81 18.01						<u> </u>	ļ			
	April. 17	46.09		17.89				_			L			
	April. 29	46.09		18.48								<u> </u>	<u> </u>	
<u> </u>	May. 20	46.09		18.53				 						
 	June, 03	46.09	18.28	18.28				1			<u> </u>	<u> </u>		
	June. 10	46.09	18.20	18.20				·			L			J
<u> </u>	June, 23	46.09	18.53	18.53				-			ļ			
	July. 15	46.09	17.51	17.51		28.56		 	 	<u> </u>		ļ	ļ	
	July. 24	46.09	17.77	17.77	0.00			 		<u> </u>	ļ	ļ	1	
	August. 06	1	17.47	11.11	0.00	20.32		< 0.005	< 0.005	- 0 04	0.000	ļ <u>.</u>	J	
	August, 26	46.09	18,30	18.30	trace	27.79			< 0.005	< 0.01	0.032	2	2.6	< 0.01
·	Sept 16	46.09	18.4	18.4	uace 0			 	 			ļ	.	-
	Oct. 30	46.09	18.3	18.3			1	-	 		ļ		 	
	Nov. 7	46.09	18.3	18.3	Ö			 	 	 	 		 	4
	Nov. 20	46.09	18.24	18.24	Ö			 	 	ļ			ļ	
	Dec. 4	46.09	18.25	18.25	0			 	 				ļ	
	Dec. 11	46.09	18.25	18.25	ŏ			 					 	
	Feb. 9, 2004	46.09	18.73	18.73	Ö				 				 	
	Feb. 19	46.09	18.75	18.75	Ö			 	 					
	March. 11	46.09		18.89			< 0.005	< 0.005	< 0.005	< 0.01		1.5	4 1	< 0.01
	April. 5	46.09	19.16	19.16	0				1	-0.01		1.0		1 0.01
	April. 22	46.09	19.16	19.16	0				1					
	May. 14	46.09	18.9	18.9	0			-	1					
	June. 17	46.09	19.05	19.05	0								 	
	June. 30	46.09	19	19	0	27.09			1				 	
	July. 09	46.09	18.77	18.77	0	27.32			1					
MW021	Monitoring wa	s discontinue	d in 1994 pe	r DC-UST [Division app	roval. Burie	ed under as	phalt.						
									1					
	ļ													
MW022	Jan.15-2003	47.37	20.5	20.5	0	26.87								
	Monitoring dis	continued in F	ebruary 200	3 per DC-L	JST Division	approval.						:		·
MW023	June.10-2003	43.98	16.28	16.28	0	27.70								
	June. 23	43.98	16.67	16.67	0	27.31					-			
	July. 15	43.98	15.53	15.53	0				IT					
	July. 24	43.98	15.79	15.79	0	28.19								
	August, 05 August, 26	42.00					< 0.005	< 0.005	0.043	< 0.01		0.79	31	< 0.01
	Nov. 7	43.98 43.98	16.4	16.4	0	27.58				T				
	Nov. 20		16.95	16.95	0	27.03								
	Dec. 4	43.98 43.98	16.35	16.35	0	27.63			ļI		T			
	Dec. 4 Dec. 11	43,98	16.4	16.4	0	27.58			LI					
	Feb. 9, 2004	43,98	16.44	16.44	0	27.54				T				
····	Feb. 19	43.98	16.75	16.75	0	27.23			LL					
	March, 10	43.98	16.75	16.75	0	27.23				I	T			
	April. 5	43.98	18.88	17			< 0.006	< 0.005	< 0.016	< 0.010		1.3	2.1	< 0.01
	Well is full of m	ud GVD0s :-	io.oo	18.88	0 0	25.1								
	10 1011 01 11	1	ascu iii pia	oc or uns w	en for mont	onng.								
			<u>-</u>									I		
MW024	Oct. 23-2002	44.99	18.80	10 00 4	5366									
	Nov. 07	44.99	18.73	18.80 t		26.19			L			1		
		Blocked - No		18.73	0.00	26.26						T		
	Nov. 21	44.99	18.48	40 46								1]	
	Dec. 09	44.99	18.65	18.48	0.00	26.51						I		
	Dec. 19	44.99		18.65	0.00	26.34]		
	Dec. 19 Dec. 27	44.99	18.49 18.40	18.49	0.00	26.50		····				1		
	Jan. 07-2003	44.99		18.40	0.00	26.59						I		
	Jan. 07-2003 Jan. 27		18.17	18.17	0.00	26.82				I]
	March, 05	44.99	18.35	18.37	0.02	26.62								1
	maich. US	44.99	16.31	16.31	0.00	28.68						T		

Well	Date	Elevation	Depth to	Depth to	Product	Water	Benzeni	Toluen	Ethyl	Xylenes	BTEV	Tono	7000	· 1
ļ			Product	Water	Thickness	Elevation	1 20112011	11010011	Benzen	VAIGIIGS	DIEY	GRO	DRO	MTBE
<u> </u>		ļ	Values	expresse	in feet	· · · · · · · · · · · · · · · · · · ·	·		Concer	tration exp	resend in	1		
		 	<u> </u>				1		1	1	10330011	- 111B(1		
MW024	March. 18	14.00									 		+	
	ed April. 01	44.99 44.99										1	1	
	April 17	44.99											1	-
	April. 28	44.99	17.40											
	May. 20	44.99						- 	 					
	June. 03	44.99	16.90			28.0		 				<u> </u>		
	June. 10	44.99	17.03		trace	27.9						 		
	June. 23	44.99	17.39	17.39	trace	27.6					- -	—	 	
	July. 15	44.99	16.47	16.47	trace	28.5		 				┼	 	
	July, 24	44.99	16.76	16.73	3	28.26					 	 	 	
	August. 06 August. 26	44.00	45.04				0.0	2 ND	0.006	3 ND		1.6	7	OND
———	Sept. 16	44.99 44.99	17.31 17.35		trace	27.68							1	11.5
	Oct. 30	44.99	17.30	17.35 17.30		27.64								
	Nov. 7	44.99	17.30	17.30		29.40 27.73		 						
	Nov. 20	44.99	17.30	17.30		29.56		 				<u> </u>		
	Dec. 4	44.99	17.30	17.30		29.85		 				 	 	
	Dec. 11	44.99	17.32	17.32		30.02					 	 	 	
 	Feb. 9, 2004	44.99	17.76	17.76		27.23		1			 		 	
 	Feb. 19	44.99	17.75	17.75		27.24	1				 		 	
	March. 10 April. 5	44.99 44.99	74.72	17.95			< 0.019	< 0.005	< 0.0097	< 0.010	1-	0.94	64	< 0.010
 	April. 22	44.99	17.83	17.83		30.27					1		<u> </u>	1
	May. 14	44.99	17.83 17.82	17.83 17.82		30.27								
	June. 17	44.99	17.87	17.87	0.00	30.96		 						
	June. 30	44.99	17.95	17.95	0.00	30.96 27.04		 	 	<u> </u>	ļ			
	July. 09	44.99	17.83	17.83	0.00	27.16		 -	 		 			<u> </u>
				***************************************	- ****			 	 	+	 			
41144000								 	+	 	-			
MW025	Jan.15-2003	42.47	15.58	15.59	0.01	26.88		 -	 	 				
	Jan. 27 March. 05	42.47	17.25	17.26	0.01	25.21				†	1			
····	March, 18	42.47 42.47	15.43	15.43	0.00	27.04								
·····	April. 01	42.47	15.14 14.97	15.14 14.97	0.00	27.33								1
	April. 17	42.47	14.81	14.81	0.00	27.50			ļ	<u> </u>				
	April. 28	42.47	15.13	15.13	0.00	27.66 27.34			ļ	<u> </u>				
	May. 20	42.47	14.83	14.83	0.00	27.64			 	 	 			
	June. 03	42.47	14.72	14.72	0.00	27.75			 	 	 			
	June. 10	42.47	14.43	14.43	trace	28.04	·		 	 				-
	June. 23	42.47	14.14	14.14		28,33				 	 			
	July. 15 July. 24	42.47	14.03	14.03		28.44								
	August 07	42,47	14.60	14.60	trace	27.87								
	August. 26	42.47	15.30	15.30	imaa	07.47	1.4	0.13	< 0.05	0.17	0.175	4.6	42	< 0.1
	Sept. 16	42.47	15.04	15.04	0.00	27.17 27.43			ļ					
	Oct. 30	42.47	15.08	15.08	0.00	27.39		·		ļ				
	Nov. 7	42.47	15.10	15.10	0.00	27.37		····	 	ļ				
	Nov. 20	42.47	14.95	14.95	0.00	27.52			 	 				
	Dec. 4	42.47	15.00	15.00	0.00	27.47		**	 	 				
	Dec. 11 Feb. 9, 2004	42.47	15.00	15.00	0.00	27.47			l	 				
	Feb. 19	42.47	15.58	15.58	0.00	26.89			L			-+		
	March. 10	42.47 42.27	15.60	15,60	0.00	26.87								
	April. 5	42.47	15.75	15.73 15.75		26.54	1	< 0.033	< 0.010	0.063		4.8	16	< 0.02
	April. 22	42.47	15.75	15.55	0.00	26.72			ļ					
	May 14	42.47	15.72	15.72	0.00	26.92 26.75				ļ		- T		
	June. 17	42.47	16.03	16.03	0.00	26.44				 			I	
·	June. 30	42.47	15.37	15.37	0.00	27.10			ļ			<u>-</u>]
	July. 09	42.47	15.62	15.62	0.00	26.85								
1W026	lon 45 0000													
111020	Jan. 15-2003	45,17	17.08	17.08	0.00	28.09					- -			
	Jan. 27 March. 05	45.17 45.17	17.72	17.73	0.01	27.44								
	March, 18	45.17 45.17	16.62 16.60	16.62	0.00	28.55	I							
·········	April. 01	45.17	15.03	16.60	0.00	28,57								
··· · · · · · · · · · · · · · · · · ·	April, 17	45.17	14.91	15.03 14.91	0.00	30.14								
	April. 28	45.17	16.62	16.62	0.00	30.26 28.55								
	May. 20	45.17	16.85	16.85	0.00	28,32								
	May. 28	45.17	16.02	16.02	0.00	29.15	0.005	0.005	< 0.005	- 0.00c				
	June. 03	45.17	16.70	16.70	0.00	28.47		- 0.000	C00.0 /	< 0.005		0.22	0.18	< 0.01
	June. 10	45.17	16.50	16.50 tr	ace	28.67						 -		
	 	··········				~0.07								

Turk Barthers

District a second

personalists sug

STATE STATE OF

	Date	Elevation	Depth to	Depth to	Product	Water	Benzer	e Toluen	e Ethyl	Xylenes	BTEX	1050	1000	
			Product	Water	Thicknes	s Elevatio	n	10.000	Benzen	Aylelles	PIEV	GRO	DRO	MTE
			Values	expresse	d in feet		<u> </u>		Concer	tration exp	Occod I			
			<u> </u>			T			1	I axp.	62280 11	i mg/i		
ALLIANA	- L												┼──	
MW026	June. 23	45.17		15.5	9 trace	29.5	8						 	
continue		45.17		16.1	0 trace	29.0			- 			 		
	- July. 24	45.17	16.17	16.1	7 trace	29.0					 	 	<u> </u>	
	July. 31					1 - 3713	< 0.005	< 0.005		20 20 000	-	 		
	August, 26	45.17		16.7	3 trace	28.4		- 0.003	0.02	22 < 0.021		0.47	1.	1 < 0.0
	Sept. 16	45.17		16.4							 			
	Oct. 30	45.17		16.4							Ь			
	Nov. 7	45.17	16.45	16.4										
	Nov. 13		T		<u> </u>	20.1	< 0.005				ļ			7
	Nov. 20	45.17	16.55	16.5	5 0.0	28.6		< 0.005	< 0.005	< 0.01		0.21	0.5	1 < 0.0
	Dec. 4	45.17	16.58	16.5										
	Dec. 11	45.17		16.6					 					
	Feb. 9, 2004	45.17	16.67	16,6				- 	<u> </u>					
	Feb. 19	45.17	16.67	16.6							Ĺ			1
	March. 29	45.17		17.4										T
	April. 5	45.17	17.00	17.0		27.7	0.006	6 < 0.005	< 0.005	< 0.01		0.57	0.0	0.0
	April. 22	45.17	17.06	17.0										1
	May. 14	45.17	17.04	17.04										
	June. 17	45.17	17.17											
	June. 30	45.17	17.16	17.17				-				- 1		1
	July. 09	45.17	16.86	17.16						1	T	 		
	August, 05	1 ~~~~1/ 	10.00	16.86	0.00	28.31								+
	1	 			 		< 0.005	< 0.005	< 0.005	< 0.001		0.21	0.5	< 0.01
	1	 			 						,	 	0.0	1
W027	Jan. 15-2003	43.90	16 70		ļ							-		1
 	Jan. 27	43.90	16.79	16.79		27.11								
	March. 05	43.90	17.38	17.39	0.01	26.51				T				
	March. 18	43.90	16.34	16.34		27.56								╁
· · · · · · · · · · · · · · · · · · ·	April. 01	43.90	16.29	16.29		27.61				"				
	April. 17	43.90	16.10	16.10		27.80		L		1				
	April, 28		16.03	16.03		27.87			T	1				
	May. 20	43.90 43.90	16.28	16.28		27.62		<u> </u>				 	 -	
	June. 03		16.00	16.00		27.90					<u> </u>	+		
	June. 10	43.90	15.71	15.71	0.00	28,19		1	1					 -
	June. 23	43.90	15.78	15.78	trace	28.12		1		1				ļ
	July. 15	43.90	15.28	15.28	trace	28.62			<u> </u>	1				
·	July. 13	43.90	15.34	15.34	trace	28.56				 				
	July. 24 July. 31	43.90	15.83	15.83	0.00	28.07		<u> </u>	 	 	+	<u>-</u> -		
	August, 26	42.60					< 0.025	0.026	0.31	0.35	0.35	4.3		-0.00
	Sept. 16	43.90	16.38	16.38	0.00	27.52				- 5,00	- 0.00		3.0	< 0.05
	Oct. 30	43.90	16.17	16.17	0.00	27.73			 	 	——-			
	Nov. 7	43.90	16.17	16.17	0.00	27.73				 				
	Nov. 20	43.90	16.19	16.19	0.00	27.71				 		 		
	Dec. 4	43.90	16.25	16.25	0.00	27.65			 					
		43.90	16.27	16.27	0.00	27.63								 ,
	Dec. 11 Feb. 9, 2004	43.90	16.25	16.25	0.00	27.65				 				
		43.90	16.72	16.72	0.00	27.18		·						
	Feb. 19	43,90	16.70	16.70	0.00	27.20		-					——	
	March. 8	43.90		16.84			< 0.017	< 0.012	< 0.019	< 0.040	 -	 -		
	April. 5	43.90	16.67	16.67	0.00	27.23		V.V 12	0.013	< 0.049		1.8	2	< 0.010
	April. 22	43.90	16.77	16.77	0.00	27.13		·					\longrightarrow	
	June. 17	43.90	16.97	16.97	0.00	26.93								
	June. 30	43.90	16.78	16.78	0.00	27.12							\longrightarrow	
	July, 09	43.90	16.84	16.84	0.00	27.06			·			<u> </u> _		
			T							·····				
(000	, , , , , , , , , , , , , , , , , , , ,									, j .				
	Jan.15-2003	43.96	16.72	16.72	0.00	27.24							I	
	Jan. 27	43.96	17.85	17.86	0.01	26.10				<u>-</u>				
	March 05	43.96	16.36	16.36	0.00	27.60			l	<u> </u> _				
	March, 18	43.96	16.28	16.28	0.00	27.68								
	April. 01	43.96	16.15	16.15	0.00	27.81								
	April. 17	43.96	15.86	15.86	0.00	28.10								
	April. 28	43.96	16.25	16.25	0.00	27.71					-1			
	Иау. 20	43.96	16.05	16.05	0.00	27.91								
J	une. 03	43.96	15.80	15.80	0.00									
	une. 10	43.96	15.75	15.75 t		28.16		[
	une. 23	43,96	15.30			28.21			T					
	uly. 15	43.96	15.30	15.30 to	ace	28.66						\dashv		
	uly. 24	43.96		15.30 t	ace	28.66								
	uly. 31	70.30	15.75	15.75 tr	ace	28.21					_	-+		
							0.025 <	0.025	0.68	0.67		6.4	83	0.05
J	United 26					07.041				7.01		V. 71	0315	0.00
J	ugust. 26	43.96	16.35	16.35 tr		27.61				""				
J A S	ept. 16 Oct. 30	43.96 43.96 43.96	16.35 16.17 16.15	16.35 tr 16.17	0.00 0.00	27.61 27.79 27.81							_	

Well	Date	Elevation	Depth to	Depth to	Product	Water	Benzene	Toluene	Ethyl	Xylenes	BTEX	GRO	Inno	1
	<u> </u>		Product	Water	Thickness		201120110	70100110	Benzene	VAIGINGS	PIEV.	GRO	DRO	MTBE
			Values	expressed	In feet	Lorovation		I		1	1	ــــــــــــــــــــــــــــــــــــــ		
				1	T	·			Concenti	ation expre	ssea in	mg/i	т	
	1				 						ļ	<u> </u>		1.
MW028	Nov. 7	43.96	16,15	16.15	0.00	27.81					 	ļ	<u> </u>	
continued	Nov. 20	43.96	16.18						ļ	ļ	 			1
	₽ec. 4	43.96		16.20	0.00				 		 -		ļ	<u> </u>
	Dec. 11	43.96	16.20	16.20	0.00					 	 	<u> </u>	<u> </u>	
	Feb. 9, 2004	43.96	17.03	17.03	0.00				 		 	 	ļ	ļ
	Feb. 19	43.96	17.05	17.05	0.00				 	 -	 -	<u> </u>		ļ
	March, 09	43.96		16.85			< 0.021	< 0.016	0.3	0.15	 			
	April. 5	43.96	17.64	17.64	0.00	26.32		-0.0.0		V. 15	 	5.1	28	< 0.020
	April. 22	43.96	16.72	16.72	0.00	27.24		····	 					<u> </u>
	May. 14	43.96	16.80	16.80	0.00	27.16			 		ļ			
	June. 17	43.96	17.03	17.03	0.00	26.93			·					
	June, 30	43.96	16.80	16.80	0.00	27.16			 					
	July. 09	43.96	16.95	16.95	0.00	27.01			 				ļ <u>.</u>	ļ
													 	
	<u> </u>					`				~~~~				
	Note: Trace m	eans the tap	e beeped,	but there w	as not eno	ugh produc	t to be me	asurad					ļ	

i.

Land Control

Total Marie

1

Company of the Control of the Contro

To: Distribution

From: F. Mahvi Jm

Re: LUST CASE #93094 - BUZZARD POINT GASOLINE UST

Date: June 1, 1994

Distribution:

Ms.

B. Gonzalez

Messrs

R. Armstrong

J. Keiller I. Monsef

M. Boland

M. Reilly

B. Campbell

M. Halpern

J. Sherman

Attached please find a case closure letter from DCRA authorizing the closure of the above referenced case. The 20,000 gallon gasoline UST was removed on 8/24/93. An UST closure report, and a site assessment report were submitted to DCRA per DCRA's directive letter dated 8/30/93. The assessment report for this case was submitted as an addendum to the comprehensive site assessment report for Buzzard Point Facility.

Mr. J. Potts cc:

Ms. F. Sepulveda

CF: Underground Storage Tanks

ANU'L CC: JFM

POTOMAC ELECTRIC POWER COMPANY 1900 PENHS

VANIA AVENUE, N. W., WASHINGTON, D. C. 20068 (202) 872-2000

April 28, 1988

Mr. M. W. Cramer Marketing Manager - Wholesale Chevron, U.S.A., Inc. 810 Gleneagles Court Towson, MD 21204

Dear Mr. Cramer:

We have reviewed the status of the two fuel tanks located at First and T Streets, SW, Washington, DC as referenced in your letter of December 3, 1987, and have determined they are no longer required for use on our system. We therefore accept your offer to have Chevron remove these two tanks at Chevron's expense.

Please contact Mr. Richard M. Armstrong of our Substation Construction and Maintenance Department (202-388-2300) to coordinate their removal.

Very truly yours,

D. F. Morrison, Manager

Petroleum Products Procurement

DFM:bjg

3

cc: Mr. M. R. Dargento Chevron U.S.A., Inc. 3790 Pickett Road Fairfax, VA 22031

bcc: C. W. Nicolson

L. J. O'Callaghan-

L. J. Himes

R. M. Armstrong

C. T. Milans

A. G. Merlene





ź٠

Mr. D. F. Morrison

:MG

C. T. Milans

IBJECT:

Disposition of Fuel Tanks at Buzzard Point

DATE:

March 30, 1988



Please reference Mr. M. W. Cramer's letter to you dated December 3, 1987 and your subsequent memorandum.

Our records indicate that both tanks are 6000 gallon units - not one at 8000 and one at 6000. At this time both are idle. One contains 3,424 gallons of lead gasoline and the other contains 5,199 gallons of diesel fuel.

These tanks are steel and were installed in 1970. Given their life expectancy, the cost to upgrade them to proposed Federal regulations outweighs their usefullness. Further, the trend is to remove steel tanks and replace them with fiberglass.

As the type of vehicles that refuel at this location predominately use unleaded gasoline, the continued need for additional fuel tanks is not indicated.

It is therefore recommended that Chevron U.S.A., Inc. remove their fuel tanks. Extreme care should be taken not to disturb the 20,000 gallon fuel tank in the ground at that location. At the time of removal, if there is a leak, Chevron will be responsible for any environmental liability and all clean-up costs.

JOE/hv

cc: Mr. J. F. Miley

Mr. H. A. Martin

Mr. L. J. O'Callaghan

Mr. L. S. Guiland

Ms. M. A. Golden



ORM 4212-6

Mr. J. A. Brain

R. M. Armstrong

SUBJECT:

See Below

ATE:

November 21, 1988



Subject: Removal of Two (2) 6000 Gallon Fuel Tanks

First and "T" Streets, S.W. - Buzzard Point

This memorandum is to inform you that on November 28 and 29, 1988 the representatives from the organizations listed below will need access to the subject property in order to remove two (2) 6000 gallon fuel tanks and two (2) dispensing pumps. This operation will be performed between 7:00 am and 6:00 pm daily. Substation Construction and Maintenance will provide a full time safety person at the site during the operation.

Organization Name

Eastern Motor Transport

Stone and Hoover

Chevron

Paul Resnick, Inc.

Self Service Systems

D. C. Fire Marshal

Equipment

18 wheel tanker truck

Dump truck and trailer with

backhoe, rubber tire crane

Tanker truck

Service Truck

Service truck

Should you have need for additional information concerning this project, please contact Mr. Iraj Monsef on extension 131-244.

IM/jam

cc: Mr. L. J. Himes

Mr. T. D. Edwards

Mr. C. R. Orrison, Jr.

Mr. J. Q. Engquist

Mr. J. E. Luley

Mr. L. J. O'Callaghan Mr. J. H. Keiller

Mr. I. Monsef

Mr. D. F. Morri



DAILY/STA.B

Facility No. 2000609



District of Columbia Department of Health Environmental Health Administration Bureau of Hazardous Materials and Toxic Substances Underground Storage Tank Division

CERTIFICATE OF TANK REGISTRATION

This certifies that PEPCO - BUZZARD POINT GEN.STAT-B

Underground Storage Tank Facility has been duly registered with the District of Columbia and that the tank registration fees have been remitted. This Certificate is valid provided that all other requirements have been met in accordance with Title 20 DCMR Chapters 55-68.

Facility Address:

1ST & V ST SW Washington, DC 20024

> Dr. V. Sreenivas, Chief for Hazardoue Marerlal and Toxic

This certificate effective 01 Jan 2003 and expires 31 Dec 2003.

This certificate authorizes the use of the listed underground storage tank system(s) only in accordance with the District of Columbia Underground Storage Tank Management Act of 1990 (D.C. Law 8-242) and supporting regulations.

The following tank(s) have been duly registered at this facility:

TANK STATUS

DESCRIPTION

SUBSTANCE STORED

009 Currently in Use

4,000 gal. Composite (Steel w/ FRP); Double-Walle

Used Oil

010 Currently in Use

4,000 gal. Composite (Steel w/ FRP); Double-Walle

Used Oil

Notification for Underground Storage Tanks		STATE USE ONLY
State Apendy Name and Address Underground Storage Tank Program, D.C. Environmental Control Division, 2103 MUX Avenue SE, Wate	hington, DC 20020	ID NUMBER 2-000609
TYPE OF NOTIFICATION		DATE RECEIVED
	CLOSURE	A. Date Entered into Computer
		B. Data Entry Clerk Initials C. Owner Was Contacted to
TO NO. O. Takes at the same	3. allab.100	Clarify Responses. Comments
INSTRUCTIONS		
Please type or print in ink all items except "signature" in section must be completed for each location containing underground stora more than five (5) tanks are owned at this location, photocopy the faheets, and staple continuation sheets to the form.	ge tanks. II	
GENERALIN	EORMATIC	ON
Notification is required by Federal law for all underground tanks that have been used to store regulated substances since January 1, 1974, that are in the ground as of May 8, 1986, or that are brought into use after May 8, 1986. The information requested is required by Section 9002 of the Resource Conservation and Recovery Act, (RCRA), as amended. The primary purpose of this notification program is to locate and evaluate underground tanks that store or have stored petroleum or hazardous substances. It is expected that the information you provide will be based on reasonably available records, or in the absence of such records, your knowledge, belief, or recollection. Who Must Notify? Section 9002 of RCRA, as amended, requires that, unless exempted, owners of underground tanks that store regulated substances must notify designated State or local agencies of the existence of their tanks. Owner means— a) in the case of an underground storage tank in use on. November 8, 1984, or brought into use after that date, any person who owns an underground storage tank used for the storage, use, or dispensing of regulated substances, and b) in the case of any underground storage tank in use before November 8, 1984, but no longer is use on that date, any person who owned such tank immediately before the discontinuation of its use. c) If the State agency so requires, any facility that has undergone any changes to facility information or tank system status (only amended tank information needs to be included). What Tanks Are Included? Underground storage tank is defined as any one or combination of tranks that (1) is used to contain an accumulation of regulated substances, and (2) whose volume (including connected underground tanks storing: 1, Gasoline, used oil, or diesel fuel, and 2, industrial solvents, pesticides, herbicides or furnigants. What Tanks Are Excluded? Tanks removed from the ground are not subject to notification. Other tanks excluded from notification are: 1, farm or residential tanks of 1,100 galions or	Pipeline Safety which is an intraction of the statement o	I lacifities (including gathering lines) regulated under the Natural Gas y Act of 1968, or the Hazardous Liquid Pipeline Safety Act of 1979, or trastate pipeline facility regulated under State laws; impoundments, pits, ponds, or lagoons; rater or waste water collection systems; ough process tanks; age or associated gathering lines directly related to oil or gas of gathering operations; tanks situated in an underground area (such as a basement, cellar, drift, shaft, or tunnel) if the storage tank is situated upon or above the floor. Setances Are Covered? The notification requirements apply to under tanks that contain regulated substances. This includes any lines as hazardous in section 101 (14) of the Comprehensive in Response, Compensation and Liability Act of 1980 (CERCLA), with of those substances regulated as hazardous waste under Subtitle C iso includes petroleum, e.g., crude oil or any fraction thereof which is lead conditions of temperature and pressure (60 degrees Fahrenheit and per square inch absolute). 5 Notify? Send completed forms to: Underground Storage Tank Program D.C. Environmental Control Division 2100 MLK Avenus SE Washington, DC 20020 Notify? 1. Owners of underground storage tanks in use or that have an of operation after January 1, 1974, but still in the ground, must not 36, 2. Owners who bring underground storage tanks into use after Met cation of any amendments to the facility send information to State diataly.
1. farm or residential tanks of 1,100 gallons or less capacity used for storing motor fuel for noncommercial purposes; 2. tanks used for storing heating oil for consumptive use on the premises where stored;	tion shall be t	ny owner who knowlingly sales to hotify or submits sales knowling subject to a civil penalty not to exceed \$10,000 for each tank for ation is not given or for which false information is submitted.
I. OWNERSHIP OF TANK(S)		II. LOCATION OF TANK(S)
	If required by Stat Exemples Lat, 42	axe, give the geographic location of tanks by degrees, minutes, and seconds. -2, 36, 12 N Long, 85, 24, 17W
Owner Name (Corporation, Individual, Public Agency, or Other Entity) Potomac Electric Power Company Street Address		e Longitude
1900 Pennsylvania Avenue, N.W.		(If same as Section I, mark box here)
Washington, D.C. 20068	Buzzaro Street Address	or Company She Identifier, as attributed to Point Station a (P.O. Box not acceptable) V. Stroot S. W.
202/ 872~2000		V Street, S.W. agton, D.C. 20024
Phone Number (Incade Area Code)	Cky	State Zp cod∙
	County	Municipality

III. TYPE OF OWNER	. IV. INDIAN LANDS						
☐ Federal Government ☐ Commercial	Tanks are located on land within an Indian Reservation or on other trust lands. Tribe or Nation:						
State Government Private Local Government	Tanks are owned by native American nation, tribe, or individual.						
	V. TYPE OF FACILITY						
Select the Appropriate Facility Description	······································						
Gas Station	RailroadTrucking/Transport						
	Federal - Non-Military XX Utilities						
Air Taxi (Airline)	Federal - Military Residential						
Aircraft Owner	IndustrialFarm						
Auto Dealership	ContractorOther (Explain)						
VI. CONT	FACT PERSON IN CHARGE OF TANKS						
Name Job Title	Address Phone Number (Include Area Code)						
Fariba Mahvi Project Engine	er 1900 Penn. Ave., 202/331-6641 Wash.DC 20068						
VI	I. FINANCIAL RESPONSIBILITY						
I have met the fin accordance with	ancial responsibility requirements in XX ,						
Check All that Apply Self Insurance XX Commercial Insurance	Guarantee State Funds Surety Bond Trust Fund						
Risk Retention Group	Letter of Credit Cther Method Allowed Specify						
VIII. CERTIFICAT	ION (Read and sign after completing all sections)						
I certify under penalty of law that I have personally endocuments, and that based on my inquiry of those in submitted information is true, accurate, and complete	xamined and am familiar with the information submitted in this and all attached dividuals immediately responsible for obtaining the information, I believe that the e.						
Name and official title of owner or owner's authorized representative (Print) John H. Keiller Sr. Project Engineer	Signature furballally Date Signed 1/31/94						
gathering and maintaining the data needed and com Chief, Information Policy Branch PM-223, U.S. Envir	to average 30 minutes per response including time for reviewing instructions, inpleting and reviewing the form. Send comments regarding this burden estimate to ronmental Protection Agency, 401 M Street, Washington D.C. 20460, marked the previous notification form as printed in 40 CFR Part 280, Appendix I. Previous supplies last.						

Ç.

X. DESCRIPTION OF UNI					•
Tank Identification Number	Tank No	B Tank No. UTP2-	BTank No. UIP3-	-B _{Tank No.} UTP4-	B Tank No
1. Status of Tank (mark only one) Currently in Use					
Temporarily Out of Use					
Permanently Out of Use	XX	XX	XX	XX	
Amendment of Information					
2. Date of Installation (mo./year)	1968	1968	1968	. 1968	
3. Estimated Total Capacity (gallons)	2,000	2,000	2,000	2,000	7
Material of Construction (Mark all that apply)					
Asphalt Coated or Bare Steel	XX	XX	XX	XX	
Cathodically Protected Steel					
Epoxy Coated Steel					
Composite (Steel with Fiberglass)					
Fiberglass Reinforced Plastic					
Lined Interior					
Double Walled					
Polyethylene Tank Jacket					
Concrete					
Excavation Liner					
Unknown					
Other, Please specify					
	l				
Has tank been repaired? 5. Piping (Material)					
(Mark all that apply) Bare Steel	XX	XX	XX	xx	
Galvanized Steel					
Fiberglass Reinforced Plastic					
Саррег					
Cathodically Protected					
Double Walled					
Secondary Containment					
Unknown					
Other, Please specify					,
6. Piping (Type) (Mark all that apply)					
Suction: no valve at tank]				
Suction: valve at tank					
Pressure					
. Gravity Feed	xx	xx	XX	xx	
Has piping been repaired?					

IX. DESCRIPTION OF UNI	DERGROUND STORAGE TANKS (Complete for each tank at this location.)						
Tank Identification Number	Tank No. ^{5⊕}	Tank No. 6P	Tank No. 7P	Tank No. 8P	Tank No		
1. Status of Tank (mark only one) Currently in Use							
Temporarily Out of Use (Remember to # out section X)							
Permanently Out of Use	xx	XX	XX				
Amendment of Information							
2. Date of Installation (mo./year)	UNKNOWN	UNKNOWN	UNKNOWN	UNKNOWN			
3. Estimated Total Capacity (gallons)	10,000	10,000	2,000	500			
Material of Construction (Mark all that apply)							
Asphalt Coated or Bare Steel	XX	XX	XX	XX			
Cathodically Protected Steel							
Epoxy Coated Steel							
Composite (Steel with Fiberglass)							
Fiberglass Reinforced Plastic							
Lined Interior							
Double Walled							
Polyethylene Tank Jacket							
Concrete							
Excavation Liner							
Unknown							
Other, Please specify							
		<u></u>					
			,	[]			
Has tank been repaired?			L	<u> </u>			
5. Piping (Material) (Mark all that apply) Bare Steel							
Galvanized Steel							
Fiberglass Reinforced Plastic							
Copper							
Cathodically Protected							
Double Walled							
Secondary Containment							
Unknown	XX	XX	XX	XX			
Other, Please specify							
6. Piping (Type) (Mark all that apply)	UNKNOWN	UNKNOWN	UNKNOWN	UNKNOWN	,		
Suction: no valve at tank							
Suction: valve at tank							
Pressure				·			
Gravity Feed							
Has piping been repaired?							

X. DESCRIPTION OF UNDERGROUND STORAGE TANKS (Complete for each tank at this location.)										
Tank Identification Number	Tank No.[77725-	BTank No.UTP6-	BTank No.	Tank No.	Tank No					
1. Status of Tank (mark only one) Currently in Use	XX									
Temporarily Out of Use										
Permanently Out of Use										
(Amendment of Information										
2. Date of Installation (mo./year)	9/1993	10/1993								
3. Estimated Total Capacity (gallons)	4,000	4,000								
4. Material of Construction										
(Mark all that apply)										
Asphalt Coated or Bare Steel										
Cathodically Protected Steel										
Epoxy Coated Steel										
Composite (Steel with Fiberglass)	XX	XX								
Fiberglass Reinforced Plastic										
Lined Interior										
Double Walled	XX	XX								
Polyethylene Tank Jacket										
Concrete		<u> </u>								
Excavation Liner										
Unknown										
Other, Please specify	Buffhide	Buffhide								
3.1121, 1.10255 Sp. 60.17	12.14.2.4.3.4.12									
. Has tank been repaired?										
5. Piping (Material)										
(Mark all that apply) Bare Steel										
Galvanized Steel										
Fiberglass Reinforced Plastic		L	L							
Copper										
Cathodically Protected	XX	XX								
Double Walled										
				<u> </u>						
Secondary Containment				<u> </u>						
Unknown				L						
Other, Please specify	Coated &	Coated &								
τħ.	rapped Steel	Wrapped Stee	21							
6. Piping (Type) (Mark all that apply)										
Suction: no valve at tank										
Suction: valve at tank										
Pressure										
Gravity Feed	XX	XX								
Has piping been repaired?										

1 ank identification number	Lank No. 111	lank No	Tank No	Tank No. 1 C4	Tank No.
7. Substance Currently or Last Stored In Greatest Quantity by Volume Gasoline Diesel Gasohol Kerosene Heating Oil Used Oil Other, Please specify	Waste Oil	Waste Oil	Waste Oil	-Waste Oil	
Hazardous Substance CERCLA name and/or, CAS number					
Mixture of Substances Please specify					
X.	TANKS OUT OF	JSE, OR CHANG	E IN SERVICE	<u> </u>	
1. Closing of Tank A. Estimated date last used (mo./day/year) B. Estimate date tank closed (mo./day/year)	8/12/92 8/13/92	9/6/93 9/9/93	_10/11/93 _10/13/93_ 	8/28/91 8/28/91	
C. Tank was removed from ground D. Tank was closed in ground E. Tank filled with inert material Describe	XX	XX			
F. Change in service . 2. Site Assessment Completed	XX	XX		XX	
Evidence of a leak detected Corrective action conducted in	XX		XX	XX	

į	Tark Identification Number	Tank No. 5P	Tank No6P	Tank No. 7P	Tank No. 8P	Tank No
,	7. Substance Currently or Last Stored In Greatest Quantity by Volume Gasoline Diesel Gasohol Kerosene Heating Oil Used Oil Other, Please specify Hazardous Substance CERCLA name and/or, CAS number	XX No. 2 Fuel Oil	XX XX No. 2 Fuel Oil	Fuel Additiv	Varsol	
	Mixture of Substances Please specify					
L	X	. TANKS OUT OF U	JSE, OR CHANG	E IN SERVICE		
	A. Estimated date last used	6/84	6/84	6/84	6/84	
	(mo./day/year)					
	C. Tank was removed from ground D. Tank was closed in ground E. Tank filled with inert material Describe	XX	XX	XX	XX	
	F. Change in service (in 1976 from Gasoline to Vars	$\left \right _{1}$			XX	
	2. Site Assessment Completed					
E	vidence of a leak detected					

Tank Identification Number	Tank NoUTP5	-BTank No. <u>UTP</u> 6-	+BTank No.	Tank No.	Tank No.
7. Substance Currently or Last Stored In Greatest Quantity by Volume Gasoline Diesel Gasohol Kerosene Heating Oil Used Oil Other, Please specify	Waste Oil	Waste Oil			
Hazardous Substance CERCLA name and/or, CAS number		·			
Mixture of Substances Please specify					
X	TANKS OUT OF I	USE, OR CHANGE	E IN SERVICE		<u></u>
1. Closing of Tank A. Estimated date last used (mo./day/year) B. Estimate date tank closed					
(mo./day/year)					
C. Tank was removed from ground D. Tank was closed in ground					
E. Tank filled with inert material Describe					
F. Change in service					·
2. Site Assessment Completed					
Evidence of a leak detected					

XI. CERTIFICATION OF COMP				TANKS AT THIS	LOCATION)
Tank Identification Number	Tank No.	Tank No.	Tank No	Tank No.	Tank No.
1. Installation					
A. Installer certified by tank and piping manufacturers					
Installer certified or licensed by the implementing agency		xx			
C. Installation inspected by a registered engineer					
D. Installation inspected and approved by implementing agency	XX	XX		,	
Manufacturer's installation check- lists have been completed					
F. Another method allowed by State agency. Please specify.					
2. Release Detection (Mark all that apply)	TANK PIPING	TANK PIPING	TANK PIPING	TANK PIPING	TANK PIPING
A. Manual tank gauging	XX	XX			
B. Tank tightness testing					
C. Inventory controls					
D. Automatic tank gauging					
E. Vapor monitoring					
F. Groundwater monitoring					
G. Interstitial monitoring double walled tank/piping					
H. Interstitial monitoring/secondary containment					
Automatic line leak detectors					-
J. Line tightness testing					
K. Other method allowed by Implementing Agency, Please specify,					
3. Spill and Overfill Protection					
A. Overfill device installed	XX	XX			
B. Spill device installed	xx	xx			
DATH: I certify the information concerning ins	allation that is prov	ided in section XI i	s true to the best o	f my belief and kno	owledge.
istallar. Thomas w Benn		Thams 1	vb. I	11-	21/94
Name General Former		Sigi	nature		Date
Position			Flippo Co	Company	
(state of marylan			\	• •	
Installer Certific	A AA	D.C 95-C	298		

POTOMAC ELECTRIC POWER COMPANY

1900 PENNSYLVANIA AVE., N.W.

WASHINGTON, D.C. 20068-0001

WASTE MANAGEMENT DEPARTMENT

Certified Mail Return Receipt Requested

January 31, 1994

Mr. Ali Nahidi Department of Consumer & Regulatory Affairs Environmental Regulation Administration 2100 Martin Luther King, Jr., Ave. SE Washington, DC 20020

RE: Registration of New Underground Storage Tanks

Dear Mr. Nahidi:

Potomac Electric Power Company, submits herewith an amended UST notification form for Buzzard Point Generating Station in order to register the two (2) new 4,000 gallon USTs installed at this station.

Please contact me at (202) 331-6641 if any additional information is required.

Sincerely,

Fariba Mahvi

Attachment



GOVERNMENT OF THE DISTRICT OF COLUMBIA D.C. FIRE AND EMERGENCY MEDICAL SERVICES DEPARTMENT



Fax Number: (202) 462-0807

Mayor

Sent via email to: kholland@haleyaldrich.com

December 27, 2013

Haley 7926 Jones Branch Drive, Suite 870 McLean, VA 22102 Attention: Kelly Holland

Dear Sir/Madam:

In my official capacity as Freedom of Information Act ("FOIA") Officer for the District of Columbia Fire and EMS Department ("FEMS"), I hereby acknowledge that I received your FOIA request on July 12, 2013 for documents related to:

Properties on Potomac Avenue & 1st Street, SW

Your request is attached to this letter. This letter both acknowledges and responds to your request. The District of Columbia Fire and EMS Department response to your FOIA request is due within fifteen business days or by August 2, 2013; however your response is being disseminated on December 27, 2013. Under FOIA, FEMS is required to make available documents that exist, but the department is not required to create documents to answer a question or to pull together information in a specific format. In addition, FEMS's responsibility under FOIA extends only to those public documents which the department maintains and does not extend to public documents which may be maintained by other District of Columbia agencies.

Please be advised as follows: (1) Shakira Pleasant, FOIA Officer for the DC Fire and EMS Department, is the public official responsible for granting or denying your request; (2) in accordance with D.C. Official Code § 2-532 (a-1), this FOIA request is partially being granted and the documents responsive to your request are attached; and (3) if you so choose, you have the right to treat the delay as a denial of your request and appeal this decision to the Mayor, or his designee, or to the Superior Court of the District of Columbia as provided in D.C. Official Code § 2-537(a) and (a-1).

Appeal rights are attached to this correspondence. If you have any questions about this response to your FOIA request, please contact me at (202) 673-3397.

Telephone Number: (202) 673-3320

Sincerely yours,

Shakin Reason

Shakira Pleasant



FOIA/PRA Request

FOIA for properties on Poto...

Request Number

13-0262

Request Status

Active - One Office

Respond By

General

Tracking Information

Request Number

13-0262

Request Status

Active - One Office

Respond By

8/2/2

Date of Request

7/24/2013

If Closed - Other,

specify reason

Date Closed

Date Request Recv'd

7/12/2013

If Imperfect, Date **Notice Sent**

Appeal Due Date

Key Dates

Acknowledgement

Letter Sent

Records Made Avail. to Requestor

Days to

Acknowledge

Days to Close

Requestor Information - (Click name for additional details)

Requestor

Karin Holland

E-Mail

kholland@haleyaldrich.com

Requesting Organization Haley

Primary Phone

858-531-1675

Fee Category

Commercial Use

Request Details

Request Type

Freedom of Information Act

Track

Track I - Simple

Short Description

FOIA for properties on Potomac Avenue & 1st Street SW

Danisat Batatla

Dear Sir or Madam,

Description of Please could you provide me all available records on the following properties under the Freedom of Inform **Documents Sent** - 100 S Street, SW - 180 S Street, SW - 1714 2nd St., SW . 1812 Half St., SW K:\foia\ **Document Location Intake Method** Web Requested Delivery Email Method **Additional Details** Is this a Referral? **Consultation Only** Is this an Appeal? No No No **Has Additional Referral Direction Consult Response To** No **Documents? Referred To/From Extension Information Extension Reason Extension Letter** Sent **Expedited Request Information Expedited** Reason for **Expedited Processing** No No **Expediting Approved Processing** Requested Reason for **Expedited Processing Denial** Citizen's Justification for **Expediting Days to Adjudicate Date of Decision on Expediting Request** Expedited **Processing** Fee Waiver Fee Waiver Granted **Agrees to Pay Fees** Yes Fee Waiver No Requested

Incident Report 2011-0121504 -000

Alarm Date and Time 11:02:00 Friday, September 9, 2011			
Arrival Time 11:08:21			
Controlled Date and Time			
Last Unit Cleared Date and Time 11:13:42 Friday, September 9, 2011			
Response Time 0:06:21			
Priority Response Yes			
Completed Yes			
Fire Department Station 07			
Shift A			
Incident Type 152 - Garbage dump or sanitary landfill fire	152 - Garbage dump or sanitary landfill fire		
Initial Dispatch Code			
Aid Given or Received N - None			
Alarms 1			
Action Taken 1 00 - Action taken, other	00 - Action taken, other		
Casualties	No		
Apparatus - Suppression 1			
Personnel - Suppression Personnel 4			
Property Loss \$0.00	\$0.00		
Contents Loss \$0.00	\$0.00		
Property Value \$0.00	\$0.00		
Contents Value \$0.00	\$0.00		
Property Use 000 - Property Use, other			
Location Type Address			
Address 1711 1ST ST SW			
City, State Zip WASHINGTON, DC 20024			

Narratives				
Narrative Name	CAD Narrative			
Narrative Type	CAD Narrative			
Author	·-,			
Narrative Text	F110121504 E Type:	OUTSIDE FIRE- UKN	Sub Type:Disp:	
	COMMENTS			

OUTSIDE FIRE-UKN

SPECIAL ADDRESS COMMENT: This record created by the CADAVU (Address Verification Utility) program.. was not selected from Case Entry.: The caller is on scene (1st party).: The caller is safe and out of danger.: It is not known if everyone else is safe and out of danger.: It is not known exactly what is burning.: The fire has not been extinguished.: The fire is not threatening anything at present.: It is not known if there are hazardous materials involved. FIRE IN SCRAP YARDResponse text:

Duplicate Event:Location =

, CrossStreet 1 = R ST SW, Cross Street 2 = S ST SW, Alarm Level = 0SPECIAL ADDRESS COMMENT: This record created by the CADAVU (Address Verification Utility) program. End of Duplicate Event data==\ATTEMPTING CALL BACK FOR BETTER LOCE07P RPTS NOTHING FOUND

Narrative Name	New Narr	ative
Narrative Type	Incident	
Narrative Date	12:16:21	Friday, September 9, 2011

Page: 1 Printed: 10/30/2013 11:47:19

Washington DC Fire & EMS Department

Incident Report 2011-0121504 -000

	Narratives	
Author		
Author Rank	SGT	
Author Assignment	1	
Narrative Text	Nothing found	

End of Report

Page: 2 Printed: 10/30/2013 11:47:20



District of Columbia Fire & EMS Department Fire Prevention Division 1100 4th Street SW, Suite: E-700 Washington, D.C. 20024-4451



RI2-Reinspection-2 Assigned To GODFREY, Brian on 11/26/2013

Start Date: Business Name:

BIG BEAR CAFE

Finish Date: Occupancy ID:

Address: 1700 1ST ST NE

Station No.:

City/State/Zip: WASHINGTON, DC 20001

Business Phone:

Complex Info	Main Floor	<u>Stories</u>	Estimated Values
Commercial Units: 0	Length: 0	Above Grade: 0	Property: \$0.00
Residential Units: 0	Width: 0	Below Grade: 1	Content: \$0.00
Complex Type: 4	Area: 0	Upper Construction: -	
Complex:	Construction: -		

An authorized representative of the Fire Chief of the District of Columbia Fire and EMS Department has observed the following violation(s) of the District of Columbia Fire Prevention Code at your premises.

ALL VIOLATIONS MUST BE ABATED IMMEDIATELY

Violations	Date Found	Date Cleared	Standard/Reference
2006 IFC CH 03			

06/10/2013

{IFC 2006 International Code set}

304.1.1 WASTE MATERIAL

304.1.1 - Waste material.: Accumulations of wastepaper, wood, hay, straw, weeds, litter or combustible or flammable waste or rubbish of any type shall not be permitted to remain on a roof or in any court, yard, vacant lot, alley, parking lot, open space, or beneath a grandstand, bleacher, pier, wharf, manufactured home, recreational vehicle or other similar structure.

2006 IFC CH 06

605.3 WORKING SPACE & CLEARANCE

06/10/2013

11/26/2013

11/26/2013

{IFC 2006 International Code set}

605.3 - Working space and clearance.: A working space of not less than 30 inches (762 mm) in width, 36 inches (914 mm) in depth and 78 inches (1981 mm) in height shall be provided in front of electrical service equipment. Where the electrical service equipment is wider than 30 inches (762 mm), the working space shall not be less than the width of the equipment. No storage of any materials shall be located within the designated working space. Exceptions:

1. Where other dimensions are required or allowed by the ICC Electrical Code.

2.Access openings into attics or under-floor areas which provide a minimum clear opening of 22 inches (559 mm) by 30 inches (762 mm).

605.5 EXTENSION CORDS

06/10/2013

11/26/2013

{IFC 2006 International Code set}

605.5 - Extension cords.: Extension cords and flexible cords shall not be a substitute for permanent wiring. Extension cords and flexible cords shall not be affixed to structures, extended through walls, ceilings or floors, or under doors or floor coverings, nor shall such cords be subject to environmental damage or physical impact. Extension cords shall be used only with portable appliances.

ABATED

ALL VIOLATIONS ABATED

11/26/2013

APPROVAL GIVEN APPROVAL GIVEN

11/26/2013

Page 1 of 3 Print Date 11/26/2013 PrintTime 12:25:33PM

RI2-Reinspection-2 Assigned To GODFREY, Brian on 11/26/2013

Start Date:

Business Name:

BIG BEAR CAFE

Address: 1700 1ST ST NE

City/State/Zip: WASHINGTON, DC 20001

Finish Date: Occupancy ID: Station No.:

Business Phone:

No violations at this time. Approval given

BB0E62C41D194

Comment:

PENALTIES-SECTION 112 FAILURE TO COMPLY WITH THE DISTRICT OF COLUMBIA FIRE CODE

F-112.3 Penalty for Violations: Any person, firm or corporation violating any of the provisions of this code or failing to comply with any order issued pursuant to any section thereof, upon conviction thereof shall be punished by a fine of not more than three hundred dollars (\$300) or imprisonment for not more than ninety (90) days, or both. Each day that a violation continues, after a service of notice as provided in this code, shall be deemed a separate offense.

F-112.4 Civil Infractions: Civil fines, penalties, and fees may be imposed as alternative sanctions for any infraction of the provisions of this code, or any rules or regulations issued under authority of this code or pursuant to Title I-III of the Department of Consumer and Regulatory Affairs Civil Infractions Act of 1985, D.C. Law 6-42, D.C. Code sec.6-2700 et seq.

(NOTICE)

Notwithstanding the existence of the above penalties, any violation or attempted violation of this code may be restrained, corrected or abated, as the case may be, by injunction or other appropriate proceeding.

SECTION 113 APPEALS

DCMR 12H F-113.1 Right of Appeal. Any person directly affected by a notice or order issued under this *Fire Prevention Code* shall have the right to appeal to the Office of Administrative Hearings, pursuant to the Office of Administrative Hearings Act, effective March 6, 2002 (D.C. Law 14-76; D.C. Official Code §2-1831.01 *et seq.* and regulations promulgated thereunder. The appeal shall be filed within ten (10) days of the date of service of the notice or order. An appeal shall be based on a claim that the true intent of this code has been incorrectly interpreted, the provisions of the code do not fully apply, or the requirements of this code are adequately satisfied by other means. Appeals of notices (other than notices pursuant to Section F-110H (Unsafe Conditions) or section F-111H (Emergency Measures) shall stay the enforcement of the notice until the appeal is heard by the Office of Administrative Hearings.

Failure to remedy said violations will subject you to the penalties as prescribed by Section 112.2 and F-112.3 of the International Fire Code (2006) as amended by the D.C. Fire Prevention code Supplement (2008) (DCMR 12H) shall constitute the D.C. Fire Prevention Code (2008). If you do not understand any part of this notice, please contact this office at (202) 727-1600

RI2-Reinspection-2 Assigned To GODFREY, Brian on 11/26/2013

Finish Date:

Business Name: Address: City/State/Zip:	BIG BEAR CAFE 1700 1ST ST NE WASHINGTON, DC	20001	Occupancy ID: Station No.: Business Phone:	
Signature				*
Recipient:				
	€1			
-0				
MR. Ryan Welsh				
Inspector				
7-11				
Brian Godfrey				
(202) 727	-1600 (office)	(202) 727-3238 ((fax)	www.fems.dc.gov

Start Date:

"Fire Sprinklers and Smoke Alarms Save Lives"



District of Columbia Fire & EMS Department Fire Prevention Division 1100 4th Street SW, Suite: E-700 Washington, D.C. 20024-4451



General Inspection (Commercial) Assigned To BRIMAGE, Ursula on 6/10/2013

Start Date: 6/10/2013 12:00:00AM

Business Name: BIG BEAR CAFE

Address: 1700 1ST ST NE

City/State/Zip: WASHINGTON, DC 20001

Finish Date: 6/10/2013 12:00:00AM

Occupancy ID: Station No.:

Business Phone:

Complex Info	<u>Main Floor</u>	<u>Stories</u>	Estimated Values
Commercial Units: 0	Length: 0	Above Grade: 0	Property: \$0.00
Residential Units: 0	Width: 0	Below Grade: 0	Content: \$0.00
Complex Type: 4	Area: 0	Upper Construction: -	
Complex:	Construction: -		

An authorized representative of the Fire Chief of the District of Columbia Fire and EMS Department has observed the following violation(s) of the District of Columbia Fire Prevention Code at your premises.

ALL VIOLATIONS MUST BE ABATED IMMEDIATELY

<u>Violations</u> <u>Date Found</u> <u>Date Cleared</u> <u>Standard/Reference</u>

2006 IFC CH 03

315.2 STORAGE IN BUILDINGS

06/10/2013

{IFC 2006 International Code set}

315.2 - Storage in buildings.: Storage of combustible materials in buildings shall be orderly. Storage shall be separated from heaters or heating devices by distance or shielding so that ignition cannot occur.

304.1.1 WASTE MATERIAL

06/10/2013

{IFC 2006 International Code set}

304.1.1 - Waste material.: Accumulations of wastepaper, wood, hay, straw, weeds, litter or combustible or flammable waste or rubbish of any type shall not be permitted to remain on a roof or in any court, yard, vacant lot, alley, parking lot, open space, or beneath a grandstand, bleacher, pier, wharf, manufactured home, recreational vehicle or other similar structure.

2006 IFC CH 06

605.3 WORKING SPACE & CLEARANCE

06/10/2013

{IFC 2006 International Code set}

605.3 - Working space and clearance.: A working space of not less than 30 inches (762 mm) in width, 36 inches (914 mm) in depth and 78 inches (1981 mm) in height shall be provided in front of electrical service equipment. Where the electrical service equipment is wider than 30 inches (762 mm), the working space shall not be less than the width of the equipment. No storage of any materials shall be located within the designated working space. Exceptions:

- 1. Where other dimensions are required or allowed by the ICC Electrical Code.
- 2.Access openings into attics or under-floor areas which provide a minimum clear opening of 22 inches (559 mm) by 30 inches (762 mm).

605.5 EXTENSION CORDS

06/10/2013

{IFC 2006 International Code set}

605.5 - Extension cords.: Extension cords and flexible cords shall not be a substitute for permanent wiring. Extension cords and flexible cords shall not be affixed to structures, extended through walls, ceilings or floors, or under doors or floor coverings, nor shall such cords be subject to environmental damage or physical impact. Extension cords shall be used only with portable appliances.

2006 IFC CH 10

General Inspection (Commercial) Assigned To BRIMAGE, Ursula on 6/10/2013

Start Date: 6/10/2013 12:00:00AM

Business Name: BIG

BIG BEAR CAFE

Address: City/State/Zip: 1700 1ST ST NE WASHINGTON, DC 20001 Finish Date: 6/10/2013 12:00:00AM

Occupancy ID: Station No.: Business Phone:

Violations

Date Found

Date Cleared

Standard/Reference

1028.5 FURNISHINGS & DECORATIONS

06/10/2013

{IFC 2006 International Code set}

1028.5 - Furnishings and decorations.: Furnishings, decorations or other objects shall not be placed so as to obstruct exits, access thereto, egress therefrom, or visibility thereof. Hangings and draperies shall not be placed over exit doors or otherwise be located to conceal or obstruct an exit. Mirrors shall not be placed on exit doors. Mirrors shall not be placed in or adjacent to any exit in such a manner as to confuse the direction of exit.

1028.5 FURNISHINGS & DECORATIONS

06/10/2013

(IFC 2006 International Code set)

1028.5 - Furnishings and decorations.: Furnishings, decorations or other objects shall not be placed so as to obstruct exits, access thereto, egress therefrom, or visibility thereof. Hangings and draperies shall not be placed over exit doors or otherwise be located to conceal or obstruct an exit. Mirrors shall not be placed on exit doors. Mirrors shall not be placed in or adjacent to any exit in such a manner as to confuse the direction of exit.

ED2A80F219192

PENALTIES-SECTION 112 FAILURE TO COMPLY WITH THE DISTRICT OF COLUMBIA FIRE CODE

F-112.3 Penalty for Violations: Any person, firm or corporation violating any of the provisions of this code or failing to comply with any order issued pursuant to any section thereof, upon conviction thereof shall be punished by a fine of not more than three hundred dollars (\$300) or imprisonment for not more than ninety (90) days, or both. Each day that a violation continues, after a service of notice as provided in this code, shall be deemed a seperate offense.

F-112.4 Civil Infractions: Civil fines, penalties, and fees may be imposed as alternative sanctions for any infraction of the provisions of this code, or any rules or regulations issued under authority of this code or pursuant to Title I-III of the Department of Consumer and Regulatory Affairs Civil Infractions Act of 1985, D.C. Law 6-42, D.C. Code sec.6-2700 et seq.

(NOTICE)

Notwithstanding the existence of the above penalties, any violation or attempted violation of this code may be restrained, corrected or abated, as the case may be, by injunction or other appropriate proceeding.

SECTION 113 APPEALS

DCMR 12H F-113.1 Right of Appeal. Any person directly affected by a notice or order issued under this *Fire Prevention Code* shall have the right to appeal to the Office of Administrative Hearings, pursuant to the Office of Administrative Hearings Act, effective March 6, 2002 (D.C. Law 14-76; D.C. Official Code §2-1831.01 *et seq.* and regulations promulgated thereunder. The appeal shall be filed within ten (10) days of the date of service of the notice or order. An appeal shall be based on a claim that the true intent of this code has been incorrectly interpreted, the provisions of the code do not fully apply, or the requirements of this code are adequately satisfied by other means. Appeals of notices (other than notices pursuant to Section F-110H (Unsafe Conditions) or section F-111H (Emergency Measures) shall stay the enforcement of the notice until the appeal is heard by the Office of Administrative Hearings.

Failure to remedy said violations will subject you to the penalties as prescribed by Section 112.2 and F-112.3 of the International Fire Code (2006) as amended by the D.C. Fire Prevention code Supplement (2008) (DCMR 12H) shall constitute the D.C. Fire Prevention Code (2008). If you do not understand any part of this notice, please contact this office at (202) 727-1600

General Inspection (Commercial) Assigned To BRIMAGE, Ursula on 6/10/2013

Finish Date: 6/10/2013 12:00:00AM

Business Name: Address: City/State/Zip:	BIG BEAR CAFE 1700 1ST ST NE WASHINGTON, DC 2000	Occupancy IE Station No Business Phone	.:
Signature			
Recipient:			
MR. stuart daven	port	Unassigned	
Inspector			
7	. <u>*</u>	,	*
Ursula Brimage		Inspector	
(202) 727	-1600 (office)	(202) 727-3238 (fax)	www.fems.dc.gov

Start Date: 6/10/2013 12:00:00AM

"Fire Sprinklers and Smoke Alarms Save Lives"

GENERAL INFORMATION

FOIA Request Response

Attached are copies of documents and/or records produced in response to a Freedom of Information Act (FOIA) request submitted to the Fire and EMS Department. Unless otherwise noted in this report, the documents and/or records attached represent a full and complete record in response to the request, as made known to the FOIA Officer by Department officials at the time this response was produced.

Privacy

Information contained in certain documents and records may be redacted to protect the privacy of individuals. Such redaction may include names, addresses, telephone numbers or other information used for personal identification, when not pertinent to the nature of the FOIA request. Individual protected health information (PHI) shall be redacted from all requested records, unless the submitted request falls within the requirements of federal and District privacy laws allowing the release of PHI.

Exemptions from FOIA Disclosure

The FOIA statute provides that certain categories of documents may be withheld from disclosure. Included among these are documents that relate to law-enforcement activities, documents subject to recognized legal privileges such as the attorney-client and work-product privileges, documents required to be withheld by other laws (federal or District), documents that reflect the internal deliberative processes of the government, and documents the disclosure of which would result in a clearly unwarranted intrusion on personal privacy. For a complete list of the exemptions, please see DC Official Code § 2-534.

Appeals or Judicial Review of Denials

If you consider this response a denial of your FOIA request, you have the right to appeal to the Mayor or to the Superior Court of the District of Columbia (D.C. Official Code § 2-537 and 1 DCMR 412). If you elect to appeal to the Mayor, your appeal must be in writing and contain "Freedom of Information Act Appeal" or "FOIA Appeal" in the subject line of the letter as well as on the outside of the envelope. The appeal must include (1) a copy of the original request, (2) a copy of the Fire and EMS Department denial letter, (3) a statement of the circumstances, reasons, and or arguments advanced in support of disclosure, and (4) a daytime telephone number, and e-mail and/or U.S. Mail address at which you can be reached. The appeal must be mailed to:

Mayor's Correspondence Unit

FOIA Appeal 1350 Pennsylvania Avenue, N.W., Suite 316 Washington, D.C. 20004.

Electronic versions of the same information can instead be e-mailed to the Mayor's Correspondence Unit at:

foia.mayor@dc.gov

Further, a copy of all appeal materials must be forwarded to the Fire and EMS Department FOIA Officer. Failure to follow these administrative steps will result in delay in the processing and commencement of a response to your appeal to the Mayor.

APPENDIX E

Site Photographs

POTOMAC AVENUE & 1ST STREET SW – AKRIDGE PARCEL, SQUARE 0607, LOT 0013 WASHINGTON, DC File No. 40223-002

Dates Photographs Taken: 28 August 2013 and 23 December 2013



Photo #1: Minor staining of asphalt in parking lot



Photo #2: Staining of concrete surrounding drain in northwestern portion of building

Haley & Aldrich Inc. Page 1 of 4

POTOMAC AVENUE & 1ST STREET SW – AKRIDGE PARCEL, SQUARE 0607, LOT 0013 WASHINGTON, DC

File No. 40223-002

Dates Photographs Taken: 28 August 2013 and 23 December 2013



Photo #3: Staining of concrete surrounding drain in southeastern portion of building



Photo #4: Concrete patch in concrete inside building

Haley & Aldrich Inc. Page 2 of 4

POTOMAC AVENUE & 1ST STREET SW – AKRIDGE PARCEL, SQUARE 0607, LOT 0013 WASHINGTON, DC

File No. 40223-002

Dates Photographs Taken: 28 August 2013 and 23 December 2013



Photo #5: Staining of concrete in building




Photo #6: Empty jerry cans in building

Haley & Aldrich Inc. Page 3 of 4

POTOMAC AVENUE & 1ST STREET SW – AKRIDGE PARCEL, SQUARE 0607, LOT 0013 WASHINGTON, DC

File No. 40223-002

Dates Photographs Taken: 28 August 2013 and 23 December 2013



Photo #7: Storage of waste inside building



Photo #8: Staining of gravel in northwestern portion in August 2013

Haley & Aldrich Inc. Page 4 of 4

APPENDIX F

Geoprobe Reports and Observation Wells installation Reports

HAL ALD	EY& RICH	z H				GEO	PROBE REPOR	Γ		ı	Воі	rin	g N	lo.	G	ΓW-	607	7-13-
Project Client Contracto	Mcl	zard Po Kissack	& Mc	Kissa		re 607, W	ashington, DC			Sh Sta		No	. 1 Dec		2 ber	5, 2 5, 2		
		Ca	asing	Sam	pler	Barrel	Drilling Equipment	and Procedures			iller			Hitti			201.	
Type Inside Dia Hammer \	Veight	in.) 2	Steel 2.25	Mac 1.2		 -	Rig Make & Model: Geor Bit Type: N/A Drill Mud: None Casing: Steel to 35 ft Hoist/Hammer: N/A N/			Ele	kA F evat tum cati	Rep tion).		Se	serk	0	
Hammer I	-all (in.	´			·	-	PID Make & Model: Min											
Depth (ft) Sample No. & Rec. (in.)	Sample Depth (ft)	PID Readings (ppm)	Stratum Change Flev/Denth (#)	USCS Symbol		VISU	JAL-MANUAL IDENTIFICATIO (Color, GROUP NAME, ma structure, odor, moisture, opt GEOLOGIC INTERPR	x. particle size*, ional descriptions	+	% Coarse	% Fine		% Medium	Fine	% Fines		SS	Plasticity Lest
0 G1 28	0.0 5.0	916	0.3	SC	no Gi	structure, a	-ASPHALT nd yellow-brown clayey SANI no odor, moist at 1.1 ft les at 1.0 to 1.2 ft, and 1.9 to 2	with gravel (SC), mps 1						20	30			
5 G2 28	5.0	1877	5.0	CĪ	no	structure,	n and gray-brown lean CLAY on odor, moist ares with higher plasticity at 5.8	_	<u>mm</u> , —					15	85			
10 G3 60	10.0 15.0	9999		CL		ellow-brown bist	n lean CLAY (CL), mps 0.42 i	nm, no structure, no odo	r,					10	90			
15 G4 60	15.0 20.0	1026		CL	Hi		, except contains mica are content from 15.2 to 15.4 f at 16.5 ft	t						10	90			
20 Date	Wa	ter Lev	ed	Deptl	h (ft)	m	Sample ID O - Open End Rod	Well Diagram ☐☐ Riser Pipe ☐☐ Screen	Overb	ouro			ıma		35.0)		
10/5/:-		Time (of C	asing	of Hol	e water	T - Thin Wall Tube U - Undisturbed Sample	Filter Sand	Rock			(ft	,	~				
12/5/13 12/6/13	11:00 08:00	21		2.27		Dry 20.49	S - Splitspoon Sample G - Geoprobe	Grout	Samp				70					
12/0/13	08:00	165	22	2.33		11.95	·	Concrete Bentonite Seal	Borir	ng	No).	G	TV	N-(607	-13 	·-1
Field Tests	:		Dilatano Toughn	y:R- ess:L	Rapid - Low	S - Slow M - Mediur	N - None Plastic H - High Dry Str	ity: N - Nonplastic L - Lovength: N - None L - Low							/ery	High	1	
*Note: Ma	ximum p	article :	size is c	letermi	ined b	y direct ob	servation within the limitation sual-manual methods of the	s of sampler size.							_			

H	IALI	EY&	z I			GEOPROBE REPORT	F	Bor ille	No.	4	022	3-00)2	507-	13-	1
73		uci		<u> </u>	_		-	Shee	_			of		iold		_
€	No.	(#)	ding؛ (۲	Jm ge yth (ft	Symbol	VISUAL-MANUAL IDENTIFICATION AND DESCRIPTION	-	avel		San E				Ś	Tes	Γ
Depth (ft)	Sample No. & Rec. (in.)	Sample Depth (ft)	PID Readings (ppm)	Stratum Change Elev/Depth (ft)	uscs s	(Color, GROUP NAME, max. particle size*, structure, odor, moisture, optional descriptions GEOLOGIC INTERPRETATION)	% Coarse	% Fine	% Coarse	% Medium	% Fine	% Fines	Dilatancy	Toughness	Plasticity	
20 -	G5 60	20.0 25.0	913		CL	Similar to G4					10	90				
						Higher moisture content at 21.6 ft										
						Gray mottling and pockets of fat clay from 23.3 to 23.9 ft										
25 -	G6 60	25.0 30.0	779		CL	Similar to G5					10	90				
30 -	67	20.0	40.4	29.3	-sc sc	Yellow-brown clayey SAND (SC), mps 0.42 mm, no structure, no odor, wet						45				
	G7 30	30.0 35.0	40.4		SC	Yellow-brown clayey SAND (SC), mps 0.42 mm, no structure, no odor, wet					70	30				
					SC	Gray-brown clayey SAND (SC), mps 19 mm, no structure, no odor, wet		10	5	25	40	20				
35 -				35.0		BOTTOM OF EXPLORATION 35.0 FT										
						Note: Initial PID readings on G2, G3, and G4 appeared anomalously high. Rescreen of these samples indicated a range of 158 to 237 ppm.										
						Note: A 1-in. inside-diameter temporary monitoring well was installed for sample collection (screen interval from 3.4 to 23.4 ft below ground surface). The initial water level was 20.49 ft below grade on 12/6/13. The static water level was 11.95 ft below grade > 48 hrs after well installation on 12/12/13.										
						The following day, 12/6/13, an additional 1-in. inside-diameter temporary monitoring well was installed at an offset of several feet for sample collection (screen interval from 30.9 to 35.9 ft below ground surface). The initial water level was 18.55 ft below grade on 12/6/13. The static water level was 18.34 ft below grade >48 hrs after well installation on 12/12/13.										
										1					-13-	_

I-A	IAL)	EY&	z H				GEO	PROBE REPOR	Т			Во	rin	g N	No.	G'	ΓW	-60′	7-13	3-2
Clie	oject ent ntracto	Mcl	Kissac	Point - I ck & Mo Drilling,	Kissac		e 607, V	Vashington, DC			Sh St	e N neet art	No). 1 De	cem	1 ber	5,			
			(Casing	Samp	oler	Barrel	Drilling Equipmen	t and Procedures			nish iller			cem Hitt		-	201	3	
Тур	e			Steel	Mac	ro		Rig Make & Model: Geo	probe 6620		ł	&A F				_	serl	co		
Insid	de Diar	neter (in.)	2.25	1.2	5		Bit Type: N/A Drill Mud: None				eva		1						
Han	nmer V	Veight	(lb)				-	Casing: Steel to 15 ft			-	atun cati		S	ee I	Plan	1			
Han	nmer F	all (in.)				-	Hoist/Hammer: N/A N PID Make & Model: Mir												
æ	9 .	o €	ngs	€	lodi		VIS	UAL-MANUAL IDENTIFICATION			\vdash	avel	;	San	d			ield	Tes	st
Depth (ft)	Sample No. & Rec. (in.)	Sample Depth (ft)	PID Readings	Stratum Change	USCS Symbol			(Color, GROUP NAME, ma structure, odor, moisture, opi GEOLOGIC INTERPR	tional descriptions		% Coarse	% Fine	% Coarse	% Medium	% Fine	% Fines	Dilatancy	Toughness	Plasticity	Strength
- 0 -	G1	0.0						-TOPSOIL	-											
-	16	5.0	47.4	0.3	ML	odo		ed-brown sandy SILT (ML), m contains brick and concrete fra				10	5	15	15	55				
-						Brio	ck and co	ncrete from 1.5 to 2.2 ft												
- - 5 -				5.0		firs	t location,	fragment blocked spoon at firs offset several feet and continu	e sampling.											
ľ	G2 32	5.0 10.0	47.8	5.4	LCL.			n and gray lean CLAY (CL), recontains mica	nps 0.42 mm, no structu	re, no		15	5	15	10 15	90 50		-+		-
-		10.0		6.0				SILT with gravel (ML), mps 19	9 mm, no structure, no o	dor,	┢-	5	5	 		90		- 1		<u></u>
-				7.1	CH	Yel	low-brow	le asphalt or ash filln and gray-brown lean CLAY	(CL), mps 4.75 mm, no	'	ļ.,	10	15		15	- E		_		L-
					CH	`\stru	cture, no	odor, moist to wet at CLAY (CH), mps 19 mm, n				10	15	3	15	33				
								ossible sheen	o structure, nyurocarbon	-IIKC										
- 10 -	G3 46	10.0 15.0	21.3		СН			and light brown fat CLAY (CE like odor, moist to wet, contai		icture,					10	90				
-				10.9	CL	stru		n and gray mottled lean CLAY odor, moist, decreasing moist of fat clay	· // 1						10	90				
-																				
15 -				15.0				BOTTOM OF EXPLORA	TION 15 0 FT											_
L						NT-4	A 1 !			I - J - C										
-						sam	ple collectace). The	i. inside-diameter temporary m etion (screen interval from 4.9 e initial water level was 14.08	to 14.9 ft below ground ft below grade on 12/6/1	3. The										
-							ic water le 12/13.	evel was 8.09 ft below grade >	>46 nrs after well installa	uion on										
-																				
- 20 -								1	1	1										
			ter Le	evel Data		n (ft) t	:O:	Sample ID	Well Diagram Riser Pipe	2. -	h			nma						
D	ate	Time	Time	(hr Bo	ttom	Bottom of Hole	\/\/ater		Screen Filter Sand	Over Rock			•	•]	15.()			
12/	/5/13	15:00	-		1.66		Dry	U - Undisturbed Sample S - Splitspoon Sample	Cuttings	Sam				3	G					
ı	/6/13 12/13	16:11 08:20	2		1.66 1.74		14.08 8.09	G - Geoprobe	Grout Concrete	Bori	ng	No) .	(T	W-	607	7-13	3-2	
	d Tests:		10	Dilatano	y : R-l	Rapid	S - Slow		Bentonite Seal	ow M-N						\/o=	, LJ:	h		
*No	te: Max	kimum p	particle	size is o	letermi	ned by	direct of	servation within the limitation	rength: N - None L - Lovers of sampler size.							very	ng	11		
		No	<u>τe: S</u>	ou ident	uncatio	on bas	sea on vi	isual-manual methods of th	<u>ne USCS as practiced</u>	by Hale	<u>y &</u>	Ald	ric	<u>n, Ir</u>	IC.					

HA AI	ALE LDR	Y& ICF	Ē Ī				GEO	PROBE REPOR	T			I	Boı	rin	g N	lo.	GT	W-6	607-	13-2
Project Client Contra		McF	Kissack	oint - L & Mc rilling,	Kissac		e 607, W	ashington, DC				Sh Sta	art	No	40 · 1 Dec Dec	of em	ber	6, 2		
			Ca	asing	Samp	oler	Barrel	Drilling Equipmer	nt and Pro	ocedures			nish iller		M.				.01.	,
Туре			S	teel	Mac	ro		Rig Make & Model: Geo	oprobe 662	20		Н8	&A F	Rep		D.	Ses	erk	o	
Inside	Diam	eter (i	n.) 2	2.25	1.2	5		Bit Type: N/A Drill Mud: None					evat atum							
Hamm	er We	eight ((lb)				-	Casing: Steel to 40 ft	T / A				cati		Se	ee P	lan			
Hamm	ner Fa	ll (in.))				-	Hoist/Hammer: N/A N PID Make & Model: Mi		000 10.6 eV										
چ چ	<u>;</u>	ω£	sgu	. €	logi		VISI	JAL-MANUAL IDENTIFICATI				-	avel		Sanc	j				Test
Depth (ft)	& Rec. (in.)	Sample Depth (ft)	PID Readings (ppm)	Stratum Change Elev/Deoth (Symbol			(Color, GROUP NAME, m	ax. particle	size*,		% Coarse	a)	Coarse	Medium	a	es	ncy	Toughness	<u></u>
Dep	E &	Sal Dep	ପ ଜୁ	Str	NSCS			structure, odor, moisture, or GEOLOGIC INTERP	otional des	criptions		Š	. Fine	Co	. Me	% Fine	Fines	Dilatancy	ong	Plasticity
0) ∞		<u>Ф</u>	Ш	i 5			02020010 1147214		• 7		%	%	%	%	%	%		ř	<u> </u>
5 -						See	Boring G	TW-607-13-2 for 0 to 15.0 ft	soil sampl	es										
	G4 60	15.0 20.0	0	15.0	_CL			nd yellow-brown mottled lead	n CLAY (0	CL), mps 0.42 r	nm, no					5	95	- +	-	-
		20.0																		
					CL	Simi	ilar to G4	, except yellow-brown and gr	ay mottled							5	95			
						Pocl	kets of gra	ay fat clay at 17.2 and 18.5 ft												
20																				
		Wa	ter Lev	el Data				Sample ID	We	ll Diagram			S	Sum	mai	ry				
Date	e .	Time	Elaps			n (ft) to Bottom		O - Open End Rod T - Thin Wall Tube		Riser Pipe Screen	Overl	our	den	(ft)	3	5.0			
			Time (of C	asing	of Hole	Water	U - Undisturbed Sample	9 9 6	Filter Sand	Rock			(ft	,	~				
12/6/1 12/12/		16:15 08:20	3 139		.71 .78		34.3 18.81	S - Splitspoon Sample G - Geoprobe	<u>.1.1.</u>	Cuttings Grout	Samp				50					_
12/14/	12	00.20	139	34	0		10.01			Concrete Bentonite Seal	Bori	ng	No).	G'	ΓW	7-60) 7 -	13-	2A
Field T	ests:			Dilatano	y: R-1	Rapid :	S - Slow M - Mediu			Nonplastic L - Lo							/erv	Hiah	1	
								servation within the limitation			IVI - IVIE	uiuil	<u>. 11</u>	- 1 11	911	v - 1	, UIY	ıııyı		

H8A-GEOPROBE-09 W/PID-2 HA-LIB09,GLB HA-TB+CORE+WELL-07-1.GDT L:/WASHINGTON DC/40223-0024/0223-002_BORING LOGS GTW-607-13-1 THRU 13-3.GPJ

AL	IALEY& LDRICH					GEOPROBE REPORT					1022	3-00)2	07-1	.3-2	4 E
	: -		St	£	0	WOULD MANUAL INFORMATION AND RECORDED IN	-		_	San		UI.	_	ield	 Tes	_ st
Depth (ft)	& Rec. (in.)	Sample Depth (ft)	PID Readings (ppm)	Stratum Change Elev/Depth (ft)	USCS Symbol	VISUAL-MANUAL IDENTIFICATION AND DESCRIPTION (Color, GROUP NAME, max. particle size*, structure, odor, moisture, optional descriptions GEOLOGIC INTERPRETATION)	% Coarse	% Fine	ě	% Medium		% Fines	Dilatancy	Ś		Τ
20	G5 60	20.0 25.0	0	Ш	CL	Yellow-brown and gray mottled lean CLAY (CL), mps 0.42 mm, no structure, no odor, moist, contains mica		8.	8.		5	95				
	G6 60	25.0 30.0	0		CL	Similar to G5 Fine gravel pocket at 26.5 ft					5	95				
	G7 60	30.0 35.0	0		CL	Similar to G6, except gray-brown and red-yellow mottled Pocket of red-yellow silt at 29.5 ft Gray-brown and yellow-brown mottled lean CLAY (CL), mps 0.42 mm, no structure, no odor, moist, contains mica					10	95				
	G8 34	35.0 40.0	0	34.6	GC GC	Yellow-brown clayey GRAVEL with sand (GC), mps 19 mm, no structure, no odor, wet Yellow-brown clayey GRAVEL with sand (GC), mps 75 mm, no structure, no odor, wet	10				10 10					
40				40.0		BOTTOM OF EXPLORATION 40.0 FT Note: A 1-in. inside-diameter temporary monitoring well was installed for sample collection (screen interval from 29.6 to 34.6 ft below ground surface). The initial water level was 34.30 ft below grade on 12/6/13. The static water level was 18.81 ft below grade > 48 hrs after well installation on 12/12/13.										

H A	[AL] LDI	EY& RICH	Ĭ			GEO	PROBE REPOR	Т		ı	Boı	rin	g N	lo.	G	SS-	607	-13	-3
Proje Clier Cont		McI	Kissack		Kissack		Vashington, DC			Sh Sta	e No neet art	No	o. 1 Dec	of cem	ber	5,			
			Ca	asing	Sampl	er Barrel	Drilling Equipmen	t and Procedures	I .		nish iller		Dec M.				201	3	
Туре	<u> </u>		S	steel	Macr		Rig Make & Model: Geo	probe 6620			kA F					serl	(O		
		neter (i		2.25	1.25		Bit Type: N/A				evat)						
		eight (´ ⁻			_	Drill Mud: None Casing: Steel to 2 ft		H		atum cati		C	00 I	Plan				
		all (in.)	` '			_	Hoist/Hammer: N/A N			LO	cati	011	3	cc i	ian	L			
	o 🙃		gs	Œ	0	VIE	PID Make & Model: Min			Gra	avel		Sano	d			ield	Tes	 st
Depth (ft)	Sample No. & Rec. (in.)	Sample Depth (ft)	PID Readings (ppm)	Stratum Change Elev/Depth (#)	USCS Symbol	VIS	UAL-MANUAL IDENTIFICATIO			se		se	шn		s	cy	Toughness	<u>₹</u>	ء
ebt	Rec	Sarr	(pp	Straf Chai	CS 8		(Color, GROUP NAME, ma structure, odor, moisture, op	tional descriptions		Coarse	% Fine	Coarse	% Medium	% Fine	% Fines	Dilatancy	ndbn	Plasticity	Ctronoth
	‰ ∝	٥٠٥		Ш	SO		GEOLOGIC INTERPR	RETATION)		%	%	%	%	%	%	ä	٥	Ba	ţ
0	G1	0.0	20.4	0.3	ML	D-41	-ASPHALT			_	15	5	10	20	50				F
	24	2.0					andy SILT with gravel (ML), recontains brick and asphalt frag		no			-							
-				2.0			BOTTOM OF EXPLORA	ATION 2.0 FT											
						Note: The b cement grout	orehole was abandoned with 60 mixture.	0% bentonite/40 % Portla	nd										
		100						W " 5:		_									L
	.		ter Lev Elaps	el Data	a Depth	(ft) to:	Sample ID O - Open End Rod	Well Diagram Riser Pipe	Overb				nma N		2 0				_
Da	ite	Time	Time (hr Bo	ttom B	ottom f Hole Water	T - Thin Wall Tube	Screen Filter Sand	Rock			`	,		2.0				
12/5	5/13	09:00				2.0 Dry	U - Undisturbed Sample S - Splitspoon Sample	Cuttings	Samp			(11	.) 10	G					
							G - Geoprobe	Grout Concrete	Borir			`			S_6	07.	.13	_3	
	- 1							Bentonite Seal	וווטם	٠y	IAC	٠.	•	U	J-0	·	13	-5	

HALEY& ALDRICH	OBSERV	ATION	WEL	L INSTALLATI	ON REP	PORT	Well No. GTW-607-13-1 Boring No. GTW-607-13-1
	Buzzard Point - Lot 13 S	Square 607		_	H&A FILE		3-002
LOCATION	Washington, DC				PROJECT		
	McKissack & McKissac	k			FIELD RE		eserko
	Vironex Drilling, Inc.				DATE INS	TALLED 12/5/	2013
	A. Hittinger			_			
Ground El. El. Datum	ft L	ocation S	See Plan			Tempora Permano	
SOIL/ROCK	BOREHOLE			Type of protective cover	:/lock	-	Well Cap
CONDITIONS	BACKFILL		↓				
Sand	Bentonite			— Height of top of riser pip above ground surface	pe		ft
	1.4						
5.0					e of Seals	Top of Seal (ft	<u>Thickness (ft)</u> 1.4
		L1					
	Sand			Type of riser pipe:			Solid PVC
Class				Inside diameter of ris Type of backfill arou			1.0 in Bentonite
Clay				— Diameter of borehole			in
				— Depth to top of well scre	een		ft
				Type of screen		Mach	ne Slotted PVC
				Screen gauge or size	of oponings	iviaciii	-
		L2		Diameter of screen	or obenings		
				Type of backfill around	coroer	ш2	1.0 in
				—Depth of bottom of well		<u> </u>	23.4 ft
		L3		— Bottom of Silt trap			23.5 ft
22.5	22.5		 	— Depth of bottom of bore	ehole		23.5 ft
23.5 (Botton	n of Exploration)	Ţ ' -	·				
	pth from ground surface in feet)				(Not to Scale)		
	6.16 ft + Pay Length (L1)	20 Length of	screen (L2	ft + 0.1) Length of silt t		= 26.26 Pay le	
COMMENTS:	4034D 4 2007-	2022 11 11	X7 11 X	I.D. (
<i>3:\Projects\40223 - I</i>	M&M Potomac Ave SW\00	z\r1eIdwork\'	weii Instal	ı keports			

PROJECT Surgest Point = Lot 13 quare 607	HALEY& ALDRICH	OBSERV	ATION	N WEL	L INSTALLAT	ION RE	PORT	-	Well No. GTW-607-13 Boring No. GTW-607-1	
Chemical Part Chemical Par	PROJECT	Buzzard Point - Lot 13	Square 607	7		H&A FII	E NO.	40223		<u>3-1</u>
Machine Mac										
DRILLER M. Robins Framework Framew			ck							
Condition Con						DATE IN	STALLED	12/6/2	013	
Solit MOCK SORTHOLE CONDITIONS BACKFILL	•						1			
Sand Bentonite Bentonite		ft L	ocation	See Plan						
Height of top of riser pipe above ground surface	SOIL/ROCK	BOREHOLE			Type of protective cove	er/lock		W	ell Cap	
Bentonite Bentonite Bentonite Bentonite Bentonite Type of Seals Top of Seal (ft) Thickness (ft) Bentonite 0.0 28.9	CONDITIONS	BACKFILL	_							
Clay	Sand	Bentonite	<u></u>			ipe			4.17	ft
Type of riser pipe: Solid PVC Inside diameter of riser pipe 1.0 End of the policy Type of backfill around riser	5.0		11						·	
Inside diameter of riser pipe Type of backfill around riser Bentonite Bentonite	Clay									<u> </u>
Inside diameter of riser pipe Type of backfill around riser Bentonite					— Type of riser pipe:			So	lid PVC	
Type of backfill around riser Bentonite						riser pipe			1.0	in
Diameter of borehole 3.50 Depth to top of well screen 30.9 Depth of screen Screen gauge or size of openings Diameter of screen 1.0 Depth of backfill around screen #2 Filter Sand Depth of bottom of well screen 35.9 Depth of bottom of borehole 3.50 Depth of bottom of well screen 35.9 Depth of bottom of borehole 3.50 Depth of bottom of borehole 3.50 Depth of bottom of screen 3.50 Depth of bottom of borehole 3.50 Depth of bottom of screen 3.50 Depth of bottom of borehole 3.50 Depth of bottom of screen 3.50 Depth of bottom of borehole 3.50 Depth of bottom of screen 3.50 Depth of bottom of borehole 3.50 Depth of bottom of screen 3.50 Depth of bottom of borehole 3.50 Depth of bottom of screen 3.50 Depth of bottom of borehole 3.50 Depth of bottom of screen 3.50 Depth of bottom of borehole								В	entonite	
Depth to top of well screen 30.9					• •		_			
Sand Sand Screen gauge or size of openings Diameter of screen 1.0	29.3	29.0	-		— Diameter of borehole				3.50	in
Sand Screen gauge or size of openings 0.010			+		— Depth to top of well scr	reen			30.9	ft
Sand L2 Diameter of screen 1.0					Type of screen			Machine	e Slotted PVC	
L2 Diameter of screen 1.0	Sand					e of openings			0.010	in
Sand Type of backfill around screen			L2		Diameter of screen	-			1.0	in
Depth of bottom of well screen		Sand		-	Type of backfill around	d screen		#2 F	Filter Sand	
Bottom of Silt trap 36.0 36.0 Comparison (Numbers refer to depth from ground surface in feet) 35.07 ft + 5 ft + 0.1 ft = 40.17 ft Riser Pay Length (L1) Length of screen (L2) Length of silt trap (L3) Pay length										
Depth of bottom of borehole 36.0			1 1		-	ll screen			35.9	ft
So.0			L3							ft
	35.0	36.0	<u> </u>		— Depth of bottom of bor	ehole			36.0	ft
						(Not to Scale)				
Riser Pay Length (L1) Length of screen (L2) Length of silt trap (L3) Pay length	(rumbers refer to de)			5	ft 0.1		_	40.17	ft	
	Riser						. –			
COMMENTS:	COMMENTS:					-				

HALEY& ALDRICH	OBSERV	ATION	WELL INSTALLATI	ION RE	PORT	Well No. GTW-607-13-2 Boring No. GTW-607-13-2	
PROJECT E	Buzzard Point - Lot 13	Square 607		H&A FII	LE NO. 40)223-002	
LOCATION V	Washington, DC			PROJEC	T MGR. G.	. Grose	
	McKissack & McKissac	:k		FIELD R		. Seserko	
-	Vironex Drilling, Inc.			DATE IN	ISTALLED 12	2/5/2013	
DRILLER A	A. Hittinger						
Ground El. El. Datum	ft L	ocation _	See Plan		✓ Temp ☐ Perm		
SOIL/ROCK	BOREHOLE		Type of protective cover	r/lock		Well Cap	
CONDITIONS	BACKFILL	_					
Silt with Clay Lens	Bentonite		Height of top of riser pi above ground surface	ipe		3.23	_ft
	2.5	-					
6.0	_			oe of Seals	Top of Seal		
		L1	B	entonite	0.0	2.5	- - -
			Type of riser pipe:			Solid PVC	-
			Inside diameter of r			1.0	_in
			Type of backfill aro	und riser	-	Bentonite	_
Clay	Sand		• Diameter of borehole			3.25	_in
		+	Depth to top of well scr	een		4.9	_ft
			Type of screen		Ma	achine Slotted PVC	_
			Screen gauge or size	of openings		0.010	_in
		L2	Diameter of screen			1.0	in
			Type of backfill around	l screen		#2 Filter Sand	_
			Depth of bottom of well	l screen		14.9	_ft
		L3	Bottom of Silt trap			15.0	_ft
15.0	15.0	_ 	Depth of bottom of bore	ehole		15.0	ft
	of Exploration)		•				
(Numbers refer to deptl	th from ground surface in feet)			(Not to Scale)			
	8.13 ft +	10		ft		3.23 ft	
	Pay Length (L1)	Length of	screen (L2) Length of silt	trap (L3)	Pa	y length	
COMMENTS: G:\Projects\40223 - M	1&M Potomac Ave SW\00	2\Fieldwork\	Well Install Reports				

HALEY& ALDRICH	OBSERV	ATION	N WELL	INSTALL	ATION RE	PORT		Well No. GTW-607-13- Boring No. GTW-607-13-2	
PROJECT	Buzzard Point - Lot 13	Square 607	1		H&A FII	E NO.	40223-0		141
-	Washington, DC				PROJEC	T MGR.	G. Gros	e	
_	McKissack & McKissa	ck			FIELD R	EP.	D. Sese	rko	
CONTRACTOR	Vironex Drilling, Inc.				DATE IN	STALLED	12/6/20	13	
DRILLER	M. Robins								
Ground El.	ft L	ocation	See Plan			✓ To	emporary		
El. Datum						P	ermanent		
SOIL/ROCK	BOREHOLE			Type of protectiv	e cover/lock	-	We	ell Cap	
CONDITIONS	BACKFILL	_							
Silt with Clay Lens				Height of top of r above ground sur				2.25	ft
6.0	Bentonite			- -	Type of Seals Bentonite	Top of S		Thickness (ft) 27.6	
		L1			e: er of riser pipe ill around riser			ad PVC 1.0	 in
Clay				Type of bucin	in around riser		Del	nomic	
	27.6	-		Diameter of bore	hole			3.50	in
				Depth to top of w	ell screen			29.6	ft
				TD 0				al I DV/a	
				Type of screen			iviacnine	Slotted PVC	
			l l		or size of openings			0.010	in
	Sand	L2		Diameter of so				1.0	in
34.6				Type of backfill a	round screen		#2 Fi	lter Sand	
Gravel				Depth of bottom	of well screen			34.6	ft
		L3		Bottom of Silt tra	p			34.7	ft
40.0	34.7	_ Ո		Depth of bottom	of borehole			34.7	ft
(Bottom	of Exploration)								
	th from ground surface in feet)				(Not to Scale)				
	31.85 ft +			ft +	0.1 ft	. =	36.95	ft_	
	Pay Length (L1)	Length o	f screen (L2)	Length	of silt trap (L3)		Pay leng	tn	
COMMENTS: G:\Projects\40223 - M	1&M Potomac Ave SW\00	02∖Fieldwork	\Well Install R	<u>leports</u>					

APPENDIX G

Groundwater Sampling Records

	LOV	V-FLO	W GR	OUND	WAT	ER SA	MPL	ING I	RECO	RD	WELL NAME 67 W - 607 - 13 - 1	
PROJECT	Buzzard P	oint - Akridg	e Parcel		FILE	NO. 402	23-002		D	ATE	Page 1 of 1	1
LOCATION			ge I areer			TYPE 4022		thylene		EATHER	& Sunny	1
		VICE Horiba	u-53			DEVICE	perista			EMPERATURE	31 °F	1
WELL I.D.	(in.) 1			LENGTH		28	(mid	posa+ 16.	27-6) FI	ELD REP	D. Seserko	
WATER LE	VEL	4.64 7	o ← MEASU	RING POI	NT top of	PVC casing			PU	MP INTAKE DE		
WELL DEP	TH (Log)	23,5	DEPTH		OM	25.09	(TOG)		W	ELL VOLUME	1.6 4	
TIME (24 hrs)	WATER DEPTH (ft)	Ph (standard)	CONDUCTI VITY (µS/cm	DO (mg/L)	TURB. (NTU)	TEMP. (°C)	ORP (mV)	DRAW- DOWN (ft)	FLOW RATE		REMARKS lor, odor, sheen) ield filtrations)	
Stabilized	within →	[+/- 0.1]	[+3%]	[+/- 10%]	[< 10]	N/A	[+/- 10]	[< 0.2]*	[<500mL/min]	(dedicated tul	bing, cleaning procedures)	
12:40	14.64								J.	Wate- Qual	ity Analyzer not utilized	
12:45	15.70							1.06	160			153
12:50	16.93							2.29	155			
		W ₁								to drawdown ,	v flow not teasible due call G. Giosa 7 e vocunte to well bottom	we11
1:20	16:78				7					splicetubing	to well bottom	
1:25	20.21		II.	4				3,43	250			25
1:30	21.92							5.14	245			24
1:35	DRY 40 25.08			1.7	è			8.30	_	well eva	cuate complete	99
										possible sol	evate complete	
					3	3						
				5.5								
							4					
							-					
							1 1000					
	,											
		- 4										
START PUI	RGE 12	:40	STOR	PURGE	13:3.	5	TOTAL	PURGE V	OLUME	~ 5.	3 4	
SAMPLE	ANALYTE	S SAM	PLE TIME	SAM	PLE CON	TAINER	FIELD	ANALYT	ES S	SAMPLE TIME	SAMPLE CONTAINER	
		\dashv							-			
	-110000-151-1-1											
												U
		_									<i>ii</i>	
* OR <0.03 t	otal change	over 3 events										
							1/ft, 2 in	well = 0.16	3 gal/ft,	4 in = 0.653 gal/ft,	6 in = 1.469 gal/ft	
1 cu. ft. $= 7.4$	logal, 1 g	gal = 3.785 L,	1L = 0.26	4 gal, 0.5	$L/\min = 0.$	132 gal/min						

	LOV	W-FLO	W GR	OUND	WAT	ER SA	MPL	ING I	RECO	RD	WELL NAME GTW-607- (3-1 Page 1 of
PROJECT	Buzzard P	oint - Akrids	e Parcel		FILE	NO. 4022	23-002		D/	ATE	12/13/13
LOCATION			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			TYPE		hylene		EATHER	
FIELD MON			11_53			DEVICE	perista			EMPERATURE	Sunuy 35 of
WELL I.D. (TOTION		N LENGTH		DEVICE	20	ittic			
WATER LE		22015				DVC agains	au			ELD REP	D. Seserko
WELL DEP	VEL	22.00	MEASU	TO DOTT	top of	25.0				MP INTAKE DEI	
WELL DEF		23.5		то вотто	JIVI	05.0	7	(Toc)) W.	ELL VOLUME	0.48 L
TIME (24 hrs) Stabilized	WATER DEPTH (ft)	Ph (standard)	CONDUCTI VITY (µS/cm [+ 3%]	DO (mg/L)	TURB. (NTU)	TEMP. (°C)	ORP (mV)	DRAW- DOWN (ft) [< 0.2]*	FLOW RATE	(cole (fie	REMARKS or, odor, sheen) eld filtrations)
	,	[,]	[1070]	[17 1070]	[-10]	1071	[17-10]	[< 0.2]	(CSOOIIIC/IIIIII)		ing, cleaning procedures)
										Samples	collected 7:15
											7.15
											£
		7									
			U.								
	,										
			-								
START PUR	GE		STOP	PURGE			TOTAL P	URGE VO	DLUME		
SAMPLE A	ANALYTES	S SAM	PLE TIME	SAM	PLE CON	TAINER	FIELD	ANALYTE	ES S	SAMPLE TIME	SAMPLE CONTAINER
		-									
		\exists									
		-									
* OR <0.03 to				column1 —	1 in well	= 0.0408 gal	/ft. 2 in s	vell = 0.16	3 gal/ft	4 in = 0.653 gal/ft,	6 in = 1.469 col/ft
1 cu. ft. $= 7.4$	8 gal, 1 g	gal = 3.785 L,	1L = 0.26	4 gal, 0.5	$L/\min = 0.$	132 gal/min	, ~ III '	0.10.	Builli, .	0.033 gai/1t,	5 III - 1.409 gal/It

	LOV	W-FLO	W GR	OUND	WAT	ER SA	MPL	ING I	RECO	RD	WELL NAME GTW-G07-13-1A
DDOIECT	D 1 D	aint Almid	DI		FILE	100	22.002				Page 1 of 2
PROJECT LOCATION			ge Parcel		FILE N		23-002			ATE _	12/12/13
FIELD MON			o II 52		TUBE			hylene		EATHER _	Mostly Claudy
WELL I.D. (VICE HOUR		N LENGTH		DEVICE	perista			EMPERATURE	31 %
WATER LE		22,54					id-point	37.57		_). Seserko
WELL DEP		36.0		TO BOTT	NT top of I		.08 7	-C		JMP INTAKE DEPT	
	WATER	26.0	CONDUCTI		T T	70	.00			ELL VOLUME	2.7 L
TIME (24 hrs)	DEPTH (ft)	Ph (standard)	VITY (μS/cm	DO (mg/L)	TURB. (NTU)	TEMP. (°C)	ORP (mV)	DRAW- DOWN (ft)	FLOW RATE	(color	EMARKS , odor, sheen) l filtrations)
Stabilized	within →	[+/- 0.1]	[+3%]	[+/- 10%]	[< 10]	N/A	[+/- 10]	[< 0.2]*	[<500mL/min]		g, cleaning procedures)
9:30	25.54										
9:35	22.59	6.48	0.809	1.56	0	12.78	-236	0.05	250	adjust	pump speed
9:40	23.59	6.54	0.788	1,43	0	12.79	-245	0.05	125		
9:45	20,58	6.54	0,776	1,32	0	12,96	-237	0.04	130		
9:50	22,59	6.56	0,759	1.17	0	13.23	-550	0.05	-		
9:55	22.60	6.57	0.755	1.03	0	13.79	-218	0.06	-		
10.00	22.60	6.57	0.754	0.96	0	13.86	-218	0.06			
10:05	22,59	6.57	0.753	0.90	0	13.66	-219	0.05	140		
10:10	22.60	6.56	0.756	1.15	0	14.11	-210	0.06	125		
10:15	22.61	6.57	0.754	1.15	_	14.61	-209	0.07	140		
10:30	22.60	6.57	0.755	1.07	-	14,97	-211	0.06	-		,
10:35	22.60	6,57	0.748	1.03	****	14.68	-199	0.06	135	pump shut	o ² 0 w №
10:30	27.60	6.57	0.741	0.98	_	1468	- 200	0.06	0_	Call G. G.O	se
10:40	22.61	6.57	0.742	0.93	_	15.10	- 200	0.07	_		
10:45	25.61	6.57	0.739	0.90		15.22	-201	0.07	140		
10:50	22,61	6.56	0,740	0.85	_	15.52		0.07	140		
10:55	22.62	6.57	0.736	0.82	20070	16.01	- 206	0.08			E.E.
11:00	22,61	6.66	0.733	0.91		15.90		0.07	-	Horiba auto-o	e stabilizing
11:05	22.62	6.60	0.731	0.80		15.79	- 508	0.08	_	Ta _{kk} .	
11:10	22.62	6.57	0.735	0.75	_	16.11		0.08	145		
(1:5	23.62	9130	0.729	0.67	1112	15,88	- 207	0.08	-	4 7	1.5
START PUR			and the state of t	PURGE	11:25	The second second	TOTAL P		The second second	~ 7.5	<i>L</i>
SAMPLE A	ANALYTES	S SAM	PLE TIME	SAM	PLE CON	TAINER	FIELD A	ANALYTI	ES S	SAMPLE TIME	SAMPLE CONTAINER
		\dashv									
		\dashv							_		-
* OR <0.03 to	otal change	over 3 events									
			eight of water	column] -	→ 1 in well	= 0.0408 gal	/ft, 2 in v	vell = 0.16	3 gal/ft,	4 in = 0.653 gal/ft, 6	5 in = 1.469 gal/ft

	LOV	V-FLO	W GR	OUND	WAT	ER SA	MPL	ING I	RECO	RD	WELL NAME GTW-607-13-1A Page 2 of 2
PROJECT	Buzzard P	oint - Akrids	ge Parcel		FILE	NO. 402	23-002		D.	ATE	12/12/13
LOCATION			,			TYPE		thylene		EATHER -	Mostly Cloudy
FIELD MON			a U-53			DEVICE	perista	-		EMPERATURE -	31°F
WELL I.D. (TOTAL TIOTHER		N LENGTH		· (mid-					D. Seserko
WATER LE		72 EV	MEASU		NT top of l	DVC casing	Potent .	37,5		IMP INTAKE DEPT	
WELL DEPT		36.0		TO BOTTO	_		0.0	W /			H 27.7 (156)
WEEE DEI	WATER	3010			JIVI	40	1.08	Tob	W.	ELL VOLUME	
TIME	DEPTH	Ph	CONDUCTI VITY	DO	TURB.	TEMP. (°C)	ORP	DRAW-	FLOW		EMARKS
(24 hrs)	(ft)	(standard)	(μS/cm	(mg/L)	(NTU).	LIVII.(C)	(mV)	DOWN (ft)	RATE		, odor, sheen)
Stabilized		[+/- 0.1]	[+3%]	[+/- 10%]	[< 10]	N/A	[+/- 10]	[< 0.2]*	[<500mL/min]	7	l filtrations) g, cleaning procedures)
										(dedicated tubin	g, cleaning procedures)
11:00	25.62	6.57	0.732	0.64		15.71	208	0.08	ton-		
11:25	25.62	6,56	0.73	0,63	August	15.71	-207	0.08	age-		
					е	1				collect sampl	os 11:30
			9								
										Note: Wa	tor Quality
										Analy:	zer did not
										properly cal	librate DO le turbidity
						μ				or provid	le turbidity
										measurenen	ts. Allowed
										other param	eters to
										stabilize	- and then Samples.
										collected	samples.
									3		
								7			
										24	
										8	
										Na.	
START PUR	GE		STOP	PURGE			TOTAL F	URGE VO	DLUME		
SAMPLE A	NALYTES	SAM	PLE TIME	SAM	PLE CON	FAINER	FIELD .	ANALYTE	S S	SAMPLE TIME	SAMPLE CONTAINER
		7									
		\dashv		-							
		\dashv									
		٦									
* OR <0.03 to	tal change o	over 3 events									-
[well volume	= 3.14 (PI) 2	x radius ² x he					l/ft, 2 in v	well = 0.163	3 gal/ft,	4 in = 0.653 gal/ft,	5 in = 1.469 gal/ft
1 cu. ft. $= 7.48$	gal, 1 g	al = 3.785 L,	1L = 0.264	4 gal, 0.5	$L/\min = 0.1$	32 gal/min					

											Page 1 of \
	Buzzard P Washingto	oint - Akrid	ge Parcel		FILE I		23-002			ATE	12/12/13
		VICE Horiba	a II 52			TYPE	polyet	hylene		EATHER	54nny
VELL I.D. (VICE HOHO		LENGTH		Chidpoint			-6) FI	EMPERATURE ELD REP	D. Seserko
			- MEASU				12.1	trom i	PI	IMP INTAKE DEI	PTH 14.6 (17.97 - 11.21)
VELL DEP		15		то вотто			(TOL)	1		ELL VOLUME	1.04 4
TIME	WATER DEPTH	Ph	CONDUCTI		TURB.	TEMP. (°C)	OPP	DRAW-	FLOW		REMARKS
(24 hrs)	(ft)	(standard)	(μS/cm	(mg/L)	(NTU)		(mV)	DOWN (ft)	RATE		or, odor, sheen) eld filtrations)
Stabilized		[+/- 0.1]	[+ 3%]	[+/- 10%]	[< 10]	N/A	[+/- 10]	[< 0.2]*	[<500mL/min]	(dedicated tub	ing, cleaning procedures)
3:50	11,37										
3:55	12.58	6,49	0.878	1.52	_	15.40	52	1.36	,		
4:00	14.40	6.59	0.854	0.94	esser	17.13	3	3.18	260		
4:02	15.20	6.54	0.817	0.96	Water-	15.19	29	3,98		lower	tubing to bottom
4:05	15.51	6.54	0.798	1.00	Report.	14,31	35	4.79	_		
4:10		6.48	0.841	0.87	_	15.21	44	5.21	200		
4:15	17.97 DRY	6.28	0.782	1.09	_	15.15	39	6.75	2mm**	ENAC. CO	omo lete
											-
TART PUR	GE I	5:50	STOP	PURGE	16:1	5	TOTAL F	URGE VO	DLUME	~ 5.75	5 4
SAMPLE A	ANALYTES	SAM	PLE TIME	SAMI	PLE CON	I		ANALYTE		AMPLE TIME	SAMPLE CONTAINER
		4								*	
		\dashv							+		9
		\dashv									
		\dashv							_		
OR <0.03 to	otal change o	over 3 events									

	LOV	W-FLO	W GRO	OUND	WAT	ER SA	MPL	ING I	RECO	RD	WELL NAME GTW-G07-13-2
PROJECT	Ruzzard P	oint Alreid	go Povool		EILE	102	22.002				Page 1 of
LOCATION			ge rarcei		FILE I	TYPE 4022	23-002	11		TE	12/13/13
FIELD MON			a II_53					hylene		EATHER	Suary
WELL I.D. (VICE HOHO		N LENGTH		DEVICE	perista	altic		MPERATURE	35°F
WATER LE		5.96 To	4 MEASU			DVC agains	,			ELD REP	D. Seserko
WELL DEP		15.0		TO BOTT		7,97 (To	()			MP INTAKE DEI	
WEEL DEI	WATER	17.0			JIVI V		-/		WI	ELL VOLUME	0.314
TIME (24 hrs) Stabilized	DEPTH (ft)	Ph (standard)	CONDUCTI VITY (μS/cm [+ 3%]	DO (mg/L)	TURB. (NTU)	TEMP. (°C)	(mV)	DRAW- DOWN (ft)	FLOW RATE	(colo (fie	REMARKS or, odor, sheen) eld filtrations)
Stabilized	within 7	[1/2 0.1]	[1 3/6]	[+/- 10%]	[< 10]	N/A	[+/- 10]	[< 0.2]*	[<500mL/min]		ing, cleaning procedures)
										Samples co	
											10:00 Am
											-
									-		~
START PUR	CF		emor.	DURCE			705:-				
SAMPLE A		SAM	PLE TIME	PURGE	PLE CONT	T	S. C. S.	URGE VO		AMDLE TIME	CAMPA E CONTAINE
			LLD TIME	SZRIVI	LE COIV	TAINER	FIELD	MALITE	.5 5/	AMPLE TIME	SAMPLE CONTAINER
		_									
* OR <0.03 to	tal change o	over 3 events									
	= 3.14 (PI)	x radius ² x he	ight of water	column] →	1 in well :	= 0.0408 gal/	ft, 2 in v	vell = 0.163	gal/ft, 4	in = 0.653 gal/ft,	6 in = 1.469 gal/ft

	LOV	W-FLO	W GR	OUND	WAT	ER SA	MPL	ING I	RECO	RD	WELL NAME GTW-G07-13- 2A Page 1 of 1
PROJECT	Buzzard P	oint - Akrids	ge Parcel		FILE	NO. 402	23-002		D/	ATE	12/12/13
LOCATION			5	-		TYPE		thylene		EATHER	Sunny
FIELD MON	VITOR DE	VICE Horiba	a U-53			DEVICE	perist	altic		EMPERATURE	31 °F
WELL I.D. ((in.) <u>1</u>			LENGTH	5	34.3	midpois	nt Toe	FI FI	ELD REP	D. Seserko
WATER LE			MEASU	RING POI	NT top of	PVC casing			PU	JMP INTAKE DEP	TH 34.3 TOC
WELL DEP	-	34.7	DEPTH	то вотт	OM	37.03	TOL		W	ELL VOLUME	2.57
TIME (24 hrs)	WATER DEPTH (ft)	Ph (standard)	CONDUCTI VITY (µS/cm	DO (mg/L)	TURB. (NTU)	TEMP. (°C)	ORP (mV)	DRAW- DOWN (ft)	FLOW RATE	(color	EMARKS r, odor, sheen) d filtrations)
Stabilized	within →	[+/- 0.1]	[+3%]	[+/- 10%]	[< 10]	N/A	[+/- 10]	[< 0.2]*	[<500mL/min]	, and a contract of the contra	ng, cleaning procedures)
2:30	20.83										
2:35	23.57		0.704	3,96	_	14.03	91	2.74			
2,40	27.55		0.636	2.75	*	15.47	51	6.72	175		
2:45	30.98		0.629	2.32	-	14.99	56	10.15	-	lots of bubbl	Dø
2:50	35.01	5.89	0.637	2.49	****	14.55	56	11.18	90 (air)	10 100.5	
2:55	30.65	5.90	0.640	2.56		13.81	61	11.82	- 85	10ts 0 t 641	obles, lowertubing to ev of bubbles
3:00	32,85	5.92	0.709	2.70	-	13.87	44	12.02	(air)	10+5	of bubbles
3:05	32,87	5.91	0.743	3.67		14.68	33	12.04	Same of the same o	Hariba auto-o	£ ±
3:10	32.84	5.89	0.696	3,47	New	15.04	41	12.01	_	Coll 6. 6.000	
3:20	34.25	5.83	0.611	3.34	_	15.03	49	13,42		pump @	the orelical may
		•									
											*
START PUR	GE /	4:30	STOP	PURGE	10	20	ТОТАГ	PURGE VO	OI IIME	~ 5.83	1
SAMPLE A			PLE TIME	Company of the State of the Sta	PLE CON			ANALYTE		SAMPLE TIME	SAMPLE CONTAINER
		-									
								171			N.
		-						3			- A1
* OR <0.03 to			. 1. 0			0.010-					
well volume $1 \text{ cu. ft.} = 7.48$	= 5.14 (PI) 2 8 gal, 1 g	$x \text{ radius}^{\text{c}} x \text{ he}$ al = 3.785 L,	eight of water $1L = 0.264$	column] — 4 gal, 0.5	I in well L/min = 0.1	= 0.0408 gal 132 gal/min	/ft, 2 in	well = 0.16	3 gal/ft,	4 in = 0.653 gal/ft,	6 in = 1.469 gal/ft

	LOV	V-FLO	W GRO	OUND	WAT	ER SA	MPL	ING I	RECO	RD	WELL NAME GTW-607-13-JA Page 1 of
PROJECT	Buzzard P	oint - Akrids	ge Parcel		FILE	NO. 402:	23-002		DA	TE	12/13/13
LOCATION			,			TYPE		thylene		EATHER	Sunny
FIELD MON	ITOR DE	VICE Horiba	u-53			DEVICE	perista			MPERATURE	35018
WELL I.D. (LENGTH		(34.3	mi d Doin	+ scieen	TOG) FIL	ELD REP	D. Seserko
WATER LE	VEL	21.04 T	MEASU		NT top of I	PVC casing					EPTH 34.3 (TOC)
WELL DEP	ΓΗ (Log)	34.7		то вотто		37.03	Too	2		ELL VOLUME	2.47 L
TIME	WATER		CONDUCTI					DRAW-			REMARKS
TIME (24 hrs) Stabilized	DEPTH (ft)	Ph (standard)	VITY (μS/cm	DO (mg/L)	TURB. (NTU)	TEMP. (°C)	(mV)	DOWN (ft)	FLOW RATE	(olor, odor, sheen) field filtrations)
Stabilized	within >	[+/- 0.1]	[+ 3%]	[+/- 10%]	[< 10]	N/A	[+/- 10]	[< 0.2]*	[<500mL/min]	(dedicated to	ibing, cleaning procedures)
										Collect	Samples
											10:30 Am
				2.							
										amber	L's lange
										tom	14.3-37.0
					-						
											~
START PUR	CF		STOR	DUDGE			TOTAL	WD CD VIC			
				PURGE				URGE VO			
SAMPLE A	NALYTES	SAMI	PLE TIME	SAMI	PLE CONT	FAINER	FIELD	ANALYTE	S S.	AMPLE TIME	SAMPLE CONTAINER
		-		-							
		-									
* OR <0.03 to											
[well volume : 1 cu. ft. = 7.48	= 3.14 (PI) x 3 gal, 1 ga	c radius x he al = 3.785 L,	ight of water 0.264	column] \rightarrow [gal, 0.5]	$1 \text{ in well} = 1$ $\frac{L}{\min} = 0.1$	= 0.0408 gal/ 32 gal/min	/ft, 2 in v	well = 0.163	3 gal/ft, 4	in = 0.653 gal/ft,	6 in = 1.469 gal/ft

APPENDIX H

Laboratory Analytical Reports



Pace Analytical Services, Inc. 205 East Meadow Road - Suite A Eden, NC 27288 (336)623-8921 Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176 Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

December 16, 2013

Greg Grose Haley & Aldrich, Inc. 7926 Jones Beach Drive Suite 870 Mc Lean, VA 22102

RE: Project: Buzzard Point Lot 13 Sq. 607

Pace Project No.: 92182244

Dear Greg Grose:

Enclosed are the analytical results for sample(s) received by the laboratory on December 06, 2013. The results relate only to the samples included in this report. Results reported herein conform to the most current TNI standards and the laboratory's Quality Assurance Manual, where applicable, unless otherwise noted in the body of the report.

Analyses were performed at the Pace Analytical Services location indicated on the sample analyte page for analysis unless otherwise footnoted.

If you have any questions concerning this report, please feel free to contact me.

Sincerely,

Kevin Herring

Kein Slern

kevin.herring@pacelabs.com Project Manager

Enclosures





Pace Analytical Services, Inc.

205 East Meadow Road - Suite A Eden, NC 27288 (336)623-8921

Pace Analytical Services, Inc.

2225 Riverside Dr. Asheville, NC 28804 (828)254-7176

Pace Analytical Services, Inc.

9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

CERTIFICATIONS

Project: Buzzard Point Lot 13 Sq. 607

Pace Project No.: 92182244

Charlotte Certification IDs

9800 Kincey Ave. Ste 100, Huntersville, NC 28078 North Carolina Drinking Water Certification #: 37706 North Carolina Field Services Certification #: 5342 North Carolina Wastewater Certification #: 12 South Carolina Certification #: 99006001 Florida/NELAP Certification #: E87627 Kentucky UST Certification #: 84 West Virginia Certification #: 357 Virginia/VELAP Certification #: 460221

Asheville Certification IDs

2225 Riverside Dr., Asheville, NC 28804 Florida/NELAP Certification #: E87648 Massachusetts Certification #: M-NC030

North Carolina Drinking Water Certification #: 37712

North Carolina Wastewater Certification #: 40 South Carolina Certification #: 99030001 West Virginia Certification #: 356 Virginia/VELAP Certification #: 460222

REPORT OF LABORATORY ANALYSIS



Pace Analytical Services, Inc. 205 East Meadow Road - Suite A

Eden, NC 27288 (336)623-8921

Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176

Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

SAMPLE ANALYTE COUNT

Project: Buzzard Point Lot 13 Sq. 607

Pace Project No.: 92182244

Lab ID	Sample ID	Method	Analysts	Analytes Reported	Laboratory
92182244001	GTW607-13-1-3	EPA 8015 Modified	NU1	2	PASI-C
		EPA 8015 Modified	GAW	2	PASI-C
		EPA 6010	JDA	12	PASI-A
		EPA 7471	MTS	1	PASI-A
		EPA 8270	BPJ	74	PASI-C
		EPA 8260	DLK	70	PASI-C
		ASTM D2974-87	TNM	1	PASI-C



205 East Meadow Road - Suite A Eden, NC 27288 (336)623-8921

Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176

Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078

(704)875-9092

SUMMARY OF DETECTION

Project: Buzzard Point Lot 13 Sq. 607

Pace Project No.: 92182244

Lab Sample ID Method	Client Sample ID Parameters	Result	Units	Report Limit	Analyzed	Qualifiers
92182244001	GTW607-13-1-3					
EPA 6010	Arsenic	7.1 mg	g/kg	0.99	12/13/13 17:46	
EPA 6010	Beryllium	0.78 mg	g/kg	0.099	12/13/13 17:46	R1
EPA 6010	Cadmium	0.39 mg	g/kg	0.099	12/13/13 17:46	
EPA 6010	Chromium	18.2 mg	g/kg	0.49	12/13/13 17:46	
EPA 6010	Copper	18.9 mg	g/kg	0.49	12/13/13 17:46	
EPA 6010	Lead	9.4 mg	g/kg	0.49	12/13/13 17:46	
EPA 6010	Nickel	11.0 mg	g/kg	0.49	12/13/13 17:46	
EPA 6010	Zinc	31.7 mg	g/kg	0.99	12/13/13 17:46	
EPA 7471	Mercury	0.030 mg	g/kg	0.0039	12/13/13 15:55	R1
ASTM D2974-87	Percent Moisture	17.1 %		0.10	12/11/13 14:15	



Date: 12/16/2013 01:15 PM

Pace Analytical Services, Inc. 205 East Meadow Road - Suite A Eden, NC 27288 (336)623-8921

Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176 Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

ANALYTICAL RESULTS

Project: Buzzard Point Lot 13 Sq. 607

Sample: GTW607-13-1-3	Lab ID: 921822	244001 Collected: 12/0	05/13 10:0	5 Received: 12	2/06/13 11:15 N	latrix: Solid	
Results reported on a "dry-weigh	nt" basis						
Parameters	Results	Units Report Lim	it DF	Prepared	Analyzed	CAS No.	Qua
015 GCS THC-Diesel	Analytical Method	: EPA 8015 Modified Prep	paration M	ethod: EPA 3546			
Diesel Components Surrogates	ND mg/kg	9	.0 1	12/06/13 15:15	12/09/13 00:30	68334-30-5	
n-Pentacosane (S)	87 %	41-1	19 1	12/06/13 15:15	12/09/13 00:30	629-99-2	
Gasoline Range Organics	Analytical Method	: EPA 8015 Modified Prep	paration M	ethod: EPA 5035A	/5030B		
Gasoline Range Organics Surrogates	ND mg/kg	5	.6 1	12/09/13 15:04	12/09/13 18:32	8006-61-9	
4-Bromofluorobenzene (S)	84 %	70-10	67 1	12/09/13 15:04	12/09/13 18:32	460-00-4	
6010 MET ICP	Analytical Method	: EPA 6010 Preparation N	/lethod: EF	PA 3050			
Antimony	ND mg/kg	0.4	19 1	12/13/13 11:05	12/13/13 17:46	7440-36-0	M1,R1
Arsenic	7.1 mg/kg	0.9	99 1	12/13/13 11:05	12/13/13 17:46	7440-38-2	
Beryllium	0.78 mg/kg		99 1	12/13/13 11:05	12/13/13 17:46	7440-41-7	R1
Cadmium	0.39 mg/kg		99 1	12/13/13 11:05	12/13/13 17:46	7440-43-9	
Chromium	18.2 mg/kg				12/13/13 17:46		
Copper	18.9 mg/kg				12/13/13 17:46	-	
_ead	9.4 mg/kg				12/13/13 17:46		
Nickel	11.0 mg/kg				12/13/13 17:46		
Selenium	ND mg/k				12/13/13 17:46		D1
	υ,	,					R1
Silver	ND mg/kg				12/13/13 17:46		R1
Γhallium 	ND mg/kg				12/13/13 17:46		R1
Zinc	31.7 mg/kg				12/13/13 17:46	7440-66-6	
7471 Mercury	·	: EPA 7471 Preparation N					_
Mercury	0.030 mg/kg	0.003	39 1	12/13/13 13:46	12/13/13 15:55	7439-97-6	R1
3270 MSSV Microwave	Analytical Method	: EPA 8270 Preparation N	/lethod: EF	PA 3546			
Acenaphthene	ND ug/kg	39	98 1	12/06/13 20:26	12/10/13 11:56	83-32-9	
Acenaphthylene	ND ug/kg	39	98 1	12/06/13 20:26	12/10/13 11:56	208-96-8	
Aniline	ND ug/kg	39	98 1	12/06/13 20:26	12/10/13 11:56	62-53-3	
Anthracene	ND ug/kg	39	98 1	12/06/13 20:26	12/10/13 11:56	120-12-7	
Benzo(a)anthracene	ND ug/kg	39	98 1	12/06/13 20:26	12/10/13 11:56	56-55-3	
Benzo(a)pyrene	ND ug/kg	39	98 1	12/06/13 20:26	12/10/13 11:56	50-32-8	
Benzo(b)fluoranthene	ND ug/kg	39	98 1	12/06/13 20:26	12/10/13 11:56	205-99-2	
Benzo(g,h,i)perylene	ND ug/kg		98 1		12/10/13 11:56		
Benzo(k)fluoranthene	ND ug/kg		98 1		12/10/13 11:56		
Benzoic Acid	ND ug/kg		90 1		12/10/13 11:56		
Benzyl alcohol	ND ug/kg		97 1		12/10/13 11:56		
I-Bromophenylphenyl ether	ND ug/kg		98 1		12/10/13 11:56		
Butylbenzylphthalate	ND ug/kg		98 1		12/10/13 11:56		
4-Chloro-3-methylphenol	ND ug/kg		97 1		12/10/13 11:56		
, ,	ND ug/kg				12/10/13 11:56		
	IND UQ/KQ	193	JU 1	12/00/13 20.20	12/10/13 11:30	100-47-0	
1-Chloroaniline			ρ 1	12/06/12 20:26	12/10/12 11-56	111_01 1	
i-Cnioroaniline ois(2-Chloroethoxy)methane ois(2-Chloroethyl) ether	ND ug/kg ND ug/kg	39	98 1 98 1		12/10/13 11:56 12/10/13 11:56		



Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176 Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

ANALYTICAL RESULTS

Project: Buzzard Point Lot 13 Sq. 607

Pace Project No.: 92182244

Date: 12/16/2013 01:15 PM

Lab ID: 92182244001 Sample: GTW607-13-1-3 Collected: 12/05/13 10:05 Received: 12/06/13 11:15 Matrix: Solid

Results reported on a "dry-weight	t" basis							
Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8270 MSSV Microwave	Analytical Method	d: EPA 827	0 Preparation Metl	hod: EP	A 3546			
2-Chloronaphthalene	ND ug/kg	g	398	1	12/06/13 20:26	12/10/13 11:56	91-58-7	
2-Chlorophenol	ND ug/kg	g	398	1	12/06/13 20:26	12/10/13 11:56	95-57-8	
4-Chlorophenylphenyl ether	ND ug/kg	_	398	1	12/06/13 20:26	12/10/13 11:56	7005-72-3	
Chrysene	ND ug/kg	q	398	1	12/06/13 20:26	12/10/13 11:56	218-01-9	
Dibenz(a,h)anthracene	ND ug/kg	g	398	1	12/06/13 20:26	12/10/13 11:56	53-70-3	
Dibenzofuran	ND ug/kg	q	398	1	12/06/13 20:26	12/10/13 11:56	132-64-9	
1,2-Dichlorobenzene	ND ug/kg	-	398	1	12/06/13 20:26	12/10/13 11:56	95-50-1	
1,3-Dichlorobenzene	ND ug/kg	-	398	1		12/10/13 11:56		
1,4-Dichlorobenzene	ND ug/kg	-	398	1		12/10/13 11:56		
3,3'-Dichlorobenzidine	ND ug/kg	-	1990	1		12/10/13 11:56		
2,4-Dichlorophenol	ND ug/kg	_	398	1		12/10/13 11:56		
Diethylphthalate	ND ug/kg	-	398	1		12/10/13 11:56		
2,4-Dimethylphenol	ND ug/kg	_	398	1		12/10/13 11:56		
Dimethylphthalate	ND ug/kg	-	398	1		12/10/13 11:56		
Di-n-butylphthalate	ND ug/kg	_	398	1		12/10/13 11:56		
4,6-Dinitro-2-methylphenol	ND ug/kg	-	797	1		12/10/13 11:56		
2,4-Dinitrophenol	ND ug/kg	-	1990	1		12/10/13 11:56		
2,4-Dinitrotoluene	ND ug/kg	_	398	1		12/10/13 11:56		
2,6-Dinitrotoluene	ND ug/kg		398	1		12/10/13 11:56		
Di-n-octylphthalate	ND ug/kg	_	398	1		12/10/13 11:56		
ois(2-Ethylhexyl)phthalate	ND ug/kg	-	398	1		12/10/13 11:56		
		_	398	1		12/10/13 11:56		
Fluoranthene	ND ug/kg	_						
Fluorene	ND ug/kg	-	398	1		12/10/13 11:56		
Hexachloro-1,3-butadiene	ND ug/kg	_	398	1		12/10/13 11:56		
Hexachlorobenzene	ND ug/kg	-	398	1		12/10/13 11:56		
Hexachlorocyclopentadiene	ND ug/kg	-	398	1		12/10/13 11:56		
Hexachloroethane	ND ug/kg	-	398	1		12/10/13 11:56		
ndeno(1,2,3-cd)pyrene	ND ug/kg	-	398	1		12/10/13 11:56		
sophorone	ND ug/kg	_	398	1		12/10/13 11:56		
I-Methylnaphthalene	ND ug/kg	-	398	1		12/10/13 11:56		
2-Methylnaphthalene	ND ug/kg	-	398	1		12/10/13 11:56		
2-Methylphenol(o-Cresol)	ND ug/kç	-	398	1		12/10/13 11:56	95-48-7	
3&4-Methylphenol(m&p Cresol)	ND ug/kç	-	398	1		12/10/13 11:56		
Naphthalene	ND ug/kg		398	1		12/10/13 11:56		
2-Nitroaniline	ND ug/kç	_	1990	1		12/10/13 11:56		
3-Nitroaniline	ND ug/ko	_	1990	1		12/10/13 11:56		
I-Nitroaniline	ND ug/kg	_	797	1	12/06/13 20:26	12/10/13 11:56	100-01-6	
Nitrobenzene	ND ug/ko	-	398	1		12/10/13 11:56		
2-Nitrophenol	ND ug/kg		398	1		12/10/13 11:56		
I-Nitrophenol	ND ug/ko		1990	1		12/10/13 11:56		
N-Nitrosodimethylamine	ND ug/ko	-	398	1		12/10/13 11:56		
N-Nitroso-di-n-propylamine	ND ug/ko		398	1		12/10/13 11:56		
N-Nitrosodiphenylamine	ND ug/ko	g	398	1	12/06/13 20:26	12/10/13 11:56	86-30-6	
Pentachlorophenol	ND ug/ko	g	1990	1	12/06/13 20:26	12/10/13 11:56	87-86-5	
Phenanthrene	ND ug/ko	g	398	1	12/06/13 20:26	12/10/13 11:56	85-01-8	
Phenol	ND ug/kg	g	398	1	12/06/13 20:26	12/10/13 11:56	108-95-2	



Lab ID: 92182244001

Units

Results

Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176

Received: 12/06/13 11:15

Analyzed

Prepared

Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

Matrix: Solid

CAS No.

Qual

ANALYTICAL RESULTS

Collected: 12/05/13 10:05

DF

Report Limit

Project: Buzzard Point Lot 13 Sq. 607

Results reported on a "dry-weight" basis

Parameters R

Pace Project No.: 92182244

Sample: GTW607-13-1-3

Date: 12/16/2013 01:15 PM

8270 MSSV Microwave Analytical Method: EPA 8270 Preparation Method: EPA 3546 398 Pyrene ND ug/kg 12/06/13 20:26 12/10/13 11:56 129-00-0 398 1,2,4-Trichlorobenzene ND ug/kg 1 12/06/13 20:26 12/10/13 11:56 120-82-1 2,4,5-Trichlorophenol ND ug/kg 398 12/06/13 20:26 12/10/13 11:56 95-95-4 1 2,4,6-Trichlorophenol ND ug/kg 398 1 12/06/13 20:26 12/10/13 11:56 88-06-2 Surrogates 50 % 1 12/06/13 20:26 12/10/13 11:56 4165-60-0 Nitrobenzene-d5 (S) 23-110 2-Fluorobiphenyl (S) 53 % 30-110 1 12/06/13 20:26 12/10/13 11:56 321-60-8 Terphenyl-d14 (S) 69 % 28-110 12/06/13 20:26 12/10/13 11:56 1718-51-0 1 Phenol-d6 (S) 57 % 22-110 1 12/06/13 20:26 12/10/13 11:56 13127-88-3 2-Fluorophenol (S) 56 % 13-110 1 12/06/13 20:26 12/10/13 11:56 367-12-4 2,4,6-Tribromophenol (S) 61 % 27-110 1 12/06/13 20:26 12/10/13 11:56 118-79-6 8260/5035A Volatile Organics Analytical Method: EPA 8260 ND ug/kg 86.0 12/12/13 23:42 67-64-1 Acetone 1 Benzene ND ug/kg 4.3 1 12/12/13 23:42 71-43-2 Bromobenzene ND ug/kg 4.3 12/12/13 23:42 108-86-1 1 Bromochloromethane ND ug/kg 43 12/12/13 23:42 74-97-5 1 Bromodichloromethane ND ug/kg 43 12/12/13 23:42 75-27-4 1

12/12/13 23:42 75-25-2 **Bromoform** ND ug/kg 4.3 1 12/12/13 23:42 74-83-9 Bromomethane ND ug/kg 8.6 1 2-Butanone (MEK) ND ug/kg 86.0 1 12/12/13 23:42 78-93-3 n-Butylbenzene ND ug/kg 4.3 1 12/12/13 23:42 104-51-8 sec-Butylbenzene ND ug/kg 4.3 1 12/12/13 23:42 135-98-8 tert-Butylbenzene ND ug/kg 4.3 12/12/13 23:42 98-06-6 1 Carbon tetrachloride ND ug/kg 4.3 1 12/12/13 23:42 56-23-5 Chlorobenzene ND ua/ka 4.3 1 12/12/13 23:42 108-90-7 Chloroethane ND ug/kg 8.6 12/12/13 23:42 75-00-3 1 Chloroform ND ug/kg 4.3 1 12/12/13 23:42 67-66-3 Chloromethane ND ug/kg 8.6 12/12/13 23:42 74-87-3 1 2-Chlorotoluene ND ug/kg 4.3 1 12/12/13 23:42 95-49-8 12/12/13 23:42 106-43-4 4-Chlorotoluene ND ug/kg 4.3 1 1,2-Dibromo-3-chloropropane ND ug/kg 4.3 1 12/12/13 23:42 96-12-8 Dibromochloromethane ND ug/kg 4.3 1 12/12/13 23:42 124-48-1 1,2-Dibromoethane (EDB) ND ug/kg 4.3 1 12/12/13 23:42 106-93-4 4.3 12/12/13 23:42 74-95-3 Dibromomethane ND ug/kg 1 1,2-Dichlorobenzene ND ug/kg 4.3 1 12/12/13 23:42 95-50-1 1,3-Dichlorobenzene ND ug/kg 4.3 12/12/13 23:42 541-73-1 1 1,4-Dichlorobenzene ND ug/kg 4.3 1 12/12/13 23:42 106-46-7 8.6 12/12/13 23:42 75-71-8 Dichlorodifluoromethane ND ug/kg 1 4.3 12/12/13 23:42 75-34-3 1.1-Dichloroethane ND ug/kg 1 12/12/13 23:42 107-06-2 ND ug/kg 4.3 1.2-Dichloroethane 1 12/12/13 23:42 75-35-4 1,1-Dichloroethene ND ug/kg 4.3 1 12/12/13 23:42 156-59-2 cis-1,2-Dichloroethene ND ug/kg 4.3 1 trans-1,2-Dichloroethene ND ug/kg 4.3 1 12/12/13 23:42 156-60-5 1,2-Dichloropropane ND ug/kg 4.3 12/12/13 23:42 78-87-5 1 1,3-Dichloropropane ND ug/kg 4.3 12/12/13 23:42 142-28-9



Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176 Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

ANALYTICAL RESULTS

Project: Buzzard Point Lot 13 Sq. 607

Pace Project No.: 92182244

Date: 12/16/2013 01:15 PM

Sample: GTW607-13-1-3 Lab ID: 92182244001 Collected: 12/05/13 10:05 Received: 12/06/13 11:15 Matrix: Solid

Results reported on a "dry-weight" basis

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qua
8260/5035A Volatile Organics	Analytical Met	hod: EPA 8260)					
2,2-Dichloropropane	ND ug	g/kg	4.3	1		12/12/13 23:42	594-20-7	
1,1-Dichloropropene	ND ug	g/kg	4.3	1		12/12/13 23:42	563-58-6	
cis-1,3-Dichloropropene	ND ug	g/kg	4.3	1		12/12/13 23:42	10061-01-5	
trans-1,3-Dichloropropene	ND ug	g/kg	4.3	1		12/12/13 23:42	10061-02-6	
Diisopropyl ether	ND ug	-	4.3	1		12/12/13 23:42	108-20-3	
Ethylbenzene	ND ug	g/kg	4.3	1		12/12/13 23:42	100-41-4	
Hexachloro-1,3-butadiene	ND ug	g/kg	4.3	1		12/12/13 23:42	87-68-3	
2-Hexanone	ND ug	g/kg	43.0	1		12/12/13 23:42	591-78-6	
sopropylbenzene (Cumene)	ND ug		4.3	1		12/12/13 23:42	98-82-8	
p-Isopropyltoluene	ND ug		4.3	1		12/12/13 23:42		
Methylene Chloride	ND ug		17.2	1		12/12/13 23:42	75-09-2	
1-Methyl-2-pentanone (MIBK)	ND ug		43.0	1		12/12/13 23:42		
Methyl-tert-butyl ether	ND ug		4.3	1		12/12/13 23:42	1634-04-4	
Naphthalene	ND ug	-	4.3	1		12/12/13 23:42		
n-Propylbenzene	ND ug		4.3	1		12/12/13 23:42		
Styrene	ND ug	-	4.3	1		12/12/13 23:42		
,1,1,2-Tetrachloroethane	ND ug		4.3	1		12/12/13 23:42		
1,1,2,2-Tetrachloroethane	ND ug	, ,	4.3	1		12/12/13 23:42		
Tetrachloroethene	ND ug	, ,	4.3	1		12/12/13 23:42		
oluene	ND ug		4.3	1		12/12/13 23:42		
1,2,3-Trichlorobenzene	ND ug	, ,	4.3	1		12/12/13 23:42		
1,2,4-Trichlorobenzene	ND ug	-	4.3	1		12/12/13 23:42		
1,1,1-Trichloroethane	ND ug		4.3	1		12/12/13 23:42		
1,1,2-Trichloroethane	ND ug		4.3	1		12/12/13 23:42		
Frichloroethene	ND ug		4.3	1		12/12/13 23:42		
Frichlorofluoromethane	ND ug	, ,	4.3	1		12/12/13 23:42		
1,2,3-Trichloropropane	ND ug		4.3	1		12/12/13 23:42		
1,2,4-Trimethylbenzene	ND ug	-	4.3	1		12/12/13 23:42		
1,3,5-Trimethylbenzene	ND ug		4.3	1		12/12/13 23:42		
•		, ,	43.0	1		12/12/13 23:42		
/inyl acetate	ND ug		8.6	1		12/12/13 23:42		
/inyl chloride	ND ug	, ,		1				
Kylene (Total)	ND ug		8.6			12/12/13 23:42		
m&p-Xylene	ND ug		8.6	1		12/12/13 23:42		
o-Xylene	ND ug	у/кд	4.3	1		12/12/13 23:42	95-47-6	
Surrogates Foluene-d8 (S)	98 %		70-130	1		12/12/13 23:42	2037-26-5	
4-Bromofluorobenzene (S)	98 %		70-130	1		12/12/13 23:42		
	99 % 106 %		70-130 70-132	1				
1,2-Dichloroethane-d4 (S)				I		12/12/13 23:42	17000-07-0	
Percent Moisture	Analytical Met	hod: ASTM D2	2974-87					
Percent Moisture	17.1 %		0.10	1		12/11/13 14:15		



Pace Analytical Services, Inc. 205 East Meadow Road - Suite A

Eden, NC 27288 (336)623-8921

Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176

Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

QUALITY CONTROL DATA

Project:

Buzzard Point Lot 13 Sq. 607

Pace Project No.:

92182244

QC Batch:

GCV/7587

QC Batch Method:

EPA 5035A/5030B

Analysis Method: Analysis Description: EPA 8015 Modified

Gasoline Range Organics

Associated Lab Samples: 92182244001

METHOD BLANK: 1101445

Matrix: Solid

Associated Lab Samples: 92182244001

Parameter

Units

Units

92182244001

Result

Blank Result

Reporting Limit

5.9

Analyzed

Qualifiers

Gasoline Range Organics 4-Bromofluorobenzene (S)

mg/kg %

ND 85

70-167 12/09/13 18:09

12/09/13 18:09

LABORATORY CONTROL SAMPLE: 1101446

MATRIX SPIKE & MATRIX SPIKE DUPLICATE:

Parameter

Spike Conc. 49.5

LCS Result 46.7

LCS % Rec 94 % Rec Limits

70-165

70-167

Qualifiers

Gasoline Range Organics 4-Bromofluorobenzene (S) mg/kg %

Units

mg/kg

%

1101448

MSD MS

87

% Rec

70-167

Parameter Gasoline Range Organics 4-Bromofluorobenzene (S)

Date: 12/16/2013 01:15 PM

MS

Conc.

46.8

1101447

ND

MSD Spike Spike

MS Conc. Result

46.8

Result 47.2 47.6

% Rec 100

80

MSD % Rec 100

84

Limits **RPD** 47-187

Qual



Pace Analytical Services, Inc. 205 East Meadow Road - Suite A

Eden, NC 27288 (336)623-8921

Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176 Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

QUALITY CONTROL DATA

Project:

Buzzard Point Lot 13 Sq. 607

Pace Project No.:

92182244

QC Batch: QC Batch Method: MERP/5938

EPA 7471

Analysis Method:

EPA 7471

Analysis Description:

7471 Mercury

Associated Lab Samples: 92182244001

METHOD BLANK: 1105179

Matrix: Solid

Associated Lab Samples:

92182244001

Blank Result

Reporting

Limit

Qualifiers Analyzed

Mercury

Mercury

Mercury

mg/kg

mg/kg

Units

mg/kg

ND

0.0050 12/13/13 15:50

LABORATORY CONTROL SAMPLE:

Parameter

Parameter

Date: 12/16/2013 01:15 PM

Parameter

1105180

Units

Units

Spike Conc.

.067

.054

LCS Result

LCS % Rec % Rec

108

Limits

80-120

Qualifiers

MATRIX SPIKE & MATRIX SPIKE DUPLICATE:

1105181

0.030

1105182

0.072

MSD

.06

MS 92182244001 Spike Result Conc.

Spike Conc.

MS Result 0.076

MS Result % Rec

0.10

MSD

MSD % Rec

123

85

% Rec Limits 75-125

RPD

Qual 31 R1

REPORT OF LABORATORY ANALYSIS

This report shall not be reproduced, except in full, without the written consent of Pace Analytical Services, Inc..



Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176 Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

QUALITY CONTROL DATA

Project: Buzzard Point Lot 13 Sq. 607

Pace Project No.: 92182244

QC Batch: MPRP/14857 Analysis Method: EPA 6010
QC Batch Method: EPA 3050 Analysis Description: 6010 MET

Associated Lab Samples: 92182244001

METHOD BLANK: 1104978 Matrix: Solid

1104979

mg/kg

mg/kg

mg/kg

Associated Lab Samples: 92182244001

LABORATORY CONTROL SAMPLE:

Silver

Zinc

Thallium

Date: 12/16/2013 01:15 PM

Parameter	Units	Blank Result	Reporting Limit	Analyzed	Qualifiers
Antimony	mg/kg	ND ND	0.50	12/13/13 17:30	
Arsenic	mg/kg	ND	1.0	12/13/13 17:30	
Beryllium	mg/kg	ND	0.10	12/13/13 17:30	
Cadmium	mg/kg	ND	0.10	12/13/13 17:30	
Chromium	mg/kg	ND	0.50	12/13/13 17:30	
Copper	mg/kg	ND	0.50	12/13/13 17:30	
Lead	mg/kg	ND	0.50	12/13/13 17:30	
Nickel	mg/kg	ND	0.50	12/13/13 17:30	
Selenium	mg/kg	ND	1.0	12/13/13 17:30	
Silver	mg/kg	ND	0.50	12/13/13 17:30	
Thallium	mg/kg	ND	1.0	12/13/13 17:30	
Zinc	mg/kg	ND	1.0	12/13/13 17:30	

		Spike	LCS	LCS	% Rec	
Parameter	Units	Conc.	Result	% Rec	Limits	Qualifiers
Antimony	mg/kg	50	50.1	100	80-120	
Arsenic	mg/kg	50	49.2	98	80-120	
Beryllium	mg/kg	50	50.0	100	80-120	
Cadmium	mg/kg	50	48.9	98	80-120	
Chromium	mg/kg	50	49.4	99	80-120	
Copper	mg/kg	50	49.8	100	80-120	
Lead	mg/kg	50	48.8	98	80-120	
Nickel	mg/kg	50	49.6	99	80-120	
Selenium	mg/kg	50	49.7	99	80-120	

25

50

50

			MS	MSD							
	92	182244001	Spike	Spike	MS	MSD	MS	MSD	% Rec		
Parameter	Units	Result	Conc.	Conc.	Result	Result	% Rec	% Rec	Limits	RPD	Qual
Antimony	mg/kg	ND	55.9	45.7	32.2	23.8	57	51	75-125	30	M1,R1
Arsenic	mg/kg	7.1	55.9	45.7	52.1	44.8	81	83	75-125	15	
Beryllium	mg/kg	0.78	55.9	45.7	52.9	43.1	93	93	75-125	21	R1
Cadmium	mg/kg	0.39	55.9	45.7	50.0	41.3	89	89	75-125	19	
Chromium	mg/kg	18.2	55.9	45.7	66.0	60.3	86	92	75-125	9	
Copper	mg/kg	18.9	55.9	45.7	71.0	61.0	93	92	75-125	15	
_ead	mg/kg	9.4	55.9	45.7	57.1	50.8	85	90	75-125	12	

24.5

48.1

49.4

98

96

99

80-120

80-120

80-120



205 East Meadow Road - Suite A Eden, NC 27288 (336)623-8921 Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176 Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

QUALITY CONTROL DATA

Project: Buzzard Point Lot 13 Sq. 607

Pace Project No.: 92182244

Date: 12/16/2013 01:15 PM

MATRIX SPIKE & MATRIX S	SPIKE DUPLICAT	E: 11049	80		1104981						
	92	182244001	MS Spike	MSD Spike	MS	MSD	MS	MSD	% Rec		
Parameter	Units	Result	Conc.	Conc.	Result	Result	% Rec	% Rec	Limits	RPD	Qual
Nickel	mg/kg	11.0	55.9	45.7	60.8	51.6	89	89	75-125	16	
Selenium	mg/kg	ND	55.9	45.7	46.9	37.9	83	82	75-125	21 R1	
Silver	mg/kg	ND	27.9	22.8	25.7	20.7	92	91	75-125	22 R1	
Thallium	mg/kg	ND	55.9	45.7	47.1	38.0	84	83	75-125	21 R1	
Zinc	mg/kg	31.7	55.9	45.7	82.3	73.5	91	91	75-125	11	



Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176 Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

QUALITY CONTROL DATA

Project: Buzzard Point Lot 13 Sq. 607

Pace Project No.: 92182244

Date: 12/16/2013 01:15 PM

QC Batch: MSV/25200 Analysis Method: EPA 8260

QC Batch Method: EPA 8260 Analysis Description: 8260 MSV 5035A Volatile Organics

Associated Lab Samples: 92182244001

METHOD BLANK: 1102369 Matrix: Solid

Associated Lab Samples: 92182244001

Associated Lab Samples. 92102	2244001	Blank	Reporting		
Parameter	Units	Result	Limit	Analyzed	Qualifiers
1,1,1,2-Tetrachloroethane	ug/kg	ND ND	5.0	12/12/13 18:27	
1,1,1-Trichloroethane	ug/kg	ND	5.0	12/12/13 18:27	
1,1,2,2-Tetrachloroethane	ug/kg	ND	5.0	12/12/13 18:27	
1,1,2-Trichloroethane	ug/kg	ND	5.0	12/12/13 18:27	
1,1-Dichloroethane	ug/kg	ND	5.0	12/12/13 18:27	
1,1-Dichloroethene	ug/kg	ND	5.0	12/12/13 18:27	
1,1-Dichloropropene	ug/kg	ND	5.0	12/12/13 18:27	
1,2,3-Trichlorobenzene	ug/kg	ND	5.0	12/12/13 18:27	
1,2,3-Trichloropropane	ug/kg	ND	5.0	12/12/13 18:27	
1,2,4-Trichlorobenzene	ug/kg	ND	5.0	12/12/13 18:27	
1,2,4-Trimethylbenzene	ug/kg	ND	5.0	12/12/13 18:27	
1,2-Dibromo-3-chloropropane	ug/kg	ND	5.0	12/12/13 18:27	
1,2-Dibromoethane (EDB)	ug/kg	ND	5.0	12/12/13 18:27	
1,2-Dichlorobenzene	ug/kg	ND	5.0	12/12/13 18:27	
1,2-Dichloroethane	ug/kg	ND	5.0	12/12/13 18:27	
1,2-Dichloropropane	ug/kg	ND	5.0	12/12/13 18:27	
1,3,5-Trimethylbenzene	ug/kg	ND	5.0	12/12/13 18:27	
1,3-Dichlorobenzene	ug/kg	ND	5.0	12/12/13 18:27	
1,3-Dichloropropane	ug/kg	ND	5.0	12/12/13 18:27	
1,4-Dichlorobenzene	ug/kg	ND	5.0	12/12/13 18:27	
2,2-Dichloropropane	ug/kg	ND	5.0	12/12/13 18:27	
2-Butanone (MEK)	ug/kg	ND	99.6	12/12/13 18:27	
2-Chlorotoluene	ug/kg	ND	5.0	12/12/13 18:27	
2-Hexanone	ug/kg	ND	49.8	12/12/13 18:27	
4-Chlorotoluene	ug/kg	ND	5.0	12/12/13 18:27	
4-Methyl-2-pentanone (MIBK)	ug/kg	ND	49.8	12/12/13 18:27	
Acetone	ug/kg	ND	99.6	12/12/13 18:27	
Benzene	ug/kg	ND	5.0	12/12/13 18:27	
Bromobenzene	ug/kg	ND	5.0	12/12/13 18:27	
Bromochloromethane	ug/kg	ND	5.0	12/12/13 18:27	
Bromodichloromethane	ug/kg	ND	5.0	12/12/13 18:27	
Bromoform	ug/kg	ND	5.0	12/12/13 18:27	
Bromomethane	ug/kg	ND	10	12/12/13 18:27	
Carbon tetrachloride	ug/kg	ND	5.0	12/12/13 18:27	
Chlorobenzene	ug/kg	ND	5.0	12/12/13 18:27	
Chloroethane	ug/kg	ND	10	12/12/13 18:27	
Chloroform	ug/kg	ND	5.0	12/12/13 18:27	
Chloromethane	ug/kg	ND	10	12/12/13 18:27	
cis-1,2-Dichloroethene	ug/kg	ND	5.0	12/12/13 18:27	
cis-1,3-Dichloropropene	ug/kg	ND	5.0	12/12/13 18:27	
Dibromochloromethane	ug/kg	ND ND	5.0	12/12/13 18:27	
Dibromomethane	ug/kg ug/kg	ND ND	5.0	12/12/13 18:27	
Dichlorodifluoromethane	ug/kg ug/kg	ND ND	10	12/12/13 18:27	
Dichiologination	ug/kg	טאו	10	12/12/13 10.21	



Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176 Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

QUALITY CONTROL DATA

Project: Buzzard Point Lot 13 Sq. 607

Pace Project No.: 92182244

Date: 12/16/2013 01:15 PM

METHOD BLANK: 1102369 Matrix: Solid

Associated Lab Samples: 92182244001

		Blank	Reporting		
Parameter	Units	Result	Limit	Analyzed	Qualifiers
Diisopropyl ether	ug/kg	ND ND	5.0	12/12/13 18:27	
Ethylbenzene	ug/kg	ND	5.0	12/12/13 18:27	
Hexachloro-1,3-butadiene	ug/kg	ND	5.0	12/12/13 18:27	
Isopropylbenzene (Cumene)	ug/kg	ND	5.0	12/12/13 18:27	
m&p-Xylene	ug/kg	ND	10	12/12/13 18:27	
Methyl-tert-butyl ether	ug/kg	ND	5.0	12/12/13 18:27	
Methylene Chloride	ug/kg	ND	19.9	12/12/13 18:27	
n-Butylbenzene	ug/kg	ND	5.0	12/12/13 18:27	
n-Propylbenzene	ug/kg	ND	5.0	12/12/13 18:27	
Naphthalene	ug/kg	ND	5.0	12/12/13 18:27	
o-Xylene	ug/kg	ND	5.0	12/12/13 18:27	
p-Isopropyltoluene	ug/kg	ND	5.0	12/12/13 18:27	
sec-Butylbenzene	ug/kg	ND	5.0	12/12/13 18:27	
Styrene	ug/kg	ND	5.0	12/12/13 18:27	
tert-Butylbenzene	ug/kg	ND	5.0	12/12/13 18:27	
Tetrachloroethene	ug/kg	ND	5.0	12/12/13 18:27	
Toluene	ug/kg	ND	5.0	12/12/13 18:27	
trans-1,2-Dichloroethene	ug/kg	ND	5.0	12/12/13 18:27	
trans-1,3-Dichloropropene	ug/kg	ND	5.0	12/12/13 18:27	
Trichloroethene	ug/kg	ND	5.0	12/12/13 18:27	
Trichlorofluoromethane	ug/kg	ND	5.0	12/12/13 18:27	
Vinyl acetate	ug/kg	ND	49.8	12/12/13 18:27	
Vinyl chloride	ug/kg	ND	10	12/12/13 18:27	
Xylene (Total)	ug/kg	ND	10	12/12/13 18:27	
1,2-Dichloroethane-d4 (S)	%	88	70-132	12/12/13 18:27	
4-Bromofluorobenzene (S)	%	102	70-130	12/12/13 18:27	
Toluene-d8 (S)	%	94	70-130	12/12/13 18:27	

LABORATORY CONTROL SAMPLE	: 1102370					
		Spike	LCS	LCS	% Rec	
Parameter	Units	Conc.	Result	% Rec	Limits	Qualifiers
1,1,1,2-Tetrachloroethane	ug/kg	47.9	65.5	137	70-131	L3
1,1,1-Trichloroethane	ug/kg	47.9	56.6	118	70-141	
1,1,2,2-Tetrachloroethane	ug/kg	47.9	55.5	116	70-130	
1,1,2-Trichloroethane	ug/kg	47.9	61.6	129	70-132	
1,1-Dichloroethane	ug/kg	47.9	44.0	92	70-143	
1,1-Dichloroethene	ug/kg	47.9	51.9	108	70-137	
1,1-Dichloropropene	ug/kg	47.9	49.5	103	70-135	
1,2,3-Trichlorobenzene	ug/kg	47.9	60.3	126	69-153	
1,2,3-Trichloropropane	ug/kg	47.9	61.8	129	70-130	
1,2,4-Trichlorobenzene	ug/kg	47.9	59.2	124	55-171	
1,2,4-Trimethylbenzene	ug/kg	47.9	57.5	120	70-149	
1,2-Dibromo-3-chloropropane	ug/kg	47.9	52.4	109	68-141	
1,2-Dibromoethane (EDB)	ug/kg	47.9	61.4	128	70-130	
1,2-Dichlorobenzene	ug/kg	47.9	62.9	131	70-140	



Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176 Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

QUALITY CONTROL DATA

Project: Buzzard Point Lot 13 Sq. 607

Pace Project No.: 92182244

Date: 12/16/2013 01:15 PM

LABORATORY CONTROL SAMPL	E: 1102370	0 "	1.00	1.00	0/ D	
Parameter	Units	Spike Conc.	LCS Result	LCS % Rec	% Rec Limits Qual	ifiers
,2-Dichloroethane	ug/kg		52.3	109	70-137	
,2-Dichloropropane	ug/kg	47.9	50.0	104	70-133	
,3,5-Trimethylbenzene	ug/kg	47.9	58.1	121	70-143	
I,3-Dichlorobenzene	ug/kg	47.9	61.3	128	70-144	
,3-Dichloropropane	ug/kg	47.9	52.4	109	70-132	
,4-Dichlorobenzene	ug/kg	47.9	61.6	129	70-142	
2,2-Dichloropropane	ug/kg	47.9	50.3	105	68-152	
-Butanone (MEK)	ug/kg	95.8	87.1J	91	70-149	
?-Chlorotoluene	ug/kg	47.9	52.9	110	70-141	
?-Hexanone	ug/kg	95.8	90.5	94	70-149	
-Chlorotoluene	ug/kg	47.9	54.3	113	70-149	
-Methyl-2-pentanone (MIBK)	ug/kg	95.8	104	108	70-153	
cetone	ug/kg	95.8	87.4J	91	70-157	
Benzene	ug/kg	47.9	53.8	112	70-130	
Bromobenzene	ug/kg	47.9	50.9	106	70-141	
Bromochloromethane	ug/kg	47.9	60.9	127	70-149	
Bromodichloromethane	ug/kg	47.9	57.0	119	70-130	
Bromoform	ug/kg	47.9	65.8	137	70-131 L3	
Bromomethane	ug/kg	47.9	50.6	106	64-136	
Carbon tetrachloride	ug/kg	47.9	64.6	135	70-154	
Chlorobenzene	ug/kg	47.9	61.0	127	70-135	
Chloroethane	ug/kg	47.9	46.2	97	68-151	
Chloroform	ug/kg	47.9	48.6	101	70-130	
Chloromethane	ug/kg	47.9	44.1	92	70-132	
is-1,2-Dichloroethene	ug/kg ug/kg	47.9	46.2	96	70-140	
is-1,3-Dichloropropene	ug/kg	47.9	52.4	109	70-137	
Dibromochloromethane	ug/kg ug/kg	47.9	63.4	132	70-137 70-130 L3	
Dibromomethane	ug/kg ug/kg	47.9	57.3	120	70-136	
Dichlorodifluoromethane	ug/kg ug/kg	47.9	51.3	107	36-148	
Diisopropyl ether	ug/kg ug/kg	47.9	42.9	90	70-139	
ithylbenzene	ug/kg ug/kg	47.9	58.0	121	70-139	
lexachloro-1,3-butadiene	ug/kg ug/kg	47.9 47.9	62.5	131	70-137 70-145	
sopropylbenzene (Cumene)	ug/kg ug/kg	47.9 47.9	64.2	134	70-143 70-141	
n&p-Xylene		95.8	119	124	70-141 70-140	
	ug/kg	95.6 47.9	48.6	101	45-150	
Methyl-tert-butyl ether	ug/kg			90		
Methylene Chloride	ug/kg	47.9	43.2		70-133	
-Butylbenzene	ug/kg	47.9	56.3	118	65-155	
-Propylbenzene	ug/kg	47.9	57.4	120	70-148	
laphthalene	ug/kg	47.9	61.3	128	70-148	
-Xylene	ug/kg	47.9	58.5	122	70-141	
-Isopropyltoluene	ug/kg	47.9	64.7	135	70-148	
ec-Butylbenzene	ug/kg	47.9	61.9	129	70-145	
Styrene	ug/kg	47.9	62.1	130	70-138	
ert-Butylbenzene	ug/kg	47.9	63.4	132	70-143	
etrachloroethene	ug/kg	47.9	69.9	146	70-140 L3	
oluene	ug/kg	47.9	57.6	120	70-130	
rans-1,2-Dichloroethene	ug/kg	47.9	45.5	95	70-136	
ans-1,3-Dichloropropene	ug/kg	47.9	56.1	117	70-138	



(336)623-8921

Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176 Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

QUALITY CONTROL DATA

Project: Buzzard Point Lot 13 Sq. 607

Pace Project No.: 92182244

Date: 12/16/2013 01:15 PM

LABORATORY CONTROL SAMPL	E: 1102370					
		Spike	LCS	LCS	% Rec	
Parameter	Units	Conc.	Result	% Rec	Limits	Qualifiers
Trichloroethene	ug/kg	47.9	67.3	140	70-132	_3
Trichlorofluoromethane	ug/kg	47.9	52.1	109	69-134	
Vinyl acetate	ug/kg	95.8	84.5	88	24-161	
Vinyl chloride	ug/kg	47.9	47.8	100	55-140	
Xylene (Total)	ug/kg	144	177	123	70-141	
1,2-Dichloroethane-d4 (S)	%			85	70-132	
4-Bromofluorobenzene (S)	%			104	70-130	
Toluene-d8 (S)	%			91	70-130	



205 East Meadow Road - Suite A Eden, NC 27288 (336)623-8921

Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176

Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

QUALITY CONTROL DATA

Project:

Buzzard Point Lot 13 Sq. 607

Pace Project No.:

92182244

QC Batch:
QC Batch Method:

OEXT/25067

EPA 3546

Analysis Method: Analysis Description: EPA 8015 Modified 8015 Solid GCSV

92182244001

Associated Lab Samples: 9
METHOD BLANK: 1100284

Matrix: Solid

Associated Lab Samples:

92182244001

Blank Result Reporting Limit

5.0

Analyzed

12/08/13 17:53

Qualifiers

Diesel Components n-Pentacosane (S)

mg/kg % ND 95

41-119 12/08/13 17:53

LABORATORY CONTROL SAMPLE: 1

Parameter

Parameter

Parameter

1100285

Units

Units

92182164007

Result

ND

Spike Conc.

LCS Result LCS % Rec % Rec Limits

Qualifiers

Diesel Components n-Pentacosane (S)

mg/kg %

Units

mg/kg

%

66.7

53.6

80 93 49-113

MATRIX SPIKE & MATRIX SPIKE DUPLICATE:

1100286

1100287

MS MSD Spike Spike

D ke MS MSD

MS

MSD % Rec L

76

81

% Rec Limits RPD Qual

Diesel Components n-Pentacosane (S)

Date: 12/16/2013 01:15 PM

Spike Conc.

nc. Conc.
79.4

Result 67.9

Result % Rec 60.5

85 93

41-119

10-146 41-119

12



(336)623-8921

Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176 Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

QUALITY CONTROL DATA

Project: Buzzard Point Lot 13 Sq. 607

Pace Project No.: 92182244

Date: 12/16/2013 01:15 PM

QC Batch: OEXT/25076 Analysis Method: EPA 8270

QC Batch Method: EPA 3546 Analysis Description: 8270 Solid MSSV Microwave

Associated Lab Samples: 92182244001

METHOD BLANK: 1100720 Matrix: Solid

Associated Lab Samples: 92182244001

Parameter	Units	Blank Result	Reporting Limit	Analyzed	Qualifiers
1,2,4-Trichlorobenzene	ug/kg		330	12/10/13 09:48	
1,2-Dichlorobenzene	ug/kg	ND	330	12/10/13 09:48	
1,3-Dichlorobenzene	ug/kg	ND	330	12/10/13 09:48	
1,4-Dichlorobenzene	ug/kg	ND	330	12/10/13 09:48	
1-Methylnaphthalene	ug/kg	ND	330	12/10/13 09:48	
2,4,5-Trichlorophenol	ug/kg	ND	330	12/10/13 09:48	
2,4,6-Trichlorophenol	ug/kg	ND	330	12/10/13 09:48	
2,4-Dichlorophenol	ug/kg	ND	330	12/10/13 09:48	
2,4-Dimethylphenol	ug/kg	ND	330	12/10/13 09:48	
2,4-Dinitrophenol	ug/kg	ND	1650	12/10/13 09:48	
2,4-Dinitrotoluene	ug/kg	ND	330	12/10/13 09:48	
2.6-Dinitrotoluene	ug/kg	ND	330	12/10/13 09:48	
2-Chloronaphthalene	ug/kg	ND	330	12/10/13 09:48	
2-Chlorophenol	ug/kg	ND	330	12/10/13 09:48	
2-Methylnaphthalene	ug/kg	ND	330	12/10/13 09:48	
2-Methylphenol(o-Cresol)	ug/kg	ND	330	12/10/13 09:48	
2-Nitroaniline	ug/kg	ND	1650	12/10/13 09:48	
2-Nitrophenol	ug/kg	ND	330	12/10/13 09:48	
3&4-Methylphenol(m&p Cresol)	ug/kg	ND	330	12/10/13 09:48	
3,3'-Dichlorobenzidine	ug/kg	ND	1650	12/10/13 09:48	
3-Nitroaniline	ug/kg	ND	1650	12/10/13 09:48	
4,6-Dinitro-2-methylphenol	ug/kg	ND	660	12/10/13 09:48	
4-Bromophenylphenyl ether	ug/kg	ND	330	12/10/13 09:48	
4-Chloro-3-methylphenol	ug/kg	ND	660	12/10/13 09:48	
4-Chloroaniline	ug/kg	ND	1650	12/10/13 09:48	
4-Chlorophenylphenyl ether	ug/kg	ND	330	12/10/13 09:48	
4-Nitroaniline	ug/kg	ND	660	12/10/13 09:48	
4-Nitrophenol	ug/kg	ND	1650	12/10/13 09:48	
Acenaphthene	ug/kg	ND	330	12/10/13 09:48	
Acenaphthylene	ug/kg	ND	330	12/10/13 09:48	
Aniline	ug/kg	ND	330	12/10/13 09:48	
Anthracene	ug/kg	ND	330	12/10/13 09:48	
Benzo(a)anthracene	ug/kg	ND	330	12/10/13 09:48	
Benzo(a)pyrene	ug/kg	ND	330	12/10/13 09:48	
Benzo(b)fluoranthene	ug/kg	ND	330	12/10/13 09:48	
Benzo(g,h,i)perylene	ug/kg	ND	330	12/10/13 09:48	
Benzo(k)fluoranthene	ug/kg	ND	330	12/10/13 09:48	
Benzoic Acid	ug/kg	ND	1650	12/10/13 09:48	
Benzyl alcohol	ug/kg	ND	660	12/10/13 09:48	
bis(2-Chloroethoxy)methane	ug/kg	ND	330	12/10/13 09:48	
bis(2-Chloroethyl) ether	ug/kg ug/kg	ND	330	12/10/13 09:48	
bis(2-Chloroisopropyl) ether	ug/kg	ND	330	12/10/13 09:48	
bis(2-Ethylhexyl)phthalate	ug/kg	ND	330	12/10/13 09:48	



(336)623-8921

Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176 Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

QUALITY CONTROL DATA

Matrix: Solid

Project: Buzzard Point Lot 13 Sq. 607

Pace Project No.: 92182244

Phenol-d6 (S)

Terphenyl-d14 (S)

Date: 12/16/2013 01:15 PM

METHOD BLANK: 1100720

%

Associated Lab Samples: 92182244001

Associated Lab Samples: 9218	32244001				
		Blank	Reporting		
Parameter	Units	Result	Limit	Analyzed	Qualifiers
Butylbenzylphthalate	ug/kg	ND ND	330	12/10/13 09:48	
Chrysene	ug/kg	ND	330	12/10/13 09:48	
Di-n-butylphthalate	ug/kg	ND	330	12/10/13 09:48	
Di-n-octylphthalate	ug/kg	ND	330	12/10/13 09:48	
Dibenz(a,h)anthracene	ug/kg	ND	330	12/10/13 09:48	
Dibenzofuran	ug/kg	ND	330	12/10/13 09:48	
Diethylphthalate	ug/kg	ND	330	12/10/13 09:48	
Dimethylphthalate	ug/kg	ND	330	12/10/13 09:48	
Fluoranthene	ug/kg	ND	330	12/10/13 09:48	
Fluorene	ug/kg	ND	330	12/10/13 09:48	
Hexachloro-1,3-butadiene	ug/kg	ND	330	12/10/13 09:48	
Hexachlorobenzene	ug/kg	ND	330	12/10/13 09:48	
Hexachlorocyclopentadiene	ug/kg	ND	330	12/10/13 09:48	
Hexachloroethane	ug/kg	ND	330	12/10/13 09:48	
Indeno(1,2,3-cd)pyrene	ug/kg	ND	330	12/10/13 09:48	
Isophorone	ug/kg	ND	330	12/10/13 09:48	
N-Nitroso-di-n-propylamine	ug/kg	ND	330	12/10/13 09:48	
N-Nitrosodimethylamine	ug/kg	ND	330	12/10/13 09:48	
N-Nitrosodiphenylamine	ug/kg	ND	330	12/10/13 09:48	
Naphthalene	ug/kg	ND	330	12/10/13 09:48	
Nitrobenzene	ug/kg	ND	330	12/10/13 09:48	
Pentachlorophenol	ug/kg	ND	1650	12/10/13 09:48	
Phenanthrene	ug/kg	ND	330	12/10/13 09:48	
Phenol	ug/kg	ND	330	12/10/13 09:48	
Pyrene	ug/kg	ND	330	12/10/13 09:48	
2,4,6-Tribromophenol (S)	%	83	27-110	12/10/13 09:48	
2-Fluorobiphenyl (S)	%	69	30-110	12/10/13 09:48	
2-Fluorophenol (S)	%	73	13-110	12/10/13 09:48	
Nitrobenzene-d5 (S)	%	62	23-110	12/10/13 09:48	

LABORATORY CONTROL SAMPLE:	1100721					
		Spike	LCS	LCS	% Rec	
Parameter	Units	Conc.	Result	% Rec	Limits	Qualifiers
1,2,4-Trichlorobenzene	ug/kg	1670	1000	60	39-101	
1,2-Dichlorobenzene	ug/kg	1670	1110	67	36-110	
1,3-Dichlorobenzene	ug/kg	1670	1070	64	35-110	
1,4-Dichlorobenzene	ug/kg	1670	1110	67	35-110	
1-Methylnaphthalene	ug/kg	1670	1220	73	45-105	
2,4,5-Trichlorophenol	ug/kg	1670	1340	80	48-109	
2,4,6-Trichlorophenol	ug/kg	1670	1160	70	45-111	
2,4-Dichlorophenol	ug/kg	1670	1190	71	51-116	
2,4-Dimethylphenol	ug/kg	1670	1370	82	42-103	
2,4-Dinitrophenol	ug/kg	8330	7050	85	28-103	

74

82

22-110 12/10/13 09:48

28-110 12/10/13 09:48



Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176 Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

QUALITY CONTROL DATA

Project: Buzzard Point Lot 13 Sq. 607

Pace Project No.: 92182244

Date: 12/16/2013 01:15 PM

LABORATORY CONTROL SAMPLE	E: 1100721	Coilco	1.00	1.00	0/ Doo	
Parameter	Units	Spike Conc.	LCS Result	LCS % Rec	% Rec Limits	Qualifier
2,4-Dinitrotoluene	ug/kg		1470	88	46-114	
2,6-Dinitrotoluene	ug/kg	1670	1410	84	48-112	
2-Chloronaphthalene	ug/kg	1670	1030	62	44-105	
2-Chlorophenol	ug/kg	1670	1370	82	36-110	
2-Methylnaphthalene	ug/kg	1670	1260	76	39-112	
2-Methylphenol(o-Cresol)	ug/kg	1670	1580	95	39-101	
2-Nitroaniline	ug/kg	3330	2690	81	44-111	
2-Nitrophenol	ug/kg	1670	1360	82	41-100	
3&4-Methylphenol(m&p Cresol)	ug/kg	1670	1550	93	43-103	
3,3'-Dichlorobenzidine	ug/kg	3330	2470	74	10-150	
B-Nitroaniline	ug/kg	3330	2910	87	35-110	
I,6-Dinitro-2-methylphenol	ug/kg	3330	2650	80	38-118	
I-Bromophenylphenyl ether	ug/kg	1670	1380	83	47-115	
I-Chloro-3-methylphenol	ug/kg	3330	2840	85	43-127	
4-Chloroaniline	ug/kg	3330	2680	80	34-109	
1-Chlorophenylphenyl ether	ug/kg	1670	1390	83	44-115	
4-Nitroaniline	ug/kg	3330	3240	97	37-111	
1-Nitrophenol	ug/kg	8330	6040	72	21-152	
Acenaphthene	ug/kg	1670	1280	77	38-117	
Acenaphthylene	ug/kg	1670	1320	79	46-107	
Aniline	ug/kg	1670	1150	69	29-110	
Anthracene	ug/kg	1670	1340	80	50-110	
Benzo(a)anthracene	ug/kg	1670	1280	77	47-116	
Benzo(a)pyrene	ug/kg	1670	1400	84	47-106	
Benzo(b)fluoranthene	ug/kg	1670	1300	78	47-100	
Benzo(g,h,i)perylene	ug/kg	1670	1400	84	39-115	
Benzo(k)fluoranthene	ug/kg	1670	1300	78	45-117	
Benzoic Acid	ug/kg	8330	5040	60	16-110	
Benzyl alcohol	ug/kg ug/kg	3330	2500	75	38-105	
ois(2-Chloroethoxy)methane	ug/kg ug/kg	1670	1220	73	39-110	
ois(2-Chloroethyl) ether	ug/kg ug/kg	1670	1390	84	19-119	
		1670	1270	76	21-110	
pis(2-Chloroisopropyl) ether	ug/kg	1670	1190	70 71	35-116	
pis(2-Ethylhexyl)phthalate	ug/kg	1670	1210	73	38-110	
Butylbenzylphthalate Chrysene	ug/kg	1670	1390	83	49-110	
	ug/kg			71	43-110	
Di-n-butylphthalate	ug/kg	1670	1180			
Di-n-octylphthalate	ug/kg	1670	1110	67	37-109	
Dibenz(a,h)anthracene	ug/kg	1670	1440	86	43-116	
Dibenzofuran Distributa balata	ug/kg	1670	1110	66	45-106	
Diethylphthalate	ug/kg	1670	1170	70	41-114	
Dimethylphthalate	ug/kg	1670	1150	69	43-110	
Fluoranthene	ug/kg	1670	1360	81	50-114	
Fluorene	ug/kg	1670	1370	82	46-114	
lexachloro-1,3-butadiene	ug/kg	1670	937	56	28-111	
Hexachlorobenzene	ug/kg	1670	1160	70	46-120	
Hexachlorocyclopentadiene	ug/kg	1670	1120	67	18-119	
Hexachloroethane	ug/kg	1670	1040	63	33-110	
ndeno(1,2,3-cd)pyrene	ug/kg	1670	1430	86	42-115	



Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176 Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

QUALITY CONTROL DATA

Project: Buzzard Point Lot 13 Sq. 607

Pace Project No.: 92182244

Date: 12/16/2013 01:15 PM

LABORATORY CONTROL SAMP	PLE: 1100721					
		Spike	LCS	LCS	% Rec	
Parameter	Units	Conc.	Result	% Rec	Limits	Qualifiers
Isophorone	ug/kg		1270	76	44-109	
N-Nitroso-di-n-propylamine	ug/kg	1670	1050	63	43-104	
N-Nitrosodimethylamine	ug/kg	1670	1020	61	29-110	
N-Nitrosodiphenylamine	ug/kg	1670	996	60	48-113	
Naphthalene	ug/kg	1670	1310	79	41-110	
Nitrobenzene	ug/kg	1670	1100	66	38-110	
Pentachlorophenol	ug/kg	3330	2540	76	32-128	
Phenanthrene	ug/kg	1670	1320	79	50-110	
Phenol	ug/kg	1670	1400	84	28-106	
Pyrene	ug/kg	1670	1250	75	45-114	
2,4,6-Tribromophenol (S)	%			97	27-110	
2-Fluorobiphenyl (S)	%			66	30-110	
2-Fluorophenol (S)	%			77	13-110	
Nitrobenzene-d5 (S)	%			64	23-110	
Phenol-d6 (S)	%			84	22-110	
Terphenyl-d14 (S)	%			73	28-110	

MATRIX SPIKE & MATRIX SP	IKE DUPLICAT	E: 110072			1100723						
	20.	100044004	MS	MSD	МС	MCD	MC	MCD	0/ Da-		
Doromotor	_	182244001	Spike	Spike	MS	MSD	MS % Ree	MSD	% Rec	DDD	Ougl
Parameter	Units	Result	Conc.	Conc.	Result	Result	% Rec	% Rec	Limits	RPD _	Qual
,2,4-Trichlorobenzene	ug/kg	ND	2020	2020	1190	1200	59	60	18-119	1	
,2-Dichlorobenzene	ug/kg	ND	2020	2020	1330	1310	66	65	50-110	1	
,3-Dichlorobenzene	ug/kg	ND	2020	2020	1290	1260	64	63	27-110	2	
,4-Dichlorobenzene	ug/kg	ND	2020	2020	1360	1310	67	65	28-110	4	
-Methylnaphthalene	ug/kg	ND	2020	2020	1410	1420	70	71	24-116	1	
2,4,5-Trichlorophenol	ug/kg	ND	2020	2020	1540	1540	77	76	28-110	0	
2,4,6-Trichlorophenol	ug/kg	ND	2020	2020	1380	1330	68	66	17-117	3	
2,4-Dichlorophenol	ug/kg	ND	2020	2020	1420	1390	71	69	21-128	2	
2,4-Dimethylphenol	ug/kg	ND	2020	2020	1410	1130	70	56	10-120	22	
2,4-Dinitrophenol	ug/kg	ND	10100	10100	7750	8570	77	85	10-107	10	
2,4-Dinitrotoluene	ug/kg	ND	2020	2020	1610	1710	80	85	36-109	6	
2,6-Dinitrotoluene	ug/kg	ND	2020	2020	1630	1690	81	84	32-110	4	
2-Chloronaphthalene	ug/kg	ND	2020	2020	1220	1210	61	60	30-107	1	
2-Chlorophenol	ug/kg	ND	2020	2020	1630	1550	81	77	14-106	6	
2-Methylnaphthalene	ug/kg	ND	2020	2020	1450	1470	72	73	10-135	1	
2-Methylphenol(o-Cresol)	ug/kg	ND	2020	2020	1710	1560	85	77	10-124	9	
2-Nitroaniline	ug/kg	ND	4020	4020	3140	3160	78	78	26-116	1	
2-Nitrophenol	ug/kg	ND	2020	2020	1710	1730	85	86	28-103	1	
8&4-Methylphenol(m&p Cresol)	ug/kg	ND	2020	2020	1630	1480	81	74	10-109	10	
3,3'-Dichlorobenzidine	ug/kg	ND	4020	4020	2470	2100	61	52	10-150	16	
B-Nitroaniline	ug/kg	ND	4020	4020	3170	3300	79	82	22-110	4	
I,6-Dinitro-2-methylphenol	ug/kg	ND	4020	4020	2840	3060	71	76	13-121	7	
I-Bromophenylphenyl ether	ug/kg	ND	2020	2020	1570	1530	78	76	31-109	3	
I-Chloro-3-methylphenol	ug/kg	ND	4020	4020	3130	3030	78	75	13-128	3	
I-Chloroaniline	ug/kg	ND	4020	4020	2800	2650	70	66	18-102	5	



Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176 Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

QUALITY CONTROL DATA

Project: Buzzard Point Lot 13 Sq. 607

Pace Project No.: 92182244

Date: 12/16/2013 01:15 PM

MATRIX SPIKE & MATRIX SPI	KE DUPLICAT	E: 11007			1100723						
			MS	MSD							
_		182244001	Spike	Spike	MS	MSD	MS	MSD	% Rec		_
Parameter	Units	Result	Conc.	Conc.	Result	Result	% Rec	% Rec	Limits	RPD _	Qua
4-Chlorophenylphenyl ether	ug/kg	ND	2020	2020	1590	1560	79	78	29-112	2	
4-Nitroaniline	ug/kg	ND	4020	4020	3410	3620	85	90	16-111	6	
4-Nitrophenol	ug/kg	ND	10100	10100	6180	6590	61	66	14-135	6	
Acenaphthene	ug/kg	ND	2020	2020	1490	1470	74	73	26-114	1	
Acenaphthylene	ug/kg	ND	2020	2020	1540	1520	77	76	32-108	1	
Aniline	ug/kg	ND	2020	2020	461	242J	23	12	10-107		
Anthracene	ug/kg	ND	2020	2020	1480	1490	74	74	32-111	0	
Benzo(a)anthracene	ug/kg	ND	2020	2020	1430	1400	71	70	25-117	2	
Benzo(a)pyrene	ug/kg	ND	2020	2020	1550	1520	77	75	25-106	2	
Benzo(b)fluoranthene	ug/kg	ND	2020	2020	1470	1410	73	70	24-110	4	
Benzo(g,h,i)perylene	ug/kg	ND	2020	2020	1490	1470	74	73	19-112	1	
Benzo(k)fluoranthene	ug/kg	ND	2020	2020	1380	1400	69	70	24-114	2	
Benzoic Acid	ug/kg	ND	10100	10100	5590	5720	56	57	10-110	2	
Benzyl alcohol	ug/kg	ND	4020	4020	2900	2740	72	68	24-106	6	
ois(2-Chloroethoxy)methane	ug/kg	ND	2020	2020	1440	1400	71	70	13-119	3	
ois(2-Chloroethyl) ether	ug/kg	ND	2020	2020	1650	1510	82	75	10-134	8	
ois(2-Chloroisopropyl) ether	ug/kg	ND	2020	2020	1460	1430	73	71	10-113	2	
ois(2-Ethylhexyl)phthalate	ug/kg	ND	2020	2020	1330	1330	66	66	10-125	0	
Butylbenzylphthalate	ug/kg	ND	2020	2020	1370	1360	68	67	18-110	1	
Chrysene	ug/kg	ND	2020	2020	1550	1510	77	75	30-110	2	
Di-n-butylphthalate	ug/kg	ND	2020	2020	1300	1290	64	64	19-112	0	
Di-n-octylphthalate	ug/kg	ND	2020	2020	1270	1260	63	63	17-105	1	
Dibenz(a,h)anthracene	ug/kg	ND	2020	2020	1560	1540	78	76	23-111	1	
Dibenzofuran	ug/kg	ND	2020	2020	1270	1280	63	64	35-103	1	
Diethylphthalate	ug/kg	ND	2020	2020	1330	1360	66	68	27-113	2	
Dimethylphthalate	ug/kg	ND	2020	2020	1350	1340	67	66	26-111	1	
Fluoranthene	ug/kg ug/kg	ND	2020	2020	1470	1510	73	75	33-109	3	
Fluorene	ug/kg ug/kg	ND	2020	2020	1540	1570	77	78	32-113	2	
Hexachloro-1,3-butadiene	ug/kg ug/kg	ND	2020	2020	1150	1100	57	55	16-116	4	
Hexachlorobenzene	ug/kg ug/kg	ND	2020	2020	1350	1310	67	65	27-120	3	
Hexachlorocyclopentadiene	ug/kg ug/kg	ND	2020	2020	1240	1290	62	64	10-108	4	
Hexachloroethane	ug/kg ug/kg	ND	2020	2020	1250	1290	62	61	10-108	3	
ndeno(1,2,3-cd)pyrene		ND	2020	2020	1530	1520	76	75	10-117	3 1	
sophorone	ug/kg ug/kg	ND	2020	2020	1450	1460	76 72	73	28-114	0	
N-Nitroso-di-n-propylamine		ND	2020	2020	1180	1130	59	72 56	27-113	4	
N-Nitrosodimethylamine	ug/kg	ND	2020	2020	1190	1150	59 59	57	10-109	4	
N-Nitrosodimetriylamine	ug/kg	ND	2020	2020	1070	1040		5 <i>7</i>	10-109	•	
N-Nitrosodiphenylamine Naphthalene	ug/kg	ND					53			3	
•	ug/kg	ND ND	2020	2020	1540	1560	77 66	77 65	25-110	1	
Nitrobenzene Pontachlaraphanal	ug/kg	ND	2020	2020	1340	1300	66	65 72	18-114	3	
Pentachlorophenol	ug/kg		4020	4020	2790	2880	69	72 73	10-122	3	
Phenanthrene	ug/kg	ND	2020	2020	1450	1470	72	73	30-114	1	
Phenol	ug/kg	ND	2020	2020	1490	1360	74	67	11-102	9	
Pyrene	ug/kg	ND	2020	2020	1400	1400	70	69	25-116	1	
2,4,6-Tribromophenol (S)	%						83	79	27-110		
2-Fluorobiphenyl (S)	%						63	61	30-110		
2-Fluorophenol (S)	%						72	66	13-110		
Nitrobenzene-d5 (S)	%						63	63	23-110		



205 East Meadow Road - Suite A Eden, NC 27288 (336)623-8921

Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176

Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078

(704)875-9092

QUALITY CONTROL DATA

Project: Buzzard Point Lot 13 Sq. 607

Pace Project No.: 92182244

Date: 12/16/2013 01:15 PM

MATRIX SPIKE & MATRIX SPIKE DUPLICATE: 1100722 1100723

Parameter	92 ² Units	182244001 Result	MS Spike Conc.	MSD Spike Conc.	MS Result	MSD Result	MS % Rec	MSD % Rec	% Rec Limits	RPD	Qual
Phenol-d6 (S)	%						75	70	22-110		
Terphenyl-d14 (S)	%						67	66	28-110		



205 East Meadow Road - Suite A Eden, NC 27288 (336)623-8921

Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176

Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

QUALITY CONTROL DATA

Project: Buzzard Point Lot 13 Sq. 607

Pace Project No.: 92182244

QC Batch: PMST/6069 Analysis Method: ASTM D2974-87

QC Batch Method: ASTM D2974-87 Analysis Description: Dry Weight/Percent Moisture

Associated Lab Samples: 92182244001

SAMPLE DUPLICATE: 1101897

92182164001 Dup Parameter Units Result RepD Qualifiers

Percent Moisture % 13.1 13.0 1

SAMPLE DUPLICATE: 1101898

Date: 12/16/2013 01:15 PM

ParameterUnits92182259007 ResultDup ResultRPDQualifiersPercent Moisture%26.527.74



Pace Analytical Services, Inc. 205 East Meadow Road - Suite A

Eden, NC 27288 (336)623-8921 Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176 Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

QUALIFIERS

Project: Buzzard Point Lot 13 Sq. 607

Pace Project No.: 92182244

DEFINITIONS

DF - Dilution Factor, if reported, represents the factor applied to the reported data due to changes in sample preparation, dilution of the sample aliquot, or moisture content.

ND - Not Detected at or above adjusted reporting limit.

J - Estimated concentration above the adjusted method detection limit and below the adjusted reporting limit.

MDL - Adjusted Method Detection Limit.

PRL - Pace Reporting Limit.

RL - Reporting Limit.

S - Surrogate

1,2-Diphenylhydrazine (8270 listed analyte) decomposes to Azobenzene.

Consistent with EPA guidelines, unrounded data are displayed and have been used to calculate % recovery and RPD values.

LCS(D) - Laboratory Control Sample (Duplicate)

MS(D) - Matrix Spike (Duplicate)

DUP - Sample Duplicate

RPD - Relative Percent Difference

NC - Not Calculable.

SG - Silica Gel - Clean-Up

U - Indicates the compound was analyzed for, but not detected.

N-Nitrosodiphenylamine decomposes and cannot be separated from Diphenylamine using Method 8270. The result reported for each analyte is a combined concentration.

Acid preservation may not be appropriate for 2-Chloroethylvinyl ether, Styrene, and Vinyl chloride.

Pace Analytical is TNI accredited. Contact your Pace PM for the current list of accredited analytes.

TNI - The NELAC Institute.

LABORATORIES

PASI-A Pace Analytical Services - Asheville
PASI-C Pace Analytical Services - Charlotte

ANALYTE QUALIFIERS

Date: 12/16/2013 01:15 PM

L3 Analyte recovery in the laboratory control sample (LCS) exceeded QC limits. Analyte presence below reporting limits in associated samples. Results unaffected by high bias.

M1 Matrix spike recovery exceeded QC limits. Batch accepted based on laboratory control sample (LCS) recovery.

R1 RPD value was outside control limits.



(336)623-8921

Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176 Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

QUALITY CONTROL DATA CROSS REFERENCE TABLE

Project: Buzzard Point Lot 13 Sq. 607

Pace Project No.: 92182244

Date: 12/16/2013 01:15 PM

Lab ID	Sample ID	QC Batch Method	QC Batch	Analytical Method	Analytical Batch
92182244001	GTW607-13-1-3	EPA 3546	OEXT/25067	EPA 8015 Modified	GCSV/16182
92182244001	GTW607-13-1-3	EPA 5035A/5030B	GCV/7587	EPA 8015 Modified	GCV/7588
92182244001	GTW607-13-1-3	EPA 3050	MPRP/14857	EPA 6010	ICP/13491
92182244001	GTW607-13-1-3	EPA 7471	MERP/5938	EPA 7471	MERC/5737
92182244001	GTW607-13-1-3	EPA 3546	OEXT/25076	EPA 8270	MSSV/8534
92182244001	GTW607-13-1-3	EPA 8260	MSV/25200		
92182244001	GTW607-13-1-3	ASTM D2974-87	PMST/6069		

Document Revised, December **Document Name:** Page 1 of 2 Sample Condition Upon Receipt (SCUR) Issuing Authority: Pace Analytical **Document Number:** Pace Huntersville Quality Office F-CHR-CS-03-rev.12 Client Name: Haley Aldrich Richmond, VA Huntersville Asheville Raleigh Eden Where Received: Optional Courier: Fed Ex UPS USPS Client Commercial Pace Other Proj. Due Date: Seals intact: yes no Custody Seal on Cooler/Box Present: yes no Proj. Name: Packing Material: Bubble Wrap Bubble Bags None Other Samples on ice, cooling process has begun Blue None Type of Ice: Wet) Thermometer Used: IR Gun T1102 71301 T1301: No Correction T1102: No Correction **Temp Correction Factor** Date and Initials of person examining Biological Tissue is Frozen: Yes No NA contents: (0 12/6/13 С Corrected Cooler Temp.: Comments: Temp should be above freezing to 6°C ☑Yes ☐No □N/A 1. Chain of Custody Present: ✓Yes □No □N/A Chain of Custody Filled Out: ∐Yes □No □N/A 3. Chain of Custody Relinquished: □N/A ☑Yes ☐No Sampler Name & Signature on COC: ✓Yes □No □N/A Samples Arrived within Hold Time: ☐Yes ☑No □N/A Short Hold Time Analysis (<72hr): ☑Yes ☐No $\square N/A \mid 7$ Rush Turn Around Time Requested: □N/A 8. ☑Yes ☐No Sufficient Volume: Yes □No □N/A 9. Correct Containers Used: ☑Yes ☐No □N/A -Pace Containers Used: Yes \Quad No \Quad N/A 110. Containers Intact: N/A 11. ☐Yes ☐No Filtered volume received for Dissolved tests ☑Yes ☐No □N/A 12. Sample Labels match COC: -Includes date/time/ID/Analysis All containers needing preservation have been checked. □Yes □No ☑N/A 13. All containers needing preservation are found to be in ☑N/A ☐Yes ☐No compliance with EPA recommendation. ☐Yes ☐No exceptions: VOA, coliform, TOC, O&G, WI-DRO (water) □N/A 14. ☐Yes ☐No Samples checked for dechlorination: ☑N/A 15. ☐Yes ☐No Headspace in VOA Vials (>6mm): ØN/A 16. □Yes □No Trip Blank Present: □Yes □No /□N/A Trip Blank Custody Seals Present

Client Notification/ Resolution:

Pace Trip Blank Lot # (if purchased):

Field Data Required?

Y / 1

Person Contacted:

___Date/Time: __

SCURF Review:

Comments/ Resolution:

SRF Review: 14

Date:

12/4/13

Note: Whenever there is a discrepancy affecting North Carolina compliance samples, a copy of this form will be sent to the North Carolina DEHNR Certification Office (i.e. out of hold, incorrect preservative, out of temp,

incorrect containers)

WO#: 92182244



Fax	Phone	92182
(703)366-4699	(703) 356-4699	244

L			Time		Date	D		ie	Time			Jate
_	,				Firm	Ħ						mur.
					Print	Pr						rint
	ection below.	If YES, please explain in section below.	TE		gn	Sign						sign
	nperd with? YES (10)	Evidence samples were tamperd with?	E		Received by	R					Relinquished by	Reling
<u> </u>			Time		Date	Ď		ne	Time			Date
		Sodium Bisulfate	Н		Firm	Fi						uni
		Methanol	G		Print	Pr						rint
1_		HCL	127		Sign	S						Sign
		H ₂ SO ₄	E		Received by	R					Relinquished by	Relino
<u></u>		HNO,	Time (115 5.9° D		Date JUan 3	D	16:00		Time		12/5/13	Date
			С		Firm Vo-	Ŧ			ر	41d1.04	Haler + Aldrich	Firm
		Sample filtered	В		Print	- 29				50/EU	Denalor Sesentes	Print
<u> </u>	Discard remaining samples not listed for analysis above.	Sample chilled	A	11 11 m	Sign Tack im	S				-	grill Karel	Sign
<u>L</u>	Sampling Comments	PRESERVATION KEY			Received by	R			Seslin	4	Sampled and Relinquished by	Samp
<u></u>						_						
···												
<u></u>							<u></u> -					
						-						
<u> </u>								:				
<u> </u>	OF Souls COI	G/H/A	VOCs, TPH-GRO/DRO, SVOCs, PP-metals		s/4oz 7/3	VOAs/4oz	Soil	10-15	10:05	12/5/2013	GTW607-13-1- 3	GTW
	Comments - (special instructions, precautions, additional method numbers, etc.)	Preservatives	Analysis Requested	of liners	Container No. of Size Containers		Туре	Depth	Time	Date	Sample No.	
	DELIVERY DATE 12/16/2013	ı	PROJECT MANAGER Greg Grose	ECT MANA	PROJ	į			Don Seserko	D	H&A CONTACT	Н&А
	3		9800 Kincey Ave, Ste 100 Huntersville, NC 28078	ÆSS	_ ADDRESS		square 607	Buzzard Point (Lot 13, Square 607)	ızzard Poir	밀	PROJECT NAME	PRO
	DELIVERY DATE 12/6/2013		Pace Analytical Services, Inc.	LABORATORY	LABC	-			40223-002	40:	H&A FILE NO	H&A
Page 2	Ą	RECOR	CHAIN OF CUSTODY RECORD	AIN	СН		, Suite 870	Haley & Aldrich, Inc. 7926 Jones Branch Drive, Suite 870 McLean, VA 22102	Haley & Aldrich, Inc. 7926 Jones Branch Dr McLean, VA 22102	Ha 792 Mo	HALEY & ALDRICH	
8 of 28	4218124											



Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176 Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

December 20, 2013

Greg Grose Haley & Aldrich, Inc. 7926 Jones Beach Drive Suite 870 Mc Lean, VA 22102

RE: Project: Buzzard Point Lot 13, Sq 607

Pace Project No.: 92182243

Dear Greg Grose:

Enclosed are the analytical results for sample(s) received by the laboratory on December 06, 2013. The results relate only to the samples included in this report. Results reported herein conform to the most current TNI standards and the laboratory's Quality Assurance Manual, where applicable, unless otherwise noted in the body of the report.

Analyses were performed at the Pace Analytical Services location indicated on the sample analyte page for analysis unless otherwise footnoted.

If you have any questions concerning this report, please feel free to contact me.

Sincerely,

Kevin Herring

Kein Slern

kevin.herring@pacelabs.com Project Manager

Enclosures





205 East Meadow Road - Suite A Eden, NC 27288 (336)623-8921

Pace Analytical Services, Inc.

2225 Riverside Dr. Asheville, NC 28804 (828)254-7176

Pace Analytical Services, Inc.

9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

CERTIFICATIONS

Project: Buzzard Point Lot 13, Sq 607

Pace Project No.: 92182243

Charlotte Certification IDs

9800 Kincey Ave. Ste 100, Huntersville, NC 28078 North Carolina Drinking Water Certification #: 37706 North Carolina Field Services Certification #: 5342 North Carolina Wastewater Certification #: 12 South Carolina Certification #: 99006001 Florida/NELAP Certification #: E87627 Kentucky UST Certification #: 84 West Virginia Certification #: 357 Virginia/VELAP Certification #: 460221

Asheville Certification IDs

2225 Riverside Dr., Asheville, NC 28804 Florida/NELAP Certification #: E87648 Massachusetts Certification #: M-NC030

North Carolina Drinking Water Certification #: 37712

North Carolina Wastewater Certification #: 40 South Carolina Certification #: 99030001 West Virginia Certification #: 356 Virginia/VELAP Certification #: 460222



Pace Analytical Services, Inc. 205 East Meadow Road - Suite A

Eden, NC 27288 (336)623-8921

Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176

Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

SAMPLE ANALYTE COUNT

Project: Buzzard Point Lot 13, Sq 607

Pace Project No.: 92182243

Lab ID	Sample ID	Method	Analysts	Analytes Reported	Laboratory	
92182243001	GTW607-13-2-2	EPA 8015 Modified	NU1	2	PASI-C	
		EPA 8015 Modified	GAW	2	PASI-C	
		EPA 6010	JMW	12	PASI-A	
		EPA 7471	MTS	1	PASI-A	
		EPA 8270	BPJ	74	PASI-C	
		EPA 8260	DLK	70	PASI-C	
		ASTM D2974-87	TNM	1	PASI-C	
92182243002	GSS607-13-3-1	EPA 8015 Modified	NU1	2	PASI-C	
		EPA 8015 Modified	GAW	2	PASI-C	
		EPA 8260	DLK	10	PASI-C	
		ASTM D2974-87	TNM	1	PASI-C	



205 East Meadow Road - Suite A Eden, NC 27288 (336)623-8921

Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176

Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

SUMMARY OF DETECTION

Project: Buzzard Point Lot 13, Sq 607

Pace Project No.: 92182243

Lab Sample ID Method	Client Sample ID Parameters	Result	Units	Report Limit	Analyzed	Qualifiers
92182243001	GTW607-13-2-2			_		
EPA 8015 Modified	Diesel Components	119 r	ng/kg	6.3	12/08/13 23:44	
EPA 6010	Arsenic		ng/kg	1.1	12/09/13 19:15	
EPA 6010	Beryllium	0.50 r	ng/kg	0.11	12/09/13 19:15	
EPA 6010	Chromium	10.3 r	ng/kg	0.54	12/09/13 19:15	
EPA 6010	Copper	37.9 r	ng/kg	0.54	12/09/13 19:15	
EPA 6010	Lead	170 r		0.54	12/09/13 19:15	
EPA 6010	Nickel		ng/kg	0.54	12/09/13 19:15	
EPA 6010	Zinc	78.5 r	ng/kg	1.1	12/09/13 19:15	
EPA 7471	Mercury		ng/kg	0.58	12/09/13 18:57	
EPA 8270	Anthracene	4720 u		4180	12/09/13 15:59	
EPA 8270	Benzo(a)anthracene	8620 เ		4180	12/09/13 15:59	
EPA 8270	Benzo(a)pyrene	8670 เ		4180	12/09/13 15:59	
EPA 8270	Benzo(b)fluoranthene	7660 u	ıg/kg	4180	12/09/13 15:59	
EPA 8270	Benzo(g,h,i)perylene	5030 เ		4180	12/09/13 15:59	
EPA 8270	Benzo(k)fluoranthene	6210 t	ıg/kg	4180	12/09/13 15:59	
EPA 8270	Chrysene	9860 ເ		4180	12/09/13 15:59	
EPA 8270	Fluoranthene	21000 ເ	ıg/kg	4180	12/09/13 15:59	
EPA 8270	Indeno(1,2,3-cd)pyrene	4610 u	ıg/kg	4180	12/09/13 15:59	
EPA 8270	Phenanthrene	18600 ເ	ıg/kg	4180	12/09/13 15:59	
EPA 8270	Pyrene	17600 เ		4180	12/09/13 15:59	
ASTM D2974-87	Percent Moisture	21.0 9		0.10	12/11/13 14:14	
92182243002	GSS607-13-3-1					
EPA 8015 Modified	Diesel Components	184 r	ng/kg	5.6	12/09/13 00:07	
ASTM D2974-87	Percent Moisture	10.3 9	6	0.10	12/11/13 14:14	



Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176 Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

ANALYTICAL RESULTS

Project: Buzzard Point Lot 13, Sq 607

Pace Project No.: 92182243

Date: 12/20/2013 11:21 AM

Lab ID: 92182243001 Sample: GTW607-13-2-2 Collected: 12/05/13 12:55 Received: 12/06/13 11:15 Matrix: Solid Results reported on a "dry-weight" basis **Parameters** Results Units Report Limit DF Prepared Analyzed CAS No. Qual 8015 GCS THC-Diesel Analytical Method: EPA 8015 Modified Preparation Method: EPA 3546 **Diesel Components** 119 mg/kg 6.3 12/06/13 15:15 12/08/13 23:44 68334-30-5 Surrogates 101 % 41-119 n-Pentacosane (S) 12/06/13 15:15 12/08/13 23:44 629-99-2 Analytical Method: EPA 8015 Modified Preparation Method: EPA 5035A/5030B **Gasoline Range Organics** Gasoline Range Organics 7.7 12/09/13 15:05 12/10/13 05:30 8006-61-9 ND mg/kg 1 Surrogates 4-Bromofluorobenzene (S) 85 % 70-167 12/09/13 15:05 12/10/13 05:30 460-00-4 **6010 MET ICP** Analytical Method: EPA 6010 Preparation Method: EPA 3050 0.54 **Antimony** ND mg/kg 1 12/07/13 09:25 12/09/13 19:15 7440-36-0 Arsenic 4.8 mg/kg 1.1 12/07/13 09:25 12/09/13 19:15 7440-38-2 1 Beryllium 0.50 mg/kg 0.11 1 12/07/13 09:25 12/09/13 19:15 7440-41-7 Cadmium ND mg/kg 0.11 1 12/07/13 09:25 12/09/13 19:15 7440-43-9 Chromium 10.3 mg/kg 0.54 12/07/13 09:25 12/09/13 19:15 7440-47-3 1 Copper 37.9 mg/kg 0.54 12/07/13 09:25 12/09/13 19:15 7440-50-8 1 Lead 170 mg/kg 0.54 12/07/13 09:25 12/09/13 19:15 7439-92-1 1 Nickel **6.9** mg/kg 0.54 12/07/13 09:25 12/09/13 19:15 7440-02-0 1 Selenium ND mg/kg 12/07/13 09:25 12/09/13 19:15 7782-49-2 1.1 1 Silver ND mg/kg 0.54 1 12/07/13 09:25 12/09/13 19:15 7440-22-4 Thallium ND mg/kg 1.1 1 12/07/13 09:25 12/09/13 19:15 7440-28-0 Zinc 78.5 mg/kg 1.1 1 12/07/13 09:25 12/09/13 19:15 7440-66-6 7471 Mercury Analytical Method: EPA 7471 Preparation Method: EPA 7471 Mercury 4.0 mg/kg 0.58 120 12/09/13 16:00 12/09/13 18:57 7439-97-6 8270 MSSV Microwave Analytical Method: EPA 8270 Preparation Method: EPA 3546 4180 12/06/13 20:26 12/09/13 15:59 83-32-9 Acenaphthene ND ug/kg 10 Acenaphthylene ND ug/kg 4180 10 12/06/13 20:26 12/09/13 15:59 208-96-8 Aniline ND ug/kg 4180 10 12/06/13 20:26 12/09/13 15:59 62-53-3 4720 ug/kg 4180 Anthracene 10 12/06/13 20:26 12/09/13 15:59 120-12-7 Benzo(a)anthracene 8620 ug/kg 4180 10 12/06/13 20:26 12/09/13 15:59 56-55-3 Benzo(a)pyrene 8670 ug/kg 4180 10 12/06/13 20:26 12/09/13 15:59 50-32-8 Benzo(b)fluoranthene 7660 ug/kg 4180 10 12/06/13 20:26 12/09/13 15:59 205-99-2 Benzo(g,h,i)perylene 5030 ug/kg 4180 10 12/06/13 20:26 12/09/13 15:59 191-24-2 Benzo(k)fluoranthene 6210 ug/kg 4180 10 12/06/13 20:26 12/09/13 15:59 207-08-9 Benzoic Acid ND ug/kg 20900 10 12/06/13 20:26 12/09/13 15:59 65-85-0 Benzyl alcohol ND ug/kg 8350 10 12/06/13 20:26 12/09/13 15:59 100-51-6 4-Bromophenylphenyl ether ND ug/kg 4180 10 12/06/13 20:26 12/09/13 15:59 101-55-3 Butylbenzylphthalate ND ug/kg 4180 10 12/06/13 20:26 12/09/13 15:59 85-68-7 4-Chloro-3-methylphenol ND ug/kg 8350 10 12/06/13 20:26 12/09/13 15:59 59-50-7 ND ug/kg 20900 4-Chloroaniline 10 12/06/13 20:26 12/09/13 15:59 106-47-8 ND ug/kg 4180 bis(2-Chloroethoxy)methane 10 12/06/13 20:26 12/09/13 15:59 111-91-1 bis(2-Chloroethyl) ether ND ug/kg 4180 10 12/06/13 20:26 12/09/13 15:59 111-44-4 ND ug/kg 4180 10 12/06/13 20:26 12/09/13 15:59 108-60-1 bis(2-Chloroisopropyl) ether



Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176 Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

ANALYTICAL RESULTS

Project: Buzzard Point Lot 13, Sq 607

Pace Project No.: 92182243

Date: 12/20/2013 11:21 AM

Sample: GTW607-13-2-2 Lab ID: 92182243001 Collected: 12/05/13 12:55 Received: 12/06/13 11:15 Matrix: Solid

Results reported on a "dry-weight	Dasis							
Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qua
8270 MSSV Microwave	Analytical Meth	nod: EPA 827	0 Preparation Meth	nod: EF	°A 3546			
2-Chloronaphthalene	ND ug	/kg	4180	10	12/06/13 20:26	12/09/13 15:59	91-58-7	
2-Chlorophenol	ND ug	/kg	4180	10	12/06/13 20:26	12/09/13 15:59	95-57-8	
4-Chlorophenylphenyl ether	ND ug	-	4180	10	12/06/13 20:26	12/09/13 15:59	7005-72-3	
Chrysene	9860 ug	•	4180	10	12/06/13 20:26	12/09/13 15:59	218-01-9	
Dibenz(a,h)anthracene	ND ug	•	4180	10	12/06/13 20:26	12/09/13 15:59	53-70-3	
Dibenzofuran	ND ug		4180	10	12/06/13 20:26	12/09/13 15:59	132-64-9	
1,2-Dichlorobenzene	ND ug	-	4180	10		12/09/13 15:59		
,3-Dichlorobenzene	ND ug	-	4180	10		12/09/13 15:59		
I,4-Dichlorobenzene	ND ug	•	4180	10		12/09/13 15:59		
3,3'-Dichlorobenzidine	ND ug	-	20900	10		12/09/13 15:59		
2,4-Dichlorophenol	ND ug		4180	10		12/09/13 15:59		
Diethylphthalate	ND ug	-	4180	10		12/09/13 15:59		
2,4-Dimethylphenol	ND ug	-	4180	10		12/09/13 15:59		
Dimethylphthalate	ND ug	•	4180	10		12/09/13 15:59		
Di-n-butylphthalate	ND ug	-	4180	10		12/09/13 15:59		
I,6-Dinitro-2-methylphenol	ND ug	-	8350	10		12/09/13 15:59		
2,4-Dinitro-2-metryiphenoi	_	-	20900			12/09/13 15:59		
•	ND ug	-		10				
,4-Dinitrotoluene	ND ug	•	4180	10		12/09/13 15:59		
,6-Dinitrotoluene	ND ug	-	4180	10		12/09/13 15:59		
i-n-octylphthalate	ND ug		4180	10		12/09/13 15:59		
is(2-Ethylhexyl)phthalate	ND ug	-	4180	10		12/09/13 15:59		
luoranthene	21000 ug	•	4180	10		12/09/13 15:59		
luorene	ND ug	•	4180	10		12/09/13 15:59		
lexachloro-1,3-butadiene	ND ug	-	4180	10		12/09/13 15:59		
lexachlorobenzene	ND ug	-	4180	10		12/09/13 15:59		
lexachlorocyclopentadiene	ND ug	-	4180	10	12/06/13 20:26	12/09/13 15:59	77-47-4	
lexachloroethane	ND ug		4180	10	12/06/13 20:26	12/09/13 15:59	67-72-1	
ndeno(1,2,3-cd)pyrene	4610 ug	/kg	4180	10	12/06/13 20:26	12/09/13 15:59	193-39-5	
sophorone	ND ug	/kg	4180	10	12/06/13 20:26	12/09/13 15:59	78-59-1	
-Methylnaphthalene	ND ug	/kg	4180	10	12/06/13 20:26	12/09/13 15:59	90-12-0	
?-Methylnaphthalene	ND ug	/kg	4180	10	12/06/13 20:26	12/09/13 15:59	91-57-6	
-Methylphenol(o-Cresol)	ND ug	/kg	4180	10	12/06/13 20:26	12/09/13 15:59	95-48-7	
&4-Methylphenol(m&p Cresol)	ND ug	/kg	4180	10	12/06/13 20:26	12/09/13 15:59		
laphthalene	ND ug	/kg	4180	10	12/06/13 20:26	12/09/13 15:59	91-20-3	
-Nitroaniline	ND ug	/kg	20900	10	12/06/13 20:26	12/09/13 15:59	88-74-4	
-Nitroaniline	ND ug	/kg	20900	10	12/06/13 20:26	12/09/13 15:59	99-09-2	
-Nitroaniline	ND ug	-	8350	10	12/06/13 20:26	12/09/13 15:59	100-01-6	
litrobenzene	ND ug		4180	10	12/06/13 20:26	12/09/13 15:59	98-95-3	
-Nitrophenol	ND ug	•	4180	10		12/09/13 15:59		
-Nitrophenol	ND ug		20900	10		12/09/13 15:59		
I-Nitrosodimethylamine	ND ug	•	4180	10		12/09/13 15:59		
I-Nitroso-di-n-propylamine	ND ug	J	4180	10		12/09/13 15:59		
I-Nitrosodiphenylamine	ND ug	•	4180	10		12/09/13 15:59		
Pentachlorophenol	ND ug	-	20900	10		12/09/13 15:59		
Phenanthrene	18600 ug	-	4180	10		12/09/13 15:59		
Phenol	ND ug	-	4180	10		12/09/13 15:59		



Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176 Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

ANALYTICAL RESULTS

Project: Buzzard Point Lot 13, Sq 607

Pace Project No.: 92182243

Date: 12/20/2013 11:21 AM

Sample: GTW607-13-2-2 Lab ID: 92182243001 Collected: 12/05/13 12:55 Received: 12/06/13 11:15 Matrix: Solid

Results reported on a "dry-weight" basis

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qu:
3270 MSSV Microwave	Analytical Metho	od: EPA 8270	Preparation Met	hod: EF	PA 3546			
Pyrene	17600 ug/	kg	4180	10	12/06/13 20:26	12/09/13 15:59	129-00-0	
1,2,4-Trichlorobenzene	ND ug/	-	4180	10	12/06/13 20:26	12/09/13 15:59	120-82-1	
2,4,5-Trichlorophenol	ND ug/	-	4180	10	12/06/13 20:26	12/09/13 15:59	95-95-4	
2,4,6-Trichlorophenol	ND ug/	-	4180	10	12/06/13 20:26	12/09/13 15:59	88-06-2	
Surrogates	· ·	Ü						
Nitrobenzene-d5 (S)	0 %		23-110	10	12/06/13 20:26	12/09/13 15:59	4165-60-0	D3,S4
2-Fluorobiphenyl (S)	0 %		30-110	10	12/06/13 20:26	12/09/13 15:59	321-60-8	
Terphenyl-d14 (S)	0 %		28-110	10	12/06/13 20:26	12/09/13 15:59	1718-51-0	
Phenol-d6 (S)	0 %		22-110	10	12/06/13 20:26	12/09/13 15:59	13127-88-3	
2-Fluorophenol (S)	0 %		13-110	10	12/06/13 20:26	12/09/13 15:59	367-12-4	
2,4,6-Tribromophenol (S)	0 %		27-110	10	12/06/13 20:26	12/09/13 15:59	118-79-6	
3260/5035A Volatile Organics	Analytical Meth	od: EPA 8260)					
Acetone	ND ug/	'ka	123	1		12/12/13 23:02	67-64-1	
Benzene	ND ug/	•	6.1	1		12/12/13 23:02		
Bromobenzene	ND ug/l		6.1	1		12/12/13 23:02		
Bromochloromethane	ND ug/l	-	6.1	1		12/12/13 23:02		
Bromodichloromethane	ND ug/	· ·	6.1	1		12/12/13 23:02		
Bromoform	ND ug/l	-	6.1	1		12/12/13 23:02		
Bromomethane	ND ug/l	-	12.3	1		12/12/13 23:02		
2-Butanone (MEK)	ND ug/l	-	12.3	1		12/12/13 23:02		
, ,	_	-		1				
n-Butylbenzene	ND ug/	-	6.1	1		12/12/13 23:02		
sec-Butylbenzene	ND ug/	-	6.1			12/12/13 23:02		
ert-Butylbenzene	ND ug/	-	6.1	1		12/12/13 23:02		
Carbon tetrachloride	ND ug/	-	6.1	1		12/12/13 23:02		
Chlorobenzene	ND ug/	-	6.1	1		12/12/13 23:02		
Chloroethane	ND ug/		12.3	1		12/12/13 23:02		
Chloroform	ND ug/		6.1	1		12/12/13 23:02		
Chloromethane	ND ug/	-	12.3	1		12/12/13 23:02		
2-Chlorotoluene	ND ug/	-	6.1	1		12/12/13 23:02		
I-Chlorotoluene	ND ug/	-	6.1	1		12/12/13 23:02		
,2-Dibromo-3-chloropropane	ND ug/	-	6.1	1		12/12/13 23:02	96-12-8	
Dibromochloromethane	ND ug/		6.1	1		12/12/13 23:02		
I,2-Dibromoethane (EDB)	ND ug/	-	6.1	1		12/12/13 23:02		
Dibromomethane	ND ug/	-	6.1	1		12/12/13 23:02	74-95-3	
1,2-Dichlorobenzene	ND ug/	kg	6.1	1		12/12/13 23:02	95-50-1	
1,3-Dichlorobenzene	ND ug/	kg	6.1	1		12/12/13 23:02	541-73-1	
,4-Dichlorobenzene	ND ug/	kg	6.1	1		12/12/13 23:02	106-46-7	
Dichlorodifluoromethane	ND ug/	kg	12.3	1		12/12/13 23:02	75-71-8	
,1-Dichloroethane	ND ug/	kg	6.1	1		12/12/13 23:02	75-34-3	
,2-Dichloroethane	ND ug/	kg	6.1	1		12/12/13 23:02	107-06-2	
,1-Dichloroethene	ND ug/	•	6.1	1		12/12/13 23:02	75-35-4	
is-1,2-Dichloroethene	ND ug/	-	6.1	1		12/12/13 23:02	156-59-2	
rans-1,2-Dichloroethene	ND ug/		6.1	1		12/12/13 23:02		
1,2-Dichloropropane	ND ug/	-	6.1	1		12/12/13 23:02		
1,3-Dichloropropane	ND ug/	-	6.1	1		12/12/13 23:02		



Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176 Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

ANALYTICAL RESULTS

Project: Buzzard Point Lot 13, Sq 607

Pace Project No.: 92182243

Date: 12/20/2013 11:21 AM

Sample: GTW607-13-2-2 Lab ID: 92182243001 Collected: 12/05/13 12:55 Received: 12/06/13 11:15 Matrix: Solid

Results reported on a "dry-weight" basis

Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qua
8260/5035A Volatile Organics	Analytical Met	hod: EPA 8260)					
2,2-Dichloropropane	ND ug	ı/kg	6.1	1		12/12/13 23:02	594-20-7	
1,1-Dichloropropene	ND ug	ı/kg	6.1	1		12/12/13 23:02	563-58-6	
cis-1,3-Dichloropropene	ND ug	ı/kg	6.1	1		12/12/13 23:02	10061-01-5	
trans-1,3-Dichloropropene	ND ug	ı/kg	6.1	1		12/12/13 23:02	10061-02-6	
Diisopropyl ether	ND ug	-	6.1	1		12/12/13 23:02	108-20-3	
Ethylbenzene	ND ug	ı/kg	6.1	1		12/12/13 23:02	100-41-4	
Hexachloro-1,3-butadiene	ND ug	/kg	6.1	1		12/12/13 23:02	87-68-3	
2-Hexanone	ND ug	/kg	61.3	1		12/12/13 23:02	591-78-6	
sopropylbenzene (Cumene)	ND ug		6.1	1		12/12/13 23:02	98-82-8	
p-Isopropyltoluene	ND ug	, ,	6.1	1		12/12/13 23:02		
Methylene Chloride	ND ug		24.5	1		12/12/13 23:02		
4-Methyl-2-pentanone (MIBK)	ND ug	•	61.3	1		12/12/13 23:02		
Methyl-tert-butyl ether	ND ug		6.1	1		12/12/13 23:02		
Naphthalene	ND ug	_	6.1	1		12/12/13 23:02		
n-Propylbenzene	ND ug		6.1	1		12/12/13 23:02		
Styrene	ND ug	_	6.1	1		12/12/13 23:02		
,1,1,2-Tetrachloroethane	ND ug		6.1	1		12/12/13 23:02		
1,1,2,2-Tetrachloroethane	ND ug	, ,	6.1	1		12/12/13 23:02		
Tetrachloroethene	ND ug	, ,	6.1	1		12/12/13 23:02		
Toluene	ND ug	•	6.1	1		12/12/13 23:02		
1,2,3-Trichlorobenzene	ND ug		6.1	1		12/12/13 23:02		
1,2,4-Trichlorobenzene	ND ug	_	6.1	1		12/12/13 23:02		
1,1,1-Trichloroethane	ND ug	•	6.1	1		12/12/13 23:02		
1,1,2-Trichloroethane	ND ug	, ,	6.1	1		12/12/13 23:02		
Trichloroethene	ND ug	, ,	6.1	1		12/12/13 23:02		
Frichlorofluoromethane	ND ug		6.1	1		12/12/13 23:02		
1,2,3-Trichloropropane	ND ug		6.1	1		12/12/13 23:02		
1,2,4-Trimethylbenzene	ND ug	_	6.1	1		12/12/13 23:02		
•	ND ug	, ,	6.1	1		12/12/13 23:02		
1,3,5-Trimethylbenzene			61.3	1				
Vinyl acetate	ND ug		12.3	1		12/12/13 23:02 12/12/13 23:02		
Vinyl chloride	ND ug			1				
Kylene (Total)	ND ug		12.3			12/12/13 23:02		
m&p-Xylene	ND ug		12.3	1		12/12/13 23:02		
o-Xylene	ND ug	укд	6.1	1		12/12/13 23:02	95-47-6	
Surrogates Foluene-d8 (S)	99 %		70-130	1		12/12/13 23:02	2037-26-5	
4-Bromofluorobenzene (S)	99 % 95 %		70-130	1		12/12/13 23:02		
	101 %		70-130 70-132	1				
1,2-Dichloroethane-d4 (S)				ı		12/12/13 23:02	1/000-07-0	
Percent Moisture	Analytical Met	hod: ASTM D2	2974-87					
Percent Moisture	21.0 %		0.10	1		12/11/13 14:14		



Pace Analytical Services, Inc. 205 East Meadow Road - Suite A

Eden, NC 27288 (336)623-8921

Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176

Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

ANALYTICAL RESULTS

Project: Buzzard Point Lot 13, Sq 607

Pace Project No.: 92182243

Date: 12/20/2013 11:21 AM

Lab ID: 92182243002 Sample: GSS607-13-3-1 Collected: 12/05/13 08:57 Received: 12/06/13 11:15 Matrix: Solid Results reported on a "dry-weight" basis **Parameters** Results Units Report Limit DF Prepared Analyzed CAS No. Qual 8015 GCS THC-Diesel Analytical Method: EPA 8015 Modified Preparation Method: EPA 3546 **Diesel Components** 12/06/13 15:15 12/09/13 00:07 68334-30-5 184 mg/kg 5.6 Surrogates 91 % n-Pentacosane (S) 41-119 12/06/13 15:15 12/09/13 00:07 629-99-2 1 Analytical Method: EPA 8015 Modified Preparation Method: EPA 5035A/5030B **Gasoline Range Organics** Gasoline Range Organics ND mg/kg 4.7 12/09/13 15:05 12/10/13 05:53 8006-61-9 1 Surrogates 4-Bromofluorobenzene (S) 84 % 70-167 12/09/13 15:05 12/10/13 05:53 460-00-4 Analytical Method: EPA 8260 8260/5035A Volatile Organics Benzene ND ug/kg 4.6 1 12/12/13 23:22 71-43-2 1g Ethylbenzene ND ug/kg 4.6 1 12/12/13 23:22 100-41-4 Naphthalene ND ug/kg 4.6 1 12/12/13 23:22 91-20-3 Toluene ND ug/kg 4.6 1 12/12/13 23:22 108-88-3 Xylene (Total) ND ug/kg 9.2 1 12/12/13 23:22 1330-20-7 m&p-Xylene ND ug/kg 9.2 12/12/13 23:22 179601-23-1 1 o-Xylene ND ug/kg 4.6 12/12/13 23:22 95-47-6 1 Surrogates Toluene-d8 (S) 96 % 70-130 1 12/12/13 23:22 2037-26-5 4-Bromofluorobenzene (S) 85 % 70-130 12/12/13 23:22 460-00-4 1 1,2-Dichloroethane-d4 (S) 117 % 70-132 1 12/12/13 23:22 17060-07-0 **Percent Moisture** Analytical Method: ASTM D2974-87 Percent Moisture 10.3 % 0.10 12/11/13 14:14 1



205 East Meadow Road - Suite A Eden, NC 27288 (336)623-8921

Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176

Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

QUALITY CONTROL DATA

Project: Buzzard Point Lot 13, Sq 607

Pace Project No.: 92182243

Date: 12/20/2013 11:21 AM

QC Batch: GCV/7586 Analysis Method: EPA 8015 Modified

QC Batch Method: EPA 5035A/5030B Analysis Description: Gasoline Range Organics

Associated Lab Samples: 92182243001, 92182243002

METHOD BLANK: 1101435 Matrix: Solid

Associated Lab Samples: 92182243001, 92182243002

Blank Reporting Limit Qualifiers Parameter Units Result Analyzed Gasoline Range Organics ND 12/09/13 23:27 mg/kg 5.9 4-Bromofluorobenzene (S) % 85 70-167 12/09/13 23:27

LABORATORY CONTROL SAMPLE: 1101436

Spike LCS LCS % Rec Parameter Units Conc. Result % Rec Limits Qualifiers Gasoline Range Organics mg/kg 49.5 50.2 101 70-165 4-Bromofluorobenzene (S) 90 70-167 %

MATRIX SPIKE & MATRIX SPIKE DUPLICATE: 1101437 1101438 MS MSD

92182099007 Spike Spike MS MSD MS MSD % Rec Parameter Units Result Conc. Conc. Result Result % Rec % Rec Limits **RPD** Qual ND Gasoline Range Organics mg/kg 50.1 50.1 48.0 47.5 95 94 47-187 4-Bromofluorobenzene (S) % 80 83 70-167

MATRIX SPIKE & MATRIX SPIKE DUPLICATE: 1101439 1101440

MS MSD 92182099008 MS MSD MS Spike Spike MSD % Rec **RPD** Parameter Units Result Conc. Conc. Result Result % Rec % Rec Limits Qual ND 47 Gasoline Range Organics mg/kg 47 45.5 47.1 96 47-187 3 100 4-Bromofluorobenzene (S) % 90 86 70-167



(336)623-8921

Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176 Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

QUALITY CONTROL DATA

Project: Buzzard Point Lot 13, Sq 607

Pace Project No.: 92182243

Date: 12/20/2013 11:21 AM

QC Batch: MERP/5913 Analysis Method: EPA 7471
QC Batch Method: EPA 7471 Analysis Description: 7471 Mercury

Associated Lab Samples: 92182243001

METHOD BLANK: 1101069 Matrix: Solid

Associated Lab Samples: 92182243001

Parameter Units Result Limit Analyzed Qualifiers

Mercury mg/kg ND 0.0050 12/09/13 17:12

LABORATORY CONTROL SAMPLE: 1101070

Spike LCS LCS % Rec Parameter Units Conc. Result % Rec Limits Qualifiers Mercury mg/kg .067 0.059 89 80-120

MATRIX SPIKE & MATRIX SPIKE DUPLICATE: 1101518 1101519

MS MSD 92182021001 Spike Spike MS MSD MS MSD % Rec Parameter Units Result Conc. Conc. Result Result % Rec % Rec Limits RPD Qual ND .078 .072 0.0069 75-125 161 M1,R1 Mercury mg/kg 0.064 81



Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176 Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

QUALITY CONTROL DATA

Project: Buzzard Point Lot 13, Sq 607

Pace Project No.: 92182243

QC Batch: MPRP/14800 Analysis Method: EPA 6010
QC Batch Method: EPA 3050 Analysis Description: 6010 MET

Associated Lab Samples: 92182243001

METHOD BLANK: 1100773 Matrix: Solid

Associated Lab Samples: 92182243001

		Blank	Reporting		
Parameter	Units	Result	Limit	Analyzed	Qualifiers
Antimony	mg/kg	ND	0.50	12/09/13 18:46	
Arsenic	mg/kg	ND	1.0	12/09/13 18:46	
Beryllium	mg/kg	ND	0.10	12/09/13 18:46	
Cadmium	mg/kg	ND	0.10	12/09/13 18:46	
Chromium	mg/kg	ND	0.50	12/09/13 18:46	
Copper	mg/kg	ND	0.50	12/09/13 18:46	
Lead	mg/kg	ND	0.50	12/09/13 18:46	
Nickel	mg/kg	ND	0.50	12/09/13 18:46	
Selenium	mg/kg	ND	1.0	12/09/13 18:46	
Silver	mg/kg	ND	0.50	12/09/13 18:46	
Thallium	mg/kg	ND	1.0	12/09/13 18:46	
Zinc	mg/kg	ND	1.0	12/09/13 18:46	

Date: 12/20/2013 11:21 AM

		Spike	LCS	LCS	% Rec	
Parameter	Units	Conc.	Result	% Rec	Limits	Qualifiers
Antimony	mg/kg	50	50.0	100	80-120	
Arsenic	mg/kg	50	49.2	98	80-120	
Beryllium	mg/kg	50	48.9	98	80-120	
Cadmium	mg/kg	50	49.5	99	80-120	
Chromium	mg/kg	50	49.8	100	80-120	
Copper	mg/kg	50	48.9	98	80-120	
Lead	mg/kg	50	49.0	98	80-120	
Nickel	mg/kg	50	50.1	100	80-120	
Selenium	mg/kg	50	48.9	98	80-120	
Silver	mg/kg	25	24.9	100	80-120	
Thallium	mg/kg	50	48.1	96	80-120	
Zinc	mg/kg	50	50.0	100	80-120	

MATRIX SPIKE & MATRIX SF	PIKE DUPLICAT	E: 11007	75		1100776						
			MS	MSD							
	92	182021001	Spike	Spike	MS	MSD	MS	MSD	% Rec		
Parameter	Units	Result	Conc.	Conc.	Result	Result	% Rec	% Rec	Limits	RPD	Qual
Antimony	mg/kg	ND	60.6	61.8	56.1	57.8	93	94	75-125	3	
Arsenic	mg/kg	1.5	60.6	61.8	62.1	61.5	100	97	75-125	1	
Beryllium	mg/kg	0.47	60.6	61.8	59.1	60.7	97	97	75-125	3	
Cadmium	mg/kg	ND	60.6	61.8	57.8	58.8	95	95	75-125	2	
Chromium	mg/kg	2.5	60.6	61.8	62.1	62.4	98	97	75-125	1	
Copper	mg/kg	6.9	60.6	61.8	67.5	67.1	100	97	75-125	1	
Lead	mg/kg	1.2	60.6	61.8	56.8	58.4	92	93	75-125	3	



Pace Analytical Services, Inc. 205 East Meadow Road - Suite A

Eden, NC 27288 (336)623-8921 Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176 Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

QUALITY CONTROL DATA

Project: Buzzard Point Lot 13, Sq 607

Pace Project No.: 92182243

Date: 12/20/2013 11:21 AM

MATRIX SPIKE & MATRIX S	SPIKE DUPLICAT	E: 11007	75		1100776						
Parameter	92 [.] Units	182021001 Result	MS Spike Conc.	MSD Spike Conc.	MS Result	MSD Result	MS % Rec	MSD % Rec	% Rec	RPD	Qual
Faiailletei	UIIIIS	- Mesuit		COIIC.	Nesuit		/0 KeC	/0 KeC		— —	Quai
Nickel	mg/kg	4.6	60.6	61.8	64.7	64.5	99	97	75-125	0	
Selenium	mg/kg	ND	60.6	61.8	57.4	59.7	94	96	75-125	4	
Silver	mg/kg	ND	30.3	30.8	29.9	30.5	98	98	75-125	2	
Thallium	mg/kg	ND	60.6	61.8	43.4	46.1	72	75	75-125	6 M1	
Zinc	mg/kg	3.2	60.6	61.8	63.5	65.1	99	100	75-125	2	



Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176 Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

QUALITY CONTROL DATA

Project: Buzzard Point Lot 13, Sq 607

Pace Project No.: 92182243

Date: 12/20/2013 11:21 AM

QC Batch: MSV/25200 Analysis Method: EPA 8260

QC Batch Method: EPA 8260 Analysis Description: 8260 MSV 5035A Volatile Organics

Associated Lab Samples: 92182243001, 92182243002

METHOD BLANK: 1102369 Matrix: Solid

Associated Lab Samples: 92182243001, 92182243002

Parameter	Units	Blank Result	Reporting Limit	Analyzed	Qualifiers
1,1,1,2-Tetrachloroethane	ug/kg	ND	5.0	12/12/13 18:27	
1,1,1-Trichloroethane	ug/kg	ND	5.0	12/12/13 18:27	
1,1,2,2-Tetrachloroethane	ug/kg	ND	5.0	12/12/13 18:27	
1,1,2-Trichloroethane	ug/kg	ND	5.0	12/12/13 18:27	
1,1-Dichloroethane	ug/kg	ND	5.0	12/12/13 18:27	
1,1-Dichloroethene	ug/kg	ND	5.0	12/12/13 18:27	
1,1-Dichloropropene	ug/kg	ND	5.0	12/12/13 18:27	
1,2,3-Trichlorobenzene	ug/kg	ND	5.0	12/12/13 18:27	
1,2,3-Trichloropropane	ug/kg	ND	5.0	12/12/13 18:27	
1,2,4-Trichlorobenzene	ug/kg	ND	5.0	12/12/13 18:27	
1,2,4-Trimethylbenzene	ug/kg	ND	5.0	12/12/13 18:27	
1,2-Dibromo-3-chloropropane	ug/kg	ND	5.0	12/12/13 18:27	
1,2-Dibromoethane (EDB)	ug/kg	ND	5.0	12/12/13 18:27	
1,2-Dichlorobenzene	ug/kg	ND	5.0	12/12/13 18:27	
1,2-Dichloroethane	ug/kg	ND	5.0	12/12/13 18:27	
1,2-Dichloropropane	ug/kg	ND	5.0	12/12/13 18:27	
1,3,5-Trimethylbenzene	ug/kg	ND	5.0	12/12/13 18:27	
1,3-Dichlorobenzene	ug/kg	ND	5.0	12/12/13 18:27	
1,3-Dichloropropane	ug/kg	ND	5.0	12/12/13 18:27	
1,4-Dichlorobenzene	ug/kg	ND	5.0	12/12/13 18:27	
2,2-Dichloropropane	ug/kg	ND	5.0	12/12/13 18:27	
2-Butanone (MEK)	ug/kg	ND	99.6	12/12/13 18:27	
2-Chlorotoluene	ug/kg	ND	5.0	12/12/13 18:27	
2-Hexanone	ug/kg	ND	49.8	12/12/13 18:27	
4-Chlorotoluene	ug/kg	ND	5.0	12/12/13 18:27	
4-Methyl-2-pentanone (MIBK)	ug/kg	ND	49.8	12/12/13 18:27	
Acetone	ug/kg	ND	99.6	12/12/13 18:27	
Benzene	ug/kg	ND	5.0	12/12/13 18:27	
Bromobenzene	ug/kg	ND	5.0	12/12/13 18:27	
Bromochloromethane	ug/kg	ND	5.0	12/12/13 18:27	
Bromodichloromethane	ug/kg	ND	5.0	12/12/13 18:27	
Bromoform	ug/kg	ND	5.0	12/12/13 18:27	
Bromomethane	ug/kg	ND	10	12/12/13 18:27	
Carbon tetrachloride	ug/kg	ND	5.0	12/12/13 18:27	
Chlorobenzene	ug/kg	ND	5.0	12/12/13 18:27	
Chloroethane	ug/kg	ND	10	12/12/13 18:27	
Chloroform	ug/kg	ND	5.0	12/12/13 18:27	
Chloromethane	ug/kg	ND	10	12/12/13 18:27	
cis-1,2-Dichloroethene	ug/kg	ND	5.0	12/12/13 18:27	
cis-1,3-Dichloropropene	ug/kg	ND	5.0	12/12/13 18:27	
Dibromochloromethane	ug/kg	ND	5.0	12/12/13 18:27	
Dibromomethane	ug/kg	ND	5.0	12/12/13 18:27	
Dichlorodifluoromethane	ug/kg	ND	10	12/12/13 18:27	



Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176 Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

QUALITY CONTROL DATA

Project: Buzzard Point Lot 13, Sq 607

Pace Project No.: 92182243

Date: 12/20/2013 11:21 AM

METHOD BLANK: 1102369 Matrix: Solid

Associated Lab Samples: 92182243001, 92182243002

		Blank	Reporting		
Parameter	Units	Result	Limit	Analyzed	Qualifiers
Diisopropyl ether	ug/kg	ND ND	5.0	12/12/13 18:27	
Ethylbenzene	ug/kg	ND	5.0	12/12/13 18:27	
Hexachloro-1,3-butadiene	ug/kg	ND	5.0	12/12/13 18:27	
Isopropylbenzene (Cumene)	ug/kg	ND	5.0	12/12/13 18:27	
m&p-Xylene	ug/kg	ND	10	12/12/13 18:27	
Methyl-tert-butyl ether	ug/kg	ND	5.0	12/12/13 18:27	
Methylene Chloride	ug/kg	ND	19.9	12/12/13 18:27	
n-Butylbenzene	ug/kg	ND	5.0	12/12/13 18:27	
n-Propylbenzene	ug/kg	ND	5.0	12/12/13 18:27	
Naphthalene	ug/kg	ND	5.0	12/12/13 18:27	
o-Xylene	ug/kg	ND	5.0	12/12/13 18:27	
p-Isopropyltoluene	ug/kg	ND	5.0	12/12/13 18:27	
sec-Butylbenzene	ug/kg	ND	5.0	12/12/13 18:27	
Styrene	ug/kg	ND	5.0	12/12/13 18:27	
tert-Butylbenzene	ug/kg	ND	5.0	12/12/13 18:27	
Tetrachloroethene	ug/kg	ND	5.0	12/12/13 18:27	
Toluene	ug/kg	ND	5.0	12/12/13 18:27	
trans-1,2-Dichloroethene	ug/kg	ND	5.0	12/12/13 18:27	
trans-1,3-Dichloropropene	ug/kg	ND	5.0	12/12/13 18:27	
Trichloroethene	ug/kg	ND	5.0	12/12/13 18:27	
Trichlorofluoromethane	ug/kg	ND	5.0	12/12/13 18:27	
Vinyl acetate	ug/kg	ND	49.8	12/12/13 18:27	
Vinyl chloride	ug/kg	ND	10	12/12/13 18:27	
Xylene (Total)	ug/kg	ND	10	12/12/13 18:27	
1,2-Dichloroethane-d4 (S)	%	88	70-132	12/12/13 18:27	
4-Bromofluorobenzene (S)	%	102	70-130	12/12/13 18:27	
Toluene-d8 (S)	%	94	70-130	12/12/13 18:27	

LABORATORY CONTROL SAMPLE	E: 1102370					
		Spike	LCS	LCS	% Rec	
Parameter	Units	Conc.	Result	% Rec	Limits	Qualifiers
1,1,1,2-Tetrachloroethane	ug/kg	47.9	65.5	137	70-131 L	_3
1,1,1-Trichloroethane	ug/kg	47.9	56.6	118	70-141	
1,1,2,2-Tetrachloroethane	ug/kg	47.9	55.5	116	70-130	
1,1,2-Trichloroethane	ug/kg	47.9	61.6	129	70-132	
1,1-Dichloroethane	ug/kg	47.9	44.0	92	70-143	
1,1-Dichloroethene	ug/kg	47.9	51.9	108	70-137	
1,1-Dichloropropene	ug/kg	47.9	49.5	103	70-135	
1,2,3-Trichlorobenzene	ug/kg	47.9	60.3	126	69-153	
1,2,3-Trichloropropane	ug/kg	47.9	61.8	129	70-130	
1,2,4-Trichlorobenzene	ug/kg	47.9	59.2	124	55-171	
1,2,4-Trimethylbenzene	ug/kg	47.9	57.5	120	70-149	
1,2-Dibromo-3-chloropropane	ug/kg	47.9	52.4	109	68-141	
1,2-Dibromoethane (EDB)	ug/kg	47.9	61.4	128	70-130	
1,2-Dichlorobenzene	ug/kg	47.9	62.9	131	70-140	



Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176 Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

QUALITY CONTROL DATA

Project: Buzzard Point Lot 13, Sq 607

Pace Project No.: 92182243

Date: 12/20/2013 11:21 AM

		0 "	1.00	1.00	0/ 5	
Parameter	Units	Spike Conc.	LCS Result	LCS % Rec	% Rec Limits	Qualifier
,2-Dichloroethane	ug/kg	47.9	52.3	109	70-137	
,2-Dichloropropane	ug/kg	47.9	50.0	104	70-133	
,3,5-Trimethylbenzene	ug/kg	47.9	58.1	121	70-143	
,3-Dichlorobenzene	ug/kg	47.9	61.3	128	70-144	
,3-Dichloropropane	ug/kg	47.9	52.4	109	70-132	
,4-Dichlorobenzene	ug/kg	47.9	61.6	129	70-142	
,2-Dichloropropane	ug/kg	47.9	50.3	105	68-152	
-Butanone (MEK)	ug/kg	95.8	87.1J	91	70-149	
-Chlorotoluene	ug/kg	47.9	52.9	110	70-141	
-Hexanone	ug/kg	95.8	90.5	94	70-149	
-Chlorotoluene	ug/kg	47.9	54.3	113	70-149	
-Methyl-2-pentanone (MIBK)	ug/kg	95.8	104	108	70-153	
acetone	ug/kg	95.8	87.4J	91	70-157	
Benzene	ug/kg	47.9	53.8	112	70-130	
Bromobenzene	ug/kg	47.9	50.9	106	70-141	
Bromochloromethane	ug/kg	47.9	60.9	127	70-149	
Bromodichloromethane	ug/kg	47.9	57.0	119	70-130	
Bromoform	ug/kg	47.9	65.8	137	70-131	13
Bromomethane	ug/kg	47.9	50.6	106	64-136	
Carbon tetrachloride	ug/kg	47.9	64.6	135	70-154	
Chlorobenzene	ug/kg	47.9	61.0	127	70-135	
Chloroethane	ug/kg	47.9	46.2	97	68-151	
Chloroform	ug/kg	47.9	48.6	101	70-130	
Chloromethane	ug/kg	47.9	44.1	92	70-132	
is-1,2-Dichloroethene	ug/kg	47.9	46.2	96	70-140	
is-1,3-Dichloropropene	ug/kg	47.9	52.4	109	70-137	
Dibromochloromethane	ug/kg	47.9	63.4	132	70-130	13
Dibromomethane	ug/kg	47.9	57.3	120	70-136	
Dichlorodifluoromethane	ug/kg	47.9	51.3	107	36-148	
Diisopropyl ether	ug/kg	47.9	42.9	90	70-139	
Ethylbenzene	ug/kg	47.9	58.0	121	70-133	
lexachloro-1,3-butadiene	ug/kg	47.9	62.5	131	70-137	
sopropylbenzene (Cumene)	ug/kg ug/kg	47.9 47.9	64.2	134	70-143	
n&p-Xylene	ug/kg ug/kg	95.8	119	124	70-141	
Nethyl-tert-butyl ether	ug/kg ug/kg	95.6 47.9	48.6	101	45-150	
Methylene Chloride	ug/kg ug/kg	47.9 47.9	43.2	90	70-133	
netriylerie Chioride i-Butylbenzene		47.9 47.9	43.2 56.3	118	65-155	
•	ug/kg	47.9 47.9	56.3 57.4	120	70-148	
-Propylbenzene	ug/kg					
laphthalene XVII.ono	ug/kg	47.9 47.0	61.3 58.5	128	70-148 70-141	
-Xylene	ug/kg	47.9 47.0	58.5 64.7	122	70-141	
-Isopropyltoluene	ug/kg	47.9 47.0	64.7	135	70-148	
ec-Butylbenzene	ug/kg	47.9 47.0	61.9	129	70-145	
Styrene	ug/kg	47.9	62.1	130	70-138	
ert-Butylbenzene	ug/kg	47.9	63.4	132	70-143	
etrachloroethene	ug/kg	47.9	69.9	146	70-140	LJ
oluene	ug/kg	47.9	57.6	120	70-130	
ans-1,2-Dichloroethene	ug/kg	47.9	45.5	95	70-136	



Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176 Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

QUALITY CONTROL DATA

Project: Buzzard Point Lot 13, Sq 607

Pace Project No.: 92182243

Date: 12/20/2013 11:21 AM

LABORATORY CONTROL SAMP	LE: 1102370					
		Spike	LCS	LCS	% Rec	
Parameter	Units	Conc.	Result	% Rec	Limits	Qualifiers
Trichloroethene	ug/kg	47.9	67.3	140	70-132	L3
Trichlorofluoromethane	ug/kg	47.9	52.1	109	69-134	
Vinyl acetate	ug/kg	95.8	84.5	88	24-161	
Vinyl chloride	ug/kg	47.9	47.8	100	55-140	
Xylene (Total)	ug/kg	144	177	123	70-141	
1,2-Dichloroethane-d4 (S)	%			85	70-132	
4-Bromofluorobenzene (S)	%			104	70-130	
Toluene-d8 (S)	%			91	70-130	

MATRIX SPIKE SAMPLE:	1104902						
		92182243001	Spike	MS	MS	% Rec	
Parameter	Units	Result	Conc.	Result	% Rec	Limits	Qualifiers
1,1-Dichloroethene	ug/kg	ND	45.6	34.7	76	49-180	
Benzene	ug/kg	ND	45.6	37.1	81	50-166	
Chlorobenzene	ug/kg	ND	45.6	36.5	80	43-169	
Toluene	ug/kg	ND	45.6	39.4	86	52-163	
Trichloroethene	ug/kg	ND	45.6	38.5	85	49-167	
1,2-Dichloroethane-d4 (S)	%				101	70-132	
4-Bromofluorobenzene (S)	%				88	70-130	
Toluene-d8 (S)	%				102	70-130	

SAMPLE DUPLICATE: 1104901					
		92182235002	Dup		
Parameter	Units	Result	Result	RPD	Qualifiers
1,1,1,2-Tetrachloroethane	ug/kg	ND	ND		
1,1,1-Trichloroethane	ug/kg	ND	ND		
1,1,2,2-Tetrachloroethane	ug/kg	ND	ND		
1,1,2-Trichloroethane	ug/kg	ND	ND		
1,1-Dichloroethane	ug/kg	ND	ND		
1,1-Dichloroethene	ug/kg	ND	ND		
1,1-Dichloropropene	ug/kg	ND	ND		
1,2,3-Trichlorobenzene	ug/kg	ND	ND		
1,2,3-Trichloropropane	ug/kg	ND	ND		
1,2,4-Trichlorobenzene	ug/kg	ND	ND		
1,2,4-Trimethylbenzene	ug/kg	ND	ND		
1,2-Dibromo-3-chloropropane	ug/kg	ND	ND		
1,2-Dibromoethane (EDB)	ug/kg	ND	ND		
1,2-Dichlorobenzene	ug/kg	ND	ND		
1,2-Dichloroethane	ug/kg	ND	ND		
1,2-Dichloropropane	ug/kg	ND	ND		
1,3,5-Trimethylbenzene	ug/kg	ND	ND		
1,3-Dichlorobenzene	ug/kg	ND	ND		
1,3-Dichloropropane	ug/kg	ND	ND		
1,4-Dichlorobenzene	ug/kg	ND	ND		
2,2-Dichloropropane	ug/kg	ND	ND		



(336)623-8921

Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176 Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

QUALITY CONTROL DATA

Project: Buzzard Point Lot 13, Sq 607

Pace Project No.: 92182243

Date: 12/20/2013 11:21 AM

Parameter	Units	92182235002 Result	Dup Result	RPD	Qualifier
				KFD	_ Qualifier:
2-Butanone (MEK)	ug/kg	ND	ND		
2-Chlorotoluene	ug/kg	ND	ND		
2-Hexanone	ug/kg	ND	ND		
4-Chlorotoluene	ug/kg	ND	ND		
4-Methyl-2-pentanone (MIBK)	ug/kg	ND	ND		
Acetone	ug/kg	ND	26.2J		
Benzene	ug/kg	ND	ND		
Bromobenzene	ug/kg	ND	ND		
3romochloromethane	ug/kg	ND	ND		
Bromodichloromethane	ug/kg	ND	ND		
Bromoform	ug/kg	ND	ND		
Bromomethane	ug/kg	ND	ND		
Carbon tetrachloride	ug/kg	ND	ND		
Chlorobenzene	ug/kg	ND	ND		
Chloroethane	ug/kg	ND	ND		
Chloroform	ug/kg	ND	ND		
Chloromethane	ug/kg	ND	ND		
cis-1,2-Dichloroethene	ug/kg	ND	ND		
cis-1,3-Dichloropropene	ug/kg	ND	ND		
Dibromochloromethane	ug/kg	ND	ND		
Dibromomethane	ug/kg	ND	ND		
Dichlorodifluoromethane	ug/kg	ND	ND		
Diisopropyl ether	ug/kg	ND	ND		
Ethylbenzene	ug/kg	ND	ND		
Hexachloro-1,3-butadiene	ug/kg	ND	ND		
sopropylbenzene (Cumene)	ug/kg	ND	ND		
		ND	ND ND		
m&p-Xylene	ug/kg	ND ND	ND ND		
Methyl-tert-butyl ether	ug/kg	ND ND			00
Methylene Chloride	ug/kg	ND ND	65.9		C9
n-Butylbenzene	ug/kg	ND ND	ND		
n-Propylbenzene	ug/kg		ND		
Naphthalene	ug/kg	ND	ND		
o-Xylene	ug/kg	ND	ND		
o-Isopropyltoluene	ug/kg	ND	ND		
sec-Butylbenzene	ug/kg	ND	ND		
Styrene	ug/kg	ND	ND		
ert-Butylbenzene	ug/kg	ND	ND		
Tetrachloroethene	ug/kg	ND	ND		
Toluene	ug/kg	ND	ND		
rans-1,2-Dichloroethene	ug/kg	ND	ND		
rans-1,3-Dichloropropene	ug/kg	ND	ND		
Γrichloroethene	ug/kg	ND	ND		
Trichlorofluoromethane	ug/kg	ND	ND		
Vinyl acetate	ug/kg	ND	ND		
/inyl chloride	ug/kg	ND	ND		
Xylene (Total)	ug/kg	ND	ND		
I,2-Dichloroethane-d4 (S)	%	117	116	1	2
4-Bromofluorobenzene (S)	%	95	99		6



Pace Analytical Services, Inc. 205 East Meadow Road - Suite A

Eden, NC 27288 (336)623-8921 Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176 Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

QUALITY CONTROL DATA

Project: Buzzard Point Lot 13, Sq 607

Pace Project No.: 92182243

SAMPLE DUPLICATE: 1104901

Parameter

92182235002 Result

Dup

Result

105

RPD Qualifiers 7

Toluene-d8 (S)

Date: 12/20/2013 11:21 AM

%

Units

101



205 East Meadow Road - Suite A Eden, NC 27288 (336)623-8921

Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176

Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

QUALITY CONTROL DATA

Project: Buzzard Point Lot 13, Sq 607

Pace Project No.: 92182243

Date: 12/20/2013 11:21 AM

QC Batch: OEXT/25067 Analysis Method: EPA 8015 Modified
QC Batch Method: EPA 3546 Analysis Description: 8015 Solid GCSV

Associated Lab Samples: 92182243001, 92182243002

METHOD BLANK: 1100284 Matrix: Solid

Associated Lab Samples: 92182243001, 92182243002

ParameterUnitsBlank ResultReporting LimitAnalyzedQualifiersDiesel Componentsmg/kgND5.012/08/13 17:53

Diesel Components mg/kg ND 5.0 12/08/13 17:53 n-Pentacosane (S) % 95 41-119 12/08/13 17:53

LABORATORY CONTROL SAMPLE: 1100285

Spike LCS LCS % Rec Parameter Units Conc. Result % Rec Limits Qualifiers **Diesel Components** mg/kg 66.7 53.6 80 49-113 n-Pentacosane (S) % 93 41-119

MATRIX SPIKE & MATRIX SPIKE DUPLICATE: 1100287 1100286 MSD MS 92182164007 Spike Spike MS MSD MS MSD % Rec Parameter Units Result Conc. Conc. Result Result % Rec % Rec Limits **RPD** Qual ND **Diesel Components** mg/kg 79.4 79.4 67.9 60.5 85 76 10-146 12 n-Pentacosane (S) % 93 81 41-119



(336)623-8921

Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176 Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

QUALITY CONTROL DATA

Project: Buzzard Point Lot 13, Sq 607

Pace Project No.: 92182243

Date: 12/20/2013 11:21 AM

QC Batch: OEXT/25076 Analysis Method: EPA 8270

QC Batch Method: EPA 3546 Analysis Description: 8270 Solid MSSV Microwave

Associated Lab Samples: 92182243001

METHOD BLANK: 1100720 Matrix: Solid

Associated Lab Samples: 92182243001

Parameter	Units	Blank Result	Reporting Limit	Analyzed	Qualifiers
1,2,4-Trichlorobenzene	ug/kg		330	12/10/13 09:48	
1,2-Dichlorobenzene	ug/kg ug/kg	ND ND	330	12/10/13 09:48	
1,3-Dichlorobenzene	ug/kg ug/kg	ND ND	330	12/10/13 09:48	
1,4-Dichlorobenzene	ug/kg ug/kg	ND	330	12/10/13 09:48	
1-Methylnaphthalene	ug/kg ug/kg	ND	330	12/10/13 09:48	
2,4,5-Trichlorophenol	ug/kg ug/kg	ND	330	12/10/13 09:48	
2,4,6-Trichlorophenol	ug/kg	ND ND	330	12/10/13 09:48	
2,4-Dichlorophenol	ug/kg ug/kg	ND	330	12/10/13 09:48	
2,4-Dimethylphenol	ug/kg	ND	330	12/10/13 09:48	
2,4-Dinitrophenol	ug/kg	ND	1650	12/10/13 09:48	
2,4-Dinitrotoluene	ug/kg	ND	330	12/10/13 09:48	
2,6-Dinitrotoluene	ug/kg ug/kg	ND ND	330	12/10/13 09:48	
2-Chloronaphthalene	ug/kg ug/kg	ND	330	12/10/13 09:48	
2-Chlorophenol	ug/kg	ND ND	330	12/10/13 09:48	
2-Methylnaphthalene	ug/kg	ND ND	330	12/10/13 09:48	
2-Methylphenol(o-Cresol)	ug/kg ug/kg	ND ND	330	12/10/13 09:48	
2-Nitroaniline	ug/kg ug/kg	ND ND	1650	12/10/13 09:48	
2-Nitrophenol	ug/kg ug/kg	ND ND	330	12/10/13 09:48	
3&4-Methylphenol(m&p Cresol)	ug/kg ug/kg	ND ND	330	12/10/13 09:48	
3,3'-Dichlorobenzidine	ug/kg ug/kg	ND ND	1650	12/10/13 09:48	
3-Nitroaniline	ug/kg ug/kg	ND ND	1650	12/10/13 09:48	
4,6-Dinitro-2-methylphenol	ug/kg ug/kg	ND ND	660	12/10/13 09:48	
4-Bromophenylphenyl ether	ug/kg ug/kg	ND ND	330	12/10/13 09:48	
4-Chloro-3-methylphenol	ug/kg ug/kg	ND ND	660	12/10/13 09:48	
4-Chloroaniline	ug/kg ug/kg	ND ND	1650	12/10/13 09:48	
	ug/kg ug/kg	ND ND	330	12/10/13 09:48	
4-Chlorophenylphenyl ether 4-Nitroaniline	ug/kg ug/kg	ND ND	660	12/10/13 09:48	
4-Nitrophenol		ND ND	1650	12/10/13 09:48	
·	ug/kg	ND ND	330		
Acenaphthylana	ug/kg ug/kg	ND ND	330	12/10/13 09:48	
Acenaphthylene Aniline		ND ND	330	12/10/13 09:48	
Anthracene	ug/kg	ND ND	330	12/10/13 09:48	
	ug/kg	ND ND	330	12/10/13 09:48	
Benzo(a)anthracene	ug/kg			12/10/13 09:48	
Benzo(a)pyrene	ug/kg	ND	330	12/10/13 09:48	
Benzo(b)fluoranthene	ug/kg	ND	330	12/10/13 09:48	
Benzo(g,h,i)perylene	ug/kg	ND	330	12/10/13 09:48	
Benzo(k)fluoranthene	ug/kg	ND	330	12/10/13 09:48	
Benzoic Acid	ug/kg	ND	1650	12/10/13 09:48	
Benzyl alcohol	ug/kg	ND	660	12/10/13 09:48	
bis(2-Chloroethoxy)methane	ug/kg	ND	330	12/10/13 09:48	
bis(2-Chloroethyl) ether	ug/kg	ND	330	12/10/13 09:48	
bis(2-Chloroisopropyl) ether	ug/kg	ND	330	12/10/13 09:48	
bis(2-Ethylhexyl)phthalate	ug/kg	ND	330	12/10/13 09:48	



(336)623-8921

Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176 Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

QUALITY CONTROL DATA

Project: Buzzard Point Lot 13, Sq 607

Pace Project No.: 92182243

Date: 12/20/2013 11:21 AM

METHOD BLANK: 1100720 Matrix: Solid

Associated Lab Samples: 92182243001

_		Blank	Reporting		
Parameter	Units	Result	Limit	Analyzed	Qualifiers
Butylbenzylphthalate	ug/kg	ND	330	12/10/13 09:48	
Chrysene	ug/kg	ND	330	12/10/13 09:48	
Di-n-butylphthalate	ug/kg	ND	330	12/10/13 09:48	
Di-n-octylphthalate	ug/kg	ND	330	12/10/13 09:48	
Dibenz(a,h)anthracene	ug/kg	ND	330	12/10/13 09:48	
Dibenzofuran	ug/kg	ND	330	12/10/13 09:48	
Diethylphthalate	ug/kg	ND	330	12/10/13 09:48	
Dimethylphthalate	ug/kg	ND	330	12/10/13 09:48	
Fluoranthene	ug/kg	ND	330	12/10/13 09:48	
Fluorene	ug/kg	ND	330	12/10/13 09:48	
Hexachloro-1,3-butadiene	ug/kg	ND	330	12/10/13 09:48	
Hexachlorobenzene	ug/kg	ND	330	12/10/13 09:48	
Hexachlorocyclopentadiene	ug/kg	ND	330	12/10/13 09:48	
Hexachloroethane	ug/kg	ND	330	12/10/13 09:48	
Indeno(1,2,3-cd)pyrene	ug/kg	ND	330	12/10/13 09:48	
Isophorone	ug/kg	ND	330	12/10/13 09:48	
N-Nitroso-di-n-propylamine	ug/kg	ND	330	12/10/13 09:48	
N-Nitrosodimethylamine	ug/kg	ND	330	12/10/13 09:48	
N-Nitrosodiphenylamine	ug/kg	ND	330	12/10/13 09:48	
Naphthalene	ug/kg	ND	330	12/10/13 09:48	
Nitrobenzene	ug/kg	ND	330	12/10/13 09:48	
Pentachlorophenol	ug/kg	ND	1650	12/10/13 09:48	
Phenanthrene	ug/kg	ND	330	12/10/13 09:48	
Phenol	ug/kg	ND	330	12/10/13 09:48	
Pyrene	ug/kg	ND	330	12/10/13 09:48	
2,4,6-Tribromophenol (S)	%	83	27-110	12/10/13 09:48	
2-Fluorobiphenyl (S)	%	69	30-110	12/10/13 09:48	
2-Fluorophenol (S)	%	73	13-110	12/10/13 09:48	
Nitrobenzene-d5 (S)	%	62	23-110	12/10/13 09:48	
Phenol-d6 (S)	%	74	22-110	12/10/13 09:48	
Terphenyl-d14 (S)	%	82	28-110	12/10/13 09:48	

LABORATORY CONTROL SAMPLE:	1100721					
		Spike	LCS	LCS	% Rec	
Parameter	Units	Conc.	Result	% Rec	Limits	Qualifiers
1,2,4-Trichlorobenzene	ug/kg	1670	1000	60	39-101	
1,2-Dichlorobenzene	ug/kg	1670	1110	67	36-110	
1,3-Dichlorobenzene	ug/kg	1670	1070	64	35-110	
1,4-Dichlorobenzene	ug/kg	1670	1110	67	35-110	
1-Methylnaphthalene	ug/kg	1670	1220	73	45-105	
2,4,5-Trichlorophenol	ug/kg	1670	1340	80	48-109	
2,4,6-Trichlorophenol	ug/kg	1670	1160	70	45-111	
2,4-Dichlorophenol	ug/kg	1670	1190	71	51-116	
2,4-Dimethylphenol	ug/kg	1670	1370	82	42-103	
2,4-Dinitrophenol	ug/kg	8330	7050	85	28-103	



Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176 Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

QUALITY CONTROL DATA

Project: Buzzard Point Lot 13, Sq 607

Pace Project No.: 92182243

Date: 12/20/2013 11:21 AM

	E: 1100721	Spiles	100	LCS	% Rec	
Parameter	Units	Spike Conc.	LCS Result	% Rec	% Rec Limits	Qualifier
2,4-Dinitrotoluene	ug/kg	1670	1470	88	46-114	
2,6-Dinitrotoluene	ug/kg	1670	1410	84	48-112	
2-Chloronaphthalene	ug/kg	1670	1030	62	44-105	
2-Chlorophenol	ug/kg	1670	1370	82	36-110	
2-Methylnaphthalene	ug/kg	1670	1260	76	39-112	
2-Methylphenol(o-Cresol)	ug/kg	1670	1580	95	39-101	
2-Nitroaniline	ug/kg	3330	2690	81	44-111	
2-Nitrophenol	ug/kg	1670	1360	82	41-100	
3&4-Methylphenol(m&p Cresol)	ug/kg	1670	1550	93	43-103	
3,3'-Dichlorobenzidine	ug/kg	3330	2470	74	10-150	
3-Nitroaniline	ug/kg	3330	2910	87	35-110	
I,6-Dinitro-2-methylphenol	ug/kg	3330	2650	80	38-118	
-Bromophenylphenyl ether	ug/kg	1670	1380	83	47-115	
I-Chloro-3-methylphenol	ug/kg	3330	2840	85	43-127	
1-Chloroaniline	ug/kg	3330	2680	80	34-109	
1-Chlorophenylphenyl ether	ug/kg	1670	1390	83	44-115	
I-Nitroaniline	ug/kg	3330	3240	97	37-111	
1-Nitrophenol	ug/kg	8330	6040	72	21-152	
Acenaphthene	ug/kg	1670	1280	77	38-117	
Acenaphthylene	ug/kg	1670	1320	79	46-107	
Aniline	ug/kg	1670	1150	69	29-110	
Anthracene	ug/kg	1670	1340	80	50-110	
Benzo(a)anthracene	ug/kg	1670	1280	77	47-116	
Benzo(a)pyrene	ug/kg	1670	1400	84	47-106	
Benzo(b)fluoranthene	ug/kg	1670	1300	78	47-100	
Benzo(g,h,i)perylene	ug/kg	1670	1400	84	39-115	
Benzo(k)fluoranthene	ug/kg	1670	1300	78	45-117	
Benzoic Acid	ug/kg	8330	5040	60	16-110	
Benzyl alcohol	ug/kg ug/kg	3330	2500	75	38-105	
ois(2-Chloroethoxy)methane	ug/kg ug/kg	1670	1220	73 73	39-110	
ois(2-Chloroethyl) ether	ug/kg ug/kg	1670	1390	84	19-119	
pis(2-Chloroisopropyl) ether	ug/kg ug/kg	1670	1270	76	21-110	
		1670	1190	70 71	35-116	
pis(2-Ethylhexyl)phthalate	ug/kg	1670	1210	73	38-110	
Butylbenzylphthalate	ug/kg	1670	1390	83	49-110	
Chrysene	ug/kg			ია 71		
Di-n-butylphthalate	ug/kg	1670	1180		43-109	
Di-n-octylphthalate	ug/kg	1670	1110	67 96	37-109 42-116	
Dibenz(a,h)anthracene	ug/kg	1670	1440	86	43-116	
Dibenzofuran Distributa balata	ug/kg	1670	1110	66	45-106 41-114	
Diethylphthalate	ug/kg	1670	1170	70	41-114	
Dimethylphthalate	ug/kg	1670	1150	69	43-110	
luoranthene	ug/kg	1670	1360	81	50-114	
fluorene	ug/kg	1670	1370	82	46-114	
lexachloro-1,3-butadiene	ug/kg	1670	937	56	28-111	
Hexachlorobenzene	ug/kg	1670	1160	70	46-120	
Hexachlorocyclopentadiene	ug/kg	1670	1120	67	18-119	
Hexachloroethane	ug/kg	1670	1040	63	33-110	
ndeno(1,2,3-cd)pyrene	ug/kg	1670	1430	86	42-115	



Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176 Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

QUALITY CONTROL DATA

Project: Buzzard Point Lot 13, Sq 607

Pace Project No.: 92182243

Date: 12/20/2013 11:21 AM

_ABORATORY CONTROL SAMPL	_E: 1100721					
		Spike	LCS	LCS	% Rec	
Parameter	Units	Conc.	Result	% Rec	Limits	Qualifiers
sophorone	ug/kg		1270	76	44-109	
N-Nitroso-di-n-propylamine	ug/kg	1670	1050	63	43-104	
N-Nitrosodimethylamine	ug/kg	1670	1020	61	29-110	
N-Nitrosodiphenylamine	ug/kg	1670	996	60	48-113	
Naphthalene	ug/kg	1670	1310	79	41-110	
Nitrobenzene	ug/kg	1670	1100	66	38-110	
Pentachlorophenol	ug/kg	3330	2540	76	32-128	
Phenanthrene	ug/kg	1670	1320	79	50-110	
Phenol	ug/kg	1670	1400	84	28-106	
Pyrene	ug/kg	1670	1250	75	45-114	
2,4,6-Tribromophenol (S)	%			97	27-110	
P-Fluorobiphenyl (S)	%			66	30-110	
P-Fluorophenol (S)	%			77	13-110	
litrobenzene-d5 (S)	%			64	23-110	
Phenol-d6 (S)	%			84	22-110	
erphenyl-d14 (S)	%			73	28-110	

MATRIX SPIKE & MATRIX SP	1100723										
	20.	100044004	MS	MSD	МС	MCD	MC	MCD	0/ Da-		
Doromotor	_	182244001	Spike	Spike	MS	MSD	MS % Ree	MSD	% Rec	DDD	Ougl
Parameter	Units	Result	Conc.	Conc.	Result	Result	% Rec	% Rec	Limits	RPD _	Qual
,2,4-Trichlorobenzene	ug/kg	ND	2020	2020	1190	1200	59	60	18-119	1	
,2-Dichlorobenzene	ug/kg	ND	2020	2020	1330	1310	66	65	50-110	1	
,3-Dichlorobenzene	ug/kg	ND	2020	2020	1290	1260	64	63	27-110	2	
,4-Dichlorobenzene	ug/kg	ND	2020	2020	1360	1310	67	65	28-110	4	
-Methylnaphthalene	ug/kg	ND	2020	2020	1410	1420	70	71	24-116	1	
2,4,5-Trichlorophenol	ug/kg	ND	2020	2020	1540	1540	77	76	28-110	0	
2,4,6-Trichlorophenol	ug/kg	ND	2020	2020	1380	1330	68	66	17-117	3	
2,4-Dichlorophenol	ug/kg	ND	2020	2020	1420	1390	71	69	21-128	2	
2,4-Dimethylphenol	ug/kg	ND	2020	2020	1410	1130	70	56	10-120	22	
2,4-Dinitrophenol	ug/kg	ND	10100	10100	7750	8570	77	85	10-107	10	
2,4-Dinitrotoluene	ug/kg	ND	2020	2020	1610	1710	80	85	36-109	6	
2,6-Dinitrotoluene	ug/kg	ND	2020	2020	1630	1690	81	84	32-110	4	
2-Chloronaphthalene	ug/kg	ND	2020	2020	1220	1210	61	60	30-107	1	
2-Chlorophenol	ug/kg	ND	2020	2020	1630	1550	81	77	14-106	6	
2-Methylnaphthalene	ug/kg	ND	2020	2020	1450	1470	72	73	10-135	1	
2-Methylphenol(o-Cresol)	ug/kg	ND	2020	2020	1710	1560	85	77	10-124	9	
2-Nitroaniline	ug/kg	ND	4020	4020	3140	3160	78	78	26-116	1	
2-Nitrophenol	ug/kg	ND	2020	2020	1710	1730	85	86	28-103	1	
8&4-Methylphenol(m&p Cresol)	ug/kg	ND	2020	2020	1630	1480	81	74	10-109	10	
3,3'-Dichlorobenzidine	ug/kg	ND	4020	4020	2470	2100	61	52	10-150	16	
B-Nitroaniline	ug/kg	ND	4020	4020	3170	3300	79	82	22-110	4	
I,6-Dinitro-2-methylphenol	ug/kg	ND	4020	4020	2840	3060	71	76	13-121	7	
I-Bromophenylphenyl ether	ug/kg	ND	2020	2020	1570	1530	78	76	31-109	3	
I-Chloro-3-methylphenol	ug/kg	ND	4020	4020	3130	3030	78	75	13-128	3	
I-Chloroaniline	ug/kg	ND	4020	4020	2800	2650	70	66	18-102	5	



Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176 Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

QUALITY CONTROL DATA

Project: Buzzard Point Lot 13, Sq 607

Pace Project No.: 92182243

Date: 12/20/2013 11:21 AM

MATRIX SPIKE & MATRIX SPI	KE DUPLICAT	E: 11007			1100723						
Parameter	921 Units	182244001 Result	MS Spike Conc.	MSD Spike Conc.	MS Result	MSD Result	MS % Rec	MSD % Rec	% Rec Limits	RPD	Qua
4-Chlorophenylphenyl ether	ug/kg	ND .	2020	2020	1590	1560	79	78	29-112		
4-Nitroaniline	ug/kg ug/kg	ND	4020	4020	3410	3620	85	90	16-111	6	
4-Nitrophenol	ug/kg ug/kg	ND	10100	10100	6180	6590	61	66	14-135	6	
Acenaphthene	ug/kg ug/kg	ND	2020	2020	1490	1470	74	73	26-114	1	
Acenaphthylene	ug/kg ug/kg	ND	2020	2020	1540	1520	77	76	32-108	1	
Aniline		ND	2020	2020	461	242J	23	12	10-107	'	
Anthracene	ug/kg	ND	2020	2020	1480	1490	74	74	32-111	0	
	ug/kg	ND	2020								
Senzo(a)anthracene	ug/kg	ND		2020	1430	1400	71 77	70 75	25-117	2	
Senzo(a)pyrene	ug/kg	ND	2020	2020	1550	1520		75 70	25-106	2	
Senzo(b)fluoranthene	ug/kg		2020	2020	1470	1410	73	70	24-110	4	
enzo(g,h,i)perylene	ug/kg	ND	2020	2020	1490	1470	74	73	19-112	1	
enzo(k)fluoranthene	ug/kg	ND	2020	2020	1380	1400	69	70	24-114	2	
enzoic Acid	ug/kg	ND	10100	10100	5590	5720	56	57	10-110	2	
enzyl alcohol	ug/kg	ND	4020	4020	2900	2740	72	68	24-106	6	
is(2-Chloroethoxy)methane	ug/kg	ND	2020	2020	1440	1400	71	70	13-119	3	
is(2-Chloroethyl) ether	ug/kg	ND	2020	2020	1650	1510	82	75	10-134	8	
is(2-Chloroisopropyl) ether	ug/kg	ND	2020	2020	1460	1430	73	71	10-113	2	
is(2-Ethylhexyl)phthalate	ug/kg	ND	2020	2020	1330	1330	66	66	10-125	0	
utylbenzylphthalate	ug/kg	ND	2020	2020	1370	1360	68	67	18-110	1	
hrysene	ug/kg	ND	2020	2020	1550	1510	77	75	30-110	2	
i-n-butylphthalate	ug/kg	ND	2020	2020	1300	1290	64	64	19-112	0	
i-n-octylphthalate	ug/kg	ND	2020	2020	1270	1260	63	63	17-105	1	
ibenz(a,h)anthracene	ug/kg	ND	2020	2020	1560	1540	78	76	23-111	1	
ibenzofuran	ug/kg	ND	2020	2020	1270	1280	63	64	35-103	1	
iethylphthalate	ug/kg	ND	2020	2020	1330	1360	66	68	27-113	2	
imethylphthalate	ug/kg	ND	2020	2020	1350	1340	67	66	26-111	1	
luoranthene	ug/kg	ND	2020	2020	1470	1510	73	75	33-109	3	
luorene	ug/kg	ND	2020	2020	1540	1570	77	78	32-113	2	
lexachloro-1,3-butadiene	ug/kg	ND	2020	2020	1150	1100	57	55	16-116	4	
lexachlorobenzene	ug/kg	ND	2020	2020	1350	1310	67	65	27-120	3	
lexachlorocyclopentadiene	ug/kg	ND	2020	2020	1240	1290	62	64	10-108	4	
lexachloroethane	ug/kg	ND	2020	2020	1250	1220	62	61	10-117	3	
ndeno(1,2,3-cd)pyrene	ug/kg	ND	2020	2020	1530	1520	76	75	10-122	1	
sophorone	ug/kg	ND	2020	2020	1450	1460	72	72	28-114	0	
l-Nitroso-di-n-propylamine	ug/kg	ND	2020	2020	1180	1130	59	56	27-113	4	
I-Nitrosodimethylamine	ug/kg	ND	2020	2020	1190	1150	59	57	10-109	4	
l-Nitrosodiphenylamine	ug/kg	ND	2020	2020	1070	1040	53	52	10-128	3	
laphthalene	ug/kg	ND	2020	2020	1540	1560	77	77	25-110		
itrobenzene	ug/kg	ND	2020	2020	1340	1300	66	65	18-114	3	
entachlorophenol	ug/kg	ND	4020	4020	2790	2880	69	72	10-122	3	
henanthrene	ug/kg ug/kg	ND	2020	2020	1450	1470	72	73	30-114	1	
henol	ug/kg ug/kg	ND	2020	2020	1490	1360	74	67	11-102	9	
yrene	ug/kg ug/kg	ND	2020	2020	1490	1400	70	69	25-116	1	
,4,6-Tribromophenol (S)	ug/kg %	שוו	2020	2020	1400	1400	83	79	27-110	ı	
-Fluorobiphenyl (S)	% %						63	79 61			
									30-110		
-Fluorophenol (S)	%						72	66	13-110		
Nitrobenzene-d5 (S)	%						63	63	23-110		



205 East Meadow Road - Suite A Eden, NC 27288 (336)623-8921

Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804

(828)254-7176

Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

QUALITY CONTROL DATA

Project: Buzzard Point Lot 13, Sq 607

Pace Project No.: 92182243

Date: 12/20/2013 11:21 AM

MATRIX SPIKE & MATRIX SPIKE DUPLICATE: 1100722 1100723

	92 ⁻	182244001	MS Spike	MSD Spike	MS	MSD	MS	MSD	% Rec		
Parameter	Units	Result	Conc.	Conc.	Result	Result	% Rec	% Rec	Limits	RPD	Qual
Phenol-d6 (S)	 %						75	70	22-110		
Terphenyl-d14 (S)	%						67	66	28-110		



205 East Meadow Road - Suite A Eden, NC 27288 (336)623-8921

Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176

Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

QUALITY CONTROL DATA

Project: Buzzard Point Lot 13, Sq 607

Pace Project No.: 92182243

QC Batch: PMST/6069 Analysis Method: ASTM D2974-87

QC Batch Method: ASTM D2974-87 Analysis Description: Dry Weight/Percent Moisture

Associated Lab Samples: 92182243001, 92182243002

SAMPLE DUPLICATE: 1101897

92182164001 Dup

Parameter Units Result Result RPD Qualifiers

Percent Moisture % 13.1 13.0 1

SAMPLE DUPLICATE: 1101898

Date: 12/20/2013 11:21 AM

 Parameter
 Units
 92182259007 Result
 Dup Result
 RPD
 Qualifiers

 Percent Moisture
 %
 26.5
 27.7
 4



Pace Analytical Services, Inc. 205 East Meadow Road - Suite A

Eden, NC 27288 (336)623-8921 Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176 Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

QUALIFIERS

Project: Buzzard Point Lot 13, Sq 607

Pace Project No.: 92182243

DEFINITIONS

DF - Dilution Factor, if reported, represents the factor applied to the reported data due to changes in sample preparation, dilution of the sample aliquot, or moisture content.

ND - Not Detected at or above adjusted reporting limit.

J - Estimated concentration above the adjusted method detection limit and below the adjusted reporting limit.

MDL - Adjusted Method Detection Limit.

PRL - Pace Reporting Limit.

RL - Reporting Limit.

S - Surrogate

1,2-Diphenylhydrazine (8270 listed analyte) decomposes to Azobenzene.

Consistent with EPA guidelines, unrounded data are displayed and have been used to calculate % recovery and RPD values.

LCS(D) - Laboratory Control Sample (Duplicate)

MS(D) - Matrix Spike (Duplicate)

DUP - Sample Duplicate

RPD - Relative Percent Difference

NC - Not Calculable.

SG - Silica Gel - Clean-Up

U - Indicates the compound was analyzed for, but not detected.

N-Nitrosodiphenylamine decomposes and cannot be separated from Diphenylamine using Method 8270. The result reported for each analyte is a combined concentration.

Acid preservation may not be appropriate for 2-Chloroethylvinyl ether, Styrene, and Vinyl chloride.

Pace Analytical is TNI accredited. Contact your Pace PM for the current list of accredited analytes.

TNI - The NELAC Institute.

LABORATORIES

PASI-A	Pace Analytical Services - Asheville
PASI-C	Pace Analytical Services - Charlotte

ANALYTE QUALIFIERS

Date: 12/20/2013 11:21 AM

1g	The internal standard response is below criteria. No hits associated with this internal standard. Results unaffected by
3	high bias.
C9	Common Laboratory Contaminant.
D3	Sample was diluted due to the presence of high levels of non-target analytes or other matrix interference.

L3 Analyte recovery in the laboratory control sample (LCS) exceeded QC limits. Analyte presence below reporting limits in associated samples. Results unaffected by high bias.

M1 Matrix spike recovery exceeded QC limits. Batch accepted based on laboratory control sample (LCS) recovery.

R1 RPD value was outside control limits.

S4 Surrogate recovery not evaluated against control limits due to sample dilution.



Pace Analytical Services, Inc. 205 East Meadow Road - Suite A

Eden, NC 27288 (336)623-8921

Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804

(828)254-7176

Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

QUALITY CONTROL DATA CROSS REFERENCE TABLE

Project: Buzzard Point Lot 13, Sq 607

Pace Project No.: 92182243

Date: 12/20/2013 11:21 AM

Lab ID	Sample ID	QC Batch Method	QC Batch	Analytical Method	Analytical Batch
92182243001 92182243002	GTW607-13-2-2 GSS607-13-3-1	EPA 3546 EPA 3546	OEXT/25067 OEXT/25067	EPA 8015 Modified EPA 8015 Modified	GCSV/16182 GCSV/16182
92182243001 92182243002	GTW607-13-2-2 GSS607-13-3-1	EPA 5035A/5030B EPA 5035A/5030B	GCV/7586 GCV/7586	EPA 8015 Modified EPA 8015 Modified	GCV/7589 GCV/7589
92182243001	GTW607-13-2-2	EPA 3050	MPRP/14800	EPA 6010	ICP/13447
92182243001	GTW607-13-2-2	EPA 7471	MERP/5913	EPA 7471	MERC/5718
92182243001	GTW607-13-2-2	EPA 3546	OEXT/25076	EPA 8270	MSSV/8534
92182243001 92182243002	GTW607-13-2-2 GSS607-13-3-1	EPA 8260 EPA 8260	MSV/25200 MSV/25200		
92182243001 92182243002	GTW607-13-2-2 GSS607-13-3-1	ASTM D2974-87 ASTM D2974-87	PMST/6069 PMST/6069		

Pace Analytical*

Document Name: Sample Condition Upon Receipt (SCUR)

Document Number: F-CHR-CS-03-rev.12

Page 1 of 2

Issuing Authority:
Pace Huntersville Quality Office

Client Name: Holey & Aldrich	
Where Received: Huntersville	Asheville
Courier: Fed Ex UPS USPS Clien	otOtherOptional
Custody Seal on Cooler/Box Present: yes	no Seals intact: yes no Proj. Due Date: Proj. Name:
	Bags None Other
Thermometer Used: IR Gun T1102 (130)	Type of Ice: Web Blue None Samples on ice, cooling process has begun
Temp Correction Factor T1102: No Correct	ction T1301: No Correction Date and Initials of person examining
Corrected Cooler Temp.: 50 C	Biological Tissue is Frozen: Yes No NA contents:
Chain of Custody Present:	✓Yes □No □N/A 1.
Chain of Custody Filled Out:	ΔΥes □No □N/A 2.
Chain of Custody Relinquished:	√Gyes □No □N/A 3.
Sampler Name & Signature on COC:	fiyes □No □N/A 4.
Samples Arrived within Hold Time:	y Yes □No □N/A 5.
Short Hold Time Analysis (<72hr):	□Yes ☑No □N/A 6.
Rush Turn Around Time Requested:	⊠Yes □No □N/A 7.
Sufficient Volume:	☑Yes □No □N/A 8.
Correct Containers Used:	⊠Yes □No □N/A 9.
-Pace Containers Used:	□Yes □No □N/A
Containers Intact:	□Yes □No □N/A 10.
Filtered volume received for Dissolved tests	□Yes □No □N/A 11.
Sample Labels match COC:	□Yes □No □N/A 12.
-Includes date/time/ID/Analysis Matrix:	
All containers needing preservation have been checked.	□Yes □No ☑Ñ/A 13.
All containers needing preservation are found to be in compliance with EPA recommendation.	□Yes □No □N/A
exceptions: VOA, coliform, TOC, O&G, WI-DRO (water)	□Yes ☑No
Samples checked for dechlorination:	□Yes □No ☑N/A 14.
Headspace in VOA Vials (>6mm):	□Yes □No □N/A 15.
Trip Blank Present:	□Yes □No ØN/A 16.
Trip Blank Custody Seals Present	□Yes □No □N/A
Pace Trip Blank Lot # (if purchased):	
Client Notification/ Resolution:	Field Data Required? Y / N
Person Contacted:	Date/Time:
Comments/ Resolution:	
	10/1/2
SCORP Review.	Date: $\frac{ 2/b/ 3 }{ - a/ 2 }$ WO#: 92182243
SRF Review: D Note: Whenever there is a discrepancy affecting N	Date: 12/9/15
Note: Whenever there is a discrepancy affecting Noses samples, a copy of this form will be sent to the Noses samples.	North Carolina Definit

Certification Office (i.e out of hold, incorrect preservative, out of temp, incorrect containers)

Page 30 of 31

Page 31 of 31

HALEY	Hale 7926	Haley & Aldrich, Inc. 7926 Jones Branch Di	Haley & Aldrich, Inc. 7926 Jones Branch Drive, Suite 870	e 870		1 V 11 V			Phone (703) 356-4699 g
ALDMCH	Mcl	McLean, VA 22102	2102		_	ДАЦ	CHAIN OF CUSTOUY RECORD	Y KECOK	Page 1 of 1
H&A FILE NO.	4023	40223-002				LABORATORY	ORY Pace Analytical Services, Inc.		12/6/2013
PROJECT NAME	Buz	zard Point	Buzzard Point (Lot 13, Square 607)	e 607)		ADDRESS			.≧.
H&A CONTACT	Don	Don Seserko				PROJECT	PROJECT MANAGER Greg Grose		DELIVERY DATE 12/16/2013
Sample No.	Date	Time	Depth	Туре	Container Size	No. of Containers	Analysis Requested	Preservatives	Comments - (special instructions, precautions, additional method numbers, etc.)
3TW607-13-2- 3	12/5/2013	12:55	5-10	Soil	VOAs/4oz	7/3	VOCs, TPH-GRO/DRO, SVOCs, PP-metals	G/H/A	d. Soul
3SS607-13-3- 12	12/5/2013	8.57	0-2	Soil	VOAs/4oz	7/1	BTEX/Naph, TPH-GRO/DRO	G/H/A	and the same of th
				i					
ampled and Relinquished by	7	Smale			Received by	by	9 9 9 9	PRESERVATION KEY	Sampling Comments
ign Doned Sanks					Sign 🔀	UPI		A Sample chilled	Discard remaining samples not listed for analysis above.
rint Dunald Sesarto	KO				Print			B Sample filtered	
im Halays Aldrich	,				Firm	•		C NaOH	
ate 12/5/13		Time	16:00		Date 12/6/19	/6/M3	1)25Time	D HNO,	
elinquished by					Received by	by		E H ₂ SO ₄	
gn					Sign			F HCL	
int					Print			G Methanol	
ım					Firm			H Sodium Bisulfate	
ate		Time			Date	1	Time		
elinquished by			!		Received by	y		Evidence samples were tamperd with?	perd with? YES NO
gn					Sign		T	If YES, please explain in section below.	ction below.
int					Print				
TID TID		ļ			Firm				
ite		Time			Date		Time		

Form 3002



Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176 Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

December 20, 2013

Greg Grose Haley & Aldrich, Inc. 7926 Jones Beach Drive Suite 870 Mc Lean, VA 22102

RE: Project: GTW-6047-13-1-A-1 Pace Project No.: 92183254

Dear Greg Grose:

Enclosed are the analytical results for sample(s) received by the laboratory on December 13, 2013. The results relate only to the samples included in this report. Results reported herein conform to the most current TNI standards and the laboratory's Quality Assurance Manual, where applicable, unless otherwise noted in the body of the report.

Analyses were performed at the Pace Analytical Services location indicated on the sample analyte page for analysis unless otherwise footnoted.

If you have any questions concerning this report, please feel free to contact me.

Sincerely,

Kevin Herring

Kein Slern

kevin.herring@pacelabs.com Project Manager

Enclosures





205 East Meadow Road - Suite A Eden, NC 27288 (336)623-8921 Pace Analytical Services, Inc. 2225 Riverside Dr.

Asheville, NC 28804

(828)254-7176

Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

CERTIFICATIONS

Project: GTW-6047-13-1-A-1

Pace Project No.: 92183254

Charlotte Certification IDs

9800 Kincey Ave. Ste 100, Huntersville, NC 28078 North Carolina Drinking Water Certification #: 37706 North Carolina Field Services Certification #: 5342 North Carolina Wastewater Certification #: 12 South Carolina Certification #: 99006001

Florida/NELAP Certification #: E87627 Kentucky UST Certification #: 84 West Virginia Certification #: 357 Virginia/VELAP Certification #: 460221



Pace Analytical Services, Inc. 205 East Meadow Road - Suite A

Meadow Road - Suite A Eden, NC 27288 (336)623-8921 Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176 Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

SAMPLE ANALYTE COUNT

Project: GTW-6047-13-1-A-1

Pace Project No.: 92183254

Lab ID	Sample ID	Method	Analysts	Analytes Reported	Laboratory
92183254001	GTW-607-13-1A-1	EPA 8015 Modified	NU1	2	PASI-C
		EPA 5030/8015 Mod.	GAW	2	PASI-C
		EPA 8260	MCK	63	PASI-C



205 East Meadow Road - Suite A Eden, NC 27288 (336)623-8921

Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804

(828)254-7176

Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

SUMMARY OF DETECTION

Project: GTW-6047-13-1-A-1

Pace Project No.: 92183254

Lab Sample ID Method	Client Sample ID Parameters	Result	Units	Report Limit	Analyzed	Qualifiers
92183254001	GTW-607-13-1A-1		Office	_ Troport Ellinic	- Tildiy 200	Quamioro
92 16325400 1	G1W-007-13-1A-1					
EPA 5030/8015 Mod.	Gasoline Range Organics	2.1 m	ıg/L	0.080	12/17/13 08:57	
EPA 8260	Benzene	10.2 u	g/L	1.0	12/17/13 18:23	
EPA 8260	cis-1,2-Dichloroethene	70.2 u	g/L	1.0	12/17/13 18:23	
EPA 8260	trans-1,2-Dichloroethene	1.0 u	g/L	1.0	12/17/13 18:23	
EPA 8260	Methyl-tert-butyl ether	3.9 u	g/L	1.0	12/17/13 18:23	
EPA 8260	Trichloroethene	43.9 u	g/L	1.0	12/17/13 18:23	
EPA 8260	Vinyl chloride	38.0 u	g/L	1.0	12/17/13 18:23	



Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176 Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

ANALYTICAL RESULTS

Project: GTW-6047-13-1-A-1

Date: 12/20/2013 10:21 AM

Sample: GTW-607-13-1A-1	Lab ID: 921832540	01 Collected: 12/12/	13 11:30	Received: 12	2/13/13 11:00 I	Matrix: Water	
Parameters	Results Uni	ts Report Limit	DF	Prepared	Analyzed	CAS No.	Qua
8015 GCS THC-Diesel	Analytical Method: EP	A 8015 Modified Prepara	ation Me	thod: EPA 3510			
Diesel Components	ND mg/L	0.50	1	12/16/13 14:45	12/17/13 12:59	68334-30-5	
Surrogates (0)	04.0/	10.440		10/10/10 11 15	40/47/40 40 50		
n-Pentacosane (S)	91 %	48-110	1	12/16/13 14:45	12/17/13 12:59	629-99-2	
Gasoline Range Organics	Analytical Method: EP	A 5030/8015 Mod.					
Gasoline Range Organics	2.1 mg/L	0.080	1		12/17/13 08:57	8006-61-9	
Surrogates							
4-Bromofluorobenzene (S)	85 %	70-145	1		12/17/13 08:57	460-00-4	
3260 MSV Low Level	Analytical Method: EP	A 8260					
Acetone	ND ug/L	25.0	1		12/17/13 18:23	8 67-64-1	
Benzene	10.2 ug/L	1.0	1		12/17/13 18:23	3 71-43-2	
Bromobenzene	ND ug/L	1.0	1		12/17/13 18:23	108-86-1	
Bromochloromethane	ND ug/L	1.0	1		12/17/13 18:23	3 74-97-5	
Bromodichloromethane	ND ug/L	1.0	1		12/17/13 18:23	3 75-27-4	
Bromoform	ND ug/L	1.0	1		12/17/13 18:23	3 75-25-2	
Bromomethane	ND ug/L	2.0	1		12/17/13 18:23	3 74-83-9	
-Butanone (MEK)	ND ug/L	5.0	1		12/17/13 18:23	8 78-93-3	
Carbon tetrachloride	ND ug/L	1.0	1		12/17/13 18:23	3 56-23-5	
Chlorobenzene	ND ug/L	1.0	1		12/17/13 18:23	3 108-90-7	
Chloroethane	ND ug/L	1.0	1		12/17/13 18:23	3 75-00-3	
Chloroform	ND ug/L	1.0	1		12/17/13 18:23		
Chloromethane	ND ug/L	1.0	1		12/17/13 18:23		
-Chlorotoluene	ND ug/L	1.0	1		12/17/13 18:23		
-Chlorotoluene	ND ug/L	1.0	1		12/17/13 18:23		
,2-Dibromo-3-chloropropane	ND ug/L	5.0	1		12/17/13 18:23		
Dibromochloromethane	ND ug/L	1.0	1		12/17/13 18:23		
,2-Dibromoethane (EDB)	ND ug/L	1.0	1		12/17/13 18:23		
Dibromomethane	ND ug/L	1.0	1		12/17/13 18:23		
,2-Dichlorobenzene	ND ug/L	1.0	1		12/17/13 18:23		
,3-Dichlorobenzene	ND ug/L	1.0	1		12/17/13 18:23		
.4-Dichlorobenzene	ND ug/L	1.0	1		12/17/13 18:23		
Dichlorodifluoromethane	ND ug/L	1.0	1		12/17/13 18:23		
,1-Dichloroethane	ND ug/L	1.0	1		12/17/13 18:23		
,2-Dichloroethane	ND ug/L	1.0	1		12/17/13 18:23		
,1-Dichloroethene	_	1.0	1		12/17/13 18:23		
is-1,2-Dichloroethene	ND ug/L 70.2 ug/L		1				
,		1.0			12/17/13 18:23		
ans-1,2-Dichloroethene	1.0 ug/L	1.0	1		12/17/13 18:23		
,2-Dichloropropane	ND ug/L	1.0	1		12/17/13 18:23		
,3-Dichloropropane	ND ug/L	1.0	1		12/17/13 18:23		
2,2-Dichloropropane	ND ug/L	1.0	1		12/17/13 18:23		
,1-Dichloropropene	ND ug/L	1.0	1		12/17/13 18:23		
sis-1,3-Dichloropropene	ND ug/L	1.0	1		12/17/13 18:23		
rans-1,3-Dichloropropene	ND ug/L	1.0	1		12/17/13 18:23		
Diisopropyl ether	ND ug/L	1.0	1		12/17/13 18:23		
Ethylbenzene	ND ug/L	1.0	1		12/17/13 18:23		
lexachloro-1,3-butadiene	ND ug/L	1.0	1		12/17/13 18:23	87-68-3	



Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176 Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

ANALYTICAL RESULTS

Project: GTW-6047-13-1-A-1

Pace Project No.: 92183254

Date: 12/20/2013 10:21 AM

Sample: GTW-607-13-1A-1	Lab ID: 92183254001	Collected: 12/12/1	3 11:30	Received: 1	2/13/13 11:00 N	Matrix: Water	
Parameters	Results Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qua
8260 MSV Low Level	Analytical Method: EPA	8260					
2-Hexanone	ND ug/L	5.0	1		12/17/13 18:23	591-78-6	
p-Isopropyltoluene	ND ug/L	1.0	1		12/17/13 18:23	99-87-6	
Methylene Chloride	ND ug/L	2.0	1		12/17/13 18:23	75-09-2	
4-Methyl-2-pentanone (MIBK)	ND ug/L	5.0	1		12/17/13 18:23	108-10-1	
Methyl-tert-butyl ether	3.9 ug/L	1.0	1		12/17/13 18:23	1634-04-4	
Naphthalene	ND ug/L	1.0	1		12/17/13 18:23	91-20-3	
Styrene	ND ug/L	1.0	1		12/17/13 18:23	100-42-5	
1,1,1,2-Tetrachloroethane	ND ug/L	1.0	1		12/17/13 18:23	630-20-6	
1,1,2,2-Tetrachloroethane	ND ug/L	1.0	1		12/17/13 18:23	79-34-5	
Tetrachloroethene	ND ug/L	1.0	1		12/17/13 18:23	127-18-4	
Toluene	ND ug/L	1.0	1		12/17/13 18:23	108-88-3	
1,2,3-Trichlorobenzene	ND ug/L	1.0	1		12/17/13 18:23	87-61-6	
1,2,4-Trichlorobenzene	ND ug/L	1.0	1		12/17/13 18:23	120-82-1	
1,1,1-Trichloroethane	ND ug/L	1.0	1		12/17/13 18:23	71-55-6	
1,1,2-Trichloroethane	ND ug/L	1.0	1		12/17/13 18:23	79-00-5	
Trichloroethene	43.9 ug/L	1.0	1		12/17/13 18:23	79-01-6	
Trichlorofluoromethane	ND ug/L	1.0	1		12/17/13 18:23	75-69-4	
1,2,3-Trichloropropane	ND ug/L	1.0	1		12/17/13 18:23	96-18-4	
Vinyl acetate	ND ug/L	2.0	1		12/17/13 18:23	108-05-4	
Vinyl chloride	38.0 ug/L	1.0	1		12/17/13 18:23	75-01-4	
Xylene (Total)	ND ug/L	2.0	1		12/17/13 18:23	1330-20-7	
m&p-Xylene	ND ug/L	2.0	1		12/17/13 18:23	179601-23-1	
o-Xylene	ND ug/L	1.0	1		12/17/13 18:23	95-47-6	
Surrogates							
4-Bromofluorobenzene (S)	96 %	70-130	1		12/17/13 18:23		
1,2-Dichloroethane-d4 (S)	91 %	70-130	1		12/17/13 18:23		
Toluene-d8 (S)	95 %	70-130	1		12/17/13 18:23	2037-26-5	



205 East Meadow Road - Suite A Eden, NC 27288 (336)623-8921

Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804

(828)254-7176

Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

QUALITY CONTROL DATA

Project:

GTW-6047-13-1-A-1

Pace Project No.:

92183254

QC Batch:

GCV/7612

QC Batch Method:

EPA 5030/8015 Mod.

Analysis Method: Analysis Description: EPA 5030/8015 Mod.

Gasoline Range Organics

Associated Lab Samples: 92183254001

METHOD BLANK: 1106486

Matrix: Water

Associated Lab Samples:

92183254001

Blank Result

Spike

Conc.

Reporting Limit

Qualifiers

Parameter Gasoline Range Organics 4-Bromofluorobenzene (S)

Units mg/L

%

ND 78

LCS

Result

0.080 12/17/13 06:41 70-145 12/17/13 06:41

LABORATORY CONTROL SAMPLE & LCSD:

Parameter

1106487

Units

1106488 **LCSD**

LCS LCSD % Rec % Rec

Analyzed

% Rec Limits

RPD

Max **RPD**

Qualifiers

Gasoline Range Organics 4-Bromofluorobenzene (S)

Date: 12/20/2013 10:21 AM

mg/L %

0.91 0.89 91 80

Result

89 78

70-150 70-145 2

30

REPORT OF LABORATORY ANALYSIS

This report shall not be reproduced, except in full, without the written consent of Pace Analytical Services, Inc..

Page 7 of 16



(336)623-8921

Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176 Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

QUALITY CONTROL DATA

Project: GTW-6047-13-1-A-1

Pace Project No.: 92183254

Date: 12/20/2013 10:21 AM

QC Batch: MSV/25249 Analysis Method: EPA 8260

QC Batch Method: EPA 8260 Analysis Description: 8260 MSV Low Level

Associated Lab Samples: 92183254001

METHOD BLANK: 1107038 Matrix: Water

Associated Lab Samples: 92183254001

Parameter	Units	Blank Result	Reporting Limit	Analyzed	Qualifiers
1,1,1,2-Tetrachloroethane	ug/L		1.0	12/17/13 11:56	
1,1,1-Trichloroethane	ug/L	ND	1.0	12/17/13 11:56	
1,1,2,2-Tetrachloroethane	ug/L	ND	1.0	12/17/13 11:56	
1,1,2-Trichloroethane	ug/L	ND	1.0	12/17/13 11:56	
1,1-Dichloroethane	ug/L	ND	1.0	12/17/13 11:56	
1,1-Dichloroethene	ug/L	ND	1.0	12/17/13 11:56	
1,1-Dichloropropene	ug/L	ND	1.0	12/17/13 11:56	
1,2,3-Trichlorobenzene	ug/L	ND	1.0	12/17/13 11:56	
1,2,3-Trichloropropane	ug/L	ND	1.0	12/17/13 11:56	
1,2,4-Trichlorobenzene	ug/L	ND	1.0	12/17/13 11:56	
1,2-Dibromo-3-chloropropane	ug/L	ND	5.0	12/17/13 11:56	
1,2-Dibromoethane (EDB)	ug/L	ND	1.0	12/17/13 11:56	
1,2-Dichlorobenzene	ug/L	ND	1.0	12/17/13 11:56	
1,2-Dichloroethane	ug/L	ND	1.0	12/17/13 11:56	
1,2-Dichloropropane	ug/L	ND ND	1.0	12/17/13 11:56	
1,3-Dichlorobenzene	ug/L	ND ND	1.0	12/17/13 11:56	
1,3-Dichloropropane	ug/L	ND ND	1.0	12/17/13 11:56	
1,4-Dichlorobenzene	ug/L	ND ND	1.0	12/17/13 11:56	
·	ug/L ug/L	ND ND	1.0	12/17/13 11:56	
2,2-Dichloropropane	ug/L ug/L	ND ND	5.0	12/17/13 11:56	
2-Butanone (MEK)	-	ND ND			
2-Chlorotoluene	ug/L		1.0	12/17/13 11:56	
2-Hexanone	ug/L	ND ND	5.0	12/17/13 11:56	
4-Chlorotoluene	ug/L		1.0	12/17/13 11:56	
4-Methyl-2-pentanone (MIBK)	ug/L	ND	5.0	12/17/13 11:56	
Acetone	ug/L	ND	25.0	12/17/13 11:56	
Benzene	ug/L	ND	1.0	12/17/13 11:56	
Bromobenzene	ug/L	ND	1.0	12/17/13 11:56	
Bromochloromethane	ug/L	ND	1.0	12/17/13 11:56	
Bromodichloromethane	ug/L	ND	1.0	12/17/13 11:56	
Bromoform	ug/L	ND	1.0	12/17/13 11:56	
Bromomethane	ug/L	ND	2.0	12/17/13 11:56	
Carbon tetrachloride	ug/L	ND	1.0	12/17/13 11:56	
Chlorobenzene	ug/L	ND	1.0	12/17/13 11:56	
Chloroethane	ug/L	ND	1.0	12/17/13 11:56	
Chloroform	ug/L	ND	1.0	12/17/13 11:56	
Chloromethane	ug/L	ND	1.0	12/17/13 11:56	
cis-1,2-Dichloroethene	ug/L	ND	1.0	12/17/13 11:56	
cis-1,3-Dichloropropene	ug/L	ND	1.0	12/17/13 11:56	
Dibromochloromethane	ug/L	ND	1.0	12/17/13 11:56	
Dibromomethane	ug/L	ND	1.0	12/17/13 11:56	
Dichlorodifluoromethane	ug/L	ND	1.0	12/17/13 11:56	
Diisopropyl ether	ug/L	ND	1.0	12/17/13 11:56	
Ethylbenzene	ug/L	ND	1.0	12/17/13 11:56	



Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176 Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

QUALITY CONTROL DATA

Project: GTW-6047-13-1-A-1

Pace Project No.: 92183254

Date: 12/20/2013 10:21 AM

METHOD BLANK: 1107038 Matrix: Water

Associated Lab Samples: 92183254001

Parameter	Units	Blank Result	Reporting Limit	Analyzed	Qualifiers
Hexachloro-1,3-butadiene	 ug/L	ND ND	1.0	12/17/13 11:56	
m&p-Xylene	ug/L	ND	2.0	12/17/13 11:56	
Methyl-tert-butyl ether	ug/L	ND	1.0	12/17/13 11:56	
Methylene Chloride	ug/L	ND	2.0	12/17/13 11:56	
Naphthalene	ug/L	ND	1.0	12/17/13 11:56	
o-Xylene	ug/L	ND	1.0	12/17/13 11:56	
p-Isopropyltoluene	ug/L	ND	1.0	12/17/13 11:56	
Styrene	ug/L	ND	1.0	12/17/13 11:56	
Tetrachloroethene	ug/L	ND	1.0	12/17/13 11:56	
Toluene	ug/L	ND	1.0	12/17/13 11:56	
trans-1,2-Dichloroethene	ug/L	ND	1.0	12/17/13 11:56	
trans-1,3-Dichloropropene	ug/L	ND	1.0	12/17/13 11:56	
Trichloroethene	ug/L	ND	1.0	12/17/13 11:56	
Trichlorofluoromethane	ug/L	ND	1.0	12/17/13 11:56	
Vinyl acetate	ug/L	ND	2.0	12/17/13 11:56	
Vinyl chloride	ug/L	ND	1.0	12/17/13 11:56	
Xylene (Total)	ug/L	ND	2.0	12/17/13 11:56	
1,2-Dichloroethane-d4 (S)	%	89	70-130	12/17/13 11:56	
4-Bromofluorobenzene (S)	%	99	70-130	12/17/13 11:56	
Toluene-d8 (S)	%	97	70-130	12/17/13 11:56	

LABORATORY CONTROL SAMPLE:	1107039					
		Spike	LCS	LCS	% Rec	
Parameter	Units	Conc.	Result	% Rec	Limits	Qualifiers
1,1,1,2-Tetrachloroethane	ug/L	50	46.4	93	70-130	
1,1,1-Trichloroethane	ug/L	50	42.7	85	70-130	
1,1,2,2-Tetrachloroethane	ug/L	50	44.6	89	70-130	
1,1,2-Trichloroethane	ug/L	50	45.0	90	70-130	
1,1-Dichloroethane	ug/L	50	42.1	84	70-130	
1,1-Dichloroethene	ug/L	50	39.8	80	70-132	
1,1-Dichloropropene	ug/L	50	46.0	92	70-130	
1,2,3-Trichlorobenzene	ug/L	50	47.3	95	70-135	
1,2,3-Trichloropropane	ug/L	50	44.3	89	70-130	
1,2,4-Trichlorobenzene	ug/L	50	46.8	94	70-134	
1,2-Dibromo-3-chloropropane	ug/L	50	46.5	93	70-130	
1,2-Dibromoethane (EDB)	ug/L	50	48.6	97	70-130	
1,2-Dichlorobenzene	ug/L	50	46.5	93	70-130	
1,2-Dichloroethane	ug/L	50	42.9	86	70-130	
1,2-Dichloropropane	ug/L	50	46.6	93	70-130	
1,3-Dichlorobenzene	ug/L	50	44.6	89	70-130	
1,3-Dichloropropane	ug/L	50	48.5	97	70-130	
1,4-Dichlorobenzene	ug/L	50	45.8	92	70-130	
2,2-Dichloropropane	ug/L	50	44.8	90	58-145	
2-Butanone (MEK)	ug/L	100	95.7	96	70-145	
2-Chlorotoluene	ug/L	50	43.2	86	70-130	



Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176 Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

QUALITY CONTROL DATA

Project: GTW-6047-13-1-A-1

Pace Project No.: 92183254

Date: 12/20/2013 10:21 AM

LABORATORY CONTROL SAMPL	E: 1107039					
Denomination	11.9.	Spike	LCS	LCS	% Rec	Oug PC -
Parameter	Units	Conc.	Result	% Rec	Limits	Qualifiers
2-Hexanone	ug/L	100	91.8	92	70-144	
1-Chlorotoluene	ug/L	50	45.8	92	70-130	
1-Methyl-2-pentanone (MIBK)	ug/L	100	87.8	88	70-140	
Acetone	ug/L	100	84.3	84	50-175	
Benzene	ug/L	50	46.3	93	70-130	
Bromobenzene	ug/L	50	44.0	88	70-130	
Bromochloromethane	ug/L	50	41.7	83	70-130	
Bromodichloromethane	ug/L	50	43.8	88	70-130	
romoform	ug/L	50	47.2	94	70-130	
Bromomethane	ug/L	50	45.9	92	54-130	
Carbon tetrachloride	ug/L	50	43.1	86	70-132	
Chlorobenzene	ug/L	50	45.1	90	70-130	
Chloroethane	ug/L	50	39.2	78	64-134	
Chloroform	ug/L	50	41.6	83	70-130	
Chloromethane	ug/L	50	48.3	97	64-130	
is-1,2-Dichloroethene	ug/L	50	42.5	85	70-131	
is-1,3-Dichloropropene	ug/L	50	47.2	94	70-130	
Dibromochloromethane	ug/L	50	48.4	97	70-130	
Dibromomethane	ug/L	50	44.1	88	70-131	
Dichlorodifluoromethane	ug/L	50	44.2	88	56-130	
Diisopropyl ether	ug/L	50	46.2	92	70-130	
Ethylbenzene	ug/L	50	45.4	91	70-130	
lexachloro-1,3-butadiene	ug/L	50	47.8	96	70-130	
n&p-Xylene	ug/L	100	94.6	95	70-130	
flethyl-tert-butyl ether	ug/L	50	46.4	93	70-130	
Methylene Chloride	ug/L	50	44.4	89	63-130	
laphthalene	ug/L	50	43.1	86	70-138	
o-Xylene	ug/L	50	48.0	96	70-130	
-Isopropyltoluene	ug/L	50	46.5	93	70-130	
Styrene	ug/L	50	48.6	97	70-130	
- Tetrachloroethene	ug/L	50	46.7	93	70-130	
oluene	ug/L	50	42.4	85	70-130	
rans-1,2-Dichloroethene	ug/L	50	41.5	83	70-130	
rans-1,3-Dichloropropene	ug/L	50	47.0	94	70-132	
richloroethene	ug/L	50	46.2	92	70-130	
richlorofluoromethane	ug/L	50	47.0	94	62-133	
inyl acetate	ug/L	100	104	104	66-157	
/inyl chloride	ug/L	50	49.7	99	69-130	
(ylene (Total)	ug/L	150	143	95	70-130	
,2-Dichloroethane-d4 (S)	%			96	70-130	
I-Bromofluorobenzene (S)	%			103	70-130	
Toluene-d8 (S)	%			96	70-130	



205 East Meadow Road - Suite A Eden, NC 27288 (336)623-8921

Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804

(828)254-7176

Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

QUALITY CONTROL DATA

Project: GTW-6047-13-1-A-1

Pace Project No.: 92183254

Date: 12/20/2013 10:21 AM

MATRIX SPIKE & MATRIX SP	IKE DUPLICAT	E: 11070	40		1107041						
			MS	MSD							
	92	183201001	Spike	Spike	MS	MSD	MS	MSD	% Rec		
Parameter	Units	Result	Conc.	Conc.	Result	Result	% Rec	% Rec	Limits	RPD	Qual
1,1-Dichloroethene	ug/L	ND	50	50	50.2	53.6	100	107	70-166	6	
Benzene	ug/L	ND	50	50	55.6	66.7	111	133	70-148	18	
Chlorobenzene	ug/L	ND	50	50	49.2	55.9	98	112	70-146	13	
Toluene	ug/L	1.2	50	50	52.1	56.0	102	110	70-155	7	
Trichloroethene	ug/L	ND	50	50	55.8	59.4	112	119	69-151	6	
1,2-Dichloroethane-d4 (S)	%						92	89	70-130		
4-Bromofluorobenzene (S)	%						103	100	70-130		
Toluene-d8 (S)	%						104	99	70-130		



205 East Meadow Road - Suite A Eden, NC 27288 (336)623-8921

Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176

Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

QUALITY CONTROL DATA

Project:

GTW-6047-13-1-A-1

Pace Project No.:

92183254

QC Batch:

OEXT/25217

QC Batch Method:

EPA 3510

Analysis Method:

EPA 8015 Modified

Analysis Description:

8015 GCS

METHOD BLANK: 1106460

Associated Lab Samples:

92183254001

Matrix: Water

Associated Lab Samples: 92183254001

Parameter

Blank Result Reporting Limit

0.50

Analyzed 12/17/13 11:26 Qualifiers

Diesel Components n-Pentacosane (S)

mg/L %

Units

Units

ND 87

48-110 12/17/13 11:26

LABORATORY CONTROL SAMPLE: 1106461

MATRIX SPIKE & MATRIX SPIKE DUPLICATE:

Parameter

Spike Conc. 10

LCS Result 7.3

LCS % Rec 73 % Rec Limits 41-114

48-110

Qualifiers

Diesel Components n-Pentacosane (S)

mg/L %

Units

mg/L

%

1106463

77

MSD

% Rec

Qual

Parameter **Diesel Components**

92183292001

1106462

ND

Result

MSD MS Spike Spike

MS Result

MSD Result 14.0

% Rec 73 % Rec Limits 41-114

RPD

n-Pentacosane (S)

Date: 12/20/2013 10:21 AM

Conc. Conc. 20

20

14.6

91

MS

70 78

48-110

REPORT OF LABORATORY ANALYSIS

This report shall not be reproduced, except in full, without the written consent of Pace Analytical Services, Inc..



Pace Analytical Services, Inc. 205 East Meadow Road - Suite A

Eden, NC 27288 (336)623-8921 Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176 Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

QUALIFIERS

Project: GTW-6047-13-1-A-1

Pace Project No.: 92183254

DEFINITIONS

DF - Dilution Factor, if reported, represents the factor applied to the reported data due to changes in sample preparation, dilution of the sample aliquot, or moisture content.

ND - Not Detected at or above adjusted reporting limit.

J - Estimated concentration above the adjusted method detection limit and below the adjusted reporting limit.

MDL - Adjusted Method Detection Limit.

PRL - Pace Reporting Limit.

RL - Reporting Limit.

S - Surrogate

1,2-Diphenylhydrazine (8270 listed analyte) decomposes to Azobenzene.

Consistent with EPA guidelines, unrounded data are displayed and have been used to calculate % recovery and RPD values.

LCS(D) - Laboratory Control Sample (Duplicate)

MS(D) - Matrix Spike (Duplicate)

DUP - Sample Duplicate

RPD - Relative Percent Difference

NC - Not Calculable.

SG - Silica Gel - Clean-Up

U - Indicates the compound was analyzed for, but not detected.

N-Nitrosodiphenylamine decomposes and cannot be separated from Diphenylamine using Method 8270. The result reported for each analyte is a combined concentration.

Acid preservation may not be appropriate for 2-Chloroethylvinyl ether, Styrene, and Vinyl chloride.

Pace Analytical is TNI accredited. Contact your Pace PM for the current list of accredited analytes.

TNI - The NELAC Institute.

LABORATORIES

Date: 12/20/2013 10:21 AM

PASI-C Pace Analytical Services - Charlotte



(336)623-8921

Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176 Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

QUALITY CONTROL DATA CROSS REFERENCE TABLE

Project: GTW-6047-13-1-A-1

Pace Project No.: 92183254

Date: 12/20/2013 10:21 AM

Lab ID	Sample ID	QC Batch Method	QC Batch	Analytical Method	Analytical Batch
92183254001	GTW-607-13-1A-1	EPA 3510	OEXT/25217	EPA 8015 Modified	GCSV/16260
92183254001	GTW-607-13-1A-1	EPA 5030/8015 Mod.	GCV/7612		
92183254001	GTW-607-13-1A-1	EPA 8260	MSV/25249		

Document Kevised, December 5, **Document Name:** Page 1 of 2 Sample Condition Upon Receipt (SCUR) Pace Analytical Issuing Authority: **Document Number:** Pace Huntersville Quality Office F-CHR-CS-03-rev.12 Client Name: Halun & AIDRich Richmond, VA Raleigh Huntersville Asheville Eden Where Received: Optional Courier: Fed Ex UPS USPS Client Commercial Pace Other Proj. Due Date: Custody Seal on Cooler/Box Present: yes in no yes Seals intact: Proj. Name: Packing Material: Bubble Wrap Bubble Bags None Other Samples on ice, cooling process has begun Type of Ice: (Wet Blue None Thermometer Used: IR Gun T1102(T1301) T1301: No Correction T1102: No Correction **Temp Correction Factor** Date and Initials of person examining Biological Tissue is Frozen: Yes No N/A С contents: Corrected Cooler Temp.:_ Comments: Temp should be above freezing to 6°C ☑Yes ☐No □N/A Chain of Custody Present: ☑Yes ☐No □N/A Chain of Custody Filled Out: ☑Yes ☐No □N/A Chain of Custody Relinquished: ☑Yes ☐No □N/A Sampler Name & Signature on COC: ☑Yes ☐No □N/A 5. Samples Arrived within Hold Time: ☐Yes ☑No □N/A 6. Short Hold Time Analysis (<72hr): ☐Yes ☐No □N/A 7 Rush Turn Around Time Requested: ☑Yes ☐No □N/A 8. Sufficient Volume: ☑Yes ☐No □N/A 9. Correct Containers Used: ☐Yes ☐No □N/A -Pace Containers Used: ŹYes □No □N/A 10. Containers Intact: □Yes □No N/A 11. Filtered volume received for Dissolved tests ĎYes □No □N/A 112. Sample Labels match COC: m59 -Includes date/time/ID/Analysis All containers needing preservation have been checked. ☐Yes □No □N/A 13. All containers needing preservation are found to be in ☐Yes ☐No ☐N/A compliance with EPA recommendation. □Yes □No exceptions: VOA, coliform, TOC, O&G, WI-DRO (water) □N/A 14. Samples checked for dechlorination: □Yes ⊅No □N/A 15. Headspace in VOA Vials (>6mm): **△**N/A 16. ☐Yes ☐No Trip Blank Present: □Yes □No DN/A Trip Blank Custody Seals Present Pace Trip Blank Lot # (if purchased): Y / N Field Data Required? Client Notification/ Resolution: Date/Time: 12/13/13 Person Contacted: 6NEG 02 SVOC'S Comments/ Resolution: DO NOT RUN

SCURF Review: Date: 12/13/13

SRF Review: Date: 12/16/13

Note: Whenever there is a discrepancy affecting North Carolina compliance samples, a copy of this form will be sent to the North Carolina DEHNR Certification Office (i.e out of hold, incorrect preservative, out of temp, incorrect containers)

WO#:92183254



PALLY NATE District Name Provided Name			THE RESIDENCE OF THE PARTY OF T		_					
Part			Time		Date		CO	Time		Date
HALE NO. AUGUSTON Processing States Pr					Firm					Firm
Part					Print					Print
Part	below.	ES, please explain in section l	If Y		Sign					Sign
Part	YES	dence samples were tamperd	Evi	l by	Received		П	,		Relinquished by
Photo Phot			Time		Date		е	Tim	11	Date
HALEY Active Ac		Sodium Bisulfate			Firm					Firm
Part All Part Al		Methanol			Print					Print
HALP All All		HCL			Sign					Sign
HALFN Albert Miles Albert Miles Mi		H ₂ SO ₄		d by	Received					Relinquished by
HAIPNACH		HNO ₃	D 00/1	12/12/1	Date	PM	N	Tim		12/12/
HALPN Place Albrich, Inc. Place Albrich, Inc. Place Plac		NaOH	C	The	Firm	,				T+ A
HALENO		Sample filtered			Print				ko	Don
Phone CHAIN OF CUSTODY RECORD Phone C703) 356-6280 Process Proce		Sample chilled		N	Sign (Sp.
Phone CHAIN OF CUSTODY RECORD Phone CHOS 356-6280 Phone CHAIN OF CUSTODY RECORD Phone CHOS 356-6280 Phone CHAIN OF CUSTODY RECORD Phone CHOS 356-6280 Phone CHOS 356-4699 Phone Phone CHOS 356-4699 Phone CHOS 356-4699 Phone Sampling Comments	ESERVATION KEY	PR	d by	Receive				by	Sampled and Relinquished	
Hadey & AMFréth. Inc. 1926 James Branch Drive. Suite \$70 1926 James Branch Drive. Suite \$70 2023-002 A0223-002 A0223-002 Bizzand Point (Lot 13. Square 607) Page 1 of 1 1		4		=	8.1				- 	
Haley & Addrich, Inc. Phone (703) 336-6200 Phone (703) 336-62										
Bialey & Atlefelt, Inc. Phone (703) 336-6200 Phone (703) 336-									3 :	
CHAIN OF CUSTODY RECORD Phone (703) 336-62100 Fax (703) 336-										
Haley & Adfrich, Inc. Phone (703) 336-6200 Page 1 of 1										
Haley & Aldrich, Inc. Phone (703) 336-6200 Fax (703) 336-6200 Phone (703) 336-6200										
Haley & Aldrich, Inc. Phone (703) 336-6200 Phone (703) 336-6200 Page Page Phone (703) 336-6200 Page Page Phone (703) 336-6200 Page Phone (703) 336-6200 Page Page Phone (703) 336-6200 Page Page Phone (703) 336-6200 Page			87	. 1						
Haley & Aldrich, Inc. Phone 703) 336-6200 MrLean, VA 22102 MrLean, VA 22102 LABORATORY Pace Analytical Services, Inc. Date Time Depth Type Size Containers Containers VOAN / 12102013 11:30 37.5 Water 1200 mL 1 Plastic				D	1 1				E	
Haley & Aldrich, Inc. Phone (703) 336-6200 Programs Programs Phone (703) 336-6200 Programs P									ì	PE P
Haley & Aldrich, Inc. Phone (703) 336-6200 Fax (703) 356-4699 VACHETICH Haley & Aldrich, Inc. Phone (703) 336-6200 Fax (703) 356-4699 VACHETICH Haley & Aldrich, Inc. Phone (703) 336-6200 Fax (703) 356-4699 VACHETICH Haley & Aldrich, Inc. Phone (703) 336-6200 Fax (703) 356-4699 VACHETICH Haley & Aldrich, Inc. Phone (703) 336-6200 Fax (703) 356-4699 VACHETICH Haley & Aldrich, Inc. Phone (703) 336-6200 VACHETICH Pace Analytical Services, Inc. Pace Analytical Services, Inc.								5 85		
Haley & Aldrich, Inc. 7926 Jones Branch Drive, Suite 870 CHAIN OF CUSTODY RECORD Fax (703) 336-6200 A0223-002	92/83254001	D/F/A	VOCs, TPH-GRO/DRO, SVOCs, PP-motal s		VOAs / Amber Liter /250 mL Plastic	Water	37.5			GTW-607-13-1A-1
Haley & Aldrich, Inc. Phone (703) 336-6200 Phone (703) 356-6200 Phone (703) 356-6200 Phone (703) 356-6200 Phone (703) 356-6200 Phone Phone (703) 356-6200 Phone Pho	nments - (special instructions, precautions, additional method numbers, etc.)		Analysis Requested	No. of Containers	Container Size	Туре	Depth	Time	Date	Sample No.
Haley & Aldrich, Inc. Phone (703) 336-6200 Fax (703) 356-4699	1/00/81 - ETOC		Greg Grose	PROJECT N				Seserko	Don	H&A CONTACT
Haley & Aldrich, Inc. Phone (703) 336-6200 Fax (703) 356-4699 Haley & Aldrich, Inc. Phone (703) 336-6200 Fax (703) 356-4699 Haley & Aldrich, Inc. Phone (703) 356-4699 Page 1 of 1	NAROUND TIMI 5-day		Pace Analytical Se	LABORATC ADDRESS		re 607)	Tot 13. Some	23-002 zard Point (402:	H&A FILE NO. PROJECT NAME
	Phone (703) 336-6200 Fax (703) 356-4699 age 1 of 1	RECORD		CHAI)	te 870	h, Inc. nch Drive, Su 2102	y & Aldric Jones Bra ean, VA 2		

Form 3002

WHITE - Laboratory

CANARY - Project Manager

PINK - Haley & Aldrich Laboratory

GOLDENROD - Haley & Aldrich Contact



Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176 Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

December 23, 2013

Greg Grose Haley & Aldrich, Inc. 7926 Jones Beach Drive Suite 870 Mc Lean, VA 22102

RE: Project: Buzzard Point (Lot 13, Sq 607)

Pace Project No.: 92183318

Dear Greg Grose:

Enclosed are the analytical results for sample(s) received by the laboratory on December 14, 2013. The results relate only to the samples included in this report. Results reported herein conform to the most current TNI standards and the laboratory's Quality Assurance Manual, where applicable, unless otherwise noted in the body of the report.

Analyses were performed at the Pace Analytical Services location indicated on the sample analyte page for analysis unless otherwise footnoted.

If you have any questions concerning this report, please feel free to contact me.

Sincerely,

Kevin Herring

Kein Slern

kevin.herring@pacelabs.com Project Manager

Enclosures





205 East Meadow Road - Suite A Eden, NC 27288 (336)623-8921 Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804

(828)254-7176

Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

CERTIFICATIONS

Project: Buzzard Point (Lot 13, Sq 607)

Pace Project No.: 92183318

Charlotte Certification IDs

9800 Kincey Ave. Ste 100, Huntersville, NC 28078 North Carolina Drinking Water Certification #: 37706 North Carolina Field Services Certification #: 5342 North Carolina Wastewater Certification #: 12 South Carolina Certification #: 99006001 Florida/NELAP Certification #: E87627 Kentucky UST Certification #: 84 West Virginia Certification #: 357 Virginia/VELAP Certification #: 460221



t Meadow Road - Suite A Eden, NC 27288 (336)623-8921 Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176 Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

SAMPLE ANALYTE COUNT

Project: Buzzard Point (Lot 13, Sq 607)

Pace Project No.: 92183318

Lab ID	Sample ID	Method	Analysts	Analytes Reported	Laboratory
92183318001	GTW-607-13-1-1	EPA 8260	MCK	63	PASI-C
92183318002	GTW-607-13-2-1	EPA 8260	MCK	63	PASI-C
92183318003	GTW-607-13-2A-1	EPA 8015 Modified	NU1	2	PASI-C
		EPA 5030/8015 Mod.	GAW	2	PASI-C
		EPA 8260	MCK	63	PASI-C



205 East Meadow Road - Suite A Eden, NC 27288 (336)623-8921 Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176 Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

SUMMARY OF DETECTION

Project: Buzzard Point (Lot 13, Sq 607)

Pace Project No.: 92183318

Lab Sample ID Method	Client Sample ID Parameters	Result	Units	Report Limit	Analyzed	Qualifiers
92183318001	GTW-607-13-1-1					
EPA 8260	Acetone	115 ug/	′L	25.0	12/18/13 18:27	
EPA 8260	Methyl-tert-butyl ether	54.0 ug/	'L	1.0	12/18/13 18:27	
92183318002	GTW-607-13-2-1					
EPA 8260	Acetone	625 ug/	L L	125	12/22/13 21:34	
92183318003	GTW-607-13-2A-1					
EPA 8260	Acetone	79.0 ug/	′L	25.0	12/18/13 18:59	



Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176 Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

ANALYTICAL RESULTS

Project: Buzzard Point (Lot 13, Sq 607)

Date: 12/23/2013 04:01 PM

Sample: GTW-607-13-1-1	Lab ID: 9218	3318001	Collected: 12/13/	13 09:15	Received:	12/14/13 10:15	Matrix: Water	
Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qua
8260 MSV Low Level	Analytical Meth	od: EPA 82	260					
Acetone	115 ug/	L	25.0	1		12/18/13 18:27	67-64-1	
Benzene	ND ug/	L	1.0	1		12/18/13 18:27	71-43-2	
Bromobenzene	ND ug/	L	1.0	1		12/18/13 18:27	108-86-1	
Bromochloromethane	ND ug/	L	1.0	1		12/18/13 18:27	74-97-5	
Bromodichloromethane	ND ug/	L	1.0	1		12/18/13 18:27	7 75-27-4	
Bromoform	ND ug/	L	1.0	1		12/18/13 18:27	75-25-2	
Bromomethane	ND ug/	L	2.0	1		12/18/13 18:27	74-83-9	
2-Butanone (MEK)	ND ug/	L	5.0	1		12/18/13 18:27	78-93-3	
Carbon tetrachloride	ND ug/	L	1.0	1		12/18/13 18:27	7 56-23-5	
Chlorobenzene	ND ug/		1.0	1		12/18/13 18:27	108-90-7	
Chloroethane	ND ug/		1.0	1		12/18/13 18:27		
Chloroform	ND ug/		1.0	1		12/18/13 18:27		
Chloromethane	ND ug/		1.0	1		12/18/13 18:27		
2-Chlorotoluene	ND ug/		1.0	1		12/18/13 18:27		
4-Chlorotoluene	ND ug/		1.0	1		12/18/13 18:27		
1,2-Dibromo-3-chloropropane	ND ug/		5.0	1		12/18/13 18:27		
Dibromochloromethane	ND ug/		1.0	1		12/18/13 18:27		
1,2-Dibromoethane (EDB)	ND ug/		1.0	1		12/18/13 18:27		
Dibromomethane	•			1				
	ND ug/		1.0			12/18/13 18:27		
1,2-Dichlorobenzene	ND ug/		1.0	1		12/18/13 18:27		
1,3-Dichlorobenzene	ND ug/		1.0	1		12/18/13 18:27		
1,4-Dichlorobenzene	ND ug/		1.0	1		12/18/13 18:27		
Dichlorodifluoromethane	ND ug/		1.0	1		12/18/13 18:27		
1,1-Dichloroethane	ND ug/		1.0	1		12/18/13 18:27		
1,2-Dichloroethane	ND ug/		1.0	1		12/18/13 18:27		
1,1-Dichloroethene	ND ug/		1.0	1		12/18/13 18:27	75-35-4	
cis-1,2-Dichloroethene	ND ug/	L	1.0	1		12/18/13 18:27	7 156-59-2	
trans-1,2-Dichloroethene	ND ug/	L	1.0	1		12/18/13 18:27	156-60-5	
1,2-Dichloropropane	ND ug/	L	1.0	1		12/18/13 18:27	78-87-5	
1,3-Dichloropropane	ND ug/	L	1.0	1		12/18/13 18:27	142-28-9	
2,2-Dichloropropane	ND ug/	L	1.0	1		12/18/13 18:27	594-20-7	
1,1-Dichloropropene	ND ug/	L	1.0	1		12/18/13 18:27	7 563-58-6	
cis-1,3-Dichloropropene	ND ug/	L	1.0	1		12/18/13 18:27	10061-01-5	
rans-1,3-Dichloropropene	ND ug/		1.0	1		12/18/13 18:27	10061-02-6	
Diisopropyl ether	ND ug/		1.0	1		12/18/13 18:27	7 108-20-3	
Ethylbenzene	ND ug/		1.0	1		12/18/13 18:27		
Hexachloro-1,3-butadiene	ND ug/		1.0	1		12/18/13 18:27		
2-Hexanone	ND ug/		5.0	1		12/18/13 18:27		
o-Isopropyltoluene	ND ug/		1.0	1		12/18/13 18:27		
Methylene Chloride	ND ug/		2.0	1		12/18/13 18:27		
4-Methyl-2-pentanone (MIBK)	ND ug/		5.0	1		12/18/13 18:27		
	100 ug/ 54.0 ug/			1				
Methyl-tert-butyl ether	ū		1.0			12/18/13 18:27		
Naphthalene	ND ug/		1.0	1		12/18/13 18:27		
Styrene	ND ug/		1.0	1		12/18/13 18:27		
1,1,1,2-Tetrachloroethane	ND ug/		1.0	1		12/18/13 18:27		
1,1,2,2-Tetrachloroethane	ND ug/		1.0	1		12/18/13 18:27		
Tetrachloroethene	ND ug/	L	1.0	1		12/18/13 18:27	7 127-18-4	



(336)623-8921

Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176 Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

ANALYTICAL RESULTS

Project: Buzzard Point (Lot 13, Sq 607)

Pace Project No.: 92183318

Sample: GTW-607-13-1-1	Lab ID: 92183318001	Collected: 12/13/1	3 09:15	Received: 1	2/14/13 10:15	Matrix: Water	
Parameters	Results Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8260 MSV Low Level	Analytical Method: EPA 8	3260					
Toluene	ND ug/L	1.0	1		12/18/13 18:27	7 108-88-3	
1,2,3-Trichlorobenzene	ND ug/L	1.0	1		12/18/13 18:27	7 87-61-6	
1,2,4-Trichlorobenzene	ND ug/L	1.0	1		12/18/13 18:27	7 120-82-1	
1,1,1-Trichloroethane	ND ug/L	1.0	1		12/18/13 18:27	7 71-55-6	
1,1,2-Trichloroethane	ND ug/L	1.0	1		12/18/13 18:27	7 79-00-5	
Trichloroethene	ND ug/L	1.0	1		12/18/13 18:27	7 79-01-6	
Trichlorofluoromethane	ND ug/L	1.0	1		12/18/13 18:27	7 75-69-4	
1,2,3-Trichloropropane	ND ug/L	1.0	1		12/18/13 18:27	7 96-18-4	
Vinyl acetate	ND ug/L	2.0	1		12/18/13 18:27	7 108-05-4	
Vinyl chloride	ND ug/L	1.0	1		12/18/13 18:27	7 75-01-4	
Xylene (Total)	ND ug/L	2.0	1		12/18/13 18:27	7 1330-20-7	
m&p-Xylene	ND ug/L	2.0	1		12/18/13 18:27	7 179601-23-1	
o-Xylene	ND ug/L	1.0	1		12/18/13 18:27	7 95-47-6	
Surrogates	_						
4-Bromofluorobenzene (S)	99 %	70-130	1		12/18/13 18:27	7 460-00-4	
1,2-Dichloroethane-d4 (S)	87 %	70-130	1		12/18/13 18:27	7 17060-07-0	
Toluene-d8 (S)	95 %	70-130	1		12/18/13 18:27	7 2037-26-5	



Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176 Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

ANALYTICAL RESULTS

Project: Buzzard Point (Lot 13, Sq 607)

Date: 12/23/2013 04:01 PM

Sample: GTW-607-13-2-1	Lab ID: 9218331800	2 Collected: 12/13/1	3 10:00	Received:	12/14/13 10:15	Matrix: Water	
Parameters	Results Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qua
8260 MSV Low Level	Analytical Method: EPA	8260					
Acetone	625 ug/L	125	5		12/22/13 21:3	4 67-64-1	
Benzene	ND ug/L	1.0	1		12/18/13 18:4	3 71-43-2	
Bromobenzene	ND ug/L	1.0	1		12/18/13 18:4	3 108-86-1	
Bromochloromethane	ND ug/L	1.0	1		12/18/13 18:4	3 74-97-5	
Bromodichloromethane	ND ug/L	1.0	1		12/18/13 18:4	3 75-27-4	
Bromoform	ND ug/L	1.0	1		12/18/13 18:4	3 75-25-2	
Bromomethane	ND ug/L	2.0	1		12/18/13 18:4	3 74-83-9	
2-Butanone (MEK)	ND ug/L	5.0	1		12/18/13 18:4	3 78-93-3	
Carbon tetrachloride	ND ug/L	1.0	1		12/18/13 18:4	3 56-23-5	
Chlorobenzene	ND ug/L	1.0	1		12/18/13 18:4	3 108-90-7	
Chloroethane	ND ug/L	1.0	1		12/18/13 18:4	3 75-00-3	
Chloroform	ND ug/L	1.0	1		12/18/13 18:4	3 67-66-3	
Chloromethane	ND ug/L	1.0	1		12/18/13 18:4	3 74-87-3	
2-Chlorotoluene	ND ug/L	1.0	1		12/18/13 18:4		
4-Chlorotoluene	ND ug/L	1.0	1		12/18/13 18:4		
1,2-Dibromo-3-chloropropane	ND ug/L	5.0	1		12/18/13 18:4		
Dibromochloromethane	ND ug/L	1.0	1		12/18/13 18:4		
,2-Dibromoethane (EDB)	ND ug/L	1.0	1		12/18/13 18:4		
Dibromomethane	ND ug/L	1.0	1		12/18/13 18:4		
,2-Dichlorobenzene	ND ug/L	1.0	1		12/18/13 18:4		
1,3-Dichlorobenzene	ND ug/L	1.0	1		12/18/13 18:4		
,4-Dichlorobenzene	ND ug/L	1.0	1		12/18/13 18:4		
Dichlorodifluoromethane	_	1.0	1		12/18/13 18:4		
	ND ug/L						
I,1-Dichloroethane	ND ug/L	1.0	1		12/18/13 18:4		
1,2-Dichloroethane	ND ug/L	1.0	1		12/18/13 18:4		
1,1-Dichloroethene	ND ug/L	1.0	1		12/18/13 18:4		
cis-1,2-Dichloroethene	ND ug/L	1.0	1		12/18/13 18:4		
rans-1,2-Dichloroethene	ND ug/L	1.0	1		12/18/13 18:4		
1,2-Dichloropropane	ND ug/L	1.0	1		12/18/13 18:4		
1,3-Dichloropropane	ND ug/L	1.0	1		12/18/13 18:4		
2,2-Dichloropropane	ND ug/L	1.0	1		12/18/13 18:4		
1,1-Dichloropropene	ND ug/L	1.0	1		12/18/13 18:4		
cis-1,3-Dichloropropene	ND ug/L	1.0	1			3 10061-01-5	
rans-1,3-Dichloropropene	ND ug/L	1.0	1			3 10061-02-6	
Diisopropyl ether	ND ug/L	1.0	1		12/18/13 18:4		
Ethylbenzene	ND ug/L	1.0	1		12/18/13 18:4		
Hexachloro-1,3-butadiene	ND ug/L	1.0	1		12/18/13 18:4		
2-Hexanone	ND ug/L	5.0	1		12/18/13 18:4	3 591-78-6	
o-Isopropyltoluene	ND ug/L	1.0	1		12/18/13 18:4	3 99-87-6	
Methylene Chloride	ND ug/L	2.0	1		12/18/13 18:4	3 75-09-2	
I-Methyl-2-pentanone (MIBK)	ND ug/L	5.0	1		12/18/13 18:4	3 108-10-1	
Methyl-tert-butyl ether	ND ug/L	1.0	1		12/18/13 18:4	3 1634-04-4	
Naphthalene	ND ug/L	1.0	1		12/18/13 18:4	3 91-20-3	
Styrene	ND ug/L	1.0	1		12/18/13 18:4	3 100-42-5	
,1,1,2-Tetrachloroethane	ND ug/L	1.0	1		12/18/13 18:4		
1,1,2,2-Tetrachloroethane	ND ug/L	1.0	1		12/18/13 18:4		
Tetrachloroethene	ND ug/L	1.0	1		12/18/13 18:4		



 I Services, Inc.
 Pace Analytical Services, Inc.

 y Road - Suite A
 2225 Riverside Dr.

 iden, NC 27288
 Asheville, NC 28804

 (336)623-8921
 (828)254-7176

Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

ANALYTICAL RESULTS

Project: Buzzard Point (Lot 13, Sq 607)

Pace Project No.: 92183318

Sample: GTW-607-13-2-1	Lab ID: 921833180	002 Collected: 12/13/1	3 10:00	Received: 12/14	4/13 10:15 N	Matrix: Water	
Parameters	Results Un	its Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
8260 MSV Low Level	Analytical Method: EF	PA 8260					
Toluene	ND ug/L	1.0	1	1:	2/18/13 18:43	108-88-3	
1,2,3-Trichlorobenzene	ND ug/L	1.0	1	1:	2/18/13 18:43	87-61-6	
1,2,4-Trichlorobenzene	ND ug/L	1.0	1	1:	2/18/13 18:43	120-82-1	
1,1,1-Trichloroethane	ND ug/L	1.0	1	1:	2/18/13 18:43	71-55-6	
1,1,2-Trichloroethane	ND ug/L	1.0	1	1:	2/18/13 18:43	79-00-5	
Trichloroethene	ND ug/L	1.0	1	1:	2/18/13 18:43	79-01-6	
Trichlorofluoromethane	ND ug/L	1.0	1	1:	2/18/13 18:43	75-69-4	
1,2,3-Trichloropropane	ND ug/L	1.0	1	1:	2/18/13 18:43	96-18-4	
Vinyl acetate	ND ug/L	2.0	1	1:	2/18/13 18:43	108-05-4	
Vinyl chloride	ND ug/L	1.0	1	1:	2/18/13 18:43	75-01-4	
Xylene (Total)	ND ug/L	2.0	1	1:	2/18/13 18:43	1330-20-7	
m&p-Xylene	ND ug/L	2.0	1	1:	2/18/13 18:43	179601-23-1	
o-Xylene	ND ug/L	1.0	1	1:	2/18/13 18:43	95-47-6	
Surrogates							
4-Bromofluorobenzene (S)	99 %	70-130	1	1:	2/18/13 18:43	460-00-4	
1,2-Dichloroethane-d4 (S)	91 %	70-130	1	1:	2/18/13 18:43	17060-07-0	
Toluene-d8 (S)	100 %	70-130	1	1:	2/18/13 18:43	2037-26-5	



Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176 Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

ANALYTICAL RESULTS

Project: Buzzard Point (Lot 13, Sq 607)

Date: 12/23/2013 04:01 PM

Sample: GTW-607-13-2A-1	Lab ID: 921833180	03 Collected: 12/13/	13 10:30	Received: 12	2/14/13 10:15 I	Matrix: Water	
Parameters	Results Uni	ts Report Limit	DF	Prepared	Analyzed	CAS No.	Qua
3015 GCS THC-Diesel	Analytical Method: EP	A 8015 Modified Prepara	ation Me	thod: EPA 3510			
Diesel Components	ND mg/L	0.50	1	12/16/13 14:45	12/17/13 13:46	68334-30-5	
Surrogates							
n-Pentacosane (S)	85 %	48-110	1	12/16/13 14:45	12/17/13 13:46	629-99-2	
Gasoline Range Organics	Analytical Method: EP	A 5030/8015 Mod.					
Gasoline Range Organics	ND mg/L	0.080	1		12/17/13 09:43	8006-61-9	
Surrogates							
4-Bromofluorobenzene (S)	86 %	70-145	1		12/17/13 09:43	460-00-4	
2260 MSV Low Level	Analytical Method: EP	A 8260					
Acetone	79.0 ug/L	25.0	1		12/18/13 18:59	67-64-1	
Benzene	ND ug/L	1.0	1		12/18/13 18:59	71-43-2	
Bromobenzene	ND ug/L	1.0	1		12/18/13 18:59	108-86-1	
Bromochloromethane	ND ug/L	1.0	1		12/18/13 18:59	74-97-5	
Bromodichloromethane	ND ug/L	1.0	1		12/18/13 18:59	75-27-4	
Bromoform	ND ug/L	1.0	1		12/18/13 18:59	75-25-2	
Bromomethane	ND ug/L	2.0	1		12/18/13 18:59	74-83-9	
-Butanone (MEK)	ND ug/L	5.0	1		12/18/13 18:59	78-93-3	
Carbon tetrachloride	ND ug/L	1.0	1		12/18/13 18:59		
Chlorobenzene	ND ug/L	1.0	1		12/18/13 18:59		
Chloroethane	ND ug/L	1.0	1		12/18/13 18:59		
Chloroform	ND ug/L	1.0	1		12/18/13 18:59		
Chloromethane	ND ug/L	1.0	1		12/18/13 18:59		
-Chlorotoluene	ND ug/L	1.0	1		12/18/13 18:59		
-Chlorotoluene	ND ug/L	1.0	1		12/18/13 18:59		
	ND ug/L	5.0	1		12/18/13 18:59		
,2-Dibromo-3-chloropropane			1				
Dibromochloromethane	ND ug/L	1.0			12/18/13 18:59		
,2-Dibromoethane (EDB)	ND ug/L	1.0	1		12/18/13 18:59		
Dibromomethane	ND ug/L	1.0	1		12/18/13 18:59		
,2-Dichlorobenzene	ND ug/L	1.0	1		12/18/13 18:59		
,3-Dichlorobenzene	ND ug/L	1.0	1		12/18/13 18:59		
,4-Dichlorobenzene	ND ug/L	1.0	1		12/18/13 18:59		
Dichlorodifluoromethane	ND ug/L	1.0	1		12/18/13 18:59		
,1-Dichloroethane	ND ug/L	1.0	1		12/18/13 18:59		
,2-Dichloroethane	ND ug/L	1.0	1		12/18/13 18:59		
,1-Dichloroethene	ND ug/L	1.0	1		12/18/13 18:59	75-35-4	
is-1,2-Dichloroethene	ND ug/L	1.0	1		12/18/13 18:59	156-59-2	
ans-1,2-Dichloroethene	ND ug/L	1.0	1		12/18/13 18:59	156-60-5	
,2-Dichloropropane	ND ug/L	1.0	1		12/18/13 18:59	78-87-5	
,3-Dichloropropane	ND ug/L	1.0	1		12/18/13 18:59	142-28-9	
,2-Dichloropropane	ND ug/L	1.0	1		12/18/13 18:59	594-20-7	
,1-Dichloropropene	ND ug/L	1.0	1		12/18/13 18:59	563-58-6	
is-1,3-Dichloropropene	ND ug/L	1.0	1		12/18/13 18:59	10061-01-5	
rans-1,3-Dichloropropene	ND ug/L	1.0	1		12/18/13 18:59	10061-02-6	
Diisopropyl ether	ND ug/L	1.0	1		12/18/13 18:59		
Ethylbenzene	ND ug/L	1.0	1		12/18/13 18:59		
Hexachloro-1,3-butadiene	ND ug/L	1.0	1		12/18/13 18:59		



(336)623-8921

Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176 Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

ANALYTICAL RESULTS

Project: Buzzard Point (Lot 13, Sq 607)

Pace Project No.: 92183318

Sample: GTW-607-13-2A-1	Lab ID: 92183318003	Collected: 12/13/1	3 10:30	Received: 1	12/14/13 10:15 N	Matrix: Water	
Parameters	Results Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qua
8260 MSV Low Level	Analytical Method: EPA	3260					
2-Hexanone	ND ug/L	5.0	1		12/18/13 18:59	591-78-6	
p-Isopropyltoluene	ND ug/L	1.0	1		12/18/13 18:59	99-87-6	
Methylene Chloride	ND ug/L	2.0	1		12/18/13 18:59	75-09-2	
4-Methyl-2-pentanone (MIBK)	ND ug/L	5.0	1		12/18/13 18:59	108-10-1	
Methyl-tert-butyl ether	ND ug/L	1.0	1		12/18/13 18:59	1634-04-4	
Naphthalene	ND ug/L	1.0	1		12/18/13 18:59	91-20-3	
Styrene	ND ug/L	1.0	1		12/18/13 18:59	100-42-5	
1,1,1,2-Tetrachloroethane	ND ug/L	1.0	1		12/18/13 18:59	630-20-6	
1,1,2,2-Tetrachloroethane	ND ug/L	1.0	1		12/18/13 18:59	79-34-5	
Tetrachloroethene	ND ug/L	1.0	1		12/18/13 18:59	127-18-4	
Toluene	ND ug/L	1.0	1		12/18/13 18:59	108-88-3	
1,2,3-Trichlorobenzene	ND ug/L	1.0	1		12/18/13 18:59	87-61-6	
1,2,4-Trichlorobenzene	ND ug/L	1.0	1		12/18/13 18:59	120-82-1	
1,1,1-Trichloroethane	ND ug/L	1.0	1		12/18/13 18:59	71-55-6	
1,1,2-Trichloroethane	ND ug/L	1.0	1		12/18/13 18:59	79-00-5	
Trichloroethene	ND ug/L	1.0	1		12/18/13 18:59	79-01-6	
Trichlorofluoromethane	ND ug/L	1.0	1		12/18/13 18:59	75-69-4	
1,2,3-Trichloropropane	ND ug/L	1.0	1		12/18/13 18:59	96-18-4	
Vinyl acetate	ND ug/L	2.0	1		12/18/13 18:59	108-05-4	
Vinyl chloride	ND ug/L	1.0	1		12/18/13 18:59	75-01-4	
Xylene (Total)	ND ug/L	2.0	1		12/18/13 18:59	1330-20-7	
m&p-Xylene	ND ug/L	2.0	1		12/18/13 18:59	179601-23-1	
o-Xylene	ND ug/L	1.0	1		12/18/13 18:59	95-47-6	
Surrogates							
4-Bromofluorobenzene (S)	99 %	70-130	1		12/18/13 18:59		
1,2-Dichloroethane-d4 (S)	87 %	70-130	1		12/18/13 18:59		
Toluene-d8 (S)	95 %	70-130	1		12/18/13 18:59	2037-26-5	



205 East Meadow Road - Suite A Eden, NC 27288 (336)623-8921

Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804

(828)254-7176

Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

QUALITY CONTROL DATA

Project: Buzzard Point (Lot 13, Sq 607)

Pace Project No.: 92183318

Date: 12/23/2013 04:01 PM

QC Batch: GCV/7612 Analysis Method: EPA 5030/8015 Mod.

QC Batch Method: EPA 5030/8015 Mod. Analysis Description: Gasoline Range Organics

Associated Lab Samples: 92183318003

METHOD BLANK: 1106486 Matrix: Water

Associated Lab Samples: 92183318003

ParameterUnitsBlank ResultReporting LimitAnalyzedQualifiersGasoline Range Organicsmg/LND0.08012/17/13 06:41

4-Bromofluorobenzene (S) % 78 70-145 12/17/13 06:41

LABORATORY CONTROL SAMI	PLE & LCSD: 1106487		1′	106488						
		Spike	LCS	LCSD	LCS	LCSD	% Rec		Max	
Parameter	Units	Conc.	Result	Result	% Rec	% Rec	Limits	RPD	RPD	Qualifiers
Gasoline Range Organics	mg/L	1	0.91	0.89	91	89	70-150	2	30	
4-Bromofluorobenzene (S)	%				80	78	70-145			



(336)623-8921

Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176 Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

QUALITY CONTROL DATA

Project: Buzzard Point (Lot 13, Sq 607)

Pace Project No.: 92183318

Date: 12/23/2013 04:01 PM

QC Batch: MSV/25269 Analysis Method: EPA 8260

QC Batch Method: EPA 8260 Analysis Description: 8260 MSV Low Level

Associated Lab Samples: 92183318001, 92183318002, 92183318003

METHOD BLANK: 1108221 Matrix: Water

Associated Lab Samples: 92183318001, 92183318002, 92183318003

Parameter	Units	Blank Result	Reporting Limit	Analyzed	Qualifiers
1,1,1,2-Tetrachloroethane	ug/L		1.0	12/18/13 13:21	
1,1,1-Trichloroethane	ug/L	ND ND	1.0	12/18/13 13:21	
1,1,2,2-Tetrachloroethane	ug/L	ND ND	1.0	12/18/13 13:21	
1,1,2-Trichloroethane	ug/L	ND	1.0	12/18/13 13:21	
1,1-Dichloroethane	ug/L	ND ND	1.0	12/18/13 13:21	
1,1-Dichloroethene	ug/L	ND	1.0	12/18/13 13:21	
1,1-Dichloropropene	ug/L	ND ND	1.0	12/18/13 13:21	
1,2,3-Trichlorobenzene	ug/L	ND	1.0	12/18/13 13:21	
1,2,3-Trichloropropane	ug/L	ND	1.0	12/18/13 13:21	
1,2,4-Trichlorobenzene	ug/L	ND	1.0	12/18/13 13:21	
1,2-Dibromo-3-chloropropane	ug/L	ND	5.0	12/18/13 13:21	
1,2-Dibromoethane (EDB)	ug/L	ND ND	1.0	12/18/13 13:21	
1,2-Dichlorobenzene	ug/L	ND	1.0	12/18/13 13:21	
1,2-Dichloroethane	ug/L	ND ND	1.0	12/18/13 13:21	
1,2-Dichloropropane	ug/L	ND ND	1.0	12/18/13 13:21	
1,3-Dichlorobenzene	ug/L	ND ND	1.0	12/18/13 13:21	
1,3-Dichloropropane	ug/L	ND ND	1.0	12/18/13 13:21	
1,4-Dichlorobenzene	ug/L	ND ND	1.0	12/18/13 13:21	
2,2-Dichloropropane	ug/L	ND ND	1.0	12/18/13 13:21	
2-Butanone (MEK)	ug/L	ND ND	5.0	12/18/13 13:21	
2-Chlorotoluene	ug/L	ND ND	1.0	12/18/13 13:21	
2-Hexanone	ug/L	ND ND	5.0	12/18/13 13:21	
4-Chlorotoluene	ug/L	ND ND	1.0	12/18/13 13:21	
4-Methyl-2-pentanone (MIBK)	ug/L	ND ND	5.0	12/18/13 13:21	
Acetone	ug/L	ND ND	25.0	12/18/13 13:21	
Benzene	ug/L	ND ND	1.0	12/18/13 13:21	
Bromobenzene	ug/L ug/L	ND ND	1.0	12/18/13 13:21	
Bromochloromethane	•	ND ND	1.0	12/18/13 13:21	
Bromodichloromethane	ug/L	ND ND	1.0	12/18/13 13:21	
Bromoform	ug/L ug/L	ND ND	1.0	12/18/13 13:21	
	•	ND ND	2.0	12/18/13 13:21	
Bromomethane Carbon tetrachloride	ug/L	ND ND	1.0	12/18/13 13:21	
Chlorobenzene	ug/L	ND ND	1.0		
	ug/L		_	12/18/13 13:21	
Chloroethane	ug/L	ND	1.0	12/18/13 13:21	
Chloroform	ug/L	ND	1.0	12/18/13 13:21	
Chloromethane	ug/L	ND	1.0	12/18/13 13:21	
cis-1,2-Dichloroethene	ug/L	ND	1.0	12/18/13 13:21	
cis-1,3-Dichloropropene	ug/L	ND	1.0	12/18/13 13:21	
Dibromochloromethane	ug/L	ND	1.0	12/18/13 13:21	
Dibromomethane	ug/L	ND	1.0	12/18/13 13:21	
Dichlorodifluoromethane	ug/L	ND	1.0	12/18/13 13:21	
Diisopropyl ether	ug/L	ND	1.0	12/18/13 13:21	
Ethylbenzene	ug/L	ND	1.0	12/18/13 13:21	



Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176 Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

QUALITY CONTROL DATA

Project: Buzzard Point (Lot 13, Sq 607)

Pace Project No.: 92183318

METHOD BLANK: 1108221 Matrix: Water

Associated Lab Samples: 92183318001, 92183318002, 92183318003

		Blank	Reporting		
Parameter	Units	Result	Limit	Analyzed	Qualifiers
Hexachloro-1,3-butadiene	ug/L	ND ND	1.0	12/18/13 13:21	
m&p-Xylene	ug/L	ND	2.0	12/18/13 13:21	
Methyl-tert-butyl ether	ug/L	ND	1.0	12/18/13 13:21	
Methylene Chloride	ug/L	ND	2.0	12/18/13 13:21	
Naphthalene	ug/L	ND	1.0	12/18/13 13:21	
o-Xylene	ug/L	ND	1.0	12/18/13 13:21	
p-Isopropyltoluene	ug/L	ND	1.0	12/18/13 13:21	
Styrene	ug/L	ND	1.0	12/18/13 13:21	
Tetrachloroethene	ug/L	ND	1.0	12/18/13 13:21	
Toluene	ug/L	ND	1.0	12/18/13 13:21	
trans-1,2-Dichloroethene	ug/L	ND	1.0	12/18/13 13:21	
trans-1,3-Dichloropropene	ug/L	ND	1.0	12/18/13 13:21	
Trichloroethene	ug/L	ND	1.0	12/18/13 13:21	
Trichlorofluoromethane	ug/L	ND	1.0	12/18/13 13:21	
Vinyl acetate	ug/L	ND	2.0	12/18/13 13:21	
Vinyl chloride	ug/L	ND	1.0	12/18/13 13:21	
Xylene (Total)	ug/L	ND	2.0	12/18/13 13:21	
1,2-Dichloroethane-d4 (S)	%	86	70-130	12/18/13 13:21	
4-Bromofluorobenzene (S)	%	99	70-130	12/18/13 13:21	
Toluene-d8 (S)	%	101	70-130	12/18/13 13:21	

LABORATORY CONTROL SAMPLE: 1108222

Date: 12/23/2013 04:01 PM

Parameter	Units	Spike Conc.	LCS Result	LCS % Rec	% Rec Limits	Qualifiers
1,1,1,2-Tetrachloroethane	ug/L		44.1		70-130	
1,1,1-Trichloroethane	ug/L	50	40.6	81	70-130	
1,1,2,2-Tetrachloroethane	ug/L	50	44.0	88	70-130	
1,1,2-Trichloroethane	ug/L	50	44.7	89	70-130	
1,1-Dichloroethane	ug/L	50	40.0	80	70-130	
1,1-Dichloroethene	ug/L	50	40.9	82	70-132	
1,1-Dichloropropene	ug/L	50	44.1	88	70-130	
1,2,3-Trichlorobenzene	ug/L	50	55.4	111	70-135	
1,2,3-Trichloropropane	ug/L	50	42.6	85	70-130	
1,2,4-Trichlorobenzene	ug/L	50	54.4	109	70-134	
1,2-Dibromo-3-chloropropane	ug/L	50	43.4	87	70-130	
1,2-Dibromoethane (EDB)	ug/L	50	45.7	91	70-130	
1,2-Dichlorobenzene	ug/L	50	48.2	96	70-130	
1,2-Dichloroethane	ug/L	50	40.9	82	70-130	
1,2-Dichloropropane	ug/L	50	46.6	93	70-130	
1,3-Dichlorobenzene	ug/L	50	46.5	93	70-130	
1,3-Dichloropropane	ug/L	50	45.7	91	70-130	
1,4-Dichlorobenzene	ug/L	50	47.5	95	70-130	
2,2-Dichloropropane	ug/L	50	42.1	84	58-145	
2-Butanone (MEK)	ug/L	100	81.1	81	70-145	
2-Chlorotoluene	ug/L	50	43.8	88	70-130	



Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176 Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

QUALITY CONTROL DATA

Project: Buzzard Point (Lot 13, Sq 607)

Pace Project No.: 92183318

Date: 12/23/2013 04:01 PM

LABORATORY CONTROL SAMPL	E: 1108222	0 "		1.00	0/ 5	
Parameter	Units	Spike Conc.	LCS Result	LCS % Rec	% Rec Limits	Qualifiers
						Quaiilleis
2-Hexanone	ug/L	100	80.7	81	70-144	
1-Chlorotoluene	ug/L	50	46.4	93	70-130	
1-Methyl-2-pentanone (MIBK)	ug/L	100	86.7	87	70-140	
Acetone	ug/L	100	69.4	69	50-175	
Benzene	ug/L	50	45.6	91	70-130	
Bromobenzene	ug/L	50	44.4	89	70-130	
Bromochloromethane	ug/L	50	37.7	75	70-130	
Bromodichloromethane	ug/L	50	43.4	87	70-130	
Bromoform	ug/L	50	42.7	85	70-130	
Bromomethane	ug/L	50	45.8	92	54-130	
Carbon tetrachloride	ug/L	50	41.7	83	70-132	
Chlorobenzene	ug/L	50	44.3	89	70-130	
Chloroethane	ug/L	50	43.1	86	64-134	
Chloroform	ug/L	50	40.1	80	70-130	
Chloromethane	ug/L	50	46.8	94	64-130	
is-1,2-Dichloroethene	ug/L	50	40.5	81	70-131	
is-1,3-Dichloropropene	ug/L	50	45.7	91	70-130	
ibromochloromethane	ug/L	50	44.2	88	70-130	
Dibromomethane	ug/L	50	44.8	90	70-131	
Dichlorodifluoromethane	ug/L	50	48.5	97	56-130	
Diisopropyl ether	ug/L	50	43.0	86	70-130	
thylbenzene	ug/L	50	42.5	85	70-130	
lexachloro-1,3-butadiene	ug/L	50	52.6	105	70-130	
n&p-Xylene	ug/L	100	85.5	85	70-130	
Nethyl-tert-butyl ether	ug/L	50	43.7	87	70-130	
Methylene Chloride	ug/L	50	41.9	84	63-130	
laphthalene	ug/L	50	49.1	98	70-138	
-Xylene	ug/L	50	44.3	89	70-130	
-Isopropyltoluene	ug/L	50	47.8	96	70-130	
Styrene	ug/L	50	44.2	88	70-130	
etrachloroethene	ug/L	50	44.8	90	70-130	
oluene	ug/L	50	44.4	89	70-130	
rans-1,2-Dichloroethene	ug/L ug/L	50 50	40.7	81	70-130	
rans-1,3-Dichloropropene	ug/L ug/L	50 50	45.5	91	70-130	
richloroethene	ug/L	50 50	44.4	89	70-132	
richlorofluoromethane	•	50 50	44.4 48.2	96	62-133	
	ug/L	100	46.2 96.0	96 96	66-157	
'inyl acetate	ug/L					
/inyl chloride	ug/L	50 150	48.7	97	69-130	
(ylene (Total)	ug/L	150	130	87	70-130	
,2-Dichloroethane-d4 (S)	%			90	70-130	
I-Bromofluorobenzene (S)	%			96	70-130	
Гoluene-d8 (S)	%			97	70-130	



205 East Meadow Road - Suite A Eden, NC 27288 (336)623-8921

Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176

Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

QUALITY CONTROL DATA

Project: Buzzard Point (Lot 13, Sq 607)

Pace Project No.: 92183318

QC Batch: OEXT/25217

EPA 3510

Analysis Method:

EPA 8015 Modified

Analysis Description: 8015 GCS

Associated Lab Samples: 92183318003

METHOD BLANK: 1106460

Matrix: Water

Associated Lab Samples:

QC Batch Method:

92183318003

Blank

Reporting Limit

Qualifiers Analyzed

Parameter **Diesel Components**

Units mg/L

%

ND 87

0.50 12/17/13 11:26 48-110 12/17/13 11:26

LABORATORY CONTROL SAMPLE:

Parameter

Parameter

1106461

Spike Conc.

Result

LCS Result

LCS % Rec % Rec Limits

Qualifiers

Diesel Components n-Pentacosane (S)

n-Pentacosane (S)

mg/L %

Units

mg/L

%

Units 10

7.3

73 41-114 77 48-110

MATRIX SPIKE & MATRIX SPIKE DUPLICATE:

1106462

92183292001

Result

ND

1106463

20

MSD MS

MS

MS

MSD % Rec

78

% Rec Limits **RPD** Qual

Diesel Components n-Pentacosane (S)

Date: 12/23/2013 04:01 PM

Spike

20

Spike Conc. Conc.

MSD Result Result 14.6 14.0

% Rec 73

91

70 41-114

48-110



(336)623-8921

Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176 Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

QUALIFIERS

Project: Buzzard Point (Lot 13, Sq 607)

Pace Project No.: 92183318

DEFINITIONS

DF - Dilution Factor, if reported, represents the factor applied to the reported data due to changes in sample preparation, dilution of the sample aliquot, or moisture content.

ND - Not Detected at or above adjusted reporting limit.

J - Estimated concentration above the adjusted method detection limit and below the adjusted reporting limit.

MDL - Adjusted Method Detection Limit.

PRL - Pace Reporting Limit.

RL - Reporting Limit.

S - Surrogate

1,2-Diphenylhydrazine (8270 listed analyte) decomposes to Azobenzene.

Consistent with EPA guidelines, unrounded data are displayed and have been used to calculate % recovery and RPD values.

LCS(D) - Laboratory Control Sample (Duplicate)

MS(D) - Matrix Spike (Duplicate)

DUP - Sample Duplicate

RPD - Relative Percent Difference

NC - Not Calculable.

SG - Silica Gel - Clean-Up

U - Indicates the compound was analyzed for, but not detected.

N-Nitrosodiphenylamine decomposes and cannot be separated from Diphenylamine using Method 8270. The result reported for each analyte is a combined concentration.

Acid preservation may not be appropriate for 2-Chloroethylvinyl ether, Styrene, and Vinyl chloride.

Pace Analytical is TNI accredited. Contact your Pace PM for the current list of accredited analytes.

TNI - The NELAC Institute.

LABORATORIES

Date: 12/23/2013 04:01 PM

PASI-C Pace Analytical Services - Charlotte



Pace Analytical Services, Inc. 2225 Riverside Dr. Asheville, NC 28804 (828)254-7176 Pace Analytical Services, Inc. 9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

QUALITY CONTROL DATA CROSS REFERENCE TABLE

Project: Buzzard Point (Lot 13, Sq 607)

Pace Project No.: 92183318

Lab ID	Sample ID	QC Batch Method	QC Batch	Analytical Method	Analytical Batch
92183318003	GTW-607-13-2A-1	EPA 3510	OEXT/25217	EPA 8015 Modified	GCSV/16260
92183318003	GTW-607-13-2A-1	EPA 5030/8015 Mod.	GCV/7612		
92183318001 92183318002 92183318003	GTW-607-13-1-1 GTW-607-13-2-1 GTW-607-13-2A-1	EPA 8260 EPA 8260 EPA 8260	MSV/25269 MSV/25269 MSV/25269		

Docament vens Document Name: Page 1 of 2 Sample Condition Upon Receipt (SCUR) ace Analytical Issuing Authority: **Document Number:** Pace Huntersville Quality Office F-CHR-CS-03-rev.12 Client Name: Richmond, VA Raleigh Eden Huntersville Asheville Where Received: Courier: Fed Ex UPS USPS Client Commercial Pace Other Optional Proj. Due Date: Custody Seal on Cooler/Box Present: yes no Seals intact: yes no Proj. Name: Packing Material: Bubble Wrap Bubble Bags None Other Samples on ice, cooling process has begun Type of Ice: (Wet) Blue None Thermometer Used: IR Gun T1102 T1301 T1301: No Correction T1102: No Correction **Temp Correction Factor** Date and Initials of person examining Biological Tissue is Frozen: Yes No N/A contents: W С Corrected Cooler Temp.: Comments: Temp should be above freezing to 6°C ☐Yes ☐No ☐N/A 1 Chain of Custody Present: ☐Yes ☐No □N/A Chain of Custody Filled Out: ☐Yes ☐No □N/A Chain of Custody Relinquished: Yes No □N/A 4. Sampler Name & Signature on COC: ☐Yes ☐No □N/A 5. Samples Arrived within Hold Time: ☐Yes ☐No □N/A 6. Short Hold Time Analysis (<72hr): □Yes □No □N/A 7. Rush Turn Around Time Requested: Yes □No □N/A 8. Sufficient Volume: ☐Yes ☐No □N/A 9. Correct Containers Used: ☐Yes ☐No □N/A -Pace Containers Used: Yes □No □N/A Containers Intact: 11. ☐Yes ☐No ☐N/A Filtered volume received for Dissolved tests 12. Received mutals bottle not on Yes ☑No ☐N/A Sample Labels match COC: -Includes date/time/ID/Analysis All containers needing preservation have been checked. ☑Yes ☐No ☐N/A 13. All containers needing preservation are found to be in ☐Yes ☐No ☐N/A compliance with EPA recommendation. ☐Yes ☐No exceptions: VOA, coliform, TOC, O&G, WI-DRO (water) Yes □No □N/A Samples checked for dechlorination: □Yes □No □N/A 15. Headspace in VOA Vials (>6mm): □Yes □No □N/A 16. Trip Blank Present:

Client Notification/ Resolution:

Field Data Required?

Y / N

Ment Houndard

Trip Blank Custody Seals Present Pace Trip Blank Lot # (if purchased):

Person Contacted: Date/Time:

Comments/ Resolution: _

SCURF Review:

Date:

Date: 12/14/3
Date: 12/16/13

□Yes □No □N/A

Note: Whenever there is a discrepancy affecting North Carolina compliance samples, a copy of this form will be sent to the North Carolina DEHNR Certification Office (i.e. out of hold, incorrect preservative, out of temp, incorrect containers)

WO#:92183318



Time Depth Type Container No. of Size Container No. of No. of Size Container No. of No						1		1			Deta
Time 13:00 Date Print Pace Analysis Requested Preservatives Property Preservatives Preservativ						Firm					Firm
Time 13:00 Date Firm Time 13:00 Received by Firm Date Firm Date Firm Date Firm Sign Firm Sign Firm Sign Firm Sign			11			Print					Print
Time		section below.	YES, please explain in	If		Sign					Sign
Time Depth Type Container No. of Analysis Requested Preservatives		mperd with?	vidence samples were ta	E	d by	Receive					Relinquished by
Time 13:00 Date 17 Time 13:00 Date 17 Time 13:00 Date 17 Time Date 17 Time Date Time 13:00 Date 17 Time Date Time Date Time 13:00 Date 7 Time Date Time				Time		Date		1e	Tin		Date
Time 13:00 Print			Sodium Bisulfate	H		Firm					Firm
Time 13:00 Date Print Page Analytical Services, Inc. Property Page Analytical Services, Inc. Property Page Analytical Services, Inc. Property P			Methanol	G		Print					Print
Time 13:00 Preserved by Date			HCL	ঘ		Sign					Sign
Time Depth Type Container Containers No. of PROJECT MANAGER Greg Grose 17 (1 c) W. t. V. V. Size Container Containers No. of Analysis Requested Preservatives 17 (1 c) W. t. V. V. Size Container Containers No. of Analysis Requested Preservatives 17 (1 c) W. t. V. V. Size Container Containers No. of Analysis Requested Preservatives 17 (1 c) W. t. V. V. Size Containers No. of Analysis Requested Print 10 : 30 34 3 (1 c) W. t. Size Containers No. of Size			$\mathrm{H_2SO_4}$	E	d by	Receive					Relinquished by
Time Depth Type Container No. of Analysis Requested Preservatives			HNO ₃	10:15 66	SIH12			ı	Tin		
Z33-002 LABORATORY Pace Analytical services, inc. Pace Individual services Project Manager Greg Grose Provervatives			NaOH			Firm					Firm x+x
Container Container No. of Size Container No. of Size Container Analysis Requested Preservatives		plas	Sample filtered			Print				3	Print Don Seserko
Container Container Container Pace Analysical Services, Inc. ADDRESS H5 H2 Enthropy, 25 R.4. Not Container PROJECT MANAGER Greg Grose PROJECT MANAGER Greg Grose Preservatives	discord 250		Sample chilled		22000	Sign C					Sign J. Speeche
Container No. of Size Container No. of Container No. of Container Container No. of Container Container No. of Container Container No. of Container Container Container No. of Container Contai	Sampling Comments		RESERVATION KEY	P	d by	Receive				by	Sampled and Relinquished by
Time Depth Type Container No. of Size Containers ADDRESS 45 4 2 6 4 4 4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			1			11 1		u ·			
Depth Type Container No. of Size Containers No. of Size Containers No. of Containers No. of Containers No. of Containers No. of Size Containers No. of Size Containers No. of Containers No. of Size Size No. of Size Size No. of Size S										3	
Depth Type Container Containers Co										3	
Time Depth Type Container No. of Size Size Container No. of Container No. of Size Container No. of Size No. of Size No. of Container No. of Size No. of Size No. of Size No. of Container No. of Size No. of Container No. of Size											1
Depth Type Container No. of Size Container Size Container Container Container No. of Size No. of									5		
Z23-002 ZABORATORY Pace Analytical Services, Inc.								B.			
223-002 LABORATORY Pace Analytical Services, Inc. Zzard Point (Lot 13, Square 607) ADDRESS Pace Analytical Services, Inc. Time Depth Type Container No. of Size Analysis Requested Preservatives 9/15 34/3(7.5) 10/30 34/3(7.5) 10/3 3 10/5<						- 1					
LABORATORY Pace Analytical Services, Inc. Pace Analytical Services, Inc. Pace Analytical Services, Inc. Pace Analytical Services, Inc. Pace Analytical Services, Inc. Pace Analytical Services, Inc. Pace Analytical Services, Inc. Pace Analytical Services, Inc. Pace Analytical Services, Inc. Pace Analytical Services, Inc. Property Property Container No. of Size Analysis Requested Preservatives Property Preservatives Property Preservatives Property Preservatives Property Preservatives Property Property Property											
Container Cont				13/13/15 5 \$ 12 \$ \$7							
Time Depth Type Container Size Container	800		17	VOCS / TPH-DRO/GRO/STACKEN		AND AL		34.3(200)	10:30	12/13/13	GTW-CO7-13-21-1
223-002 LABORATORY Pace Analytical Services, Inc. Pace Analytical Services, Inc. Pace Analytical Services, Inc. Pace Analytical Services, Inc. Pace Analytical Services, Inc. Pace Analytical Services, Inc. Production Avaluation Proservatives Depth Time Depth Type Container Containers Analysis Requested Preservatives Preservatives	600			VOCS		404		17 (760)	10:00	12/13/13	01-1-13-2-13-2-1
LABORATORY Pace Analytical Services, Inc. Pace Analytical Services, Inc. Pace Analytical Services, Inc. Pace Analytical Services, Inc. Pace Analytical Services, Inc. ADDRESS 45 % 2 % 2 % 2 % 2 % 2 % 2 % 2 % 2 % 2 %	183318001	9	F/A	V0Cs	W	4°A		24 (700)		12/13/13	Grv-607-13-1-1
LABORATORY Pace Analytical Services, Inc. LABORATORY Pace Analytical Services, Inc. DELIVERY DATE 12月37日	(special instructions, precautions, additional method numbers, etc.)	Comments - (Preservatives	Analysis Requested	No. of Containers	Container Size	Type	Depth	Time	Date	Sample No.
IABORATORY Pace Analytical Services, Inc. Pace Analytical Se	100121 Stotletim	DELIVERY		MANAGER Greg Grose	PROJECT N				on Seserko	D	H&A CONTACT
LABORATORY Pace Analytical Services, Inc.	mas > l	TURNAROUN	Concord NC 2807	1.50 R	ADDRESS		are 607)	t (Lot 13, Squ	uzzard Poin	_B	PROJECT NAME
DELIVERY DATE	DATE 12/14/13	DELIVERY DATE		Pace Analytical Ser	LABORATORY)223-002	40	H&A FILE NO.
CHAIN OF CUSIOUT RECORD Page 1 of 1	ige 1 of 1	_	RECON	N OF CUSIODY	НАШ			22102	cLean, VA	Z	
Phone (703) 336-6200 Fax (703) 366-4699	(703) 336-6200 (703)366-4699		BECOB	N OF CHETON			ite 870	ch, Inc. anch Drive, Sı	aley & Aldri 26 Jones Br	H:	HALEY &
9 of 19											

Form 3002

WHITE - Laboratory

CANARY - Project Manager

PINK - Haley & Aldrich Laboratory

GOLDENROD - Haley & Aldrich Contact